

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
16-Nov-15	Vehicle	215	New Windscreen	star stone chip in windscreen	rock	-
17-Nov-15	General Equipment	215	Have batteries available	20Xp torch LED torch flat does not appear to charge when engine is turned off so dead flat when engine off, 2nd torch SI20lp combo - led, is charged, it does not appear to be charging as not red light is activated engine off or on.	As above	Fault formed raised last week, aware
18-Nov-15	Vehicle	215	-	aerial broken off	unknown, discovered when completing vehicle check	-
17-Nov-15	Vehicle	215	-	Interior LED light strip broken and hanging down Passanger side mirror casing cracked and cover with tape to prevent injury	-	Found on morning of 18/11 while completing vehicle check
18-Nov-15	Vehicle	215	Taken directly to mechaninc	Reported to OIC, OCS and taken directly to mechanic.	-	Vehicle has been repaired, leak found to be o ring in the rear heating unit. Unit is now operational. Wide bay fleet 18/11/2015.
21-Nov-15	Vehicle	215	Wide Bay Fleet has removed step and replacement ordered.	Bracket holding sliding step passenger side broken, step not usable front broken not supporting step collapses to ground if any weight put on it	unknown	State Fleet is investigating problem, and organizing replacement step. Wide Bay Fleet will advise of when replacement part arrives for fitment. 27/11/2015 Step has now been replaced
22-Nov-15	Vehicle	215	changed suction pot and tubing. Found that the red hose was creating a vacuum, but as soon as the canister was introduced suction failed to work.	Suction pump inside the truck not working.	-	-
22-Nov-15	Vehicle	215	vehicle driven back to Burnett coast station	Vehicle acceleration poor. Check engine light flashing. Car missing gears. ?fuel injection issues	unk	Vehicle unable to be driven in a safe or efficient manner. High revs. Skipping. vehicle has been repaired and returned to station.
25-Nov-15	Vehicle	215	-	Step light is hanging out of attachment site	-	Unknown how long light has been unattached
27-Nov-15	Vehicle	215	-	Side step works intermittently	-	step only just been replaced
30-Nov-15	Vehicle	215	Repairer aware ,awaiting screen	stone chip to middle on windscreen	-	-
2-Dec-15	Vehicle	215	Report to OIC, SOS, CDS	Battery seems faulty and unsafe to respond on EA until checked. Wouldn't kick over at first, jumper leads required, kick over very sluggish to start after a drive to Childers and only 1 minute switch off, same problem on attempt to leave childers	?alternator	-
3-Dec-15	Vehicle	215	Reported to OIC	Running light below fuel filler loose	-	-
3-Dec-15	Vehicle	215	accident paperwork completed, OIC informed	Alteration to panel work on rear side sliding door, front of rear side wheel arch and side door step	striking a low, steel light bollard at Maryborough Hospital	-
4-Dec-15	Vehicle	215	-	Rear tyres approx 2mm tread from wear marker	-	-
15-Dec-15	Vehicle	215	-	Engine warning light is being displayed	-	-
12-Dec-15	Vehicle	215	fault form raised	Radiator light on, fluid level alarming and service needed on dash	Radiator light on, fluid level alarming and service needed on dash	-
12-Dec-15	Defibrillator	215	Swapped for unit in training room as no designated spare able to be identified	Clock does not continue to count in the background when unit powered off	Unknown	-
17-Dec-15	Stretcher	215	Reported to Coms, taken off road.	Stretcher collapsed from loading position to floor position at the feet end only.	Unknown	-
17-Dec-15	Vehicle	215	Just basic checking of controls	Air-conditioning in rear cabin works intermittently. At times, there is still air flow but it doesn't produce cold air. 'Doors Open' signal stays on on control panel when all doors are closed.	not known	-
18-Dec-15	Vehicle	215	-	Stair makes ratchet like noise when closing	-	Unknown when fault began only noted at start of rotation
22-Dec-15	Vehicle	215	-	New defibrillator tray install on last service does not open as bolts are too long and hit frame of door. Also side and scan lights are too dim and useless at night.	-	-

RELEASE

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
22-Dec-15	Stretcher	215	Stretcher made u/s for investigation.	Stretcher collapsed at head end with heavy patient on it when operated by Officer All wheels down, collapsed when moved away from vehicle. This was witnessed by myself and RN escort from MBH.	-	Incident reported to CCS, SOS and OIC Maryborough station.
24-Dec-15	Vehicle	215	nil	Blades came off driver front wiper, windscreen cracked lower mid windscreen	blades came off when wipers activated on bruce highway	-
25-Dec-15	Vehicle	215	nil	Bracket for gps broken, gps loose in cabin	?	-
28-Dec-15	Stretcher	215	Taken out of use	Stretcher no longer within service date	Missed During Reservicing	Reservice Date 12/09/15
30-Dec-15	General Equipment	215	this delightful fault form has been completed.	Pager does not switch on. Battery checked and changed. Still not working.	?	-
31-Dec-15	Vehicle	215	Reported	Clunking and thudding coming from L front wheel while driving and when turning	-	-
1-Jan-16	Vehicle	215	-	Drivers side rear park light blown	-	-
4-Jan-16	Vehicle	215	-	Passenger side headlight blown	-	-
5-Jan-16	Vehicle	215	Fault form	Vehicle pulling to left when driving, also some noise from left front when driven from station, heavy in steering	Unknown	-
5-Jan-16	Vehicle	215	reported	Approx 20 cm crack to top left side across windscreen	unknown	passenger side
5-Jan-16	Vehicle	215	nil	Water (from rain) entered front cabin through radio base on ceiling. Concern as water was then dripping onto main controls.	Not known but believe it may be from recent windscreen replacement.	Operation in dry weather, not in wet.
13-Jan-16	Vehicle	215	vehicle taken to mechanic who attended immediately to the issue	Air con in rear not working	-	-
14-Jan-16	Vehicle	215	fault form completed	Secondary battery failing to charge. Goes flat after small amount of time not running. If car left on, car is operational.	Unknown	-
28-Jan-16	Vehicle	215	Reported	Drivers side rear taillight cracked	Unknown	Not noticed when vehicle checked this morning however not caused today
28-Jan-16	Vehicle	215	Reported	Drivers side rear taillight cracked	Unknown	Not noticed when vehicle checked this morning however not caused today
29-Jan-16	Stretcher	215	Stretcher taken off road	Gas strut lifting/lowering head leaking, with head unable to be laid flat	Unknown	N/a
1-Feb-16	Vehicle	215	Nil	Sensors need tweaking as vehicle beeps when turning corners and going over bumps. Sensors also trigger emergency lights which then flash.	Nil	-
2-Feb-16	Vehicle	215	incident report, fault report	Button to open rear door not working	patient pulled out wiring and broke	-
2-Feb-16	Vehicle	215	-	Went to take car home on call, low water alarm coming on, appears to have plenty of water ? Sensor	-	Spoke to same thing happened a few weeks ago, he thought it had been fixed
3-Feb-16	Vehicle	215	Water was mopped up prior to exiting vehicle with pt	Vehicle leaking water in rear compartment. Travelled through heavy rain and water was dripping from front 2 internal rear lights closest to the cab.	Heavy rain	-
5-Feb-16	Vehicle	215	Nil	12 volt plug in front centre console not working. Needed to charge tough books	Unknown	-
7-Feb-16	Vehicle	215	oic notified -emailed	Rear air conditioning unit mounted to roof coming off the roof. Risk of falling onto patients	old holding piece has snapped -normal wear and tear. Noticed after a job, fine before	-
12-Feb-16	Vehicle	215	Report	Reversing camera menu button faulty & screen appears dark	-	-
8-Feb-16	Vehicle	215	Fault report	Back right parking break out	?	-
15-Feb-16	Vehicle	215	-	Side step will not deploy	-	-
17-Feb-16	Vehicle	215	-	Side step not functioning	-	-
3-Mar-16	Vehicle	215	-	VHF radio switches on and off intermittently while engine is not switched on and even when plugged in on charge at station. And SRS warning light on dash illuminated.	?auxiliary battery related issue	-
14-Mar-16	Vehicle	215	OIC notified	Rear compartment doors locking with difficulty unlocking. Has been taken to ken days before with same issue.	Locking fault	Vehicle taken off road

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
16-Mar-16	Vehicle	215	Vehicle returned to station and taken off road	Door locks, unable to gain access to vehicle	Vehicle locked and unable to gain access. Remote on keys wouldn't work. Then once inside, vehicle was 'locked' in park and wouldn't start, no dash lights etc.	-
19-Mar-16	Vehicle	215	-	30cm crack in windscreen passenger side top area.	Stone strike	-
24-Mar-16	Vehicle	215	N/a	Drivers side rear stop light not working	N/a	-
24-Mar-16	Vehicle	215	-	Front passenger headlight out	-	-
24-Mar-16	General Equipment	215	Bag of splints removed from vehicle 4442 replaced with orange type of splints	Hartwell evac-u-splint new pump found in bag still in packaging but is missing adaptor part to connect to newest type of vac splints with red air release valve. pump does not connect correctly. Splints unusable	Missing part	Bag left at OIC door with note
16-Apr-16	Vehicle	215	-	Bin drawer in rear compartment of 4406 has come off the wall ?pop rivets have broken taking rail off wall. Bin hard to pull out and replace, risk of needle stick injury due to sharps container not lining up correctly.	-	-
18-Apr-16	Vehicle	215	user test Called Mackay LASN Mechanic	user test	user test	-
19-Apr-16	Vehicle	200	-	Siren not working	Unknown	is looking into ways to isolate the issue, siren speakers or siren driver. May need to get unit to Mackay workshop to fix.
19-Apr-16	Vehicle	210	Broken plastic removed from roof of vehicle. Incident reported to Ops Super, Sos and Oic	Plastic cover of the Right Rear Red Beacon Broken and electrical wires exposed.	Automatic Rollerdoor came down onto the vehicle while reversing into the plant room	The vehicle is mechanically sound, however due to the exposure of the electrical wires, the vehicle should only be used as a last resort and only in suitable weather.
20-Apr-16	Vehicle	250	Nil	Top right hand side strobe missing. Part in glovebox. Right hand side rear door stay broken. Left hand side rear stay required to have replacement screws.	Unknown, found with vehicle check.	-
20-Apr-16	Vehicle	250	Nil	Reversing camera not working.	Unknown	Nil
20-Apr-16	Vehicle	210	Report fault in checklist	Flat tyre. This is a test for vehicle checklist trial	Screw	-
20-Apr-16	Vehicle	200	Nil	Front left tyre worn on outside edge. Was picked up during tyre check.	Needs wheel rotation	Advised by to get wheels rotated.
21-Apr-16	Vehicle	215	Na	Door lock on side to enter rear compartment is loose & does not open effectively	Unknown	-
22-Apr-16	Vehicle	200	Taken to workshop 21/04	One siren speaker not working, other working intermittently. Seen by mechanic 21/04/16 requested to stand vehicle down next day and return to workshop for investigation	-	-
20-Apr-16	General Equipment	185	LASN CAH Business Support Manager & Readiness Coordinator informed	Charging Bracket Defibrillator (Corpuls) faulty. The circular charging plug is loose causing the Monitor to get stuck in the cradle. Charging wires are hanging over the charging plug.	Unknown. This is a loan vehicle (Unit 7169) Possible wear and tear during insertion and removal of the Corpuls.	Pictures of fault sent to Business Support Manager and Readiness Coordinator
21-Apr-16	Vehicle	185	Tyre pumped to tyre manufacture specifications	Left rear slowly going flat.	-	-
22-Apr-16	Vehicle	195	Headlight changed	DRIVER FRONT HEADLIGHT FAULTY	-	-
23-Apr-16	Defibrillator	210	Corpuls has been removed from service and reported to SOS and OCS Diagnostic test by RACQ. Repairs to be arranged.	Damage to printer post trip	accidental damage	-
17-Apr-16	Vehicle	215	-	Faulty glow tube	Unknown	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
23-Apr-16	Vehicle	250	Unable to fix remote. Able to secure vehicle by locking back doors from central lock. Manually locking passenger door and using key to lock drivers door. May cause delays in arriving at patient.	Remote lock for vehicle is not operational on key. Only one set of keys for vehicle.	-	-
23-Apr-16	Vehicle	240	RACQ called and removed the broken bar and it fell to bottom of inside door	Front Left Passanger door internal guide bar broke inside and prevented door from closing	corrosion	needs to be followed up by service provider to replace the guide bar
23-Apr-16	Defibrillator	250	-	CF Card not found	-	-
24-Apr-16	Stretcher	195	Called Comms and advised.	Power stretcher legs will not come all the way down.	Nil	-
24-Apr-16	Vehicle	210	NIL	WINDSCREEN STONE CHIP	ACP 2 ADVISED WHILE TRAVELING BEHCIND A A TRUCK SUSTIANED A CHIP - ? ROCK.	VEHCILE CAN BE REPAIRED LOCALY.
24-Apr-16	Vehicle	210	NIL	LARGE CRACK IN PAASENGER SIDE LOWER LEFT WINDSCREEN.	UNKNOWN - NO CHIP ASSOCIATED	MAY REQUIRE REPLACMENT WINDSCREEN.
24-Apr-16	Vehicle	250	-	1. Right side rear door won't stay open - Door stay not holding the door. 2. MDT casing opened and exposed the internal electronics- closed with medical tape. 3. Intermittent Air con fault. Blows warm and has a urine type odour. Will eventually cool	3. Continued from above - Air con blows warm , with "Urine type odour" blows cold after about 10 mins if the vehicle is moving	-
25-Apr-16	Vehicle	200	Vehicle was plugged into power and charged for 24hrs completion of vehicle checklist to identify fault	Rear module would not unlock. Various attempts to remedy problem unsuccessful. Rear module unlocked randomly uncertain why. During vehicle check rear module power went off within two minutes ? Flat batteries	Vehicle was left plugged in but was not turned on.	Vehicle currently back in service.
25-Apr-16	Vehicle	230	noted on Vehicle	MDT not operational on vehicle. Reset from mains to still not work.	not known, faulty electrics	-
25-Apr-16	Vehicle	230	Checklist	Evidence of power to MDT, but no information showing whatsoever. Cigarette lighter power adapter no longer operational - unbale to use in car charger for QAS Earf Toughbook. Diagnostic conducted - checked in car charger in other two vehciles works.	nil known cause	Nil additional comments.
26-Apr-16	Vehicle	210	Nil.	Cracked windscreen --> Chip with significant starring of crack to A-Pillar and bottom of windscreen	Unknown.	-
26-Apr-16	Vehicle	200	Vehicle fault form completed	Rear tail light on drivers side not working	Unknown- Found on pre-shft check. ? Rock chip	Windscreen should be replaced ASAP
26-Apr-16	Vehicle	250	-	Definitely slide bracket broken inhibiting closure	blown bulb	-
26-Apr-16	Vehicle	210	Broken bit adjusted	Vehicle taken to and they reported a problem with the step motor. They are going to order in new part. Attempting to get to for review	-	-
26-Apr-16	Vehicle	215	-	Side Step Motor Fault. Step wouldn't go in.	-	-
27-Apr-16	Vehicle	215	-	Side step (passenger side) not engaging and vehicle pulls to the left whilst driving - ? Requires wheel alignment	? Gravel or grit in side step	-
27-Apr-16	Vehicle	250	Oil, radiator and coolant fluid levels checked and within range.	Coolant temp warning light on dash	-	Spoke to who stated he thought it was a faulty sensor and he would look at the vehicle tomorrow.

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
22-Apr-16	Vehicle	205	non	The Auxillary battery is not holding charge. Even when all radios turned off over nite on call you need to start the car to get radios to turn on.	no	-
28-Apr-16	Vehicle	200	Out of service, to be taken to be repaired	No. Windscreen loose from seal.	-	-
28-Apr-16	Vehicle	200	Taken out of service	Windscreen loose from seal	-	-
28-Apr-16	Vehicle	210	Fault form	Drivers seatbelt doesn't retract all the time	No	-
28-Apr-16	Vehicle	215	-	Rear door not locking. When lock car makes locking sound however door not locked.	-	-
28-Apr-16	Vehicle	200	-	All other door at back are locked .	-	-
28-Apr-16	Vehicle	200	-	Small right rear lower beacon not working	-	All other beacons working
28-Apr-16	Vehicle	210	temporary fix by machanic	Water hose novel is missing from the left wiper blade, so the hose is loose and flapping, machanic did temporary fix with zip tie.	unknown	-
28-Apr-16	Vehicle	215	Comms notified, OIC notified	Vehicle radio fault. Radio turns off when transmitting.	Unknown, vehicle has been on charge every day	-
28-Apr-16	Vehicle	215	Nothing at this stage. Report to OIC on Monday (next shift)	Rubber along radio cord has somehow come down exposing wires near handset.	Unsure of cause however coil is quite tight.	-
29-Apr-16	Defibrillator	200	Default form submitted. Corpuls to be charged in bracket of centre console pt compartment when required.	Corpuls not charging in bracket in kit compartment side of vehicle. Plugged into charger, Corpuls locked into bracket, ?faulty connection somewhere. Also difficult to remove from bracket. Has previously been defected for same issue.	N/A	-
28-Apr-16	Vehicle	200	OIC and SOS have been notified, claim for has been filled out.	Damage to driver side rear lights on 2129	QPBS truck side swiped stationary QAS 2129.	-
30-Apr-16	Vehicle	210	vehicle has been taken off road and replaced by unit 2452 at Emerald Station waiting for repair.	Air suspension stuck down and unable to re inflate airbags. This caused the ride in the vehicle to be extremely rough and hard hitting when going over bumps in the road.	Unknown	notified of fault and advised to leave vehicle in Emerald for repairs the next day.
30-Apr-16	Vehicle	210	nil	Faulty torch battery. Battery not holding charge	-	Light dims on torch after a couple of seconds use. Other torch in vehicle working as normal.
30-Apr-16	Defibrillator	200	SOS notified for replacement of lead.	Small breakage of outer plastic cover on Sp02 lead (section from monitor to adapter)	Unknown- noticed while cleaning lead for North Mackay crew	SPo2 lead unable to be replace on the shift- due to inaccessibility of replacement lead over weekend. Was replaced on the Monday morning.
29-Apr-16	Vehicle	215	Nil	Side Step is not working properly, has been playing up now appears to be worse. The motor can be heard at times but doesn't seem to be associated with any movement of the step.	Unknown	The vehicle can be used for the time being but not the step.
30-Apr-16	Vehicle	200	-	Both side work lights and rear load light not operating.	-	All other lights and switch panel functions operational.
30-Apr-16	Vehicle	200	Nil	Rear suspesion failure. ?air suspension. Rear of vechile riding very low and unable to use switch to reinflate.	-	Vechile is drivable however, very uncomfortable and potentially unsafe code 1.
30-Apr-16	Vehicle	210	Nil, light brackets seems to be broken and can't be fixed	Sliding step light loose, belt attachment with buckle missing on top of door entry equipment tray	Unknown	Nil
29-Apr-16	Stair Chair	210	NA	Green lap belt buckle missing one prong on 2286 stair chair, still functioning but with reduced effectiveness.	Unknown, fault was detected on scene when stair chair was used	-
1-May-16	Vehicle	185	nil	Passenger side door plastic stone guard (at bottom of door) found this morning to be broken.	unknown	Would be good if there was a camera icon to take a picture as well
1-May-16	Vehicle	210	This report filled out. attempt to find missing key	Side door to rear compartment can not be locked. Leaving ambulance drugs and equipment exposed to possible theft.	Unknown. Missing key to door lock	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
2-May-16	Vehicle	215	-	- back door does not open. - Internal car oxygen tap broken - Rear A/C not working. - Alarm sound when mains is turned on.	-	-
2-May-16	Vehicle	240	reported to QPS and OIC	Vehicle was kicked and punched by a bystander on scene causing dent to L rear door and broken plastic R rear tail light	assault by bystander initially in cyclone Marcia started lifting the stickers - now flapping in wind so they were removed.	-
2-May-16	Vehicle	210	-	Bonnet reflective stickers need replacing Bolts from bottom hinge of rear stair door have come away/loose. Door still operates as normal. Unit is also sluggish to start. Emergency start icon glowing red on middle console. Also appears new scratch down rear cab driver's side.	-	-
2-May-16	Vehicle	200	-	-	-	-
1-May-16	Vehicle	245	None, requires services of Auto Electrician	Battery warning light showing on vehicle instrument panel. Batteries not charging when plugged into 240 volt outlet 2 issues with vehicle retracting side step, 1: protective corner cap L) side of step has fallen off and has exposed sharp corners and I ripped my pants while accessing patient care bags. 2: step making terrible sound and not retracting back into the car	Possible faulty alternator	-
3-May-16	Vehicle General	200	Replace corner cap/step motor	-	no	thule brand step
3-May-16	Equipment General	185	Nil	Test form	Failed to carry	Test
3-May-16	Equipment	185	-	Test fault	-	-
3-May-16	Vehicle	215	Vehicle to be taken to mechanic this morning step cleaned and tracks sprayed with silicone	Diesel leak from filler hose Intermittent issue with Auto side step deploying and not retracting. This issue is intermittent and has been ongoing for some time. The issue self resolves and the re-occurs at times.	? loose hose clamp	Wrong vehicle vault form generated should have been 4335
1-Mar-16	Vehicle	180	spray.	-	unknown	-
3-May-16	Vehicle	215	vehicle taken off road, and being taken to mechanics this morning Comms notified by radio and SOS met with crew at hospital to assess the damage and discuss with crew what happened. Vehicle returned to Coomera station.	fuel leak from filler hose	? Loose clamp	Vehicle returned this afternoon, hose clamp changed over and tested
3-May-16	Vehicle	250	-	Damage to Rear Left Break Light Wearing on front driver's side tyre - recommended to check wheel alignment by tyre check. - "No immediate action required"	Ambulance was being reversed out of a gate when vehicle collided with the edge of the gate as it was closing. Immediately outside the gate was a police car and a fire truck responding to an different emergency across the road.	As per SOS... SHE report pending conversation with OIC
3-May-16	Vehicle	200	-	Front aircon fan not blowing air causing uncomfortable cabin temp and also unable to de-mist windscreen	-	-
4-May-16	Vehicle	200	vehicle fault form	-	no	Should be fixed ASAP
4-May-16	Vehicle	200	spoke to who stated vehicle still operational if required	Fuel filter light illuminated on dash	-	-
4-May-16	Vehicle	205	Fault form completed	Siren non operational	-	-
			Reported to operation center, SHE report completed and QBE			
30-Apr-16	Vehicle	215	form sent to SOS.	Side Mirror plastic light cover broken, glass loose and mild crack	Hit on side of plant room door	-
4-May-16	Vehicle	215	Fault form completed	Crack in windshield	Rock hitting windscreen	-

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
4-May-16	Stretcher	200	Duty officer and OIC advised	Stretcher collapse at head end from one click above ground while patient has sat down on the stretcher. Nil injury to patient or officers. Witnessed by a number of nurses at MBH.	-	Incident occurred around 1300
2-May-16	Other Equipment	185	Job logged with IT comms notified and spoke to ocs. Drove back to station and swap vehicles	Internal wire sat phone has no power, PTT is not connecting	-	-
4-May-16	Vehicle	245	OCS and Comms notified. Drove vehicle back to station in out of service mode and swapped vehicle.	Engine light flashing on dash and loss of power	unknown cause	-
4-May-16	Vehicle	245	-	Vehicle radio receiving but not transmitting	no idea	Oil notified via email
5-May-16	Vehicle	210	Reported to OIC at handover on Wednesday the 27th April 2016	Fentanyl vial, below normal drug fluid in vial	Possibly a manufacturing fault as the vial does not appeared to be tampered with in any way. No fluid discoloration, no water marks, no visible holes.	Volume irregularity was noted during hand over, drug signing at Tieri Station. Vial was noted to have less than normal drug fluid contained inside. Vial was put aside to be noted to OIC Tieri station the next morning.
5-May-16	Vehicle	215	-	Passenger side windscreen wiper broken, not holding blade in place.	-	-
5-May-16	Stretcher	200	stretcher taken out of vehicle and given to mechanic	Lowered the stretcher to second lowest level on foot end, red handle released & stretcher 'clicked' into place, stretcher then let go of by officer. The stretcher then fell to the bottom level. Patient was on stretcher but was unharmed by stretcher drop.	Unknown	-
6-May-16	Vehicle	210	Non	Vehicle runs rough and makes noises when accelerating. Vehicle side door opens periodically when driving and side step ejects automatically	-	-
5-May-16	Vehicle	185	off road and fault form filed. SOS notified	Chunk of rubber missing from tyre	contact with curb	-
5-May-16	Vehicle	210	Complete fault report.	Rear Air-Conditioner does not work.	Not known, just stopped during shift.	-
6-May-16	Vehicle	250	-	Blown number plate light	-	-
5-May-16	Vehicle	250	Fault form	Reverse camera does not work	Nil	-
6-May-16	Vehicle	250	Fault form	Nail in tyre in left front.	Run over a nail	-
6-May-16	Vehicle	235	Notified OIC who will contact SOS.	Car has a large chip on the windscreen (approx 20c piece). Drivers side	Unknown what caused fault, was present prior to shift starting	The car will be taken off road unless there is a shortage in vehicles at station
6-May-16	Vehicle	195	Reporting the incident and damage	Accident Damage rear Step fiberglass platform near side rear	Reversing Accident	Refere to SHE reportNo. 034971 for details and Motor Vehicle Accident Claim form
6-May-16	Vehicle	250	-	SRS warning light on dash	-	lunch monitor spoke to mechanic who stated the vehicle was safe to drive despite the warning light.
6-May-16	Vehicle	250	-	Passenger side tail light not working	blown bulb	-
7-May-16	Vehicle	185	fault form	Side step malfunctioning	-	-
7-May-16	-	210	Unable to be fixed	Battery Terminal tray swinging open - broken plastic cover door	Unlatched battery terminal	-
6-May-16	Vehicle	210	vehicle taken to Workshop	Wilful damage to the drivers revision mirror	wilful damage reported to QPS via Policelink. QP Photos provided to QPS vis Policelink.	-
7-May-16	Vehicle	200	-	?rear suspension issue. Large banging noise over small bumps. Vehicle feels unstable. Vehicle returned from workshop yesterday due to airbag issues.	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
31-May-16	Vehicle	215	Officer to attempt to take vehicle to QAS auto electrical contractor in Bundaberg	1. Batteries not holding charge. Flattening easilly off 240v charging.	1. Auto	-
7-May-16	Vehicle	185	Car returned to station. No further action taken.	Vehicle in "limp" mode. As accelerator pressed vehicle made hissing sound, a bump felt in the engine and engine light started flashing. vehicle entered limp mode.	Suspected turbo hose blown.	Officer driving at time of fault.
7-May-16	Vehicle	185	Fault form filled in so as issue can be repaired or fixed	1. Secondary Battery goes flat even when it is plugged in. 2. Defibrator Cradle release handle broken. 3. Left side work light broken off vehicle. 3. Tyre Presure Monitor faulty. Continuously beep even though the tyres appear to be okay.	Unknown discovered during vehicle check	-
7-May-16	Vehicle	250	SHE hazard report completed	Rear door hinge on passenger side of vehicle not working door does not stay opened and can close without warning	-	-
7-May-16	Vehicle	210	Stretcher has been removed from service. Vehcile still operational / OPs Centre and OCS / SOS notified.	Strectcher Asset # BB3995 has a faultly struct / leaking and now stretcher non-operational.	Unknown.	Strut is used to lift the back of the stretcher up and down - will no return to a supine postion stuck in a sem-recumbant postion. Struct has leaked hydrolic fluid over the vehcile floor and stretcher.
5-May-16	Vehicle	215	Fault form completion, Notified OCS at time of fault.	Radio not in working order	N/A	Vehicle is operational, however due to limiting radio network it is not appropriate to have a vehicle with no working VHF radio. Trigger button needs replacing on hand-held aspect of radio. Unable to make transmission.
8-May-16	Vehicle	210	This report and annotations on eVehicle checklist	Drivers rear barn door magnetic catch has detached (magnet only)	Poor gluing at time of manufacturing	-
8-May-16	Vehicle	185	None as nil replacements on site.	Stretcher belt missing	Swapping over of stretchers most likely on recent loan to Cairns for mountain bike races at Smithfield.	-
8-May-16	Vehicle	245	notified secom CDS out of service. Notified afcom roc. Will notify OIC.	Flashing check engine light. Vehicle likely to go into limp mode.	?	-
8-May-16	Vehicle	210	Comms notification, nil other vehicles available on station at 1900hrs	Siren malfunction	-	-
8-May-16	Vehicle	185	don't use	Side step not fully extending out, only half coming out. Appears to be blocked but cannot locate cause	-	A/OIC advised 11/5/2016 vehicle has been repaired.
8-May-16	Vehicle	245	-	Cracked mirror and lens on passenger side	hit driveway post	-
8-May-16	Vehicle	245	-	Cracked mirror and lens on passenger side	hit driveway post	-
8-May-16	Vehicle	245	-	Cracked mirror and lens on passenger side	hit driveway post	-
9-May-16	Vehicle	185	Plugged it back in. Fault form raised.	Rear module will not unlock unless engine is running.	Vehicle not plugged in overnight. Auxiliary battery possibly failing.	Usable but unreliable.
9-May-16	Vehicle	185	spoke to and she stated to do fault form.	Frayed hand piece to hand help radio in front compartment.	No	-
8-May-16	Equipment	185	Removed from service and reported.	Battery clasping mechanism loose, unit turns off and on by itself. Not a battery issue.	-	-
6-May-16	Equipment	195	has been removed from the vehicle at this stage	vacumn mattress must have a hole in it as it is not staying vacuumed. Old piece of equipment.	na	-

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
9-May-16	Vehicle	240	Notified OIC, OS and Comms. Vehicle Accident Report Form and SHE filled out.	Dent to back door and back step >> Back door unable to be opened	Reversing accident >> Reversed into a pole	-
10-May-16	Vehicle	210	-	Left headlight out	-	-
10-May-16	Vehicle	215	Nil - new stay required	LHS rear door stay snapped off	-	-
10-May-16	Vehicle	210	reported	Front drivers side fender and small panel under light is coming loose or the bracket may have broken.	vibrations etc from driving on local roads	At this stage is only causing rattle.
10-May-16	Vehicle	210	-	Rear air suspension not working correctly. Suspension appears to be stuck in deflated state & unable to be reinflated >> when pressing the air suspension button there is no release of air.	-	During transportation of patients it has been extremely rough (more than normal) with patients commenting when driving on the road and especially over train tracks or bumps.
10-May-16	Vehicle	210	Air con repair please	Air conditioner faulty, not blowing cool air, drivers compartment and patient care compartment	-	-
10-May-16	Vehicle	240	followed manual and OC directions	SRS light is intermittent and then remains on - risk of airbag deployment . OC advised to return car slowly to North lakes	No	-
10-May-16	Vehicle	185	removed from service. sos notified and operational readiness coordinator	Rear Ac not working in car	unknown job number V 44	04 - vehicle back on road.
11-May-16	Vehicle	210	-	Siren not working on dual function mode	-	-
11-May-16	Vehicle	200	override levers	Power arm failure when unloading stretcher . Stretcher stuck half out of vehicle with power arm not engaged. Fleet called and used override levers to return stretcher to normal.	power arm failure	-
11-May-16	General Equipment	195	reset	Unit 1616 - GPS - Freezes and requires reset, then works for a while then freezes again	-	REpalced with new unit by RRC
11-May-16	Vehicle	215	-	Side step stuck half way out	-	-
10-May-16	Vehicle	215	Light has been removed to prevent further damage, tree branch no longer hanging over driveway. Incident form will be completed and OIC will be notified when off fatigue.	Right scan light housing broken	Fallen Tree branch on job 7588816	-
3-May-16	Vehicle	185	-	Paint/decal damage and scratches found on right front bumper on 10/5/2016	-	OIC CAIRNS to investigate when/where/ damage occurred, & have responsible officer complete a SHE report and insurance claim, if a claim is required.
11-May-16	Vehicle	210	-	Hand break needs adjusting. Not holding on steep incline	-	-
11-May-16	Vehicle	180	Vehicle had been taken to Auto Electrician	Main Control Panel Faulty - (inter, R/scan, L/scan, R/work, L/work, Rear/Drive, E/lights, H/lights, Siren)	Unknown	Awaiting Spare parts from - Cooktown
12-May-16	Other Equipment	210	-	Crossband vehicle radio cord exposing wires on hand held speaker. TM8200 radio TMAA02-08 F08 hand held S/N. Photo in vehicle check list completed today, under communications.	Unknown cause. Identified by Officer during vehicle check	-
12-May-16	Vehicle	210	Vehicle is booked into the mechanic to be replaced today	Right drivers headlight has blown	-	-
12-May-16	Vehicle	195	Nothing fill out fault form	Fluid leaving from window washer bottle I believe.	Unknown	-
12-May-16	Vehicle	195	taken vehicle out of service	Step will not retract	unknown	Car was not on charge, to be monitored
13-May-16	Vehicle	210	-	Side step doesn't feel stable. Leaning towards the left side	Found during vehicle check	-

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
13-May-16	Vehicle	210	-	15cm vertical crack in centre windscreen originating from significant stone chip	Unknown found prior to vehicle check	-
13-May-16	Defibrillator	185	-	Beeping sound	-	Job logged with
5-May-16	Vehicle	185	Vehicle taken to Cairns for Repair.	Rear Differential noise	N/a	Main switch panel being assessed at the same time - PSBA. Repairs at - QAS job number V 4424.
7-Mar-16	Vehicle	185	Cleaning and flushing with high pressure water jet.	Faulty side step operation. Has been long term and ongoing issue. Original step replaced by different model. Step ceases to function due to dirt and gravel jamming mechanism.	dirt and gravel caught in mechanism preventing step from working.	Vehicle due for 120000 km service, will have step removed and cleaned during service.
13-May-16	-	250	SECOM NOTIFIED, CDS, AOS AND SOS INSPECTED VEHICLE TO ENSURE TRUE FAULT.	MDT NOT WORKING CORPULS CRADEL DOES NOT CHARGE.---> replaced yesterday	Found at commencement of shift in same condition	-
13-May-16	General Equipment	195	Taken out of service	Exposed wires on charger cord for vehicle charging	-	-
13-May-16	Vehicle	250	Confirmed by second officer it does not charge confirmed that it does not charge by A/OS Confirmed no charge by SOS Fault form written	Flat battery Instructed by OS to put vehicle OOS	Found at shift check to be in this condition	-
14-May-16	Vehicle	185	Nil	Side step not working not even when using the over ride switch	No	Has had previous faults . Repair number V 4429. Vehicle can be in Cairns later this week for repair - I'll let know exactly what date.
14-May-16	Vehicle	200	Inspector notified	When driving the vehicle engine fan stays on and is very loud. Seems like the fan clutch not de engaging? Also seems to rev high at speed compared to normal - but may just be the additional noise. Drove vehicle till warm and symptoms partially better	-	-
13-May-16	Vehicle	210	Sometimes you can lock and unlock the vehicle while holding the door closed will get it to close but this problem needs to be rectified before we start losing gear due to the door flying open whilst moving.	The side door where response gear is placed will intermittently not close. This has occurred several days times in the past week while I have been using this vehicle.	Unknown	-
13-May-16	Vehicle	210	Officer had to enter the vehicle and open door from inside the vehicle	The rear door would not unlock to open the door.	Unknown	-
14-May-16	Vehicle	185	report fault, currently using red internal level	Rear door latch on drivers side not releasing properly when using rear button	-	Repair number V 4433
23-Feb-17	Vehicle	240	Different charger being used	Flat battery	Possible faulty charger	-
14-May-16	Vehicle	235	Vehicle placed under awning at station, vehicle fault form completed and sent to fleet and OIC and also left in vehicle for others to take notice of.	Siren not functioning. Vehicle fine for management use but not for operational duties.	unknown, found to not work whilst on case.	-

RTI RELEASE

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
14-May-16	Vehicle	215	RACQ called. Coms notified. A/OS informed. Option to exchange unit at Burleigh or continue to use. Training program recognised to defect equipment	Battery issues, would not start. RACQ called and jump started vehicle	Batteries flat.	-
14-May-16	Vehicle	250	immediately. Take different vehicle if	Corpuls limb lead plug defective.	Machine passed shift check. On fourth job it was noticed that the limb lead connector was ajar due to housing being snapped. A lot of difficulty was required to replug in.	Organised to swap unit at coral gardens.
13-May-16	Vehicle	185	IFT requires 240v racq jump start , vehicle run 1hr , racq recommend 240 v charger fitted, OIC	240v AC power inverter non-operational	U/K	RRC spoke with A/OIC even date. OIC advises that there is nothing wrong with the 240v power inverter. VEHICLE IS ON ROAD.
15-May-16	Vehicle	250	notified	Vehicle would not start ,, battery flat	battery flat	-
15-May-16	Vehicle	250	Fault form	Blown light	No	-
15-May-16	Vehicle	250	Fault form	Side step does not retract. Step requires to be jiggled for it to retract into undercarriage	Discovered like this	-
15-May-16	Vehicle	195	nil	Rear passenger door locking pin not engaging	unk	-
15-May-16	Vehicle	210	NA	Both vehicle torches won't turn on/ charging stations for torches won't activate. Doesn't seem to matter which torch is in which station, nothing works (both vehicle connected to 240V outlet or disconnected)	unknown, could be a fault with the torches or the charging stations.	-
15-May-16	Vehicle	185	fault report generated	No spare defibrillator to place in vehicle, as main defib unservicable	-	Advice from Q/OIC Mareeba even date reveals defib is fully operational. Vehicle 7400 taken off road due to not having a replacement defib.
15-May-16	Defibrillator	185	fault report generated	Lead III not attaching to pads/test box correctly. No connection	-	ADVICE FROM A/OIC MAREEBA EVEN DATE REVEALS DEFIB FULLY OPERATIONAL
15-May-16	Vehicle	185	off road	Rear barn door jamming and unable to open from the outside. Right hand rear sticking	-	Repair number V 4427 - Cairns
15-May-16	Vehicle	240	nil	Front Left Headlight U/S Number Plate Light U/S	-	-
15-May-16	Vehicle	240	Service contractor avail.		NA	-
16-May-16	General Equipment	190	Attempted to fix it but couldn't. Officers were still able to use handhelds.	In car radio turns itself on and off. often turning itself off during transmission. Then unable to turn it back on.	-	-
16-May-16	Vehicle	210	-	Bolt in rear right tyre	-	-
14-May-16	Vehicle	215	to mechanics	Engine Management light on	unknown	At , glow plug problem
16-May-16	Other Equipment	190	Removed the hand piece and radio is still operational	The radio hand piece is not working. The radio is working ok when the hand piece is disconnected from the radio indicating there may be a problem with the hand piece only	Unknown	-
17-May-16	Vehicle	200	QAS Mechanic has been notified and will assess this morning	Intermittent electrical fault, affecting ignition and ? Also stretcher function (stretcher fault completed separately). Vehicle did start normally during morning vehicle check. When later responding to job, vehicle ignition did not start...	error message indicates vehicle plugged in, when it wasn't. Exterior light seen to be rapidly flickering during fault, which eventually resolved. Electrical fault/ poor contact	Prefer not to utilise vehicle until ignition problem and stretcher fault is assesed
17-May-16	Vehicle	190	Notified OIC	Nil internal lights, emergency lights, siren or external step operation - ?nil ax. battery	-	-
17-May-16	Vehicle	190	nil	Load light not functioning	unknown	-
17-May-16	Vehicle	200	-	Leak in oxygen hosing for D size O2 cylinder. Alarm constantly sounding.	-	Oxygen cylinder turned on to add O2 to the hose, then turned off. This lasts approx 20 mins until the O2 leaks out and the alarm sounds again

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
17-May-16	Vehicle	185	SOS aware and he notified Comms therefore code 8	Unable to open rear door of vehicle. Rear door stuck on the right corner.	-	regular fault. Job number V 4437.
18-May-16	Stair Chair	215	Stair chair placed in shipping container with red sign advising service is overdue	Due for service on 13/05/16	Nil, just overdue for next service	Swapped out as per local practice.
18-May-16	Vehicle	210	Fault report completed	Left and right scan lights will not turn on	-	-
16-May-16	Defibrillator	210	contacted device technologies and logged fault contacted Qld agent and replacement Leads being sent to station asap.	Lead fault v6 not recognising in tester	unknown found on vehicle check	Should be here Friday at latest
18-May-16	Vehicle	215	Vehicle taken to mechanic for repairs.	Rear door not closing properly. Bottom left hand side of door not locking into place so can still be opened, even when rear door locked.	Unknown.	Vehicle taken to mechanic 18/05/16. Part being ordered.
19-May-16	Vehicle	215	Nil	Drivers side side mirror outer case cracked and mirrors slightly askew.	Driving through Hervey Bay airport hanger, went too close to roller door.	-
18-May-16	Vehicle	245	fault form completed.	Left side work light missing. Unknown when damaged.	unknown	Oic advised
19-May-16	Vehicle	200	-	1) Red handle missing from defibrillator cradle release catch 2) flashing beacons on bonnet have separated from double sided tape, still secured by bolts	-	-
19-May-16	Vehicle	250	Contacted CDS and mechanic. Mechanic assessed at Southport Station who consulted with stated they will look at the vehicle first thing 20/05/2016 at Burleigh Station.	O2 outlet has been broken at the pt head end.	The outlet was broken when swapping the regulator over to an O2 hose that was required for a ventilated pt transfer. The outlet has a slow leak of oxygen and unable to isolate it.	-
19-May-16	Vehicle	215	This report..	Power plug plastic cover is cracked.	Repetitive use?	Will need complete replacement
19-May-16	Vehicle	210	defect form	L) taillight not working	-	-
19-May-16	Vehicle	200	fault report, will also notify duty officer in morning.... Stretcher is still operational and can be used safely. Stretcher swapped out following day to have red switch repaired.	1) on 20% slope, after pressing red release button on stretcher deploy track, entire base of stretcher track deployed with gravity, causing incorrect deployment, and jamming of stretcher. Stretcher still locked onto base, and unable to be deployed.	Gravity caused entire locking mechanism to deploy incorrectly. Required accessing manual release switch on base railing to return track into vehicle, where it was able then to deploy correctly. 2) plastic cover for red switch noticed to be broken	2 faults noted, ? Related... Perhaps the cover for the red stretcher release button being broken, allowed the stretcher base to slide over the red button and deploy in an unusual manner, as the cover for the switch seems to normally contact a yellow hook.
19-May-16	Vehicle	200	booking vehicle into mets to battery checked.	Aux battery not holding charge, main control panel is black and says "ready for V-MUX download.	?? Auxiliary Battery	-

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
20-May-16	Defibrillator	210	I was asked to look for possible connection problems with all 3 devices. A loose connection was found on the defibrillator box and was asked to tighten a small screw.	Defibrillator was not charging.	Contacted corpuls technical service.	-
20-May-16	Defibrillator	210	Replacement leads organised	V1 Lead Broken Battery cover missing from test box Front legs does not fold out properly and needs assistance to lock in when removing from ambulance. Chest straps are Ferno straps that only adjust from one side to secure pt in and not from both side like the proper striker straps.	Unknown, returned from other station.	- Vehicle was returned from other station. vehicle check completed in preparation for next use, item found broken Corpus test box - battery cover missing
20-May-16	Stretcher	210	-	-	-	-
21-May-16	Defibrillator	220	CORPULS TAKEN OUT OF SERVICE AS IS UNIT 3250 AS VEHICLE HAS NOW HAS NOT DEFIBRILLATOR. A/SOS NOTIFIED	CORPULS BATTERY FULLY DRAINED. CORPULS NOT ON OVERNIGHT AND AT DAILY CHECK 20/5/16 CORPULS 608MINS REMAINING. CORPULS USED FOR 1XJOB 20/5 WITH NIL ISSUES. CORPULS NOT CHARGING IN BRACKET WHEN INSITU. BRACKET TESTED WITH OTHER CORPULS AND IS CHARGING.	CHARGING FAULT	- unit was not found to be faulty on testing, unit was recharged and was found to be operating correctly maintaining charge and operating to standards placed back into service after lengthy testing.
21-May-16	Vehicle	210	battery placed on charge To see if they will recharge to rule out faulty battery charger in vehicle.	Both batteries flat, spoke with fleet coordinator.	-	-
21-May-16	Vehicle	210	report submission	Cracked rear bumper (R) side near door	unknown cause or age. Noticed during pre shift inspection 21/5/16	-
21-May-16	Vehicle	185	nil	Rear door sensor faulty, emerg lights flashing with door closed. Sos notified. States can be used if 4wd required otherwise avoid use	?	job number V 4471. OIC Atherton - please notify me when vehicle is repaired.
21-May-16	Vehicle	185	Keep vehicle plugged in where possible.	LED light for retracting side step stays on at all times.	U/k	This is standard for the build vehicles.
21-May-16	Other Equipment	185	similar fault previously rectified by . Radio fault form submitted	Internally wired sat phone has no power, PTT is not connecting. This is the same fault that was fixed by (Cairns) 2 weeks ago with a software reset	? software issue	job number 4475. I will advise when this vehicle can be in Cairns for repair OR can you nominate a day please?
21-May-16	Vehicle	185	-	Rear barn door jamming and unable to open from the outside. Right hand rear sticking	- probably a blown bulb	job number V 4472. PLEASE NOTE : THIS UNIT DOES NOT HAVE BARN DOORS.
21-May-16	Vehicle	250	nothing	SRS warning light still on and passenger side headlight not working	unknown	-
21-May-16	Vehicle	185	.Bulb replaced	Passenger side headlight blown during a code 1 to Kuranda.	unknown	A/OIC has replaced bulb.
22-May-16	Vehicle	195	Contacted OCS	Module battery has been cooked, no power to module unless car is running	-	-
22-May-16	Vehicle	185	-	Vehicle slow to turn over, warnings low coolant and oil. High engine temp.	-	Job number V 4470
22-May-16	Vehicle	210	Fault report completed. Details recorded on daily vehicle checklist. vehicles off road sos notified.	Scan light switch on front panel not working. L+R scan lights not operational. Vehicle is slow to start and has engine warnings "high engine temp" and "low coolant" levels checked, oil is low as is coolant.	Unknown.	Vehicle still operational
22-May-16	Vehicle	185	notified.	low coolant" levels checked, oil is low as is coolant.	Unknown	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
22-May-16	Vehicle	200	Fault form completed. OIC will be notified on this coming Thursday. another spo2 probe tried, but blue fault light still blinking	Tyres are low in tread. <0.5cm from indicator line. Uneven wear.	-	unable to take photos, ipad not connecting to telstra, submitted on desktop.
22-May-16	Defibrillator	190		Blue machine fault light flashing	defective O2 sensor	-
23-May-16	Vehicle	245	-	Reserve battery not holding charge voltage drops below 8.6 while parked at hospital main battery voltage drops to 12.4 volts	-	-
22-May-16	General Equipment	245	Send hover jack back to at Brendale for repairs	Hover jack inlet inflation ports leaking around edges day shift crew found fault and advised night shift they did not complete fault form	General use	-
23-May-16	Vehicle	200	Nil, staff advised not to use vehicle for night transfers due to no driving lights	Driving/rear loading light switch on front control panel broken, unable to operate driving lights and rear loading light from drivers compartment due to same.	-	-
23-May-16	Vehicle	220	Have checked other vehicle and station base set. Have checked turning the master switch on during a transmission from Op centre and this is the mostly cause I can up with so far	Radio speakers not working when master/main switch is on. Op centre can still receive transmissions but vehicle radios silent.	No idea however the only thing different is a he corpus has been fitted this rotation and the master switch is being turned on prior to leaving residence and then radio check is being done	Vehicle operational at this point waiting on further advice from SOS . Master switch required to charge vehicle whilst on station and to run emergency lights during code 1, air cons, suction etc. sat phone and mobile are operational
23-May-16	Vehicle	185	indicator repaired	Left indicator faulty	unknown	Indicator bulb replaced
23-May-16	Other Equipment	210	Toughbook has been synced with cable network connection with nil effect. eARF support has been contacted and advised that if syncing did not repair then it would require return.	Toughbook AP8956 (CCP1) has multiple faults. Does not recognise pen, continually freezes, and loses network connection.	-	-
23-May-16	Vehicle	195	Taken to Kirwan in Kirwan	Wearing of rear tyres. Taken to flat tyre at Sandstone Drive. Kirwan in Kirwan this morning after a	Unknown	Gentleman at said he will give from Fleet a call as the other tyre needs replacing.
23-May-16	Vehicle	195	notified that VHF displaying disconnected. Advised to take to Kirwin QPS station to let radio tech assess	VHF Radio antenna disconnected	-	VHF not transmitting. Other radios working
23-May-16	Vehicle	200	Light removed from the housing and unplugged from the socket	Broken alley light drivers side rear	Light hit a tree	-
24-May-16	Vehicle	215	OIC has arranged service of vehicle with in Bundaberg.	40000 km service due. Module air conditioning unit low on gas.	-	-
23-May-16	Vehicle	200	None	Airway chair in back of car has a broken seat belt. The buckle does not undo once seat belt is clipped together.	-	Buckle got stuck twice today, the first time QAS were able to get the buckle off, the second time it was used it could not be taken apart.

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
24-May-16	Vehicle	210	Currently Completing necessary Paperwork	Vehicle taken out of service after Sustained Damage from hitting Kangaroo	Traffic Crash Vehicle vs Kangaroo	-
23-May-16	Vehicle	210	Submitting necessary Paperwork to have vehicle checks and fixed	Damage to Bullbar, fog lights, and mesh grill	Hitting a Kangaroo	-
24-May-16	Defibrillator	215	Taken out of service	Technical issue with the ECG reading - not diagnostic quality.	-	-
24-May-16	Vehicle	235	Vehicle was put in park	Failure to start	Vehicle was not in park properly	-
23-May-16	Vehicle	210	Has already been fixed (23/5/16) - airbag replaced with another	Driver's side suspension airbag broken	-	-
24-May-16	Vehicle	200	-	After 10-15 minutes of engine on, aircon on. Air stops coming out of vents, even at speed 4. Air con needs to be turned off for 5-10 minutes before it works again. Will only work again for 10 minutes. Same fault found in 2294	-	-
24-May-16	Vehicle	200	-	Air conditioning turns off after a period of time on its own. Fan continues to run, however little air comes out of the vents regardless of what the fan speed is set on.	-	Same fault found in 2117
24-May-16	Vehicle	185	notified sos/oic	Aux/2nd battery fails immediately if car not turned on or plugged into power, radio equipment & lights cut out.	The car has too many communication devices that may drain the battery. Removal of communication devices could prevent the 2nd/aux battery from failing	Job number V 4480
25-May-16	Vehicle	200	-	Leak in washer wiper fluid reservoir and Garmin GPS not operating.	-	-
24-May-16	Vehicle	245	Fault form completed OIC informed, vehicle taken out of service until repairable.	Both batteries flat upon attempting to prepare vehicle for shift. Charging cable was plugged in.	Broken 240V converter inhibiting the vehicle's ability to be charged.	Vehicle located in bay at station, if it needs to be seen at mechanic will need towing (or jump start). Otherwise does not require towing from dangerous or other location.
23-May-16	Vehicle	235	silicon spray. So far no effects noted	Rear door cannot be opened without using the internal handle.	-	-
25-May-16	Stretcher	190	liaising with lasn office.	Legs at head end are "sticky" - Slow to extend.	unknown.	damage/stress noted to stretcher - liaising with LASN office.
25-May-16	Vehicle	195	-	1) Cable loose on back of GPS, navigation still works 2) Siren can not be changed to different tone	-	-
25-May-16	Vehicle	210	The loose part of the muffler was removed and vehicle was driven the short distance back to plant room floor.	Part of muffler fell off vehicle	? While driving out of station a very loud scraping sound was heard. Vehicle pulled over for inspection and part of the muffler was hanging from under the vehicle.	-
26-May-16	Vehicle	210	Nil	R) Headlight out.	Unknown	-
26-May-16	Vehicle	210	Restarted, sim card removed and re-entered, screen cleaned.	Fault with GPS unit touch screen in vehicle. When attempting to enter an address and press the screen, where you push is not where the screen registers. It is about 2-3cm off to the side - unable to enter address.	Unknown.	-
26-May-16	Vehicle	235	-	Side access door to equipment is unable to be opened using the button, door has to be opened from inside.	-	car is operational but access to emergency equipment is hampered.
26-May-16	Vehicle	235	Oic notified	Rear door not opening, catches on passenger side load noise coming from under bonnet seems to be getting worse	Continuously happening	Can open the rear door from inside but this increases the hazard
26-May-16	Vehicle	195	Sent for repairs	Side step not working	.? Mechanical failure	Contacted OCS, ver taken out of service.
26-May-16	Stretcher	220	stretcher removed from service and isolated till repairs can be made	Runners on leg raising mechanism on top part of stretcher (to elevate patients legs) have fallen apart and can no longer be operationally used	unknown	Stretcher came from Morven unit and transferred during a hot case to a Charleville unit. Nil patient involvement. Hazard identified during daily check and immediately isolated.

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
25-May-16	Defibrillator	180	Paper checked. Door to paper checked. OIC informed.	When printing 12 lead ECG leads III, AVF and lead 6 not printing completed so cannot be used for diagnosis purposes.	-	-
26-May-16	Vehicle	185	Vehicle now with for repair.	A/C not working and no emergency lights or siren working due to fault with main switch.	Unknown electrical problem.	Compressor unserviceable. ordering new. V 4482. job number V 4484. Oil topped up (previous service 28/3/2016 at 135,000klm.
26-May-16	Vehicle	185	visiting to top up oil	Low engine oil	Normal use of the vehicle	
26-May-16	Vehicle	230	Reported to OIC, completed DVR, Will call into ?Monday to see if it can be quickly replaced.	Rear right door holding latch snapped off	Unknown	-
27-May-16	Vehicle	210	N/A	Only one onboard torch is working. Also, the bracket holding the front centre radio speaker has had one arm broken off: the speaker still functions normally, but is no longer secured by bracket.	unknown. Due to torch charging stations not having a light to indicate 'charging in progress' it's very difficult to determine whether it is the torches that are broken or the charging stations themselves. Speaker is located at floor level. ?kicked.	-
27-May-16	General Equipment	250	Contacted EARF support. They informed to plug in to which was done for 30mins with no change	Toughbook does not have VACIS program.	-	OS informed . Replaced
26-May-16	Vehicle	200	OIC has been notified, plan being made to rectify fault	The "DRIVE/REAR" switch is faulty	Whilst turning the DRIVE lights on during a transfer, the switch came loose and completely pulled out of the panel. It was all put back together but there is no connection therefore there is no activation of DRIVE lights or REAR light	Fault does not incur any operational concerns
27-May-16	Vehicle	240	As fuel tank not empty, vehicle was turned off and on several time per manual	Engine light on dashboard indicating problem with fuel system	-	-
27-May-16	Vehicle	210	N/A	Reversing camera screen in driver compartment has a screw missing that attaches screen to its stand, causing it to slide off of stand while vehicle is moving	unknown.	-
27-May-16	Vehicle	210	-	Corpus charging cord in vehicle is split it still charges corpus at this time	-	-
28-May-16	Other Equipment	235	-	Missing pager, missing torch, interior front light not working, no Caltex card, no pat slide	-	Loan unit 603685
28-May-16	Vehicle	250	Call os	Crack to windscreen	Unknown. It was like this at start of shift.	-
28-May-16	Vehicle	195	Nil - OCS and Duty SOS advised of vehicle unserviceability	Rear airbags fail to raise - Air pump heard to be working	Intermittent fault no longer intermittent	-
28-May-16	Vehicle	250	sos notified, coolant level checked and default form done	Coolant light appeared on dash and continuous beeping. Coolant level checked at beginning of shift and at Robina at approx 1500 with sos. Coolant level normal. ? Faulty alarm.	No	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
28-May-16	Vehicle	195	Plastic step has been placed in vehicle as a temporary replacement. Not as strong though so unsure of safety.	Side step intermittently does not work.	-	-
28-May-16	Vehicle	190	OIC Notified	Smashed R) side mirror	Driving on the highway from SE in Cloncurry when a big bird flew into it. Nil other damage noted.	-
28-May-16	Vehicle	200	have taken 117 to last night to fix an air conditioning problem. He doesn't have a spare part and says to get a part locally at in Cannonvale . Will leave for OIC to do on Monday	Broken R fog light	unknown	-
29-May-16	Vehicle	210	vehicle placed on charge on station and visualised under the bonnet to see if problem could be identified - unable to detect.	Engine sluggish to start this a.m. Going from residence into station. Audible ticking/tapping noise coming from the engine.	Unknown, nil issues with the vehicle yesterday.	-
29-May-16	General Equipment	210	Vehicle has been on charge for 12 hours without use.	Two way radios not working.	???? Faulty battery	-
29-May-16	Vehicle	190	notify oic	One torch missing	-	-
29-May-16	Vehicle	210	Vehicle is now on station and plugged in for charging. Audible noise can still be heard coming from engine. SOS notified, vehicle is non-operational until checked.	Sluggish to start this morning (vehicle is used for E.A.). Audible ticking/tapping noise can be heard coming from the engine.	Unknown, vehicle was operational yesterday with nil problems.	-
28-May-16	Vehicle	185	Auto electrician	Rear door not opening properly. R latch faulty, possible loose cable not releasing latch. Also vehicle inverter not working properly...power board switch tripping, reset a number of times, not staying on.	Gremlins	Vehicle responsible however not for transfers requiring 12 v cabin power for equipment. Door able to be released from internal lever, however not ideal.
29-May-16	Vehicle	235	Fault form lodged. Staff at station notified.	Broken clear plastic cover over R side view mirror indicator. Front bumper and rear right indicators are still working post incident however the right indicator speed in now increased. Incident occurred due lack of maneuvering space at case scene.	Difficult driving location / tight parking location / greater than usual obstacles to avoid.	-
28-May-16	Stretcher	215	Taken out of service	Red release handle sticking and foot end legs not lowering	-	TBA
28-May-16	Vehicle	215	-	Tire pressure warning light on and beeps Left initiator light out	-	New vehicle number 4414
29-May-16	Vehicle	185	-	Sidestep will not come out	unknown. Started shift to find it not working	Cairns OIC has reset the step - working fine.

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
30-May-16	Vehicle	185	and contacted. has a sensor - will be delivered to Tully QAS this afternoon. JOB NUMBER V 4496.	Front right the pressure gauge not working	-	JOB NUMBER V 4496. - PLEASE ADVISE ME WHEN THE SENSOR HAS BEEN REPLACED.
30-May-16	Vehicle	185	nil	Side step not working creating a work safety problem	no	Vehicle is to be bought to for replacement step to be installed, repairs were carried out on 26/5/16 (document however step has failed again. Job numver V 4497.
30-May-16	Vehicle	210	I've changed the tyre with the spare.	Tyre puncture (rear, driver's side). It appears to be from a small (sharp) rock. Air hissing from the site. Pics attached.	A rock	The vehicle can be used if required, but I've swapped to the other vehicle because I'd prefer not to use the vehicle without a spare tyre. Current tyre is a Bridgestone Dueler.
28-May-16	Vehicle	210	barn door is opened fully around to the car to reduce the door from coming back and pointy bit of stay bar left moved inwards as to not catch on anything	Stay bar on drivers side rear barn door broke	nurse attempted to close it without releasing the bar	During vehicle check the Thursday before I found that the bar was slightly already bent but could still clip into place
30-May-16	Vehicle	215	used the brakes on multiple occasions. Completed this form	Right rear brake light fail	It's all	fault
30-May-16	Vehicle	210	-	Left side patient access door will not unlock/open without the use of a key.	-	-
30-May-16	Vehicle	190	-	Top draw near treating seat has been Brocken	-	-
30-May-16	Vehicle	190	Pending new seatbelt to be ordered and installed. It will be checked by MI workshop in case of easy repair.	Air way seatbelt not retracting	-	-
30-May-16	Vehicle	190	New siren being posted to station for installation	Siren not turning on	-	Being stalled by Mornington island workshop
30-May-16	Vehicle	190	New siren being posted to station for installation	Siren not turning on	-	Being installed by Mornington island workshop
30-May-16	Vehicle	185	swap vehicles when on station next	Query faulty auxillary battery, radios turning off when car off. Completing check when given job. On completing iPad checklist stated vehicle non operational. Bonnet not lifted, no notes left on station.	Unknown	Vehicle operational if left running, radios malfunction only when car off only. job number V 4500.
31-May-16	Vehicle	210	N/A	GPS won't stay on Power problem, initially stating low battery when mains and car on	Unknown	-
31-May-16	Vehicle	235	Fault form	Only one torch	Spare unit	-
31-May-16	Defibrillator	185	Placed back on cables, fell off again. Now in top draw of defibrillator check draws.	ECG cable holders fall off	-	A second set of holder was also on the draws, suggesting another Corpuls3 is without one set.

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
31-May-16	Defibrillator	185	Placed back on cables, fell off again. Now in top draw of defibrillator check draws.	ECG cable holders fall off	-	A second set of holder was also on the draws, suggesting another Corpuls3 is without one set.
31-May-16	General Equipment	250	report- replaced. Operational	6692 fire extinguisher missing	-	-
31-May-16	Vehicle	220	reported the fault	Strap to secure battery was not attached	Unknown cause. Assume the it had not been attached from service.	fault fixed by officer notification only
31-May-16	Vehicle	210	Contact OIC	The side step that automatically opens at the back of the ambulance no longer slides out automatically	Unknown	-
31-May-16	Defibrillator	215	OIC notified, Defib taken out of service immediately.	Defibrillation pads not registering when plugged into monitor and in manual defibrillation mode. Defib pad socket/port issue?	N/A	Unable to obtain serial number at time of creating this form.
31-May-16	Vehicle	210	yes fixed the issue changes switch mechanic aware	Headlight flasher light switch broken	unknown	All works well now after being fixed
17-May-16	Vehicle	225	N/a	Star to the front windscreen, Lh side under wiper blade path	unknown	-
1-Jun-16	Vehicle	200	Load light still activates using other switches, unable to activate "drive" lights	Vehicle rear load light/drive light switch in console not working, switch no longer "clicks" and light does not turn on.	Unknown when and how it occurred.	OIC aware.
1-Jun-16	Vehicle	185	-	Oxygen low pressure alarm not working in rear of vehicle, nil issues with oxygen flow, red light works however nil siren	-	authority number V 4509.
1-Jun-16	Vehicle	225	-	Side step not working	-	-
1-Jun-16	Vehicle	215	Nil	GPS no longer working, does not identify streets and does not identify towns. Rear left door stay snapped off	Nil	LH door stay has been replaced
1-Jun-16	Vehicle	185	Keeping the car running or plugged in at all times	Aux battery failure when car plugged in or not turned on	-	RRC has spoken to OIC. Edmonton staff have been advised to keep vehicles on charge all the time.
1-Jun-16	Vehicle	210	email Oic	Yellow door stay snapped off R)rear door, therefore door cannot be held open.	Whilst securing the vehicle onscene, the stay must have come out of its holder, because when the door was opened back up, it was broken.	The vehicle is still operational.
1-Jun-16	Vehicle	245	When this fault is checked again the vehicle needs to be accelerated aggressively to see if it is able to do so. Seems to drive ok when going very gentle, but problem is obvious when mimicking emergency response.	Flashing check engine light. Major problems with acceleration. Able to accelerate normally at low speed and with minimal throttle compression. But when moderate or full throttle pressure is applied the vehicle quickly ceases accelerating.	-	-
1-Jun-16	Vehicle	230	no action at this stage as after hrs	Upon Completion of shift and whilst driving back to station, crew have noticed vehicle warning lights come on, also vehicle speedo has stopped working	-	vehicle is still driveable and not in limp mode, just no speedo
1-Jun-16	Vehicle	185	None. Requires new bolts and the Emergency light mounting checked for damage.	Emergency lights retaining bracket - front- drivers side - bolts missing.	Uncertain - abnormal angle of light bar noted on vehicle cleaning this PM - likely cause is low hanging branches	Emergency light assembly working as normal but unsafe for operational use until checked by Thursday morning 2/6/16. On duty Officer has swapped into Unit 7311 for EA tonight. job number V 4508.

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
1-Jun-16	Vehicle	180	-	Right/Left Work light switch in control panel not working	-	Will require auto electrician to check, new switch maybe required.
2-Jun-16	Vehicle	210	-	Rear boot door gas struts not working completely, hand brake poor function, right front blue grill light not flashing	-	-
2-Jun-16	Vehicle	195	Turn on and off	Air conditioning not turning on at mains switches for rear cab aircon	No	-
2-Jun-16	Vehicle	210	GPS reset	GPS - Maps don't always load, ?memory full Defib door - Several screws loose Windscreen wipers need replacing	-	-
2-Jun-16	Vehicle	215	Checked switches	Step into rear compartment of ambulance stuck in the out position	Unknown	Step is sticking out
1-Jun-16	Vehicle	210	Vehicle taken to by arvo crew and new tyre put on	Front driver side tyre flat	Metal piece in inside wall of tyre	Vehicle now operational
2-Jun-16	Vehicle	195	Repair contractor / Fleet Mgr review	After driving from Kirwan Station to Northern Beaches Station Vehicle has strong odour ? Hot Clutch like smell with noise emanating from under bonnet ? Air-conditioning compressor pulley.	? As Above description - Air-con compressor	Unit is now repaired
2-Jun-16	Defibrillator	235	ECG cords look intact and conections look good.	D-ECG slow to respond, each time 'Start' pressed the rhythm disappears and dotted line occurs. It then does not print.	?	This is the only spare Defib at this rural station. It had good battery life in it when fault was occurring.
3-Jun-16	Vehicle	195	Nil	1) Windscreen washers non operational 2) Reversing camera display on dash shows very poor unclear display	Unknown	As this is a single officer vehicle, the camera display is important for safe reversing!
3-Jun-16	Vehicle	210	Corpuse charging cable has been replugged back in, though it still will not charge Corpuse.	Corpuse charging cable faulty. Will not charge corpuse even when plugged back in.	Looks as if it has been accidentally ripped out from power plug socket. Socket housing has minor damage where the screw holes are.	-
3-Jun-16	Vehicle	235	-	Reversing camera is not working.	-	-
3-Jun-16	General Equipment	225	reporting there is another torch in this unit being used.	Torch not working and not charging	unknown	Torch is not charging and not turning on.
3-Jun-16	General Equipment	225	Reported to eARF Support	Toughbook Asset number TB000153 not working	Unknown, will not turn on at all	Awaiting arrival of replacement Toughbook from eARF Support. Approx. 30 other replacements in line before Oakey unit.
3-Jun-16	Vehicle	235	Taken off road	Electrical accessories turning on and off lights and sirens turning on and off randomly. Electrical accessory switch panel all lights illuminating and flashing when side door opened and closed ? fault in door.	-	Left at back of plant room
3-Jun-16	Defibrillator	195	Unplug Defib pads went out of d-ecg screen and we to back to home screen then went back to D-ecg screen only lead two had tracing Double checked limb leads where attached to apt.	Unable to obtain 12 lead ECG only lead two showing. Defibrillator pads on pt .Defib pads unplugged but still only showing lead two	Unknown	CCP contacted OIC and ops supervisor.taken out of service and tried on test box at station swapped for exchange Monitor.
3-Jun-16	Vehicle	235	-	Airbags in rear would not pump up while on a case.	-	-
3-Jun-16	Vehicle	250	vehicle taken out of service	Air suspension not lowering when either front or rear buttons pressed	don't know	-
4-Jun-16	Vehicle	210	-	Low beam lights not working	-	-
4-Jun-16	Vehicle	210	vehicle defected	Low beam not working	-	-
4-Jun-16	Vehicle	210	nil	L) headlight out and front interior reading lamp out	unknown	-
4-Jun-16	Vehicle	200	-	Door seal for oxygen separating from vehicle. Door also not locking properly and has come open on multiple occasions when driving. Door for kits not connecting to magnet when open.	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
3-Jun-16	Other Equipment	210	-	Unit 2479 plastic cover next to clutch has come off. Officer vacuuming vehicle and noticed it moved and that it was only placed there and not glued to floor.	-	Plastic cover removed for driver safety, Unit 2479 still operational.
4-Jun-16	Vehicle	200	nil	Missing/ broken radio handset clip (rear)	unknown , found when checking vehicle	-
4-Jun-16	Defibrillator	235	Monitor taken off road, Place outside drug room at Ipswich station and replaced with another monitor in 6605.	Printer not working	unknown	-
5-Jun-16	General Equipment	185	Nil	X2 Torches missing from 7162.	Unknown	OIC Cairns to locate torches. Nil torches available at the moment, on order.
5-Jun-16	Vehicle	200	completed fault report.	Crack in windscreen drivers side. Over 150mm long, car not roadworthy.	small starring in windscreen outside of drivers view has developed into a crack during my transfer to mackay from PDH tonight.	-
4-Jun-16	Vehicle	215	-	Battery and other dash lights illuminated whilst driving vehicle at night .same problem same situation as last two faults	alternator failure	-
5-Jun-16	Vehicle	210	Nil so far / Unit is operational.	Aerial on the left hand side of the vehcile - seems to have been broken off at the base / missing. All communications are operational.	Unknown.	Need for radio / communications techs to attend and review damage and repair.
5-Jun-16	Defibrillator	210	As directed by SOS SpO2 monitor cable had been replayed by education monitor (CEU2) SpO2 cable; Serial NO: DFIB0736	SpO2 monitor cable not working	Unknown	-
4-Jun-16	Vehicle	215	-	Drivers side floor awash with water after heavy rain cause unknown no obvious leaks	-	-
5-Jun-16	Vehicle	195	Fault report completed	Vehicle pulling to left while driving	Unknown	May require wheel alignment?
5-Jun-16	Defibrillator	215	Taken off road, OIC notified.	Corpuls states 'check therapy electrodes' when defibrillation pads are connected. This is the 2nd time this week I have found this issue with defib. Unsure whether it is same monitor?	N/A	-
5-Jun-16	Vehicle	195	Called SOS and CCs	Engine light came on when starting car at hospital	Unknown	-
6-Jun-16	Vehicle	230	-	test	-	test
6-Jun-16	Vehicle	215	-	Garmin satnav not working Driver's seat height not adjusting Rear view mirror not attached Patient care chair missing left arm rest Patient care chair right arm rest missing padding off end - could cause skin tear to patient	-	Garmin Satnav not working at all
6-Jun-16	Vehicle	180	Vehicle awaiting parts for repair at	Switch for side lights on main control panel not working. Rear control panel working intermittently. Rear cabin camera not working.	Wear and tear.	-
6-Jun-16	Vehicle	185	fault form and inform OIC	lights not illuminating - drivers side park light & orange guide light along side (near driver door)	n/a	OIC to arrange vehilce to got to for repair. V 4530.
6-Jun-16	Vehicle	200	Stopping vehicle to press cover and clean/ wipe inside cover to attempt proper seating of cover. Still intermittent fault.	External 240 V charge point intermittent fault. Plug pulled, car wont start until cover firmly pressed in and in transit/ driving warning alarm activated saying cover open when its closed.	? contact/ wiring defective.	Intermittent fault still activating alarm.
6-Jun-16	Defibrillator	245	Straighten cable	Faulty pulse oximetry cable	? Kink in cable	Corpuls is operational, pulse oximetry not

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
7-Jun-16	Vehicle	210	It needs re-glueing and flares need to be supplied.	Loose trim no flares otherwise ok.	Bumps in the road and old age.	-
7-Jun-16	Vehicle	195	Reported to PTO Dispatched, Fault form to OIC-Sth TVS	Side step is not working. Stuck in neutral.	Unkown	-
7-Jun-16	Vehicle	210	tested the door multiple times with out success. Using controls in cabin and the keys central locking.	Side door on rear of vehicle can not be opened from the outside.	unknown.	door can be opened by manually by inserting key into door.
7-Jun-16	Vehicle	235	-	FM/AM radio not working	-	-
7-Jun-16	Vehicle	235	-	Two small windscreen chip.	-	-
8-Jun-16	Vehicle	210	Will report to OIC and organise a time for the vehicle to go to the workshop	Both parking lights are out	-	-
8-Jun-16	Vehicle	185	Notified OIC	R tail light out L rear emergency light intermittent fault R front bonnet emergency light intermittent fault Whirring noise front left tyre Fan belt squealing H/light flasher switch missing Cabin fluoro light (above corpuls) falling off roof	Wear and tear	L rear emergency light intermittent fault, R front bonnet emergency light intermittent fault R tail light out - V 4534 F&R brakes - V 4532 Tensioners & Pulleys - V 4533.
8-Jun-16	Vehicle	225	vehicle booked in for gasket repair at DALBY on Friday 10/06/16 for repair	Fluid leak from front Diff Husing	gasket requires replacing	Normal wear / tear.
8-Jun-16	Stretcher	235	Stretcher removed from service. WTM Fleet notified.	Delay in legs locking whilst unloading.	-	-
8-Jun-16	Vehicle	210	Fault form	Rear light cover on passenger side broken.	Unknown. Found when loading patient into the vehicle. Not seen when doing vehicle checklist this am	-
8-Jun-16	Vehicle	235	None.	Rear drivers side door arm is broken off. Yellow arm that locks in to hold door open.	The door was pushed to close while the arm was still locked in.	-
8-Jun-16	Defibrillator	250	Tape used to attach to finger	Pulse oximetry finger probe broken.	-	-
8-Jun-16	Vehicle	250	-	side step not coming out, headlight not working passenger side. Light over number plate not working.	-	extremely difficult to get patients into the vehicle with no step - painful to step in and out of vehicle
9-Jun-16	Vehicle	235	-	Left headlight out	-	-
7-Jun-16	Vehicle	210	Unknown oic informed	Damage to l rear bumper bar	unknown	Photo submitted during yesterday's vehicle check
7-Jun-16	Vehicle	210	Unknown oic informed	Damage to l rear bumper bar	unknown	Photo submitted during yesterday's vehicle check
7-Jun-16	Defibrillator	210	-	When I went to defibrillate in wireless mode, the Corpuls on a number of occasions wouldn't recognise the Pads and on the screen it would say OJ. Further info in additional comments.	-	When Corpuls would recognise Pads, 200J would display; however, when charge was pressed on a few occasions it would not charge up and then all of a sudden the screen would show that it has full charge of 200J
9-Jun-16	Vehicle	195	Reported to OIC	Side step not retracting	Unknown	-
9-Jun-16	Vehicle	200	Fault form completed, Mackay LASN mechanic to be contacted	Emergency light bars on bonnet and roof have sections not working. On the bonnet - the first set of 3 red bulbs not working; on the roof the first 3 sets of blue bulbs not working	unknown	-

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
9-Jun-16	Vehicle	215	Tried switches etc but step stuck in.	Rear door step not working again	Nil	-
9-Jun-16	Vehicle	215	Dropped at mechanic	Fuel filter change required Air conditioning not working	-	-
8-Jun-16	Other Equipment	235	unable to rectify	Digital keypad not functioning correctly. Cannot use the "a" key or the erase button	-	will require urgent replacement
8-Jun-16	-	235	-	Airbags will not deflate	-	But makes it very difficult on crews to load and unload, placing additional strain on crew, particularly with heave patients.
9-Jun-16	Vehicle	235	Shown to who could not reproduce issue in a short period of time	Rear door catching, both sides at times, at times this will release when pushing inwards on rear door. This fault has been reported and repaired multiple times, please last report last week. Gwn radio speaker needs moving to centre of front cab.	Gravel and rough roads	Will monitor and if continues unit will be immediately taken off the road.
9-Jun-16	Vehicle	195	placed out of service	Aux battery not charging/holding charge	-	Vehicle UHF and rear interior lights turning off while driving
9-Jun-16	Vehicle	235	Discussed with SOS. SOS stated that a mechanic had checked the vehicle yesterday and the vehicle is still operational.	Vehicle making shuddering, clunking sounds.	-	-
10-Jun-16	Vehicle	195	-	Red LED light on bonnet cluster not illuminating	-	-
10-Jun-16	Vehicle	200	-	Engine light stays on has been taken to local mechanic who has put computer on vehicle system has indicated that number 6 glow plug has an intermittent fault.	-	-
10-Jun-16	Vehicle	200	reported to Mackay LASN mechanic	In vehicle suction unit intermittently not working	unknown	Easy to access portable suction unit if required
10-Jun-16	Vehicle	210	D size cylinder in front to remain turned off unless needed.	D size oxygen cylinders in vehicle have slow leak somewhere. Cylinder closest to drivers seat leaking faster than other.	-	Leak had been noticed over number of weeks with changes to multiple cylinders needed although no oxygen really being used on cases.
10-Jun-16	Vehicle	200	-	remote unlock button not working, battery replaced 9/6. still not unlocking or locking car despite extended push time or holding close to car.	-	-
9-Jun-16	Vehicle	235	-	Front cabin aircon only functions when vehicle is moving forward. pumps warm air when stationary. REAR MODULE aircon will not cool	-	Unable to use vehicle in current weather conditions
9-Jun-16	Defibrillator	235	currently taped to prevent further breakage	pulse ox intermediate cable broken	-	-
10-Jun-16	Vehicle	185	-	CRACK NOTICED TO R HAND SIDE OF FRONT WINDSCREEN APPROX 8CM'S IN LENGTH.	UNKNOWN, NOTICED WHEN CONDUCTING VEHICLE CHECK THIS AM.	job number V 4551. A/OIC Tully to necessitate repairs and report back to RRC on completion.
10-Jun-16	Vehicle	225	-	Module Battery Low	-	-
10-Jun-16	Vehicle	235	Fault form completed.	Passenger side mirror is cracked.	Cause of fault unknown - discovered upon logging onto truck for first time this set of shifts.	-
11-Jun-16	Vehicle	245	Started on the 6th attempt	Took 5 attempts to start the unit	-	-
11-Jun-16	Vehicle	225	Replaced bulb	R Headlight not working. Reported to day shift by night shift crew	-	-
10-Jun-16	Vehicle	245	Reporting via vehicle checklist and this vehicle fault report, writing on station vehicle whiteboard	During shift Left indicator started flashing at higher frequency and light indicating light fault turned on at all times. Car radio when pressing in talk button at times not responding to being pressed with the talk tone being delayed or not sounding.	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
11-Jun-16	Vehicle	245	Fault form, written on station vehicle whiteboard	Front Right main headlight blown, all other headlights and high beams working Back cabin light will not go into 'dim' function. Issues written on station vehicle whiteboard prior to starting shift- unsure if have been reported already.	-	-
11-Jun-16	Vehicle	225	Fridge to be looked during service booking.	Fridge non operational, 75000 Kim Service required	Nil	-
11-Jun-16	Vehicle	235	-	1. Second IV DRAW IS GETTING STUCK HALF WAY. 2. WINDSCREEN CHIP IN MIDDLE OF WINDSCREEN. 3. STEP NOT FULLY RETRACTING (nil obvious damage)	-	-
11-Jun-16	Vehicle	200	fault submitted, OIC will also be informed.... external power lead is known issue.	2 faults: 1) rural GPS screen non functional/corrupted display; 2) external power lead fault causing intermittent incorrect vehicle detected as still plugged in, so unable to start... However bypass switch still allows vehicle start.	general wear?	rural GPS non operational, second, inferior GPS still working. Unit is able to be started using bypass switch.
11-Jun-16	Vehicle	200	fault submitted, OIC will also be informed.... external power lead is known issue.	2 faults: 1) rural GPS screen non functional/corrupted display; 2) external power lead fault causing intermittent incorrect vehicle detected as still plugged in, so unable to start... However bypass switch still allows vehicle start.	general wear?	rural GPS non operational, second, inferior GPS still working. Unit is able to be started using bypass switch.
11-Jun-16	Vehicle	195	-	The front lights does not turn off unless turning off the car engine. The dash board control of front light is faulty.	-	-
11-Jun-16	Stretcher	225	Battery checked, stretcher replaced, fault form completed vehicle not used on EA, will remain in plant room plugged into power supply.	not charging properly. Intermittent green flashing light, periods with lack of charge light.	Unknown. ? Charge Issue	SHE report to follow Safety issue identified with malfunction occurring in Cherbourg community
12-Jun-16	Vehicle	200	-	Vehicle losing power within 3 hrs of not being plugged into external source. Warning sound (short siren noise) comes from vehicle with internal display panel flashing.	-	-
12-Jun-16	Vehicle	200	Nil	Rear airbag suspension failure. Vehicle is low to ground at rear end, bouncing when driven. Air suspension unable to be manually evacuated or inflated.	-	-
12-Jun-16	Vehicle	235	Removed from service to avoid electrical shorts as has previously happened with this unit. Video to be emailed to fleet tech.	Emergency lights and siren - control module failure.	Electrical fault	-
5-Jun-16	Vehicle	215	Equipment required will be discussed with fleet Widebay Only minor equipment required.	Some equipment missing from vehicle. Vehicle has just been returned from an extended time off road due to repairs.	-	Will be organised.
12-Jun-16	Vehicle	225	na	Requires 100,000 Kim service, will book at next week while I am on RDO,s as it will be at klm and is a month overdue by time?	Na	will pick it up and drop it back
12-Jun-16	Defibrillator	250	We have tucked the strap away	We had the corpuls machine sitting behind the head rest of the stretcher (where you can put Pt bags etc) and I went to lift the stretcher and it fell off causing a small clip to break. There are 2 straps that tighten the side bags, the clip on one of thes	-	-
12-Jun-16	Vehicle	245	-	Sudden fan belt noise followed by red engine warning light, power steering failure and high temp warning light illuminated. MDT now inoperative	-	-

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
13-Jun-16	Vehicle	210	Vehicle and Corpuls defected and removed from service.	Auxiliary power low. Corpuls battery critically low. Charging cradle in vehicle not working. Monitor & patient box components able to be charged using wall charger, defib box not charging. Vehicle insufficiently charged, side step not working.	Unknown, faults discovered during routine pre-shift checklist.	-
13-Jun-16	Vehicle	200	-	Cracked windscreen	Rock hitting windscreen	-
13-Jun-16	Vehicle	200	OIC (Proserpine) contacted Mackay workshop and organised vehicle to be repaired by Proserpine	Rear Airbags unable to inflate.	Unknown	Unit is attached to Bowen Station. ACPII arrived at Proserpine Stn on 12/06/16 with Unit and advised OIC of fault. was in the process of IHT and removed pt and Took over unit 2492. Unable to contact workshop due to weekend.
13-Jun-16	Vehicle	195	Nil	Right headlight is blown	-	-
11-Jun-16	Vehicle	185	ADVISED READINESS CO-ORDINATOR AND TIME TO BE SET FOR REPAIRS WITH OR LOCAL AUTO ELECTRICIAN	REVERSING CAMERA IS ONLY WORKING PERIODICALLY, NOT AT ALL THIS MORNING	NOT KNOWN BUT THIS HAS HAPPENED IN THE PAST	JOB NUMBER V 4552. OIC Babinda: can this unit be bought to Miles on Thursday 16/6/16?
11-Jun-16	Vehicle	185	SPOKE WITH MECHANIC WHO BRIEFLY INSPECTED AND ADVISED TO GO FOR REPAIR ON 16.6.16	GPS SYSTEM NOT WORKING - DID BRIEF INSPECTION AND ADVISED NEEDS REWIRING (REBOOKED FOR 16.6.16. SAT PHONE APPEARS NOT TO BE CHARGING	NOT SURE, THE GPS WAS ONLY REPLACED WITH A NEW ONE LAST MONTH - ? WARRANTY JOB FOR THE GPS job number V 4553.	-
9-Jun-16	Other Equipment	235	tried to charge it , removed battery reinserted.	sat phone will not charge.	-	-
13-Jun-16	Other Equipment	200	'Out of order' sign placed on GPS. Officers to utilise local council maps.	GPS not responding to touch screen. Screen appears to be not synchronised with 'select' buttons. Unable to use navigation component.	Unknown	-
13-Jun-16	Vehicle	225	Fault form recorded, OIC notified, vehicle for service tomorrow 14/6/16	Wall mounted suction intermittently working, ? Fuse fault. Missing 1 x torch. L) high beam driving light blown	-	-
13-Jun-16	Vehicle	210	Nil. Does not want to remove nail from tyre because tyre might leak air after removal. Does not appear if air is leaking from it currently	Nail in R rear tyre	-	-
13-Jun-16	Vehicle	210	Nil. Does not want to remove nail from tyre because tyre might leak air after removal. Does not appear if air is leaking from it currently	Nail in R rear tyre	-	-
13-Jun-16	Vehicle	240	informed OIC	Passenger side front LED auto front head lights blown bottom one	nil	Vehicle currently at when returns. TBA Will be sent to for warantee repair

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
13-Jun-16	Vehicle	190	Reporting.	FAULT ONE: Reversing Camera is always on - Whole time while driving, regardless of what gear the vehicle is in. FAULT TWO: The rear radio/phone bracket is broken. The rear radio/phone just flies around in the truck.	Unknown.	-
13-Jun-16	Vehicle	250	NIL	Corpuls charging cradle not locking into bay. Keeps rocking around and slamming into door while turning corners. No yellow door stops on rear doors. Steering vibrations driving above 100kmphr.	NIL	-
13-Jun-16	Vehicle	235	-	3rd console drawer won't fully extend and side door step won't extend fully	-	-
13-Jun-16	Vehicle	195	Tried override switch and restarting the mains.	Side step not working.	-	-
14-Jun-16	Vehicle	250	-	Headlight globe blown	-	-
14-Jun-16	Vehicle	235	Informed mechanic	While driving vehicle there was a distinct burning smell noted crew ? Battery issue	? Battery	Vehicle is on the plant room floor bonnet it up and is out of service
14-Jun-16	Vehicle	225	oic to use vehicle	Side step not functioning	-	-
14-Jun-16	Vehicle	225	-	bracket that attaches combicarrier to the roof, snapped from roof.	Driving vehicle and combicarrier fell from roof, bracket found snapped	combicarrier now located on top of stretcher, not attached to vehicle roof.
13-Jun-16	Vehicle	215	-	VHF radio microphone not working. Can hear Comms but they can not hear us, nil light not.	-	Notified OIC
14-Jun-16	Vehicle	185	-	Battery draining low when vehicle is at scene or at CBH. Comms Radio turning off and unable to be turned back on until vehicle running. AM/FM radio not working at all. Inside of Vehicle smells like exhaust when running.	-	OIC to take unit to for inspection/replacement (V 4562). IF comms are still playing up OIC to log job with PSBA. Please notify RRC when repairs completed.
14-Jun-16	Stretcher	195	-	-	-	-
14-Jun-16	Vehicle	215	Reported	Dented passenger front rim	-	-
13-Jun-16	Vehicle	250	Flow meter to stop leak	Rear oxygen connector leaking requiring flow meter to stop leaking	Discovered yesterday	If removed it will drain oxygen store.
15-Jun-16	General Equipment	195	replace or tighten	Top drawer lock in patient care area in back of vehicle is constantly coming loose and opens in transit.	faulty lock	nil
15-Jun-16	Vehicle	200	Nothing so far. Unsure if it has been reported before today.	The light Above the attendant seat in the back of the car leaks onto the officer when it is raining.	-	-
15-Jun-16	Vehicle	225	OIC notified	Side step not working Headlights not working	-	-
15-Jun-16	Vehicle	185	Notified sos. Plugged into outlet	Vehicle not starting ?flat battery	Vehicle unplugged	A/OIC Innisfail - please advise which battery is failing, have vehicle taken to for repair and report back to RRC when complete. Cheers V 4561.
15-Jun-16	Vehicle	225	-	FEI U007 - Brake Hose replacement	-	-
15-Jun-16	Defibrillator	250	Equipment has been taken off road	Oxi cable defective and CF card almost full	Not known	-
15-Jun-16	Vehicle	200	Replacement of tyres	All four tyres have approached the indicator line, well over the line.	Wear and tear	-
15-Jun-16	General Equipment	225	fault form lodged	One Torch missing.	unknown, presumed left on a scene?	Unknown how long torch has been missing.
15-Jun-16	Vehicle	200	Repair of damaged section	Damage to indicator section of drivers side mirror.	Unknown how damage occurred, found during daily checks, unsure if previous officers completed fault report.	-
15-Jun-16	Vehicle	225	Nil	1. Heater in rear module not enough air flow 2. Rear module doors not opening unless unit running	1. unknown 2. ?voltage drop, batteries check ok 2 mths ago	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
14-Jun-16	Vehicle	185	TESTED THE SIREN - CHECKED ALL CONNECTIONS NO LOOSE OR DISCONNECTED WIRING - SPOKE TO AUTO ELECTRICIAN	SIREN NOT WORKING PROPERLY - THE MIX FUNCTION DOES NOT WORK ANYMORE ONLY WAIL OR YELP	UNKNOWN	TO BE CHECKED BY TOMORROW 16/06/2016. V 4564.
15-Jun-16	Vehicle	235	NIL	UNIT RADIO NOT WORKING	UNKNOWN	RADIO WILL NOT SWITCH ON.
15-Jun-16	Vehicle	235	Sirens tested multiple times. Mains switched on/off.	Sirens ceased to function whilst driving code one.	-	-
15-Jun-16	General Equipment	195	-	Thermometer not working. Batteries were changed with no effect. Thermometer is now in Townsville OIC in tray.	-	-
15-Jun-16	Vehicle	185	nil	Radios/lights stop operating when vehicle not running for any length of time. Possible faulty battery	unknown	Operates fine with car running
16-Jun-16	Vehicle	235	Notified oic	Front driver side lower bumper light not working	-	-
16-Jun-16	Vehicle	235	-	Left side mirror found smashed by previous crew.	-	-
10-Jun-16	Vehicle	245	-	Right headlight low beam out	-	-
16-Jun-16	Vehicle	225	booked in to for service on 16 June 2016	85000 km service	-	PTO drove vehicle to Toowoomba for service whilst attending PSO workshop
8-Jun-16	Vehicle	215	nil	Refrigerator in vehicle not working.	N/a	-
16-Jun-16	Vehicle	185	removed device from port	Front dual 240v/cigarette lighter port not functioning	Might be an issue with the cords, as the charger for the Navigational device still works when plugged into the port	this is needed so that charging of the toughbook and Navigation can function
16-Jun-16	Vehicle	225	-	Requires regular service and repair of previously reported electrical side step	-	-
16-Jun-16	Defibrillator	210	called spoke with tech and did check confirming the lead not the machine. Tech confirmed fault and is sending a replacement lead. Should be here in about 2 days	Net co2 lead not registering on machine in 2115	faulty lead	-
16-Jun-16	Stretcher	225	AREA SPARE AT KINGAROY SOURCED TO BE REPLACED	SERVICE DATE OVERDUE	-	RRC NOTIFIED AND AND OUT OF SERVICE TAG ON STRETCHER
16-Jun-16	Vehicle	215	Arranged servicing with 21.06.16	70,000km service due.	-	-
16-Jun-16	Vehicle	240	checked by and OS on shift	Power to MDT keeps spontaneously cutting out - despite being on charge overnight.	AUX battery has been checked by - who state is working properly	-
16-Jun-16	Vehicle	210	Put a fault report in and emailed OIC	Crack in the middle of the windshield	Query rock	-
16-Jun-16	Vehicle	185	-	Side step not functioning and cable loss and hanging from inside door/step area	-	OIC taking vehicle to for repair even date. V 4583. Seat height adjustor missing, wiring exposed from sliding door OR side step.

RTI RELEASED

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
17-Jun-16	Vehicle	195	SOS notified immediately. Crew changed to different vehicle. Vehicle tagged out of service.	Vehicle currently has no module power. Lights, sirens, vehicle radio not working.	Module power was left on and despite being plugged in and turned on it seems to have not charged. Module battery fault.	-
16-Jun-16	Stretcher	235	Nil	After sliding empty stretcher back into vehicle, the stretcher would not lower into locking cradle. Stretcher removed and reloaded with identical response. Stretcher removed and replaced a third time, with stretcher finally lowering and locking.	Unknown	-
16-Jun-16	Vehicle	225	-	FEI U007 - Brake Hose replacement	-	-
16-Jun-16	Vehicle	225	-	FEI U007 - Brake Hose replacement	-	-
16-Jun-16	Vehicle	225	Unit has been repaired	FEI U007 - Brake Hose replacement	-	-
16-Jun-16	Vehicle	225	-	FEI U007 - Brake Hose replacement	-	-
16-Jun-16	Vehicle	225	-	FEI U007 - Brake Hose replacement	-	-
16-Jun-16	Vehicle	225	-	FEI U007 - Brake Hose replacement	-	-
16-Jun-16	Vehicle	225	Booked into for 30/06/2016	FEI U007 - Brake Hose replacement	-	-
16-Jun-16	Vehicle	225	-	FEI U007 - Brake Hose replacement	-	-
16-Jun-16	Vehicle	225	-	FEI U007 - Brake Hose replacement	-	-
16-Jun-16	Vehicle	225	-	FEI U007 - Brake Hose replacement	-	-
16-Jun-16	Vehicle	225	-	FEI U007 - Brake Hose replacement	-	-
17-Jun-16	Vehicle	185	from inspected step at QAS Gordonvale 16/06/2016 and step operated for a short period.	Retractable side step not operating normally, will operate sometimes if over ride switch is toggled.	Possibly due to mud and grit in slide tracks.	-
16-Jun-16	Vehicle	225	-	FEI U007 - Brake Hose replacement	-	-
16-Jun-16	Vehicle	225	-	FEI U007 - Brake Hose replacement	-	-
16-Jun-16	Vehicle	225	-	FEI U007 - Brake Hose replacement	-	-
16-Jun-16	Vehicle	225	-	FEI U007 - Brake Hose replacement	-	-
16-Jun-16	Vehicle	225	Unit has been booked in for repairs	FEI U007 - Brake Hose replacement	-	Unit getting serviced while at mechanics
16-Jun-16	Vehicle	225	-	FEI U007 - Brake Hose replacement	-	-
16-Jun-16	Vehicle	225	-	FEI U007 - Brake Hose replacement	-	-
16-Jun-16	Vehicle	225	-	FEI U007 - Brake Hose replacement	-	-
16-Jun-16	Vehicle	225	-	FEI U007 - Brake Hose replacement	-	-
16-Jun-16	Vehicle	225	Booked into to have hose replaced and a service on the 07/07/2016	FEI U007 - Brake Hose replacement	-	-
16-Jun-16	Vehicle	225	-	FEI U007 - Brake Hose replacement	-	-
16-Jun-16	Vehicle	225	-	FEI U007 - Brake Hose replacement	-	-
17-Jun-16	Vehicle	215	Organised service and repairs for the 23/06/16.	90,000km service. Check faulty glow tube. Replce mirror cover	-	-
17-Jun-16	Vehicle	225	Cleaned power inlet cover - had dirt clogging release button	240v Power inlet plug cover sticks and opens sometimes and hard to open or stuck unable to open othertimes	plug cover	OIC to monitor

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
17-Jun-16	Vehicle	240	Vehicle taken to after incident and parts to be ordered and mirror will be fixed on Monday 20th June as vehicle is due in for a service. Vehicle out of service over weekend.	Right review mirror is damaged - blind spot mirror and back of mirror broken completely and remaining glass cracked.	Vehicle was parked outside a patient's house and while crew were inside someone has hit the right review mirror and damaged it. Crew found mirror to be damaged once they had taken the patient out to the vehicle and no note was left.	Case number: 07710366 Vehicle was parked close to curb. OIC has photos of vehicle when parked outside residence.
17-Jun-16	Vehicle	225	Continually shut door.	Battery door on module not opens whilst driving. Latch not holding door shut when bumping on roads.	-	Bracket is not strong enough. Requires modifications.
17-Jun-16	Other Equipment	185	charging socket pulled off the PCB so cannot be replaced without soldering	GPS charging cable pulled out of rear of device when repositioning. Cable pulled the socket off the PCB and is now inoperable. Device cannot be charged and now does not turn on when vehicle running.	repositioning the unit, cable got caught and pulled out of rear of device.	OIC - please have unit taken to to see if they can repair/reposition GPS. Let me know when repair has been completed. REPLACEMENT PART FORWARDED TO OIC BY RRC 28/6/16.
17-Jun-16	Vehicle	245	none	MDT is shutting down intermittently. Side step not working	unknown. Aux battery voltage has been reading low intermittently too	Vehicle has been kept in service as there was no replacement available
18-Jun-16	Vehicle	185	unable to problem solve	side step not operational, will not extend out	-	Vehicle to for repair. V 4582
18-Jun-16	Vehicle	215	Vehicle unoperational	Corpuls Not Charging correctly in Vehicle	Loose power outlet on truck. Provides charge if adjusted in certain positions	Fault not with corpuls only with wall plug; *****Vehicle Unit Number is 4414 -Vehicle registration associated with incorrect vehicle numbering
18-Jun-16	Other Equipment	235	Fault form completed	GPS freezes frequently and does not navigate at all to the address at times	-	-
18-Jun-16	Vehicle	235	-	Steering shudder @ 80kph	may require wheel balance	-
18-Jun-16	Vehicle	195	Reported to Comms, SOS returned vehicle to station awaiting mechanic organised by SOS	Rear airbag suspension completely flat when driving, would not pump up when driving or on scene.	unknown, suspect leak in air bags?	When tested on station, air bags would rise and fall with handbrake on, however compressor attempting to re inflate bags when lowering, also continued to pump for 20+ mins. After compressor stopped suspension completely flat again after approx 1hr sitting
18-Jun-16	Other Equipment	185	Replace battery	Vehicle Mobile phone battery goes flat very quickly and can be charged very quickly; ? very diminished charge holding capacity.	? AGE	PLEASE
18-Jun-16	Vehicle	185	No action	Hole punctured through plastic protective cover of satellite phone antenna	Plastic edge of side panelling on station building was hit while entering plant room. Plastic edging broke off and impaled plastic cover of satellite phone antenna puncturing a hole.	V 4589
18-Jun-16	Vehicle	245	-	#NAME?	-	-
18-Jun-16	Vehicle	235	-	MDT malfunction	-	-
19-Jun-16	Vehicle	210	Charged vehicle, still not working. Turned the main for car off and back on again, still not working. Was tested while on highway and while vehicle turned on, with handbrake off.	Siren was tested while driving and discovered to not be working. Charged the vehicle, and attempted again however still not working.	Unknown	Vehicle is still operational as emergency lights and horn are in full effect. Due to rain, vehicle is needed on road.
24-Jun-16	Vehicle	240	Light placed in flood light reseviour	Rear left side flood light sheared off (cable still attached light still working)	Small sign extending outwards towards road half way up a telegraph pole adjacent to road lane connected with flood light	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
19-Jun-16	Vehicle	195	General fault finding checks unsuccessful. Notified fleet manager, Comms and SOS.	Siren failed on code 1	Unknown	-
19-Jun-16	Vehicle	195	Fleet manager notified	No siren sound	-	-
19-Jun-16	Vehicle	250	removed from service	Vibration through steering at approx. 110kmh Rear air suspension not working	found this way	-
19-Jun-16	Defibrillator	240	Monitor removed from operational service, this form submitted and on road managers aware. MNSOS and CSO aware of case - protocol print out left with Officer	Failure to Transcutaneous pace in demand and fixed mode upto 150ma (max setting). Multiple attempts with pads in anterior/posterior and changed to anterior/lateral positions (3 different sets of pads used) and limb electrodes distal (ankles and wrists) and	unknown	Monitor is at Kenmore Station and OIC made aware. Earf # case #
19-Jun-16	Vehicle	235	Fault form submitted.	Visible damage to ? airconditioner/fan belt under bonnet of car. Belt appears to be frayed and damaged in places.	-	Photos of above fault have also been included in the vehicle checklist submitted for 601624 on 19/06/16.
19-Jun-16	Vehicle	215	Vehicle left in back shed at station and taken off road due to continued rainfall.	Approx 3L of water came out of airconditioning unit in rear cabin during rainfall. 4404 was driven around a corner resulting in approx 3L water coming out of the airconditioning unit and onto the floor.	-	ONLY OPERATIONAL WHEN NOT RAINING HEAVILY
19-Jun-16	Vehicle	200	Unable to find origin of leak. Cross band radio switched off, and towel placed below.	Water leaking through overhead radio console in drivers compartment during rain. Leak comes through near cross band radio.	-	-
19-Jun-16	Vehicle	200	tried to reset safety switch, tried several power cords	Despite being plugged into 240V vehicle is not charging	unknown	-
19-Jun-16	Vehicle	225	-	Right and left alley lights non operational	-	-
19-Jun-16	Vehicle	240	Contacted OC, and vehicle was towed back to Mitchleton station	All lights and sirens going off at intermittent intervals during a transport, had to pull over due to causing traffic to take evasive action multiple times	Unknown	Officer was on this vehicle yesterday and stated that the duress alarm was activated twice without either officer on the vehicle touching it, not sure if this is related.
20-Jun-16	Vehicle	195	Previously reported but not actioned	1) Windscreen washers non operational 2) Reversing camera display on dash shows very poor unclear display	-	-
19-Jun-16	Vehicle	210	Parked in enclosed/dry ambulance bay, power cord plugged in, main switch left off.	When main switch is on - internal lights flash on and off, vent unable to be turned off, L Work light unable to be turned off.	?Water leak. Heavy rain throughout time prior to fault.	-
20-Jun-16	Vehicle	200	-	Car will only start with auxiliary battery. Has been on charge and main switch and radio turned off.	-	-
20-Jun-16	Vehicle	250	Spoken to mechanic at southport.	Siren not working	-	-
20-Jun-16	Vehicle	210	-	Unit 2479 not starting. Unit on charge from 0700 - 1200, battery reserve 14.8 however vehicle not starting. Comms notified.	-	-
20-Jun-16	General Equipment	195	nil. Unable to open drawer	Top cannula drawer is locked shut. Will not open.	unknown	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
13-Jun-16	Vehicle	225	Vehicle placed on Tilt tray Tuesday 21 June for transport to Toowoomba	Airbags Take 10 minutes to inflate, vehicle has nil rear suspension until airbags are inflated. Vehicle cannot be safely driven until airbags have inflated. Possible airbag leak, and pump fault.	-	Vehicle can remain operational, but possible delays while waiting for airbags to inflate.
19-Jun-16	Vehicle	210	Nil. (Towel on dash when raining).	Windscreen seal (passenger A pillar) appears kinked and leaking when raining.	Inproper installation of new windscreen.	-
20-Jun-16	Stretcher	235	Stretcher removed from 6665 and replaced with second stretcher from 6666.	Head end legs of stretcher loose. Stretcher uneven and unsteady when lowered.	Unknown	This stretcher has been collected and returned to Ipswich for repair or decomission
20-Jun-16	Vehicle	250	Compartment taped and moved to Southport to get fixed.	Oxygen compartment on side of vehicle opened during transit.	-	-
20-Jun-16	Defibrillator	215	ECG connection disconnected then connected again. Nil changes. Defib put out of service and left in front of OIC room. Fault form filled out	3 lead ECG unrecordable - erratic reading when attached to a pt lying still on a bed.	-	Treating officer
20-Jun-16	Defibrillator	250	removed from service , borrowed corpuls from 6588. No corpuls sign placed onto 6588 andd white board. SOS informed	Blue light , SD Card Almost full	N/A	-
21-Jun-16	Vehicle	200	tyre repaired as authorised by	Flat L) rear tyre	nail	-
21-Jun-16	Other Equipment	225	nil	1/5 on radio. Comms are also only hearing 1/5. Lots of static. Both inside and outside the station.	Unknown, radio problem	-
21-Jun-16	Vehicle	195	Somebody has put a tourniquet around the holder and the rail to hold it in place.	Stereo not working. Corpuls holder not locking in so it just turns and doesn't get locked into position.	-	-
21-Jun-16	Vehicle	200	sent photos to mechanic	water appears to be coming in from silicon missing on front windscreen into radio compartment and also the space between the drivers and rear compartments	silicon missing	-
22-Jun-16	Vehicle	225	fault form	Airway seat belt not retracting when not used.	not known found on morning	No OIC on Toowoomba station to notify
22-Jun-16	Vehicle	225	Booked in at	Low tread on all tyres and wheel alignment needed. Still within legal parameters and OIC to organise replacement today.	-	-
22-Jun-16	Vehicle	235	-	Fuel gauge is not reading correctly. Crew advise that the vehicle was showing full and then upon being restarted again after a case only showed two bars. Was refuelled and only took \$40 worth of fuel.	-	-
22-Jun-16	Vehicle	210	-	Unit 2479 not starting again as per Fault Report #3447 on 20.06.16	-	-
22-Jun-16	Vehicle	195	OIC Notified	L) Rear Tail light not working	-	-
22-Jun-16	Vehicle	235	-	Siren on vehicle activating however not functioning correctly	Uknown	-
22-Jun-16	Stretcher	195	OIC Notified	Front legs getting slower at lowering when pulling out of the vehicle and not locking. Particularly after stretcher has not been used after long period of time ie overnight. Requiring to kick the legs out every time to ensure they lock in.	-	Nil stretcher collapses as crew aware whats required to ensure legs lock in.

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
20-Jun-16	Vehicle	190	-	10-15cm crack appeared on the drivers side of the windscreen from the top downward	Eagle struck windscreen	Unit 1444 in transit from QAS Mt Isa to QAS Doomadgee
22-Jun-16	Other Equipment	240	attempted swapping batteries and phoned Earf support who advised the toughbook needs to be sent away for repair or replacement.	Toughbook wont work unless plugged into a 240V powerpoint. Toughbook turns off when removed from charging cable. Toughbook is not working on battery power. Tried with several different batteries unsuccessfully.	-	placed out of service at direction of Earf support. Replaced.
22-Jun-16	Vehicle	210	Notified Operational Readiness Supervisor. unable to contact him again today due to being dispatched on a job to rectify concerns /issues. Will follow up 23.06.16	Vehicle will not start. All electrics including dash and LCD panels are working. Defib is charging. Have checked to ensure car is plugged in and power turned on. NIL issues noted.	Unknown ??? Starter motor.	-
22-Jun-16	Vehicle	210	Notified Op readiness coordinator. (Did not get back to him today due to being on a job.) Checked battery connections, leakages, lighting/electrics (what works and what does not), ensure vehicle was/is plugged in and turned on. NIL issues detected.	Started vehicle this AM was hard to start ? due to cold morning. let vehicle run for a while and placed back onto charge. Went out to vehicle a little while later to run again and it will not start.. All electrics and LCD screen working.	???? Starter Motor.	-
23-Jun-16	Vehicle	195	Run the vehicle to see if the battery would charge up and hold charge.	Flat battery. Unable to start vehicle normally. Had to use aux battery.	Charge lead not in place	fixed racq
23-Jun-16	Vehicle	215	SMALL CRACKS - BOOKED IN FOR REPAIR	RIGHT HAND MIRROR	MIRROR IMPACTED SIDE OF ROLLER DOOR	-
23-Jun-16	Defibrillator	235	it has been removed from service	unable to perform preshift ECG check as the D-ECG LT- ECG option were not available for selection on the screen - aka they were grey	unknown	-
23-Jun-16	Vehicle	195	Vehicle parked on station. SOS and Comms alerted.	Yellow engine diagnostic indicator lamp began flashing whilst driving back to station (a few blocks away). Vehicle was stopped, re-started and warning light returned. Refer page 222 troubleshooting section of Sprinter manual	-	-
24-Jun-16	General Equipment	195	Wires have been disconnected and reconnected. GPS was attempted to be restarted, however despite all attempts screen remained locked.	Vehicle 1102 GPS is not working. GPS screen is locked to start up screen.	Unknown. Appears to have faulty wire connection.	-

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
24-Jun-16	Vehicle	195	OIC notified, OIC informed fleet manager.	The step does not retract when side door closed. Inverter was reset however did not fix the issue.	Unknown, tracks were washed with pressure hose.	-
23-Jun-16	Vehicle	210	I used a piece of plastic and the light next to it to hold it up	The light in the front of the car between the driver and passengers fell off the roof of the car	Old	-
24-Jun-16	Defibrillator	210	defect reported and pushed battery into slot and made clips stick	Battery fault in defibrillator unit of corpuls clips not wanting to clip in	unknown found battery with issue tape in battery from previous person and battery want to slip out	-
17-Jun-16	Defibrillator	245	I extracted it with a pair of tweezers.	When performing a pre shift defib chek, I was unable to insert the tester into the socket at the rear of the unit.	On closer inspection, I realised a piece of a defib plug had broken off and was preventing insertion of the testing device.	If this happened in an operational case, defibrillation would not have been possible.
24-Jun-16	General Equipment	225	Out of service labelled, RRC contacted nil area spares OIC to Purchase replacement	Cracks in Plastic moulding of scoop	unknown	Scoop will be replaced with Combi Carrier
14-Jul-16	Vehicle	225	Booked in for Service 07 July 2016	Requires vehicle service by Due date 14 July 2016 as six months will expire.	-	-
24-Jun-16	Vehicle	185	sos notified	Drivers seatbelt frayed, drivers seat torn on base	Wear & tear	Frayed seat belt - V 4629. (Photos to be taken by OIC of seat to ascertain extent of damage.)
24-Jun-16	Vehicle	245	-	#NAME?	-	-
24-Jun-16	Vehicle	195	SOS contacted immediately, vehicle not started, arrangements made to tow vehicle to RACQ holding yard and for tank to be drained so as not to damage the vehicle.	Upon refueling at completion of shift, 17 Litres of regular ULP was pumped into the vehicle instead of diesel. incident was recognized prior to tank being full, vehicle ignition was not started, vehicle was not moved in any capacity.	-	-
24-Jun-16	Stretcher	235	-	Missing middles seatbelt	-	-
24-Jun-16	Vehicle	235	-	Rear tail light + front spot light not working	-	-
25-Jun-16	Vehicle	235	attempted to spray WD40 on step	Retractable side step not full coming out when side door is open. Making grinding noise	-	Hazard report completed
25-Jun-16	Vehicle	185	Contacted who referred matter to as they had no mechanics working on weekend. Car booked for inspection at 1000 same day, if unable to resolve the matter car booked at on Monday. Op sup and OIC notified.	Radios not working if vehicle off and not connected to 240v, query battery issue. When left unplugged battery monitor screen state main 12.6, reserve 9.0.	-	Photo of monitor stored on iPad, can email if required
24-Jun-16	Vehicle	225	Taken off road	Engine warning light came on whilst returning and vehicle went into limp mode	-	Flashing engine warning light on, in limp mode, all fluid levels good, engine will start and drivable in limp mode. will require flat bed truck to pick up and take to service department.
25-Jun-16	Defibrillator	225	-	4cm significant scratch to screen	Unknown, picked up in vehicle check. - OIC ware Sunday 19th June	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
25-Jun-16	Vehicle	200	Mechanic consulted and is now aware.	Dash board light fault.... Engine warning light constant... After consulting mechanic, fault is likely a common fault, caused by a faulty glow plug (glow plug light does illuminate again during driving)... Vehicle is safe to drive.. Confirmed fluids ok.	-	-
24-Jun-16	Stretcher	225	Stretcher has been removed from ambulance and replaced with spare. Waiting to contact Resources Readiness Coordinator for advice.	Front legs/wheels will not lock into place upon removal of stretcher from back of ambulance.	-	-
25-Jun-16	Vehicle	200	vehicle fault form lodged	Right rear tail light outer casing cracked and broken	unknown	Fault found during routine vehicle inspection
25-Jun-16	Vehicle	195	being seen by a mechanic tomorrow	Crack in windshield	unknown	-
25-Jun-16	Stretcher	235	-	Stretcher missing middle and lower belts	unknown	-
25-Jun-16	Vehicle	250	-	Battery not holding charge, whilst on scene engine taking multiple attempts to turn over	-	is operational however suitability to emergent taskings crewnot confident in its ability to turn over as it should
25-Jun-16	Vehicle	200	-	- Fridge not cooling > noticed first at 1700. - 'Grating' sound while driving/changing gears/accelerating > noticed first at 1900.	-	-
25-Jun-16	Vehicle	240	OCS NOTIFIED, OCS STATING VEHICLE WILL BE TOWED, VEHICLE LOCKED WITH X 1 SET OF KEYS GIVEN TO PETROL STATION STAFF AS DIRECTED BY OCS, VEHICLE REMAINING AT PETROL STATION. OIC NOTIFIED BY EMAIL	VEHICLE REFUELED WITH UNLEADED PETROL, VEHICLE IGNITION NOT ENGAGED AS FAULT BECOMING APPARENT WHEN FUEL CARD DECLINED	AS ABOVE	CALTEX RECEIPT AND PETROL DRIVE-OFF OFFENCE REPORT FORM (GIVEN TO QAS BY CLATEX STAFF) PLACED IN OIC OFFICE. UNSURE OF SPEEDO READING, NUMBER ENTERED COULD BE INCORRECT
26-Jun-16	Vehicle	210	Nil, car has been left on charge today at different charging station	Despite being on charge at station throughout the day, vehicle had to be emergency started (AUX) after EA. There was no additional drainage on battery ie. all lights were off, as were the mains and fridge. Same issue with different officer previous night.	unknown	-
26-Jun-16	Vehicle	235	Notified orcs to report same	Duress keeps going off	Unknown	-
26-Jun-16	Vehicle	195	Sent email to OIC and vehicle taken out of operation	Left headlight not working	-	-
26-Jun-16	Vehicle	225	No	Small windscreen crack	Unknown	-
26-Jun-16	General Equipment	225	OIC notified	Satellite phone unable to get service, despite being in open area and aerial pointing to sky; Charger fault	Faulty charging system. Sat phone was charged remotely on station however Unit charger was not working. Repaired 27/6/16	Nil SHE report as phone has not been required to be used, fault noted on vehicle check
25-Jun-16	Vehicle	215	Stuck in on position won't release	UHF microphone not working	Found at start of shift	-
25-Jun-16	Vehicle	185	Vehicle Taken off road SOS notified	Engine Light on Dashboard Flashing Yellow And Vehicle has lost power Front right headlight faulty	-	V 4624 (glo plugs) V 4625 (head light)

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
25-Jun-16	Vehicle	245	Fault report, noted on station vehicle board	Mains electrical fault. Defib cradle will not charge. Swapped cradle still won't charge. ? problem with 12V mains supply. Mains switch panel continuously beeping "low cool" light illuminated.	Unknown cause	Whilst vehicle is still operational, its response capacity may be hindered as defibrillator may run flat as vehicle charge is compromised. Unknown if mains power fault will hinder use of emergency lights or sirens.
26-Jun-16	Other Equipment	240	removed from vehicle	Toughbook charging cable damaged.	? wear/tear from old age	Replaced
27-Jun-16	Vehicle	210	-	Passenger headlight out. Bulb dimmed/ went out while driving	-	-
26-Jun-16	Vehicle	225	Fault Report	Radio in car will not turn off even with keys out of ignition	-	Found last night when vehicle was on call.
27-Jun-16	Vehicle	190	changed tyre with spare. Unit to be sent to for tyre replacement 28/06/2016.	Left rear tyre flat	-	-
26-Jun-16	General Equipment	245	EQUIPMENT WILL NEED REPLACEMENT	EQUIPMENT FOUND AT START OF SHIFT BROKEN UNUSABLE	UNKNOWN	-
27-Jun-16	Vehicle	185	Advised RRC	Main Switch will not switch on. Checked 240v inlet. Restarted truck. Still will not work.	Unknown. Noticed on commencement of vehicle check.	A/OIC to take unit to 28/6/2016. V 4627.
27-Jun-16	Vehicle	210	Step hosed with water to attempt clearing	Side step will not extend when side door is opened, nil evidence of physical damage. Vehicle primary radio transmits calls to Capcom but response from capcom is often not heard and unreliable. Appears to be an issue with the receive call sensitivity.	Build up of road grime in the mechanism	vehicle remains operational
27-Jun-16	Other Equipment	210	Nil	Vehicle primary radio transmits calls to Capcom but response from capcom is often not heard and unreliable.	Receive sensitivity settings? Antenna issue?	Able to use vehicle mobile when communications unreliable.
27-Jun-16	Other Equipment	240	Turn off and turn back on	error code 09/10, keeps occurring preventing unit from receiving or sending. turning off then on resets however issue returns.	Unknown	Asset: QGN303707
26-Jun-16	Vehicle	210	I've put a rolled up piece of paper in the hole where the post should be, to stop the alarm sounding. The only problem with that is, if the door IS left open accidentally, the alarm now won't sound.	Rear door (nearside) sensor broken. See pics. Causes the "door open" alarm to sound. The post that sticks out and makes contact with the door has come out at some stage.	-	This is more of an FYI than anything. If you're happy to leave it like this (with the paper in the hole) so am I. The only thing is, as mentioned, the alarm will now no longer sound if the door is left open.
26-Jun-16	Vehicle	180	Vehicle booked for Auto electrician today	Master switch panel beeps and 'low water alarm' light turns on with radio operations, still operational however requires auto electrician to have a look	-	-
27-Jun-16	Vehicle	225	Vehicle was turned off and restarted but the light is still on.	Engine management light staying on.	After starting the vehicle from cold and driving a short distance the glow plug light came on. It stayed on for approx 30 secs and then went off. Since this time the engine management light has come on. Vehicle running as per normal, nil operational issue	Found one glow plug faulty No 4
27-Jun-16	Stretcher	240	Stretcher taken out of service for inspection.	Stretcher collapsed	-	Head of stretcher collapsed as pt sat down, nil injury to pt, operator or any other person.
27-Jun-16	Vehicle	250	SOS informed, SHE report and MVA claim form completed	Minor damage to paint and number plate on front of vehicle	Crew witnessed car performing U-Turn 3 cars in front, breaks were applied immediately, however vehicle did not stop in time.	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
27-Jun-16	Vehicle	240	Vehicle has been left on charge. Still occurring.	Battery showing signs of being flat. Difficulty in starting, gwn radio and mdt slow to turn on. Power steering doesn't work for 30 seconds after turning car on.	Battery	-
28-Jun-16	Vehicle	210	-	Rear door struts not working properly	-	-
28-Jun-16	Vehicle	210	-	Rear door struts not working properly	-	-
16-Jun-16	Vehicle	215	Reported to CORR	Cracked rear wing right hand side	reversed into over hanging side walk sign	Vehicle accident paperwork will be completed today. Minor damage to wing but Emerg lights are still operational
28-Jun-16	Vehicle	225	-	Low water alarm on panel cluster and vehicle warning on dash on start up.	unknown cause, water level appears normal.	-
28-Jun-16	Vehicle	240	-	Rear heater switch loose - unable to tell if turn on/off	-	-
28-Jun-16	Vehicle	225	-	Rear Red LED Beacon not working and some LED's out on drivers side brake light.	-	Noticed by mechanic after last service.
28-Jun-16	Vehicle	240	contacted	Vibration in front wheels at 100 kph	? Wheel balance	-
28-Jun-16	Vehicle	215	Reported to CORR	Rear of vehicle height is too high for the stretcher when pulling it out.	Adjustment of ride height	-
28-Jun-16	Vehicle	200	fluid levels topped up. Searched for leak. Will contact mechanic	Wiper reservoir light on. Low fluid level topped up. No water coming out of wiper reservoir onto windscreen. Possible leak unable to locate source.	Found during vehicle check unknown cause	Wiper function normal just no water
28-Jun-16	Other Equipment	185	2x previous visits to with software reset and hardware replacement over previous weeks. Same fault has reoccured. PTT has been turned on and off numerous times to try to resolve fault with no success.	7490 PTT radio/phone has no power	Recurrent fault. PTT handset has no power, unable to connect and no wurring sound heard when vehicle powered off. Vehicle did have main and reserve batteries replaced at different times over the past 4 days due to battery failure. notified	
21-Jun-16	Vehicle	240	-	Vehicle has "brake wear visit workshop" notice	-	-
28-Jun-16	Vehicle	210	attempted to manually fill air suspension but unsuccessful	rear suspension wont fill or lift. fill mnually after phone conversation with SOS but but was unsuccessful	-	-
28-Jun-16	Stair Chair	210	report to aoic emerald -	Crack in green belt clip. Clip not completing broken however could be a hazard	no	-
28-Jun-16	Other Equipment	250	Day OS will see the Gold Coast FMO for a fix.	Torch holder in 607573 appears to have 1 screw in it the rest was held by silicon gel which has given way.	Usage of the torch	-
28-Jun-16	Vehicle	225	Master switch in Off position whilst vehicle on station.	Battery fault. Vehicle not charging whilst on trickle charger. Required jump start.	-	-
28-Jun-16	Vehicle	235	Truck has been taken off road and we have changed vehicles for the remainder of shift	Electrical fault. While driving all of the lights would flash on when you hit a bump on the road. This would cause the side lights rear lights and interior lights to come on. Sometimes the sirens would come on and the emergency lights.	Electrical fault?	This issue can be very distracting while driving and is quite dangerous as it takes the drivers attention away from the road.
28-Jun-16	Vehicle	210	-	Rear heater not working	Fan sounds as if it is running but no air is beeing blown from the vents	The vehicles airconditioning is not good enough to compensate for the lack of heater, as such it is is not appropriate to use in the current weather as a lot of patients require worming.
29-Jun-16	Vehicle	225	OIC informed, fault report form completed	faulty airbags/suspension	unknown	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
20-Jun-16	Vehicle	240	Reported to OIC	Spare key broken when dropped - key section lost ??? Down drain MDT Powers down when vehicle is running, master switch is on and vehicle was taken to to have Aux batt. checked - all ok. issue is intermittant	Accidental drop	Replacment key sourced by OIC under warranty from
29-Jun-16	Vehicle Other	245	NA		? electrical with MDT	Jobs may be sent to MDT but if it turns off no info can be looked at or maps
29-Jun-16	Equipment	185	PSBA Job Logged	Vehicle radio handset cable has split so bare wires visible at handset end	Cable perished	A/OIC - please advise when problem is rectified.
29-Jun-16	Vehicle	210	Fault form	Large crack in windscreen	Found it on my vehicle check today	-
29-Jun-16	Vehicle	240	OC notified, due to heavy workload crew unable to stop at during work hours. OIC also notified.	Air conditioning not working & making loud strange noise when turned on.	-	-
29-Jun-16	Vehicle	240	Stretcher swapped and left at Chermside station for servicing, Chermside OIC aware.	Stretcher front legs frequently do not engage when unloading , particularly when unloading at slow speed.	Unknown	Stretcher sent to for repair from Chermside station V 4639. A/OIC to advise when problem is repaired.
29-Jun-16	Vehicle	185	-	ABS WARNING LIGHTS DISPLAYED ON DASH. BROKEN ABS SENSOR.	-	-
29-Jun-16	Vehicle	195	Reported to unit manager and fleet manager	Battery flat	No	-
29-Jun-16	Vehicle	225	Vehicle has been plugged into the power at the station with the Mains switch turned off.	No power and vehicle had to be jump started. After leaving miles hospital, about half way home power in rear unit/drive lights etc lost again.	-	It could be considered operational, at a pinch, but is currently considered unreliable.
30-Jun-16	Vehicle	240	Engine turned off, and restarted with nil change. - ROC notified and vehicle returned to station and removed from operation.	Engine Light flashing on and of on dash on route to scene (Code 2). Vehicle then noticed to be having delayed power on acceleration and not changing gears.	Unkown. Vehicle was serviced on 29th June at	-
30-Jun-16	Vehicle	235	-	R break light not working	-	-
29-Jun-16	Vehicle	225	-	Panel for mains power to control vehicle emergency and work lights no longer turning on. Mains power still available in patient care section of unit however unable to activate lighting for code 1/scene lights from front. Panel functioning at start checks.	-	-
29-Jun-16	Vehicle	225	Booked in for repairs	Siren only working when horn engaged. Noted by previous officer	Faulty limit switch on hand brake	Only operational vehicle - others being serviced
30-Jun-16	Vehicle	210	None, as I can not rectify this fault	Possibly the seals at the rear doors of the vehicle may need replacing as the rear door does not close seamlessly and when driving on dirt roads, dirt n dust enters the rear of the vehicle, covering the interior rear and anything that is sitting there.	Unknown	I have informed OIC who told me to put in fault report
28-Jun-16	Vehicle	185	Reported to Operational Readiness Officer	Reverse camera intermittent fault	Not known	Vehicle is still currently in use. V 4646. Vehicle to be taken to for repair. OIC to advise when vehicle will be in.
29-Jun-16	Vehicle	240	-	Garmin GPS not charging	? Cord unplugged. Unable to plug back in, cord disappears behind the dash.	OIC aware
30-Jun-16	Defibrillator	215	Taken from road for service/ fault find	failed to capture rythm with all leads and dots connected correctly. Nil problem detected in moring machine check.	unknown cause	-
30-Jun-16	Defibrillator	240	Reported to job no 8000063104	Monitor 12 ECG Corpuls3 displayed a paced rythm at 300 with the underlying rhythm at 76BPM. Jogg wheel flashing Blue then orange. patients actual heart rate 76 bpm recorded manually and with a hospital monitor.	-	Redcliffe 4

NOT RELEASED

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
30-Jun-16	Vehicle	195	OCS informed and vehicle taken of road.	Side module door (defib bay) motor making loud grinding noise. Missing screw from top latch which is loose. Door opening on occasions whilst driving.	unknown	-
30-Jun-16	Vehicle	240	fault report	Rear door right stay bar catch broken	snapped under tension	-
1-Jul-16	General Equipment	240	Notified the OIC and a fault report	MDT shutting off between jobs, when the crew is with patient and at hospital	-	-
23-Jun-16	Vehicle	195	Mechanic in town was able to retract the step. He has also replaced the step once and made multiple adjustments to current step. Has now advised is unable to make any further adjustments ? need another replacement or to replace module/electrics.	Side step not functioning. Initially unable to be retracted, now not working at all.	Unknown.	UPDATE 02/07/16 - spoke to Fleet Manager and am awaiting further advicer regarding repairs/replacement.
1-Jul-16	Vehicle	235	-	Scan light cover missing R front.	-	-
1-Jul-16	Vehicle	185	Notified OIC cairns . Yellow sticker placed on windscreen vehicle left in plant room of cairns station	Engine has clonk sound intermittent but offen while idolling	Unknown, just happen when turn on at start of shift.	This sound not heard before. V 4651. No problem found, general maintenance checks done on vehicle. back on road.
30-Jun-16	Vehicle	225	Booked in to have light fitted for the Thursday 28/07/2016 Replacement light part has arrived from Fleet manager and is with vehicle.	On Drivers side of modular compartment (underneath O2 storage), small orange light has come off	Vehicle was being reversed into plant room and driver misjudged distance between plant room wall and vehicle.	-
1-Jul-16	Vehicle	225	Mechanic notified and booked in for repair	Brakes fade in vehilce. Once they are hot brake pedal pushed hard to the floor and vehicle doesnt stop	unkown	-
1-Jul-16	Vehicle	195	Nil, fault rectified after about 15/60	Siren, gps and radio not working	-	-
1-Jul-16	Other Equipment	250	I have attempted to reboot the MDT twice but the screen only boots up to a black screen.	MDT failure. Over the course of the day the MDT was flashes different colours and began to fade to a black screen between 1430 and 1530. Unit 608569	-	-
30-Jun-16	Defibrillator	210	strap removed - defib still in use	Clip of carrying strap snapped	-	-
2-Jul-16	Vehicle	230	Nothing	Crack across bottom right of windscreen	A big rock	-
1-Jul-16	Vehicle	195	Nil	Left spot light and left tail light not functioning. Side step not functioning.	Nil	Nil
1-Jul-16	Vehicle	240	-	Main switchboard for lights and sirens not functioning	-	Repaired

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
1-Jul-16	Defibrillator	245	Connection was pulled out and put back in carefully with nil change, corpuls was turned off and on again with nil change. OC was contacted and once back at station and tested the cord again it was working.	SpO2 monitor defective. During pre-shift check SpO2 sensor working nil issues. When used on first job on shift corpuls kept flashing red "defective oxi".	Unknown - nil visible damage to cord or connection.	After the first pt where the the SpO2 monitor was not working, on the second pt it was working fine. Once back at station re-checked the corpuls and SpO2 monitoring was working fine. Went to use it on a pt ? and it stopped working again.
2-Jul-16	Vehicle	250	Reset 240v curcuit breaker	Battery issue - Needs emergency start	-	-
2-Jul-16	Vehicle	210	accident and insurance form completed and notified comms centre and OIC. Tape also has been placed over the crack in the fibreglass.	scrape and crack through the fibreglass on drivers side panel above rear wheel due to scraping along another vehicles bullbar - nil damage to other vehicle but minor paint transfer	turning vehicle and scraping along other vehicles bullbar	-
2-Jul-16	Vehicle	225	-	Main radio will not transmit via microphone. Was working this AM at commencement of sport special but would not work at end of day. All other hand piece functions work, ie channel change.	-	-
2-Jul-16	Stretcher	225	notified SOS and removed from service	head end legs will not lock in to place unless pressure is applied when removing stretcher from vehicle on level ground	-	-
2-Jul-16	Vehicle	185	mirror pulled back into postion	minor damage to plastic trim on passengers side wing mirror.	reversing up up a narrow dirt track drive way in the dark and thick mist. A vine caught on the mirror and forced back 90deg.	reprted to SOS and SHE report completed. photo's sent to SOS as requested
2-Jul-16	Defibrillator	185	Awaiting technician	Oxy cord defective alarm showing. spO2 not reading	?	OIC - please advise if machine has been sent away foir repair, and if so, advise when it is returned to service so this fault report can be closed.
2-Jul-16	General Equipment	250	Spoke to earf helpline who stated it was not fixable over the phone. Needs to be sent away	Will only log onto Windows screen. Message displays - Windows cannot connect to the domain, either because the domain controller is down or otherwise unavailable, or because your computer account was not found.	-	OIC able to fix toubokk with assistance of eARF support via phonw
2-Jul-16	Vehicle	210	-	1. Rear suspension is faulty, rear air suspension continually trying to deploy 2. Screws missing and becoming undone on kit access door. 3. Corpuls brackets applied in wrong areas	-	-
2-Jul-16	Vehicle	225	- rear attendant door on passenger side ajar > fault report submitted previously (manually) 22/02/16; 06/01/16; 15/10/15 - rear suspension fault > fault report submitted previously (manually) 09/11/15; 24/10/15 > SHE hazard/risk (NOT report) submitted	- rear attendant door on passenger side ajar (step closes upon door closing, but bottom of door remains ajar, and warning indicator shows on instrument panel in front cabin) - rear suspension does not deflate to load/unload patients (SHE hazard/risk)	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
2-Jul-16	Vehicle	240	-	Aux battery not holding charge. >14v when running however once vehicle is turned off the voltage drops to below 11v. This is causing the MDT turn off however the radio remains on.	-	-
2-Jul-16	Vehicle	185	Taken to new glow plug ordered, they will advise when it is ready	ENGINE AND GLOW PLUG LIGHTS ON	Glow plug number 5 faulty	Job number V 4656 - A/OIC to advise when repair has been done.
3-Jul-16	Vehicle	240	Officers have to open doors completely to prevent premature closing.	Rear loading doors not holding open. Doors swing shut potentially hitting officers and or patients.	-	-
3-Jul-16	Vehicle	210	troubleshooting of controls.	Patient cab heater (roof mounted) not supplying warm air.	?	-
3-Jul-16	Vehicle	210	Cleaning with hose.	Side step not extending fully.	? Build up of dirt/dust.	May require cleaning with air gun and silicone lubricant applied.
3-Jul-16	Defibrillator	195	Attempted to reposition Dfib & move to remain on charge with no success.	Dribble / bracket loose charging connection. When Dfib placed on bracket charging light comes on, then goes off after a very short time.	-	-
3-Jul-16	Vehicle	185	-	side step stuck in the extended position	-	V 4653 (side step + garmin + am/fm radio) V 4654 for 210,000klm service
3-Jul-16	Vehicle	245	-	Mechanical fault in front right wheel, leave klunking sound on and after braking, wheel felt to shudder. Remote lock only working intermittently, in able to secure vehicle and drugs	-	-
4-Jul-16	Vehicle	210	mechanic booked	Inverter not working, reported by night crew	Unknown noises from under the engine and strong exhaust smell	-
4-Jul-16	Vehicle	210	-	Head lights / emergency don't not work .	-	-
4-Jul-16	General Equipment	185	Nil at this stage. has fixed it in the past.	When the portable Radio is activated the AF wave sets off the Emergency lights on the Unit. In the past this has also caused the siren to go as well but just lights this time.	When the PTT system was fitted the cables run side by side and they had no shielding, it was fixed but needs to be relooked at again as this measure may have moved.	OIC - which unit is this? It neds to come to for repair.
26-Jun-16	General Equipment	225	Advised service department who were unable to fix and stated needed an auto electrician to look at it. OIC has advised Resource Readiness Coordinator who advised for A/OIC to fill out a fault report to keep track of progress.	Fridge in unit 3167 not working. Advised by Service electrician to look at it.	needs auto	Unkown
26-Jun-16	General Equipment	225	Have advised Resource Readiness Coordinator who has ordered a new step and awaiting arrival so it can be installed. Advised to fill out fault form as A/OIC.	Side step not working.	Unknown	-

RTI RELEASE

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
4-Jul-16	General Equipment	225	Attempted to hold in place repaired	Reversing camera - above driver side of vehicle, set behind sun visor - clip is broken and screen falls down.	Unknown	-
3-Jul-16	Vehicle	220	mechanic to check vehicle	Vehicle not going into drive without stalling	-	Have received back from the Mechanic and is now operational
4-Jul-16	Vehicle	240	Fleet technician advised repairer advised	TMR defect notice issued for loose/ missing bolts to seat mounts and safety hand rail	-	-
4-Jul-16	Other Equipment	245	trued turning on and off	No maps found on gps therefor won't work	-	Located outside oic office
4-Jul-16	Defibrillator	225	Attempted to roll wheel myself multiple time and manually feed paper through fault continued to happen	Spooling device in printer that feeds paper out continues to get stuck causing a paper jam and impacting paper speed	Spooling reel jammed	Defib can be used but only when putting pressure on paper to feed it through, this effects paper speed and makes ECG's non diagnostic.
5-Jul-16	Vehicle	185	will talk to when get to cairns to replace bulb	Drivers side headlight	old age job n	umber V 4659.
5-Jul-16	Vehicle	225	Inspection by repair agent	Slow leak in rear airbag suspension system.	wear and tear	-
5-Jul-16	Vehicle	200	Awaiting advice from QAS mechanic	Ongoing issue with unit wall suction not working. Previously repaired and functional, however today's vehicle check not working. Also, rear radio fader not working	Unkown	Able to utilise portable suction unit if needed
5-Jul-16	Vehicle	240	Turn vehicle on and off to reset. Fault returns.	traction control and enhanced stability program disengaged	computer, sensor error? electronic fault?	-
5-Jul-16	Defibrillator	210	I acquired another corpuls, ensured the ETCO2 was working on it and switched the leads between the two machines. Neither the lead nor the corpuls worked with the other monitor or the other lead.	ETCO2 function not working	Unknown	Corpuls belonging to vehicle 2209. Unit removed and replaced with a lifepack 12.
5-Jul-16	Vehicle	235	Mechanic notified. Vehicle off road.	Mechanic notified by officer 20000.	Engine light is flashing. In limp mode. Loss of power when accelerating.	-
5-Jul-16	Vehicle	185	kept car plugged in and turned on when at scene	Car battery not fully charged despite not being plugged in all day	-	Email photo to Oic. OIC taking vehicle to to check battery chargers, solenoids. V 4670.
5-Jul-16	Vehicle	240	OIC notified	Mobile phone facia falling off - circuit board exposed	very old phone- ??? Wear and tear	But unsure for how long
5-Jul-16	Vehicle	240	Vehicle has been taken to service dept for them to have a look	Vehicle siren keeps turning off and alternator light illuminates on dash whilst under load of driving. It is an intermittent fault.	The vehicle had the same fault a few months ago.	Requested by Mechanic to place vehicle out of service due to fault. Vehicle repaired by 08/07/16
5-Jul-16	Vehicle	225	Fault report form lodged	Centre drawers in rear cabin are locked in place, lever to unlock does not work, appears bolt is stripped.	Unknown found today when attempting to slide drawers forward	-
5-Jul-16	Vehicle	240	-	EPS workshop light, engine light, car with squiggly lines under tyres all came on at once, and car went into limp mode. After stopping and turning the car off and back in again the car came out of limp mode but all 3 lights remained on.	-	ROC notified, 2215 Tuesday 5/7/16

RTI RELEASE

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
5-Jul-16	Vehicle	195	We taped the blade back on but believe this is not safe so we took the vehicle out of service. We contacted the SOS and an email has been sent to the Kirwan station OIC.	The right windscreen wiper fell off when wipers were turned on.	There is a catch that secures the wiper blade that has broken and needs to be replaced.	-
5-Jul-16	Vehicle	235	-	2 x Amber side lights on drivers side not working	-	-
6-Jul-16	Vehicle	200	-	One of the cluster of four flashing led lights on the right rear red beacon is not working. The rest of the lights on that beacon are operational	-	-
6-Jul-16	Vehicle	200	Completed fault report. Tape applied to interior map lamp to maintain integrity - not effective.	Chip in windscreen size of 20 cent piece. Overhead interior map light is broken.blind spot assistance dash light is on indicating it is not working. Front strobe has detached from bonnet.	Checked vehicle this AM and faults discovered.	-
6-Jul-16	Vehicle	225	called fleet coordinator arranged to have local garage look into fault	rear suspension was not lifting this morning	? hand brake switch	-
6-Jul-16	Vehicle	225	? VECHICLE IS BEING DRIVEN TO LOCAL GARAGE	REAR SUSPENSION NOT LIFTING	rear suspension bags worn out	-
6-Jul-16	Vehicle	190	Upward reporting.	Red Fault on Dash re: Tyre pressure - ? Sensor issue, as tyre pressure appears to be appropriate.	unknown.	There is a comment on the Vehicle WhiteBoard stating that a tyre sensor issue was being addressed, however this was dated 22/04/16???
6-Jul-16	Vehicle	225	Continued from above box as run out of typing space. Seems possible that crew could be locked out of car at job and be unable to load / unload stretcher.	Vehicle central locking isn't working, driver and passenger door don't open with remote entry, need to use key. Rear door doesn't open even when car is unlocked, have to open it from the inside.	unknown, changed into this vehicle and problem noticed on first job	-
6-Jul-16	Vehicle	215	nil	back door not shutting correctly at bottom of door	unknown	-
6-Jul-16	Defibrillator	245	case completed with faulty printer	Printer not printing well, printer door not closing properly	noticed the problem while on a case	-
6-Jul-16	Vehicle	235	-	Vehicle went into limp mode without warning. Would not reset	-	Vehicle parked Ipswich station
6-Jul-16	Vehicle	250	Vehicle taken OOS	Very strong Burning smell after driving vehicle short distance	-	-
7-Jul-16	Vehicle	235	nil	Faulty fuel gauge - ? just repaired Vehicle refuelled then driven 220 klms was only down 2 bars - next time used fuel light on and only showing 1 bar	-	-
7-Jul-16	Vehicle	200	fault form.	Radiator fluid just below the minimum mark. The defibrillator docking station next to the stretchers is very stiff when locked and difficult to open.	found during car check .	-
6-Jul-16	Vehicle	240	informed & will collect on Thursday to rectify	Siren stopped working on a code 1 front drivers side does not seem to work. Battery was showing as low & radio was also having issues ? Aux battery issue also	-	-
7-Jul-16	Vehicle	225	Organise new and tested extinguisher	Vehicle Fire Extinguisher hasnt been checked since April 2015	-	-
7-Jul-16	Vehicle	185	Unit handed to OIC	GPS unit not working S/N HN7AAU115003659	-	-
7-Jul-16	Vehicle	210	Notification of RRC and communications technicians	X-Band on vehicle base set appears to not have X-band channels programmed.	-	Other radio operations functional.

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
7-Jul-16	Vehicle	240	Nil	Front right wheel grating against inside of wheel hub when full right steering lock applied. Spare battery not charging effectively. Radio and MDT take time switching on after engine started and MDT occasionally not sending or receiving information.	Unknown	Nil
7-Jul-16	Defibrillator	215	took paper in and out again... nil change	Corpuls not printing any ink on paper	-	-
8-Jul-16	Vehicle	240	-	Rear heater not working	-	-
8-Jul-16	Vehicle	215	locking manually	Rear passenger door central locking not working	-	-
7-Jul-16	Vehicle	210	mechanic replaced the battery for a new one and working fine now	flat battery in key remote no.2 red tag	staff advised it has been playing up past few days	-
8-Jul-16	Other Equipment	220	Reported. Phone has been progressively checked over the week with varying level of charge and environments.	Obtaining registered signal but dropping and stating "network busy"	-	-
8-Jul-16	General Equipment	235	Removed from unit 6698	Oxygen pipe attached to regulator is leaking due to damage to tubing.	Unkown	-
8-Jul-16	Vehicle	195	Completing fault report, OIC and SOS made aware.	Air conditioning stopped working in vehicle. Initially only front air conditioning was affected but now there is no air conditioning at all - vents are blowing hot air. Was working fine at start of shift. No obvious malfunction. Heater is definitely off.	Unknown	-
8-Jul-16	General Equipment	185	removed from service	Portable Radio belonging to 7260 (radio QAS7860) unable to turn cell call off or deactivate cell call.	-	Advice from officer even date is that portable appears to be working to capacity. OIC to advise any further problems.
8-Jul-16	Defibrillator	195	Reported to SOS who requested it be taken out of service	Default when shocking. Machine charged up however, did not allow crew to shock. Button held down for over 3 seconds a number of times. CPR recommenced, machine charged up on its own again, crew was then able to shock and able to do subsequent shocks.	Unknown	-
8-Jul-16	Vehicle	185	Fault form sent	Left headlight blown	-	Replaced by NFAD.
8-Jul-16	Vehicle	225	Tried putting on charge even a long drive did not recharge vehicle	Flat battery, keys will not lock or unlock vehicle. Only one key will lock the vehicle but will only unlock drivers door, vehicle difficult to start	Flat battery	The equipment in the vehicle operational however the vehicle itself not.
9-Jul-16	Vehicle	245	-	Both sets of keys do not close/open door when pressing buttons, manually closing with key does not close sliding door- unable to secure car	-	-
9-Jul-16	Vehicle	210	vehicle defected	Corpuls not charging. Cradle is operating	unknown, functioning yesterday	-
9-Jul-16	Vehicle	210	-	Corpuls not charging via cradle or external charger pack	-	Cradle is operational. Tested on different monitor
9-Jul-16	General Equipment	250	Unit taken from service and placed in OIC tray	Nil suction during unit test. Red warning symbol illuminated	Unknown	-
9-Jul-16	Vehicle	240	Troubleshooting by turning on & off etc. nil change	Truck radio not turning on unless on/off button continually held. Won't remain on with car running or not.	Found like this at start of shift	Vehicle Charged overnight. Resolved issue. Vehicle operational
9-Jul-16	Defibrillator	240	nil at present	Pacing spikes appearing on a non paced patient ecg	Unknown	Information gained by and unit 501229 redcliffe

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
2-Jul-16	General Equipment	215	Attempted to swap out both ends of sats probe cable individually, successful when new attachment cable attached (between Corpuls and the probe cable). Faulty part swapped out for new one, faulty part taken out of service, left in OIC intray	Light on in sats probe, Corpuls reports faulty cable, nil readings	Unknown	-
9-Jul-16	Vehicle	185	tried to refit. Unsuccessful	Seat belt Mechanism broken	V 4677.	A/OIC taking unit to this morning.
9-Jul-16	Vehicle	195	None	The Drop down tray next to airway seat has a broken clip not allowing the tray to be folded away. Tray edges are sharp and present a hazard	Unknown	-
9-Jul-16	Vehicle	210	Replaced with another machine. 6502 is now operational	Corpuls not operational. Exchanged with unit 2261	Etco2 connector	-
9-Jul-16	Vehicle	185	SOS notified, fault form completed.	Both car radios not working, Auxillary battery flat.	Flat Auxillary battery	OIC advises that Unit started without problem and is is use. NFAD
9-Jul-16	Vehicle	185	Sos notified, fault form completed.	Car not starting, Key not turning in lock barrel, no power to vehicle at all	Unknown, suspected flat battery.	OIC advises vehicle is operational. NFAD.
9-Jul-16	Vehicle	185	-	Vehicle radio. Three times in this 10 hour shift the radio would not receive or broadcast. Portable radios are working. Channel intermittently changes from channel 21 to 16. They were not knocked.	-	OIC Cairns advises radios working as normal this am, will be monitored.
9-Jul-16	Vehicle	190	reporting - vehicle taken out of service.	Front drivers headlight fail	unknown - Nil damage present	-
9-Jul-16	Vehicle	190	reporting - vehicle taken out of service	Front drivers headlight fail.	Unknown - Nil damage evident.	-
9-Jul-16	Vehicle	240	-	The gas struts on the boot lid are failing the keep the boot lid in the open position when required.	-	-
9-Jul-16	Vehicle	250	-	AC not working. ? Needs a re gas	-	-
10-Jul-16	Vehicle	235	Tried to re set	Mdt not working or updating halfway through shift	-	-
10-Jul-16	Defibrillator	240	Nil action to be taken to rectify, completed fault form.	12 lead Cable housing that attaches to monitor has been cracked, still operates and passing tests but can slip out of male/female connection quite easily.	-	This cable will need to be replaced as it could become faulty during operation.
10-Jul-16	Vehicle	250	-	Corpuls charging cable broken. Not charging	-	Rplaced defib cradle.
8-Jul-16	Vehicle	225	Booked in for repair	5 chips in windscreen checked with 2 old chips repaired 3 new chips 1 too small to be concerned 2 require attention booked in for Tuesday 12 1430 hrs	Stone from road !	-
10-Jul-16	Vehicle	250	Taken out of service. Stretcher at southport station	Head end legs of stretcher slow to lock	-	-
10-Jul-16	Stair Chair	230	Defect form has been lodged and chair has been removed from vehicle.	Chair unable to be opened (unfolded) on scene when required for use.	Not known	Equipment from vehicle 401851, rego 489TQM.

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
10-Jul-16	General Equipment	235	REMOVED MIC FROM RADIO AND PLACED IN OIC INTRAY. RADIO IS BEEN USED AS PER NORMAL	60107P2 RADIO MIC IS REMAINING ON AIR AS SOON AS THE RADIO IS TURNED ON. WHEN THE MIC IS REMOVED FROM THE RADIO THE RADIO IS FUNCTIONING NORMALLY.	FAULT IN THE MIC	RADIO FROM 601607.
10-Jul-16	Other Equipment	230	Fault form raised and phone has been removed from vehicle.	When phone is turned on, the (U)sim pin code is required. This is unknown to QAS officers.	Unknown, phone turned on and pin code screen appeared.	Phone is from vehicle 401851. Rego 489TQM
10-Jul-16	Defibrillator	240	-	SpO2 Monitor periodically not working for 2/7. Despite probe appearing to be functioning (red light active), saturations & a pulse rate will not register at all on the monitor. At times a saturation & pulse rate will register however is not accurate.	-	-
10-Jul-16	Vehicle	225	notified SOS	Vehicle radio not working	-	-
10-Jul-16	Vehicle	240	-	Vehicle used all morning responding to jobs. While driving had difficulty turning on interior lights. Next job while driving, siren, and two way radio not turning on. While parked red light flashing on module battery panel.	Na	Seems to have reset after driving back to station. Unit 5105.
10-Jul-16	General Equipment	240	Nil	Lines missing on display, making it hard to read the MDT.	Na	-
10-Jul-16	Defibrillator	240	Connect/reconnection.	Defib unit not syncing with monitor unit. Unable to defibrillate. Red message stating 'no connection with defibrillator unit'	N/a	Images sent to Oic spring hill email.
10-Jul-16	Vehicle	250	-	Auxiliary battery flat not holding charge 11.4 volts MDT shuts down not working if engine switched off.	-	-
11-Jul-16	Vehicle	185	.	Front compartment A/C faulty and not working	?	OIC advised crew to stop in at for mechanic to check. V 4678.
11-Jul-16	Vehicle	210	Tyre pressures checked and maintaining 240kpa pressure	Left Front Tyre has a Bolt/Screw imbedded in middle tread of tyre.	Unknown cause	-
11-Jul-16	Vehicle	225	Fix d by auto electrician recently for same thing.	Hit and miss working of suspension lowering and raising and locking of doors hit and miss of unlocking mechanism. Vehicle has recently had these things looked at by auto electrician but still faulty.	Unknown	Due to sporadic events still able to load patients safely.
11-Jul-16	Vehicle	250	Restart and recalibrate- did not fix	MDT navigation not working	-	-
11-Jul-16	Vehicle	195	Fault form, OIC notified	Side passenger step not working	Unknown	-
11-Jul-16	Defibrillator	240	Checked connections and plugs - all good and light on but nil reading obtained	Pulse oximetry probe does not work	Unknown - was working when unit checked at start of shift	-
11-Jul-16	Vehicle	240	-	Indicator lens broken and door to oxygen compartment not closing properly	minor Rtc	-
11-Jul-16	Vehicle	240	TOOK VEHICLE TO , ADVISED TO RETURN TO STATION AND NOTIFY OIC. step not used throughout remainder	REAR DOOR INTERMITTENTLY STICKING, UNABLE TO OPEN FROM THE OUTSIDE. ALSO AIRBAGS TAKING A LONG TIME TO COME BACK UP AFTER RESTARTING THE VEHICLE.	N/A	Vehicle Repaired by 12/07/16
11-Jul-16	Vehicle	195	of shift	Side step broken, step gives way under any weight.	As an officer stood on step is gave way	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
11-Jul-16	Vehicle	240	Spoken to ROC and driven to	Engine has excess movement during idle causing whole vehicle to shake. Surging when coming to a stop.	Problems started after code 1 drive	-
11-Jul-16	Vehicle	225	Advices oic	Car start battery not holding charge slow to crank. Rear door safety catch broken causing door to hit patients or officer.	-	-
11-Jul-16	Vehicle	240	informed and will look at vehicle on 12/7/16	Low aux battery despite vehicle being on charge all night & day MDT failure 2 hours into shift whilst at hospital	? alternator or battery issue	-
11-Jul-16	Vehicle	240	OIC notified and vehicle taken to for checking. Mechanic states no major problem detected, perhaps wear to rubber bush, ok to drive. Vehicle due for scheduled service in 3 days so they will take a closer look.	Clunking noise inR front heard when driving at slow speed over uneven road surface. Centre console that controls master switch, external lighting, emergency start etc - backlighting on switches is extremely bright and very distracting while driving at night. Have to cover with something at night so doesn't pierce eyes while diving.	-	-
11-Jul-16	Vehicle	250	-	Front and rear cabins intermittently smell like exhaust fumes. Very strong odour, even patient complaining of the smell in transit	-	-
11-Jul-16	Vehicle General Equipment	230	Nil. Vehicle off road	portable radio P2 stays 'open mice' when microphone extension is connected	? Exhaust fault	-
11-Jul-16	Vehicle	235	-	-	-	-
11-Jul-16	Vehicle	185	Oic and SOS informed	step wont retract	-	Vechile to be checked by on the 12/7/16. Job number V 4681. A/OIC to advise me when vehicle is back on road.
11-Jul-16	Vehicle	185	Despite numerous restarts vehicle has remained in limp mode. A/OIC, OCS and SOS notified. 7241 to be checked at on 12/7/16	Officer reported a fault with 7241 this evening. On return from hospital whilst driving along highway, engine management light illuminated and vehicle went into limp mode.	Unknown	Job number V 4780. A/OIC to advise me when vehicle is back on road.
11-Jul-16	Vehicle	195	SOS notified and car out of service	Smoke and bad smell coming from air conditioning. Loud clunking noise coming from L side front wheel when reversing.	-	-
11-Jul-16	Vehicle	185	-	axillary battery not holding charge. after stopping on scene or CBH all electronics stop within minutes. on restarting vehicle electronics including emergency lights, radio and internal lights do not come on for approx 10-15 minutes	-	unable to transport patients without internal lights and cannot attend code one cases. Vehicle has been checked, emergency lights, siren, interior lights all working. VEHICLE IS NOT TO BE USED FOR 24 HRS - afternoon crew to utilise Unit 7147.
11-Jul-16	Other Equipment	210	defect and sought replacement	vehicle power lead extension lead caught on side of vehicle (please note lead was unplugged at time) and has pulled lead from power plug. still usable but unsafe	-	-
12-Jul-16	Vehicle	180	vehicle taken off road and local mechanic notified of the problem and given allocated time to investigate the problem. Vehicle has been delivered to the local mechanic.	Vehicle engine warning light aluminated of dash. Vehicle does start and drives.	Unknown, possible blocked airfilter sensor or fuse blown	EGR valve malfunction, repairer cleaned EGR and now operational.

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
11-Jul-16	Vehicle	215	Fault form done	L) Side mirror loose	?	May need to be seen to ASAP as if the mirror becomes more loose then it may fall out?
12-Jul-16	Vehicle	195	-	GPS Unit not charging and external aerial connector damaged	-	-
12-Jul-16	Vehicle	225	-	Rear door passenger side hinges allowing door to slam. Not holding door open	-	-
12-Jul-16	Vehicle	250	None	Needs service 190000kms	-	-
12-Jul-16	Vehicle	250	None	has flat tyre	puncture	-
12-Jul-16	Other Equipment	225	-	Low oxygen mute switch does not mute the alarm	unknown	Nil action required
12-Jul-16	Vehicle	240	-	Issue with battery and battery charged. Mechanic already advised and correct problem. Report only.	-	-
12-Jul-16	Stretcher	195	stretcher removed from service and tagged out	Stretcher collapse, foot end of stretcher collapsed as patients legs were placed on to stretcher. Stretcher was at half height and checks were performed before loading patient on to stretcher. Nil injury to patient.	Unknown	-
12-Jul-16	Vehicle	240	Attempted to trouble shoot - hard restart + moved outside to get better coverage	MDTnot logging on	Unknown	-
12-Jul-16	Defibrillator	215	problem solved split modules as directed no effect	Monitor displays "shutting down" but won't shut down	-	-
12-Jul-16	Vehicle	235	-	Bottom draw in back doesn't stay shut	-	-
12-Jul-16	Vehicle	235	-	Battery door doesn't shut properly setting alarm off	-	-
12-Jul-16	Vehicle	245	repeated assessment by assigned persons	Earf draw latch broken	Yoodoo?	-
12-Jul-16	Vehicle	245	repeated assessment by assigned persons	MDT. Repeatedly fails with screen blacking out, freezing, clicking noises coming from CPU.	unknown recurring	-
12-Jul-16	Vehicle	240	RACQ contacted changed tyre.	Flat tyre damaged rim	Unsure. LHS rear tyre PSI low at commencement of shift - pumped up at approx 1850. At 2235 whilst looking for pt in park large gutter was reversed off. No issue noted after case however at 2330 tyre appeared to be flat. Pulled over when safe to do so.	Email sent to MN day OS to have tyre changed. Vehicle not at station on commencement of shift
12-Jul-16	Vehicle	240	Not to my knowledge	Radio not working	Discovered fault on start of shift	DP - Vehicle charged overnight. Fault resolved - Charging issue.
13-Jul-16	Vehicle	225	vehicle fault form.	Right headlight not working.	unknown	1 headlight not working. The rest are good. vehicle still operational.
13-Jul-16	Vehicle	225	attempted to replace bolts however none suitable	R) side grab bar unsecured (bolts missing). - could be a falls risk if a problem goes to grab it	Unknown	-
12-Jul-16	Vehicle	210	None	Back airbags / suspension	not known but at approx 1630 yesterday after coming back from Rockhampton car was parked at station. A Big Bang was heard but no source could be found at the time ??	-
13-Jul-16	Vehicle	210	None	Back airbag / suspension	not know however after traveling back from Rockhampton the car was parked at station and at approx 1630 a loud bang was heard ... At the time source could not be identified.	-
13-Jul-16	Vehicle	215	Nil	Reversing camera not functioning	-	-
13-Jul-16	Vehicle	240	-	Ongoing issues with battery. Delay of 3 mins responding to 1A due to waiting for MDT and radio to restart. Vehicle was plugged in at the time.	-	MDT shuts down completely when sitting at station which causes significantly delay in response time and acquiring the mapping.

RTI RELEASE

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
10-Jul-16	General Equipment	200	Oic and duty manager advised.	Drug ampoule found with small scratch on top of vial near break dot during transferring of drugs at end of shift.Slight amount of condensation seen in the ampoule. Duty manager advised. Ampoule was Aspen type.	Possibly caused during use of another ampoule during the day.	-
13-Jul-16	Vehicle	195	Turning vehicle off and on, same with modular power, front air conditioning mains and rear air con main	Rear Air Conditioning not working	Unknown	All other component operational in back.
13-Jul-16	Stretcher	240	Na	External locking mechanism seems to falsely engage at times. Resulting in a jolting and partial drop in movement	Na	Roc notified...vehicle 229
13-Jul-16	Vehicle	240	-	MDT taking awhile to update and also randomly switching off numerous times in a shift. Once requiring a reset on the master switch.	-	MDT still operates however switches off at inconvenient times
13-Jul-16	Defibrillator	210	placed on several different (working) 240volt wall chargers with nil effect	Corpuls not charging	unknown	-
14-Jul-16	General Equipment	195	-	When at a suction section of oxygen kit. Attempts made to clean section however has appeared to soak into lining.	Small suction bottle overflowing before QAS realised.	Oxygen kit was from 1133. Kit removed from vehicle and left on floor of plant room with note on top of Kit. Oxygen kit removed from 1435 as nil spare found.
14-Jul-16	Vehicle	245	Advised Acting OIC, Central and Met. Sth Operational Supervisors respectively via mobile phone to organise repairs.	Non operational MDT and Radio.	technical issue - software, electrical?	Ongoing issue with MDT attended by numerous technicians over two years.
14-Jul-16	Vehicle	225	-	Drivers seat has 2 x tear in upholstery- will be repaired during next routine service	-	-
14-Jul-16	Vehicle	185	vehicle taken back to station at 60 kph	Severe vibration on vehicle while under power which starts at 70 kph , at 80kph the vehicle is shuddering and the steering wheel is also vibrating. On lifting off the throttle pedal the vibration stops. Whit the vibration the noise level increases	-	OIC taking unit to V 4695.
13-Jul-16	Defibrillator	250	All three units of the Corpuls3 were taken apart and put back together several times with unsuccessful result.	Patient Box would not recognise other units which caused disassociation of all three units which made it inoperable.	Unsure. Units were separated earlier in the day in order to get the Serial Numbers from all three components.	Nil compromise in Patient care as a backup unit was obtained a few minutes later while enroute to hospital.
14-Jul-16	Vehicle	240	OIC notified, light removed from plug and placed inside the vehicle	R) scan light found disconnected from vehicle, hanging by cord.	Unknown- vehicle was washed without noticing any problems, on arrival at scene when R) sliding door was opened scan light dangled down.	-
15-Jul-16	Vehicle	250	Fleet tech	Side step us Right rear tail light us Amber dash engine warning light	-	CDs informed
14-Jul-16	Vehicle	195	Ocs notified and changed out of vehicle,	Roof leak above passenger side stretcher, raining.	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
15-Jul-16	Vehicle	195	Vehicle fault form completed. Passenger seat inside cabin will not be used.	1101. Sliding side door not opening properly ?rubbish stuck behind door. Bin inside cabin not secure ?cause. Passenger seatbelt inside cabin also loose ? safe.	unknown	-
15-Jul-16	Vehicle	200	water been cleaned up and monitoring	During rain last pm significant amount of water came through air conditioning unit into vehicle this am	Heavy rain	-
22-Feb-17	Vehicle	235	Fleet and OIC notified.	Excessive play in steering, vehicle over steers and under steers, also pulling to the left. Particularly noticeable at speed when being driven under code 1 conditions.	-	-
14-Jul-16	Stretcher	215	taken out of service	Collapsed under test Due for service	-	-
24-Feb-17	Vehicle	245	Called ROC	Beacons and siren not working. Onboard oxygen not working - cylinders are full. Front headlight on R) HS not working.	-	-
15-Jul-16	Vehicle	210	Vehicle taken off road, under investigation at	vehicle leaking in wet weather, inside rear compartment along lighting strips, dripping onto passenger side stretcher. in situ > saturated & leaking through.	-	-
15-Jul-16	Vehicle	195	Car has been placed on charge, SOS notified. Car placed out of service until further notice.	Car wouldn't start	Car was charged over night and started normally during pre shift check. However car was unintentionally left off charge for approximately 25 mins. Car wouldn't start after this. Both batteries on the car were in the red.	1030 SOS notified that are on their way
15-Jul-16	Vehicle	210	Fault report.	2 small stone chips in the windscreen one on each side. Require filling for repair	Unknown	Stone chips look very old.
15-Jul-16	Vehicle	250	Phoned mechanic, no answe, he is off sick. Phoned and advised SOS	No electricals. Click only when turning on ignition key. Orange light on charge box behind side sliding door does not light up. No change after pressing reset button.	-	Vehicle returned after service yesterday. .? Not plugged.... Will assess at end of shift.
24-Feb-17	Vehicle	230	OIC Maroochydore attempted to push it back into alignment (reclip in) but was unsuccessful	Front drivers side door panel, black trim on the bottom of the door has become unclipped, displaced slightly	Unknown	Non urgent, if it could be noted and managed at the next service at that would be appreciated.
15-Jul-16	Vehicle	225	VEHICLE TAKEN TO AT ~ 11:20 AM (VEHICLE OFF ROAD - AWAITING PARTS ? ACA COMPUTER MODULE FAULT).	DAILY VEHICLE CHECK COMMENCED AT 08:05 (Not completed due to Code 1 @ 08:09 - case # 7796098 refers)	DURING CODE 1 RESPONSE, ENGINE FAULT LAMP BEGAN TO FLASH.	-
15-Jul-16	Defibrillator	195	Probe removed from service and replaced with new probe.	Spo2 probe not working, Working intermittently.	-	-
15-Jul-16	Vehicle	250	Report forms completed, SOS notified.	Minor scrape on lower rear portion of passenger side sliding door	At Emergency scene, very difficult and narrow access to get to patient. Misjudged a low lying black painted post and caused minor scrape to plastic trim and red reflective trim.	-
16-Jul-16	Vehicle	200	Comms notified. ICT fault report has been logged.	two-way radio not transmitting	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
16-Jul-16	Defibrillator	195	Several attempts of trouble shooting has been done - swapping sensor, swapping cable, removing and inspecting plugs etc. Has been removed from service.	Fault with SPO2. Top left of screen displaying "Defective Oxy cable" This leads to intermittent readings.	Unknown	OIC rectified the issue - new SPO2 lead
16-Jul-16	General Equipment	195	Removed from service.	Air leak from ?burst seal from hole in base of regulator (look at the blue metal part) inbetween oxygen tube connector and "Y" branch tubing.	Unknown, ?oxygen cylinder opened too fast causing extreme pressure on seal.	Last tested June 2016
16-Jul-16	Vehicle	250	Fault form.	No power to MDT. Will not turn on.	-	-
16-Jul-16	General Equipment	195	Replace	Zippers on response kit broken and kit needs to be replaced.	N/A	-
16-Jul-16	Vehicle	210	-	Stretcher carrier mechanism attached to vehicle doesn't lock in place as you're loading the stretcher onto it. This only occurs intermittently.	Unknown	-
16-Jul-16	Vehicle	240	Changed tyre	Vehicle had Puncture on passenger side rear tyre. Tyre changed over with spare by RACQ. unable to get tyre repaired on weekend. Vehicle now has no working spare. Low tyre pressure warning light still showing on dash.	-	-
16-Jul-16	Vehicle	190	-	Missing inverter switch	unknown	-
16-Jul-16	Vehicle	185	Checked that fridge was switched on - it was, fault form completed needs to go to OIC to take to	Fridge not working	-	Issue resolved itself after vehicle had been used. ? low battery turning fridge off. AOIC to monitor issue and resubmit fault report if req
16-Jul-16	Vehicle	245	OIC to take to	Music radio doesn't turn off- The on/off button doesn't work The front 12V port doesn't work so cannot charge the toughbook	-	Unable to charge toughbook
17-Jul-16	Vehicle	220	Not using the heater. Will need to be checked by a mechanic on a weekday The screen does not affect the operation of the vehicle. All functions can be used through other screens.	When the heater in the rear of the vehicle is turned on it does not work and there appears to be a diesel leak under the middle of the vehicle which stops once the heater is turned off. The screen in the rear of the vehicle is not functioning	Unsure	-
17-Jul-16	Vehicle	185	Unknown	Radio	Unknown	Radio continues to change to channel 16 from channel 21. This action is only intermittent and does not get knocked. OIC Cairns to log IT job and have 7289 taken to PSBA for repair.
17-Jul-16	Vehicle	225	Attempted to push door open from inside and pull open from outside with no success.	Rear door will not open	Unknown, morning vehicle check rear door latch was stiff but functioned normally. I went to throw some gear in the rear compartment and could not open the door.	-
16-Jul-16	Vehicle	220	refer to tomorrow, 18th July 2016	Driving lights non operational	whilst driving to Roma on a case the driving lights remained on despite dipping and turning off lights on emergency panel. Pulled over and unplugged driving lights and cut positive wire to light bar.	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
8-Jun-16	Vehicle	205	reported to OIC and she report completed	Damage to rear module. Passenger side. Just behind rear wheel	impact with a kangaroo	speedo reading approximated due to un-sure of exact at time of incident - Quote received and Insurance Claim Accepted. Awaiting information from to book vehicle in. Vehicle driven to Ravenshoe station and secured. Job number V 4696
16-Jul-16	Vehicle	185	nil	Broken rear door window	backing into a clothesline	
16-Jul-16	Vehicle	225	-	the charging point on the vehicle is registering it still has contact so the engine would not start	??? a magnetic issue within the socket	vehicle started by other means - ie pressing another button
17-Jul-16	Vehicle	245	reported to ROC, and this form has been created	Left side rear door upper/top door lock will not in gauge and lock. Step to rear cabin not working (believed this has already been reported. Battery fault/alternator light illuminated on dash, ?due to lights left on and vehicle not plugged into charge.	unknown this fault was found when doing vehicle check this evening	-
17-Jul-16	Vehicle	225	mechanics need to fix.	Rear air bag suspension does not work and continuously deflated. patient compartment very rough on transport	unknown cause	-
17-Jul-16	Defibrillator	210	Checked and changed blood pressure cuffs and air line with nil effect. Reported fault to SOS and device services. Vehicle defect is being	Blood pressure unit not functioning. Blood pressure very slowly inflates to 160mmHg (unable to inflate any more), remains at this pressure for a long time before timing out.	Defective air pump in unit	As per instruction of SOS unit 2209s corpuls was placed in unit 2179, as 2209 is defective and no other units were available at shift logon
17-Jul-16	Vehicle	210	completed	Vehicle makes an audible and physical shuddering when started. Appears to be coming from fan belt	-	-
17-Jul-16	Vehicle	210	Ensured equipment restrained. Tested airbags- appeared to be normal.	Whilst driving vehicle 286 low speed turning left had a dull knocking noise. All equipment restrained, steering not on full lock.	Unknown	-
18-Jul-16	Vehicle	240	contacted, and dealing with this, as vehicle had same fault last week	Flat battery car will bot start	-	-
18-Jul-16	Vehicle	240	contacted and dealing fault form completed	Flat battery	-	-
18-Jul-16	Vehicle	225	Booked for service Tuesday 26/07/2016.	30,000km service due.	No fault	-
18-Jul-16	Vehicle	235	The vehicle will be dropped back at Ipswich station.	While travelling through Esk heading to case at Lindville, became aware of strong pungent smell from within vehicle	We believe the power pack servicing the MDT was the cause of the problem, situated behind passenger seat.	-
18-Jul-16	Vehicle	245	sent to repairer	tail lights broken	vehicle crash	-
18-Jul-16	Stretcher	225	support has been notified and is booked to service the stretcher tomorrow morning.	Faulty battery on lift component	-	-
18-Jul-16	Vehicle	215	-	Knocking noise in rear suspension when traveling over rough terrain. Usually when vehicle is articulating.	? Loose suspension or control arm bushes	-
18-Jul-16	Vehicle	225	RACQ CALLED OUT & NEW BATTERY FITTED.	POSSIBLE BATTERY FAULT - PATIENT COMPARTMENT LIGHTS FLICKERING AND LOSS OF 12 VOLT POWER DURING A CODE 4.	-	FAULT TO BE MONITORED.
16-Jun-16	Vehicle	215	-	Reversed into over hanging sign on footpath parking bay	over hanging sign	-
18-Jul-16	Vehicle	185	-	Vehicle is not holding charge	-	Reported to OIC & have been advised to take vehicle off the road. SOS will have afternoon S'field crew take unit to V 4701.
18-Jul-16	Vehicle	245	Nil	Rear equipment module with broken draw and not stay closed.	?	-
18-Jul-16	Vehicle	240	nil as is MDT.	MDT had turned itself off - unable to be turned back on - attempted reset with no result - no power at switch.	? Electrical fault or fuse.	Requires technical officer to investigate.

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
18-Jul-16	Vehicle	235	-	Rear Drivers side Tyre/wheel Missing Tyre Pressure indicator.	Punctured Tyre was Replaced. New Tyre/wheel missing Tyre Pressure Instrument. Car alarming on dashboard regarding this.	Just keeping fleet informed.
4-Jul-16	General Equipment	245	Previously electronically lodged report.	Fault with operational radio. Loud audible beeping sound which is intermittent every five seconds.	Soft ware programme, electrical fault.	N/A
19-Jul-16	Vehicle	225	Nil	Abs warning lights Stretcher has hit the passenger side tail light and made a hole approximately 10 mm wide	Unknown	-
17-Jul-16	Vehicle	240	Training from OIC Due for service and	1. Power plug for torch and earf has no 12V output	Stretcher rolled should have had break on	-
19-Jul-16	Vehicle	245	booked in this week car has been turned off and locked and started again.	2. Rear right scan light loose and falling off	Unknown	Nil
19-Jul-16	Vehicle	240	Will take vehicle to in Tully when available	Car will not accelerate above 20km/h Half of the code one lights on the front of vehicle not working, blown fuse in vehicle fuse panel. QAS officers replaced fuse and tried lights again, fuse immediately short circuited.	driving code 1, the car then jolted and would not accelerate Small LED light on bonnet appears to be cracked query water intrusion/short circuit	ROC notified Vehicle going to even date. V 4704.
19-Jul-16	Vehicle	235	nil	right rear scan light filling with water and not all lights are operational.	faulty light module?	-
19-Jul-16	Vehicle	250	-	As we drove out of the station we noticed that the rear of the vehicle scraped along the driveway exit. We pulled over and found the rear suspension to be fixed into the low position and unable to be raised using normal procedures (switch).	-	The car was extremely rough and bumpy to drive. As the rear suspension is so low it also poses a risk to safe operation of the vehicle,
19-Jul-16	Vehicle	185	Notified OIC, COMMS. IF POSSIBLE, WE WILL TAKE THE CAR TO MECHANICS TODAY	Problem with car battery. This morning, whilst completing vehicle check car battery was extremely low despite being on charge since this morning The internal lights turned off within a couple of minutes of checking the car.	-	OIC to take unit to V 4706.
19-Jul-16	Vehicle	240	OIC inspection of locking mechanism found it to be engaging without fault after numerous tests completed with different stretchers. Red release button clicks but when disengaged can seem "spongy".	Stretcher does not lock in place securely in vehicle. Locking mechanism does not appear to be securely holding stretcher on base plate in vehicle. ROC notified 19/7/16	Unknown - constant use/fault?	-
19-Jul-16	Vehicle	185	Will contact the SOS	SRS warning light is on the dash board, hasn't gone away. SRS (supplemental restraint system) Manual states malfunction in the system.	-	Vehicle to be taken to V 4705.
19-Jul-16	Defibrillator	215	taken equipment out of service	Not charging in car cradle, 2 cars tried	-	-
19-Jul-16	Vehicle	225	Informed OIC	R Headlight not working	-	-
16-Jul-16	Vehicle	215	Vehicle was taken to the mechanics and repaired on return from job	Patient care door locked while officer in vehicle.	Faulty locking mechanism at patient care seat door	-
11-Jul-16	Vehicle	215	Taken to Repair agent who performed fault finding and actioned faults	Satellite phone not charging - ? Fuse. Reverse camera sensor continuously activated noise in reverse	Blown fuse - fault find. Isolated reverse sensor as a temporary measure	-

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
5-Jul-16	Vehicle	215	Broken sensor - part ordered and replaced a week later	Ride height incorrect - rough ride in module.	Broken sensor - part ordered and replaced a week later	With caution
16-Jul-16	Vehicle	215	-	'Door open ' alarm intermittently alarming.	-	-
20-Jul-16	Vehicle	210	Tyre inflated to 420 Kpa but still need to be repaired	Nail in R rear tyre. Tyre deflated to 350kpa. Tyre pump up to 420kpa again.	-	-
20-Jul-16	Vehicle	240	-	Siren does not operate. As per conversation with ROC have been instructed to take the car to the mechanics to get it looked at.	-	-
20-Jul-16	Defibrillator	250	cable replaced	Pulse oximetry not reading, indicating cable fault	Unknown	-
19-Jul-16	Vehicle	225	UNIT TAKEN TO LOCAL MECHANICAL REPAIR.	12 VOLT SOCKET FOR DEFIB NO POWER AND VARIOUS LIGHT BULBS BLOWN IN PATIENT AREA.	FUSE BLOWN AND SEVERAL BLOWN BULBS.	-
18-Jul-16	Defibrillator	185	Notified OIC Monday 18th July	When doing vehicle check prior to shift start, noticed Damage to V5 lead connection. At this stage, it does not effect the reading however this is visible damage. There is a photo attached in the vehicle checklist I completed on Mon 18th. 7147	-	OIC Edmonton to log job/order new leads.
20-Jul-16	Vehicle	210	Authorised to replace globe tomorrow	Front passenger head light	-	Globe blew late this afternoon
19-Jul-16	Defibrillator	245	Equipment removed from vehicle. OIC notified	Not registering the pads/test box when plugged into the back ?faulty connection	No idea	contacted for advice with issues resolved 21/7
21-Jul-16	Vehicle	240	-	Fridge not working, has no power supply and on/off switch isn't working.	Unsure ? Wiring or switch issue	-
21-Jul-16	Defibrillator	225	Cable has been replaced	Spo2 main cable damaged	-	-
21-Jul-16	Vehicle	240	-	MDT intermittently shutting down en route to jobs and when driving	-	-
21-Jul-16	Vehicle	205	none - Duty Officer and business manager notified	A light has come loose and is hanging off the vehicle.	backing into a roller door	-
21-Jul-16	Vehicle	200	1. Handle can be manually pushed in, allowing door to close. 2. Shears/other long flat object can be used to manually release pins holding in defib.	1. Rear barn door exterior handle "sticking" open, preventing door from closing. 2. In car Corpuls bracket not releasing defib from bracket when handle is pulled.	-	-
22-Jul-16	Vehicle	240	to assess	vehicle picked up from Spring Hill - hard to start. On charge all night flat today	Unknown	-
22-Jul-16	Vehicle	240	Narangba OIC notified	Driver side window button broken off. And the consumables compartment door in the upper left rear of vehicle broken off.	-	-
22-Jul-16	Stretcher	245	nothing. Just keeping	When returning the stretcher to the vehicle and as it hits the sensor, it is slightly out of alignment (approx. 1.5), so needs to be manually pulled to the right in order for it to lock in at the foot end of the stretcher.	brand new stretcher never used.	-
22-Jul-16	Vehicle	210	Nil	Dent in yellow reflective area on rear right hand side door	Unknown, noticed after vehicle check	-
22-Jul-16	Vehicle	240	-	Stair chair bracket loose pre- existing	-	-
22-Jul-16	Vehicle	240	First time it was plated with another piece of metal screwed on with stainless steel bolts.	Fold -Out alloy step has hairline cracks going through the front edging of the step-Safety concern.	Each time an obese Pts weighing approx 150 KLG.stands on this light weight step - The step has buckled.?? strenght not suitable current usage.	Requires a heavy duty step.
21-Jul-16	General Equipment	195	Placed in Sth Townsville Oic tray door, labelled	Laryngoscopes body in airway wall mounted treatment cabin light not working, changed batteries interchanged blades with nil change faulty	Unknown	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
22-Jul-16	Vehicle	240	-	Brakes very spongy and smelled horrendous while driving moderate code 1. Ok code 2. Front passenger wheel still smelled bad 1hour later.	-	repaired
22-Jul-16	Vehicle	185	-	Rear communications radio faulty and won't turn on. 'Clunking' and high pitch noises with vibrations through steering wheel when turning	-	Radio 'repaired' by PSBA - wasn't plugged in correctly.
23-Jul-16	Vehicle	240	Restocked	Operational as in able to be driven but extremely low on essential stock	Vehicle not restocked by previous shift.	-
23-Jul-16	Vehicle	240	-	MDT is flickering and turning purple when hitting bumps in road	-	-
23-Jul-16	Defibrillator	200	different pads were tried. The machine was restarted and it could still not connect.	Defibrillator pads cannot connect to the machine. It continually says therapy electrodes loose.	not known	-
23-Jul-16	Vehicle	200	Notify SOS, complete fault report, email OIC, vehicle still drivable, scan light only damaged	Driving through RFDS gate, contacted RHS scan light on protruding part of upper gate (will try to attach photos), pulling scan light from side of unit (still attached).	Unit 2999 is tight fit, focused on squeezing through open gate, and was unable to see upper part of gate was angled to the degree it was... So scan light brushed against gate protrusion.	-
23-Jul-16	Defibrillator	240	Attempted unplugging spo2 and restarting monitor with no success. It has been taken out of service and placed out front of OIC's office	SPO2 sensor monitoring is defaulted. It did not pick up pulse or SPO2 at the beginning of shift.	Unknown	Replaced
23-Jul-16	General Equipment	225	-	low O2 alarm not sounding when tested	-	-
23-Jul-16	Vehicle	195	-	Side step is broken and will not retract.	-	-
23-Jul-16	Vehicle	195	fault form raised	Vehicle suction not working, circuit-breaker has not tripped, module power reset with no change to fault	Vehicle suction not working, switch not working, circuit-breaker has not tripped, module power turned off and on...no change	-
23-Jul-16	Vehicle	225	car taken off road	rear suspension not working, drivers compartment light randomly lighting up, oxygen door drivers side randomly opening	-	Waiting for windscreen washer pump ordered
24-Jul-16	Defibrillator	240	Reported fault for further investigation as unit still under warranty	Spo2 not registering. Unit warning of a defective SPO2 cable	Unknown just stopped working	OIC emailed about fault
24-Jul-16	Vehicle	215	SOS and Comms informed, fault form completed	Strong smell in cab (rotten eggs) , believed to be fault with battery	? Battery	-
24-Jul-16	Vehicle	225	Restart vehicle to see if computer resets.	Engine warning light illuminated, vehicle not down changing gears.	-	-
24-Jul-16	Vehicle	225	Restart to see if computer resets.	Engine warning light illuminated, not down changing gears.	No	-
24-Jul-16	Vehicle	210	-	Light that indicates car is charging not glowing when lead is plugged in and power is on.	-	-
24-Jul-16	General Equipment	210	-	Medium splint has holes along edge with white tag about 1cm under seam. Will not stay deflated.	-	Could not locate a spare on station to replace.
24-Jul-16	Vehicle	225	-	Second battery is going flat. Main battery is ok. There is no warning indicator in the vehicle, noticed radio switched off when attempting to transmit. Battery doesn't appear to be charging when plugged in at the station either.	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
24-Jul-16	Defibrillator	250	taken out of vehicle and tried to charge off mains, starts to charge but doesn't stay charging	Not charging in bracket or mains	-	Low battery 14%
24-Jul-16	Vehicle	225	Step mechanism has been cleaned and now working correctly	Side step won't retract in,	Unknown	-
24-Jul-16	Vehicle	215	-	No interior lights in rear of ambulance	-	NOT OPERATIONAL AT NIGHT
21-Jul-16	Vehicle	225	Tried to turn on on several occasions	AM/FM radio not turning on.	initially radio was working but unable to turn off, change station or adjust volume. Next time vehicle was turned on radio would not work at all.	-
24-Jul-16	Vehicle	225	restart engine many times . Nil success	Glow plug light had come on , then Engine light	?????	-
25-Jul-16	Vehicle	245	Fault form completed	Right headlight not working	Blown globe	-
25-Jul-16	Vehicle	240	unable to reset on restarting. Arrange for workshop	Engine dash light flashing - vehicle won't drop down gears when accelerator pressed to floor - lacking power to climb uphill	Unknown	-
25-Jul-16	Vehicle	225	Once vehicle is started the doors are able to be opened.	Module doors intermittently not opening when vehicle is not running even though vehicle is unlocked and module doors showing green light.	-	Vehicle has been sent for repair on a previous occasion , however this has started occurring again.
25-Jul-16	Vehicle	240	repairs	Fuel line	failure	-
22-Jul-16	Vehicle	215	Reported	Water leak in rear of cabin. After scent rain. Water was seen on the passenger side walls, floor and stretcher. Vehicle was parked at an angle of Friday (leaving towards passenger side) and water dripped from the roof onto the floor over the sitar area	Roof leak	-
25-Jul-16	Vehicle	240	-	Front left park light out	-	-
24-Jul-16	Vehicle	250	-	Sliding door stiff to operate sliding mechanism unserviceable	Wear and tear	A/OIC Inspected on 28/9/16. No fault found. Unsure if it has been repaired previously and not recorded.
25-Jul-16	Defibrillator	240	Taken out of service. Unable to be screwed back on as it has broken off the actual defib.	Terminal on the defib box broken off.	Defib was pulled apart for a job and when I went to connect the patient box, the terminal plus springs broke off.	-
25-Jul-16	Vehicle	235	SOS was notified by phone immediately and SECOMM were also contacted straight away. The unit was placed OOS in the IGH ED bay and the crew were required to wait while RACQ attended. As such, the crew did not receive any meal break (7-5 shift).	Crew were required to ramp with patient in IGH ED for extended time frame > 3/24 (Case . Upon placing patient into cubicle, preparing vehicle and advising Partial Availability, the dual stretcher ambulance 602667 was found to have flat batteries.	Unit 602667 has been found to have this exact fault on numerous occasions, placing into an unserviceable state and requiring RACQ. The electrical fault has never been repaired. It is obvious that the issue is too many electrical items in the ambulance.	The SOS requested that the unit be taken to Ipswich Station and swapped over for an alternative ambulance unit.

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
24-Jul-16	Vehicle	240	reboot	The MDT on 5003 shuts itself down within 5 minutes of the vehicle ignition being turned off, and takes several minutes to wake up once the vehicle is restarted. This is regardless of whether or not the vehicle is plugged into the mains.	-	-
25-Jul-16	Vehicle	190	-	Rear LCD screen non-functional.	unknown.	Mains and other essential panels in good order.
24-Jul-16	Vehicle	215	This fault report	Left head light out	-	only not being used at night
26-Jul-16	Vehicle	240	-	Front left headlight blown	-	-
26-Jul-16	Vehicle	210	Will discuss with OIC to see if vehicle can be dropped by workshop during duty today for a quick assessment on fault & if parts are required to be purchased prior to fixing.	Front drivers side bullbar emergency beacon non-operational during vehicle check this morning.	-	-
26-Jul-16	General Equipment	230	The fault has been reported and a note left on the vehicle for future crews and portable O2 removed from vehicle.	Post O2 changeover of portable oxygen, the suction would do the opposite of what it is intended to do (blowing out).	Not known	-
26-Jul-16	Vehicle	250	-	Heater not functioning at all. Navigator stand attached to internal front unit vibrating +++ when moved slightly will stop. During fast driving vibrations increase +++. Entire unit that mains and navigator are in is coming out of position this has resulte	Resulted in mains periodically disconnecting. This seems to happen more when going code 1 and unit needs to be manually pushed back in to have lights/sirens working as they cut out.	Mains not functioning when Nav unit vibrating
26-Jul-16	Vehicle	240	-	Side step not retracting. OIC informed and organised repair.	-	-
26-Jul-16	Vehicle	240	Nil	Passenger side light near step underneath vehicle taken off.	Scraped over rock in patient's driveway	-
26-Jul-16	Defibrillator	210	Taken out of service until rectified. Corpuls service centre called and issue has been reported.	Will not go into test mode when connected to tester box.	-	-
26-Jul-16	Defibrillator	245	notified OIC, taken out of service, replaced with training defib	defib handle snapped off	device fell over	AOIC contacted 26/7/16 at 0950. Awaiting call back from technician.
26-Jul-16	Vehicle	240	refer for service department - vehicle placed off road.	Flashing Amber engine light, abs, tyre pressure lights on Amber. Vehicle now stuck in limp mode. Cannot drive over 60kph	unknown	-
26-Jul-16	Stretcher	240	Pt removed, prongs dislodged	Power load prongs slipped onto other side of stretcher. Stretcher unmoveable	30 degree angle of truck	-
26-Jul-16	Vehicle	225	booked in and dropped off for a service on the 26/7/2016	vehicle service required - service due at 30000,	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
26-Jul-16	General Equipment	210	Equipment has been removed from unit (out of order), I have ordered a new one through medical orders. I changed the batteries and cleaned the tip of the thermometer with nil improvement.	Tympanic thermometer in unit 2243 response kit is not reading the correct temperature - when used its showing 3-4 degrees celcius below the actual temperature. For example when I checked my own temperature it recorded a temp of 33.1.	Unknown.	-
26-Jul-16	Defibrillator	240	Cables were replaced with another spare set and fault was rectified.	Lead III was showing as faulty. It was displaying as vertical lines on the screen.	Unknown	-
26-Jul-16	Vehicle	195	-	Engine light began flashing whilst driving on the way to a job, SOS notified and advised vehicle to be placed out of service.	-	-
26-Jul-16	Vehicle	185	None	Magnet missing off of side door for kit bags, now will not stay open when needed	Loss of magnet	-
26-Jul-16	Vehicle	185	None	Small round white light in n/s front bumper not working	-	AUTHORITY NUMBER v 4738. Email invoice to <QASLASNCAH.ReadinessCoordinator@ambulance.qld.gov.au>
26-Jul-16	Vehicle	185	Vehicle off road, awaiting repair	Bonnet blue light bar has come detached from housing and is now hanging by cables.	Whilst attending a job at a neighbour came out and was admiring our blue light system. He stated that "it just came of in his hand"	Double up of fault report
26-Jul-16	Vehicle	185	Vehicle off road awaiting repair connected new adult and pedi probes without successful resolution	Bonnet light bar broken, now hanging by cable	Whilst vehicle was parked up at a neighbour came out and admired our blue light system. He stated the "it just came off in his hand"	JOB AUTHORITY - V 4737. Please email invoice to <QASLASNCAH.ReadinessCoordinator@ambulance.qld.gov.au>
26-Jul-16	Defibrillator	185		sPO2 probe intermittently drops out	unknown cause	Cairns OIC to log a job with
27-Jul-16	Vehicle	225	Filled with water in the morning	Slow leak in radiator water	-	-
26-Jul-16	Vehicle	225	Reported fault on checklist and defect form. Spoken to requested assessment	SIDE step malfunctioning. Does not come out.	-	Staff to take care when entering and exiting vehicle. Ensuring they use 3 points of contact getting in and out of back of ambulance, whilst STEP is out of action.
27-Jul-16	Vehicle	190	Unable to rectify	Defibrillator charging plug snapped off in socket. Unable to charge defibrillator in cradle	Unknown	-
27-Jul-16	Vehicle	240	Informed the OIC and reported the fault.	The power is greatly reduced when taking off on a hill or over such things as a speed bump. No power to take off from a stopped position on a hill. Not sure but my guess is a sticking turbo??? Taking off in some instances such as an busy intersection	may prove hazardous at times. This has been reported before under the old system earlier this year and has not been resolved.	The vehicle is operational however it is on occasions that the fault may become hazardous when on a steep grade or busy intersection etc. on a steep grade the vehicle sometimes needs to to be reversed to make a 'running start' to take off on a hill.
26-Jul-16	Vehicle	200	Device has been turns on/off - not successful. Ensured all cords connected. Nil result.	GPS device in unit 2155 not working. Device turns on but touch screen will not register when touched to enter destination details. Device did not work from commencement of shift.	Unknown	-
27-Jul-16	Stretcher	215	Put out of serviced	Pt was on stretcher and being raised, head end first. When head was raised, the feet end dropped to the ground. No officer was touching any of the buttons at the feet end when stretcher dropped.	Unknown	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
27-Jul-16	Vehicle	225	-	Due for service 115000km	-	-
27-Jul-16	Vehicle	235	Completing a fault form.	Plastic covering inside drivers door falling off.	Lazy Germans and a lack of quality control during manufacturing.	I have inspected this at IGH after receiving the fault report and assessed damage, appears to be a fast repair.
27-Jul-16	Vehicle	210	Fault reported	The electric side step is not functioning properly it only comes out half way then retracts . An alarm is sounding regarding the malfunction of the step. I have turned the step switch off	Not known	-
26-Jul-16	General Equipment	235	27/7/16 phone call report to acting fleet tech and email with photo attached...	O2 spare 'C' cylinder bracket in 6643 is not locking shut, so O2 is loose and banging within bracket as travelling	-	ongoing problem as has been reported and checked previously.
26-Jul-16	Defibrillator	240	Unit placed out of service for service department to inspect.	ECG Limb Lead fault, wandering baseline - Cannot read test leads in 3 and aVL intermittent fault.	? faulty / damaged limb leads.	-
27-Jul-16	Vehicle	225	-	Pink fluid leaking from enginebay ? Power steering fluid approx 20ml	-	Spoke to mechanic at who advised its ok to drive in to Dalby
26-Jul-16	Vehicle	185	Have contacted We tried to get 7147 into the mechanics today however was told this job will take a while to fix up the light. Will try and get 47 to mechanics tomorrow if permits.	1 x emergency light out only. Top square blue light on dash board.	job number V 4741. OIC to advise	when repairs complete.
27-Jul-16	Other Equipment	240	Tough book placed at OIC office door	TB000188 not working, turns on however when trying to launch VACIS it displays a fatal error message and does not open VACIS	-	-
28-Jul-16	Vehicle	185	VOR awaiting repair	O/S rear window smashed on way to Cairns by passing B-Double	? Rock job	authority V 4739. Will be in touch with OIC.
24-Jul-16	Vehicle	245	Vehicle repaired already	Broken L tail light	Stretcher hit L rear tail light cracking and breaking the tail light	Incident occurred on the 24/08/2016 and was repaired on the 25/07/16
28-Jul-16	Vehicle	185	-	Wiper washer motor not working, reservoir full but not pumping.	-	OIC Cairns to have unit taken to for repair. V 4744.
28-Jul-16	Vehicle	250	Fridge lid still sits on top of fridge	Fridge door hinges broken	Opening the fridge door with one hand all three hinges broke at once	-
28-Jul-16	Vehicle	190	None	Crack in windscreen above drivers head	Unknown	-
28-Jul-16	Vehicle	230	Made sure door shut fully with regular checks	Access door on the passenger side of vehicle flung open whilst driving.	Faulty lock??	-
28-Jul-16	Vehicle	200	Fault form has been completed	Left spotlight isn't working	-	-
28-Jul-16	Vehicle	245	-	Bottom patient care draw has fault, ? Object may be jammed behind draw, unable to clear. Door does not close.	-	-
29-Jul-16	Vehicle	250	Ensure all operational procedures are followed	Driving lights not working (front spot lights)	No	-
29-Jul-16	General Equipment	215	Officers looked around in the door and floor etc but unable to locate aerial.	Aerial missing from radio. Radio was in door of drivers side of 4403 with aerial on and then officers noticed aerial missing.	-	-
29-Jul-16	Vehicle	230	-	TEST	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
29-Jul-16	Vehicle	235	Using iPad for direction..... Safety risk Notified and lodged	Consistently freezes after approx 10 min needing to be reset	using second hand equipment	-
28-Jul-16	Vehicle	245	fault report.	Prior to commencement of shift noticed damage to rear of vehicle door.	Unknown. Incident occurred during previous shift.	Acknowledge incident occurred after handover of vehicle to oncoming officer at 1400.
29-Jul-16	Vehicle	205	OIC notified	Multiple chips and crack in windscreen	? Stones being flicked up by other vehicles	-
29-Jul-16	Stretcher	225	taken off road	front gas strutt faulty keeps sticking	wear and tear	-
29-Jul-16	Vehicle	210	Nil action taken.	Door alarm constantly active. All doors are secured and alarm still active.	Unknown	Vehicle is operational / all doors are able to be secured.
29-Jul-16	Vehicle	245	Reported to OIC via this fault report. Vehicle is still operational. Fault can be inspected at next service.	Passenger side automatic sliding door making noises when opening and also stopping half way. Intermittent fault. Possibly worn belt.	-	-
29-Jul-16	Vehicle	240	Nil able to be taken by crew	Siren ceased operating	No. Siren did return for split second during code 1 drive, but failed again straight away.	Operational for non-emergent driving only. O.C. notified.
29-Jul-16	Defibrillator	240	new corpatch was sourced which was successful	cor patch failed on a cardiac arrest, attempted to remove corpatch from plastic that sticks to sticky part of corpatch and the sticky part of the patch was stuck to the plastic and then was destroyed when the plastic finally came off.	Faulty equipment	-
30-Jul-16	Vehicle	240	-	Front left headlight out needs new bulb, parking lights still working however main bulb needs to be changed	-	-
30-Jul-16	Equipment	215	Notified	Radio found with no aerial	-	-
30-Jul-16	Equipment	225	-	Gps in unit 3913 states update is required and very slow to load when vehicle starts. This has led to some delays in response while waiting for gps to startup.	-	-
30-Jul-16	Vehicle	245	called ROC and organising to take vehicle to asap closed but alarm had stopped and when visually checked the level was above the minimum expected therefore vehicle could be in service as per roc	this vehicle checklist was completed late due to job7844988 dispatched prior to log on time. Issues were established and a plan to rectify established	low radiation fluid	-
30-Jul-16	Vehicle	235	-	Drivers Door inside cover loose and requires to be taken off to re-fixate	-	-
27-Jul-16	Defibrillator	250	Will require to do a repair	Printer door hinge broken on one side	Unknown -reported by night shift at commencement of shift 27/7	-
26-Jul-16	Defibrillator	250	Checked connections and attachment to pateint at the time by crew	Not displaying V5 and not printing or ocmpleting a summary at end of 12 Lead	-	-
30-Jul-16	Equipment	210	Radio is a GME TX342D unfollow radio.	Advised by off duty officer that UHF radio in unit 2263 / 539MDI is not able to transmitting. Officer found radio not transmitting when calling RFDS flight into Blackwater. OIC checked and radio recives transmission but not receives.	Radio needs diagnostics to determine issues. Unable to replicate issue as of yet and no need to use radio.	-

RTI Released

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
30-Jul-16	Vehicle	235	-	Antenna on roof over passenger seat broke off, unknown how. ?Occurred while on EA at officer's residence	-	-
29-Jul-16	Vehicle	245	-	2nd Bottom draw will not open normally. Have to open bottom draw and pull out draw above to open	-	-
30-Jul-16	Vehicle	225	-	Driver side headlight is not working, ?blown	-	-
30-Jul-16	Vehicle	245	-	Indicator cover broken on L side mirror- bulb still operational	Sports special at Brisbane Lions game- as crew/supporters were moving equipment they struck mirror of ambulance. QAS notified by security staff at venue	-
30-Jul-16	Vehicle	240	OC notified, tow truck arranged to pick up unit from Caltex, King st Caboolture to holding yard, then workshop on Monday	12 litres of unleaded fuel into tank by accident when refuelling	-	Engine Was not started when fault was realised
31-Jul-16	Other Equipment	235	Left in OIC tray at Ipswich station for investigation.	Pager is not activating at all. One of the pagers in 6605, unable to obtain SIM No or IMEI No. Pager stopped working during shift on the 30/7/2016. Nil pagers received since.	-	-
31-Jul-16	Vehicle	245	-	Both rear tyres needing replacement	-	-
1-Aug-16	Vehicle	225	MDT constantly shutting down and delaying response time due to nil GPS directions available for 2-3min	Leak	Nff	Nil
1-Aug-16	Vehicle	210	mechanic needs to be notified	Left back brake light not working	unknown	-
1-Aug-16	Vehicle	210	-	Engine light flashing.	engine will not start	Vehicle parked in plant room until rectified.
1-Aug-16	Vehicle	240	vehicle plugged in for excess 24 hrs - still won't start	2130 hrs 29/7/16 vehicle would not start for Officer Reported to the OC. 30/7/16 vehicle started. Has been plugged in to power in excess of 24 hrs.	(Unable to confirm GPS, lights etc due to flat battery)	-
1-Aug-16	Vehicle	200	report only	Broken headlight bracket, Top on drivers side	possible wear and tear due to rough driving conditions.	-
1-Aug-16	Vehicle	235	spoken with fleet - organised a spare vehicle at Ipswich station.	Engine light fault - contacted fleet - advised out of service - going to Ipswich to change over vehicle.	-	-
1-Aug-16	Vehicle	195	Fleet Manager contacted	AM/FM radio not working	-	-
1-Aug-16	Vehicle	195	Fault form	Rear Aircon not working. Front Driver seat damaged.	Unknown	-
1-Aug-16	Vehicle	200	-	Aircon not working front & back. Rear aircon unit reading L/P ?? low pressure?	U/K	Have spoken to and will attempt to get unit into Mackay for repair Thursday when he is back at work.
18-May-16	Vehicle	240	Various reports (written and spoken)	passenger seatbelt's clip/buckle has been broken, doesn't work, being held	????	Please rectify asap
1-Aug-16	Vehicle	240	-	The switch for the side scan lights is missing therefore the scan lights are not operational. Also, the wires within the scan light switch area is faulty and switches the scan lights on and off randomly. This has been previously reported.	-	Part has been ordered - awaiting.
1-Aug-16	Defibrillator	240	Unit taken out of service	12 lead ecg taken full of artifact, not useable. Changed to alternative Defib using same leads, ecg dots, obtained clean 12 lead.	In a stationaty vehicle, calm patient, good conection to skin noted.	-
1-Aug-16	Other Equipment	215	-	phone is stating SIM error. replacement SIM required	-	-
1-Aug-16	Vehicle	240	draw taped shut, unable to access equipment within.	Cannulation draw 3 is broken	unknown, been present since vehicle arrived brand new.	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
1-Aug-16	General Equipment	245	unknown many report forms completed by many others	Reversing camera intermittent working	unknown	-
30-Jun-16	Vehicle	215		Brake light fail. Interior lights fail. Do not switch on from drivers compartment	-	-
1-Aug-16	Vehicle	240	ROC notified, unit placed OOS	Vehicle operational but stretcher not operational. Vehicle suspension to high for stretcher to load smoothly. Loading plate bent from attempting to load stretcher whiteout lifting the front end of the stretcher.	Unknown fault, stretcher was functioning appropriately for first case.	-
2-Aug-16	Vehicle	210	Manual lifting of front end of stretcher to load.		Unknown	-
2-Aug-16	Vehicle	195	Fault form	Stretcher will not load and unload easily (601006152)	Unknown	-
1-Aug-16	Vehicle	195	Fault form and OIC notified	Stretcher will not load and unload easily	Unknown	-
2-Aug-16	Vehicle	200	None	Headlight flash not working, fog light cover broken	-	-
1-Aug-16	Vehicle	250	Booked in to Friday 5th August	Steering feels unusual at high speed >90kms/hr Airconditioning not cold	Unknown cause but has been in to for the same problems last month	-
2-Aug-16	Vehicle	190	-	Left small emergency beacon (small beacon located on left side bull bar) not working, minor cracking noted to plastic casing.	not known	Other emergency lights functioning well.
2-Aug-16	Vehicle	210	Vehicle defected.	Hinge under stretcher missing. Hinge has come up and bent. Unable to pull stretcher out of vehicle easily.	Missing screw.	-
2-Aug-16	Vehicle	200	-	Cracked windscreen, getting worse over time and further rock hitting windscreen has cause it to start creeping towards drivers view.	-	-
2-Aug-16	Vehicle	200	mechanic has been notified. Step has been cleaned and checked	Step on vehicle is not retracting back into place.	unknown	-
2-Aug-16	Vehicle	245	Oic aware	Left side access door to rear of unit solid oud keeps clicking, oxygen door will not open from outside	Nil	-
2-Aug-16	Vehicle	195	called Comms and created this form	Yellow engine light, yellow coil light illuminated when driving. Also radios stopped working.	-	-
2-Aug-16	Defibrillator	195	Unsure of whether still operational. Tried to contact SOS but unsuccessful. Took off line.	Blue light illuminated. Cf card almost full. Continued to illuminated despite turning off and on. Stays on after turning on/off.	-	-
2-Aug-16	Vehicle	240	-	Na headlight bulb out	-	Vehicle left at CAH. With keys left with Caboolture OIC
2-Aug-16	Vehicle	245	Have left unit running to charge battery's,	Found unit not on charge, with flat battery, went to plug in and noticed that all prongs where bent and not able to attach power lead. There was just enough power to start unit and it was left running.	contacted ROC to report, they stated that a call had come in from public stating they had noticed a unit travelling down the road with a power lead still attached.	-
2-Aug-16	Vehicle	200	-	Cannulation drawers cabinet bolt on bottom left corner coming undone and when handle is lifted to move cabinet, stopper does not come up easily, making movement of cabinet difficult	-	?? To be rectified by 3/8 when car taken to mechanics by morning crew
2-Aug-16	Defibrillator	240	-	Heart Rate / ECG reading abnormal numbers when attached or not attached to a patient	? Due to getting wet whilst on scene at an RTC	Taken from vehicle, pulled apart into modules and left at OIC door to see if drying out would rectify problem
2-Aug-16	Vehicle	245	Nil action taken - 3/8/16 PST attending station to replace bulb	The left head light is dim	Unsure of cause	-
2-Aug-16	Vehicle	215	Ni	Sat Nav not working	Unknown	Came up as battery low then turned off and would not restart.

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
3-Aug-16	Vehicle	210	Vehicle removed from service and fault reported to comms	suspension airbags will not inflate and unknown gas escaping from underneath the vehicle	No	-
1-Aug-16	Vehicle	245	filled out this report and verbally reported to OIC	SMALL Engine oil leak	oil escaping from the engine although it is yet to make a run for it!	Will be ok until next service
3-Aug-16	Vehicle	245	Fault form/OIC notified	Crack in windscreen	Unknown. Not sure if it has happened today	-
3-Aug-16	Vehicle	230	reported through old LASN DVR system	front AC is not working	-	To be reported to
3-Aug-16	Vehicle	235	-	GPS on the MDT is not functioning. Unable to locate satilites.	-	The MDT is still functioning but the GPS is not.
28-Jul-16	Vehicle	225	-	All doors to rear of vehicle will only open with engine running. When on scene, the vehicle has to be left running or in idle hold to be able to open the side doors or rear doors.	-	This could potentially pose a safety issue if in a situation where you need to get into the vehicle quickly and are unable to open the doors.
3-Aug-16	Vehicle	240	unable to clip back into place	Driver door - lower plastic panel is loose	Poor door design and cheap plastic clips	-
3-Aug-16	Vehicle	225	-	Check engine light stays on, coil light for vehicle start comes back on after vehicle started correctly	-	-
3-Aug-16	Vehicle	235	Discussed with SOS and completed online fault report.	??wheel bearing on front drivers side wheel. Thumping noise when driven over 40km/hr. Car does not feel dangerous or unsafe to drive.	-	-
3-Aug-16	Vehicle	240	-	Warning Light came on. (Brake Wear Visit Workshop) also Clip on rear backdoor is broken on Passenger side unable to clip door open.	-	-
4-Aug-16	Vehicle	185	-	Front right side low beam light glob blown	Blown globe	A/OIC will rectify with on station spare globes.
4-Aug-16	Vehicle	225	New LED supplied from Resource Readiness Coordinator - to be installed at regular service 24/08/2016.	One interior blown bulb in front drivers cab area and Faulty Strobe on bonnet (Left side).	-	-
4-Aug-16	Vehicle	225	Mechanic advised and new parts ordered. Vehicle to be fixed Friday should parts arrive.	Rear door unable to stay open as gas struts have failed. Near impossible to load a patient and hold door open as a single officer.	Gas struts failed	-
4-Aug-16	Vehicle	225	Booked into to fix	Reverse camera monitor bracket broken at screw that fixes bracket to monitor	No Suspect vehicle vibration or design fault	-
4-Aug-16	Vehicle	225	Booked into to fix	Reverse camera monitor bracket broken at screw that fixes bracket to monitor	No Suspect vehicle vibration or design fault	Job created X2 as already reported
4-Aug-16	Vehicle	240	vehicle has been plugged in.	vehicle will not start	vehicle started earlier this morning (0730). It will now not start.	-
3-Aug-16	Vehicle	215	Inspected by who has recommended that the bullseye be glued to prevent the crack	Bullseye in windscreen, passenger side, approx. 15cm from the top.	Road conditions	-
4-Aug-16	Vehicle	225	N/A	6 Month Service due 24/08/2016	N/A	To be booked into local agent 'A' Service due.

RTI RELEASE

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
24-Jul-16	Vehicle	205	Nil at this time OIC just returned to work and noticed damage unsure what if any reporting has been completed at this time	Fibreglass panel behind passenger side door has been damaged again by roo strike	roo strike	-
4-Aug-16	Vehicle	215	Vehicle taken to ken days for inspection	Unable to close driver side door	Broken drivers side door strap	-
4-Aug-16	Vehicle	240	-	Side step does not function, seat belt in treating seat not functioning,	-	-
4-Aug-16	Vehicle	210	-	Brakes starting to 'grind'.	-	Vehicle still braking fine - just beginning to make grinding sound on braking.
4-Aug-16	Defibrillator	240	-	Caboolture 6 corpuls not charging in vehicle. Nil wall charger available to test if corpuls or charging unit at fault. Corpuls alarming low battery when turned on. Insufficient charge for a shift.	-	Vehicle OOS
4-Aug-16	Vehicle	240	Tried different corpuls devices to see if they charge in 5354, they did not. Vehicle fault form completed.	Corpuls not charging correctly insufficient battery on device to use.	-	-
4-Aug-16	Vehicle	200	defect report, mechanic will be notified as part of this process	Engine warning light illuminated, vehicle fluids all ok... Vehicle unresponsive during acceleration, appears rev limited... Vehicle slow during Code One driving conditions	common fault with this unit. Mechanic reset the faulty engine code.	-
4-Aug-16	Vehicle	240	Turned on and off With no luck.	During normal operation loss of power and vehicle went into limp mode. Engine warning light on dash. Reported to ROC who instructed if vehicle can go over 60kph to drive it back to North Lakes.	-	-
4-Aug-16	Vehicle	185	none. It's mechanical.	Can hear a grinding noise . Front right wheel upon breaking.	unknown	Still drives ok but probably needs a look by mechanic. authority V 4770. OIC to advise when vehicle is back on road.
3-Aug-16	Vehicle	240	-	Engine warning light on. Bonnet warning lights not operating fully	-	-
5-Aug-16	Vehicle	240	ROC will be contacted and ?take vehicle to for repair or assessment.	Passenger side clearance light fitting broken.	Unknown.	-
5-Aug-16	Vehicle	240	requires workshop	Stryker stretcher - head end, extendable handle, red lever to lower stretcher, cable is snapped, handle therefore not working, only one handle to lower stretcher.	Unknown	-
4-Aug-16	Defibrillator	205	CSO consulted and advised to take Defib out of service and return unit.	Pace spikes showing on ECG trace when NIL pacemaker fitted	Corpuls fault	-
5-Aug-16	Vehicle	240	-	Battery charging cables no longer work, connector has been removed	car was driven while still plugged into car charger	Vehicle is operational at the moment but will probably require charging at some stage
5-Aug-16	Vehicle	230	-	Rear AC not working	-	Returning from Brisbane with x2 PTs and x2 escorts. Quite stuffy in the back but being not a hot day, was able to return to Nambour with Pts on board.
5-Aug-16	Vehicle	210	-	Passenger side headlight blown. Grounded for night time use.	-	Grounded for night time usage.
5-Aug-16	Vehicle	245	nil	A self tapping screw has come through the side of the ambulance, under the airway kit. Possible	Poor workmanship	Nil
6-Aug-16	Vehicle	185	unknown	Rear cupboard (with ct6/niej) door hinges broken (all 3 completely broken) held in place only by opening latch	unknown	authority number V 4789. A/OIC will get unit to this morning.

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
6-Aug-16	Vehicle	250	SOS advised 6/8/16. Email to OIC.	Large nail stuck in back tyre. ? Safe to drive at speed.	-	Trye repaired and now back on vehcile (A/OIC)
11-Aug-16	Vehicle	225	Booked in for routine service	Due for service by date booked in for 60,000 service	N/a	-
6-Aug-16	Vehicle	210	Discussion with resource readiness manager. Organise vehicle for diagnostics and repair this coming Monday.	Airbag system is very slow to respond. Takes approx 2 minutes to raise vehicle to full height.	Recently fitted airbag system. Diagnostic conducted nil issues found.	-
6-Aug-16	Vehicle	240	problem solved unable to locate fuses	emergency beacons and spot lights not working	-	-
5-Aug-16	Stretcher	240	-	Head end, extendable handle, red lever to lower stretcher, cable broken	-	Fault form completed - nil incident.
6-Aug-16	Vehicle	225	take offline, OCS and SOS aware	No indicators or interior fan? Possible fuse issue	happened while transporting to hospital?	RACQ requested to attend but SOS declined calling due to pending IHT.
6-Aug-16	Vehicle	240	Used vehicle in low power mode and forced gear change manually to complete assigned jobs. At meal break, parked vehicle, turned engine off, restarted engine with accelerator pressed to floor, revved engine at high RPM for 5 to 10 seconds.	Vehicle in low power mode - will not drop down gears when accelerator pressed to floor and low power output on engine. Very slow to accelerate and loses speed uphill	Emission control issues/service	Full power returned to engine, and remained for remainder of shift. Possibly a temporary measure as core fault has not been addressed.
6-Aug-16	Vehicle	185	Tagged vehicle out, bonnet is up	Left head light out 7276	-	OIC replaced bulb 8/8/2016.
7-Aug-16	Vehicle	215	multiple fault recordings in vehicle checklist	Patient care seat belt doesn't work	-	-
7-Aug-16	Vehicle	240	nil	siren not working	-	-
7-Aug-16	Vehicle	210	Nil	Screeching noise made by front brakes got light and heavy braking.	Possible need to replace brake pads soon.	-
7-Aug-16	Other Equipment	240	n/a requires replacement	Recliner chair in lounge room is broken and unusable	unknown has been broken for several days	CHAIR BROKEN AND DISPOSED OF.
7-Aug-16	Vehicle	185	off road	Clicking noise from around radiator fan area. Bonnet lifted, fault form completed, sos notified	unknown authority number V 4790.	-
7-Aug-16	Vehicle	200	Initially noted that step did not extend, tried pressing the manual extension button which did not work, then inspected damage of step under car and fault form entered.	Damage to motorised step to side door, step will not extend.	Step was working this morning but upon returning from off road RTC step will no longer extend.	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
7-Aug-16	Vehicle	235	Car check list not complete due to problems with car check list saying 6667 is off rd...everything seem fine yesterday and today while driving other then scratch noted today	Large scratch found down side of 6667 ? Driving thought ruff driveway on the 060816...	Driveway had been ruff into property I had been driving but did not not hitting anything in driveway ..? May have happen prior to driving it on the 060816 and did note while doing vehicle check till today 070816...	-
7-Aug-16	Vehicle	195	Visual inspection is sound.	Driver's side spot light is faulty and not working.	Unsure.	Unable to locate obvious cause of fault.
7-Aug-16	Vehicle	245	Vehicle taken OOS	?blown radiator	Unknown	Driving back from a job approx 100m from station the radiator light came on. Pulled into plant room to find water dumped all over floor
4-Aug-16	Vehicle	235	Report only.	No mobile phone, and only one pager for vehicle. One batterie in torch passengers side seems not to be charging, maybe batterie is faulty. No folders to secure documents such as mental health and life extinct forms.	Not known where equipment is. This is a Sector spare, and items were missing when collected from Ipswich station. battery terminals loose. After tightening vehicle still would not start.	Upon collection the vehicle was very dirty inside, and had to be cleaned by Rosewood staff before it could be used operationally. Daily vehicle reports not done.
8-Aug-16	Vehicle	225	-	Vehicle would not start on call, flat battery. RACQ called to start vehicle.	Unknown, fault identified during transport from RBH to RDH	RACQ jump started vehicle and vehicle returned to station.
7-Aug-16	Vehicle	240	OIC notified, Vault form completed	240V outlet continues to trip breaker.	Unknown, fault identified during transport from RBH to RDH	-
8-Aug-16	Vehicle	215	-	Oxygen tubing to D size cylinder rubbed through on access door metal support bar. Fault previously submitted >12 mths for same issue.	Rubbing on steel worn through see pictures	Has caused a hole
8-Aug-16	Defibrillator	240	attempted to see if would charge in different charging bases however nil	Defib not charging	-	Operational however taken off road due to battery life
8-Aug-16	Vehicle	215	This form.	Two large cracks in windscreen, noted during vehicle check.	Unknown	Vehicle is operational at present, but could become non- operational in near future due to size of cracks.
8-Aug-16	Vehicle	215	This form.	Two large cracks in windscreen, noted during vehicle check.	Unknown	Vehicle is operational at present, but could become non- operational in near future due to size of cracks.
8-Aug-16	General Equipment	215	Charged unit, pulled charger out and replaced.	GPS turning on then screen going blank.	-	-
8-Aug-16	Vehicle	240	Took vehicle to Workshop however closed due to public holiday. Vehicle turned on and off, plugged in, all doors closed,	Continuous Beeping when vehicle not running, red flashing light on modular battery board, MDT turning off after vehicle stopped running. Vehicle was plugged in and charging overnight, MDT was turned off until vehicle started.	Unknown - ? Battery fault	-
31-Mar-16	Stretcher	215	-	Service overdue	-	In rear shed awaiting service
20-Jan-16	Stair Chair	215	-	Service overdue	-	In shipping container at rear of station awaiting service
13-May-16	Stair Chair	215	-	Service overdue	-	In shipping container at rear of station awaiting service
6-Aug-16	General Equipment	225	Tray removed from vehicle. Defibrillator not damaged and placed inside of vehicle on defibrillator cradle.	Defibrillator tray damaged	Door left open with defibrillator tray extended out. Officer didn't notice and drove out of plant room which then resulted in tray coming into contact with edge of roller door track. Nil damage to vehicle or defibrillator.	Defibrillator cradle which sits inside of tray not damaged, therefore require replacement tray including pull out component. SHE report incident number 036222.
7-Aug-16	Vehicle	225	Filled out fault report	Broken glass on off side fog light	Rock from road	-
19-Mar-16	Stair Chair	215	-	Past service due date	-	Awaiting service

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
29-Aug-15	Stair Chair	215	-	Past service due date	-	-
8-Aug-16	Vehicle	225	All fluids and fuses checked to nil effect	The vehicle ABS, traction control are orange and brake light red. Car not operational.	-	-
19-Mar-16	Stretcher	215	-	Past Service due	-	Located in 4542 which is at workshops. Contact OIC Maryborough prior to service to arrange for collection and swap out/service
3-Apr-15	Stair Chair	215	-	Past Service due	-	Located in 4542 at vehicle service centre. Contact OIC Maryboroguh to arrange collection/swap out/service
8-Aug-16	Vehicle	240	-	Air conditioning not working	-	-
8-Aug-16	Vehicle	195	logging this fault form	Non-functioning R front indicator	-	-
8-Aug-16	Vehicle	230	Cleaned senses contacted cds	Rear doors not shutting properly door open senses on and emergency lighting on when lights are on	Senses my need adjusting cleaned with alcowipes still showing door open	Fault noted this afternoon only unit functional today
8-Aug-16	Vehicle	195	-	Yellow bracket for cannulation draws broken	unknown	-
9-Aug-16	Other Equipment	215	Replaced battery	Only receives transmissions intermittently.	Unknown	-
9-Aug-16	Vehicle	245	-	Rear side oxygen door won't lock is held closed by strap, side rear door won't open unless you use a key, rear door sticking, airbag suspension lowers occasionally.	Oic aware of issues	-
7-Aug-16	Vehicle	250	-	Stone chip to front windscreen	Passing vehicle driving on highway.	-
9-Aug-16	Vehicle	210	-	Side step not working reversing camera not working gps not working	-	-
9-Aug-16	Vehicle	240	OIC and have been made aware	Siren on vehicle keeps turning off and battery light on dash comes on on code one drives, rear aircon cuts out also.	This has been an ongoing fault, the dayshift on Monday 8/8 noticed that the battery light was showing on the dash and the rear air con was turning off.	The vehicle is operational but have to be careful when doing a code one drive.
9-Aug-16	Vehicle	185	-	Engine light on and centre console in back between stretchers, the bottom draw won't stay closed.	-	authority V 4793 (engine light) V4794 (centre console)
9-Aug-16	Vehicle	190	Replacement panel and network adapter being sent by	Issue with main emergency control panel freezing in front cabin. Unable to switch off warning devices / scan lights etc after a period of travel, needing to switch off "Main" switch to disengage warning devices and lights	Unknown	Build number
9-Aug-16	Vehicle	200	-	Button on kit access door will not release door and manual release is required to be used	-	-
9-Aug-16	Vehicle	210	vehicle taken off road and booked into the mechanic to readjust suspension, OIC notified and on call mechanic	Suspension dropping too low and causing the stretcher wheels to not have enough clearance to fully lock in	unknown how it has happened	-
9-Aug-16	Vehicle	245	-	Rear lcd screen will not acknowledge when you try and activate either lights, inverter, emergency lights	-	-
9-Aug-16	Vehicle	250	Notified OIC	Damage to left side wheel arch area	Discovered whilst performing vehicle check	Unknown cause, unknown if insurance form completed. This is notifying that damage was discovered by us NOT CAUSED by us.
9-Aug-16	Vehicle	240	nil	Front right headlight u/s	nil	Vehicle has not been removed from service will need to go to workshops during business hours
9-Aug-16	Vehicle	240	turned car off and on again.	Commercial Radio buttons don't work except for volume.	-	-
9-Aug-16	Vehicle	195	SOS notified, fault form completed, vehicle 'tagged out'	Driving to code 1 case approx 2005 when I noted the red Parking Brake "words" and three yellow brake warning lights came on. Comms radioed and informed that unit would continue to case (with care)	-	-
9-Aug-16	Vehicle	185	-	Engine surging, making funny noise, lack of power on acceleration	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
9-Aug-16	General Equipment	195	-	Handheld radios signal not going through crossband radio in vehicle, Opcen unable to hear crew calling on handheld radios. Seems that the handheld signal is being received at the crossband radio in vehicle but signal not being sent onwards.	?	-
10-Aug-16	Defibrillator	250	Replaced cable with new one. Operational reported.	Pulse oxy lead not working	-	6568
10-Aug-16	Vehicle	185	-	12volt charging plug not working. GPS not working as low charge.	Unknown	Nil. authority V 4803. OIC to arrange vehicle to go to
10-Aug-16	Vehicle	215	Reported to mechanic	Clutch slipping	-	Clutch shutters on take off
10-Aug-16	Vehicle	215	Nil	Windscreen Crack drivers side does not obstruct view	Unknown	-
10-Aug-16	Vehicle	215	Check with , will require replacement	Damaged windscreen	Unknown	-
10-Aug-16	Vehicle	215	Check with , will require replacement	Damaged windscreen	Unknown	-
9-Aug-16	Defibrillator	195	Still operational	CF memory card almost full	CF Memory card almost full	Reported to Coordinator and reported to LASN Resource Readiness
10-Aug-16	Stretcher	230	Stretcher taken to investigation for	Pt slid off stretcher. Unsure if red lever deployed	? Operator error	She completed
10-Aug-16	Vehicle	240	fault form.	Rear right door latch Brocken and not catching.	Unknown	-
10-Aug-16	Vehicle	235	Dispatchers have been advised.	Vehicle not tracking properly on CAD. Will generally be displayed at another location to where it physically is. EG at PAH when it is at Springfield or showing on the north side of Brisbane	-	-
9-Aug-16	Vehicle	225	Head light bulb replaced	N/S headlight blown	unknown	-
10-Aug-16	Stretcher	210	The incident was reported to SOS, and to the mechanic. Stretcher has been replaced	officer lowered stretcher to the second lowest height setting and tested it was locked in by pushing down on it. When PT sat on the stretcher and raised her legs to lye semi-recumbent, officer standing at foot end. The head end of the stretcher collapsed	Unknown	Nil injuries incurred in the incident
9-Aug-16	Vehicle	240	Notified OIC	Hand rail behind passenger seat opposite driver side is broken.	Patient departing vehicle holding on to hand rail.Rail pulled out of wall.	Handrail re-welded and fixed by
10-Aug-16	Defibrillator	240	fault form. Monitor taken OOS	Printer faulty. Only bottom half of page printed with ink.	accidentally dropped on scene	-
10-Aug-16	Vehicle	235	Fault form.	EMERG start activation required when starting vehicle.	?Radio does not power down. ?needs new battery.	Vehicle starts after being on charge at station without the use of the emergency start switch . It is when car is turned on out on case or after parking at hospital that the switch is required.
10-Aug-16	Vehicle	245	-	Intermittent power supply (DC) in back of ambulance during transfer. All indicators show power but no power delivered.	?	STRU for normal barractric retrieval is ok.
10-Aug-16	Vehicle	225	-	Second drawer slider mount rivets broken and drawer is loose.	-	-
11-Aug-16	General Equipment	200	handle won't stay in place, but Can still pull metal bar up to release monitor, is more difficult. Will put some material tape around it to try help.	Red handle of corpuls cradle inside of car has come off	wear and tear, handle was difficult to release and excess pulling?	-
11-Aug-16	Vehicle	240	Vehicle out of service. OIC notified.	Corpuls charging bracket not working in 172. Tried corpuls in 173 and its was charging.	Unknown	-
11-Aug-16	Vehicle	225	reported to OIC	Rear flashing emergency light lower both right and left u/s	?	-
11-Aug-16	Vehicle	210	SOS notified	Charge cable bared	cable being slammed in door	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
11-Aug-16	Defibrillator	210	A technical support line was contacted as per SOS instruction and waiting for a call back from technician	end tidal CO2 not working during pre shift check	-	-
11-Aug-16	Vehicle	210	Nil available	Two issues: #1= When siren is on, incoming radio transmissions are completely unreadable or silent, only when siren is then switched off the radio transmission is audible again. #2= channel 23 this AM completely unable to hear Comms.	-	Radio code 1, not operational
11-Aug-16	Vehicle	225	OIC aware	Approaching scheduled service, aux battery may need checking	-	-
9-Aug-16	Vehicle	220	noted on vehicle check & fault form completed	Rear compartment access door not locking with central locking. Able to secure with key manually.	-	Most staff on station aware
11-Aug-16	Vehicle	215	nil	reversing camera intermittent feed.	unknown	-
11-Aug-16	Vehicle	195	-	Side patient care door opening during transport	-	-
11-Aug-16	Stretcher	215	-	Broken / cracked red leg lift assist lever - see photo	-	-
10-Aug-16	Vehicle	210	-	Brake squeal considerably at low speed braking.	? stone.	-
11-Aug-16	Vehicle	200	Advised duty mechanic	Passenger rear tyre tread wear was identified as low on tyre inspection at Approx 1mm till needs legal replacing	- advised	ok to drive but should be replaced ASAP
11-Aug-16	Vehicle	235	None	High temp light keeps flashing and beeping intermittently... Spoke to mechanic coolant still full... MDT also not working	Unknown	Mechanic happy for us to continue on case however due to MDT problems taken out of service.. Job logged with COMMS attempted to turn off and turn back on however no jobs went to MDT since 1200
11-Aug-16	Vehicle	200	Corpuls charged by wall socket	Corpuls vehicle charger not working	Unknown	Nil
11-Aug-16	Vehicle	185	Fault form	During shift noticed right side head-light is not working.	Bad bulb	Noticed near end of shift. Wanted fault to be sorted before next afternoon shift. OIC to replace bulb.
12-Aug-16	Vehicle	245	Nil, bonnet of vehicle raised to signal out of service	Mdt not working, no oxygen kit in vehicle, back right tyre low pressure	Vehicle was bored by and returned in this state	No car phone found, nil carry strap on the corpuls
11-Aug-16	Vehicle	245	Ensured visablilty is still achievable through mirror & is road worthy.	Glass inside passenger side-mirror is cracked	Mirror fixture was pushed inwards during a code one drive where it clipped the back content of a stationary ute, when fixture was returned to normal position glass has cracked	-
12-Aug-16	Other Equipment	210	observed to see if something is causing the button to stick, nothing found	Button to communicate through radio is sticking, not releasing on some occasions. Need replacement of hand held speaker piece only.	-	-
12-Aug-16	Vehicle	240	Secured with strap	Drawer has come off its track and a sheared bolt found.	Unknown	-
12-Aug-16	Vehicle	240	-	side step not working. 12v plug in centre console not working	- not sure if you ha	ve these detials the unit is booked for service next week.
12-Aug-16	Vehicle	215	Taken to Maryborough for code reset. Drove 100m and problem reoccurred. Left at and 504 obtained as on loan vehicle.	SRS WARNING LIGHT ILLUMINATED	-	-
12-Aug-16	General Equipment	195	Battery swapped from other & works well	Torch only working intermittently	-	New battery required

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
10-Aug-16	Vehicle	200	All doors checked and re-closed.	faulty door sensors, door open alarm constantly goes off when driving over minor bumps or corners. All doors confirmed closed by crew however issue continues. Note - has been a recurrent problem but now much worse, alarms approx every 3 sec.	-	-
12-Aug-16	Vehicle	225	Restock and report to SOS	Vehicle was missing a significant amount of equipment including phone, fuel card and stretcher base out of date and Corpuls flat and not able to charge	neglect	-
12-Aug-16	Vehicle	245	-	(L) head light out	-	-
12-Aug-16	Vehicle	225	Comms centre advised	Car battery not hold charge	-	Radio want work, nil cabin lights
12-Aug-16	Vehicle	210	-	yellow door hinge, right side at back door of vechile has snapped off	Officer pushing against door.	-
13-Aug-16	Vehicle	195	Plugged in to recharge. Not rostered to be used for 26 hours. Battery appears to be charging.	Battery completely flat to the point it wouldn't lock/unlock with the key fob.	Not plugged in correctly. ? Radios left on too.	-
13-Aug-16	Vehicle	235	Main power turned off when vehicle not being operated to prevent drain of battery; fault form submitted	Middle bulb of R) headlight always on - only turns off when main power switched off	Unknown	-
13-Aug-16	Vehicle	210	-	Front passenger side park light not working.	-	-
13-Aug-16	Defibrillator	195	-	The SpO2 pulse oximetry is not working sometimes. It keep saying oximetry is defective. But it works again at the end of the shift. We did check the connection and it was not the connection issues.	-	-
13-Aug-16	Defibrillator	205	I have removed the defib and replaced it several times; I have ensured that the charging bracket is plugged in, and that the rear module has power.	The Defib is not charging in the bracket in the car. I have checked that it is plugged in, and that the rear module has power, but the charge light on the monitor is not lit. The monitor appears to sit in the bracket correctly.	-	No action required, main power was not on.
12-Aug-16	Stretcher	240	none	Stretcher buttons become jammed and difficult to press whilst trying to deploy stretcher from car.	not known	She report not require as no patient involved as advised by the ROC.
13-Aug-16	General Equipment	195	Maintained full tank on visual	Fuel gauge on generator flicks between zero & 1/4; however tank full	-	-
13-Aug-16	Vehicle	215	Fault form	Petrol tank on dashboard states half a tank of fuel - attempted to refuel and either the petrol sensor is broken or the dashboard gauge broken - did not change after refuel and only able to put approx 6L of Diesel in it.	-	Sub tank still full.
12-Aug-16	Vehicle	225	-	Already reported 16 th July emergency over ride button needed to start engine . Charging socket not registering disconnected	-	-
12-Aug-16	General Equipment	225	have left both regulators switched off OC notified. Vehicle	D size oxygen system has a slow leak	unknown	-
13-Aug-16	Vehicle	245	OOS and returned to South Brisbane to swap cars. OIC notified mechanic.	Strong sulfur odour throughout cabin. OC notified and states caused by battery. Placed OOS.	Auxillery/main battery?	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
13-Aug-16	Vehicle	245	still works just no cover over the mechanics of the button	Button from passenger side electric window	Unknown - went to use it today and it was not there	-
13-Aug-16	Defibrillator	235	Taken out of service	Ecg fault	Unknown	Lowwood had defibrillator do the same before failing later on a job
13-Aug-16	Vehicle	245	nil.	Right headlight became faulty during shift. Rear right tyre reading low PSI - does not appear flat nor is there any noticeable handling difference.	Unknown.	-
14-Aug-16	Vehicle	250	needs charging point replaced	Vehicle torch Charging point missing - not operational	not found in veh	-
14-Aug-16	Vehicle	240	Placed on charger however was on charge prior to being checked.	Vehicle not turning on. Battery alarm on and flashing red.	-	-
14-Aug-16	Vehicle	210	vehicle has been defected, OCS and SOS have been notified	no engine oil	-	-
14-Aug-16	Vehicle	235	-	MDT not working in vehicle	-	-
12-Aug-16	Vehicle	235	Went through the trouble shooting process.	Stretcher not unloading . Loading rail not locking when Str all the way out. Str not locking down when placed in vehicle	?	-
14-Aug-16	Vehicle	240	-	Park break is not working if the car is on much of a slope	-	-
14-Aug-16	Vehicle	225	SOS and COMMS notified. Out of service tag on steering wheel.	Suction in rear compartment not working. Step working intermittently. L rear door hinge will not stay open, strut does not lock into place allowing door to swing close. Door can be opened all the way back to avoid safety issues	-	Vehicle located at Fairview station.
14-Aug-16	Vehicle	195	-	Monitor cupboard hinge broken	Leaning on cupboard	-
14-Aug-16	Vehicle	250	-	-	-	-
14-Aug-16	Vehicle	230	Vehicle taken out of service for day as is not open on Sunday's. Notified CDS. note left for crew to refill Monday at start of shift.	No engine oil, oil mark well below minimum mark. Vehicle due for service in 2 days.	-	Low level of engine oil
14-Aug-16	Vehicle	240	-	Front r headlight US	-	-
14-Aug-16	Vehicle	245	-	Main battery does not hold charge. Day crew required to, twice use emergency start on an incident. Car was on charge for approx eleven hours prior to use.	-	-
14-Aug-16	Vehicle	210	-	-	-	Reversing incident - post hit in station
14-Aug-16	Defibrillator	210	Officer (Senior Operations Supervisor) was able to put screw back; however, charging terminal on docking station still not sitting correctly and not aligning with charging terminals on the defibrillator.	Charging dock in Unit 2216 not Charging Corpuls.	Charging section on docking station loose as centre screw had come out. As a result charging terminals not aligning with Corpuls when defibrillator placed in dock.	12V socket tested and is working fine.

RTI REQUEST

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
14-Aug-16	Vehicle	235	nil	Sirens are faulty. Volume decreases for periods of time for an unknown reason then returns to normal and will fluctuate between being loud and being soft.	Unknown	-
14-Aug-16	Vehicle	240	-	Loose torch charger poses trip hazard.	-	-
14-Aug-16	Vehicle	240	-	Bolt to R) rear cargo barrier has fallen out (barrier still functional).	-	-
14-Aug-16	Vehicle	240	-	Park brake insufficient	-	-
14-Aug-16	Vehicle	240	-	Park brake insufficient	-	-
15-Aug-16	Vehicle	240	OIC advised, vehicle now in a non operational status with applicable tag applied to keys	Drivers side rear sliding door to oxygen bay will not open, appears to be slightly misaligned on door track. No obvious damage noted.	-	-
14-Aug-16	Vehicle	240	VOR	Unable to move through the gears and into reverse this problem is intermittent	-	This does not happen everytime however it has been increasing each day the number of times this occurs
15-Aug-16	Defibrillator	195	-	SpO2 cable split, wires exposed	-	-
14-Aug-16	Vehicle	205	Nothing.	The Master switch panel at the front of the vehicle switches itself off, even when on mains power; back mains panel seems sometimes independent from front. Drive lights will not switch on and the rear step had to be disabled because it was going haywire.	Electrical?	-
15-Aug-16	Vehicle	195	Vehicle off road, OIC notified	Engine light on	-	-
15-Aug-16	Vehicle	240	nil	12v plug at front of vehicle broken	-	Plug has been pushed inside panel and cannot be reached without unscrewing side access panel
15-Aug-16	Defibrillator	245	Tried pulling apart and put back again with no change. Checked leads.	Turns itself on, states has come apart. Is not charging. When turned off noted not charging. Removed from cradle and replaced. Cor pulse then turned itself back on. Also turned itself on whilst we were driving back from hospital..	Battery went down to 42 min, Then up to 278 min	Removed from service
15-Aug-16	Defibrillator	245	Tried pulling apart and put back again with no change. Checked leads.	Turns itself on, states has come apart. Is not charging. When turned off noted not charging. Removed from cradle and replaced. Cor pulse then turned itself back on. Also turned itself on whilst we were driving back from hospital..	Battery went down to 42 min, Then up to 278 min	Removed from service
15-Aug-16	Defibrillator	245	Tried pulling apart and put back again with no change. Checked leads.	Turns itself on, states has come apart. Is not charging. When turned off noted not charging. Removed from cradle and replaced. Cor pulse then turned itself back on. Also turned itself on whilst we were driving back from hospital..	Battery went down to 42 min, Then up to 278 min	Removed from service
15-Aug-16	General Equipment	195	Turned GPS off and on did not resolve	GPS keypad not aligning, press one letter another randomly appears. Back arrows or rubber will not remove mistake.	Unknown	Vehicle is still operational, using ipad for maps.
15-Aug-16	Defibrillator	195	SOS contacted who brought out a new set of leads	Right arm Lead cut off while attempting to cut clothing from unconscious pt (lead under pt's shirt not known to officer cutting pt's shirt).	scissors	-
15-Aug-16	Vehicle	215	Reported	Rear door isn't locking with vehicle is locked. Taken to for inspection and it seems the rear door locking mechanism motor needs replacement	Unknown	-
15-Aug-16	Vehicle	235	mechanic notified	seatbelt in the rear attendants seat has seized and will not retract or extend	-	-
15-Aug-16	General Equipment	240	n/A electrical wiring issue	Car Toughbook Charger from 5472 has been broken during day shift	Rear compartment charging port being used to charge toughbook, cord became tangled when removing stretcher resulting in charger being broken	Filled in on behalf of (Day shift)
15-Aug-16	Defibrillator	195	SOS notified cable replaced.	SPO2 sensor main cable to monitor defective. Not sensing Corpuls error states defective cable SPO2. Disconnected finger cable and attached to another Corpuls Spo2 functioning detecting Spo2.	No	-
15-Aug-16	Defibrillator	250	-	Where 6 lead plugs into machine, the plug has been pulled out of socket, but part of the plug has been left in the socket and we cannot remove it.	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
15-Aug-16	Vehicle	235	nil, unable to fix	Power loader for power stretcher not working.	there seems to be no power getting to the loader	Unit is at Ipswich station and crew swapped into sector spare 6618
15-Aug-16	Defibrillator	225	Attempted to replug it in. Unsuccessful	Battery not charging. Other vehicles defib charging in same vehicle	Unknown	-
15-Aug-16	Vehicle	240	-	Seat adjuster on drivers seat completely broken	-	Sort of still operational but unable to adjust seat for safe driving
15-Aug-16	Vehicle	195	none - we took out of service after reading the handbook. Possible belt tension/airbags error code	SRS - light on the dash came on and stayed lit. Also warning message flashed on the dash as well.	unknown	-
15-Aug-16	Defibrillator	195	Machine has been turned on and off again, cable connection has been unplugged and plugged back in. No change noticed.	SPO2 probe is only working intermittently. Machine alarms and probe won't read heart rate or O2.	-	Machine in only operational when probe is working correctly.
15-Aug-16	Vehicle	240	Ring Corpuls for replacement red handle	Corpuls Bracket - Red handle is broken. Still able to be used.	-	-
16-Aug-16	Vehicle	200	Removed module battery terminals and replace. Activate lights multiple times as per directions of Mackay LASN mechanic. All other power units in module operational.	Wall suction in vehicle not working. Previously reported and repaired.	-	Able to access portable suction easily if required
16-Aug-16	Vehicle	240	IS CURRENTLY ON CHARGE & SHOULD CHARGE UP & START. NEEDS FURTHER INVESTIGATION TO PREVENT RECURRENCES.	BATTERY GOES FLAT WHEN THE MAIN MDT SWITCH IS LEFT ON. IS FLAT AGAIN TODAY.	-	-
16-Aug-16	Vehicle	195	-	Crack in windscreen. Not initially seen during preshift check	Unknown	-
16-Aug-16	Defibrillator	215	-	EtcO2 not working	-	-
16-Aug-16	Vehicle	245	-	Oscillating/humming noise audible while driving ? From front wheels or engine, clunking noise heard following engine stop	-	-
16-Aug-16	Vehicle	185	Vehicle has been placed off road.	Engine light flashing on dash board, with loss of power. Vehicle has been placed off road.	Unknown, vehicle was working earlier in the night.	-
17-Aug-16	Vehicle	240	Attempted to reboot the MDT with the master switch. No change in screen.	MDT fault - displaying screen advising that a removable device was attached	A removable device was plugged into the MDT system	Vehicle scheduled for service. MDT Repair will be booked when vehicle returns.
17-Aug-16	Vehicle	240	Attempted to release step manually but unable to access	Side step not working properly, step is stuck out and won't retract.	Unknown, Nightshift said that it seemed fine during night.	DUPLICATE
17-Aug-16	Vehicle	215	This form	Internal rear lights not working	Unknown	On Call vehicle following rolling fatigues. Plugged in to power for the day and no issue found
13-Aug-16	Vehicle	225	-	Door open warning light and alarm going off all the time	-	-
17-Aug-16	Vehicle	180	New windscreen ordered	Crack in Windscreen from stonechip	Rock from a passing vehicle	To be replaced by top end motors

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
17-Aug-16	Vehicle	210	This report	Suction container missing	Nil	-
			I have removed and refitted connecting cables with no success. Problems comes and goes. OIC contacted OSU and repair done on			
17-Aug-16	Vehicle	240	21st sept 16	MDT goes blank. Intermittently screen returns.	-	MDT worked ok at start of shift, failed enrollee to job.
17-Aug-16	Vehicle	225	-	Service due 160000 16/10/2016	Forgotten	-
17-Aug-16	Vehicle	240	none	Accident damage paint scratching on offside	hooded gate entry key pad at Roma Street Station.	Accident claim form to be completed.
17-Aug-16	Vehicle	230	Referred to	Locking mechanism in back of car faulty. Locks with key but doors can still be opened by toggle on side door	-	-
3-Aug-16	General Equipment	200	storage discussed with officer and review of storage	Green cap dislodged off drug. Drug in plastic wrap	unknown but vial squeezed into elastic hoop probably contributed to green cap off	entered on ADAPT. Vial sent to forensic q Health
17-Aug-16	Vehicle	250	Locking has been intermittently working/not working over the past month. It is unreliable and is required to be locked at all times due to drug compliance.	Central locking intermittently working. Unable to secure vehicle at times. Also LED light to the front Left (under headlight) are not working.	Unknown	Booked into for Monday 22nd August 0820.
17-Aug-16	Vehicle	240	Power resets, Mdt head cable removed and re-inserted, vehicle mains switch reboot	Mdt fails to boot...cycles through startup screen then blank	-	-
17-Aug-16	Stretcher	240	exchange stretcher on plant room floor	Cot leg support, in bent knee or leg elevated position collapses under the weight of patient's leg. Pin disengaged from slot on right hand side.	Pin arms not wide enough to maintain pressure against side of bracket to keep pin in slot under weight of patient's legs.	-
17-Aug-16	Vehicle	245	Reported to OIC	Airconditioning not working in 539	-	But hot in the back with patients
17-Aug-16	Vehicle	245	Nil.	Started vehicle and found the engine fault light on. This is the light that, according to the handbook, indicates a fuel line fault resulting in low engine pressure	-	-
17-Aug-16	Other Equipment	200	Reported to OCS and Duty Officer. Advised by OCS issue has been reported to OSU.	Pager still turns on but not receiving messages.	Unknown.	Submitting fault report upon advice from OCS.
18-Aug-16	Vehicle	225	-	10 000kms out of service. 192,000km service tag	-	-
17-Aug-16	Vehicle	230	-	Orange engine light came on whilst driving	-	-
18-Aug-16	Vehicle	245	Fault form raised	No MDT	-	-
16-Aug-16	Vehicle	200	Nil - fault report submitted	Rear modular not holding power when not running or plugged in. Lose occurring within several hours	-	-
18-Aug-16	Vehicle	225	speaker moved to a sensible central position will be notified.	Radio speaker too close to bulk head, almost touches firewall, has to be turned up excessively to be heard.	Bad placement of radio speaker	This fault is on almost all operational units in Toowoomba, this is the worst example.
18-Aug-16	Vehicle	240	tissue box has been taped to wall	Spare oxygen cylinder base - falling apart.	wear and tear	-
18-Aug-16	Vehicle	235	tissue box has been taped to wall	Wall mounted tissue holder is broken	unjnaw, has been broken for a long time	Tissue box holder is broken, has been for quite sometime, requires replacement for safety and hygiene reasons.

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
17-Aug-16	Vehicle Other	245	This report	Rear airway seats seat belts not functioning as designed	Probably Spring failure in the retractor	-
17-Aug-16	Equipment	210	Fault form	Was on EA with 2463 pager and during the night It received 2248 page Right hand seat belt not retracting every time you put it on or take it off . Sometimes it work correctly other times it want retract	Unknown	This has happened a while back
17-Aug-16	Vehicle	210	None		Unknown	-
18-Aug-16	Stretcher	195	SOS and COMMS informed. Fault form and SHE completed. Stretcher tagged and taken out of vehicle.	Officer was slowly unloading (R) side stretcher (no patient). Front legs failed to deploy and front end dropped to ground.	-	SHE COMPLETED
18-Aug-16	Stretcher	195	SOS and COMMS informed. Fault form and SHE completed. Stretcher tagged and taken out of vehicle.	Officer was slowly unloading (R) side stretcher (no patient). Front legs failed to deploy and front end dropped to ground.	-	-
17-Aug-16	Vehicle	240	Fault form completed and sent to OIC	240V outlets do not work	Unknown. Fault was uncovered throughout shift - Unable to complete fault form as operational Ipad ran out of battery (which is what uncovered the fault)	Will cause issues for critical IHT transfers requiring ventilators or infusion pumps, particularly if retrieval team is unaware of power issues prior to departure. Odometer reading unavailable at the time of creating fault form
18-Aug-16	Vehicle	250	-	Colours on MDT have become extremely bright and unable to be changed. MDT is unreadable.	-	A similar problem happened earlier this week and the MDT screen was replaced.
18-Aug-16	Vehicle	240	OIC advised today - fault form completed when operationally able to	Multiple - 1. Fridge not working - works for a while then error code "E0" appears on fridge screen 2. Front passenger side driving light out 3. Rear control (next to sliding door) faulty and cracked / loose screws	-	Fridge - U/S Light - U/S Rear control - working however requiring to have screws tightened by officers so does fall off wall and smash when closing door
19-Aug-16	Vehicle	185	Nil	L low beam headlight out	-	Bulb ceased working during shift
19-Aug-16	Vehicle	185	Vehicle taken for repair this am.	Bottom Draw of cannulation cabinet faulty. Draw wont stay closed due to catch being broken.	Possible cause to much weight in draw or draw has been closed hard and plastic clip has been damaged.	Draw can be held closed if needs be but slides back & forth if left unsecured. authority V 4831.
18-Aug-16	Defibrillator	250	Replaced cable with new one. Operational.	Pulse oximetry sensor wire damaged at connection near sensor. Insulation broken and wires exposed.	-	-
15-Aug-16	Vehicle	215	reported.	Rear door not locking, vehicle taken to Monday and at this stage they are thinking that the door motor mechanism has failed.	unknown	Spoke to and and vehicle operational with golf officers only as no drugs carried. Called 19/08 for update and no fault form received by them. Resubmitted on the desktop as original form submitted via ipad.
19-Aug-16	Vehicle	210	Nil	Frayed vehicle radio (front) cord	-	-
19-Aug-16	Defibrillator	210	We have troubleshooted the machine, checked the plug in port, checked all the connectors to each dot by disconnecting and reconnecting, dots were changed for new ones on all leads, machine was also restarted, with nil resolving occurring.	Corpus 3 stopped getting a monitor reading of a 4 Lead and 12 Lead ECG during a cardiac chest pain job, whilst trying to monitor patient. Initial 4 lead and 12 lead were gained (9:05), by 9:15 all monitoring was lost.	Unknown	Machine has been removed from operational use

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
19-Aug-16	Vehicle	185	tape	Front ambulance sticker peeling off	wear and tear	If the sticker is becoming a hindrance, peel it off. I will order a new one.
19-Aug-16	Vehicle	230	-	Rear AC not working	-	Vehicle to be used only during the night. Too stuffy in the back without AC.
19-Aug-16	Vehicle	200	Comms and SOS notified fault form completed.	Car has entered a limp mode and will not accelerate beyond 50km/h.	-	Car was dispatched on a IHT from Proserpine to Mackay at approximately 1400 but would not operate normally not accelerating beyond 50km/h.
19-Aug-16	Vehicle	215	Limited. Tried turning off & on, changed settings etc. nil changes.	Air conditioning in front cabin playing up, making a whistling noise, with limited cold air coming out.	Nil	Nil
19-Aug-16	Defibrillator	250	-	Adult sats probe not reading correctly. Paediatric works fine. Adult probe removed from service and in OIC pigeon hole.	-	-
19-Aug-16	Vehicle	235	Reported here - still functional - awaiting assessment and necessary repairs.	Side step / LED side step light sustained some damage - still functional.	Driving on dirt road responding to Code 1 downgraded to Code 2 backup - drove over slight mound in dirt road and ? scraped step / LED step light on top of dirt mound? Heard scrape.	Going on days off now - can be contacted via work email or if urgent details required, personal mobile phone.
20-Aug-16	Vehicle	195	Vehicle taken off road	Exhaust fumes coming into front cabin. Oil leak ? From turbo hose near air filter	Unknown	-
19-Aug-16	Vehicle	210	nil	toggle switch for spotlights broken	?	-
20-Aug-16	General Equipment	235	-	6607 PHONE- not receiving pages. Unable to call out. It states on the phone that it is offline. screen is cracked. Battery cover is falling off	-	Phone is located in Ipswich OIC Intray
20-Aug-16	Other Equipment	190	Phone notification with Townsville Comms centre. E-mail to Comms and Manager of business support in Mount Isa	The vehicle radio in unit 1302 is transmitting but not receiving. Comms can hear my transmission but when they reply there is nothing on the radio in the vchile from them or any other radio traffic	Unknown This morning I called at approx 0800 to log on for the shift and it was fine. The PTT system was installed last week	It is the only vehicle available at Julia Creek Station today and tomorrow as the second vehicle for Julia Creek is at Sedan Dip on a sports special. Unit 1302 is operationsl and advise from comms is to use Phone as primary communication in the unit
20-Aug-16	General Equipment	250	Removed from service. Replaced	Tough book charger not working. .? Plug / connector that plugs into tough book is loose.	-	-
20-Aug-16	Vehicle	195	Taken off road to be assessed	Engine dash light flashing and trouble accelerating.	-	-
20-Aug-16	Vehicle	210	Fluids checked preshift and again before submitting this fault.	Engine check light is flashing. This only appears to have started now (both officers on station have not previously seen this indicator flashing before today).	I have a feeling it could be because the local mechanic after the last service was unable to reset the service indicator. The instrument display currently says 3100km "past service".	Perhaps if we could try resetting the service indicator, it might fix the engine light problem...?
20-Aug-16	Vehicle	240	Fault report	Main battery not holding charge. Battery lost sufficient charge to start vehicle after standing at RBWH for over 2 1/2 hours. Used auxiliary battery to assist starting of vehicle.	Faulty battery	-
21-Aug-16	Vehicle	225	OIC found that interior lighting was working with no issues. Vehicle has been on cahrge all day.	Power to rear module switches off by itself multiple times in short space of time. Noticed on nightshift when interior lights used	-	-
21-Aug-16	Vehicle	245	pressed back on as best as possible	Plastic fering and indicator lamp beside the drivers door and plastic fering over front wheel arch on drivers side are both damaged after a kangaroo jumped into the side of the vehicle.	a kangaroo	-
21-Aug-16	Vehicle	195	Car out of service, fault form completed. Car parked outside of plant room.	Coolant temperature warning light appeared, car coolant rising to temperatures over 100 degrees, when checked under bonnet oil splatter under bonnet- unknown cause	unknown cause	-
20-Aug-16	Vehicle	235	-	GPS on MDT not functioning and SECOMM report vehicle not tracking correctly.	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
21-Aug-16	Vehicle	230	Contacted marathon field officer in charge	Crossed over partially on medium strip due marathon barrier as I came off the medium strip I caught the left side step , step was not able to appropriately work .	Medium strip gutter .	-
21-Aug-16	Vehicle	220	Currently running vehicle with O2 turned off until required.	Slow leak from an O2 outlet within the vehicle.	unknown. Os had been serviced in May.	Similar fault found with similar O2 delivery system in St George.
21-Aug-16	Stair Chair	215	-	Noted clip for chest safety strap missing	-	-
21-Aug-16	Vehicle	185	A/OIC notified and fault form lodged.	Main switch in front compartment not working, Blue screen showing only and none of the lighting or siren functions work.	-	V 4838
21-Aug-16	Vehicle	235	-	Electronic faults, problem with the siren. See above notes.	-	-
21-Aug-16	Vehicle	240	ROC- has been notified of incident	When traveling any speed over 20kpm vehicle makes horrible dragging sounds and loses power to accelerate.	? issue with turbo	repaired
21-Aug-16	Vehicle	240	ROC has been notified.	When vehicle is driven any speed over 20kpm, dragging/screeching sound is heard. When attempting to drive vehicle there is loss of power and acceleration with heavy steering.	? issue with turbo	-
20-Aug-16	Vehicle	225	Informed OIC	2 stone chips on windscreen happened at the same time, car passing.	Stones	-
21-Aug-16	Vehicle	235	-	Damage to front bumper and rego plate.	Hit kangaroo on highway.	-
21-Aug-16	Vehicle	235	Nil	L side tail light globe not operational	suspected blown tail light globe	-
21-Aug-16	Defibrillator	235	Nil. Requires new cable.	Pulse oximetry cable defective. Has an alert message saying the cable is defective, pulse oximetry does not work, cable is required to be unplugged from main socket of defibrillator then reinserted to overcome the fault, but will then just stop working	Unknown	Devil is labelled "Springfield 1"
22-Aug-16	General Equipment	235	nil.	Defibrillator bracket holder/rotator does not lock into place.	unknow but ? Wear and tear	Requires replacement. Quite frustrating that the defib keeps moving about and not locking in place and detracts for core duty of pt care and reading information off the monitor screen eg cardiac rhythm and alarms.
22-Aug-16	Vehicle	215	Completed this form.	Side Step not working properly and makes noises, now not retracting fully. Left Front passenger main headlight is not working. Need new pager as light does not work.	Unknown	-
22-Aug-16	Vehicle	185	N/A	Rear step not working/activating.	Unknown	Vehicle still operational. authority V 4839. OIC Gordonvale to take unit to for repair.
22-Aug-16	Vehicle	240	to check	Flat battery - advised	. Charging fuse - vehicle plugged in with master switch on	-
11-Aug-16	Vehicle	240	None	Left hand indicator lens on rear view mirror broken.	Discovered by while checking unit.	-
11-Aug-16	Vehicle	240	None	Left hand indicator lens on rear view mirror broken.	Discovered by while checking unit.	-
22-Aug-16	Vehicle	240		Master switch on panel board U /S	Normal wear	Switch not clicking in or out
22-Aug-16	Vehicle	205	Booked in for 24/08/16	Service -B2	-	-
22-Aug-16	Vehicle	205	Booked in for 24/08/16	Service - B2	-	-
22-Aug-16	Vehicle	205	They have attempted to tighten the aerila	Faulty radio - Whilst responding on a case the aerial came lose and since this has occurred they have had very little radio reception	The aerial coming lose may have broken some wires	Requires urgent attention
22-Aug-16	Defibrillator	235	New probe purchased checked if plugged in to external power.	SpO2 probe has electrical tape on cable. Unwrapping tape, exposed wires are noted (on distal end of cable, closest to monitor)	Unknown, logged onto vehicle today (22/8) and found it 'fixed'. No spares on station, OIC and other staff unaware	Not operational, but no spares so will make do until new one acquired
22-Aug-16	Vehicle	240	Contacted mechanic	Vehicle will not start. Vehicle attached to power all weekend. Faulty battery	flat battery	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
22-Aug-16	Vehicle	240	Car driven to workshops for diagnosis/repair	Aux battery not holding charge meaning no power to lights & sirens internal lights and other electronics that run off aux battery ? Defective battery or alternator	-	-
22-Aug-16	Vehicle	230	At repairers	Vehicle was taken to this morning. Engine warning light on	-	No odometer reading as vehicle already at
21-Aug-16	Vehicle	200	The QAS mechanic was notified on the 22nd. He stated the bash plate was no longer under the car & the step had been damaged. He stated that the step would not work & it would need to be fixed.	Side step not working	unknown what caused the fault, it was found at the start of our shift. The side step was not operating. It would not come out from under the car.	-
22-Aug-16	Vehicle	230	DVR raised. Vehicle taken off road	Rear AC not working. Just returned from repair. When crew started car AC fired up initially for a couple of mins. Now u/s again	-	-
22-Aug-16	Stretcher	250	Notified SOS attempted troubleshooting, fault form. SOS states crew to take stretcher to Southport at log on at beginning of shift tomorrow (23/08, 13-2300) for maintenance & replacement.	Foot end of stretcher not on tracks. Unable to put in modified sims position	Unknown cause	-
22-Aug-16	General Equipment	250	Cord was discarded	First part of pulse oximetry cord frayed	Unknown	-
22-Aug-16	Vehicle	210	Complete fault report.	Rear air-conditioning not working.	Unknown; a/c unit suddenly started making a loud noise.	Red warning lights are active on the a/c control panel in front of cabin.
22-Aug-16	Vehicle	230	DVR completed, OIC advised.	Bottom drug drawer in rear of the vehicle will not open. Phone charger holder in front broken. Drivers arm rest faulty. Rear airbag very slow to go down and doesn't always go down low enough. Not all rear air vents for AC working.	-	-
22-Aug-16	Vehicle	235	-	R) Headlight Out AM/FM Radio does not turn on Vehicle 'shudders' when turning on every third time or so, and turned itself off when prolonged idling	-	-
23-Aug-16	Vehicle	195	Vehicle needs to have the sockets replaced and tested	Corpuls is not charging one socket does have the internal parts and the other does not work	-	-
23-Aug-16	Vehicle	225	-	Brake warning light on dash	service due	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
23-Aug-16	Vehicle	240	Main switch turned off, plugged in. waiting for enough charge to start vehicle. Was to be taken to yesterday however operations prevented this. Intention to take to today when vehicle starts.	vehicle will not start. Main MDT switch (behind passenger seat) was turned off end of shift yesterday. Main switch on dash left on Vehicle plugged in to power	Main switch left on?	-
23-Aug-16	Vehicle	195	-	Central locking system NOT working correctly. Vehicle does not lock using the vehicle remote control. When the vehicle is stopped and the driver side door opened, the central locking still keeps all the doors locked, doors have to be manually unlocked.	-	-
22-Aug-16	Other Equipment	215	contacted on 23/08/2016.	charging bracket cable for the corpuls defib unit broken	maybe rough handling	-
23-Aug-16	Vehicle	225	Nil	Water leaking from roof of module, soaking passenger side dickie chair, stretcher and overhead cabinet.	Drove through moderate rainfall the night before, noticed water in the module next morning.	-
23-Aug-16	General Equipment	245	-	The loading device for the power stretcher in vehicle 6446 does not engage when pulling the stretcher out when stretcher is at full removal length. The only way to get the mechanism to engage is to bring the stretcher out quickly which is unsafe	-	-
23-Aug-16	Vehicle	190	notified my OIC	The airconditioner unit in the back of the vehicle leaked a lot of water this evening.	the vehicle was home on E/A and it was raining	-
23-Aug-16	Vehicle	245	-	Windshield wipers not working at all.	-	-
23-Aug-16	Vehicle	245	Has been reported	WINDSHEILD WIPERS NOT WORKING.	-	-
24-Aug-16	Vehicle	245	vehicle returned to station and out or service sign place on it	Engine warning light flashing and vehicle very slow but not in limp mode.	No idea why fault started.	-
24-Aug-16	Vehicle	235	None-	Vehicle will not accelerate in lower gears. Is 'lagging'. Going up hills vehicle struggles. Not able to proceed code 1 due to difficulty building up speed. Yellow engine light flashing	Not known	-
24-Aug-16	Vehicle	215	-	Cannula tigon drawer #2 the slide railing has broken	screws missing	-
23-Aug-16	Vehicle	200	-	2294 entered limp mode during drive out local at approx 50 km/h. driven 500m back to station and taken off road.	-	car taken off road, replaced with 2492 from proserpine.
24-Aug-16	Vehicle	225	Checked rear safety switches. Checked charge. Vehicle has been running and on charge. Power to front and radios.	No power to rear module	N/A	-
24-Aug-16	Vehicle	225	Nothing as yet as the equipment needs to be looked at by an auto electrician.	The monitor for the reversing camera is displaying a 'white out' once reverse is engaged. This possibly indicates that the camera is damaged or the cables are faulty.	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
24-Aug-16	Vehicle	225	Called mechanics and they asked us to call in to have scan tool put on vehicle.	Check engine light on dash	Unknown	Called into mechanics had test performed.
24-Aug-16	Vehicle	240	Vehicle removed from service and OC informed	Water located in the electrical panel located RHS of vehicle above MDT cabinet. Causing complete electrical failure an multiple alarms on the main panel	Water from either rain or condensation from the air conditioning unit entering the electrical compartment	-
22-Aug-16	Vehicle	230	Charge plug still works, needs replacing notified OIC of fault.	Charge plug for corpuls under Cardiac 1 Cupboard has broken from mounting screws	Unknown	-
24-Aug-16	Vehicle	210	Vehicle to continue on IFT case.	(R) Stryker stretcher of dual stretcher unit front struts of stretcher appear to have intermittent problem locking.	Unsure	Officer currently assigned to vehicle on IFT advised of potential hazard.
24-Aug-16	Vehicle	235	taken vehicle to Ipswich station	Power stretcher cot has lost power and has stopped working. Unable to unload.	Not known	-
22-Aug-16	Vehicle	235	rebooted several times	MDT not working. Asks to be rebooted, rebooting not fixing problem	? Software	Vehicle located at Toogoolawah station
24-Aug-16	Vehicle	240	Vehicle picked up by this morning, assessed and found to have blockage/soot in exhaust. Blockage cleared and vehicle now ok and running normally. Returned to Ningi and operational.	Driver has exited a steep driveway, when the check engine light has come on. Called the OC and was advised to turn everything off and restart the engine, which was done three times, which did not work. ? Strange odour was coming from the engine.	-	OC advised to drive back to station and change vehicles
25-Aug-16	Vehicle	195	RCD reset and car put on charge	Module not unlocking.	RCD tripped	RCD had tripped and not charging - now rectified
25-Aug-16	Vehicle	240	Charge increased after driving without emergency lights or other electrical demands.	Siren was intermittently loud and soft. Noted the Battery monitor shown the Module battery reading Low.	? Busy night with lots of electrical drain (lights/sirens, internal lights, internal heater etc) no opportunity to charge via mains due to workload.	To be monitored and possibly have battery checked.
25-Aug-16	Vehicle	225	-	Reversing camera not working	-	-
25-Aug-16	Defibrillator	225	Contact Technical Service report fault	SD card full	-	-
25-Aug-16	Defibrillator	225	Report fault to Technical Services	SD card full	-	-
25-Aug-16	Vehicle	225	Fleet manager notified and new struts ordered	Back door struts failed	-	-
1-Nov-16	Vehicle	245	Turning off ignition and restarting vehicle	Engine warning light began flashing and vehicle went into Limp Home mode. Turning engine off and restarting has not rectified the problem	Unknown	-
1-Nov-16	Vehicle	210	Notify CRR	Broken DS rear yellow metal hinge broken for rear door jam. Also the emergency lights come on intermittently when going around corners as though the rear door not shut properly.	Reported to me this am	-
2-Nov-16	Vehicle	230	-	check rear doors hinges and latch. possible adjustment required.	-	Officer reported doors difficult to close.
2-Nov-16	Vehicle	230	Contacted Comms. Contacted	Vehicle won't start by turning key or emergency start. ? flat battery	? flat battery	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
25-Aug-16	Vehicle	250	Nil	Reversing camera only working intermittently. When reversing only "snow" shown on the screen.	Unknown	-
24-Aug-16	Vehicle	225	Tyre was changed by crew at Kingaroy station	Left rear tyre found flat after job. Screw found in tyre	Screw	On 25/8/16 the day after flat tyre, vehicle was taken to mechanic to replace spare and check tyre
25-Aug-16	Vehicle General	185	reported	Side step not working	unknown	Sensor intermittent. Sometimes works and sometimes doesn't. Authority number V 4854 to
25-Aug-16	Equipment	240	-	The 12 volt connector is broken where the corpulse plugs into. not able to charge the corpulse	-	-
26-Aug-16	Vehicle	225	Load and reload stretcher. Topped up coolant.	1) Drivers side stretcher head-end wheels won't collapse outwards, unable to unload stretcher out of unit without lifting entire weight of stretcher. 2) Low radiator coolant alarm continuously sounding even though radiator tank is full.	3) Air bag suspension not lifting rear of unit. Only lifts with hand break on and manually pressing button. Unknown why stretcher stuck, worked without problem for first half of shift.	Requires a service to the vehicle
24-Aug-16	Vehicle	250	-	Side step not functioning	Unknown	-
25-Aug-16	Vehicle	210	This report	Side step not working	Unknown	-
				Rear suspension not working. When pressing let down suspension button, there is no movement just a buzzing sound.		
26-Aug-16	Vehicle	230	-	Very rough ride for patients and crew.	-	-
26-Aug-16	Vehicle	215	-	Oil leak	-	-
26-Aug-16	Vehicle	215	onto it	Faulty step	grit in work ings	U/s due to previous fault
26-Aug-16	Vehicle	235	attempt to see fleet mechanic	Handbrake not working, pt step not auto retracting, rear suspension wallowing all over road particularly at speed, pt care door hinge (bottom one) broken, door alarm constantly activating, scratch down drivers side.	-	-
26-Aug-16	Vehicle	225	-	Vehicle overdue for service. No sticker on windscreen to say when it is due but ? has not been serviced since the vehicle was basically brand new.	-	-
25-Aug-16	Vehicle	240	mechanic informed, visualised and gaining approval to fix. Mechanic informed unit not operational.	Leaking pink coloured fluid 2m long on plant room floor from under vehicle.	water pump leak	-
26-Aug-16	Vehicle	215	yes	Rear passenger side little light	Hit a bumper of another vehicle	Light needs replacing
26-Aug-16	Vehicle	225	Using jump starter on frequent occasion to start unit. Will take to mechanic for battery replacement asap.	Will require replacement battery as soon as practicable.	-	-
26-Aug-16	Vehicle	225	Will take to mechanic when practicable.	Flat battery	-	-
26-Aug-16	Vehicle	245	ROC notified	R) brake light out- dash light comes on whilst braking	-	-
26-Aug-16	Vehicle	230	OIC/ CDS notified. Defect form completed. Sign placed in driver's seat	Engine light flashing, jerky acceleration and decreased power	-	-
27-Aug-16	Vehicle	240	none, fault forms are completed and no action is taken - after hours	Front R headlight u/s	fault is ongoing for 3+ weeks	REPAIRED DURING SERVICE

RTI RELEASE

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
27-Aug-16	Vehicle	185	Replace/repair vents	A/C vents in rear compartment broken, one above attendants seat has full stream gale coming through it even when a/c is set on lowest fan	-	One airvent fixed on stn, one airvent remains broken. Authority to fix at V 4852. & I will send parts down with Tully PTO officer.
27-Aug-16	Vehicle	200	called DO and completed fault form	Yellow brake pad wear indicator lamp light appeared when vehicle started. Officer looked up light on dash in manual - manual stating the brake pads have reached their wear limit. Called DO who stated to complete current job and transfer out when pos	Brake pad wear	Vehicle located in front shed at South Mackay
27-Aug-16	Vehicle	185	Completed a fault report. Will inform acting OIC on Monday	The plastic covering of the car radio is frayed and wires are exposed.	-	I will attach a photo in vehicle checklist. A/OIC to log an IT job with PSBA and have the vehicle taken therefor repair.
27-Aug-16	Vehicle	230	The master switch has been used to reset the MDT with no change in the screen status which reads 'A disk read error occurred.'	MDT not working	-	Refer to checklist photo for details of error.
27-Aug-16	Vehicle	215	Fault form completed, SOS notification via telephone to follow.	Drivers' side gas strut for rear opening door unserviceable.	During pre-shift vehicle check, Officer noted that strut leaked fluid and gas.	N/A
27-Aug-16	Vehicle	225	Repaired at	Out of service at 12:16 siren and horn failed	-	-
27-Aug-16	Vehicle	225	REpaired at	Siren failed and horn failed while on code one	-	-
27-Aug-16	Vehicle	245	open circuit replaced.	Siren failed and horn failed while on code one	-	-
27-Aug-16	Vehicle	245	fault form	Right parking light blown	age	Has this worked?
27-Aug-16	Stretcher	245	manually returned the stretcher back into the vehicle and made vehicle non operational.	The lifting arm on the loading mechanism is not working. To difficult to explain the actual problem due to not knowing the specific part names.	No idea. It worked on the previous removal and replacement of the stretcher.	-
27-Aug-16	Stretcher	245	Fault form completed. SOS/OS aware who stated he would notify OC.	Raising/lowering arm attached to vehicle will not work. Stretcher had to be manually loaded into vehicle	-	-
27-Aug-16	Vehicle	235	Fault form completed	Passenger side low beam light has blown	-	-
27-Aug-16	Vehicle	210	Nil	Aluminium bumper bent up on end	Damage found at start of shift during vehicle check	-
27-Aug-16	Vehicle	230	True changed by RACQ, flat in spare position	Flat tyre	Stone lodged through tread	Flat tyre requires repair
28-Aug-16	Vehicle	240	Vehicle restarted as above and ran without issues for rest of shift and the following night shift.	VEHICLES ENGINE STOPPED RUNNING ON RETURN FROM BRIBIE ISLAND. PULLED OVER AND ATTEMPTED RESTART WHICH WORKED.	-	Mechanic spoken to on 29/8 and advised that nil further issues not and advised to send to them if any further issues otherwise will check at next service.
27-Aug-16	Vehicle	240	Mechanic and QAS workshops contacted, mechanic able to repair and will order spare parts, vehicle will be repaired once parts arrived.	BRUSHED DRIVERS SIDE MIRROR ON CLOSED IN CONCRETE WALL BREAKING INDICATOR COVER. LIGHT STILL FUNCTIONING PROPERLY	DRIVER ERROR	SORRY

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
25-Aug-16	Vehicle	200	Topped up with water	When collected from workshop on Thursday a low water alarm sounded ten minutes into the drive to station. Water topped up to full at that time. Upon starting vehicle this morning after EA the alarm sounded again. Approx 500ml water needed to top up	-	-
28-Aug-16	Defibrillator	245	Taken out of service and left in OIC office	Printer not working	-	-
28-Aug-16	Vehicle	215	Vehicle report filled out	"knocking/clunking sound" when going over bumps - ? strut or dry ball joint in (Left) side front suspension.	unknown	currently 82875 - next service 90000. Needs to be looked at at next convenient time.
28-Aug-16	Vehicle	195	Removed from service, informed OIC via email.	Srs airbag light on in the dash.	Unknown, came on during shift while driving.	-
27-Aug-16	Vehicle	225	-	CORPULSE does not charge when in cradle when car is on and/or off and QAS had tried another monitor to confirm the issue was the charger in the car.	nit known	-
28-Aug-16	Vehicle	230	-	Rear ac keeps turning off as we have been directed to only use on auto and not set below 23 degrees	Used as indicated by stickers on vehicle	became so stuffy in rear of vehicle cardiac pt became nauseous
27-Aug-16	Stretcher	210	Stretcher deemed not-operational and faulty. Comms and SOS instantly notified.	SHE incident 036470: Head end of stretcher collapsed when foot end red lever pressed head end (mid-height) higher than foot end (lowest-height). Patient had been on stretcher for a few minutes prior to collapse.	-	-
28-Aug-16	Vehicle	195	ADVISED SOS AND VEHICLE HAS BEEN LEFT ON PLANT ROOM FLOOR	AIRBAGS NOT DEPLOYING AIRCON EXTREMELY LOUD IN THE REAR CABIN	-	-
28-Aug-16	Vehicle	250	sticky tape to hold it in place	Screen is lose on MDT	unknown	-
29-Aug-16	Vehicle	235	-	Fuel gauge went down to empty even though car had fuel in it, after that check engine light started flashing and car not speeding up properly once over 40km/h.	-	-
29-Aug-16	General Equipment	185	nil available actions-medtek required. Nil spare oxygen kit available.	Leaking demand valve port	unknown	Officer to advise me of vehicle unit number so I can log a job with
29-Aug-16	Vehicle	245	Inform OIC Nathan station. Require to notify workshop technician for routine maintenance and repairs.	Brake pad/disc wear indication light appearing on dashboard.	Excessive use of brakes over period of time.	-
29-Aug-16	Vehicle	190	Swapped lamp to other charger so can get some power, ? Top charger plug bent/faulty	1x headlamp not working	-	-
29-Aug-16	Vehicle	210	-	LHS bulbar fog light has broken cover but bulb still working.	Unknown found at commencement of shift.	-
29-Aug-16	Defibrillator	210	Unit will charge the defib through mains power when needed.	In car charger port is broken. The system seems to have a plug ripped out and will no longer plug into itself. Pieces of the system seem to be missing.	Poor construction / cable not secured well.	Unable to attach photos. Photos availed if needed.
29-Aug-16	Vehicle	215	Booked for repair	Rear Passenger door latch at top of door needs adjusting as not secure fitting	-	-

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
28-Aug-16	Stretcher	215	taped in place and repair/replacment part arranged through 1800667558	Red plastic protector on drop arm damaged and needs replaing	stretcher arm not dropped completely to ground level due to weight of pt and uneven ground , manual release used	-
27-Aug-16	General Equipment	185	use of torch from another unit	1x Vehicle torch going flat on use / not charging, requires replacement	?? needs new battery pack	A new torch will be sent to Malanda to replace faulty one.
29-Aug-16	Vehicle	245	completed fault form	No shoulder strap on defibrillator, damage to stretcher loading ramp above scoop	?repeated ramming of stretcher into the loading ramp at wrong height to load into vehicle. Someone has removed the shoulder strap from defibrillator	-
29-Aug-16	Vehicle	180	Batteries charged and working.	Failed to start, flat batteries.	Batteries	On going issue, batteries were replaced <12 months ago and a solar panel was installed. Once the batteries age they are no longer able to hold enough charge over night to be able to start the vehicle in the morning.
28-Aug-16	Vehicle	180	Latch is pulled back manually each time it is used but it will need to be looked at by a mechanic. Will liaise with OIC to arrange most appropriate time for repair.	Internal side door latch is sticking open	Internal door handle	-
28-Aug-16	Vehicle	185	Currently wedged in place with padding, but not secure	Main Comms radio in cab fell from bracket after hitting bump in road appears that no screws were in place holding it to bracket	No screws	Requires repair. authority number V 4869. A/OIC to have unit taken to
29-Aug-16	Vehicle	210	-	Yellow flashing engine light on dash.	-	Travelling in 60 k zone, car lost power, officers thought gear stick had been knocked. Finished job travelling in 60k zone engine flashing light appeared.
28-Aug-16	General Equipment	185	-	Portable radio speaker	it crackles all the time, then stops for a bit, but starts again	Officer Scarborough - which portable? A/OIC to log IT job with PSBA and facilitate that repair.
29-Aug-16	Vehicle	215	nil	Drivers Window operating button broken	normal operation	-
29-Aug-16	Vehicle	245	none	Broken side arm of stretcher	found faulty during shift	-
29-Aug-16	Vehicle	235	nil	L side tail light globe is not functioning.	? Blown bulb	Reported some time ago ? Never repaired.
29-Aug-16	Vehicle	225	-	Torches do not charge	-	Equipment does not work
29-Aug-16	Vehicle	225	-	Passenger side wing mirror is attached with arms that are the wrong design, they are for a left hand drive unit. As such anybody over 1.5m tall cannot see the mirror fully due to the window divider getting in the way and have to constantly lean forward	-	-
30-Aug-16	Vehicle	235	tried to reinsert multiple times but keeps coming free	Glovebox light keeps coming free from its housing	unknown	-
30-Aug-16	Defibrillator	250	Cable replaced defib operational	Pulse ox cable defective. End that plugs into defib. Has been replaced.	-	Cable replaced
30-Aug-16	Vehicle	210	notify OIC, proceed to workshops for replacement	Front L indicator bulb (headlight) blown	-	-
30-Aug-16	General Equipment	250	Mulitpe attempts, have tested on other monitors. Resulted in replacing cable. Cable replaced operational	Corpuls pateint oxygen sats cable not working.	-	OIC notified.

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
30-Aug-16	Vehicle	210	-	Minor damage/dent to rear of sliding door on the left (passenger side) of the vehicle.	Operator error - I unfortunately misjudged the corner turning a hard left into the parking bay at RBH. RBH was ramping at the time & parking bays were full so the vehicle was parked to the rear of the turn facility.	OpCen had been advised at the time of the incident.
30-Aug-16	Vehicle	240	Fault form	Sirens are not operational	Not known	-
30-Aug-16	Vehicle	240	Fault form completed Note in windshield	Sirens not operational	Unknown	-
30-Aug-16	General Equipment	210	Sometimes the suction will work after driving around. We are prepared to use kit suction if the vehicle suction is not working.	Vehicle suction is working intermittently. Will sometimes turn on for start of shift check.	Unknown	-
30-Aug-16	Vehicle	230	None, closed.	Front passenger side headlight u/s	-	Email oic
31-Aug-16	Vehicle	245	Pager given to OIC	Pager fault. Pager is not receiving pages, it is only working intermittently	Unknown	-
30-Aug-16	Vehicle	210	-	Rear suspension failed to raise post loading stretcher	-	-
31-Aug-16	Vehicle	235	-	Vehicle engine cuts out at random, even while the vehicle is in motion. Appears to 'stall' despite being an automatic.	-	-
31-Aug-16	Vehicle	215	-	VHF radio fault displayed "invalid serial port"	-	-
31-Aug-16	Vehicle	230	-	Rear left tail light broken (3) still functioning	-	3 of 4 tail lights still functioning likely wait till service?
31-Aug-16	Vehicle	210	Reporting visible indentation On fault report form.	Panel damage to body of vehicle, located on and yellow panel at the end of sliding door when door is closed, noted prior to shift commencement.	-	-
31-Aug-16	Vehicle	230	-	MDT interfering with microphone when swivelled pressing microphone button	-	Problem can be fixed by moving microphone mount to the right or relocating to passenger side near glovebox.
31-Aug-16	Vehicle	250	-	Vehicle has been on charge overnight and will not start	-	-
31-Aug-16	Vehicle	240	Nil - reported to Vehicle service contractor for fault find at regular service on 02/09/16	? Auxiliary Battery running flat after short period of time not attached to Mains power or when vehicle not running. All Aux power lost until vehicle restarted. MDT may sometimes require resetting after power fail.	-	-
31-Aug-16	Vehicle	215	Nil	Driver's seat unable to get gas suspension to work. CD still stuck in CD player.	Unknown	-
27-Aug-16	Stretcher	180	Taken off road, tagged. New stretcher organised from Thursday Island	Stretcher drop	? issue with locking device	no injuries
31-Aug-16	Vehicle	190	Vehicle will need to be taken off line tomorrow and taken to the service centre for repair. This is the only available vehicle on station and therefore will need to be taken home on call this evening.	Master switch will not turn on and therefore unable to operate emergency lights or siren.	-	-
31-Aug-16	Vehicle	210	nil	Left headlight out	unknown	-
31-Aug-16	Defibrillator	245	Put battery in and taken out again with nil success	Battery falling out. Clip broken?	No	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
31-Aug-16	Defibrillator	240	OIC informed and device taken out of service	Corpuls3 won't charge in manual mode	-	OC advised and corpuls3 taken from 5124 and placed on 5127
1-Sep-16	Defibrillator	195	Contacted SOS to report fault. Item has been exchanged with Corpuls from training room as per SOS instructions. was tested and all tests passed with training room machine. registered to vehicle	When testing machine to defibrilate, display message showed, "unable to connect to defibrillation cable". This message was again repeated on multiple attempts and again on another test unit and then again when live defibrillation pads were connected	-	-
1-Sep-16	Vehicle	215	Vehicle has been driven to mechanic (1klm) Limp mode during transit	Vehicle failed to start correctly this morning. Vehicle shuttered violently. Flashing engine light on	-	-
1-Sep-16	Vehicle	250	FleetMech has been contacted	Trailer Plug is bent up and back	?Reversing Mud on hitch	-
1-Sep-16	Vehicle	200	OIC notified of fault	Rear right side of the emergency beacon light bar has LEDs that are not working/flashing.	Unknown cause	-
31-Aug-16	Vehicle	185	V 4878 - for door solenoid repair V 4879 - for rear air con. OIC Cairns to arrange vehicle to be delivered to both repairers (call RRC if required)	1) Rear air con not working. Pushing semi cool air, not cold air. Very warm in the back for pts. 2) 'Door open alarm' faulty and beeps even though all doors are closed. 3) Side door to rear cabin faulty. Intermittently not working	-	While attending a code 1 pt we could not access the rear of the vehicle and hence delayed our response time.
1-Sep-16	Stretcher	210	Stretcher has been removed from service, currently on Emerald station, OIC, SOS and Resource Readiness Coordinator were all notified.	Stretcher was removed from vehicle as normal, lowered to half height for patient to sit on. As pt sat on the stretcher, the head of the stretcher dropped to the ground. The patient stood up straight away, nil injury occurring.	Unknown	Stretcher was removed from vehicle at start of shift to ensure it was operational, stretcher was also checked it had locked into place once it was lowered to half height. Stretcher was checked by SOS and OIC after the incident at the hospital.
30-Aug-16	Vehicle	215	send to mechanics and notify fleet officer and SOS and OPCEN of situation.	Funny noise heard during slow front passenger wheel in motion - sort of shuddered grinding noise but it did not affect steering and was okay to drive to take to mechanics.	unknown	Nil
1-Sep-16	Vehicle	240	OIC/OC notified and crew took ambulance to - unable to fix, require windscreen specialist	Crack to windscreen from rock - crack approx 2cm in diameter	Rock flew off truck tyre on D'Aguilar Highway and hit windscreen	-
26-Aug-16	Vehicle	230	nil	Cracked windscreen on passenger side.	stone chip off road.	Can be replaced during 30000 km service next week. No impedance to driver view.
1-Sep-16	Vehicle	240	All usual checks done	Side step not working	Unknown	-

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
1-Sep-16	Vehicle	240	advised usual service agent, who will seek approval and book in repair.	growing crack from base extending towards center of windscreen.	nil obvious.	repaired on site - organised by - windscreen replaced.
1-Sep-16	Vehicle	250	Car OOS, mechanic advised and will take car for replacement battery 2/9. SCE advised, SOS advised that CSO group may require spare OS car. Mechanic advised car not suitable for use as car may not start when out in the field.	Car failed to start, battery charger replaced this morning, problem still occurring.	Mechanic advised probable battery failure	-
1-Sep-16	Vehicle	245	Vehicle taken to PST during shift. Staff reset air filter sensor. Problem rectified, vehicle operational.	Engine light came on whilst driving with patient to GPH	Unknown	-
1-Sep-16	Vehicle	195	vehicle will be taken to local mechanics Friday A.M.	Loud and unusual noise coming from main cooling fan/ water pump assembly	unknown	-
1-Sep-16	Vehicle	210	fire extinguisher removed from tape and placed behind passenger seat	Fire extinguisher bracket broken, tape used to secure fire extinguisher	unknown	-
1-Sep-16	Defibrillator	250	advised OS & returned to station to be placed OOS	SpO2 and NIBP not working. Lead v2 intermittent & not printing well	unknown	-
1-Sep-16	Vehicle	235	Attempted to workout what was catching however difficult	Load and unload stretcher more difficult than normal ? That there has been damage while loading and the battery is catching on the loader when unloading.	Nil ? Was a problem from the beginning of the day nil known incident which could of caused the problem	-
1-Sep-16	Vehicle	225	mechanic looked at it 01/09/16 and stated it needs panel beater	Rear right hand tail light panel was damaged earlier in 2016 and has been approved by insurance company for repair. The damage to right hand rear tail light panel is now not allowing the rear veh door to open.	Existing insurance claim for damage caused by impact with driveway	Unable to open back door from the outside
1-Sep-16	Vehicle	250	-	Corpuls docking station not charging	unknown. Cables all connected	-
1-Sep-16	Vehicle	210	This defect notice	Automatic gear stick knob comes off when attempting to engage gears	Not known	-
1-Sep-16	Vehicle	235	-	Broken front right headlight	-	-
31-Aug-16	Defibrillator	240	taken out of service	ETCO2 error alarm and not sensing	-	-
1-Sep-16	Other	195	Corded attachment removed from device	Corded radio speaker and microphone attachment fault. Does not produce sound	Unknown	-
1-Sep-16	Equipment	195	removed from device	Left rear brake and left rear tail light put. Warning on dash for a while. R tail lights loose	Unknown	-
1-Sep-16	Vehicle	250	unable to	Passenger step intermittently not working or will move in and out of own volition. Other times it will work perfectly. A bit of a lucky dip.	unknown. Has been like this for a while	-
2-Sep-16	Vehicle	225	-	Passenger step intermittently not working or will move in and out of own volition. Other times it will work perfectly. A bit of a lucky dip.	-	Step working order. Officers to make sure the vehicle is on charge when not in use.

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
2-Sep-16	Defibrillator	195	out of service	When testing machine to defibrillate, display message showed, "unable to connect to defibrillation cable". This message was again repeated on multiple attempts and again on another test unit and then again when live defibrillation pads were connected	-	-
2-Sep-16	General Equipment	245	Given to OIC, New probe in situ.	SpO2 Probe end does not work. Infra-red light comes on but will not read	-	-
2-Sep-16	Vehicle	250	-	Damage to the interior sliding door panel was noticed on this mornings vehicle check. The cracked panels are now protruding with sharp edges which is hazardous.	Unknown.	Email with photo has been sent to OIC Burleigh.
2-Sep-16	Vehicle	210	This report and annotations on vehicle check list with photos.	Drivers side rear barn door magnetic catch detached	Unknown	Passenger side has already been repaired for same fault, however catch has been reattached in the reverse position.
2-Sep-16	Vehicle	240	-	Airconditioning not working and very clunky transmission Vehicle has stalled 4 times throughout shift	-	-
2-Sep-16	Vehicle	240	vehicle previous inspected and has had batteries replaced twice in past 3 weeks.	Ongoing battery issue. Unit has to be started with emergency start as it is failing during shift.	? Charging issue or battery power being drained through fault.	At risk of failing to start during shift.
2-Sep-16	Vehicle	240	Report created	Siren is not functioning	-	ESU. Can still respond code 2. unit number is 5454 and not 9070
2-Sep-16	Vehicle	240	vehicle taken off road.	charging lead shorted out - smouldering along lead and under bonnet.	vehicle driven when charging lead still plugged in.	-
2-Sep-16	Vehicle	250	Towed to be drained of petrol	Vehicle filled with petrol instead of diesel in error	Officer	Rego 356med is unit 602585, not 6584 as form automatically allocated above
2-Sep-16	Vehicle	200	-	Front left tyre has scuff mark	Unknown	Fault form completed as per SOS request.
2-Sep-16	Vehicle	195	Directed by Fleet Manager to for repairs. Fault rectified by staff, and vehicle fit for return to Ingham.	Rear A/C system U/S.	unknown	-
2-Sep-16	General Equipment	230	Oxyviva removed from service and spare taken from 4892 (signage placed on vehicle)	The pressure hose near the suction port appears to have a crack in it which has been taped (?). This was hidden by the compartment housing of the oxyviva bag. This section is now not holding pressure and a significant leak can be felt / heard.	Unknown. Someone has attempted to fix using tape.	Spare oxyviva in OIC office (signed).
2-Sep-16	General Equipment	240	Tape to hold it together	Wall mounted airway kit, plastic is splitting along seam, vehicle is <12mths old	Poor quality	swapped out for new
2-Sep-16	Vehicle	235	Vehicle / ambulance placed on charge for the night and to be tested in morning. If this proves effective a second form will be complete to show resolved.	Vehicle wont start, even once placed on charged for short time.	Not charged from previous night shift / crew.	-
2-Sep-16	Vehicle	195	Placed car out of service and SOS informed.	Liaised with SOS on duty about warning light- informed to continue on with patient. Once at TTH informed SOS car went into limp mode and we were told to drive vehicle back to station and put out of service. Nil warning lights present at start of shift.	-	-
3-Sep-16	Vehicle	230	Reduction of some consumables to lessen risk.	Several overhead locker access clips do not anchor securely when in closed position allowing stowed contents to spill out over stretcher & floor area of rear patient care compartment.	Unknown ? design flaw.	While not a critical issue it is annoying & looks unprofessional upon opening rear hatch to find a variety of stores strewn throughout vehicle.

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
3-Sep-16	Vehicle	185	-	Back seat and rear module unable to be moved and to far apart to be used properly. Touch screen next to suction not working. Mains turned off and on again- same issue. Other touch screens functioning normally.	- authority number V 4882.	
3-Sep-16	Vehicle	240	Nil action able to be taken by officers. Requires review by qualified person	Stretcher locking mechanism in vehicle won't engage if there is weight on stretcher when stretcher is loaded into vehicle. Locking mechanism only half engages (red button only half pops out) allowing stretcher to move during transit	Unknown	BNE OPCEN OC advised of issue.
3-Sep-16	Defibrillator	250	-	SPO2 not sensing. Cable which connects to the machine replaced which resolved the issue	-	-
3-Sep-16	Vehicle	240	tried to adjust seat angle to free seat belt as per mechanic advice. Not working.	Seatbelt for pt care officer rear seat jammed.	this seatbelt has not been operational for over 6 months	reviewed and operational
3-Sep-16	Other Equipment	210	nil	Some pixels on pager not displaying correctly and as a result hard to read information.	?	-
3-Sep-16	Vehicle	240	informed ROC	Diesel leaking underneath engine bay. As opposed to the air conditioning system condensation, it is identified by the fuel leak now on the plant room floor Approx 200-300ml leaking whilst at patient residence and once again at hospital. Fuel tank 2/3 full	-	Vehicle equipment remaining serviceable
3-Sep-16	Vehicle	250	-	Reversing proximity sensors not working.	Wire to proximity sensors damaged and hanging down from rear step.	-
3-Sep-16	Vehicle	225	Fault form lodged	Difficulty starting vehicle when cold. Significant engine vibration and miss noted upon starting. No problem noticed after idling vehicle for approx 2 minutes. No problem noted throughout the day.	-	-
3-Sep-16	Vehicle	240	-	MDT will not boot up error message and requires to be connected to key board to rectify	-	-
3-Sep-16	Vehicle	240	Tried to reboot several times	MDT faulty	-	-
25-Aug-16	Vehicle	235	-	Left and Right Alley Lights Not Working	-	-
3-Sep-16	Vehicle	235	-	Right Alley Light Not Working	-	-
3-Sep-16	Stretcher	210	Stretcher defected and left in 2286 with defect notice.	Stretcher rolled downhill hitting a parked car, damaging car, bending control protective guard on stretcher	Me not applying the brakes	-
3-Sep-16	Vehicle	235	tyre pressure test	Shuddering coming from front end when turning right more noticeable under code 1 driving conditions	tyre pressures checked and found to be normal whilst checking pressure wet oil noticed under passenger side engine compartment	-
4-Sep-16	Defibrillator	250	-	Faulty printer. Paper will not print out as required.	Unknown	-
4-Sep-16	Vehicle	225	Checked vehicle fuses	FM radio in ambulance not working	-	-
4-Sep-16	Vehicle	230	filled tank, still doesn't work, just dribbles from drivers side washer	Windscreen washer not working	unknown	-
3-Sep-16	Vehicle	245	6/9/16 - PST attended site to repair faulty light	Left work light doesn't work	-	-
4-Sep-16	Defibrillator	250	-	Memory card full	-	Left in OIC office
4-Sep-16	Vehicle	240	Called OC and returned to station	The vehicle does not accelerate and has engine warning lights on	-	-
4-Sep-16	Vehicle	225	Compel have replaced handset phone is now operational	Flat battery in sat phone	-	Ongoing problem , has been investigated but cause has not been found.

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
4-Sep-16	Vehicle	225	-	Flat battery in sat phone	-	Ongoing problem , has been investigated but cause has not been found.
4-Sep-16	Defibrillator	200	See above. Happy to keep using at the moment, but want issue investigated further, as not the only machine I have noticed this on.	On doing 12 lead the tracing is very faint in particular the QRS is very faint and hard to see. I've cleaned the printer per instructions and also tried a new roll of paper. These slightly improved the quality	-	In 2512
3-Sep-16	Vehicle	235	n/a	rear aircon not working, constant alarm ? airbags, equipment table unable to be moved	n/a	parked at ipswich station
4-Sep-16	Vehicle	210	Nil	Vehicle airway cupboards making squeaky noise while driving. It appears as if the roof lining has sagged and are rubbing on the top of the cupboards.	-	-
4-Sep-16	Vehicle	200	Tried to check it was all secured properly and it appears to be.	Vehicle 126 internal suction is not sucking very hard.. Very quiet when you out the tube next to ear. Double checked everything was attached and secured firmly but cannot fix.	-	-
4-Sep-16	Vehicle	245	Inflated yesterday and again today	Tyre leak - tyre inflated yesterday and is low again today (back right tyre on 5296)	-	-
4-Sep-16	Defibrillator	240	-	Pulse oximetry cable faulty	-	-
2-Sep-16	Stretcher	215	P/T needs bariatric truck. P/T was expecting bariatric truck as she has used it before for transport.	P/T to large for stretcher weight and size (width). QAS estimated 250-260kg. Stretcher was able to lift P/T into car but would not lower stretcher down to lock into mechanism once in car. Stretcher worked fine once P/T was off stretcher for rest of day.	P/T to large For stretcher.	P/T felt very unstable on stretcher since she was to wide for stretcher and became very anxious with whole situation. Stretcher has been working perfectly since this P/T.
4-Sep-16	Vehicle	240	Fault report form, advise OIC, car still operational	Broken cover on left rear taillight	reversed into rubbish bin	-
5-Sep-16	Vehicle	200	-	Both gps units not charging despite connection check. Also oem USB port inactive. Query if recent sat phone install has damaged these connections	possibly recent sat phone install. Oem USB port also inactive on 2103	-
5-Sep-16	Vehicle	240	nil	Left front park light broken	-	-
5-Sep-16	Vehicle	215	-	Step not operating	-	-
5-Sep-16	Vehicle	210	-	Rear right yellow door holder not locking in to hold door open.	?	unknown when fault occurred and if it has already been defected
5-Sep-16	Vehicle	205	-	Windscreen crack. Has expanded to approx 3/4 width of windscreen.	-	BSM aware of initial crack. Has significantly increased overnight. Requires replacement.
2-Sep-16	Vehicle	205	Replacement part ordered by mechanic.	Right rear shock absorber damage identified at service on 2/9/16.	-	Mechanic advises vehicle is still suitable to remain operational.
4-Sep-16	Stretcher	225	Notified OIC. Removed from service.	Stretcher had been lowered and dropped one notch as pt was boarding.	unknown	-
5-Sep-16	Vehicle	240	-	no 12v power to from or rear plugs, unable to charge corpuls monitor	?? fuse.	vehilce on station offline
5-Sep-16	Vehicle	200	Switch has been turned on then off. Attempted to visualise if a stone is stuck in step.	Vehicle step is slightly stuck out, does not completely fold into vehicle when door is shut	Unknown	-
5-Sep-16	Vehicle	240	-	Regularly going into idle mode which has caused engine light to come on. Reset by mechanic however vehicle went back into idle	-	-
5-Sep-16	General Equipment	230	-	broken MDT, will not power on, appears to have broken case	unknown	-
5-Sep-16	Vehicle	230	contacted re repair	Vehicle has flat battery	-	-

RTI RELEASE

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
5-Sep-16	Vehicle	235	Discussed and inspected with WTM fleet management	Cannulation drawer #2; left bracket that secures drawer to housing unit is broken	Unknown	-
4-Sep-16	Vehicle	185	-	Damage to right rear taillight cover and scratch to paintwork adjacent to right rear taillight, light is fully functional.	Don't remember striking anything as vehicle was used on a night on a late call out, possible a tree branch on a driveway.	NFAD.
5-Sep-16	Vehicle	225	doors closed again to ensure they are shut	Rear door open alarm on when doors are shut, sometimes causing rear emergency lights to come on	unknown	-
2-Sep-16	Vehicle	190	fault logged with Boss on ICT portal. Technicians are coming to station next week	Vehicle VHF radios not transmitting and intermittently receiving	-	-
5-Sep-16	Vehicle	215	vehicle taken to who has removed nail and sealed. operational	chip in windscreen nail in rear left tyre	-	chip still needs repair
5-Sep-16	Vehicle	240	Informed	Side step not coming out automatically when door opens. Will work with manual override.	Stopped working overnight.	-
1-Sep-16	General Equipment	230	Replacement	Torch missing	Unknown, been highlighted on electronic report	Only one torch identified in checks since electronic checks began. Rainbow Beach 4x4 unit 4943. Registration number 927WBI. Unknown when item was misplaced.
5-Sep-16	Defibrillator	215	We attempted to replace the cord - no change. Defib swapped with 411 for remainder of shift. COMMS notified.	Monitor showed "oxy cable defect" alarm. SPO2 inaccurate when compared to 4700 at same time.	unknown	-
6-Sep-16	Vehicle	245	-	Not safe for gaining entry to rear of ambulance (side step not functioning). Not safe for code 1 driving (nil siren function, nil horn function, nil passenger reading light function).	-	-
5-Sep-16	Vehicle	195	nil	Right rear work light not functioning properly. Is semi illuminating but not projecting light.	unknown	-
6-Sep-16	Vehicle	230	Comm notified. Crew swapped into another vehicle. Vehicle taken off road, OIC notified.	While driving at high speed (80kph+) the vehicle began to shutter heavily.	Unknown, vehicle returned from service yesterday and this is the first use since.	-
6-Sep-16	Vehicle	210	nil	Broken defibrillator bracket	found on vehicle check	-
6-Sep-16	Vehicle	210	-	broken drivers side indicator	struck object	-
6-Sep-16	Stretcher	210	Nil	When stretcher pulled out of vehicle the legs would not lower down to the ground. Fault rectified by changing batteries even though a new charged battery had been replaced on the stretcher at start of shift.	Faulty battery??	-
5-Sep-16	Vehicle	235	Nil	Right hand (driver side) alley light not working	-	-
7-Sep-16	Defibrillator	245	Fault report form filled out 7/9/16 - OIC Sourced replacement cable, unit operational 0741 070916	Blood pressure attachment on hose from defibrillator has broke, can't connect blood pressure cuffs	-	Vehicle 6417 has sufficient manual blood pressure cuffs

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
7-Sep-16	Vehicle	205	Fault form completed, business manager and duty OIC contacted.	In vehicle radio not receiving or transmitting	Not known but reported radio issues in the region.	-
7-Sep-16	Vehicle	240	-	Warning signal reading ESP and visit workshop.	-	-
6-Sep-16	Vehicle	240	towed to pinjarra. Oc notified, booked to workshop.	Sudden loss of power and vacuum noise when accelerating on code 1 response, ?busted turbo. Engine light flashing when car turned on, undrivable.	Nil	-
7-Sep-16	Vehicle	215	Vehicle taken to step fixed	Side step not working despite problem solving	unknown	-
7-Sep-16	Vehicle	235	Mechanic informed and sighted problem	Red 240 v inverter tripping.	unknown	Both RED access plug points tripping inverter
7-Sep-16	Vehicle	200	Nil	Broken Drivers side lower rear view mirror	Unknown, whilst checking out the vehicle this morning I noticed it was broken	-
3-Sep-16	Vehicle	245	-	Tough book charging point/socket doesn't appear to be operational. Tried it with different (new) toughbook charging cable and different tough book but with no success.	-	-
7-Sep-16	Vehicle	230	-	Cigarette lighter faulty - can't charge tough book	-	OIC Aware
7-Sep-16	Vehicle	215	Tyre pressures have been checked by and they have now suggested a balance of tyres is required	Vehicle has a vibration in the front wheels when driving code 1 at speed of approx 110-115ks	Unknown	-
7-Sep-16	Vehicle	240	Repaired once and blew again later same day	Step fuse breaking	-	-
4-Sep-16	Vehicle	240	Needs panel beater to reattach	Noticed on return to work Sunday 5/9/16. Trim to exterior front passenger door is loose	Suspected related to height of curb and gutter depth in some locations	Has occurred previously. Previous repairs evident and look to have used silastic.??? Needs new clips
4-Sep-16	Vehicle	240	Needs panel beater to reattach	Noticed on return to work Sunday 5/9/16. Trim to exterior front passenger door is loose	Suspected related to height of curb and gutter depth in some locations	Has occurred previously. Previous repairs evident and look to have used silastic.??? Needs new clips
7-Sep-16	Vehicle	235	Fault form	Siren non operational- Stopped working during code 1 case	-	-
7-Sep-16	Vehicle	235	Vehicle out of service and vehicle fault report	Opened side door for vehicle check and O2 t-piece fell out; appears to have snapped off. T-piece sitting on drivers seat.	Unknown; fell out when opening door	-
8-Sep-16	Vehicle	230	problem has been reported and vehicle has been placed OOS and non-operational	Developed a shudder whilst responding to that caused a vibration throughout the vehicle, similar to previously reported also noted burnt oil odour was smelt around the front of the vehicle and the vibration was present during the return trip.	-	-
8-Sep-16	Vehicle	210	Nil	Stow bar on right side has been bent , door is closing but alarm is sounding that door is open	Unknown - found like this	-
8-Sep-16	Vehicle	245	Fault form submitted, vehicle placed out of service temporarily	MDT not functioning	-	-
8-Sep-16	Vehicle	235	-	As previous - Car engine now struggles to turn over on ignition, but also now cutting out completely during low gears whilst driving - worst over cold night shifts. L) parker light now out. AM/FM radio did work for 2 days, now on/off again.	-	It seems engine issue is the same as previous fault form - but worse.

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
7-Sep-16	Defibrillator	225	-	Pt was monitored through defib pads showing rhythm. All limb and chest leads were placed for 12 lead ECG but after pressing D-ECG, no rhythms in any lead would show on the screen. Pt could only be monitored through pads. Leads were working prior to this.	-	Monitor left in care of OIC. Reported fault with
8-Sep-16	Vehicle	240	OCS notified; Samford staff notified that car 'off road'.	Primarily-main battery has failed. Progressively more difficult to start - whether it has been left on continuous charge or on-call at home. Yesterday I had to resort to using the AUX battery This morning -MAJOR problems starting on AUX battery	Other - MDT failure.	Descriptive photo (MDT error message) emailed to QAS Workshop Brisbane
8-Sep-16	Vehicle	230	The crew advises this fault has been reported many times prior to this incident, however fault is recurring	Faulty MDT/ SIGTEC Brand the unit shuts itself off, then reboots itself, appears to have an intermittent connection fault, crew advises this occurs on almost every case they attend, crew advises MDT loses all data including GPS	unknown	Crew advises intermitent use that is not reliable. Frequently shuts off.
8-Sep-16	Vehicle	205	-	Main radio screen periodically goes completely black on start up, does not effect function, just unable to read screen. Unable to see channel selected. If turn radio off then back on, sometimes rectifies issue.	unknown	-
8-Sep-16	Vehicle	215	Oic, fault form . Sos informed ,fleet officer informed and now oic has informed mechanic	Windscreen damage	truck driving south flung stone up hitting windscreen	-
8-Sep-16	Vehicle	250	Reported	Drivers side driving light not working. Map reading light not working.	-	-
8-Sep-16	Vehicle	225	-	Little red ball with silver pin that locks stretcher to floor of vehicle is missing. Unable to secure stretcher	-	-
8-Sep-16	Vehicle	235	QAS mechanic notified - advised take vehicle back to station (Redbank) and put out of service. OCS notified. OIC notified. Vehicle put out of service. Fault form completed.	Engine light flashing; vehicle revving excessively, slow to pick up speed	-	-
15-Aug-16	Defibrillator	225	Corpuls3 is now out of service	AED analyse function fault, nil record of analysis	-	-
8-Sep-16	Vehicle	215	Notified OIC +	Noticed to have windscreen chip. ?occurance	probably a rock or ?UFO	-
8-Sep-16	Vehicle	185	-	Air con in rear cabin not cold. Uncomfortable for pts. Also, GPS not working.	-	We are aware of the air con fault. This unit is booked into on Monday 12/9/16 to have a new air con compressor fitted. It can then go to for GPS. V 4879 job authroity already allocated.
8-Sep-16	Vehicle	250	Nil	Passenger side sliding door is sticking when used , door also appears loose when fully open	Unknowen	-
8-Sep-16	Vehicle	245	As above and fault form taped to drivers side door	MDT not operational	Unknown was working fine yesterday and logged off at midnight without any issues	-
8-Sep-16	Vehicle	200	Fault report lodged	Air conditioner unit in the back is leaking rusty coloured water onto the ceiling of the rear cabin	-	Photos attached to vehicle checklist
8-Sep-16	Vehicle	235	-	Stryker power stretcher will not unload from unit device.	-	-
8-Sep-16	Vehicle	240	Attempt to fill tyre up again, ROC informed	Tyre pressure fault; emergency alarm came on indicating low tyre pressure in front left. Refilled at service station as per ROC, not maintaining pressure ? Leak	-	-
8-Sep-16	Vehicle	250	Removed from vehicle	Wall mount airway kit	Unknown	Fault form and note left for OIC
9-Sep-16	Vehicle	250	Notified roc	Nail in front right tyre	-	Vehicle repaired by Nathan Station

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
9-Sep-16	Defibrillator	240	-	CF card full	-	-
9-Sep-16	Vehicle	195	-	The coolant light remains on. Audible alarm, no obvious lack of coolant.	-	-
6-Sep-16	Vehicle	185	-	Dent to the left side edge of roof above the side access door. There is no penetration or crack through the roof.	vehicle was being parked and contact was made with eve of parking shed.	SHE report & Insurance Claim to be submitted, assessed & authorised. Will be updated when panel repairs have been carried out.
9-Sep-16	Vehicle	185	Booked into for replacement	Damage to Near Side wing mirror - main mirror glass missing	contact with post at side of road whilst driving	small mirror at bottom of unit still present so realigned to us for drive back. Officer to submit SHE & insurance claim. THIS REPORT WAS ENTERED INCORRECTLY - WRONG UN IT NUMBER.
9-Sep-16	Vehicle	185	booked into for replacement	Damage to main glass in near side wing mirror	whilst pulling over to side of road, i caught the near side wing mirror on a post causing the glass to pop out and smash on ground	small mirror in unit still in situ so realigned to enable vehilce to be driven back to station
9-Sep-16	Vehicle	240	Reported	Rear patient care seat pre tensioner prevents seatbelt being pulled out	Unknown	as per unit design of seat. Seatbelt retratcs with change in movement of seat recliner - operational.
9-Sep-16	Vehicle	240	Reported	Side step doesn't work	Unknown	-
9-Sep-16	Vehicle	240	Reported	Car radios (am/fm) not working	Unknown	-
8-Sep-16	Vehicle	225	Repaired.	Cracked windscreen due to stone chip.	Passing truck flicked up a rock off the road.	-
9-Sep-16	Defibrillator	230	Multiple attempts at checking electrode dot connection, re-seating cable to Pt care box, disconnect/reconnect seperate modules. ECG trace was recorded after disconnecting SP02 cable. Corpulse passed shift checks after returning to station.	ECG failed to receive data from electrodes	Unknown, Corpuls passed daily checks at 1000 before failing on first job at 1030. Copy of Start of shift printout emailed to OIC.	This monitor currently has previously reported faulty SP02 cable (monitor cable not probe) from DEFIB0752 to reduce OOS corpuls numbers. Defib at Beerwah OIC office. Disp. Unit S/N: 15601956 Pt box S/N:15701768 Defib S/N:158514830
9-Sep-16	Vehicle	245	-	'Passenger' side stretcher locking mechanism is becoming increasingly stiff and difficult to locate/lock when a pt is on stretcher. Needs a firm 'shove' to ensure it locks in place.	-	Crew try and utilise 'drivers' side stretcher as often as possible to ensure pt comfort and ease of loading
9-Sep-16	Vehicle	210	-	GPS not remaining on when vehicle is in use. Reports battery not charged when trying to use.	-	-
9-Sep-16	Vehicle	210	-	Also side step used on 270kg patient may need assessing.	-	-
9-Sep-16	Defibrillator	240	Checked attachment. Replaced electrodes.	Error therapy electrodes loose	-	-
9-Sep-16	Vehicle	215	-	Garmin will not hold charge and torches in front are flat	-	-
9-Sep-16	Defibrillator	225	Test dump attempted and failed. SOS and COMMS notified.	Defibrillator alarm on screen. Failed test dump.	? Tipped forwards onto floor on job.	-
9-Sep-16	Vehicle	240	Both a different cable and new power source was attached and vehicle still not charging. OCS notified.	Vehicle not charging and battery not holding charge.	plugged vehicle in on return to station and sparks and smoke came from power chord at vehicle end. Orange charging light initially came on and then went out.	Vehicle located at North lakes station. Unable to be operational due to vehicle not charging together with battery not holding charge through out the day (noted in vehicle check list).
9-Sep-16	Vehicle	215	-	Main battery low ..??. Not charging Emergency start required initially to turn on Comms radio unit ... Car radio not working main power intermittently turning off ... Even after driving and with charging lead connected	-	-
10-Sep-16	Vehicle	235	-	Fuel cap broken. Does not lock into place	? Noticed when re-fuelling	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
8-Sep-16	Vehicle	250	Possibly fix CV joint	Front right wheel area clinking when turning and in operations.	-	-
9-Sep-16	Vehicle	210	Reported	Air Conditioning in front of unit unservicable	N/A	Vehicle would only be suitable for local work
8-Sep-16	Vehicle	200	OIC inspected area when reported	R rear yellow reflector unit broken, plastic moulding same area scratched/broken	gate opening with reduced width	Rear of veh within property boundary due to having to reverse same because of limited space with in property and if not reversed in vehicle would be nose front on to main road due to location of property,
10-Sep-16	Other Equipment	215	Non/ this report and email to OIC	Left headlight out. Only one touch in truck	-	-
10-Sep-16	-	235	Turned MDT off for 30sec and on again using main switch behind drivers side door. Ensured all cables at rear of MDT plugged in.	MDT GPS Not Tracking	-	SE Comms CCS advised to change to alternate vehicle and implied to only use as last option.
10-Sep-16	Vehicle	240	-	Whilst travelling code 1 on our third job of the day the MDT stopped working, when trying to contact control via the radio that was not working, then the siren stopped. A similar event happen on tuesday 6th. I have no idea of the outcome.	? charging problem.	-
10-Sep-16	Defibrillator	235	Leads have been taken off corpuls and new leads have been attached. Broken leads have been placed outside OIC office at Ipswich. The new leads have been taken from the SOS' car under his instructions.	4 Lead cable broke when loading a patient. LL lead got stuck between stretcher and the ambulance when loading causing it to crack and not work properly.	-	-
10-Sep-16	Vehicle	230	Parked at Noosa Station, Non Operational sign placed on vehicle	Vehicle engine light illuminated on the dash and vehicle has gone into LIMP Mode	Engine Fault	-
10-Sep-16	Vehicle	245	Attempted reboot of MDT w/switch, however screen remains frozen on (even with MDT switch in off position). ROC notified, crew advised to change vehicles.	MDT screen frozen, unresponsive.	-	-
11-Sep-16	Vehicle	245	-	MDT needs to constantly reset during start of shift as is not connecting... May be result of dead spot in plant room or fault? Needs to be looked at	-	2 broken mets to be reviewed at station on Monday should look at this one as well as dose not start on shift until 11
11-Sep-16	Vehicle	210	motor vehicle accident claim form has been completed	Damage to rear back step	accidentally reversed into bollard at QPS station while on a job	-
10-Sep-16	Vehicle	240	RACQ attended jump started and connected to power over night at home station	flat battery	Vehicle unattended at Ningi station to respond code1 in 4x4 station which has no parking bays with power charge to connect to	needs battery check and connect defib MDT to master switch that radio is connected to !

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
11-Sep-16	Vehicle	230	-	Intermittent fault. Side step, not completely extending, slow to retract.	Unknown	-
10-Sep-16	Stretcher	185	Note has been placed on stretcher in question, noted in work diary, OIC informed, SHE report will be filed	Extendable stretcher handle> front of stretcher. Jammed in extended position	Front legs did not lock in when removing stretcher from car at hospital> weight on extendable arm caused fault	A/OIC Tully to arrange for stretcher to be dropped at [redacted] for inspection/repair. I have logged a job with [redacted] refers
11-Sep-16	Vehicle	200	Reported fault	Steering wheel vibrates at speed (100km/hr). Car also wants to veer to the left.	Unknown	-
11-Sep-16	Vehicle	200	none	Engine management light fault flashes	came on while driving	-
11-Sep-16	Vehicle	245	Plugged in to charge batteries	Flat batteries not plugged in	Flat batteries 6.9 volts	-
11-Sep-16	Vehicle	240	Notify SOS.	Damage to front beacon of ambulance.	Collision with roller door.	Extensive damage to front beacon.
10-Sep-16	Defibrillator	215	New sensor/cord tried with nil success.	SpO2 not reading/sensing.	?	-
11-Sep-16	Vehicle	235	-	Drivers side lowbeam headlight is out. MDT keeps flickering colours causing distraction and difficulty reading.	-	-
12-Sep-16	Vehicle	185	Notified OIC	Back R) tyre flat	?	Officer [redacted] to cancel this fault report & resubmit with the correct odometer reading.
12-Sep-16	Vehicle	200	-	Right driver side front driving light not working. Very dangerous driving at night. This is the night operational car. Check angle of left front driving light.	light bulb blown.	-
12-Sep-16	Vehicle	240	Pressed the override button and tried pulling out the step.	Side step has stopped working	Unknown	-
12-Sep-16	Vehicle	235	nil	L side Parker light globe is blown. Bonnet mount flashing lights not flashing	unknown	-
11-Sep-16	Vehicle	240	OC notified, different power cable plugged in, form completed and crew logged onto different vehicle. Note on vehicle board.	Vehicle won't turn on. Different power cable used and initially started to charge, then checked several hours later and still unable to turn vehicle on or turn key in ignition.	unknown	Unable to get speedo.
11-Sep-16	Vehicle	240	Notified ROC	ESR Fault light on.	-	-
10-Sep-16	Vehicle	225	Mount replaced	Gps unit faulty and not staying on. Mount replaced with nil effect.	-	IPad utilised for navigation
4-Sep-16	Vehicle	230	fault report entered 4/9/2016	Windscreen washer does not work.	-	-
12-Sep-16	Vehicle	215	for repair of headlight	off side headlight u/s fault/tear/rip to drivers seat	normal operation	-
12-Sep-16	Vehicle	235	Fault form	Vehicle suction unit not working, vehicle radio turns off when power to rear module turned on, AED out of date for check, fire extinguisher out of date for check,	Who knows	Vehicle off road
12-Sep-16	Vehicle	210	Put a piece of Velcro on it tote it down	1. R break light not working. 2. L rear tyre pressure low. Did not see a nail or notice obvious reason why it is deflating. 3. Stair chair making noise while driving.	Stair chair foot rest is loose and move back and forth while driving banging against the side of its enclosure.	-
12-Sep-16	Vehicle	215	Fault form written up	L) Headlight appears to be dim. Light is working but when driving at night it is noticable that it is not as bright as the R). Officers reporting that it is difficult to see the L) of road during night time driving.	?	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
12-Sep-16	Vehicle	225	Attempted to tighten the catch but the nutserts have stripped the holes in the module body and bolts cannot be tightened any more.	Rear drivers side barn door sensor broken, causing the door alarm and rear emergency lights to stay on. Also, the catch on the same door is loose. Stretcher had clicked in and green lights presented in order to lift stretcher.	End of the plastic sensor is snapped off, meaning it doesn't contact the door when closed.	-
11-Sep-16	Stretcher	210	Stretcher, placed back down and realigned	Upon lifting stretcher when attached to vehicle over lifted and stretcher was on the wrong angle. When looked further into why noticed arms of lifter in wrong spot.	Arms of lifter not in line	-
12-Sep-16	Vehicle	235	-	Driving along brisbane valley highway - rock flicked up from truck in front causing med-large stone chip in windscreen approx 3cm diameter	rock	-
12-Sep-16	Vehicle	240	Vehicle fault report has been filled and sent	Belt tensioner has let go and has thrown the belt off. The side step is also stuck out	Unknown	-
12-Sep-16	Vehicle	240	OCS notified	Belt Tensioner has let go, side step is stuck out	Unknown was discovered during vehicle check	-
12-Sep-16	Vehicle	200	Reported	Intermittently goes into limp mode - very slow to accelerate. Engine light still flashing.	-	Car is operational - just. Unable to swap vehicles as did not get back to station.
27-Aug-16	Other		connection checked.			
12-Sep-16	Equipment	185	Unable to identify fault	Unit does not appear to charge and is non-operational	unknown	Has been removed from vehicle and given to OIC Cairns. Replacement parts on order from supplier.
12-Sep-16	Vehicle	235	-	R rear tail light not working		-
12-Sep-16	Vehicle	215	Washed large quantity of stones and dirt from tracks	Powered step to passenger compartment fails to open fully	Tracks clogged with stones and dirt	Still does not extend fully.
13-Sep-16	Vehicle	245	Notified roc	Lost transmission won't select gears forward or reverse	Unknown	While travelling along an early road with patient on board transmission started to slip then went into limp mode shut vehicle down restarted vehicle but symptoms became worse to the point lost all forward and reverse gears.
13-Sep-16	Vehicle	215	nothing	UNIT 4405- windscreen chip passenger side	unknown	-
12-Sep-16	Defibrillator	240	CALLED	CF CARD ALMOST FULL	-	-
13-Sep-16	Vehicle	230	OIC and Comms notified	MDT shuts down intermittently, during operation off vehicle and while in standby mode, with or without a case on it.	-	-
13-Sep-16	Vehicle	225	-	Brake wear warning light on, vehicle service	-	-
13-Sep-16	Vehicle	215	Nil	Intermittent fault will emergency switch panel light keep coming on without activation of switch	Maybe earth fault	-
13-Sep-16	Vehicle	230	called to arrange uplift	Back door on 772 sticking at both sides, passenger side worst. Risk of staff injury	Unknown	-
13-Sep-16	Equipment	190	nil action at this time	Head lamp not functioning. E.g will not turn on	unknown	-
13-Sep-16	Vehicle	210	Nil	Belt clip on equipment cabinet at L side sliding door missing	-	-
13-Sep-16	Vehicle	225	have retrieved vehicle and it is at their workshop, SOS have been advised.	Swivel housing bearing mount bolt has sheared off	unknown	Unsure of repair time but they will have it done ASAP
12-Sep-16	General Equipment	215	computer rebooted and attempted to destabilise connection manually	Not connecting to wifi for hospital printer --unable to print earf s	unkown	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
13-Sep-16	Vehicle	225	Unit has been booked in with for the issue to be fixed.	ESP Warning light on dash came on and car taken off road on return to station.	-	-
13-Sep-16	Vehicle	230	Called into , they state A/C has a leak somewhere that needs to be fixed, they have re gassed it for now for a temporary fix, although needs to be booked back in	Air Cond not working	no gas due to a leak somewhere	-
13-Sep-16	Vehicle	210	Nil	Nail in tyre	Unknown	-
13-Sep-16	Vehicle	210	Nil	Nail in tyre	Unknown	-
12-Sep-16	Vehicle	235	Taken off road for repair.	Driver's side rear ambulance door impacted with tree.	Tree.	-
12-Sep-16	Vehicle	235	Taken off road for repair.	Driver's side rear ambulance door impacted with tree.	Tree.	-
14-Sep-16	Vehicle	185	Reported to coordinator operational readiness,	Intermittent fault with side step opening when side door opened.	General wear and tear.	OIC taking unit to this morning for inspection/repair. V 4917.
14-Sep-16	Defibrillator	235	-	Spo2 faulty	-	Outside OIC office
14-Sep-16	Vehicle	195	Spoke to local mechanic who stated R) rear work light would probably have to be replaced.	R) rear work light not illuminating properly ? several bulbs not working R) back door arm/chock broken off Unknown when or how either fault occurred, was not reported.	-	Pictures attached to today's vehicle checklist
14-Sep-16	Vehicle	195	-	Front R) park light cover has larger piece missing/broken Unknown when or how	-	Picture attached to today's vehicle checklist
14-Sep-16	Vehicle	215	-	Squeaking noise in front end suspension	-	-
14-Sep-16	Vehicle	210	-	Front left tyre has porcupine needles in it. Photo attached above	-	-
14-Sep-16	Vehicle	240	Await repair	Rear step bent. L headlight out, ? Inverter fault. Would not operate neocot through the powerpoint	Unknown	Damage not sustained on our shift, simply reporting upon identification of fault Taken to for review and repair and also programming of key as ordered last service.
13-Sep-16	Vehicle	240	Field	-	-	-
14-Sep-16	Defibrillator	240	service	CF card almost full	-	-
14-Sep-16	Defibrillator	240	-	CF card almost full	-	-
14-Sep-16	Defibrillator	240	-	Cf card almost full	-	-
8-Sep-16	Vehicle	240	The only damage that can be repaired is a small 1 inch piece taken out of the yellow paint work for the rear bumper bar. The rest of the damage is scratches	There is 2 adjacent parking bays ONLY for the large IHT vehicles to reverse park at the Pts. area of Royal Brisbane. Both bays require the vehicle to be parked within inches of a vertical concrete column adjacent to the rear of the vehicle.	After loading 2 Pts for transport I inadvertently commenced my turn to exit too early causing the last few inches to scrap the concrete column	-
14-Sep-16	Vehicle	185	Nil	No electrical output from the 240V inverter	unknown	Identified by electrician when testing the safety switch in the ambulance vehicle. States that it is likely the inverter. Vehicle booked into 16/9/16. V 4920.

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
14-Sep-16	Vehicle	210	Spare corpulse replaced into vehicle. OIC and SOS notified.	Corpulse not printing.	Whilst in transport the monitor fell out of the cradle. When picked up it was noted that the printer cartridge/paper had fallen out. After replacing the paper it did not print.	-
14-Sep-16	Vehicle	200	contacted mechanic	Windscreen wiper blade fell off	unknown	All action completed
14-Sep-16	Defibrillator	230	OIC notified.	During routine pre shift check, defibrillator did not discharge shock to test unit (connected correctly, charged up prior to failing). Charge cancelled, then retried. Successful discharge x 3 after this.	Unknown.	-
14-Sep-16	Vehicle	250	Nil	Damage dint to Left front guard	Driver error reversing and turning in confined environment.	-
14-Sep-16	Vehicle	210	fault form entered	Stone chip and separate crack to windscreen	Unknown found start of shift on 14/09	-
13-Sep-16	Other Equipment	185	Replace poer cable.	USB Power cable to Hema Mapping unit broken, with 'male' connection broken away from the cable and located within the mapping unit.	It appears the power cable is not long enough and over time has become bent over and then broken under the pressure.	OIC had indicated he would like the local auto electrician to assess and replace this fault. Replacement charger to be purchased by RRC 15/9/16.
14-Sep-16	Defibrillator	245	-	Sats probe and v1-6 leads damaged. Leads were pulled out of machine damaging the connection pins of leads and possibly the female plug in the main machine.	Patient drug affected and tangled the leads while writhing around on the bed.	-
14-Sep-16	Vehicle	195	Attempted manual levers, changed battery, manually lifting stretcher, nil worked.	Stretcher stuck/locked down half way out. Unable to use manual levers to disengage.	-	-
14-Sep-16	Vehicle	200	Side step able to be pulled back in as to not be a danger to staff and public.	Side step function on side patient compartment door not working when door is opened. Originally stuck in 'out' position, but was able to be brought back in by internal wiring switch.	Unsure of what caused fault.	-
14-Sep-16	Vehicle	235	noted on vehicle checklists and fault forms. Awaiting fleet tech to facilitate repair.	Left side tail light globe is blown. Reported previously on checklist and fault forms. Not yet actioned.	blown light globe I suspect.	-
14-Sep-16	Defibrillator	250	Printer strip on defib cleaned. Printing normally. Back in service	Corpulse printer faulty. Only printing on half the width of paper. Taken out of service due to not able to read ECGs.	-	-
15-Sep-16	Vehicle	235	-	Vehicle stalls when in idle	-	-
13-Sep-16	Vehicle	225	#NAME?	#NAME?	-	-
14-Sep-16	Vehicle	215	-	Main communications radio switched off while on a job and will not switch on	-	-
15-Sep-16	Vehicle	230	Test	Test to see if recieve the email	-	emails that are forwarded from this app to are not being recieved.
15-Sep-16	Vehicle	230	-	Test to see if email will forward	-	-
15-Sep-16	Vehicle	230	-	Test another email address	-	-
15-Sep-16	Vehicle	230	-	Testing email to	-	-
15-Sep-16	Vehicle	210	reported	Air con is not working	not known	-
15-Sep-16	Vehicle	230	-	Testing email forward to	-	-
15-Sep-16	Vehicle	205	unable to rectify, needs to be re-installed	Front windscreen that was just replaced leaks water. Water leaks onto radio and dash.	poor windscreen install	1 vehicle on station, upon return of second vehicle this unit 2343 should be made unoperational.

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
1-Sep-16	General Equipment	225	eARF notified on the 1st September 2016 by A/OIC at Millmerran. eARF support advised that a replacement would be sent but not currently available and to continue to use. Faults still occurring with toughbook. step has been electrically disconnected by Auto Electrician	multiple faults with blue screen error and mutiple error messages after sync occurs	Unknown cause	email sent on the 15th September 2016 to eARF support for update regarding replacement.
15-Sep-16	Vehicle	185	Left at cairns stn awaiting repair by	Broken side step to vehicle	mechanical failure of plastic fitting which holds step in place	Requires a new replacement step fitted. V 4932 (please note: step was repaired/replaced by on 9/5/16)
15-Sep-16	Vehicle	185	Attempted to turn off using power button on head unit - nothing happened. Turned MDT power switch located in the right side door off/on - nothing happened. Screen still showing the same message. Drove to	Rear A/C u/s, display flashing 'HP'	-	V 4921.
15-Sep-16	Vehicle	230	unable to fix.	MDT stopped working and displayed "Reboot and select proper boot device or insert boot media in selected boot device and press a key" on a blank screen.	-	CDS contacted by phone and advised to return to station and swap into another vehicle.
8-Sep-16	Vehicle	225	NIL	FAULTY LEFT ALLEY LIGHT.	NIL	-
15-Sep-16	Vehicle	240	multiple times the vehicle has been shut down and restarted removing the key, the warning light is refractory despite these measures	Whilst proceeding code 1 to case the engine light activated and the vehicle lost power.	Unknown	-
15-Sep-16	Defibrillator	245	Rechecked machine, machine restarted, errors occurring several jobs apart	Printed obs with date set to 1970 and times different to actual. When machine time checked it was correct. Pressed D-ECG while monitoring lead II, showed nil trace all leads, exited D-ECG, trace lead II normal, repeated several times to confirm error.	-	-
15-Sep-16	Vehicle	240	None	Damage to lower hinge of passenger-side rear door and door / facia damage	Large 4x4 drove into back while vehicle stationary at roundabout	The vehicle is fine to drive, but repeated opening of passenger-side rear door is likely to break / dislodge light cluster.
16-Sep-16	Vehicle	240	Comms advised and we were returned to station to change vehicles.	Beacons on top of the vehicle in front only operate when vehicle lights are on and the beacons are not switched on. Unable to switch the beacons off.	Possible water in the relay which operates the headlight flash mechanism (had been raining prior to the fault).	-
16-Sep-16	Vehicle	230	CDS & Duty OIC notified	Overwhelming smell of burnt electricals within truck cabin	unknown	-
16-Sep-16	Vehicle	195	Advised OIC.	Rear compartment fridge not working	Unknown	Nil
16-Sep-16	Vehicle	240	None	Side step not working	Unknown	-
16-Sep-16	Vehicle	195	Advised OIC	Right rear lower emergency light not working	unknown	nil

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
16-Sep-16	General Equipment	230	-	Initial computer fault, now not turning on	-	Rainbow Beach V 4934 Reg 249 VDC
16-Sep-16	Vehicle	195	Temporary solution has been engineered with suction hose creating a good seal and suction strength.	Hose from vehicle wall to the red/white plastic bracket of the suction has deteriorated and has a poor seal. resulting in decreased suction.	Unknown. ? perished plastic or poor initial fitting	-
16-Sep-16	Vehicle	250	-	Car not starting	-	-
16-Sep-16	Stretcher	210	stretcher taken off road.	After pt was loaded onto the stretcher, Officers proceeded to raise the pt up each end at a time. As officers raised foot end, head end of stretcher dropped a click with pt loaded. Nil complaint from pt.	-	-
15-Sep-16	Vehicle	225	Needs to be repaired by panel beater	Damage to fiberglass housing of rear high light bar	Backed into pole - single officer and misjudged distance -raining and at night so little help from camera or mirrors - misjudged the light bar overhang compared to rear of vehicle	-
16-Sep-16	Vehicle	235	advised management with this form	Two stone chips in windscreen	properly stones	-
16-Sep-16	Vehicle	240	Advised OIC	Reversing camera failed	-	-
15-Sep-16	Stretcher	190	used station replacement	Front legs are stuck and won't extend	-	Found by officer during a case. She Report number - 0064889 Fault was able to to be repaired during annual service of medical equipment.
16-Sep-16	Vehicle	210	Notified SOS, OCS, completed vehicle fault, completed she report. Completed check of mirror and indicator still operational	Scuff mark to Right side mirror, nil breakages, glass not broken	During code 1 response whilst merging into turning lane car towing caravan has applied the breaks suddenly, mirror hitting side of caravan	-
17-Sep-16	Defibrillator	240	Tried different charging docks in other cars, attempted to charge through wall charger, took apart and put together multiple times, removed stuff from bags to see if it was causing a bad connection, turned on and off.	Not charging	-	This cor pulse was not put together properly therefore not Charging - corrected
17-Sep-16	Vehicle	215	CCS advised.	Main battery failure - will not start vehicle	.?flat/faulty main battery. Did not charge during night shift.	-
17-Sep-16	General Equipment	250	Equipment taken out of service and left with OIC of station	Pulse oximetry cable (Corpuls end) found to be defective on vehicle check at start of shift	Unknown	-
17-Sep-16	Other Equipment	210	-	mobile radios dont work	-	-
16-Sep-16	Vehicle	250	Towed to Robina hospital and TYRE. Changed to spare	Front right tyre puncture	Motorway debris on shoulder of road	Tyre on spare requires exchange
17-Sep-16	Vehicle	245	RACQ called for tow	Fan belt	Slipping belt	-
17-Sep-16	Vehicle	230	-	Side step U/S not going in/out automatically	-	Vehicle has been repaired at

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
17-Sep-16	Vehicle	200	Fault reported by 25.6.17 and also noted on checklists at times. Vehicle still not repaired.	Engine light and glow plug light on dash	need to replace glow plugs	-
17-Sep-16	Other Equipment	185	taken out of service, one other handheld still available to crew	handheld radio not transmitting or receiving, nil cell calls heard throughout day	unknown	OIC to log job with . OIC fixed problem at Station.
17-Sep-16	Vehicle	210	Reported to SOS & CCS	Patient care seat fails/broken	-	-
17-Sep-16	Defibrillator	240	Attempted to hold down the ON button, the Corpuls proceeded to give a single flash of red on the home button, then returned to having a green light with a black screen and did not turn off.	Monitor appears that it is on with the second green light appearing, however the monitor screen is black and shows nothing appearing on the screen. Monitor will not turn off.	Unknown	Corpuls from 501226
17-Sep-16	Vehicle	215	Contacted CDS.	Battery fault. All internal electrics turn off after engine turned off. Slow to come back after starting if it starts	??Battery	-
17-Sep-16	Vehicle	225	This officer rostered on day shift Monday 19/9, will confer w OIC for attending to top up at service provider.	Oil level is well below minimum, barely showing on dipstick. Top-up required urgently.	-	-
17-Sep-16	Vehicle	240	Car taken out of service and operations supervisor and QPS notified. Statements from officers given to QPS for police report she report to be completed on return to station	Broken windscreen wiper on drivers side after a resident at a boarding house caused damage to the vehicle	Wilful damage from a resident at	Operations supervisor on scene with QPS. Constable from city station (Charlotte street) ph number; () officer who took statements from officers
18-Sep-16	Vehicle	190	-	Copious water coming through air con vent on roof in rear cabin	Rainy weather - only in rain for short period before leakage began	-
9-Sep-16	Stair Chair	230	Reported	Ankle strap missing	Unknown	Have stated this is operational - but it is a hazard due to pts feet not being controlled. As there is no spare stair chair it cannot be removed from service
18-Sep-16	Vehicle	210	Logged with system support through BOSS	Frayed wire in main radio handset. Handset not working - keypad not working, and not allowing transmission.	Wear and tear. Has been on the way out for a while and have just been waiting for it to be checked during routine servicing.	-
18-Sep-16	Vehicle	225	-	Drivers seat back adjusting knob missing	-	-

RTI RELEASE

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
17-Sep-16	General Equipment	225	Informed OIC . A non QAS sat Nav is currently in car and informed there are manual maps but if a sat Nav is in in a vehicle and it does not show correct route and it shows you are on a certain road and does not change reroute until to late you are unaware	QAS GPS does not allow any input into screen ?Nil sat connection. Inspection of connections of wires they are lose, no difference when moving them. This has happened before. There is a non QAS sat Nav in car does not always give best road type route to go.	Wires lose and ill fitting to back of sat Nav. Hc of same.	-
18-Sep-16	Vehicle	185	-	4 x faults. 1)Siren not working correctly. 2)Air con leaking water in rear cabin. 3)Engine warning light on. 4)"Door open" alarm faulty.	-	- V4937 - - V4801
18-Sep-16	Vehicle	225	Nil	Reversing camera assembly has been damaged and is loose. Camera bracket is bent, though camera still functional.	Unknown	-
18-Sep-16	Defibrillator	225	1. Leads checked at plug in point on the machine. 2. Machine restarted. 3. Dots replaced on patient. 4. Machine turned off for approx 5 minutes. After this ecg worked ok.	Ecg limb leads not picking up a trace on patient. Also has very slow CF Card and sometimes shows an unavailable	-	Equipment removed from service pending check.
18-Sep-16	Vehicle	195	SOS informed,marked out of service	Engine light flashing	unknown	-
17-Sep-16	Vehicle	240	-	Side step on vehicle not working.	-	-
18-Sep-16	Vehicle	225	RACQ contacted by OpCen and vehcile placed on charge via extension cord.	Unable to Start - Flat Battery	Vehcile had not been put on charge after being out local (sitting for 4hrs). Radio and mains had been turned off inside unit.	1510: attended and tested battery - passed, alternator charge passed.. Was working earlier in the day. Aircon in rear compartment still working. V4936.
18-Sep-16	Vehicle	185	nothing	Air conditioner not working	unknown	-
18-Sep-16	Vehicle	200	Vehicle sent back to dealer for maintenance	Engine maintenance light is flashing and vehicle in limp mode. Tried turning the car off and on again twice but continued to stay in limp mode.	-	-
19-Sep-16	Vehicle	225	On confirmation from OIC, vehicle to be taken to service agent today if possible, for filling.	Requires oil as noted previously.	-	-
17-Sep-16	Vehicle	215	Fault report completed.	Vehicle shakes when starting and driving.	Unknown.	-
19-Sep-16	Vehicle	225	Nil	12 volt charging socket in front centre console has fallen down inside the console. Unable to see the socket, so not sure if it will cause a short that will blow a circuit breaker/ fuse. Unable to charge to E/ARF Toughbook.	-	-
19-Sep-16	Vehicle	225	-	Brake pad fault light intermittently appearing. Service due	-	OIC notified
19-Sep-16	Vehicle	245	-	Corpuls was dropped in the ED department during transfer between our stretcher and Resus bed. The clips that connect the defibrillator and screen of the monitor have broken off.	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
19-Sep-16	Vehicle	225	Filled out fault report to generate email for car to be serviced.	Service interval is overdue by 2630 ks so will need to be booked into	-	-
17-Sep-16	General Equipment	195	-	GPS not working	-	-
19-Sep-16	Defibrillator	245	Taken out of sevice	Intermittent fault we the ecg tracing. Nil damage to leads noted. Whilst monitoring pt Ecg would intermittently display. Also does not appear to be recording info to SD card. Case number 8012167	-	She report completed
19-Sep-16	Vehicle	210	SOS notified and stretcher swapped out.	Red lever on head end of stretcher will not always engage unless leg end has been lowered first. Fault intermittent.	-	Defected stretcher serial number: 141141310 (Top and bottom) QCR: QNR04704
19-Sep-16	Vehicle	230	Vehicle jump started each time. Will be taken to this afternoon to have battery inspected. Mains switched off when vehicle not in use but still going flat.	Flat battery. Vehicle has had to be jump started using jump pack 3x over previous 2 days.	-	-
19-Sep-16	Vehicle	215	this fault report	blue emergency lights not operating correctly. Only one touch in truck	-	-
19-Sep-16	Vehicle	235	fault report completed	Seat belt on attendant seat (behind drivers seat, in patient care compartment) won't retract	-	-
19-Sep-16	Vehicle	235	-	Rear A/C not working at all. Stopped working during shift.	-	Nil air conditioning or heater in rear patient care area.
18-Sep-16	Vehicle	205	mechanic contacted. has picked up vehicle for repair.	Vehicle tire noted to be flat, refilled - flat within 4 hrs	-	-
17-Sep-16	Vehicle	205	-	Large amount of water appears to be coming internally from airconditioning unit vent and running onto stored equipment following rainfall.	?fault with airconditioning unit	Operational unless moderate - heavy rainfall.
19-Sep-16	Vehicle	210	-	Front Driver's Side headlight non-operational. Parker light operational. Possibly blown globe.	Unknown	-
20-Sep-16	Vehicle	230	none - it can't be opened.	Rear door does not open.	Unknown	Catch on L side of door not releasing.
16-Sep-16	Vehicle	185	VEHICLE WAS DRIVEN BACK TO CAIRNS STATION	VEHICLE BECAME FAULTY WHILST DRIVING ON KURANDA RANGE. VEHICLE WOULD NOT ACCELERATE BEYOND 40KM/H AND RED ENGINE LIGHT APPEARED.	UNKNOWN	SOS WAS NOTIFIED. Engine in LIMP mode. Vehicle towed to 19/09/2016 V4939.
20-Sep-16	Vehicle	250	Removed from service. Shock hazard.	240 V charger has broken plug.	?	Reported to OIC.
20-Sep-16	Vehicle	230	Vehicle has been changed to a 1A	Unable to select corpulse in vehicle check	-	-
20-Sep-16	Vehicle	235	-	When starting, MDT has black screen. Unable to work, says press 'any key' with no response	-	-
20-Sep-16	Defibrillator	210	Will notify OIC	Extension cable from the machine is faulty and will not read the SPO2 readings	Unknown	-
20-Sep-16	Vehicle	230	notified	Car was driver out of station, chugged then stalled. Not starting	Unknown	-
20-Sep-16	Vehicle	230	Vehicle at for rectification	Vehicle in limp home mode	-	-
20-Sep-16	Vehicle	230	Taken to	Vehicle engine warning light on. Vehicle in limp mode	-	-
20-Sep-16	Vehicle	240	Reported to OIC. Called into to order part.	Clear indicator panel on drivers side mirror.	Opening door in confined space. Accidentally hit brick building.	Excess removed and tape applied. Indicator still works.

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
20-Sep-16	Vehicle	225	Reported to Comms, OIC and taken immediately to mechanic who determined a Diesel Partial Pressure Sensor is required. Vehicle is still operational awaiting arrival of part.	Engine light flashing on dash. ESP light is still intermittently illuminating - reported previously via paper copy.	-	-
20-Sep-16	Vehicle	245	-	When driving there is a smell of petrol fumes in the driving cabin	-	OIC AWARE, vehicle being taken off road and sent to workshop tomorrow.
20-Sep-16	Vehicle	240	car towed after incident, unable to drive	Left tyre popped, left side mirror smashed Cradle charger for defibrillator is not charging under any circumstances (engine off/engine on, master switch on/off). Defibrillator would not charge all day despite vehicle engine going for several hours. ? Fault with charger connected to vehicle mains	Car merged in front of Ambulance mid intersection forcing ambulance to swerve onto gutter, hitting traffic light pole.	Unit is back into service
20-Sep-16	Vehicle	240	Unknown. Electrical inspection. vehicle turned off and back on again - no improvement.	While driving code 1, engine light came on and started flashing, and engine power reduced to 75%.	Unknown	Removing Defib off vehicle overnight to manually charge.
20-Sep-16	Vehicle	240	-	MDT won't connect. Says on screen "testing link to modem"	unknown	Was able to transport pt nil issues.
20-Sep-16	Vehicle	210	-	Limp mode while driving	-	SENT TO WORKSHOPS AND OPERATIONAL AS OF THE 04/10/2016
20-Sep-16	Vehicle	225	West star motors to investigate.	Rear air conditioning no air coming from the vents when turned on, can hear the AC unit running.	? When	-
21-Sep-16	Vehicle	240	Attempted to power up numerous times, Master Switch turned on	Load light not working	had it apart last.	-
21-Sep-16	General Equipment	225	Report to	GWN radio in unit 3201 will not power up	Unknown	Went and checked vehicle. Turned radio on as normal. No power issues. No further action required.
21-Sep-16	Vehicle	240	Report to	REversing Alarm not working.	-	-
21-Sep-16	Vehicle	210	car taken off road and supervisor/ Comms notified, fault form completed	Sudden Continuous alarm indicating low water and light on dashboard however coolant level normal	-	-
21-Sep-16	Vehicle	215	Sos and Cs informed	Suspect alternator failure	Multiple water crossing poor design location of alternator	-
21-Sep-16	Vehicle	215	CDs and Cs notified unit to be driven off island in daylight hours	Engine fault light illuminated on dash whilst engine running	Poor design location of alternator	-
21-Sep-16	Vehicle	230	Report	Shake on heavy braking, shake in front at speed	Multiple water crossing	-
21-Sep-16	General Equipment	245	-	frayed cable, not charging.	-	-
21-Sep-16	Vehicle	225	New scan light fitted	Rear top drivers side scan broken	due hitting pole on station	-
21-Sep-16	Defibrillator	210	Removed from vehicle, notified OIC, default form applied to defibrillator	Whilst monitoring the patient, pacing spikes began appearing on the tracing. Pt does not have a pacemaker. Printout of this was gained but not full the full time it was occurring	Unknown	-
20-Sep-16	Vehicle	245	-	Radio clip broken	unknown, was broken at commencement of shift.	Radio clip for vehicle radio on centre console broken - bottom screw missing
21-Sep-16	Vehicle	240	OIC Organised repair on 22nd Sept 16	No headlights	-	Headlights working at start of shift. Noticed once darkness took that no low beams

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
21-Sep-16	Vehicle	230	attended. Vehicle started immediately with jump start.	Flat battery	Unsure. Vehicle was perfectly operational all day prior.	tested charge whilst running and stated the vehicle was charging adequately.
21-Sep-16	Vehicle	250	nil	Engine makes a "ticking" noise when idling.	unsure, just happened throughout the shift	-
22-Sep-16	Vehicle	195	Vehicle has been plugged into a power source	Vehicle has flat batteries	Vehicle was left unplugged	-
21-Sep-16	Vehicle	215	Completed fault report	Pt care seatbelt not working correctly. Unable to pull seat belt out	Unknown	-
22-Sep-16	Vehicle	250	nil	Master control switch for the lights, beacon etc, not working in the rear near the back door right side. Front control panel working fine.	Unknown	-
22-Sep-16	Vehicle	190	No	Mine cap lamp U/S	Unknown	Only 1 lamp operational
22-Sep-16	Vehicle	225	contacted and attended. Battery tested and failed test. Battery replaced.	Vehicle wouldn't start, flat battery.	Battery failed roadside testing.	Battery still under Warranty, battery to be returned to for testing.
22-Sep-16	Vehicle	210	Fleet manager and contacted to rectify fault by jump start Unit 2505.	Flat battery, car not starting	-	Fleet manager confirmed Unit 2505 taken to for battery to be charged.
21-Sep-16	Vehicle	210	-	Aerial cable needs checking / servicing to X band.	-	-
22-Sep-16	Vehicle	240	removed tyre and replaced with spare	Flat driver rear tyre	screw	-
22-Sep-16	Vehicle	240	Previously reported	3x star chips in windscreen as per photos attached to vehicle checklist	Stone chips in traffic. Possible deterioration and exacerbation of crack	Submitted at OIC request
22-Sep-16	Vehicle	240	nil	Overdue for service was due at 12/09 - alarm sounding on dash - red led on bonnet drivers side faulty - 1x siren speaker faulty not working	missed service	Siren & LED needs repair
22-Sep-16	Vehicle	235	Turned mdt off to reset but same message	Mdt screen shows out of range	-	-
22-Sep-16	Vehicle	240	assessed vehicle stating will need to have steering / tracking alignment reset. Requested fault form completed and they will collect vehicle on 23/09/16 to effect repair	Vehicle pulling to left	U/k	-
22-Sep-16	Vehicle	200	Spoken to LASN mechanic and it is at	Has gone into limp mode	Hit a pot hole at low speed and light on the dash came on and vehicle went into limp mode	-
21-Sep-16	Vehicle	200	Nil	Activation of Emergency Beacons activated flickering of siren.	Unknown	-
22-Sep-16	Vehicle	240	SHE Report completed	O I C & R O C Advised	Foreign object hit windscreen whilst driving	-
22-Sep-16	Vehicle	185	Fire department, operations supervisor and readiness co-ordinator notified	Burning smell coming from inside of truck	?Electrical fire smoke coming from under truck	Battery disabled by fire department and advised to not to drive. Towed by . V4951. Electrical issues fixed. found heater was permanently turned on, so heater disconnected until switch can be ordered and fitted.

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
22-Sep-16	Vehicle	195	-	Cable cover on VHS handheld piece frayed.	Noticed cable being frayed when checking vehicle for shift.	-
22-Sep-16	Vehicle	230	Car turned off and then back on again, problems self resolved. "Brake distribution error" message comes up when driving for a short time.	Car is still showing "brake distribution error" when turned on. ABS dashboard light staying on. Still unable to change from Park into Reverse, Drive etc. car turned on however no accessories working. Lights do not turn on when switch is turned on.	-	This does not happen every time the car is turned on and seems to self resolve by being turned off and on again.
23-Sep-16	Vehicle	200	Nil	Cracked windscreen	? Rock	-
22-Sep-16	Vehicle	240	-	Transmission problem. Motor continues to run, however no power to drive train. Then unable to manually select gear. Vehicle not in limp mode. Warning light disappears after switching off warning light however reappears within 1 km of further driving.	-	Towed to
23-Sep-16	Vehicle	200	SOS contact with no answer. Email to be sent	Corpuls removed from vehicle	Corpuls ETCO2 not function.	-
23-Sep-16	Defibrillator	200	Basic problem solving. Mackay LASN Education Unit contact. DTA contacted, job lodged	ETCO2 not functioning	nil	-
22-Sep-16	Vehicle	225	Notify OIC	Stone chip damage to windscreen in drivers side	-	-
23-Sep-16	Vehicle	240	O.I.C. & Comms notified	Cracked windscreen	Stone thrown up by passing truck	Vehicle to be picked up to torque ford at approx 1130 213/9 to be fixed today and returned. aware and organising WON.
23-Sep-16	Vehicle	245	Not fixable.	L) side mirror broken.	-	-
23-Sep-16	Vehicle	195	Nil	Rear camera video feed nonoperational	Unknown	waiting for parts
23-Sep-16	Vehicle	205	Nil as yet	Large crack in windscreen	Unknown - changed in to vehicle this morning and noted fault	Within drivers line of sight but not significantly obstructing view
23-Sep-16	Other Equipment	205	Replaced with unit from Comm Ed store	Tympanic thermometer in 2381 failed	Unknown	Require replacement unit to be ordered
23-Sep-16	Vehicle	235	SOS, fleet manager notified, car driven from toowoomba to ipswich, for change over, car improved but still displayed same as above.	as above, engine warning light, limp mode, lose of power at > 80 kph poor handling in front end, car blew one large plume of black smoke which self resolve in seconds TWB to lppy.	unknown	-
23-Sep-16	General Equipment	215	email to OIC	SpO2 cable connecting to Corpulse defective.	-	-
23-Sep-16	Vehicle	230	CDS notified, vehicle inspected nothing obvious found, driven carefully back to Caloundra station, fault report completed.	Vehicle smelling of burning rubber while driving, fault seems intermittent	-	Crew note small amounts of oil sprayed around the top of the engine, which was not present on vehicle inspection at start of shift.
23-Sep-16	Vehicle	235	Notification	Rock from truck flicked up and chipped windscreen	Rock	-
24-Sep-16	Vehicle	210	Contacted CCS	Recharge cable port not recognising cable is out and not allowing vehicle to be turned on.	Query happened whilst washing vehicle	-
23-Sep-16	Defibrillator	240	Turned off and on, removed all sections and replaced, changed cords when Corpuls off	Spo2 not reading, lead 2 showing normally, but others not showing or not clear	Unknown	Nil issue with Corpuls - SPO2 lead required replacement

RTI RELEASE

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
24-Sep-16	Vehicle	230	nil	Fluid leaking from middle seal of radiator reservoir	unknown	Still has fluid in reservoir to the middle seam
24-Sep-16	Vehicle	185	nil	Vehicle was exchanged on last shift after a repair for the same problem, on the way back to station the engine light came on and the vehicle lost power, as per the previous incident	unknown	Unit 7274 towed from Mareeba Stn to for repair. found computer may have misread issue. Has test driven multiple times without issue and happy to put back on road.
22-Sep-16	Stretcher	185	Stretcher has been taken off road and replaced with a functioning stretcher. Fault form and SHE report filed.	Legs swung down and "locked" but there was no "click" heard (I thought it may be a user error), then later, when unloading, the front legs caught on the back legs and had to be manually moved into.	-	SHE 006497 - Dropping off tagged stretcher at Cairns Hospital with next transfer to Cairns.
24-Sep-16	Vehicle	245	Reported to oic and fleet via this fault report	Rear door handle fault. Stays out making it difficult to close door. Requires operator to push handle in to close door.	Repetitive use and fatigue	Requires replacement at next service. See vehicle checklist 71791 for photo
24-Sep-16	Vehicle	230	N/a	Small scrap left hand side	turned too early through narrow gateway	n/a
24-Sep-16	Vehicle	235	Fault form completed Needs to be assessed by	Vehicle has large chip in windscreen noticed at the beginning of shift. Drivers side emergency light on the hood of the truck (just below the windscreen) is a solid red and not flashing.	Unknown what caused chip and was present prior to log on of shift	-
24-Sep-16	Vehicle	200	OIC informed me to wait for awhile too see if was returned, nothing to date		-	-
25-Sep-16	Other Equipment	235	Towed to station. Await instructions from mechanic on Monday. Probable tow to Monday 26/09/16. Unit currently scheduled for service 27/09/16.	Missing pager, has been missing for a period of time,	Possible taken home by relieving staff	Order a replacement for this unit
24-Sep-16	Vehicle	240		Electrical burning smell in cabin followed by electrical warning light. Shortly thereafter over temperature warning noted in assoc. with loss of power steering and aircon cooling.	Engine belt failure - loss of A/c, power steering, water pump and ? alternator. Intake pipe between front grill and airbox is missing. ? fell into belt and pulley below damaging belt and causing its eventual failure.	Following engine over temp warning vehicle shifted into neutral and coasted off freeway. Run time following warning light approx 1 min. Engine bay did not feel excessively hot on opening bonnet. Belt looked in GC based upon small piece found in engine bay
25-Sep-16	Vehicle	240	VOR, will require service centre to assess and fix	Ongoing issues with auxiliary battery retaining charge. Mains and radio would lose power when not plug into external power. Attempted to charge vehicle for 18 hours at station before using, however, same problem occurred after attending 1 case.	Unknown, suspected fault with auxiliary battery	-
25-Sep-16	Vehicle	235	Tried all trouble shooting techniques but no luck	Interior high and low lights not working - Also the defibrillator charger light appears to be shimmering ?... Not charging	No	-
25-Sep-16	Defibrillator	200	Defibrillator removed from service and defected.	'Defect oxy sensor' message of screen. Spo2 not working.	Unknown. Working during vehicle check today.	-
25-Sep-16	Defibrillator	235	Pulled the plug from defibrillator and reinserted same and it works for a very short period of time	Pulse oximetry not working properly	-	Do not have a spare plug to fit and try same, defibrillator has been left in unit 603673 as it can be used if needed
25-Sep-16	Vehicle	230	Report it.	Rear AC not cold. Cool air only, so it appears the aircon is working, just not very well.	Unknown	Please assess during service on Tue 27th Sept
25-Sep-16	Vehicle	240	Oc informed and car taken off road.	Broken windscreen from a rock during code 1	Rock from a passing vehicle	-
25-Sep-16	Vehicle	240	-	Bent rear step	Reversing into wooden bollard	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
25-Sep-16	Vehicle	210	New door hinge.	Rear barn door hinge broken.	Crew member from Life Flight attempted to help by closing rear door, without folding door hinge. QAS officers were unaware at the time & were unable to stop the crew member before the door hinge was damaged.	Incident occurred at RH ED - video surveillance available for incident.
26-Sep-16	Vehicle	245	Vehicle due for service 29/9/2016!can be inspected then	Air suspension take a long time to raise up after vehicle has been sitting overnight unit is due for service 29/9/2016!technician can investigate issue then still operational.	Na	-
26-Sep-16	Defibrillator	195	Notify OIC/technician via fault report	CF card full	-	-
26-Sep-16	Vehicle	245	fix trip switch	Won't charge at station or lch	-	-
26-Sep-16	Vehicle	235	Tried turning master switch on and off with nil effect	MDT/GPS has failed. No power to unit.	While driving to a case on a dirt road, the vehicle hit a small bump and the MDT immediately stopped working.	-
1-Sep-16	Vehicle	240	The parts of the unit and inserts have been changed and correct assembly has been checked - issue appears to be with oxygen system not creating sufficient suction.	Suction Unit on vehicle does not work correctly - not enough suction to be effective.	Unknown but has been this way for some time.	TYhe vehicle can be used and the suction unit in the oxygen bag can be used however this unit needs rectifying as soon as practicable.
26-Sep-16	Vehicle	200	Taken to mechanic at	Fuel leak under car	unknown. Noticed today.	Fault fixed and unit is now operational
26-Sep-16	Vehicle	230	Reported to	Puncture right front tyre	Rugged track Mothar Mountain	-
26-Sep-16	General Equipment	215	notified OIC	No airport card or FSPH swipe card in 4404	Someone removed card?	-
4-Sep-16	Defibrillator	205	Defib has been removed from service and the sensor is being returned for replacement on advice from tech support.	The CO2 sensor is not registering CO2	After speaking to the tech hotline, it appears to be the sensor and not the module itself. The end of the sensor is to be posted to tech support and they will send a replacement.	It is not required to use this monitor at the moment as we have another fully functioning Corpuls. If, however, it is required before the replacement arrives, all other functions appear to work. The monitor can do ECGs, take BPs and record SpO2.
26-Sep-16	Vehicle	215	charging and running of vehicle	Module battery low Side step, Comms radio and corpuls Charger intermittently failing due low battery	normal usage	-
26-Sep-16	Stair Chair	215	oic informed attempted to locate a replacement nil currently available	Restraint clip (black chest strap) broken	unknown found broken in vehicle	Vehicle 4401
26-Sep-16	Vehicle	230	visual inspection.	Retractable step into vehicle cabin not retracting.	Unknown	Spoke to CDS who allowed us to return to station and swap into another vehicle.
26-Sep-16	Vehicle	245	-	Both headlights blown	-	Caution required at night; spot lights required
26-Sep-16	Vehicle	240	-	ROC and OIC	-	-
26-Sep-16	Vehicle	240	Sent to workshops	Just returned from three weeks at workshop to fix lack of power first drive by OIC unit still severely under powered in fact will not go up a 25% incline in first gear with foot to floor at a speed greater than 15 kms per hour	Unknown	This vehicle has along history of this fault and to date has not been rectified it is dangerous to drive in this state

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
27-Sep-16	Vehicle	240	vehicle fault report form completed. Vehicle accident form will be completed upon return to station.	Driver side panel door below charging point damaged Having hit keypad panel stand at Ashgrove Station	Driver error	-
27-Sep-16	Vehicle	215	Tried to release door lock after removing trim but didn't work	Driver side door will not open Lighting panel switch intermittent fault not allowing activation of lights	Unknown	-
26-Sep-16	General Equipment	240	Unable to rectify fault and suction unit is unserviceable.	Suction Unit attachment bracket to vehicle has broken and detached.	-	Vehicle is still operational but has no internal suction unit - so is not ideal and unit is currently being used by OIC only.
27-Sep-16	General Equipment	245	-	AED was last serviced 08/15, due for next inspection 02/2016. AED is over due service and OOD. Additionally, there is NO Paediatric key card for this equipment	-	-
27-Sep-16	Other Equipment	235	-	Lost phone	-	-
27-Sep-16	Other Equipment	235	-	-	-	-
26-Sep-16	Vehicle	215	checked for anything obstructing door, checked step for obstruction - nothing noted.	passenger side sliding door often difficult to close properly and step appears sticky when extending and retracting	unknown	-
27-Sep-16	Vehicle	185	-	Side step malfunction	-	Sent to V4981 issued.
27-Sep-16	Vehicle	200	notified OIC who has notified mechanic	Corpuse bracket not charging corpuse	-	-
27-Sep-16	Vehicle	240	Tried other suction insert, no difference, hose appears clear	Vehicle suction unit very poor ability	-	Use O2 suction instead
27-Sep-16	Vehicle	250	-	Rear passenger tyre has nail in it	-	Unable to get odometer reading
27-Sep-16	Vehicle	250	Fault form completed	Rear passenger tyre has nail in it and low pressure	-	Taken to by A/OIC and now repaired.
27-Sep-16	Vehicle	245	Reporting on several occasions to OIC and OS ()	Consistent thumping from vehicle while car is in motion and going over speed bumps. Very bad knocking noise even going around corners. Might have something to do with the suspension? VERY VERY Loud Noise in the Roof in the Module. Again gets louder and louder the faster you go and over bumps. Anyone would think that the Aircon is about to fall out.	General wear and tear	-
27-Sep-16	Vehicle	245	Not sure if this has been reported previously	CF card almost full. Flashing blue selection button	Unknown	-
27-Sep-16	Defibrillator	240	Powered off then on again.	Reversing camera not working. Static shows on screen when reverse camera activated.	-	Requested to take out of service by SOS
27-Sep-16	Vehicle	195	Oil level checked again, it is just on the low line. All doors checked- can not see a reason for door open warning.	Oil light on intermittently and door open warning always on.	Unknown	Waiting for replacement camera
27-Sep-16	Vehicle	195	-	MDT not operational. Will not load operational software.	Low oil level, unsure for door open warning.	-
28-Sep-16	Vehicle	230	-	dent to top R) corner of back side door. Door is now sticky to open.	-	opening the door onto a large tree branch with some force
27-Sep-16	Vehicle	190	told the A/OIC Rubber seal located under patient care seat in car	Rubber seal on back door has come off	Unknown	-
28-Sep-16	Vehicle	200	Manually opening door- north Mackay OIC notified	Equipment side door not unlocking by remote key	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
27-Sep-16	Vehicle	185	Contacted fleet and equipment, vehicle at	Engine light flashing, turbo not working, car still functional	-	Taken to V4979. Needs to come through to at for diagnostics.
27-Sep-16	-	210	OIC has booked car into hotwired and car is being dropped with them by officers from fairview	Drivers side headlight not working	N/A	-
28-Sep-16	Vehicle	225	Fault form created and notified the Fleet manager.	aircon is not working Unit 2230 side rear door (entrance to back of vehicle) door unlocks however does not open. The door can only be opened manually with the key.	-	When the car is unlocked the green light appears, however when you press the button to open the rear side door, it can not be opened. The door can only be opened manually with the key.
28-Sep-16	Vehicle	210	-	AED is OOD for service. Was due in Aug 2016	-	-
28-Sep-16	Equipment	230	decomission and recommission a new phone	Plastic surround to tighten hose to d size O2 regulator is brokenThe	it broke while tightening by hand to change cylinder	4773
28-Sep-16	Equipment	235	Other	vehicle mobile is lost and or missing goes to message bank	-	phone unable to be located
28-Sep-16	Equipment	235	Other	phone lost or unable to be found	-	-
28-Sep-16	Equipment	235	Other	phone is lost	-	-
28-Sep-16	Equipment	235	Other	mobile phone missing	-	-
28-Sep-16	Equipment	235	-	lost mobile phone	-	-
28-Sep-16	Vehicle	235	-	Chip to windscreen	Driving code 1 to a job in Fernvale (case # 8042575) when 2 trucks drove past, a rock flipped up, hit the windscreen and chipped it.	-
27-Sep-16	Vehicle	205	Nil! Suspect replacement will be required, will attempt to follow up with mechanic tomorrow	Damaged fuel sub-tank cap	Unknown, appears someone has attempted to force cap open and damaged keyhole	Image contained in vehicle checklist for this vehicle 28/09/2016
28-Sep-16	Vehicle	210	attempted switching off and on. checked no wires were lose	LED driving lights not working	unknown	high beam headlights work properly
28-Sep-16	Vehicle	235	-	Fridge is on but not working	-	-
28-Sep-16	Vehicle	225	#NAME?	#NAME?	#NAME?	- sufficient to wait for next vehicle service (ie @ 45 000km)
28-Sep-16	Vehicle	245	-	Vehicle making screaming/hissing noise when accelerating, and rubbery smell noted	-	Vehicle towed to service location
28-Sep-16	Vehicle	240	The ROC was notified, I used Redcliffe OIC's car for the cases out to Stanmore and the ROC advised to put the car out of service and for the day shift to use Chermshire OIC's vehicle.	When travelling above 60km/hr there is a distinct rubbing sound that can be heard inside the car. It sounds like it is probably coming from one of the wheels (on inspection there is nothing that can be seen but the sound and slight bumping feeling remains	Unknown... Was like it when I started my shift but wasn't like that PM of the 27th.	-
29-Sep-16	Equipment	195	-	BSL kit missing from unit 435.	-	Replaced

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
29-Sep-16	Vehicle	215	-	Plastic plate on slide panel is starting to lift, causing power stretcher to be caught and stuck on slide before stretcher lifts itself up. Stretcher clicks on panel every pull, heavier patients on stretcher get stuck, requiring a strong pull to free stre	-	-
29-Sep-16	Vehicle	240	A review of the power both when engine is off and when engine is running. No difference. thought a fault form was completed but checking with c r r no it hasn't	Internal LED Light above the Patient Care Officer in the Rear is not working all the time.	Unknown	-
28-Sep-16	Vehicle	210	-	Air con does not work not cold air Refrigerator not working. Checked fridge rear rocker switch which does not light up or make it cool in either position	noticed a few days ago apparently	-
29-Sep-16	Vehicle	240	-	its booked for workshops to fix Reset battery as per previous instruction	-	Reviewed and is operational. Light is not working in switch only.
28-Sep-16	Vehicle	240	-	Fan belt fell off	-	-
29-Sep-16	Vehicle	200	-	Suction not working in main cabin Windscreen wipers are past their best. Both L and R don't make good contact in the middle sections, leaving large sections of the windscreen still wet, and smeared with water + dirt	Unknown	-
29-Sep-16	Vehicle	210	-	-	-	-
29-Sep-16	Vehicle	230	Fault form logged and notice placed on vehicle	Interior nights either won't come on and if they do come on they won't stay on	-	-
29-Sep-16	Vehicle	230	Fault form logged and notice placed on vehicle	Interior nights either won't come on and if they do come on they won't stay on	-	-
29-Sep-16	Vehicle	210	Notified OIC, got to have a look, however they stated its not the normal problem that arises, and is not a quick fix. And that an actual appointment would be required.	Step to enter the rear compartment of the vehicle is not working	Unknown	-
29-Sep-16	Vehicle	240	ROC called, written on whiteboard, fault form attempted to calibrate touch pad on GPS pick up new garmin from fleet	Engine light and coil light on when car started.	Unknown	-
29-Sep-16	Vehicle	245	-	Garmin GPS touch screen faulty despite calibration. Very difficult to enter addresses and unable to backspace when touch pad enters incorrect letter - results in small delays proceeding to address.	As is at start of shift	-
29-Sep-16	Stretcher	240	ROC notified, Stretcher taken out of service, OIC notified via email 29/9/16	Locking mechanism into vehicle is not working properly. Red button remains half depressed. Stretcher has not become dislodged during any transport however when other stretchers were tested in this vehicle the locking mechanism worked perfectly.	No known cause	Stretcher is technically operational, it has not become dislodged during transport however myself and my partner do not want to take this risk knowing other stretchers will lock into the truck perfectly.
29-Sep-16	Stretcher	240	ROC notified, Stretcher taken out of service, OIC notified via email 29/9/16	Locking mechanism into vehicle is not working properly. Red button remains half depressed. Stretcher has not become dislodged during any transport however when other stretchers were tested in this vehicle the locking mechanism worked perfectly.	No known cause	Stretcher is technically operational, it has not become dislodged during transport however myself and my partner do not want to take this risk knowing other stretchers will lock into the truck perfectly.

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
29-Sep-16	Vehicle	225	#NAME?	#NAME?	-	#NAME?
29-Sep-16	General Equipment	245	Spare pedimate taken from stores and used by crew. restraint removed from service.	Main black connection strap is missing from the child harness. It is not attached to the stretcher and is not in the equipment bag or located in any of the cupboards in the vehicle. Spare unable to be located at station.	-	-
29-Sep-16	Vehicle	240	Resetting the MDT has not resolved the message box relating to system recovery.	MDT fault. System recovery fault.	unknown. Vehicle returned to station today after repairs of damage from RTC.	MDT restarted with assistance from OSU - checked with Comms and working correctly.
30-Sep-16	Vehicle	250	-	Screw in rear right tyre	-	-
9-Sep-16	Vehicle	240	Reported to OIC, Vehicle accident report, SHE outstanding and OIC addressed issue with Officer.	Broken rear passenger side tail light.	Officer reversed into rubbish bin at Rom t station when attempting to reverse into garage.	-
30-Sep-16	Vehicle	235	report it	Large Chip in windscreen drivers side middle	A stone	-
30-Sep-16	Vehicle	230	reported to SOS and RRC (acting) SSC	Damage to 'A' pillar and front guard drivers side vehicle.	Semi trailer reversed into same at roundabout, Truck had stopped as had small vehicle, in front. QAS vehicle parked behind on angle. Truck reversed into same.	Inspected at deemed unsafe due to compromised 'A' pillar damage and drivers door not opening fully. Driver will complete insurance form etc
30-Sep-16	Vehicle	230	Removed from service, CDS notified of unit not functional and report generated. Crew to work in unit 4931	Rear air conditioner blowing hot air	Unknown, working this morning	Nil
30-Sep-16	Vehicle	230	OIC aware. Fault form completed	MDT turns off whilst car is turned off. On a job MDT turned off and when vehicle was turned back on it did not turn itself back on. Vehicle had to be restarted to get MDT to work. The FM radio is also not working.	-	-
30-Sep-16	Vehicle	250	Nil	Rear reversing camera not working	-	Can it be looked at when vehicle has the rear master control panel repaired next week.
30-Sep-16	Other Equipment	245	ensured screen is not locked, restarted multiple times - did not rectify problem and remains broken	GPS faulty - unable to make any menu selections or enter address. Touch screen completely unresponsive.m	unknown. Touch screen very temperamental yesterday and now completely faulty and not able to be used	-
30-Sep-16	Stretcher	245	Stretcher placed out of service at Carina.	Unloading stretcher from vehicle, no patient in board. Head-end wheels clicked into position however did not take the weight of the stretcher causing it to collapse.	Unknown.	-
30-Sep-16	General Equipment	210	Removed from service and defect note attached	Cylinder leaking Empty cylinder in kit, changed to full one, turned on to check it was full, turned off and gas leaking from tubing to empty within 30 seconds.	-	-
30-Sep-16	Vehicle	230	RACQ	Flat battery on scene no pt transported	battery issues	-
31-Oct-16	Vehicle	195	Reported	From start of shift noticed left indicator blinks too fast and uncontrollably. Dash light indicates issue. This issue was not occurring when we used 107 on wednesday 28th October. Did not use on Thursday	-	-
1-Oct-16	Vehicle	230	Nil, vehicle going in for service next week	Side lights and load lights working intermittent	-	-
1-Oct-16	Vehicle	190	-	Car radio talk button is very loose, still engages but is awkward to use	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
30-Sep-16	Vehicle	210	Nil	Broken fog light passenger side.	Unknown	Oil level found to be low. Notified SOS & was directed to go to house of for oil top up. Vehicle is due for service in another 40km at 103 000km.
1-Oct-16	Vehicle	250	Notified SOS who attempted to rectify fault but was unable to.	Side step will no longer extend thus officers and patients unable to step safely in and out of vehicle.	-	-
1-Oct-16	Vehicle	235	Vehicle has been sent for quotes for repair	Right hand headlight assembly broken minor right 1/4panel damage	Collision with kangaroo @90kph	Will only require indicator globe to return to operational status
1-Oct-16	Vehicle	220	advised OiC - will replace charger	Charger in vehicle for Sat phone not working despite being plugged into car and having green light on.	faulty charger	Charger is not operational, sat phone is being charged by another charger and is operational
1-Oct-16	Vehicle	190	OiC advised via this form.	Warning Fault on Dash - Fault/Failure of SRS and ESP safety features - Warning on dash states to take to service repairer.	Unknown	-
30-Sep-16	Vehicle	240	Nothing - not dangerous	Passenger plastic door trim which is attached to the lower of door has sustained minor damage to it as it got caught on the footpath when trying to close door	-	LHS door trim - to be actioned and repaired at next service.
1-Oct-16	Vehicle	245	unknown	Engine turned off/ lost power while idle at lights. Able to restart with difficulty shuddering a lot, able to drive back short distance to station	Unknwown	vehicle checklist form completed manually today. OS and OiC notified.
1-Oct-16	Vehicle	195	Report to SOS and OpCen. Taken out of service as instructed.	Brake distribution : Take to workshop. Warning on dashboard.	-	-
1-Oct-16	Vehicle	225	Nil - car cooled and parked at station	During code 1 drive to case, engine warning displayed on dashboard stating that 'incorrect oil level when running'. Oil was checked immediately, dipstick showing low oil, smoke coming from oil dipstick. Once car cooled down, dipstick level showing as full	Unknown	Not wanting to run further risk of damage with unknown fault. Nil increased temperature according to vehicle dial.
2-Oct-16	General Equipment	185	Unsure if fault form was lodged by Officer Fault form lodged, AOIC informed	Car refridgerator does not appear to be cooling.	-	Car still functional. V 4987.
2-Oct-16	Vehicle	225	Fault form has been submitted by	Rear aircon not working fault for has been submitted by another officer	-	-
2-Oct-16	Vehicle	215	-	R) sided headlight is out	Bulb blown	-
1-Oct-16	Vehicle	235	water level was checked prior to shift commence and found to be within normal limits	Engine light and low water alarm came on under acceloration	-	-
1-Oct-16	Vehicle	215	Lead currently taped to power socket in an attempt to reduce movement	Cigarette style connection for Corpuls charge lead is poor quality and continually moves in socket resulting in Corpuls not charging location of female socket results in lead being moved / bent by stretcher pillow	Recommend the following actions be taken Good quality side mount turn and lock cigarette style power point be fitted to all 3 Fraser Island vehicles This will prevent poor connections and stop patient/ stretcher pillow interfering with the power lead	Photos forwarded to Wide Bay Vehicle Co ordinator
2-Oct-16	Vehicle	195	Have taken GPS out of 1139 and it is working in 1120. Have placed the broken unit in OiC in tray	GPS not functioning	N/A	Nil

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
2-Oct-16	Vehicle	210	vehicle defected , this form filled and OIC will be sent an email	Oxygen door on side of vehicle not latching properly	unknown	-
2-Oct-16	Vehicle	240	Vehicle is at North Lakes	Car continually losing power & unable to accelerate. Problem is not rectified by stopping & switching off vehicle. Engine light on dashboard is solid amber.	-	Vehicle is back on road and fully operational.
2-Oct-16	Vehicle	225	-	While driving 3180 at 60 kms/hr the Orange motor warning light came on.we returned to Dalby station and parked vehicle on plant room floor.	-	-
2-Oct-16	Vehicle	225	Vehicle taken off road. Comms notified.	Monitor cradle not charging monitor.	-	OIC changed montitors around and bracket, now recharging
2-Oct-16	Defibrillator	245	Replaced with new sensor.	Spo2 not working, error message / alarm !! Oxi: Check conn. To P-box. Multiple attempts to rectify, disconnect, Restart, change connector, message still displayed nil lights on probe.	unknown cause, operated fine on previous case, did have volatile scene with non compliant agitated patient. Could have damaged lead.	-
2-Oct-16	Vehicle	210	-	Knocking/Banging coming from front left of vehicle ?? front left strut (according to a patient's family member, who is a mechanic, who travelled to hospital in the front passenger seat!)	Found on driving this vehicle for O/T shift	-
2-Oct-16	Defibrillator	245	Monitor charges positionally - towel forced in underneath monitor when in cradle to hold in position in which it will charge	Monitor does not charge/charges intermittently when placed normally in charging cradle	?? Problem with connection - either charging cradle or monitor	-
3-Oct-16	Stretcher	235	Stretcher taken out of service - left at Ipswich station for review.	Stretcher collapsed while offloading pt from rear of vehicle. Head end of stretcher dropped 3 'clicks' after initially clicking 'in'. On inspection post, head legs seem loose (can be pushed side to side).	#NAME?	-
3-Oct-16	Vehicle	240	Vehicle due for service Wed 5th Oct - Can this be repaired during service?	Cigarette lighter / charger broken in front compartment of vehicle	-	Still working but requires to be fixed back into place
28-Sep-16	Vehicle	240	fleet notified, accident documentation completed and incorrect fault form completed by officer.	Reversing camera making loud warning noise whenever placed in reversed.	Previously accident may have contributed to fault.	Requires immediate attention.
3-Oct-16	Vehicle	185	Unknown. Another officer says he has sent an emial to the OIC last week.	Unable to open rear door.	Ongoing issue has become worse.	V 4991.
1-Oct-16	Vehicle	235	Duct Tape	Vehicle assaulted by aggressive beast Broken tail light.	An aggressive beast	OIC aware.
3-Oct-16	Vehicle	230	Nil to date	MDT continually shuts off at random then reboots. Ongoing issue.	-	Multiple crews have reported this issue
3-Oct-16	Vehicle	230	Vehicle taken to for checking and repaired with next service	Wire for 2nd left reversing sensor has detached.	Looks melted under step tread	-
30-Sep-16	Defibrillator	240	Remove faulty cable, replaced with spare.	Corplus SpO2 Intermediate lead faulty.	-	Ongoing issue of intermediate cable failure.

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
1-Sep-16	Vehicle	240	240v charger placed into vehicle to charge when @ hospital and/or via inverter.	Compuls charging bracket will not charge. Other defibs and brackets exchanged and found to be bracket/plug fault rather than defib fault.	-	-
3-Oct-16	Vehicle	185	Notified OIC	Chip in the centre of the windscreen	?	-
2-Oct-16	Vehicle	235	OIC advised will contact fleet coordinator for battery replacement.	Reserve battery voltage level drops to 9 volts when off 240v power supply.	-	-
3-Oct-16	Vehicle	185	Fault form will be completed, SOS contacted, tagged car out	Constantly out, will not reside despite using step override button.	-	OIC advises side step stuck out. V 4986, vehicle will be bought into this morning
3-Oct-16	Vehicle	185	SOS has been contacted . Vehicle has been tagged out	Side step not functioning. Is constantly out. Will not reside despite using over ride button.	- V 4986	
4-Oct-16	Defibrillator	200	-	co2 not reading during cardiac arrest with LMA in situ. Pre shift checks completed with co2 working.	? Chip reading problem	-
4-Oct-16	Vehicle	215	visual inspection - pressure test	Evidence of dried fluid on number of hoses under bonnet - pressure check and inspection needed.. Nil loss of water	?water leakage - maybe old or new	-
4-Oct-16	Vehicle	215	-	Left front light out	-	-
3-Oct-16	Vehicle	235	Nil, towels used to contain water and protect equipment	Water comes pouring through the air conditioning above the kit storage area during rain, especially when cornering	?Design fault	Video to be to emailed to fleet technician separately
4-Oct-16	Vehicle	235	Fault form filed.	Stone strike to windscreen causing large chip full depth of glass	Rock strick from passing car	Possible cracking of wind screen if not repaired.
29-Sep-16	General Equipment	235	reporting	601672 has outdated MDT which is difficult to read even after adjusting back light. Makes responding more dangerous as you need to stretch over to read taking eyes off the road for longer.	old outdated equipment	Equipment is operating however difficult to read. Needs to be updated to new generation of MDT.
3-Oct-16	Defibrillator	245	defib still charges, used external 240v charger in unit.	The defib cradle is lose and does not allow the defib to charge. cradle is in unit 601421.	a lose cradle	Cradle is still safe to use to hold the defib during operations.
4-Oct-16	Vehicle	195	-	Brake pad warning light on	-	-
1-Oct-16	General Equipment	235	reporting	GPS unit freezing while in transit. is slow to input required information delaying response time	not suitable equipment	Should be updated to new generation MDT which has inbuilt GPS at one push of a button (route to incident)
4-Oct-16	Vehicle	185	reset attempted	GPS not turning on	n/a	Map books are available in vehicle to use in meantime
4-Oct-16	Vehicle	215	Checklist completed, fault form completed.	2nd cannulation drawer does not close and fridge alarms when turned on ?after 10-15 mins has passed.	-	-
3-Oct-16	Vehicle	215	and OIC has been notified.	Side access door of vehicle will not lock.	-	Due to vehicle not being able to lock - car will not be able to be taken home on EA
3-Oct-16	Vehicle	215	-	Vehicle car stereo will not work.	-	-
3-Oct-16	Vehicle	185	Unknown. OIC and SOS aware	Back door difficult to open catching at both corners and at times unable to open. Alarm for back door alarming when going around corners.	not known.	V 4973.
15-Sep-16	Vehicle	235	OIC notified, fault form completed	Plastic cover that sits over the internal access to the D size oxygen cylinders cracked on the 15/09/16 and became dislodged on 03/10/16.	attempted to adjust his position by leaning on the cover, which subsequently cracked.	Vehicle is operational, cover has been removed from vehicle.
4-Oct-16	Vehicle	195	-	side step not working	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
4-Oct-16	Vehicle	240	Changed battery without any change to issue. Removed key from service and replaced with fully operational spare key Reported to oic and	Key for 501126 will lock but not unlock vehicle.	-	Only 1 spare remaining (2 x in operational use, 1 x spare with OIC, 1 x faulty)
4-Oct-16	Vehicle	240	fault form filled out	Crack in windscreen passenger side approx 40cm long. Lower section	Unknown	-
4-Oct-16	Vehicle	195	-	Two chips to front windscreen (passenger side), one 50cents in diameter, one 20cents in diameter	Unknown	-
4-Oct-16	Vehicle	210	-	Damage to rear of vicheale	-	-
4-Oct-16	Vehicle	185	attempted to change bulb; none at station Fault report completed. Vehicle restarted several times to try a	Back L) lower brake light faulty	?	-
4-Oct-16	Vehicle	230	'reset'. Taken off duties and placed outside OIC	Engine light flashing, in limp mode	Unknown.	-
4-Oct-16	Defibrillator	245	office	Corpuls not charging in multiple cradles.	-	-
5-Oct-16	Vehicle	200	Bulb replaced by SOS	Only one headlight, unsafe to drive at night	-	-
5-Oct-16	Vehicle Other	215	-	?battery not holding charge - appliances/mains turn them self off after 20 mins not plugged in on jobs. nil problems with starting car at any time.	-	-
5-Oct-16	Equipment Other	215	-	Pivotel cradle fallen off cradle holder- ? Missing screw	-	-
5-Oct-16	Equipment Other	210	-	Unable to read the screen	Unknown	Changed the battery and that didn't help
5-Oct-16	Equipment	210	-	Unable to read the screen	Unknown	Changed the battery and that didn't help
5-Oct-16	Vehicle	240	Vehicle left on idle for approx. 60min with stretcher in vehicle to attempt to charge stretcher battery to no avail.	Bariatric stretcher not raising or lowering once removed from vehicle power supply. Makes a clicking sound when trying to raise or lower stretcher when under battery power.	Unknown.	-
5-Oct-16	Vehicle	210	Workshop	Side step not working, rear cabin	-	-
5-Oct-16	General Equipment	195	Mic changed with known serviceable mic, no receive . Tried with no handset mike, no receive . Distress function tested as serviceable. Transmit function serviceable. Vehicle at	Nil receive function.	-	Radio left in service to provide distress function and radio still has transmit function for emergency use.
2-Oct-16	Vehicle	225	Kingaroy for service/repairs on 5/10/16	Retractable side step not working	Unknown	-

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
5-Oct-16	Vehicle	225	Vehicle booked in for service and repair 6 Oct 16, tomorrow. Collected vehicle, step not repaired, awaiting part. TBA.	Side step not working	Step has not been working for approx 1 month. Unknown cause.	-
3-Oct-16	Vehicle	240	Unable to fix - door either closed or fully open	Right Hand Side (Driver) rear door catch to keep door open broken - unable to keep door open.	-	-
5-Oct-16	Vehicle	215	Fault form completed and contacted and are picking up vehicle on 06/10/2016 (tomorrow) for repairs. notified SOS	Brake pad wear indicator light on and engine warning light flashing.	?	Car apparently runs fine but due to potential vehicle/person damage car placed off road.
5-Oct-16	Vehicle	215		Right work light damaged	I drove the vehicle too close to the side puller of the ambulance bay door	Vehicle can be used but light is hanging down
5-Oct-16	Vehicle	245	adjusted power cables. Flicked switch at vehicle switchboard	Power has failed to mdt	-	-
5-Oct-16	Vehicle	215	Swap ambulance when able to	Side step broke on when partner exited the ambulance,	Standing on side step	There was a 30 cm high that my partner had landed on his feet, jarred right side.
5-Oct-16	Vehicle	230	-	MDT and Radio switched off and cannot be powered on.	No obvious cause. The radio had powered off enroute to hospital and the MDT had powered off while vehicle was at hospital. All other electrical systems were working and batteries appeared to be charged.	to check battery condition and charging
5-Oct-16	Vehicle	240	-	NOT OPERATIONAL FOR REDUCED LIGHT TIMES.	-	-
5-Oct-16	Defibrillator	215	Corpuls taken off road nil DEFIBRILLATOR in 4524	Corpuls unable to perform a BP, SPO2 or ECG	Unknown	Machine disassembled and put back together and tested x 2 on tester All ok
5-Oct-16	Vehicle	225	Turned vehicle on and off, turned AC on and off, tried various fan and temperature settings.	Air conditioning in rear of vehicle not working, only blowing hot air.	-	-
5-Oct-16	Vehicle	185	-	Engine light flashing & vehicle in limp mode	-	Vehicle located on Smithfield station. V 4976.
6-Oct-16	Vehicle	245	nil	Stone chip driver side windscreen	-	-
6-Oct-16	Vehicle	240	-	Right headlight U/S	-	-
6-Oct-16	Vehicle	215	Fault report and told OIC	2 x chips in windscreen	Unsure	-
6-Oct-16	Vehicle	210	-	Front left and right headlight mounted indicator not functional. Front bullbar and wing mirror indicator still functional. Rear indicator still functional.	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
6-Oct-16	Vehicle	190	Corpuse removed and replaced several times, power point checked, and vehicle charge power and levels checked. No fault found with these.	Corpuse cradle is not charging the corpuse	-	-
6-Oct-16	Vehicle	225	Awaiting advise from RRC for ordering new harness	Power stretcher paediatric restraint missing from vehicle, can't find at station	-	New Harness placed in Vehicle
6-Oct-16	General Equipment	225	-	Missing	-	-
6-Oct-16	Vehicle	225	-	Missing seat adjustment knob	-	-
5-Oct-16	Vehicle	240	AOIC to discuss mechanics of the incident and how to reduce to chance of it occurring again	Driver side mirror damaged/broken	vehicle was reversing down step drive way brakes were applied and the vehicle slid back hitting tree stump shattering driver side mirror	VFRF completed on behalf of Officer
6-Oct-16	Vehicle	225	Fleet Contractor has been contacted and repair has been organised for tomorrow Friday 7th October at Proston station	Winscreen Crack 300mm long in center from base of windscreen	When washing vehicle this am the vehicle was in direct sunlight the possibility of cold water being applied to an unseen stone chip on the base of the windsceen may be the cause.	-
6-Oct-16	Defibrillator	240	Don't know how to fix it	When performing the defib test it prints that there is no ECG available during the shock. The printer is also very slow.	Not known	ROC contacted. OIC emailed. Photo taken of test strip. Note left on the corpuls stating that it is not working.
6-Oct-16	Other Equipment	230	4928 using hand held radios, pts comes notified	Vehicle Motorola not working, display shows, out of range	-	-
5-Oct-16	Defibrillator	240	Replacement cord fitted	Spo2 cable damaged-> exposed wires	-	-
6-Oct-16	Vehicle	250	Towed to informed.	Check engine light appeared on dashboard, loss of power to vehicle.	-	SOS notified at GCUH, organised for vehicle to be towed.
6-Oct-16	Vehicle	240	1- fault form completed 2- fault form completed 3- 1449 OC contacted and heading to for assessment	1. Step not working 2. Sliding door switch panel not working 3. Definitely 12v charger not working	-	-
6-Oct-16	Stretcher	250	STRETCHER PLACED OOS	STRETCHER BACK WHEELS DO NOT ALWAYS FULLY LOWER	UNKOWN	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
6-Oct-16	Defibrillator	230	Unit 4787 taken to who verified problem with Defibrillator not making proper connection in multiple cradles and also fault with cradle. Vehicle was taken OOS and defibrillator and cradle were removed from 4725 to make 4787 operational.	Not charging in any cradle unless pulled forward or backward in cradle.	Defibrillator not making proper connection in multiple cradles and also fault with cradle. No power to cradle even though Power active at accessory power outlet.	-
6-Oct-16	Vehicle	230	Reported three times in September	Left Alley light not working - reported 10th, 17th and 18th September	-	-
7-Oct-16	Vehicle	230	check MDT power switch to on, start vehicle - MDT not functioning	MDT not working, not booting when vehicle started	unknown	-
6-Oct-16	Defibrillator	240	Remove from service.	Error in top L of screen: "Defib Failure (4)" Error on main scree: "Charging not possible"	Found during shift check	-
7-Oct-16	Stretcher	225	Both paramedics on duty aware to take care when pulling out stretcher in this vehicle. Fault report. Emailed oic. Stretcher working fine now.	When pulling out stretcher front wheels/legs failed to come down. A couple attempts later front wheels came down with assistance. Next attempt and there after pulling stretcher out front legs worked fine.	Unknown	Stretcher has been checked & re-checked several time & fault has not been found. Stretcher has not had issue since. Possible stuck as this units is not used regularly.
6-Oct-16	Vehicle	200	Called LASN Mechanic reported; 2277 delivered to for repair.	Brakes faulty intermittently; failed three times then worked.	-	-
6-Oct-16	Vehicle	195	As above	Side step not working, worked on last case After being on charge all day; however got stuck out. Today 7th battery level checked power disconnected allowing step to retract ; however no longer works.	- notified	-
7-Oct-16	Vehicle	210	nil	Passenger side headlight not working	nil	-
7-Oct-16	Vehicle	200	Attempts to reattach lever have failed.	Driver seat control to raise/lower seat broken. Comes away from seat in hand, and able to be detached. Very difficult to raise seat to proper position to drive.	Not known how seat was broken.	-
7-Oct-16	Vehicle	235	-	vehicle coolant reducing may have a leak	-	-
7-Oct-16	Vehicle	230	turned vehicle off and restarted at Caloundra. Repeated procedure at SCUPH. Repeated procedure at Coolum and Noosa hospital. No change. Tyre changed and taken to	ENGINE light on dashboard came on at approx. 1400 hours. Vehicles top speed is 70kms when accelerator flat to floor.PTO dispatch advised. Advised duty officer to check - over weekend.	Unknown. Feels like transmission is not changing gears correctly.	-
6-Oct-16	Vehicle	230	have fixed	Flat drivers rear tyre	nail in tyre	Now repaired

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
7-Oct-16	Vehicle	240	tried to rectify by turning off main switch, unsuccessful, further advised ROC.	MDT failure	-	OIC organised to repair. All good now.
7-Oct-16	Vehicle	215	oic informed, mechanic closed so unable to fix	Coolant over 80 degrees	no known	No Fault found, Driver Education needed and will be spoken to.
7-Oct-16	Defibrillator	245	Equipment removed from service	Printer malfunctioning.	-	-
7-Oct-16	Vehicle	210	vehicle fault report filed	2 deep scratches noted on the outside of the glove compartment	unknown - unknown when it occurred - day shift denied noticing it.	none
7-Oct-16	Vehicle	235	-	Spot light not working	-	-
7-Oct-16	Vehicle	230	Use Aux battery to start when not on station and keep vehicle on charge when on station	Vehicle unable to be started every time on main battery after being off charge for a few hours but able to start on aux battery.	Unknown	-
7-Oct-16	Vehicle	230	Noticed CDS about fault and vehicle taken back to Nambour station and put out of service with a fault report done	Vigorous vibration throughout vehicle when accelerating from 40km/h or over. Lighting in back of vehicle also flickering when vehicle vibrating and unable to turn off from back when doing so.	Unknown	-
7-Oct-16	General Equipment	215	Filled in this wonderful form	Zipper broken and does not fasten	Kits are overstocked	-
7-Oct-16	General Equipment	215	Swearing, called eARF support but they were closed, rebooted the machine twice.	Toughbook will not connect to hospital WiFi. Switched on wireless and rebooted twice but it is still as much use as a cheese chopstick.	Switching to WiFi when Bluetooth did the job nicely.	Can we have the plug and play driver installed? It would save a lot of time messing around and assist in the problem of failing to print case sheets.
7-Oct-16	Vehicle	185	-	Vehicle taken off road as headlight out and also headlights alternatively flashing with lights and sirens even though headlights turned to on. Distracting at night. Keys are on hook and vehicle at cairns station	-	V 4999. A/OIC to make arrangements to have unit taken to ASAP.
7-Oct-16	Vehicle	225	OIC notified, to order new part.	Broken pin that held the back swing door open	found yesterday when opened the door.	-
8-Oct-16	Vehicle	195	-	Windscreen wipers not spraying water despite bottle being full. Red emergency flashing light on bonnet not working.	-	-
8-Oct-16	Defibrillator	230	Swapped with Corpuls from Tin Can Bay. OIC is ordering a replacement NIBP 'lead'..	The white connector on the NIBP 'lead' has come apart, unable to attach any BP cuff.. Cannot find the part of connector that has come off.	?	-
8-Oct-16	Vehicle	195	ocs notified, vehicle off road	Dash light - brake force distribution error message, see workshop.	unknown car was moved and on for 20 min while checking vehicle with no issues, then sent on job and error occurred prior to leaving station	-
8-Oct-16	Vehicle	250	OIC took vehicle to the auto electrics, fuse was replaced.	Flat Battery	Upon investigation and after RACQ started vehicle, it was found that the fuse for the vehicle charger had blown and the vehicle probably hadn't been charging for some days.	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
8-Oct-16	Vehicle	240	Nil	Shattered rear right hand side window between C and D pillars.	Rock thrown from ride on mower	Vehicle located at Caboolture Station as directed by the ROC. Ride on mower operators details:
8-Oct-16	Defibrillator	215	swapped defibs to remain operational and tagged defib with fault report/checklist in front of OIC office	Does not charge from cradle, tested on cradle of 4412 and 4412 to no success. Defib from 4417 charges in both cradles.	-	-
8-Oct-16	General Equipment	210	Removed from operations	High flow port assembly come apart inside of connector	Unknown	Leak noted, attempted to remove attached tubing, port noted to be defective
8-Oct-16	Vehicle	185	Vehicle off road. SOS notified.	Main belt frayed.	-	V 4998 for
8-Oct-16	Vehicle	235	Nil	Driver side spotlight and alley	Unknown	-
8-Oct-16	Defibrillator	210	-	Charging dock loose as screw has fallen out from Unit 2229. Therefore when defibrillator placed in dock it isn't being charged.	-	-
8-Oct-16	Vehicle	245	Attempted to charge when driving and plugged into power at hospital / at station.	Auxiliary battery flat and does not charge while plugged in or while vehicle running...internal lights, radio, MDT etc do not work unless vehicle is running or plugged in.	Unknown.	Battery needs ? Replacement.
9-Oct-16	General Equipment	220	have placed the equipment out of service. Have replaced the equipment in unit 3250 with the oxygen kit from 3405 and left a note to advise they do not have portable oxygen in the vehicle.	Outside valve leaking when oxygen bottle is turned on. Unable to stop this leak.	valve inside the outside oxygen is lowered and this means the cover does not shut off the flow of oxygen as it normally would if the valve was in the correct position.	-
8-Oct-16	Vehicle	215	Fault reported through appropriate channels.	Unit VHF radio does not appear to be transmitting or receiving at adequate levels, compared with other QAS units at the same QAS station.	Unknown	-
9-Oct-16	Vehicle	220	Out of service oxygen kit will be fixed ASAP or replacement will be sourced	Not Operational as it is missing the oxygen response kit. Vehicle is able to be used in emergency if oxygen kit provided from other vehicle.	out of service oxygen response kit due to fault	O2 kit exchanged with spare kit on station. Old kit to be used in training
9-Oct-16	Vehicle	250	Left ambulance on to allow for extra charge, and have taken ambulance out of service to allow for extra charging time at station.	Battery not working properly, when ambulance is turned off, it immediately turns the MDT and radio off, and unable to power up either until 15-20 minutes following ambulance being turned on again. Also when reversing, nil reversing sounds.	-	-
9-Oct-16	Vehicle	210	-	Doors to open o2, equipment and door to enter into back of ambulance catching on latch. Unable to open	-	On final assessment, noted car plugged into charge however charge not turned on. Car left to charge to see if fault fixes itself
8-Oct-16	Other Equipment	240	None can be	Vehicle Corpulse mounting bracket broken. Bracket spins freely. Charging bracket is working fine.	Unknown	-
9-Oct-16	Vehicle	240	ROC has been contacted.	Engine alert light on the dash flashing. The car does not has acceleration.	-	-
9-Oct-16	Vehicle	190	Duty officer notified	Fan belt made loud noises during the middle of shift. On inspection belt very worn with large cracks throughout belt.	-	-
8-Oct-16	Vehicle	225	Notify A/OIC and OCS, request radio to be fixed	Radio cuts during communication, poor reception at times, requiring to call Comms	no	radio has no fault radio interference is common in this area A/OIC can not find anything wrong with radio

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
9-Oct-16	Stretcher	245	Vehicle towed to station	Stretcher locking mechanism didn't unlock when unloading stretcher, resulting in stretcher getting stuck half way.	Unloading the stretcher - nil fault noted when loading the stretcher on previous job, all lights were green prior to unloading, unloaded as per instructions and stretcher got stuck half way. Noted that locking mechanism also came out with stretcher	-
9-Oct-16	Vehicle	195	-	Brake light broken, dash warning light activating (not making unoperational)	Stretcher inertia bar locking pin broken, left hand side (located in hole in dash below radio)	-
9-Oct-16	Vehicle	215	Vehicle towed from gin gin. Used 433 as a substitute.	Vehicle entered limp mode, flashing engine light, unable to be solved via trouble shooting provided by Comms or Sos	Dash warning light wheel activated.	-
9-Oct-16	Vehicle	250	kit taken out of car fleet manager notified , insurance paperwork and she report completed.	oxygen kit tubing leaking Vehicle was involved in an incident and hit a deer. Officer completed a vehicle checklist but forgot to do the fault form . Insurance forms have been completed. Has an aerial missing and a broken headlight / indicator cover but light still working.	-	Also sat phone not operational kit placed in OIC office 10/10/16 - Fixed by A/OIC and Officer Leaking hose identified and tightened by officers. Back in service.
2-Oct-16	Vehicle	235	completed.	particle filter fault and limp home mode on. aware and picking car up today	wild animal ran onto road and hit by vehicle responding to case unavoidable.	photos attached to vehicle checklist
10-Oct-16	Vehicle	245	collecting today	Notify CDS, liaise with Duty OIC. Review with	-	-
10-Oct-16	Vehicle	230	Vehicle taken to workshops.	Driving 823 out on code one roller door started coming down whilst driving out of station	Roller door closing	Duty OIC to handle broken roller door.
10-Oct-16	Vehicle	225	Attempt to retract without success	Oil leaking from front diff	oil noticed in the ground on Thursday 6th, unknown what caused leaking.	-
9-Oct-16	Vehicle	210	-	Seatbelt fault on patient care seat in rear compartment. Does not retract	No idea. Found in this condition	Not sure when this occurred. Found during shift when I went to buckle up.
6-Oct-16	Vehicle	250	-	Tyre sensor reading incorrect pressures and alarm constantly sounding.	-	-
6-Oct-16	Vehicle	250	-	Rear plastic mounting section for corpuls / garbage container splitting approx 5cm.	-	-
10-Oct-16	Defibrillator	200	Printed again a few times, turned off and on again, print out still the same.	The shock protocol print out states 'no ecg available'. The protocol states that the shock has been delivered and the screen has shock delivered also. A 12 lead is still printable and a rhythm strip is obtainable.	-	-
10-Oct-16	Defibrillator	250	Remove from service	V1 lead not recording on two separate occasions. Tested at beginning of shift and when I returned to station with no issue identified. 12 lead completed on colleague which again no fault identified. ECG's kept.	-	Job logged with technical support.
7-Oct-16	Vehicle	200	Mechanic will make arrangements for replacement X 2 tyres rear of unit 2155.	2 rear tyres need replacing per mechanic for unit 2155. Friday afternoon repaired head rack in rear cabin it had been broken off, replaced strap and buckle on side compartment, screwed up the glovebox. No previous defects had be	Wear and tear.	-
10-Oct-16	Vehicle	215	replaced battery	Slow cranking power by battery - load tested and failed	flat battery	-
10-Oct-16	Vehicle	230	DVA completed.	Reverse camera does not work. Side door often needs reclosing (drug door) as alarm goes off whilst driving.	-	Taken to by crew for repair 11/10
10-Oct-16	Vehicle	215	Fault form	Drivers side back brake light out.	Blown bulb	-
10-Oct-16	Equipment	240	-	Toughbook fault - it is freezing and syncing did not rectify fault	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
10-Oct-16	Stretcher	230	Being checked during vehicle service today	Wheels are not tracking in line with stretcher. Ie. Stretcher when being pushed straight does not line up and veers to either side	-	Completed
10-Oct-16	Vehicle	240	-	Left tail light not working.	-	-
10-Oct-16	Vehicle	240	Called OCS, was advised to "take due care, we will try to get you back to station".	Drivers side headlight not working - ? Bulb blown.	. Bulb blown	Item repaired
10-Oct-16	Defibrillator	240	Attempted to find a permanent replacement pulse oximetry, Corpuls removed from vehicle, Corpuls taken from 501 361 for 501 216.	Pulse oximetry not registering PR / SpO2, working pulse oximetry taken from another Corpuls which registered a PR / SpO2 on the Sandgate 3.	-	Proximal sp02 cable replaced and unit is now operational
11-Oct-16	Vehicle	195	Removed from service, fleet manager advised.	While checking vehicle, officer step onto the step and heard a loud noise. The support bracket broken away, step hanging from under the vehicle.	While checking vehicle, step broke from support brackets. Fleet manager on station while it occurred.	-
11-Oct-16	Vehicle	200	fault form	Load light smashed and not working	unknown	Damaged identified while completing daily vehicle check
4-Oct-16	Vehicle	235	Nothing has been rectified.	Spot lights not operational Inside lights do not work when the door is opened. Rear side door does not stay open when attempting to get equipment out,	Unknown, fault has been reported on a number of occasions.	Difficult with inadequate lighting while on call, single officer responses when trying to get equipment out of the unit when the door continually closes.
10-Oct-16	Vehicle	185	ic aware	Rear door alarming when cornering. As per previous fault form. Not fixed. Monitor alarm cradle not locking in and flies open when door opened. Siren changing sounds without switch being changed	It has been like this over a long time not fixed	Fix it please!!!!!!!!!! V 5015.
11-Oct-16	Vehicle	205	To be taken to Longreach for repairs.	Vehicle starting problem means this vehicle is not currently suitable for use in a remote/isolated single officer response location.	Intermittently occurring since service.	Repaired in Longreach
11-Oct-16	Stretcher	195	Will be taken off road as soon as convenient	incident at hospital when offloading. First stretcher would not release from loading device. Stretcher wheeled back inside the vehicle then out again. Then nil lights on offloading device, and stretcher fail....legs not extending. Manually extended...but unable to manually release. Stretcher wheeled back into vehicle and battery in stretcher replaced. Seems to be working now with loading device working okay as well. Nil warning lights on stretcher prior to incident indicating low battery.	-
10-Oct-16	Vehicle	225	-	Right spot light not working.	-	-
7-Oct-16	Vehicle	225	-	Rear ventillation not working	-	-
11-Oct-16	Vehicle	210	Lodged this report	Window screen damage drivers side	Rock from another vehicle hit windscreen	-
11-Oct-16	Vehicle	190	defib removed from vehicle. Only one defib at station currently, will have to swap unit between vehicle if needing to change vehicles.	Defibrillator from vehicle not accepting charge. Defibrillator removed from vehicle. Replacement needed. Checked by mechanic. Mechanic was advised to not open charging unit as possible voiding of warranty through corpuls.	Defibrillator unit not accepting charge. Alternate defibrillator working and accepting charge. Problem with corpuls unit not with charger.	-
11-Oct-16	Vehicle	210	Checked by QAS Workshop, Unable to fault at this time, (TESTING OK)	Reversing camera not working	No idea. Went to reverse and found it had a blank blue screen	-
11-Oct-16	Stretcher	250	-	top of upper control panel broke off	accidental hit on rail in hallway of gcuh whilst an orderly had a pt on bed coming in the other direction...no pt on str at time of incident	SHE report not completed as nil pt on str at the time of the incident.
12-Oct-16	Vehicle	245	Fault form	Smashed cover of L reversing light	Hit it with handle of stretcher	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
11-Oct-16	Vehicle	230	Reported to OIC	Sigtec maps are not following MDT very very slow	No	-
12-Oct-16	Vehicle	240	Officer advised to ensure code is input so gate will not close.	Smashed passenger side, side mirror and housing.	Side mirror struck when Officer drove through Roma St gate. Gate closed on vehicle when following another vehicle through gate.	-
12-Oct-16	Vehicle	225	Notify officer in charge	Excessive wear to left front wheel on inside of tyre	-	Two new front tyres placed on unit
12-Oct-16	Vehicle	210	Report filed	Access door to O2 tanks is stuck.	-	The door is not operational, but O2 tanks can be accessed externally
12-Oct-16	Vehicle	215	-	GPS power cable broken so GOS won't stay on	-	-
12-Oct-16	Defibrillator	240	replaced at the time	SpO2 cable from monitor to middle connection failed	-	-
12-Oct-16	Vehicle	185	OIC notified	External Locker Doors intermittently faulty and at times open on their own Defibrillator cradle in passenger side does not lock in GPS cable that plugs into Navman needs becoming frayed at connection point and falls out intermittently	?	for inspection/repair. V 5011 doors, V 5012 garmin. VEHICLE TO 14/10/16. OIC to source replacement defib cradle (possibly Business Manager can assist)
11-Oct-16	General Equipment	210	changed batteries between torches to confirm battery or LED failure and identified defective battery. Torch is not charging, indicated by flashing charge light. STREAMLIGHT TORCH	Torch not working in 2130	Faulty battery	-
11-Oct-16	Vehicle	185	OIC notifies	Cigarette port in front cabin faulty, doesn't hold enough charge to charge tough book	-	-
9-Oct-16	Vehicle	200	Realigned with it being held with tape	Modular cupboard door on drivers side has been loose, causing door open alarm to continually active.	This side of the vehicle has been damaged prior to arrival at moranbah station. Recently was struck again on a gate at station (reported). It would appear with the rough roads the door has become more 'unhinged'. The door sits uneven with an obvious gap	Photo taken and attached to vehicle checklist completed today
12-Oct-16	Vehicle	225	-	Both rear seat belts do not retract properly.	-	-
12-Oct-16	Stretcher	210	-	Sliding arm mechanism that locks stretcher into car not locking	Have only come on shift today and apparently this is occurring past few days	-
12-Oct-16	General Equipment	230	OIC informed	MDT is too dark to read in poor light , brightness is on maximum	-	-
12-Oct-16	Vehicle	195	Fault finding done with no result	Corpus vehicle charger not functioning.	Unknown	Corpus fully charged via 240v
8-Oct-16	General Equipment	230	repeated vehicle check list fault plus this fault form today	Only one pager functioning	does not appear calibrated to vehicle. Left in office	-
13-Oct-16	Other Equipment	215	investigation & fixing where appropriate	Station Hot water in Plant Room - U/S. takes long time to heat up - if at all. Potential Infection control hazard Hot water to station - OK	Faulty hotwater service -	-
13-Oct-16	Vehicle	240	Cleaned organised and stocked the entire car appropriately	Damaged resus equipment and empty o2 tanks	Damaged resus equipment and empty o2 tanks	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
12-Oct-16	Vehicle	205	magnet placed back in location to allow for starting, caution taken when opening cover to ensure not to loose magnet, have applied glue to magnet and allowing to dry before use	Magnet on 240v inlet keeps falling out.	poor glue quality	-
13-Oct-16	Vehicle	215	-	main communication radio still turning off at random times despite the vehicle running and on the charge	-	previous fault report done and vehicle checked although fault still present
13-Oct-16	Vehicle	215	-	door open warning light on despite all doors closed, rear door of the vehicle does not close correctly on uneven ground	-	-
13-Oct-16	Vehicle	250	-	GPS - Garmin (old type) not working	Unknown	Vehicle is operational, officers advised to utilise refidex until it's fixed.
12-Oct-16	Vehicle	245	OIC/workshop notified	Damage to side step as a result of difficult terrain. Scaped on uneven off road surface whilst extricating a patient. Side step not working.	Terrain.	-
13-Oct-16	Vehicle	215	Auto electrician has been contacted to rectify issue	Lights and suction unit not working post installation of PTT Satellite radio. Officer on duty notified OIC this am on his return to duty.	Unsure	-
13-Oct-16	Stretcher	210	REPAIRED BY	Crazy wheel function not engaging on one side only.	-	No patient involved when defect was discovered.
13-Oct-16	Vehicle	185	Vehicle off road	Vehicle in limp mode, as per same 1 week previous	-	Vehicle only just received back from mechanic following previous limp mode last week.
11-Oct-16	General Equipment	250	none. Unable to be fixed.	Broken red handle off Corpulse3 Cradle handle release lever	unknown - believed to have broken off after general wear.	V 5023.
13-Oct-16	Vehicle	235	-	Damage to rear step found at start of shift	-	vehicle 6517
13-Oct-16	Vehicle	200	Vehicle towed to RACQ Proserpine who checked fault codes on vehicle. One was apparently 'fuel rail pressure' other not listed mechanic said may be Mercedes specific code. Advised to check in to mechanic to have looked at possibly Mercedes mechanic.	Driving on highway through heavy rain vehicle suddenly lost power and engine fault light came on, unable to accelerate or steer vehicle and steering locked up, passively rolled vehicle to side of road safely. Same occurred in tip tropic mode.	Unknown cause, vehicle working properly prior to issue occurring.	Vehicle fault codes reset, vehicle able to be driven back to station without incident. OIC advised issue has occurred several times previously.
13-Oct-16	Vehicle	200	fault report filled.	Bent/damaged rear bumper passenger side corner.	single officer reversing vehicle night time poor weather, car low speed struck pole.	Poor visibility, heavy rain, night time
13-Oct-16	Vehicle	230	OCS informed and vehicle for repair tomorrow am 14/10/16 pre 1400 shift start	When main switch switched on in saloon, electrical gremlins playing havoc with the suction, vent, emergency beacons and main LED lights. ? Water ingress short circuit	Unknown. Water ingress?	-
13-Oct-16	Vehicle	185	-	Side Door where equipment is located, door difficult to lock. Spent 20 min at RFDS trying to close the door.	?	Needs to be fixed as it is a hazard
13-Oct-16	Vehicle	250	OOS	None of the 12V plugs have power and can not charge including charging the corpuls. Corpuls only has 100mins charge.	-	V 5024

RTI RELEASE

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
14-Oct-16	Vehicle	215	-	PA door passenger side window frame rusted completely through.		
14-Oct-16	Vehicle	215	-	Water leaks into vehicle when it rains or unit is washed Sharp rusty metal edges exposed posing risk to staff and public Reflective stickers missing from passenger door	Working environment Fraser Island Salt water environment	Photos forwarded to LASN fleet co ordinator Photo forwarded to LASN Fleet Co ordinator
14-Oct-16	Vehicle	215	-	Passenger door equipment pocket requires securing to inner door skin To enable storage of equipment	-	-
14-Oct-16	Vehicle	210	NA	R) side alley light not working, ?blown bulb	NA	-
14-Oct-16	Vehicle	220	corpuls technician has been contacted Replacement CORpuls recieved from ROma station at 1820 14/10.	This vehicle is not operational as defibrillator 1078 is not operational. No replacement defibrillator available.	-	-
14-Oct-16	Vehicle	240	Vehicle operational. OIC Aware sent for immediate repair at	OIC Aware sent for immediate repair at	-	-
14-Oct-16	Vehicle	230	Reported	1. Drivers side single red flasher on bonnet not functioning properly - needs replacing 2. Rear step damaged	-	-
13-Oct-16	Vehicle	200	Fault reports lodged	Rear bumper damaged, photo attached to vehicle checklist.	Fault caused the previous night by other crew backing into a pole	Fault report completed by crew that were working with the vehicle when it occurred.
14-Oct-16	Vehicle	235	Fault report submitted	Driver's side rear brake light is not working		Safety issue
14-Oct-16	Vehicle	250	Vehicle OOS	Leaking diesel under engine bay. Officers showed A/OIC 'puddles' of diesel they have found post jobs. Obvious leakage in plant room.		PTS manager notified.
14-Oct-16	Vehicle	245	hard reset, fault form, sort advice from PST who stated MDT issue	MDT loses power for no reason, is able to be rebooted and returns to job, however the problem is becoming more frequent during the shift and was once in need of a hard reset via side switch in side of truck	?	Will soon be not operational if not adressed
14-Oct-16	Stretcher	240	ROC notified. Pt transported on another unit and crew assessed stretcher at hospital, loading it into and out of ambulance many times with both officers sitting on stretcher. Release button slightly sticky occasionally but stretcher working normally now.	Patient loaded on power stretcher and connected to loading lift unit. Green lights indicated stretcher was in correct position but when the legs were lifted up, arms of power loading unit got stuck on stretcher legs. Then unable to disconnect stretcher.	Pt was moved safely to another stretcher. officers then able to better assess stretcher and noted the arms of loading unit had not connected to normal part of stretcher, ?arms slightly out of line due to some damage from past usage. Scuff marks on R leg.	Nil impact on patient care and nil injury to patient.
14-Oct-16	Vehicle	210	Taken to QAS WORKSHOP FOR REPAIR.	Left front blinker bulb is blown and therefore not working	-	-
15-Oct-16	Vehicle	195	staff advised not to use second stretcher attendant seat; vehicle plugged into 240v power	Module power resets when vehicle is started and screen in front cab turns off; passenger side attendant seat loose, only being held in place by 2 bolts.	?	-

RTI RELEASE

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
15-Oct-16	Vehicle	190	Corpulse has been swapped with another vehicle. The item was reported a week ago to the OIC and booked in for review however later noted to be charging correctly hence vehicle appt was cancelled due to pending other fleet needs.	Corpulse is not charging in the cradle.	Potentially the magnet is not making contact with the defibrillator	-
15-Oct-16	Vehicle	240	Unable to identify cause	Oil leak. Oil over engine bay.	No oil dip stick was in place and oil filler cap tight.	-
15-Oct-16	Vehicle	185	QAS officers checked to see if any circuit breakers were tripped and looked under the bonnet to see if there were any obvious broken wires. Nothing obvious found.	No power to module or in-vehicle radios. Vehicle fine at start of shift but early into the day officers noticed that the radios dropped out and on checking, no power to rear module.	-	Vehicle is able to be driven. All normal vehicle warning lighting, indicators, brake lights etc operational. V 5031.
15-Oct-16	Vehicle	240	I filled out this form.	Electrical failure whilst on a code 1 response. Vehicle lights, sirens, MDT and internal radio all had various faults and were no operational after initial functioning fine.	Dodgy electrics	-
15-Oct-16	General Equipment	240	-	Leaking oxygen cylinder in kit bag. Bodox seals replaced multiple times? Leak in white hosing. Empty seats cylinder in <5mins not safe for patient use	-	OIC replaced O2 kit - unable to repair zip
15-Oct-16	Defibrillator	200	Our vehicle used a corplus from another vehicle and reported fault to SOS. Print out of fault has been left attached to corplus and left OIC door.	When delivering a shock there is a print out stating no ECG available. Concern is that when preparing to shock a patient there will be no view of the ECG.	Full CF card	-
15-Oct-16	Vehicle	225	Nil at this time.	Vehicle over due for service, due at 90000 current mileage is 91419. Tyres are getting low on tread and vehicle is pulling to the left.	Regular maintenance.	-
15-Oct-16	Vehicle	210	Acting OIC/SOS notified, relevant paperwork filled out.	While reversing down QPS watch house driveway, backed into pathway railing causing dint to rear drivers side door. Nil internal damage caused to equipment.	Railing unseen and reversed into it.	-
15-Oct-16	Vehicle	245	Put out of service so mechanic can resolve	Dashboard light on, and low cool light on and consistently beeping. Also engine makes unusual noise in front right hand side.	-	-
14-Oct-16	Vehicle	200	reported	Stone hit to front windscreen right side half way up A pillar, has started to run down windscreen	stone hit by passing vehicle	N/a
16-Oct-16	Defibrillator	250	-	Front plastic around button has been damaged. Pulse lead damaged, still works	found at start of shift	-
16-Oct-16	Vehicle	250	SOS notified, vehicle out of service at Southport Station.	Dent to front and rear left tyre rims, pressure warning light on dash, side step not working.	Hit vertical curb at low speed (~20km)	Unknown vehicle registration. Unit 6523 single stretcher ambulance out of Coral Gardens Station.
16-Oct-16	General Equipment	215	leads switched	Corpuls lead malfunction- V6	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
15-Oct-16	Vehicle	215	attempted to reset and trouble shoot although failed	upon trasporting a patient to bundaberg hospital the vehicle went into limp mode	-	vehicle limped to bundaberg ambulance station for retrieval by mechanic
14-Oct-16	Vehicle	225	Repaired by auto electrics	Rear doors and side access door not locking, power button to side access door not operational	-	-
16-Oct-16	Vehicle	215	Checked hoses at suction end and no leaks.	Suction not very strong. Can find no leaks from hoses in vehicle.	-	-
13-Oct-16	Vehicle	235	Locker 16 has been leaking and items inside have been wet and now dry seal the unit	however smell so have been thrown out	water either from rain or washing. Most likely washing as it gets more washing than rain	-
16-Oct-16	Vehicle	185	-	Faulty side step	Possibly a high curb	authority V 5032. Vehicle is still operational. Possibly have unit to AFTER 7140 is back on station.
16-Oct-16	Vehicle	240	Rock and cons notified of situation.	Stretcher unable to be unloaded from unit on 2 seperate occasions with Mechanism locking ? Reason. After multiple attempts stretcher unloaded	-	-
16-Oct-16	Vehicle	195	Need replacement asap	Note vehicle starting comment. SOS notified and is seeking guidance from OCS and Fleet Manager.	Main battery has failed. Emergency start is working as required.	-
16-Oct-16	Vehicle	240	Changed for the spare.	Punctured tyre- rear right	Nail	Vehicle can be utilised if urgently required. Completed shift in vehicle (due to high workload), but placed OOS so that tyre can be repaired at first opportunity.
17-Oct-16	Vehicle	185	taken off the road until business hours, it can then be looked at. Will inform the OIC when he arrives for work at 0700hrs today	The engine went into reduced power mode while driving on a code one case. able to drive the vehicle back to Mareeba but the engine power was lacking under a load.	Engine management light on, though this might not be a new fault. seems to be the engine control system fault	OIC Mareeba advises vehicle is back on road. V 5033 for
16-Oct-16	Defibrillator	240	notified OIC.	SpO2 not working. Cable apples frayed / split	Unknown	-
16-Oct-16	Other Equipment	185	extension handset removed from radio > still operational without extension microphone	extension microphone damaged > plastic housing broken and wires not held into handset	unknown > found when came onto shift	OIC to log a job with to replace microphone.
17-Oct-16	Vehicle	230	Reported to CDS; OIC, and all forms completed by Officer	Damage to front grill, radiator and air conditioner	Vehicle collided with Scrub Turkey - driven by Officer	-
17-Oct-16	Vehicle	250	-	Rear door gas struts not holding up door	Could hear leak in Right side strut while door was up	-
17-Oct-16	Vehicle	230	notify OIC	Mobile phone not charging	unknown	But will go flat and not work
17-Oct-16	Vehicle	210	-	Car fridge keeps tripping and resetting itself. And not cold	-	-
17-Oct-16	Vehicle	200	-	Cracked windscreen	A large stone from truck hit windscreen and the heat of the car locked up has caused it to spread across windscreen	-
17-Oct-16	Other Equipment	230	A defective equipment form has been completed and Caloundra OIC informed.	The pager for unit 4771 is not synced to the vehicle. The pager is not able to recieve any of the job messages that should be coming through.	-	Incident reported as per OIC reporting officer -> not witnessed fault. CAPCODE: 0491395 Other Code: 11wKA51J0646
17-Oct-16	Defibrillator	240	Plugs unplugged and replugged. machine shut down and restarted, nil change	Initially showing "defective oximeter", able to capture one 12-lead ECG, then machine showing no ECG attached	-	OIC reviewed Corpuls and was able to replace SPO2 lead and coorec ECG lead issues.
17-Oct-16	Vehicle	235	-	Side step not working, MDT keeps turning off, windscreen cracked	-	-

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
26-Oct-16	Vehicle	205	Booked in for service on the 26th October 2016	A4 Service	-	-
17-Oct-16	Vehicle	240	New battery. Arranged for vehicle to be serviced at	Power module failed.	Module battery	Unit is losing radio and emergency lights
17-Oct-16	Vehicle	215	on the 18/10/16. Fleet technician to be made aware, staff at station using this vehicle notified.	105,000 km service due. Module side step not automatically extending and retracting when module door is opened and closed.	Operational use.	-
17-Oct-16	Vehicle	235	Vehicle taken to	Sprinter Passenger Side Sliding Door = wont stick / lock / stay in open position when opened.	?hook or mechanism faulty and getting worse = wont hold door open safely.	In addition to the current form the older style Vehicle & Equipment fault report form will be completed and emailed.
16-Oct-16	Vehicle	210	on the 17/10/2016 for review.	Dash warning light activated on start up. Vehicle in emergency mode	Nil	Discussion with manager of resource readiness when occurred. Vehicle defected and offline.
17-Oct-16	Vehicle	210	Checked all tyre pressures and filled to specs. Recalibrated warning system to new pressures, still active.	Tyre pressure light indicator on dash board.	Nil	-
17-Oct-16	Vehicle	210	Nil	Vehicle pulls to the left during driving.	Nil	Needs a wheel alignment
17-Oct-16	General Equipment	210	Notified OIC, using charger on station	The charging point on the charging bracket for the corpuls to be broken.	-	-
17-Oct-16	Vehicle	215	Called OIC (told about missing pager and flat phone) - took operational car	No pager (missing) and the phone battery is flat - nil communication devices	-	-
17-Oct-16	Vehicle	230	Car driven in slow mode back to QAS Nambour. Not suitable for emergency response but able to be driven. Unable to find resolution. Taken off road, parked at Nambour and signage placed on vehicle, keys and OIC Nambour informed.	Acute PTS crew and driving onto Bruce HWy when the accelerator would no longer power the car. Max speed between 50-80 kms/HR. Yellow engine symbol flashing at times. Nil other issues.	Unknown, worked fine for first 7 hrs of shift.	-
17-Oct-16	Vehicle	215	Fault report completed and mirror sticky taped together to hold	Right side mirror not holding together	Whilst reversing side mirror hit palm tree branch and bent backwards. Unavoidable accident and when pushing mirror back into place, mirror case fell off, some plastic clips seem to have broken. All parts still working just not staying on due to clips.	-
18-Oct-16	Vehicle	190	-	Load light not working	-	-
18-Oct-16	Vehicle	185	2nd bottle kept turned off to avoid alarms sounding and availability if required.	Slow leak from D size O2 cylinders, ?internal wall as unable to hear or feel gas escaping.	Unknown	Vehicle booked into today.

RTI RELEASE

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
18-Oct-16	Vehicle	185	2nd bottle kept turned off to avoid alarms sounding and availability if required.	Slow leak from D size O2 cylinders, ?internal wall as unable to hear or feel gas escaping.	Unknown	-
18-Oct-16	Vehicle	225	Returned to station and plugged in. Checked that it is charging, which it is. Changed into another unit to allow to charge until it can be looked at. Turned the volume up. Checked with OIC to see if it was a known fault. Not previously reported.	Vehicle takes a while to start after being on EA. Had to use emergency start 2/7 ago and vehicle has been on charge for 2 full days since then, however has been unplugged at night time. Started without fault yesterday but struggled again today.	When on station there's no issue, only after being on EA, not plugged in.	On 16/10/16 when returning from BFD vehicle would not start. Attempted to start using emergency start but failed. SOS instructed to turn key into accessory position and press emergency start 6 times and then attempt to start. This worked.
18-Oct-16	Vehicle	230	Lodge this report informed, oic and garage	MDT not making any sounds/tones when receiving jobs etc.	-	-
12-Oct-16	Vehicle	210	Booked in with	Windscreen damage drivers side	Stone	Vehicle requires windscreen repair
18-Oct-16	Vehicle	215		Front tyres and front disc rotors need replacing. Front scan lights and emergency beacons on the top left and right of patient care cabin not working.	operational use	-
18-Oct-16	Vehicle	240	VFRF submitted	Fire extinguisher needs servicing. Intermittent- when the emergency lights are turned on the siren automatically comes on but makes a sporadic squeal sound. This is not occurring each time the warning lights are used	Unknown	-
18-Oct-16	Vehicle	195	Checking as various times OSU contacted and a technician is due to assess on 19/10/16	MDT failure	unknown	There have been issues with 401 and 405 at different times with the emergency lights and siren. This siren often won't switch on at all when the vehicles are wet
18-Oct-16	Stretcher	195	form will come to get the unit prior to the commencement of the next PTS shift and do a service. Car will be taken by crew to	Stretcher relocated/repositioned by CCP & ACU observer student (1102). When placed pt on stretcher (secured on scoop) head end has dropped down to next locking position. Observer student stated did not think she disengaged red handle properly.	Potential user error	-
18-Oct-16	Vehicle	240		Oil leak and engine light	no	-
18-Oct-16	Vehicle	230		Side step not working.	-	-
17-Oct-16	Vehicle	245		Right rear taillight doesn't work	-	-
18-Oct-16	Defibrillator	235	attempts made to clean contacts and restart machine still reading the same	Spo2 probe showing defective cable and not working	-	-

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
18-Oct-16	Vehicle	230	DVR completed.	MDT turns itself off often, leaving us without case information, duress alarm and reverse camera. Can sometimes be activated back on after shaking MDT unit which is not appropriate. Rear doors....	Continued..... bottom catch needs adjustment as often activates emergency flashing lights whilst driving. Windscreen washer requires adjustment. Rides very rough in rear.....? Requires suspension check.	Another car to be serviced today (19/10). MDT fixed 19/10. Other dvr items to be fixed during service 25/10.
18-Oct-16	Vehicle	250	Some form of lighting when driving lights activated to show where buttons are located.	Nil illumination of emergency beacon and siren switches causes difficulty to see where buttons are located when driving at night time	-	-
18-Oct-16	Vehicle	215	Fault form completed	One stretcher missing and Corpuls missing SPO2 Cable	-	Corpuls removed from vehicle and placed outside OIC office
18-Oct-16	Vehicle	215	Fault form completed.	Stair chair latch broken causing stair chair to come in and out whilst driving making banging noise, also risk of jamming side entry/exit door so it can't be opened. SAT phone states 'no card'. Back passenger side red light out.	-	-
18-Oct-16	Vehicle	215	Fault forms completed, CDS notified.	Vehicle missing one stretcher, Corpuls missing spo2 cable, fault form completed and Corpuls placed by OIC door. Vehicle checklist completed however not all checks done as per form as jobs pending therefore moved out of vehicle and into another.	-	-
18-Oct-16	Vehicle	215	-	drivers seat suspension ?broken. very very bouncy chair even with adjustment of weight scale	-	-
18-Oct-16	Vehicle	240	-	Blown front left headlight	-	-
19-Oct-16	Vehicle	215	Take vehicle out of service	Low water alarm activated and low water warning light on dash board	-	-
19-Oct-16	Vehicle	200	-	Needs new rear number plate bulb and key batteries cr2025	-	-
13-Oct-16	Vehicle	220	Notification via report and verbal to OIC	Air conditioning in front cab not operating	Unknown	Long standing problem with many units of this model
19-Oct-16	General Equipment	210	NA removed from vehicle	Puncture in oxygen piping hence leak	Unknown, found it on pre shift vehicle check	-
19-Oct-16	Vehicle	215	Reported to OIC. Advise to take to mechanic	Missing spot light cover. Driver side mirror held on by tape, 'Rattle feeling' in floorwell of driver side ?driveline. No effect to drive of car.	Vehicle was at GIN GIN station. Unknown cause	-
17-Oct-16	Vehicle	235	Vehicle fault raised	Cracked windscreen	Unknown. Occurred driving through storm on Monday afternoon. Possible a small branch from trees along the roadside. Severe winds at the time.	-
19-Oct-16	Vehicle	240	One officer is used as a guide when reversing the vehicle for risk mitigation.	Reversing camera is displaced off brackets and mount.	Unknown	OIC notified.
19-Oct-16	Vehicle	225	Unit was taken straight to for investigation WARRANTY CLAIM FORM GENERATED TO	? centre bearing	Departing Hospital post case vehicle started making unusual noise under acceleration driven straight to	-
19-Oct-16	Vehicle	210		led driving lights not working.	Unknown	-
19-Oct-16	Vehicle	230	Removed scan light and placed on OIC desk	Rear driver side scan light knocked off	Backing vehicle at Nambour Pvt hospital knocked scan light on pillar	Accident report sent to Officer. ordering new scan light. Accident report now completed and forwarded to fleet manager.

RTI RELEASE

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
19-Oct-16	Vehicle	230	1) NOTIFY COMMS. OF VEHICLE ISSUE; REQUEST FOR VEHICLE BE TAKEN TO REPAIR.	INCREASED SLUGGISH EXCELARTION. INITIALLY NO INDICATOR LIGHT ON VEHICLE DASH.	UNKNOWN	* AT APPROX. 1700HRS TODAY UNIT 4858 WAS TAKEN TO WITH FLASHING ENGINE INDICATOR LIGHT ON VEHICLE DASH & INCREASED SLUGGISH EXCELERATION. UNIT ASSESSED & REPAIRED & RELEASED BACK TO CREW BY STAFF.
19-Oct-16	Vehicle	240	2) NOTIFY BUDERIM OIC OF VEHICLE ISSUE	LATER FLASHING ENGINE INDICATOR LIGHT COMES ON.	-	-
18-Oct-16	Vehicle	235	R) D cycliner has needed to be 'locked off' at the bottle each time to prevent further leakage.	Oxygen tubing leading to the R) D cylinder is faulty - continually leaks. Only noticed overnight, when cylinder would lose half a tank without use. Also, the bottom drawer in the IV station is jammed. Have tried multiple times to jimmy it open.	Unknown	-
20-Oct-16	Vehicle	230	Fault report Previous servicing. Notified all parties concerned.	Rear air con cool, not cold. Seems to struggle during the hotter hours of the day.	-	crew to take to for investigation
20-Oct-16	Vehicle	245		Non operational MDT.	ongoing issue	-
19-Oct-16	Vehicle	200	Comms and SOS Aware	POWER LOAD has system error solid amber LED showing. POWER LOAD did not engage when pulling strecher out of car at hospital, strecher returned into car and pt stand transferred. car returned and crew swapped out.	-	-
20-Oct-16	Vehicle	235	None as clip has broken	The small black clip/latch that holds the back right hand side door open has broken. Yellow arm is fine but the clip has broken preventing the door from being held open	Opening the back door normally at hospital time keeps moving & people keep using vehicle	-
20-Oct-16	Vehicle	225	-	Service due	vehicle	-
19-Oct-16	Vehicle	185	-	Cracks right hand side of windscreen	Stone chip	Will require replacement windscreen. Waiting on insurance claim from OIC to action. Insurance claim lodged 24.10.16
20-Oct-16	Defibrillator	240	Swapped rainbow and patient cable - fault continues. Job logged with Corpuls. Attending stn 20/10/16.	Fault - Defective Oxi Cable - recent Config update	??	SPo2 intermediate (rainbow) cable found to be faulty
20-Oct-16	Vehicle	225	none at this stage,will consult with OIC today who is away	may be a second battery fault. Vehicle started with power lead plugged in and on. Vehicle did start ok. Defibrillator was turn on	-	-
20-Oct-16	Vehicle	190	OIC and LASN manager have been informed. car dropped at	Hole in radiator.	? Rock	-
20-Oct-16	Vehicle	230	for repair	vehicle in limp home mode	-	-
20-Oct-16	Vehicle	185	nil at this time	Broken top and bottom hinges, bent middle hinge on module side access door	unknown	Reported by phone to oic. V 5047
20-Oct-16	Defibrillator	240	tested with new rainbow and patient cables - continues to fault	fault "Defective Oxi Cable" recent 2016 Config update	??	intermediate patient (rainbow) cable found to be faulty

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
19-Oct-16	Vehicle	210	OIC Notified	Stone chip in front windscreen	Car travelling in opposite direction drove over loose gravel causing a small stone to fly up and hit the windscreen.	-
19-Oct-16	Vehicle	215	-	60000 km service due. Main battery requires testing/replacement.	Operational use.	-
20-Oct-16	Vehicle	240	Quickly attended - unable to diagnose problem will pick car up for detailed look at wiring	Electrical fault - electrical items in rear / exterior of vehicle intermittently turning on/off.	-	-
20-Oct-16	Vehicle	245	-	Coming around corner and a loud popping noise came from under the car then the car lost power and went into limp mode. Engine light on permanently and flashing yellow	General wear and tear	We called Comms/OCS and we advised to limp it back to South Brisbane station. As soon as we got to Creek/Old Clveland Rd a burning smell came from the engine and lots of smoke. OIC Notified, OS and OCS. Tow truck came an hour later.
21-Oct-16	Vehicle	210	-	Caltex fuel card declined. Attendant stated card was not recognised as being valid. Card is still in date and has obviously been used previously.	unknown	-
21-Oct-16	Defibrillator	240	Nil	Connector clip that connects back defibrillator battery and screen broken, still able to clip together at this stage	Unknown	-
21-Oct-16	Vehicle	245	All parties previously notified.	Awaiting technician to repair/replace MDT.	Ongoing.	-
21-Oct-16	General Equipment	215	reported. Still able to utilise bracket until lever is repaired.	Lever on defibrillator bracket malfunctioned - In Unit 4402	? Spring missing from lever arm	-
21-Oct-16	Vehicle	225	Book in for service	Service required was due at 90000klm	-	-
20-Oct-16	Vehicle	225	none	side step stuck in locked position - when door opens the side step remains unusable	unknown	-
21-Oct-16	Vehicle	240	Taken to tech Dx and reset fault.	Engine light flashing	-	-
21-Oct-16	Vehicle	210	spoken with as above.	Engine light flashing on dash - spoke with COR and he advised vehicle would need to Go to Rockhampton on a tow truck to be looked at and fixed	Unknown - officer noticed vehicle was sluggish when driving up a hill to work in the morning and noticed the orange flashing engine light on arrival at station.	-
21-Oct-16	Vehicle	240	Mechanic has taken unit to check issue.	Master switch panel not functional front or rear. Also Reverse camera is showing blue screen on mdt only.	-	-
20-Oct-16	Defibrillator	240	replaced intermediate rainbow cable from spares stock held on station	fault "Defective Oxi Cable" recent 2016 config upgrade	-	-
20-Oct-16	Defibrillator	240	-	Brand new in box SPo2 intermediate rainbow cable used to test 2 x Corpuls 3 faulting with "defective oxi cable" alert. Alert continued and consulted and sent Tech to Kenmore station. Brand new SPo2 intermediate cable found to fault	-	Cable replaced under warranty by - advised other cables would not be warranty as cannot confirm age - ie advised warranty and life expectancy only 6 months
21-Oct-16	Vehicle	215	replace ASAP	Handset for UHF front radio - spring in button missing,, unable to be adequately pressed	missing spring in button - UHF front handset	Can be used,, but hard at times,, handset button is "floppy"
21-Oct-16	Vehicle	185	Fault form raised. Taken to mechanics.	Defibrillator not working, no spare	Vehicle not charging unit	V 5054.
21-Oct-16	Vehicle	185	Taken to the mechanics.	Vehicle not charging defibrillator.	Not known.	Defibrillator currently is flat. V 5054.

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
21-Oct-16	Vehicle	240	Unit not being used on shifts in reduced light...night or arvo shifts later than 6pm.	Not operational in times of reduced light as the top rear emergency lights illuminate when the headlights are on.	The cause may be the rear door is not closed properly (it has never closed properly) but it may be a faulty sensor and therefore triggering the EM lights.	-
21-Oct-16	Vehicle	195	reported to OCS / SOS, was advised to return to station and swap out of vehicle.	Rear airconditioner not working.	Unknown	-
21-Oct-16	Vehicle	210	Clean brakes with water spray.	When reversing and turning steering wheel past halfway to steering lock from straight, left front of vehicle makes Grunting noise.	-	-
21-Oct-16	Vehicle	200	OIC will be notified next Thursday on handover.	Engine slow to start, ? Battery issue. Main switch, fridge and radio turned off overnight. Was slow 2 weeks ago during ea, fine last week as what at station plugged in for ea.	-	Just had a service yesterday.
21-Oct-16	Vehicle	230	Notified Comms/OIC	Sliding door will not lock into place	Unknown	-
21-Oct-16	Vehicle	230	-	Side door not locking, unable to closer securely	-	-
21-Oct-16	Vehicle	245	-	As per discussion with OIC	-	-
20-Oct-16	Vehicle	245	This report, contacted OIC and ROC	Rear suspension not functioning as designed, brakes and steering need checking, glow plug warning light on since yesterday.	Not sure, age and road debris is my guess.	Reported by _____ for clarification of issues if required. I did a better report earlier but it didn't go through for some reason.
20-Oct-16	Vehicle	185	Fault form	Second draw in back jammed closed	unknown	Operational, however anyone taking this vehicle should take extra supplies that are located in that draw. V 5055.
22-Oct-16	Vehicle	245	-	Powerlifting stretcher can only be unloaded in manual mode MDT not starting	?Electrical fault. Appears auxiliary battery is not holding charge as voltmeter shows 13.2 when driving but drops to flashing low and 10.2 when stopped.	-
22-Oct-16	Vehicle	230	RACQ called battery replaced in vehicle	Flat battery	Main switch left on however watch house QPS staff have reported car used for watch house last weekend also ran flat for QASand needed RACQ. Vehicle technician from RACQ has tested battery and states it needs replacing as it is reading too low to recharge	RACQ called at 530am by CDs _____ and arrived at 0620 to Qps watch house.
22-Oct-16	Stretcher	230	Fault form	Load arm stuck up an half way. Repeated attempts at using manual mode before loading arms could be lowered to correct position to load the stretcher.	No know cause	Stretcher can't be used until fault is identified and rectified.
22-Oct-16	Vehicle	240	fault report form OC notified	Unable to start	likely battery / charging issue	-
22-Oct-16	Vehicle	215	We plugged the car in and charged the battery before use.	Cars battery was flat.	Car was not plugged in power overnight.	-
21-Oct-16	Stretcher	225	report to Comms vehicle is technically a single stretcher ambulance	unable to unlatch from vehicle	during a transfer the unlatch img button made a loud clunk and did not work	-
21-Oct-16	Stretcher	225	report to Comms vehicle is technically a single stretcher ambulance	unable to unlatch from vehicle	during a transfer the unlatch img button made a loud clunk and did not work	-
21-Oct-16	General Equipment	235	Resetting MDT	Buttons do not work on MDT. MDT receives information but cannot view it and it beeps constantly to let you know there is information to be viewed. All the red lights along the top are displayed.	Unknown. It happened on the way back from a job when trying to retrieve times.	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
22-Oct-16	Stretcher	250	Stretcher left at southport station and swapped for	Rear head rest hydraulic leaking and broken	-	No incident fault from stretcher no she report required
22-Oct-16	Vehicle	250	Soss contacted, vehicle taken off road, OIC contacted, fault form completed	Stretcher loading dock loses power	Unknown	-
22-Oct-16	Defibrillator	215	Checked leads connected correct.	Unit not showing 12 lead ECG, ECG not working	Unknown	-
22-Oct-16	Vehicle	245	Make this report.	Vehicle has trouble starting when ignition is turned on even though it has been driving all day. Only happens after short periods of not being plugged into charge.	-	Doesn't seem to be a car breaking issue at the moment but has the vibes of becoming worse as time goes on.
22-Oct-16	Vehicle	200	-	POWER LOAD failed to deploy stretcher during case. troubleshooting involved removing and entering stretcher manually, stretcher will not self raise legs. powerload reset, car turned on and off. car plugged into mains for 10+ hours today.	system error with powerload, solid yellow triangle present despite troubleshooting.	case today was a 1B hanging, same fault reported on wednesday and rectified?
22-Oct-16	Vehicle	250	Sos contacted, forms completed, vehicle oos	When responding code 2 and headlights are on, vehicles red beacons on top of vehicle are on and flashing. Traffic moved out of the way for vehicle while responding to job. Witnessed by 6160, qut student.	?Short circuit while headlights are switched on.	-
22-Oct-16	Vehicle	210	OIC and western SOS notified via Email, SHE incident report unable to be completed as website was not loading (also documented in email).	Scratch (approx 1m) to yellow reflector sticker drivers side module. Module itself is fully intact with no damage.	Incident occurred when driving forward out of a patients driveway gate. Full description recorded in OIC & SOS email.	-
23-Oct-16	Vehicle	225	racq attended vehicle and changed tyre for spare	Flat tyre	screw from road in tyre	Incident occurred on a Sunday and so was unable to take vehicle to a tyre centre to have the tyre repaired/replaced. Vehicle currently using the spare which is not to be used long term and also has no usable spare now in the event of another puncture
22-Oct-16	Other Equipment	230	Reported to sos	MDT continually loses power, also results in no gps	-	Vehicle currently at Pomona stun with a single officer operator
22-Oct-16	Vehicle	235	-	Equipment door will not shut properly. Requires multiple attempts to close. Needs to be slammed shut.	-	-
23-Oct-16	Vehicle	240	ROC was informed and advised crew to continue to Northgate station and utilise one of their vehicles for the remaining shift, and that vehicle will be fine for crew to drive back to Petrie at the end of our shift, despite crews concerns.	Front passenger side brakes worn down to metal on metal	-	Vehicle picked up and brake pads replaced 24/10.
23-Oct-16	Vehicle	210	Notified SOS of both issues risen above and vehicle has been taken out of service.	Vehicle checklist performed after first use of vehicle for the day due to getting a job immediately.	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
23-Oct-16	Defibrillator	230	Inspected line, disconnected and reconnected however didn't fix problem. Taken out of service, given to OIC and default form filled out.	BP error. On screen error 'inflation impossible'. BP cuff having trouble inflating and deflating, not producing a reading.	-	-
23-Oct-16	Defibrillator	215	Unit check de ok @ shift start. At first patient no connect with module wouldn't take BP. Split modules, booted all modules and individually shut each one down. Unit operational again. Double check at HBH issue reoccurred. Unit brought back to station.	Fault in recognising module. Unit not taking blood pressure won't shut down	-	-
23-Oct-16	Defibrillator	195	-	Pneumatic blockage with large bp cuff	-	-
23-Oct-16	Vehicle	195	-	Mains system not working - buttons in the back aren't working	-	-
23-Oct-16	Vehicle	185	To be taken to during office hours tomorrow - Monday	Left headlight U/S.	-	-
23-Oct-16	Vehicle	185	Nil	2 x large cracks to front windscreen	Unknown, found during checks.	Insurance claim lodged 24/10/16.
23-Oct-16	Vehicle	235	-	Passenger front low bean light blown	-	-
23-Oct-16	Vehicle	230	Reported	Reversing camera u/s	?	Screen remains blue when vehicle put in reverse gear
23-Oct-16	Vehicle	240	ROC notified	Vehicle had been on charge and not used for 2 days. During shift interior and exterior lights dimmed and stopped working and radio wouldn't turn on. ROC advised and vehicle returned to station out of service.	auxillary battery reading 9.4 when lights and radio stopped working.	-
23-Oct-16	Defibrillator	230	report lodged, Comms aware. Crew used another defibrillator	SPO2 sensor not working	? Cord fault > nil light on sensor, not registering on monitor.	Corpuls still able to be used on road. > ? New cord/ sensor required.
24-Oct-16	Vehicle	245	Previous fault.	Unable to log on!	Unknown.	-
23-Oct-16	General Equipment	240	Notified OIC, & checklist completed.	MDT NOT WORKING - BLACK SCREEN. OCCURRED THROUGHOUT SHIFT. Unit 501151.	-	-
24-Oct-16	Vehicle	230	OIC inform Comms notified - RACQ notified	Flat/dead battery or query alternator problems unable to be turned over ongoing issues not master switch involvement reoccurring issues with vehicles and communication equipment turned off to prevent power drainage	Unknown	-
24-Oct-16	Vehicle	250	none	Water Sprayer on windscreen wiper are not working	-	-
24-Oct-16	Vehicle	225	-	50,000km service due	-	-
24-Oct-16	Vehicle	230	OIC notified, fault reported and email sent through to for actioning	Cracked front screen	-	Will run into drivers vision if not replaced

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
23-Oct-16	Vehicle	240	Notified OIC, Written OOS on shift board at station for others reference & fault report for vehicle & general equipment has been completed.	MDT NOT OPERATIONAL - BLACK SCREEN.	-	OCCURRED DURING NIGHT SHIFT. ROC CONTACTED & OIC NOTIFIED. Checklist completed, unknown speedo reading above for unit, due to not being at station when completing checklist.
24-Oct-16	Vehicle	240	plugged in. turned of master switch and MDT.	flat battery	not plugged in by last user - Paramedic at Redcliffe Watch-house	-
23-Oct-16	General Equipment	200	Taken out of service	Frayed adapter cord	Wear + tear	Repaired
24-Oct-16	Vehicle	240	Nil	Casing from back of mirror broken off - traffic indicator not working	Rear of truck impacted with mirror - casing broken off - mirror functional	-
24-Oct-16	Vehicle	195	-	Windscreen chip, Washer bottle leaking.	-	-
24-Oct-16	Vehicle	230	Numerous repairs for same issue.	Power Issues causing the MDT, GPS, Phone charge, AM/FM radio, Siren & Emerg Lights to not work.	?Ongoing faulty wiring or battery issues.	Equipment Fault Report #6046 submitted by @ Pomona also relates to this fault report.
24-Oct-16	General Equipment	230	240v power source checked and power going to lead and CTEC.	CTEC Vehicle Battery Charger will not turn on or power up.	Unknown- ? faulty CTEC from normal wear and tear.	Given to from when he picked up Unit 903 for testing and replacement as per advise from Fleet Mgr.
24-Oct-16	Vehicle	230	None needs to be investigated by auto electrician	Reverse camera intermittently not working	-	-
24-Oct-16	Vehicle	215	nil	car stereo not working	unknown	-
24-Oct-16	Vehicle	225	inspection booked with mechanic CMS.	Smell of sulphur noted in vehicle plant room and within cabin of vehicle when entered. suspect leaking vehicle battery. (only vehicle in plant room at time).	? leaking lead acid battery in engine compartment.	Nil
24-Oct-16	Vehicle	250	able to temporarily fix the O2 door while at hospital however I have no knowledge about cars or if it has been fixed correctly. I have had an issue with the truck in the past where the O2 door would open while drive (very dangerous for other road users)	unable to close oxygen door (back drivers side) after opening it to change o2 tank. Also beep (like the O2 door is open/ the recharge plug is open) even when both are closed.....	back O2 door - ? the red metal flap is loose and falling out of its correct position.. im not sure about the beep.. spoke to a PTS officer who was in the truck a few days ago while at hospital and he advised that he had to turn the mains off all day.	Called OS who advised us to go OOS until problem has been fixed.. Unit driven back to Coomera station with out incident. Unable to fix the beep...
24-Oct-16	Vehicle	250	Changed battery with nil success.. vehicle has been plugged in so i dont think it is a charging issue.. driven back to station. CDS + OS notified	power stretcher arm (the bit joined to the car) has no power. orange light flashing on head end. unable to unload/load stretcher...	unknown cause. this unit was taken off road 2/7 ago for same... put back in service.	-

RTI RELEASED

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
24-Oct-16	Vehicle	250	Removed from service SOS notified OCS notified Fault form complete SHE form completed	Multiple faults 1. Rear door does not stay up due to faulty gas struts 2. Door open alarms continually going off despite all doors closed 3. Passenger side door light fitting mirror loose 4. Patient care draws (bottom door) does not lock	-	-
24-Oct-16	Vehicle	230	Changed truck to 4772 at Nambour station Spoke to at he said it sounds like an internal wire has snapped or let go and the unit will need to be repaired by them. Will liaise with GP to arrange repair/replacement.	Interior cabin lights non operational	Unknown	Unable to perform adequate patient care had to use torchlight in unit 852 for last patient monitoring
25-Oct-16	Stretcher	180	repair/replacement.	1 x wheel not unlocking when free wheel mode selected.	Unknown	-
24-Oct-16	Vehicle	245	Once patient handed over ensured O2 hosing connected correctly, still no O2 delivered into vehicle. Contacted Metro South OC, advised to continue on shift and utilise small cylinders if required.	In-Vehicle switch-over O2 tank switch not working. Attempted to switch over to second tank which is full during a case and no oxygen delivered	-	Empty tank replaced and O2 now able to be delivered into vehicle. Appears 2nd tank, hosing or change over switch not working.
24-Oct-16	Other Equipment	230	searched both vehicle and station, conveyed with all current staff as to potential for pager to have been taken home mistakenly	lost pager from vehicle 4961	lost	-
24-Oct-16	Vehicle	185	Oic notified for repair	L work light not working	Unknown	V 5061. OIC Edmonton to take vehicle to
22-Oct-16	Vehicle	240	-	Strap inside back of vehicle used to hold scoop to roof has snapped. unable to secure board.	-	-
25-Oct-16	Vehicle	245	-	Strong odour of diesel fumes in front compartment. Worse when aircon in operation.	-	-
25-Oct-16	Vehicle	250	plug in to charge as much as possible. Attempt to leave vehicle engine on on scene where safe to do so,	Electronics shut down. Immediately post switching off ignition the master switch to the main cabin, the radio and the MDT shut off. This reduces ability to respond to cases quickly,	unsure	-
25-Oct-16	General Equipment	250	Taken out of service and replaced.	Suction in oxygen kit not functioning - Unknown if suction unit itself or white oxygen cable attached.	Unknown - Found on morning vehicle check.	Unable to take off white oxygen cable to test suction unit on it's own to isolate the fault. OIC notified.
23-Oct-16	Vehicle	235	-	The car radio (for music) does not work (a safety issue when using the tunnels), the air vent does not work, and there is no fridge.	-	-

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
25-Oct-16	Vehicle	235	-	Deep chip in windscreen with approx 20cm crack. MDT screen is completely dead no luck switching MDT on/off or pulling fuses.	MDT screen connector in middle of cable was loose, MDT screen not coming back on after disconnect and reconnecting. Chip in windscreen at beginning of shift.	-
25-Oct-16	Vehicle	240	investigated briefly and advised needs to be out of service.	#NAME?	-	-
25-Oct-16	Vehicle	195	Vehicle taken to for repair.	Airbag has blown while stationery after refuelling at approx. 1700 hrs. Vehicle now at	Airbag deflation.	-
25-Oct-16	Vehicle	250	OIC and SOS notified as soon as incident happened	Chip to driver side windscreen, in line of vision	Rock flicked up into windscreen whilst driving on highway	-
25-Oct-16	Vehicle	195	-	Right head light out	-	-
25-Oct-16	Vehicle	240	ROC and RACQ notified	While driving on a code 1, both officers heard a loud vibrating sound coming from the rear of the vehicle. Officer who was driving noticed the vehicle wasn't handling as per normal. Rear left tyre Flat.	unknown	Vehicle was pulled over to the side of the road immediately when safe to do so and found the L rear tyre flat.
25-Oct-16	Vehicle	195	Comms and SOS advised.	Vehicle flashing engine warning light. In emergency mode.	Unknown, light came on while proceeding code 1.	-
25-Oct-16	Vehicle	240	-	Portable radio p1 fault. Intermittently cannot change channels. Keeps beeping. Can't select zone channel or status	-	Appeared to be fixed by removing extension mouthpiece and cycling power
25-Oct-16	Vehicle	240	Restarted car and reset MDT and radio with no change, kept car engine running for an hour with nil change to battery power	MDT and car radio not working, main battery and aux battery very low and not recharging	-	-
26-Oct-16	Vehicle	225	Advised OIC	Side step not working. It is stuck out despite all doors being properly closed as well as the override switch being used.	-	-
26-Oct-16	Vehicle	240	-	Rear roof emergency lights not working.	-	-
26-Oct-16	Vehicle	210	-	small LED emergency light in left of bonnet mount not working	unknown	-
26-Oct-16	Vehicle	210	This report	Gps maps Navman, locks unable to use then will return to normal only to freeze up agai	Unknown	-
26-Oct-16	General Equipment	230	-	Rear step not working, falls risk.	-	-
26-Oct-16	Vehicle	205	-	Vehicle 4922, Needs B service at 30000 km	-	-
25-Oct-16	Other Equipment	210	The flow metre has been removed from vehicle and placed in the OIC tray	oxygen flow metre fault - oxygen escaping out of flow metre whilst turned off.	-	-
26-Oct-16	Vehicle	185	Off road at end of shift	Airway chair in rear has ? Missing bolts?, balding tyres on outer side, tail light rear left not functioning	Na	A/OIC to arrange vehicle to go to V 5089. VEHICLE HAS BEEN DEOCMMISSIONED
26-Oct-16	Vehicle	240	phoned OIC, notified ROC, OOS to go to Northlakes	Weird wobbling noise coming from front R) wheel when over 60km/hr, turning and braking.	Unknown	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
26-Oct-16	Vehicle	240	Notified OIC	When unit 5534 is turned off everything in the unit shuts down MDT, radio, door actuators master switch and all AUX devices. Upon starting 5543 all systems have to be turned on again MDT has to reboot master turned on	?electrical or battery	Equipment operational only while unit is running
23-Oct-16	Vehicle	245	Problem solving - reposition leads, slow vehicle	Corpuls - transcutaneous pacing, intermittent failure if any vehicle movement.	.? Known issue with Corpuls	Monitoring and defibrillator-working as normal. Unit taken from vehicle to recover data
26-Oct-16	Defibrillator	195	Tagged the unit out of service and taken unit from vehicle 331. Kirwan OIC notified.	Oxy sensor reading defective cable. Still reading defective cable with new cable attached.	-	-
25-Oct-16	Vehicle	225	OIC notified, vehicle not turned on, keys left at service station with staff member, vehicle arranged to be towed to Kingaroy for tank to be emptied.	42 litres of 98octane filled into fuel tank of diesel vehicle.	Operator error.	-
26-Oct-16	Vehicle	245	Notified OCS	Flashing warning light on instrument cluster (vehicle manual says vehicle operating in emergency mode), vehicle lost significant accelerating power whilst driving, unable to reach normal road speeds, worse on ascent	-	-
26-Oct-16	Vehicle	215	fault report	Second battery goes flat very quickly, even after been charged for a long time	old battery?	-
26-Oct-16	Vehicle	240	OIC notified	Vehicle damaged post RTC entrance of	RTC post being struck by other vehicle rear L) panel	-
26-Oct-16	Vehicle	250	Pulled cover back off, checked connections, reattached. Turned off master switch and turned back on. Stil no power to screen.	MDT is not working - Front cover fell off whilst driving and when LARU officer put it back on, there was no power to unit. MDT master switch turned off/on with nil effect. MDT not operational.	Unknown	Email sent to 26/10/2016
26-Oct-16	Vehicle	240	ROC advised 16:10 of Front Passenger Door fault care with closing will be taken during shift.	At Start of Shift approx 16:20 crew noticed clicking sound to left front passenger door. Approx 16:00 the front passenger door has snapping noise & resistance on closing. 16:10 ROC advised as Precaution. Care will be taken with Door during shift.	Unknown	First time this has happened no problems with Front Passenger Door during previous afternoon shift.
26-Oct-16	Vehicle	210	Secured by tape - needs to be properly repaired	Side step light loose - still in working condition but hanging by wires	Unknown	-
26-Oct-16	Vehicle	230	Checked mains / fuses for fault, nil found. Created fault form, only used stretcher for pt access throughout shift.	Side step not functioning/releasing, closed in	-	-
26-Oct-16	Vehicle	245	-	Right scan light not working	unsure	Right scan light not working during afternoon shift.
27-Oct-16	Vehicle	240	-	Inverter not working	-	Has been last week for same fault. Found to working. Hence unreliable
27-Oct-16	Vehicle	230	-	Risk of not starting, high pitched noise coming from vehicle and chip in windscreen is getting bigger	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
26-Oct-16	Vehicle	230	Officers called into and Mechanics advised not to use, fan parts and replacement required and will be picked up Thursday 27.10.16 for repairs.	Airconditioning Unit Faulty	As stated by PTO - returning from Brisbane when unit stopped working and was making noise like truck air brakes locked on.	from fully aware of fault and plans. Vehicle required for Noosa Triathlon on Sunday 30.10.16
27-Oct-16	Vehicle	185	taken off line. Replaced by a spare unit.	Portable oxygen pack. Flow rate control knob at odd angle and difficult to turn.	no.	I cannot confirm that the flow rate show at the dial is what might be delivered.
26-Oct-16	Vehicle	185	OIC aware	Right headlight blown and kit side door difficulty shutting	nil V 5091. OIC Cairns to arrange	vehicle to go to V 50991 & V 5092
26-Oct-16	Vehicle	215	Assesed by	Air con is not working properly - AC is only blowing warm air regardless of the temperature setting	-	-
26-Oct-16	Vehicle	250	Flat form	Broken radio Ariel snapped from base	-	-
26-Oct-16	Vehicle	240	-	Portable radio 501374P serial number 481CPZ9653.	-	-
27-Oct-16	Vehicle	230	None	Radio is missing the channel selection knob on top. Unable to select ch unless you remove radio from pouch an manually enter ch an select.	-	-
27-Oct-16	Vehicle	225	Temporary repair. Working so far. Needs to have the alarm reset button pushed each time the vehicle is put into drive.	Rear parking camera screen not operating (blue screen only)	Rear door sensors are tripping alarms. It was assessed by and it requires new sensors.	-
27-Oct-16	Vehicle	215	It looks as though the marks are from the front of another vehicles bumper and should be able to be buffed out, however the battery compartment door has sustained scratches and the hinges may need to be checked	Vehicle has been swipped by Unknown vehicle on drivers side, rear compartment. First noticed 27/10, however unsure when incident occurred. Both officers checked vehicle surrounds Monday and can confirm that there was no mark or damage noted then.	Unknown vehicle, unknown location and time	-
27-Oct-16	Stretcher	230	Loaded and unloaded multiple times	Head end of stretcher legs failed to engage when taken out of vehicle, and during same incident, once pt onboard stretcher at a lowered height, stretcher was lifted while pressing red leaver at headend resulting in failure of headend legs from disengagi	Unknown	-
27-Oct-16	General Equipment	215	Battery change. Restarted. Nil resolution	4403 pager fail.	-	-
27-Oct-16	Defibrillator	240	Unit removed from service.	Corpuls displaying alarm Defective Oxi Cable, pulse oximetry not operating.	Unknown.	-
27-Oct-16	Vehicle	240	notify OIC	Engine warning light on.vehicle losing power slightly. Front left park light out.	N/a	Have spoken to mechanic who advised is a glow plug issues will take to mechanic this am. Glow plug replaced and vehicle now operational.

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
28-Oct-16	Defibrillator	225	Corpuls removed from vehicle (3175) and COMMs notified. OIC replaced SPO2 cable, Corpulse back in service	SPO2 monitor not working	-	-
28-Oct-16	Stretcher	215	Stretcher removed from 4403 and replaced with spare from BBH DEM. Noted placed on stretcher	When engaged in locking mechanism, difficult to unengage (press red button) to unload. Difficult loading, required heavy force to fully engage in locking mechanism.	-	-
28-Oct-16	Vehicle	185	OIC NOTIFIED contacted to ensure part available	Bonnet strobe on the drivers side not working properly just visible.	Unknown V 5093.	-
28-Oct-16	Vehicle	185	Notification	Rear drivers side check strap to rear door broken	Normal operational use V 5092.	-
28-Oct-16	Vehicle	235	Notification	Chip in lower middle of windscreen	Query stone chips	-
27-Oct-16	Vehicle	240	are going to attend Roma Street station and fix this	No headlights just side lights	No	-
28-Oct-16	Vehicle	230	Tow truck booked, fault form completed. Vehicle turned off, key removed, then restarted to attempt a reset. Several times.	Engine will start, but no power.	No	-
28-Oct-16	Vehicle	240	report to OIC	Loan unit 502364 right indicator light un-serviceable and does not flash	electrical as rear LED does not flash either	Vehicle can not indicate that it is turning right and requires repair
28-Oct-16	Vehicle	185	Removed draw from vehicle	Bottom draw of attendant cabinet hinge broken	-	-
27-Oct-16	Defibrillator	215	It is to notify an issue with Corpuls 3	The patient was having AF and multiple times the machine gave a VT/VF alert.	-	General recommendation of documenting each time a fault occurs with Corpuls machine in regards to its reliability - last night the VT/VF flashing red light and beeping kept happening at home and during transport and case no.:8137070
28-Oct-16	Vehicle	240	Nil	Chipped windscreen	Stone thrown up by passing vehicle	OIC has spoken to mechanic and vehicle booked for service 2/11 and will be repaired at that time.
28-Oct-16	Vehicle	230	nil	Engine light on vehicle dash illuminated.	-	Also exhaust appears to be expelling more black smoke than usual.
28-Oct-16	Vehicle	240	put towels over Pt and notify OIC	Water drips from the right side of 5543 onto patients from the Air conditioner	condensation building up inside the a/c condenser and leaking from the roof	-
26-Oct-16	Vehicle	210	Temporary fix with sticky tape.	Small magnet on vehicle charging port has fallen out. Currently being held in place by sticky tape. Vehicle won't start without magnet in place.	-	-
28-Oct-16	Vehicle	185	notified on 28/10/2016 and vehicle taken to for investigation.	in car vehicle radio issue. in car radio turning it self off and on when transmitting a message via the portables or the in car handheld. When vehicle is turned on and running nil radio issues noted.	-	V 5098 - POSSIBLE BATTERY FAULT???
28-Oct-16	Stretcher	240	exchange stretcher	Foot end collapse to floor from bottom latch point, knee support collapse on cot a	unknown , knee support collapse under weight of legs (large oedema)	-
28-Oct-16	Vehicle	230	CDS advised,	Air con u/s in rear compartment	-	-
28-Oct-16	Defibrillator	230	removed from service - replaced with Corpuls from OIC vehicle	Hinge on printer door is broken on one side - leaves the print head not in contact with paper roll and therefore doesn't print.	Found with plastic hinge broken during vehicle check on 401789 at 1800hrs	-
28-Oct-16	Vehicle	240	non	Damage to rear step	contact with concrete pillar	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
28-Oct-16	Vehicle	230	Advised OIC, jump charger strapped into vehicle	Vehicle charging unit does not appear to be charging vehicle, vehicle battery flat at start of shift.	Possible remote charger not working	Charger not operational
29-Oct-16	Vehicle	225	Ni	Rear right Red LED is US on the Light Bar. Left one works when ALERT button pressed, Right and Left do not display when PRIMARY is pressed (Rarely used)	Unknown	Serviceable as the rear still has visible red LED. Will need replacement at next avail opportunity.
29-Oct-16	Vehicle	185	-	Side oxygen door not opening, car unlocked, still doesn't unlock when vehicle is turned on. Light flashes when trying to open	- V	5101.
29-Oct-16	Vehicle	230	dvr and vehicle checklist	Vehicle mobile phone screen is cracked and unreadable	unknown- vehicle was not used previously by current crew	-
29-Oct-16	Vehicle	200	-	Wall mounted airway kit casing has come apart and is falling open. Will not stay closed, the plastic has come out of the vinyl casing.	-	This really needs to be fixed as equipment from inside the kit is falling out into the ambulance.
29-Oct-16	Vehicle	190	OIC advised	Radio mic works, but requires replacement	unknown	-
29-Oct-16	Stair Chair	210	-	Out of service test date	-	Nil incident, stair chair out of test date
29-Oct-16	Vehicle	235	-	small Square emergency strobe above passenger side of roof not functioning. also a short in the clearance lamps along passenger side of vehicle when emergency beacons are activated.	?	-
29-Oct-16	Stretcher	210	-	Out of date for service	-	Nil incident,
28-Oct-16	Vehicle	210	Tried to reset, GPS frozen	GPS frozen, can not turn off	-	-
28-Oct-16	General Equipment	185	Replace	X2 zips fell off Minor trauma kit.	-	Barely Operational. Cannot be carried as designed
29-Oct-16	Vehicle	185	This has been a long term issue and has been reported some months ago.	Side step does not retract as designed. Vehicle needs to be running for some time before step retracts or vehicle needs to be plugged into 240v for some time before step retracts.	Electrical problem and step tracks needs wiring.	At times the vehicle is required to be driven with step extended thus increasing the risk of damage to the step and bystanders near the vehicle. This concern may also breach TORUM Vehicle Standards.
29-Oct-16	Vehicle	235	Vehicle has been taken out of service	Coolant level below minimum level. Visible fluid leak. "Low water" alarm sounding	Not known	-
29-Oct-16	Vehicle	185	SOS and Comms notified, fault reported. Car taken off road at Edmonton and bonnet left up.	Car working fine during morning of shift. Nil hazard lights present. SOS and coms notified of issue. 7182 taken to Edmonton station. Crew changed into 7147. Note - Vehicle checklist not formally completed in morning due to case dispatch at 0713.	-	VEHICLE BEING TOWED TO 31/10/16. V 5102.
29-Oct-16	Vehicle	245	Checked coolant, does not appear to be low, however cds notified and advised to leave car at station	Low coolant alarms going off	-	-
29-Oct-16	Vehicle	240	Tried to reset the vehicle by restarting it 3-4 times as per manual with no improvement.	Engine light flashing, vehicle in idle mode	unknown. Vehicle was recently refuelled before fault light appeared.	ROC notified and vehicle driven to Roma street station in idle mode
29-Oct-16	Vehicle	215	-	Back door ?not closing properly . R) Latch appears not connect . Rear air conditioning Not working. Blowing room temperature air	Nil	-
29-Oct-16	Vehicle	225	Comms notified, OIC notified. Fault tag attached	Car is not accelerating fully. Will not rev past 2500 with full throttle. Feels as though 1/4 throttle is being used when full throttle is used. Car turned off then restarted will no improvement.	-	-
28-Oct-16	Other Equipment	230	Turned unit on and off - seemed to fix unit	MDT not sending information consistently to CDS. Returning to home screen after pushing on scene / at station and not sending the information. This likely happened when logging on unknown to us.	Unknown	-
29-Oct-16	Vehicle	210	-	Dent and scratches to unit 2335's bullbar, snorkel and bonnet	Unknown - vehicle is back from being swapped with Tieri	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
30-Oct-16	Vehicle	240	Driven back to station and put out of service.			
30-Oct-16	Vehicle	240	Roc contacted attempts to turn it on	Left front tyre flat Vehicle radio does not turn on	Tyre vs bolt from previous mvc -	Accurate speedo Unknown as unable to pull up with flat tyre error message able to use hand held radio effectively
30-Oct-16	Vehicle	240	The charger is also exposed to weather which I doubt is appropriate for this charger.	Plug from SMART charger separated from lead.	This is a domestic charger of poor quality and unsuited for the application it currently used for. Not designed for frequent and repeated plugging in and out.. Typically the charger can be connected and disconnected several times a shift. Lead caught in door and connection ripped off and charger ran over.	-
28-Oct-16	Vehicle	240	Replacement	Battery charge broken		Damage reported to Rock and OIC
30-Oct-16	Vehicle	195	SOS and OCS have been notified of issue and out of service tag applied to car key area.	Warning light flashing "low coolant" and alarm sounding on initial start up of car.	-	-
30-Oct-16	Vehicle	230	Nil	1. MDT NOT PRODUCING AUDIBLE ALERTS. 2. FM radio (stereo) not functioning at all	Not known	Marginal. Risk of cases or case updates not being received by crew as no alert to bring this to our attention. Higher risk during daylight hours as not as visual contrast is obvious when new cases or updates are received due to glare in cabin.
30-Oct-16	Vehicle	215	She report and fault form	Side rear driver side light torn off and scratching to rear of compartment.		Single Officer with no reversing guide and plant room is reverse in only with small turning area.
30-Oct-16	Vehicle	185	-	? Battery fault. No interior lights or emergency lights working Faulty side step. Gets stuck when coming out and requires pulling out manually.		
28-Oct-16	Vehicle	235	Nil known.		Unknown.	
30-Oct-16	Vehicle	235	-	Left headlight and right spotlight not working. R headlight out, stretcher wheels not always coming down when leaving vehicle, side step making very loud noise.		
31-Oct-16	Vehicle	240	-			
31-Oct-16	Vehicle	230	Racq called to SCUPH and replaced damaged tyre with the spare	Back left tyre had a nail in it, noise from tyre on the ground and slowly deflating	industrial nail	Replacement spare required
27-Oct-16	Vehicle	230	Fault form	MDT turns off after car engine turns off	? Car battery issue	401954 will call into today when clearing NGH.
31-Oct-16	Vehicle	195	-	Side Step not operational	-	-
30-Oct-16	Vehicle	215	-	Reversing Camera not working	Working environment	-
31-Oct-16	Vehicle	225	-	When turning main switch on on the front panel the interior high light always comes on. The switch appears loose and has to be wriggled back and forth to get it to turn off.		This happens every time you turn the master switch on despite light being off when the master switch is turned off. This problem has only been occurring over the last week or two (was handed over by officer 9151 last Thursday on changeover day).
31-Oct-16	Vehicle	195	Taken to to be fixed. Comms, OIC and Fleet Manager notified.	Rear door lock not releasing unless unlocked by key. Linkages need adjusting.	Linkages in rear door.	Operational by key to unlock. Door will not lock or unlock by remote control.
31-Oct-16	Vehicle	230	Taken to to top up oil and disconnect light will review light and switch tomorrow as service	Low engine oil and scan light switch broken, taken to for top up and disconnect light, service due tomorrow and will review light and switch than.		Laised with These items will be fixed during service on 1/11

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
31-Oct-16	Vehicle	215	Notified and to have it repaired. will organise for windscreen repairer at Agnes Water to fix on 1.11.2016 at 0900am.	Crack in windscreen between drivers side and passenger side, bottom of windscreen. Does not cause vision problems.	? stone of some sort.	-
31-Oct-16	Vehicle	225	-	Electrical safety certificate out of date on electrical panel in vehicle.	-	-
29-Oct-16	Vehicle	240	Cleared Code - Monitor	Engine Light Flashing	-	-
31-Oct-16	General Equipment	230	OIC called earfsupport - not able to be rectified. TB000749 taken out of circulation and to be swapped out	Toughbook does not turn on. Works only if plugged in however there is no charger in vehicle.	Unknown	Nil email required. Swap out arranged by phone and OIC Maroochydhore awaiting a replacement Toughbook
31-Oct-16	Vehicle	245	We tried to clean it with a gurney in case there was an obstruction in the tracks at the instruction of our OIC. This report given the gurney didn't fix the issue.	Side step not operating. Unresponsive in the retracted position	Unknown, item was operational at PAH and not operating when we arrived at destination while driving we heard what sounded like something hitting the underneath of the vehicle on that side but we can't see any damage or debris.	Side door was also not functioning prior to the step ceasing to function, would not open even though the mechanism sounded like it was disengaging for door to open. Possibly unrelated but want to give as much info as will fit character count.
31-Oct-16	Other Equipment	240	Notified OIC	Waste bin broken/unhinged and won't reconnect to shelving	Unknown ongoing issue.	Repairer aware of issue and has remain broken due to supplier going into receivership and nil fault form create. Repairer will attempt to fix this week.
31-Oct-16	Vehicle	210	The vehicle has been taken to local mechanic as requested by	Whilst driving back into town transporting a pt, the car began to make knocking noises, increasing in number over time.	Unknown	-
31-Oct-16	Vehicle	230	Fill out vehicle check list email oic	Bracket that holds D cylinders in broken	Wear and tear	The bracket has been fixed and the vehicle is operational.
31-Oct-16	Vehicle	250	Removed from service. Comms and oic notified. Paper fault form completed and emailed to oic	MDT stopped working approx 1 1/2 hrs into shift. Also this means there is no reversing camera.....2nd officer unable to assist if treating pt. On return to station centre console warning message," low coolant" and " high engine temp"	Unknown	Secomm did not consider these vehicle faults to be issues for an out of service request. Photos supplied on email to oic. Completed at later time , speedo details Unknown
31-Oct-16	Vehicle	245	-	Left headlight out	-	-
31-Oct-16	Vehicle	240	None at this stage	Paint scrap and slight dent to left side door	Ran into yellow bollard at TPCH while reversing	None
31-Oct-16	Vehicle	195	Vehicle sent to for repair.	Rear suspension failing to inflate the air bags therefore no rear suspension.	Right Height Valve failure.	-
31-Oct-16	Vehicle	185	-	Siren not functioning correctly. Siren sound turning off while switch still in on position while driving and siren only functioning intermittently.	-	-
1-Nov-16	Vehicle	230	Fault has already been reported but not fixed	Side step does not work	-	-
31-Oct-16	Defibrillator	225	-	Safety technical Check due 10/2016, not yet complete.	-	Contacted help desk and advised technician would call back OIC. 02/11/2016 called back and was advised that this unit was not due for service 02/2017.

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
1-Nov-16	Vehicle	230	Fault raised multiple times.	Vehicle reverse camera intermittently working, fault raised multiple times	Unknown	Camera working intermittently, ? Possible replacement required or Auto electrical intervention required to problem solve. Vehicle still in operation, however with camera not functioning appropriately.
9-Nov-16	Vehicle	190	Nothing - unable to repair at station level. Both officers aware	Windscreen washer bottle has split and does not hold water	Unknown - wear & tear	Does not directly affect vehicle's readiness but does require replacement
8-Nov-16	Vehicle	200	Attempted to straighten out the step.	Bent rear step/bumper assembly.	Entering rural property in Bloomsbury there is a rise into front from roadway and the back end of vehicle bottomed out scraping on ground.	-
12-Nov-16	Vehicle	195	Report	UHF and vhf not turning on and module power for interior light not working	Something wrong with the module	Radios came on after switching of car power on and off. Suspect battery possible?
14-Nov-16	Vehicle	250	Rear tail light replaced	Drivers side rear indicator damage - indicator still works, cover has been broken	-	Unknown date of incident, seen and fault form complete this AM
13-Nov-16	Vehicle	240	-	MDT and radio shutting down - check aux battery	-	-
14-Nov-16	Vehicle	210	defect form issued. Car is still in operational use.	Left front head light is faulty, scratch/crack on back side panel, step going into rear cabin makes a grinding noise when opening and closing.	-	-
15-Nov-16	Vehicle	210	Multiple attempts to lock door.	Personal side access door to module on left side does not lock.	-	-
17-Nov-16	Vehicle	200	SOS advised.	Crack in front cross member	unknown ?? damage from driving over something. Found yesterday by tyre fitters when putting new tyres on unit.	-
16-Nov-16	Stretcher	250	Reported to Acting Operation Supervisor who inspected and put stretcher off road. called by Officer	Damage to right rear wheel housing	Stretcher was lowered to allow patient to walk to hospital bed and on raising stretcher, heard sudden grinding noise. Stopped power raise immediately and noted male seat belt clip had inadvertently become locked onto wheel housing nut.	Incident occurred at approximately 0900 yesterday and technician reviewed in pm. to fix today
18-Nov-16	Vehicle	210	Reported	2 x Crossband radios not connecting or transmitting through radio	Unknown	QAS OIC IS GOING TO CHECK OUT AND NOTIFY.
19-Nov-16	Stretcher	230	STRETCHER REMOVED FROM SERVICE AT NGH, CDS AND HLO NOTIFIED	STRETCHER COLLAPSED AT LOWEST HEIGHT AFTER PATIENT SAT ON IT	-	NIL INJURY TO PT
25-Nov-16	Vehicle	200	-	AUX battery not holding charge	-	-
28-Nov-16	Vehicle	215	Fleet notified	Air conditioner working intermittent	-	-
2-Dec-16	Vehicle	210	It is believed that vehicle was only returned yesterday from having step fixed/replaced	Fridge not working . Vehicle plugged in fridge switch on. No cooling in compartment. Sidestep only working when switch turned on and off. No automated retraction, feeling unstable slanting approx 30 degrees downward when stepped on.	-	-
12-Dec-16	Vehicle	235	Check and replace if required	Brake wear light on the dash advised to visit workshop	Unknown	-
5-Dec-16	Vehicle	215	Nil	Broken car stereo	-	-
5-Dec-16	Vehicle	215	Nil	L&R alley lights will not turn on	-	-
6-Dec-16	Other Equipment	230	Station and car have been searched without any success	Both pagers from vehicle 4959 have been declared lost????, indications are that they have been missing for some time!	Unknown	-
6-Dec-16	Vehicle	210	Defect report	The small driving light located under the right indicator light has a blown bulb. Vehcile warning panel also advises of the same	Unknown	This defect could be corrected at the same time as the steering wheel is repaired. Nil significant impact on lighting capability. Vehicle is operational.

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
5-Dec-16	Vehicle	225	Need to be assessed by auto electrician	Rear door closed sensor not working. Vehicle has open door alarm and alert on screen.	? faulty door sensor	Warning alarm turns off after approx 2mins
14-Nov-16	Vehicle	180	Auto electrician visited and they'll attend to vehicle as soon as workload permits.	LED emergency lights on the bullbar come on when driving lights are turned on. L sided blue light only turns on - does not flash and only the bottom two of the four leds turn on.	Vehicle inspected by Auto Electrician 16/11/16 and found burnt out earth on the Front bullbar emergency LED.	Further investigation revealed Emergency lights all still work when activated however some flash out of sync with the others and some simply do not flash but remain on.
15-Nov-16	Vehicle	250	N/a	Side step not working. Will not come in and out automatically	N/a	-
15-Nov-16	Vehicle	230	Turned car and MDT off and on again. Ensured leads properly connected - nil effect.	MDT frequently switching itself off while driving. Switches itself back on after brief period.	-	Operational while working..
20-Nov-16	Other Equipment	230	None,	Charging cable in vehicle was found broken by day crew on Saturday 19th	No idea, found like this	Cable replaced
20-Nov-16	Defibrillator	230	Reported to CDS/OIC	Printer unit not printing correctly	? Impact to underside of unit	-
21-Nov-16	Vehicle	210	Vehicle checklist and fault form completed	Left parking light not working	NO	-
20-Nov-16	Defibrillator	185	Emailed OIC to ask about replacement cord, filed fault form, will ring OIC when they start shift	Alarm on screen that says 'defective oxi cord' and SPO2 cord stopped working halfway through treating patient, when double checking back at station cord was working again	Unsure	Rest of corpuls working and SPO2 cord works intermittently.
21-Nov-16	Stair Chair	185	Swapped from 7104 to 7283	Missing foot strap	Found missing during vehicle check	-
21-Nov-16	Other Equipment	230	Unable to rectify	Charging point damaged. Unable to charge phone.	-	-
22-Nov-16	Vehicle	240	Previous fault forms raised	MDT intermittently turning off for periods of time before restarting itself, occurred whilst driving to code 1 job	-	Hinders appropriate response times
22-Nov-16	Vehicle	225	-	Radiator reserve bottle leaking	-	Requires investigation, next service due at 180000klm
22-Nov-16	Vehicle	215	Battery tested at and found to have low voltage. Fleet Coordinator advised. New battery to be supplied by	Radios switching off and side step did not work when vehicle was turned off.	Auxiliary battery may need replacing.	-
22-Nov-16	Vehicle	230	Crew, attempted reset which was unsuccessful, then phoned CDS to attend who concluded they couldn't fix the issue	MDT suddenly switched off during shift and despite system reset remained so. Able to log on with nil issues though.	Unknown	-
22-Nov-16	Other Equipment	215	moved pager to OIC in tray.	Positive anode on pager broke during installation of new battery.	previous people jamming batteries in.	-
23-Nov-16	Vehicle	230	Buttons on MDT do nothing when pushed. Switched on/off MDT switch in (R) side panel with no effect.	MDT U/S. Screen shows black screen with white text "The last attempt to resume the system from its previous location failed. Attempt to resume again?"	-	-

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
23-Nov-16	Vehicle	200	Notified SOS advised to remove from service and await return of LASN Mechanic	Rear Barn doors cracked out. This causes a loose connection resulting in the activation of the rear beacons when driving on the road. This causes confusion to other road users.	Cracked out door	-
23-Nov-16	Vehicle	240	Note made and have swapped vehicles being a night shift ambulance not used vehicle still operational	Front left headlight not working	? Defective bulb	-
23-Nov-16	Vehicle	245	none	A) Steering wheel making knocking sound when turning either L) or R) - started when turning right. B) 240 volt alarm keeps going off. ?? electrical connection loose on outside inlet.	unkown	Left operational - however probably prefer to use another truck if available.
24-Nov-16	Defibrillator	240	Monitor taken from OIC car for remainder of shift. Defective monitor taken off road.	Defective Spo2 monitor. Cables replaced 2/7 ago (cable attaching probe to monitor). Continual SPO2 failure. Attempted different probes/ turning monitor off/ on. ?? issue with monitor itself, not cables. SPO2 failed 1/2 way through a case.	-	-
11-Nov-16	Vehicle	220	Notified OIC	No tail lights, number plate lights or clearance lights on module part of vehicle. Vehicle not roadworthy.	Unknown	Repaired in Nov 2016
14-Nov-16	Vehicle	210	Reported to SOS, fault report completed	Back door does not lock	Lock does not work	-
21-Nov-16	Vehicle	225	-	Vehicle requires 45000km service.	-	Routine service
24-Nov-16	Vehicle	240	Fault and accident report forms, ROC advised	Step housing damaged	Drove concrete manhole cover within prison grounds on grass road	-
24-Nov-16	Vehicle	210	NA	Reversing camera monitor not functioning normally - turns on automatically when vehicle is placed in reverse but has a blue screen with nil visibility of objects behind vehicle	Unknown	Nil faults with vehicle, only reversing camera/ monitor
25-Nov-16	Defibrillator	210	02sat probe replaced with new one. Fault form filed	Printer stopped working partway through a defibrillator shock admin test. 02sat probe not working.	-	-
26-Nov-16	Stretcher General Equipment	240	Document, stretcher serviced and lever repaired by servicing crew.	Broken red release lever cable has come adrift from fitting	Broken by other crew.? Who handed over stretcher with retrieval team equipment attached	On arriving lch to pick up retrieval team officer from other unit had child stretcher Instu and insisted we take over her stretcher . Was after she left that I was informed of damage to stretcher
26-Nov-16	Equipment	235	-	Fridge in rear compartment of 6645 is not operating and not cooling	-	The vehicle is still operational juts the fridge not working
26-Nov-16	Stretcher	235	Taken out of service and at Ipswich station	When unloading from dual stretcher vehicle, stretcher collapsed head end down (no patient on board at the time) Radio intermittently transmitting. When PTT depressed, handset displays error 'Cannot Transmit'. It appears that middle green light on handset is staying on constantly.	-	-
27-Nov-16	Vehicle	210	-	-	-	Intermittently operational.
5-Nov-16	Vehicle	215	OIC notified	Rubber Join between Cabin and Module pouring water through from rain Aircon defective. Not working in either crew cab and rear of vehicle. AC display flashing LP. Blowing warm air	-	-
27-Nov-16	Vehicle	240	Reported	-	Unknown	-
27-Nov-16	Vehicle	195	SSR Raised	Top cannulation drawer, lever broken. Officer spence went to open drawer at beginning of shift and noticed unlock/lock lever loose, not attached.	-	SRR sent 29/11 for repairs

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
27-Nov-16	General Equipment	210	Removed extension and replaced with an operational one	Power cord extension to plug into vehicle does not work	Unknown	Faulty cord on desk near OIC office
28-Nov-16	Vehicle	210	None.	Back door latch broken.	Wear & tear.	-
1-Nov-16	Vehicle	205	Vehicle booked in for replacement parts 02 December 2016	Replacement of belts and pulleys	Wear and tear	-
28-Nov-16	Vehicle	225	-	6 monthly service/ safety inspection due.	-	Possible wheel alignment to be completed.
28-Nov-16	Vehicle	185	reported to OIC	Vehicle radio not being read by Comms. Able to read comms 5/5.	-	Vehicle to be taken to Cairns even date.
28-Nov-16	Vehicle	185	-	Reversing camera screen unable to see anything.	-	-
28-Nov-16	Vehicle	235	-	Rear right tail light not working	-	-
28-Nov-16	Vehicle	230	Fridge is turned on	Fridge not cooling	-	-
28-Nov-16	Vehicle	225	#NAME?	- rear cabinet locker access N/W (inside lug is 'sticking', requiring universal scissors to open) (rear cabinet locker containing CT6 splints, etc)	#NAME?	-
28-Nov-16	Defibrillator	215	Cables checked for damage	ECG failed to trace. Nil abnormalities on start of shift check. Monitor showing DEauto and could not be changed back to normal.	-	-
28-Nov-16	Vehicle	225	Nil	Glow Light stays on	Nil	This came on yesterday, However officer who I worked with yesterday had been told if this happened it should go away with a good run, however it didnt.
29-Nov-16	Vehicle	225	Will arrange repair when vehicle goes in for next routine service	Driver seat has tear in aphotstery	-	-
4-Dec-16	Defibrillator	185	wiped the rollers with alco swaps to see if that would fix the printing but did not work - discovered faulty door.	not printing on the paper properly - paper door keeps coming out of the socket and not closing	-	OIC Cairns to advise RRC result/date of repair.
6-Dec-16	Vehicle	245	Vehicle taken back to station and swapped for another	Engine light came on and then transmission issues on first case code one	-	-
8-Dec-16	Other Equipment	230	Let CDS know the problem and email OIC	Phone won't receive calls or TXT until you remove the battery and reinstall it. Happens every 6 hours or so.	-	-
11-Dec-16	Vehicle	230	nil	large crack in windscreen	unknown, found at start of shift, unknown if fault report already created.	Found at start of shift, unknown if vehicle fault report already created.
10-Dec-16	Vehicle	230	Placed in view of OIC	Oxygen airflow regulator reported to be leaking by the previous crew	-	Now replaced and fully operational
11-Dec-16	Vehicle	240	-	Nail in right back tyre	-	-
12-Dec-16	Vehicle	210	-	Engine warning light displaying on dash.	Completing start of shift checks, engine warning light and ? glow plug light present on dash. Vehicle has not been driven used this week only started when completing checks.	Not operating out of this unit. Glow plug light disappears prior to starting however returns with engine warning light when engine is running. Glow plug light disappears again after 2-3min however engine light stays on.
12-Dec-16	Other Equipment	240	-	Volume knob on portable radio 501491 p2 missing Serial number 481CQK0148. Asset number QGN 308590	-	-
12-Dec-16	Vehicle	195	Vehicle marked unoperational until further	Car radio cutting out, ? Battery or electrical issues	Unknown	-

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
12-Dec-16	Vehicle	230	RACQ called and spare tyre fitted. Visited and tyre had tyre replaced. More work to be done with service on 13.12.16	Flat tyre rear drivers side	Threaded steel bar in tyre	Apparently abnormal wear on other rear tyre means all tyres need to be replaced and wheel alignment done with service.
12-Dec-16	Vehicle	240	Charger was swapped - turned off and on and attempted to use another charger	Flat battery	unknown. Car was on charge	notified and attended to jump start
12-Dec-16	Defibrillator	200	Emailed advised to do a fault report Will change ECG dots if it occurs again to rule that out Made copies of the ECGs and a timeline of events (also emailed to	Electrical artefact (vertical line artefact) looking similar to a pacemaker spike occuring frequently during the treatment of a patient. Emailed a copy of the ECGs and timeline of events	unknown	This Corpuls3 has undergone the 2016 configuration update (01/11/2016)
14-Dec-16	Vehicle	240	-	Stretchers not working correctly, not suitable for training New PTS officers	-	-
13-Dec-16	Vehicle	240	-	Cracked windscreen	-	-
14-Dec-16	Vehicle	215	Fault form and taking vehicle to for step and for radio 15/12	Vehicle side step not coming out. Vehicle self locking VHF radio unreadable when vehicle is approx 5km from station/hospital	-	-
14-Dec-16	Vehicle	230	Chair has been removed (at NGH) as crew were given a tasking to Gympie. Crew to go to for repair ASAP	stair chair bracket loose	-	-
14-Dec-16	Vehicle	250	-	Loud alarm tone sounding in rear of vehicle. Appears to originate in back right of vehicle. Initially an occasional beep has then become a more regular and has then become a constant tone.	-	Tone sounds regardless of whether vehicle in Park, Drive, Neutral or Reverse. Tone is different from alarm tone which sounds when vehicle reversing.
15-Nov-16	Vehicle	240	Fault report and have removed maps and replaced (did not rectify the issue)	Garmin not working	Unknown	Emergency repsonse vehicle
24-Nov-16	Vehicle	240	-	1. Drivers side mirror, keeps coming loose on dirt roads 2. AM/FM Radio annetana not working 3. On three occasions in last week, would not start, used over-ride switch to start vehicle	-	-
6-Dec-16	Vehicle	240	Nil	MDT GPS screen frozen - unable to reset.	Unknown	All other functions of MDT unaffected.
7-Dec-16	Vehicle	195	This fault form	1. Fridge is not cooling 2. External GPS antenna cable has been "ripped out" of its socket, causing fraying and unable to be plugged back in	1. Unknown 2. Carelessness	Sent to repairer
6-Dec-16	Vehicle	225	Has been replaced with station spare. Replacment lead has been requested from RRE.	SpO2 cable not working. ?faulty lead/wire	-	-

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
7-Dec-16	Vehicle	225	-	Gas door strut on floor compartment containing scoop stretcher is broken it does not keep the door in an open position	-	Gas strut replaced
5-Dec-16	Vehicle	210	I have completed fault form	R alley light not working	Unknown. Was handed over with station handover, found on first day vehicle check	-
8-Dec-16	Vehicle	235	Car taken off road	Check engine light active while on first case	-	-
8-Dec-16	Vehicle	215	-	Cracked front windscreen	Stone from vehicle in front	Crack to passenger side of window
8-Dec-16	Vehicle	230	-	Electric step loud clicking ratcheting sound when extending out, but not when retracting. Started 2 hours into the shift.	-	-
8-Dec-16	Vehicle	215	Car now at .with OIC aware of all .	Battery draw won't slide . Wood holding it in place Air bags drop too low and then won't automatically go up . Have to press button in front switch.	-	-
8-Dec-16	Vehicle	250	NilReplace 2x bulbs.	License plate lamp is not working.	-	-
8-Dec-16	Vehicle	225	this form, keys have been tagged not for use, notified SOS	Damage to lower hinge on kit door	Unknown, noted at end of shift	-
8-Dec-16	Vehicle	210	-	"Door Open" dash light staying on and back beacons illuminates whilst driving and alarm sounds constantly	-	-
8-Dec-16	Other Equipment	250	All seals replaced crew keeps D cylinders off unless required.but will slow leak if left on	601557 Ongoing fault with D cylinder oxygen system in this vehicle slow leak	Has been investigated previously but unable to rectify	-
8-Dec-16	Vehicle	195	-	While driving a red brake alert warning light started flashing. Manual says vehicle shouldn't be driven.	-	SOS consulted and he agreed vehicle should be placed out of service.
9-Dec-16	Vehicle	195	reported and tyre reinflated and monitored	Front L hand parking light blown and front R hand tyre continually loosing pressure.	Bulb blown, leaking valve.	Apparently this tyre has a recent history of loosing pressure.
9-Dec-16	Vehicle	240	reported to OIC, MDT technician notified	MDT intermittent power loss - MDT loosing power / rebooting whilst on active jobs / shut down whilst on code 1 case. Vehicle charged nil apparent battery issue all other electronics remained functional	unknown	Off road for repair today
9-Dec-16	Vehicle	230	Stretcher cleaned. Floor of ambulance cleaned but blood continues to flow from inside stretcher mount.	Blood throughout stretcher mounting bracket. Caked into seals and longitudinal runners - unable to access to clean without removal of stretcher mounting bracket.	Bleeding patient	Biohazard but cannot be cleaned without removal of mount.
9-Dec-16	Vehicle	210	-	the air-conditioner was working at start of shift over the shift it just started blowing air (not cold at all) - it then starting working again for about 15 mins and then went to just blowing air again. It is now just blowing cool air not cold aircon air	-	The car is still operational however very uncomfortable to drive as it get so hot.
9-Dec-16	Vehicle	210	-	Front air conditioner not working	-	Car operational, aircon not.
9-Dec-16	Vehicle	215	-	Light in back broken -strobes	-	-
9-Dec-16	Vehicle	210	-	GPS not working. Won't turn on.	-	-
24-Nov-16	Vehicle	245	-	Losing mains power when driving. Intermittently losing power to MDT and Radio. When parked at hospital loses all power. After starting vehicle radio requires turning on manually .	-	-
23-Nov-16	Vehicle	215	see above	Issues: rear of car higher than normal, front lower No sat phone Rear tail light out - taken to ken days Damage to rear top spoiler - quote to be obtained	-	-
24-Nov-16	Vehicle	235	notified fleet tech	Left headlight smashed	unknown	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
24-Nov-16	Vehicle	215	Bundy OIC directed crew to QPS Bundaberg Station for replacement. Replacement obtained, problem now fixed.	VHF radio cord outer plastic protection frayed, electrical wires exposed.	unknown	Problem is now rectified.
24-Nov-16	General Equipment	240	Oic's office	Car phone from 124 not working. No ingoing or outgoing texts and calls.	-	-
24-Nov-16	Stretcher	230	Removed from Service and swapped out with functioning stretcher at NGH. Report completed. OpCen notified.	Head end legs slow to descend. Reported by ACP NOOSA QAS UNIT 401903	Unknown	NO COLLAPSE OR PATIENT INVOLVEMENT.
24-Nov-16	Vehicle	240	OC and OIC notified and emailed. Returned vehicle to station and marked VOR by CCP	Key stuck in ignition. Full functioning, only unable to be removed from barrel.	Unknown.	-
24-Nov-16	Stretcher	235	Stretcher cover applied to reduce risk	The side arms are cracked. The stretcher mattress has split at the seams	-	-
24-Nov-16	Vehicle	210	Turning screen on and off. Changing gears P to R - all with nil change	Reversing camera not working. Turns on when car in reverse however screen remains blue.	?	-
25-Nov-16	Vehicle	240	-	When parked at an RTA and engine is running whilst emergency lights are on, siren starts to come on at a low volume and will not shut off, even though the siren switch is off	-	-
25-Nov-16	Defibrillator	250	New cable fitted	Faulty oximetry cable	-	-
25-Nov-16	Vehicle	230	Where safe on Caloundra road, then at station, veh turned off, key out and retried . To no avail.	When taking off on the highway, veh has gone into a 'sort of safe mode' where it has no real acceleration but will get to the speed limit, eventually. It will drive at this fine. The engine light began flashing at the same time. A lightbulb light also lat	? Quick acceleration getting back onto the highway.	SOS notified
25-Nov-16	Stretcher	250	Has been left at southport station & an operational stretcher taken	Front lowering level cable snapped	?	No
25-Nov-16	Vehicle	245	-	MDT KEES SHUTTING DOWN DUE OT OVERHEATING	-	-
25-Nov-16	Defibrillator	215	Tried different probes. Light comes on but no reading	SP02 Not reading	-	Defib Taken from 4409. Defective defib left at OIC door
25-Nov-16	Defibrillator	215	Turn off each unit, separate completely, cycle each unit, reassemble, power on.	CF Card Error	-	Job lodged with job id
26-Nov-16	Vehicle	245	Vehicle placed inside station garage to dry.	Electrical faults	Believed to be due to water ingress from very heavy rainfall.	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
25-Nov-16	Vehicle	245	Checked tyre pressures and these were correct	Vehicle pulls to the left whilst driving. Tyre pressures checked and equal and correct on both sides of front. Also at approx 100kph steering wheel has vibration wobble. Possible needs both tracking, alignment and wheel balancing to be checked	-	There is a loud rattle which has been evident all week, worse on engine start up, coming from the exhaust system. it appears, the hanging bracket in front of the rear wheels is either missing, broken or not attached
26-Nov-16	Vehicle	200	Placed on charge. SOS notified. Mechanic to check Monday 28th November 2016.	Possible main battery failing.	Unknown.	-
26-Nov-16	Vehicle	200	SOS notified. Vehicle to be placed on battery charger.	Mains power lost to radios & emergency functions.	Unknown.	Fault rectified 26-11-2016
26-Nov-16	Vehicle	200	-	engine light came on - black smoke blowing from exhaust -message on display said 'check oil'	-	vehicle located at south mackay station
26-Nov-16	Vehicle	210	Defect form completed, vehicle defected	Corpuls not turning on correctly	Unknown	-
29-Nov-16	Vehicle	225	Consulted with Satphone installers, checked fuses and did troubleshooting over the phone. No joy. Satphone installers say seek autoelectrician assist.	Hardwired Satellite phone not powering up (part of the recently installed PTT hardware)	-	Will use cordless Iridium satphone until the hardwired satphone is repaired. Autoelectrician inspected on 8 Dec 2016 and advised need new cradle for satphone. Equipt recently installed and still under warranty. Await new cradle for installation.
29-Nov-16	Vehicle	210	Report to mechanic who organised highway auto to fux	Slow leak in airbag goes down after 6 Tor more hours after car turned off and stationary at Stationary.	Happening for a week keeping an eye in it. When being driven all day all good, but if down and first job very rough	Service due at 98k by sticker on wind screen.
29-Nov-16	Vehicle	210	NA	Reversing sensors constantly alerting imminent crash despite there being nothing behind car, and reversing camera is looking down at the ground at a much smaller angle then it should be, limiting vision while reversing.	Unknown, sensors on car are attached to the metal 'step' on rear of vehicle so potentially the step has been dislodged or malformed over time and sensors are not properly calibrated for new position.	Reversing camera still gives adequate visibility despite the reduced angle.
29-Nov-16	Vehicle	210	Nil	Rear brake light not working	.?	-
29-Nov-16	Vehicle	225	Cleaned camera, moved front mirror to see some of the blind spot. OIC Comments - unit is having a new reversing dsiplay fitted, prices being sorted for new mirrows if possible. sun visor been approved and waiting for it come in.	Left hand mirror has no blind spot mirror, right hand mirror to small to see objects clearly, reversing cam always fuzzy on screen hard to see what's at back of vehicle, reversing cam monitor to small and to far away from driver to be of any use.	Poor design	Additional fault of no sun visor on vehicle unable to see highway due bright sunlight on Brisbane bus run.
29-Nov-16	Stretcher	225	-	Sliding component not working as power was turned off	As above	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
29-Nov-16	Vehicle	245	Spoke with OIC whom advised requires workshops PST inspected vehicle and advised vehicle now operational with nil issues	Red dash light appeared "brake distribution " visit workshops	Nil	-
29-Nov-16	Vehicle	240	Taken off road due to potential damage possible	Significant loud high pitched switching sound coming from engine	-	Oncoming bariatric crew advised that this is a known noise with the vehicle and has been assessed in the apst at and fit for service.
30-Nov-16	Other Equipment	210	Equipment has been removed from vehicle	vacuum mattress leaking beads from where the valve is missing, it has been taped up. pump to mattress is also missing	not known, equipment found in pool vehicle 2356	-
30-Nov-16	Vehicle	230	fault form - car placed back on charge	Mdt continually flickering and switching off, fridge defrosted, radio switching off	query electrical issue as car had been charging	-
29-Nov-16	General Equipment	250	Assistance via Comms and reset of MDT.	Unknown job appearing on MDT, unable to be cleared by Comms or by a reset.	Job dropped down via comms	-
30-Nov-16	Vehicle	215	Vehicle has been taken to mechanics and fault shown to staff there	Revering camera intermittently working with blue screen present when reversing.	NA	-
30-Nov-16	Vehicle	240	Cursory examination performed by unable to diagnose fault	MDT not functioning- no power to screen	-	-
30-Nov-16	Vehicle	240	minimise use	Rear compartment sharps bin/rubbish bin rolling draw is broken.	wear and tear	-
30-Nov-16	Vehicle	230	-	Officer advised the MDT Mounting bracket broken. MDT still operational but being held in place with duct tape.	-	-
30-Nov-16	General Equipment	240	N/A	MDT is switching on and off, ongoing problem, ?flat aux. battery, main battery power at 14.0 volt	Aux battery not charging	-
1-Dec-16	Vehicle	195	Fault form filled out and notified on vehicle checklist	Front right side lower light, glass broken.	Unknown cause. Possibly hit low flying bird.	-
1-Dec-16	Vehicle	250	Notified OCS/CDS/OC and SOS	Beacons are not working - working yesterday and at vehicle check this morning.	-	-
1-Dec-16	Vehicle	240	Contacted service department	Loss of power . Engine light flashing	-	-
14-Dec-16	Vehicle	245	Reported to OIC/Comms	Wing on the (L) ahdn side of the vehicle has come off along with fog/scan lights in the rear. Everything in front seat.	Hit a tree branch in Junction Street - Traffic was really busy turning into Logan Road near the roundabout so I thought I would go up the inside where there is no traffic but I didn't realise that there was a tree branch overhanging until I hit it.	Had patient on board and other PTO sitting in back but no one hurt and no other damage to vehicle.
13-Dec-16	Vehicle	215	Attempted to replace bulb but nil spare bulbs on station	Drivers side high beam bulb blown	-	-
14-Dec-16	Vehicle	250	Nil	Crack in windscreen in the centre of windscreen,,	Unknown.	If small "chip" is not fixed there is a risk of crack becoming bigger.

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
15-Dec-16	Vehicle	215	We turn airconditioning switches off, leave 20 mins then turn back on, and appears to work again, but for a short time. Is playing up on both short and long journeys.	Airconditioning in both front and rear cabins intermittently playing up.	Nil	-
15-Dec-16	Vehicle	240	Reset MDT, checked plugging in and power button.	MDT nil power or turning On.	-	-
16-Dec-16	Vehicle	230	Car going to for service today. Repair to be carried out at the same time please	Back door clip sheared off so door now swings when open. Chance of injury to staff/ patients	-	-
16-Dec-16	Vehicle	230	Panel beating. Forms completed for work.	Pushed in back Rhs door	Toyota Land Cruiser troop carrier with bullbar rear ended our stationery vehicle at a roundabout.	to inspect and report whether vehicle is operational.
18-Dec-16	Vehicle	240	Documented on vehicle checklist form	Back driver side door not latching when fully open	Unknown	-
17-Dec-16	Defibrillator	210	Checked cable, checked with other charger units in other vehicles and still did not charge	2115 Corpuls is not charging	-	-
19-Dec-16	Vehicle	190	SHE report and Claim form will be completed asap.	Damage to the top of rear L) exterior of vehicle above door 10-15cm long post backing into pole.	Reversing into bay at station and hit long metal pole between parks.	Though there is some damage to top rear emergency light - light is still working and operational
21-Dec-16	Vehicle	215	-	D size cylinder faster missing cylinders currently held in by elastic strap	Found on morning vehicle checks	-
21-Dec-16	Vehicle	225	Taken it out of service.	Raining outside and water began leaking through upper seals on rear door at patients feet and also through air con ducts near rear above stretchers. Lighting began flickering so possibly water in roof area. Also rain coming in through side door wits kits	Car has been continuously faulty for a long time.	-
21-Dec-16	Vehicle	230	MDT manually reset. QAS ATTEMPTED RESET TROUBLE SHOOTING	MDT WOULD NOT RESET AFTER ACCIDENTAL DURESS ALARM	-	-
22-Dec-16	Vehicle	230	None	Electronic step on side entry door not retracting	-	-
24-Dec-16	Vehicle	210	Reported.	3 x dash warning lights (abs and handbrake) remain illuminated after vehicle starts and runs. This has happened before with the same lights involved and only returned on Friday after being fixed?.	Unknown	Waiting on word back from Mechanics as to whether the vehicle can still be driven. Just received from Mechanics to take vehicle off road.
24-Dec-16	Vehicle	235	This has been faulted multiple times and sent back ? Fixed / safe. Despite all officers at station believing otherwise.	Suspension front left bottomed out on small bump	Worn suspension	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
24-Dec-16	Vehicle	240	fault report	Left low beam bulb blown	wear and tear	operational day time
24-Dec-16	Vehicle	220	Not sure if this fault has already been reported	Drivers side mirror has a broken indicator cover, however bulb to intact and working fine	Not sure as I found the vehicle like this when I took over for my 8 days on	Photo of damaged mirror in 24/12/16 vehicle checklist
26-Dec-16	Vehicle	225	Previously repaired 1 week ago for same problem.	This Unit has only just returned to service after having the Rear Airbag Suspension "Fixed" the airbag system has failed within 2 -3 days.	-	-
26-Dec-16	Vehicle	185	Off road.	Major leak of oxygen inside walls from D size cylinders.	Faulty hoses or connectors.	Frequent occurrence with this unit.
9-Dec-16	Vehicle	215	Fault form	O2 leak, right hand 'D' cylinder drained during shift with no use.	-	-
9-Dec-16	Vehicle	230	Disconnected the step so it won't go in or out. Step dangerous if stood on so left step retracted.	Side step broken off body LHS	-	-
9-Dec-16	Vehicle	230	Reported to OIC, Fault form completed, Vehicle to be taken to for repair/replacement of GPS at the next opportunity.	Garmin GPS not working	-	Navigating to jobs on shift via QAS maps and referdex.
9-Dec-16	Vehicle	210	-	1. Rear left lower flasher not working - still to be repaired; 2. Switch for rear door faulty - temporarily repaired on 9/12; 3. Windscreen wiper reservoir tubing broken - repaired on 9/12.	-	-
10-Dec-16	Vehicle	210	Fault form filled out - rear camera/sensor bolted in fixed place	Reversing Camera/Sensor - when reversing, close-proximity alert tone sounds continuously regardless of presence of/distance to any obstacles, making it annoying and useless	Unknown	Camera itself still works fine
11-Dec-16	Vehicle	215	Faulty form.	Vehicles interior light flash repeatedly in a strobe light fashion.	-	-
11-Dec-16	Defibrillator	240	-	Spo2 Faulty	-	-
11-Dec-16	Vehicle	225	-	Vehicle 6 Month Service / Inspection Booked 12/12/16	-	-
12-Dec-16	Vehicle	200	Notify LASN mechanic	Flat battery	Mains were turned off over the weekend	-
12-Dec-16	Vehicle	240	Took to North Lakes. replaced both Bulbs.	Right Tail Lamp out. Right Middle Side Marker Lamp out.	-	-
12-Dec-16	Vehicle	235	Turned car on and off a few times - nothing changed.	Engine light came on while driving and car wouldn't accelerate	-	-
12-Dec-16	Vehicle	205	Vehicle booked in for repair on the 15th december 2016	Aircon unit in vehicle works intermittently	Unit is freezing up	-
13-Dec-16	Defibrillator	250	Cable replaced	Spo2 sensor fault	-	-
13-Dec-16	Vehicle	230	Visual check of sensors no damage evident	Reverse camera sensors faulty. Says stop as soon as in reverse with nothing behind vehicle	? Faulty sensors	Vehicle may be able to be taken to by crew on Wednesday
12-Dec-16	Vehicle	200	called OIC	Side step not working - stuck in	while accessing a pts driveway i drove through a muddy ditch which required some speed to get through. as i was coming out of the ditch onto train tracks and relatively hard ground i heard a loud noise and later noticed the side step was stuck in.	-
12-Dec-16	Vehicle	225	None	Side step U/S	Unknown	Only issue is with side step, vehicle otherwise operational.

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
13-Dec-16	General Equipment	195	Noted in vehicle check list - will attempt relocate replacement	Both yellow torches in Unit 1138	Unsure - didn't pass pre shift check	-
13-Dec-16	Vehicle	250	Nil	In car charger for touch book is no longer functional as 12v plug has been damaged.	Unknown	-
13-Dec-16	Vehicle	250	Nil	Stretcher harness seatbelt on the right side is missing the clamp and unable to be applied.	Unknown	-
13-Dec-16	Vehicle	225	side door needs to be fixed as access to rear important at all times	Side door entrance to rear is intermittently inaccessible as door will not open	as intermittent appears to be issue with side door lock/ electrical components	-
13-Dec-16	Vehicle	195	none, reported to SOS, advised to return to station (as end of shift anyway) driving slowly completion of fault	whistling noise on acceleration (mostly above 40kph)	was working fine en route to pt and then en route to TTH the noise was there from when leaving scene	no warning lights came on, no fluid leak noted under car
14-Dec-16	Other Equipment	215	report, putting radio in OIC's 'in tray'.	Radio 4412 2 of 2, once turned on screen does not illuminate or display any channels. Other ways of identifying radio is its allocated number of "#058"	unknown	Repaired at the QPS radio workshop
26-Nov-16	Vehicle	230	-	MDT not working	-	-
26-Nov-16	Vehicle	240	Fault form submitted	Steering heavy ? Loss of power steering	Unknown	Ongoing issue for several months
27-Nov-16	Defibrillator	200	I cleaned the printer spots twice. I also tried two seperate rolls of paper both before and after cleaning. Nil improvement	On print out of ECG there is defined spots of lightness to the point of missing entire QRS complexes.	-	-
26-Nov-16	Vehicle	215	No action	Minor scrap to side door of rear module	The patients automatic gate closed on the rear of the vehicle as QAS was leaving.	-
25-Nov-16	Vehicle	245	VOR	Battery light on	-	Centenary OIC aware
27-Nov-16	Vehicle	240	Oos	Fan has detached from engine - not operational - out of service as per roc	Loud bang heard in engine while idle	-
27-Nov-16	Vehicle	225	#NAME?	#NAME?	- unknown; both items faulted for some time now	-
27-Nov-16	Stretcher	250	-	Power load lights which indicate stretcher engaged in the loader faulty. Left side remains green all the time, right side is both green and orange all the time, regardless of whether stretcher is engaged or unengaged? Stretched loads without issue.	-	No issue with stretcher, only loader..
27-Nov-16	Vehicle	245	-	Drivers Side Headlight not working	-	-
26-Nov-16	General Equipment	250	-	CTEK charger out of 6573 has stopped working. Does not turn on when connected to power point.	-	-
28-Nov-16	Vehicle	240	-	MDT keeps shutting down, Battery voltage slow to charge.	?Faulty battery	-
28-Nov-16	Vehicle	210	OIC informed, told to write defect as can not remember what the cause of clunking noise was last time.	Car is making clunking noise again when being driven	Unknown	-
29-Nov-16	Vehicle	240	Spoken to	MDT shutting down and Main dash flashing	Does not seem to last the shift keeping MDT powered and then ? whether plugged in overnight. MDT still showing job from last night so unsure if you could clear it.	-
29-Nov-16	Vehicle	240	to look at	Left front head light not operational	-	-

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
29-Nov-16	General Equipment	230	-	12v battery charger light blinking/ fault light. Other 12v charger used and tested and charging vehicle.	-	-
29-Nov-16	Vehicle	230	Fault form	Reverse camera isn't working. Blue screen.	-	-
29-Nov-16	Vehicle	240	Spoke to [redacted] at [redacted] who has a replacement LHS lens replacement in stock	LH brake light lens cracked - damaged by another QAS vehicle while parked at the Wesley Hospital ambulance bay	Inatentive driving by officer in second QAS vehicle	Driver of second QAS vehicle counselled on correct driving paractice and need for guidance
29-Nov-16	Vehicle	220	Cables checked to see if any are loose, one behind driver seat found to be disconnected, reconnected with nil improvement in situation/data/antenna connection.	Sat phone not working correctly. Coming up with error messages. System Error, Antenna Cable lost Calibration Calibration Data Error Antenna Failure No Antenna Found Car radio also having intermittent issues, See additional comments	Unknown.	Car radio randomly cycling through QAS radio channels with no personnel interaction. Will not stop until radio is power cycled. Then radio works normally again. This is the main radio and not the cross band.
28-Nov-16	Vehicle	225	Taken to tyre service for repair	Slow leak in near side rear tyre	-	Tyre has been repaired.
29-Nov-16	Vehicle	235	Have notified fleet tech to organise new handle to be fitted.	Broken door handle main sliding door passenger side	Officer was sliding door shut when handle broke off.	-
29-Nov-16	Vehicle	240	Sent to repair	Significant AC leaking onto patients	-	-
30-Nov-16	General Equipment	185	As per roller door fixing checking sheet. OIC informed.	Roller door two (on entering plant room side) is opening but not shutting. Troubleshooting performed, still not working.	unknown	-
1-Dec-16	Vehicle	225	-	Front end wheel alignment.	-	Booked in for after 'D' service on 12th December 2916. - Wheels balanced and front end alignment complete.
2-Dec-16	Vehicle	250	-	Rear passenger side door will closes but is loose when closed.	-	-
2-Dec-16	Vehicle	215	n/a	Back door frequently unable to be opened from the outside despite being 'unlocked'. The only way to open it is for an officer to lean over the seat inside and manually turn the lock on the inside.	Unknown. This unit has had numerous locking Issues previously	-
2-Dec-16	Vehicle	240	-	Blown low beam light drivers side	-	Being taken to [redacted] for immediate repairs
2-Dec-16	Vehicle	210	-	Damage to drivers side wheel arch panel post impact with handrail at transport centre case no. 8255587	The driver	-
2-Dec-16	Vehicle	230	-	MDT frequently turns itself off and on again while car running and in use. Reported this issue before but it is still occurring despite repair (15/11)	-	-
2-Dec-16	Vehicle	240	Checklist completed, OIC emailed, ROC notified, vehicle taken out of service, fault report form completed, vehicle put on charge at station.	MDT & vehicle radio do not turn on, vehicle lights flickering on & off and battery monitor states "check battery", visual display is also faded.	?battery	Vehicle became non operational at 17:00 due to multiple faults described.
2-Dec-16	Vehicle	240	Car left unplugged to drain battery in an attempt to rectify the problem.	Vehicle air-con does not turn off even when vehicle is turned off, when vehicle is turned on the front air-con fan cannot be adjusted or turned off.	Unknown	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
2-Dec-16	Vehicle	240	ROC was notified and told that vehicle needed to be put off road but he advised that the Metro South vehicle had gone to Hervey Bay. If required the unit could be used in an emergency as a last resort for Bariatric transport.	Alternator light on dash comes on whilst accelerating causing the rear air conditioner and siren to cut out.	This has been an ongoing intermittent problem with the vehicle.	-
2-Dec-16	Vehicle	190	Fault raised 18/10 however nil action taken. Impacts on paramedic safety as no light to rear of ambulance at night time.	Load light not working	-	-
2-Dec-16	Vehicle	225	End of fuse/re-set button has been pressed.	Vehicle fridge is not operational - currently running at 21 degrees.	-	Has been to Hotwire for repair, all power is good to fridge, fridge is the issue needs to go to Dealer for repair.
3-Dec-16	Vehicle	235	Attempted to restart MDT, unplugged	MDT displays a black screen with white typing of a script. Unable to fix by switching the MDT switch.	-	-
3-Dec-16	Defibrillator	195	SOS notified and corpuls out of service	Printer ink faulty, cannot obtain clear printout	-	-
3-Dec-16	Vehicle	195	Unit put out of service, SOS notified, OIC Ayr notified by SOS, mechanic to fix first thing Monday morning	Auxiliary battery draining easily - rear air conditioning and all communications radios stop working / reset intermittently. Clock unable to keep correct time. Dash alert frequently beeping that truck is overdue for service.	Voltage display of auxiliary battery fluctuates, ranges from 12.5 down to 8.5	Unit parked in Ayr garage, plugged into charger, fault notifications placed in vehicle
3-Dec-16	Vehicle	185	Tried to turn back on failed	Main vhf radio unit turns off for no reason and could not be switched back on, Comms notified of issue, same issue on Thursday, vehicle being used for sport special, nil radio contact required	Unknown	Radio checks received as normal, unknown reason, on Thursday radio turned back in spontaneously after a period of time on 240v power
3-Dec-16	Vehicle	245	fault form, Informed ROC whom has documented and Emailed OIC.	The vehicle kept stalling on a code One; all power was lost including Mains and Radio. This happened several times on return to station. Vehicle would also randomly put sirens and lights on and the whole main switch board would light up.	unknown	Not safe to drive which current faults.
3-Dec-16	Vehicle	230	Stopped at Nambour station to swap corpulse for one that was charged to maintain operational status during return to Gympie. Tested original corpulse on charger at Nambour station, successfully charged which suggests fault was not with corpulse.	Corpulse not charging in charging bracket, 12V port in Cardiac locker loosening from wall.	Fault in 12V port or Corpulse charging bracket	Upon loading replacement corpulse from Nambour into charging bracket it indicated that it was charging again, however 12V port remained loose.
3-Dec-16	Vehicle	230	Nil	Passenger headlight not functional	?	Not suitable for evening/night use

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
3-Dec-16	Vehicle	210	-	Right front park light blown.	-	-
15-Dec-16	Vehicle	250	spoke to SOS and ran through everything we knew how to fix it	car will not turn over	unknown, seems has had similar faults over last 12 months	-
15-Dec-16	Vehicle	185	Going to be repaired immediately	Tyre and headlight to be fixed	-	-
14-Dec-16	Vehicle	240	-	Loss of power and smoke from exhaust	-	-
15-Dec-16	Vehicle	195	Opcen/OIC notified	Damaged front passenger tyre and rim after running over crank shaft that had broke off heavy vehicle travelling in front.	Crank shaft laying on road.	-
15-Dec-16	Vehicle	230	reported to CDS	side step not working	-	-
15-Dec-16	Vehicle	230	Dvr went to and they needed it booked in	The fuel gauge is not working properly- at times it will drop to a quarter or to reserve fuel when in fact there is plenty of fuel. Went to and they stated they would need 1 day to complete. Also left side siren is intermittently cutting ou	Unknown	-
15-Dec-16	Vehicle	195	Vehicle reported and taken to	Flashing engine light illuminated on screen. Vehicle lost power and wouldn't change gear.	Nil	-
15-Dec-16	Vehicle	200	-	Seatbelt in rear airway seat - buckle won't release from fastener.	-	-
15-Dec-16	Vehicle	210	Informed OIC	Dash indicator message "Brake ware"	Use of brakes	-
15-Dec-16	Vehicle	240	Nil action, it is an electrical fault	Speedometer and rev gauges not working, as well as dashboard light display not working	-	After turning the car on and off 3 times issue resolved, however deemed unsafe to drive incase it occurred again
16-Dec-16	Vehicle	245	Tried to restart car multiple times, notified Comms to organise tow truck and taxi Will be taken to today	Truck would not go over 20km/h after loud thump heard and felt. Did not hit anything.	-	-
16-Dec-16	Vehicle	230	for repair	Defib charging bracket loose	-	-
16-Dec-16	Vehicle	215	Taken to in Bundaberg	Small crack in windscreen	Unknown	Both items above repaired
16-Dec-16	Vehicle	210	Completion of this form	Defib charging socket has broken in rear of vehicle	Unknown - possibly caused by thrown up rock	Unknown when caused, located whilst doing a vehicle check at start of shift.
15-Dec-16	Vehicle	210	Mechanic checked vehicle yesterday and stated vehicle requiring check by to rectify problem, vehicle operational in the interim	Stone chip - star on drivers side of windscreen in line of sight	Unknown	-
16-Dec-16	Vehicle	185	Taken to requires new part - on order	Tyre pressure warning light on. Fault was detected yesterday with the tyres being checked by mechanic , who stated nil problem detected with tyres, car requiring check by to rectify problem. Vehicle stated to be operational.	Unknown	-
17-Dec-16	Vehicle	210	-	Rear O/S door unable to be opened from outside	-	-
17-Dec-16	Vehicle	240	Attempts to shut down MDT failed	Side step not automatically working	-	-
17-Dec-16	Vehicle	240	MDT failed	MDT fault, black screen with stating to reboot device	-	OIC aware.
17-Dec-16	Vehicle	240	ROC organised for us to take 562546 instead.	Engine starts only with emergency start feature.	Possible failing battery. Engine started fine at the beginning of the shift but this fault was noticed later in the morning during cases. ROC and Comms advised. ROC organised for 562505 to be left at NORTH LAKES station to be picked up by workshops.	Fixed by

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
17-Dec-16	Vehicle	215	-	Mains malfunctioning and radio turning on and off by itself	-	-
17-Dec-16	Defibrillator	250	OIC has replaced the propbe and rainbow cable, operating correctly.	Corpuls SPO2 lead turns off after 5-10secs. Replaced lead with a working lead and same fault occurred. Replaced original leads back onto the machine.	-	Test performed, witness . Performing correctly.
17-Dec-16	Vehicle	215	Faulty form.	Communications radio reads only 1-3/5 for both in and outbound radio traffic.	-	-
14-Dec-16	Vehicle	185	As above.	Drivers side rear door stabilising arm broken off	Door being closed when arm in use bent the arm, an attempt to Straighten the arm broke it.	Broken piece in on station OIC door
14-Dec-16	Vehicle	240	Attempts at fixing step - unsuccessful	Automatic side step on ambulance not working.	Unknown	Rest of car still functioning - potential hazard.
14-Dec-16	Vehicle	190	I used my finger and tapped the light casing with nil success	Front right emergency light on bonnet not working.	-	-
14-Dec-16	Other	210	-	Radio does not switch on and remain on.	-	-
14-Dec-16	Equipment	210	-	Radio does not switch on and remain on.	-	-
15-Dec-16	Vehicle	185	replace handle	inside handle of passenger rear door missing	-	-
15-Dec-16	Vehicle	240	-	Reduced tyre pressure in rear left tyre. Warning sign on dash during vehicle start up and visually low tyre pressure	Flat tyre	Has been reported to ROC who got RACQ to attend vehicle and not change tyre
14-Dec-16	Defibrillator	205	-	Unit intermittently fails to register an ECG when leads are attached to patient. Unit passes test when attached to test box. Attempts were made to utilise new ECG dots and reattach leads with no success.	unknown	-
15-Dec-16	Vehicle	210	Nil	Radio mike bracket holder broken	-	-
15-Dec-16	Vehicle	195	Notified and tagged vehicle offroad	Automatic side door not longer closing.	Unknown	-
15-Dec-16	Vehicle	230	-	Front driver side tyre flat R side rear door not staying open - Latch broken.	-	-
15-Dec-16	Vehicle	185	Taken back to station placed unserviceable	On the way to case 8300192, whilst on Yorkeys knob rd, audible alarm for vehicle water level came on followed by orange radiator light on dash....continued to case then checked water level, which was ok informed Sos	-	Audible alarm makes it impossible to work through fault
15-Dec-16	Defibrillator	230	Sensor unplugged straightened out plugged back in and not working. Corpuls restarted, sensor replaced with paed sensor in case it was just the end piece that's faulty however also showing 'defective' on screen with no readings.	Oxy sensor not working. Message on corpuls screen states ' defective oxy sensor' and nil readings. Worked when checks were done and treating first patient.	-	-
16-Dec-16	Defibrillator	230	-	'Defib error' on screen, not charging to deliver shock.	Shoulder strap broke loose while carrying into a transfer from Maleny hospital causing corpuls to fall on ground. A check was performed at Maleny station immediately after, and failed check.	-
16-Dec-16	Vehicle	215	-	Bottom draw on cannulation draw will not stay closed	-	-

RTI RELEASE

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
16-Dec-16	Vehicle	230	Car turned off, locked, waited 1min and turned car back on. Car struggled for about 5mins and then got some power back. Still not driving 100%	Engine light flashing. Car struggled to go faster than 5km/hr even with foot pressed to ground.	Unknown	-
16-Dec-16	Vehicle	195	-	MDT cradle in the way ... unable to see some aircon controls while driving and hazard lights.	-	Dangerous to use air con controls whilst driving
16-Dec-16	Vehicle	240	-	Met has no power to it. Vehicle back from service today.	-	Fault rectified over the phone by OIC
15-Dec-16	Vehicle	245	Job logged via BAS. attended 9/1/17 and placed appropriately sized extinguisher in bracket.	Fire extinguisher clip broken, does not secure.	Unknown.	-
16-Dec-16	General Equipment	250	Sos contacted	Mdt attachment broken	Twisting to see	-
14-Dec-16	Defibrillator	240	Whole corpse placed outside OIC office with note attached	SP02 cord stopped working at end of shift with respiratory patient.	Unknown.	SHE report already submitted.
16-Dec-16	Defibrillator	205	I have removed the roll of paper and put it back in several times. I have pulled the paper as it prints so that it flows and prints correctly but, unless I am pulling it, it stops and starts, missing parts of the print out.	The printer keeps jamming since I changed the paper. It is the corpuls defib paper and I have inserted it several times but the problem persists.	-	-
30-Nov-16	Vehicle	195	This fault form.	Tyre pressure indicates may be a leak.	Unknown.	-
30-Nov-16	Vehicle	195	Nil	front left hand head light not working. Only parkers and high beam.	N/A	-
2-Dec-16	Vehicle	210	-	Tyre pressure error on dash. Rear right tyre needs more air. Was advised by other officer that the tyre pressure at servo did not go high enough. Loud fan belt.	-	-
1-Dec-16	Stretcher	235	-	Head end	-	-
2-Dec-16	Other Equipment	230	Fault form completed. There is a spare pager for 802 at station which I gave to the crews but it is not receiving the cases. Apollo pager capcode 0439535 with SN 12mKA51J0736. This is a new and working pager but not receiving cases from the OPCEN	Screen on pager no longer receives or displays any information, it just has a large black ink splodge pattern on the screen.	CCP states it flicked out of the holder onto the floor of the plantroom when he was getting into 4802, he then accidentally stood on the pager when looking for it. The screen cracked and pager no longer works.	IF the new Apollo pager I have here can be connected sucessfully to 4802 there will be no need for a replacement. However, due to the serious nature of the cases received by the CCP POD, this needs to be rectified as soon as possible.

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
2-Dec-16	Vehicle	240	Vehicle report form completed Email to OIC Placed on charge at startion	This vehicle became non operational at 17:00. Vehicle appears to have a battery issue.	?Battery	-
2-Dec-16	Vehicle	195	-	Inverter not working, car not charging	-	Ocs not notified as vehicle was being moved within the station - not operational on shift
2-Dec-16	Vehicle	195	nil	Right rear tail light out.	Bulb blown	nil
2-Dec-16	Other Equipment	250	Turning off and restarting all equipment, synchronising thoughbook.	Tough book will not connect to either wifi printer at GCUH	Unknown	-
2-Dec-16	Vehicle	185	Spoken to SOS about vehicle communication issues.	Unable to communicate with Comms via Vehicle radio (10+ attempts) and had difficulty with Portable radios as well after 4 attempts. Communicated with Comms via phone to return to station to swap vehicles.	? Secondary battery.	Vehicle to be taken to Cairns even date.
3-Dec-16	Vehicle	230	-	Reverse camera not working, only blue screen visible. Parker light (front) not working.	-	-
3-Dec-16	Vehicle	225	-	Bonnet mounted beacons faulty. L beacon is not working and R beacon is stuck on (when emergency beacons are activated). All other lights ok.	-	Nil safety issues. All other beacons operational
3-Dec-16	Vehicle	245	repaired step	Step on vehicle not working	-	-
3-Dec-16	Vehicle	225	Nil due to weekend	Digital radio not turning on	Unknown	Analogue radio in vehicle still operational.
3-Dec-16	Vehicle	240	SHE Report	Hole in driver's flooring catches heel of boot inhibiting safe operation of vehicle - tends to trip up transferring foot to alternate pedal	Wear and tear	Floor replaced.
3-Dec-16	General Equipment	230	Nothing	4902 Met and radio cut out / power failure	Unknown	-
4-Dec-16	Vehicle	235	-	Reverse camera not displaying on MDT - showing a blue screen	-	-
4-Dec-16	Vehicle	235	None	Left head light blown	None	-
4-Dec-16	Vehicle	215	Fault form completed	Side step only comes out half way. Trip/fall hazard.	N/A	-
4-Dec-16	Vehicle	240	Photographs taken of minor damage	Minor scratches to passenger side front bumper	Collision with Subaru	Driver of Subaru admitted fault and apologised for pulling into path of ambulance. Two independent witnesses stated Subaru driver was at fault. Awaiting repairs
3-Dec-16	Vehicle	240	Notified oic	Right head light blown Not working	-	repaired
5-Dec-16	Vehicle	235	-	Both rear windows have been smashed by aggressive patient.	-	SHE completed.
5-Dec-16	Vehicle	195	Vehicle placed on charge.	Vehicle accessories main computer resets itself when vehicle is started. This resets a lot of the computers options, such as lighting, air-con, module power. Also, the inverter did not work during an IHT, unknown if this is related.	Last time this occurred, a fresh battery was put into the vehicle, this did not fix the problem.	Nil
3-Dec-16	Vehicle	245	Advised Metro South ROC of issue and was instructed to leave truck at Durack station.	Engine light blinking after truck loss power accelerating up an incline. No visible fault of engine upon inspection. Truck is only able to drive in emergency mode with no power to accelerate. Truck is at Durack station awaiting further review	Accelerating up an incline cause engine to switch into emergency mode.	-
3-Dec-16	Defibrillator	240	Notified oic	Pulse ox not working. It passes the test but when applied to a patient looses a trace and gives a cable fault alarm. Occasionally restarting the monitor helps but not for long	?	oic replaced faulty cable
5-Dec-16	Vehicle	245	Repaired a number of times without resolution of issue	Rear air bag suspension faulty. Ongoing issue. Rear airbags not fully inflating, causing harsh ride in rear, resulting in risk of injury to patient and attendant.	Ongoing issue, possible faulty airbag or compressor.	-
5-Dec-16	Vehicle	240	-	Making squealing sound when vehicle is turned on	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
3-Dec-16	Vehicle	240	already repaired and vehicle back in service - Refitted & Adjusted Cable On RH Sliding Door	02 side unable to close.	-	OIC completing fault report form due to officer not completing form.
5-Dec-16	Vehicle	210	Checked taken to for check	Intermittent electrical fault with door release for the module side door	-	Fault appears to be intermittent and works when checked. Some terminals were tightened.
5-Dec-16	Defibrillator	250	New leads	V6 failed in user test, new leads placed on v6 now works. Old leads given to OIC	-	-
5-Dec-16	Vehicle	235	Switched vehicle off, placed into park, handbrake applied, removed key, sited for period of time - all to no avail. Tried this multiple times (10+).	On return from case (no patient on board), vehicle went into limp mode and unable to return vehicle to normal driving mode.	Unknown - operating vehicle under normal driving conditions.	Contacted comms, duty SOS and fleet manager.
6-Dec-16	Defibrillator	195	Cable in working order, tested on different monitor. Attempted replacing cable with brand new but still does not work.	Oximetry not working on corpuls. Red light will come on and flash but unable to sense.	Unknown	-
5-Dec-16	Vehicle	195	-	loud screeching from aircon unit in the rear cabin	-	-
5-Dec-16	Vehicle	240	-	side step deploying whilst driving and turning corners	-	-
6-Dec-16	Vehicle	200	Report	beeping in the front cabin from the alarm stating that one of the doors is open when all doors have been checked and slammed shut	-	-
6-Dec-16	Vehicle	200	Contacted mechanic had batteries checked found faulty; 2 new batteries installed at	LHS door making loud noise when opening and closing	-	-
6-Dec-16	Vehicle	195	played with connection; however still not working	Garmin Nuvi GPS not charging	Not known	wiring and connections checked to the unit. As unit in hard wired we cannot check all connections.
6-Dec-16	Vehicle	200	Failed to start charged with external cord; two new battery organised and installed after contacting mechanic	Right dipped headlight not working	Faulty batteries	-
6-Dec-16	Vehicle	195	OIC has retested them and noted them to be faulty. OIC contacted who advised to send the fault equipment so they could assess it and where applicable return to Corpuls.	8 x SPO2 sensors 4 x SPO2 finger probe 1 x set of chest leads 1 x set of limb leads	no	Taken to & already replaced as faulty globe
6-Dec-16	General Equipment	240	-	Vibrating/noisy steering wheel at low speed and at about 80km/h	-	-
6-Dec-16	Vehicle	240	-	-	-	-

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
6-Dec-16	Vehicle	240	Taken to get re-gassed	AC doesn't work	-	-
6-Dec-16	Vehicle	235	Notification	Interior lights not staying on. MDT on button broken. MDT and radio turning off all the time.	-	-
6-Dec-16	Vehicle	240	OC notified, vehicle taken off road	No power steering, extremely difficult to manoeuvre at low speed, risk of injury to driver.	Ongoing issue for long time ? Getting worse	-
6-Dec-16	Vehicle	240	Have informed Reef Comms and SOS.	Engine light flashing	-	-
10-Dec-16	Vehicle	185	Comms and SOS.	Boot lid doesn't close easily and the locking mechanism seems aligned incorrectly.	-	-
12-Dec-16	Vehicle	240	Notified OIC	During testing no ecg waveform present when test box connected to defibrillator socket, no ability to charge and deliver shock. 4-lead ecg is present	-	-
17-Dec-16	Defibrillator	245	-	Tyre pressure warning light has been on for perhaps all day. All tyres appear appropriately filled but the right rear tyre may be lower than the rest.	-	Replaced in car with training defib
17-Dec-16	Vehicle	250	-	-	-	-
17-Dec-16	Vehicle	240	all fluid levels checked and are ok	low water alarm constantly alarming.	-	-
18-Dec-16	Vehicle	240	Tried to perform test with another test box, still failed to produce current.	-	-	-
19-Dec-16	Defibrillator	230	Fault form and OIC notified	No current displayed when obtaining 12-lead for vehicle check. MDT and charging equipment shuts down when unit is turned off and not plugged into 240v.	-	Defib is in Cooroy OIC office.
17-Dec-16	Vehicle	230	-	-	Maybe house battery r/s. ????	to check aux battery, in for service and more checks on 29th dec kept overnight.
19-Dec-16	Vehicle	215	fault report for faults previously submitted	one torch doesn't work, review mirror needs attaching, two vents in rear cabin broken so cannot be fully closed	nil	review mirror is above passenger side sunviser
19-Dec-16	General Equipment	185	-	Vehicle oxygen leak. Left D cylinder	-	-
19-Dec-16	Vehicle	210	Reported to RRC. Advised to contact Corpuls to report faults with defibrillator bracket and subsequent charging issues	Air conditioning in back of vehicle does not appear to be as cool as it should. Defibrillator bracket in side cabinet does not lock in at times and defibrillator does not charge at times. Bracket may be loose ?	Unknown, officer was travelling in the back of the vehicle with a patient the other day and thought that the air conditioning was not cool.	-
20-Dec-16	Vehicle	210	Spoken with CRR awaiting callback	Brake light and 3 dash lights remaining illuminated on dash	Officer noticed it this morning while driving to work	Operational at this stage awaiting callback to advise differently
20-Dec-16	Vehicle	215	-	Bottom cannulation draw is broken and does not stay in. When accelerating the draw comes out and strikes treating officers legs. Potential for injury.	-	-
20-Dec-16	Vehicle	240	-	Rear door locking mechanism not working	Found on vehicle check start of shift	Actual Vehicle Number - 5371 Actual Rego - 738SZT
19-Dec-16	Defibrillator	240	job logged with DT	hinge on top of defib box broken - falling back inside unit	??	-
20-Dec-16	Stretcher	210	Taken off road immediately until issue has been dealt with	Front wheels of stretcher did not lock into place on loading a patient. Front end of stretcher collapsed to ground when patient sat on it. Rear legs stayed locked.	Mechanical cause	-
20-Dec-16	Vehicle	250	Taken to Southport mechanic() at 1330 this day who varified that the rear a/c was non operational.	no rear a/c	found this way	OIC notified by myself and Mechanic Replaced rear a/c belt & tensioner.
20-Dec-16	Vehicle	210	Closed system, not rectifyable at station level	Corpuls charging cradle not charging Corpuls	Unk	At the moment, Corpuls are being cycled through on 240 volt charger on station.

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
20-Dec-16	Other Equipment	230	Email sent to staff to search personal uniforms and kits. Email to SCT OIC. Not location to date.	Pager unable to be found with in vehicle and station.	-	OIC Noosa submitting Loss Item Report forwarding to Fleet & XO
20-Dec-16	Vehicle	240	OIC emailed - advised me to fill in this form.	Vehicle battery charger is broken. I believe no damage to vehicle.	Reversed while charger was attached resulting in power cord breaking from power pack.	Vehicle 5228. Still operational with no apparent damage and another charger at station in drive thru. This charger was from top car park.
17-Dec-16	Defibrillator	250	Reported to OIC for replacement/repair. Still in operation in 6568	Damage to plastic casing on display module	Unknown	-
21-Dec-16	Vehicle	195	Taking car to	Electrical steering pump warning came up on the dash and steering became difficult. Car still drove. Turned car off and on again and it worked.	-	-
21-Dec-16	Vehicle	225	Vehicle taken of road, Comms notified, fault form completed, email sent to A/OIC and	Siren still not working, radio turning on no radio communications able to be sent or received, chips in windscreen along with crack on drivers side of windscreen, unknown if reported. Electrical fault issues have been raised to A/OIC and	Rocks to windscreen, poorly designed electrical system in the vehicle	-
15-Dec-16	Vehicle	225	Fault reported contact attempts with Contractor awaiting call back	Power Steering fluid noticed on lower hoses of steering box	NA	-
16-Dec-16	Vehicle	210	N/A	The rear door can not be opened from the outside, must be unlatched from the inside.	Unknown	-
16-Dec-16	Other Equipment	215	To seek out replacement remotes	Rear Garage Door remotes often not functioning	Age and wear and tear	-
16-Dec-16	Vehicle	245	We have taped the mirror to reduced movement and have completed a SHE report.	L side mirror cracked and a bit loose from being pushed forcibly into parrallel position	Slowly bumped side mirror into the metal rear corner of a delivery truck at 10km/h whist getting through an intersection driving code 1	-
16-Dec-16	Vehicle	215	No headlight on station	Left Headlight not working	-	Lamp located and replaced
17-Dec-16	Vehicle	230	Nil to date.	1. Left rear tyre wearing heavily on outside edge - may require replacement soon. 2. Driver's door lower plastic trim clip has pulled away out outer edge. Flaps audibly in rain. requires refit.	1. Tyre wear. 2. Bottom edge of door strikes grass footpath easily if parked against traffic.	-
17-Dec-16	Vehicle	240	-	High temp warning, fan shroud loose and damaged. Fan damaged.	-	-
17-Dec-16	Defibrillator	240	-	fai;ed to capture ecg 12 lead or 4 lead at about 7 pm last night. nil leads read on screen	-	-
17-Dec-16	Vehicle	200	Reported in vehicle defect form. Requires service with replacement of brake pads.	Brake pads wear light came on on way to job on 17.12.2016	N/A	Please book in for brake pad replacement asap
18-Dec-16	Vehicle	240	reset MDT, discuss with OC	reversing camera not working - single officer response, dangerous to use vehicle without camera	unknown	size of unit makes for a narrow field of vision when reversing, consider it unsafe to use vehicle without working reversing camera
19-Dec-16	Defibrillator	235	None	RL (green cord) broken unable to hold dot at all..	Unknown	Unable to conduct an ECG due to dots not being held by lead
19-Dec-16	Vehicle	225	ensured vehicle was receiving power and was found to be still not charging accessories	1. Torches in front cabin not receiving power/not charging 2. Automatic side STEP not automatically coming in or out 3. Airconditioning reported to be "barely cold"	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
19-Dec-16	Vehicle	225	-	Airconditioning "barely cold". Requires servicing.	-	-
19-Dec-16	Vehicle	225	Tyres, joints and arms have been checked NOTHING found. ? needs wheel alignment/balance	vehicle pulling to the LEFT.	-	-
20-Dec-16	Vehicle	225	All relevant person notified and options to rectify issue discussed. Scheduled for further investigation 22/12/2016 by Vehicle is operational.	Reversing camera was replaced previous week however there appears to be a connection issue or possible fuse issue, camera screen is not activating when in reverse.	Unknown	Reversing alarm is working screen is not working.
19-Dec-16	Vehicle	225	#NAME?	#NAME?	#NAME?	-
20-Dec-16	Vehicle	250	vehicle removed from service- to be checked by Brisbane fleet services	Sirens failed during code 1 journey	not known	ongoing issue with this vehicle over past few weeks.
20-Dec-16	Stretcher	210	Nil actions taken, stretcher still safe to use operationally but would recommend against using knee elevation mechanism.	Mechanism for knee elevation on 2122's stretcher does not disengage when red handle is deployed when there is any weight placed on legs of stretcher. Knee elevation mechanism does work when there is no weight being applied.	Unknown	Power pro stretcher only has one SN available at top of stretcher - Stretcher still located in Unit 2122.
21-Dec-16	Vehicle	215	-	SRS airbag warning light illuminated on dashboard. Also a chip in the windscreen, back door latch is broken and bottom cannulation drawer is broken.	-	-
20-Dec-16	Vehicle	240	Sent to	-	Engine Light On and Oxygen Door wil only lock with a key.	-
5-Dec-16	Vehicle	200	-	UHF radio cable split	Wear and tear	-
3-Dec-16	Vehicle	240	Spoken to ROC	Apparently vehicle in Limp mode	?	-
3-Dec-16	Vehicle	230	Reported to Comms	MDT keeps switching off	-	-
5-Dec-16	Stretcher	215	stretcher replaced	Stretcher head end collapsed down one click when loading patient	-	-
5-Dec-16	Vehicle	230	Called to notify pickup needed	MDT shuts itself on and off intermittently, including reversing camera	-	The unit is needed for the 07:00 start Tuesday morning. The headlight will need to be replaced sometime before the commencement of the 16:00 shift on Tuesday.
5-Dec-16	Vehicle	240	- vehicle left at Ipswich. Replaced with sector spare.	Passenger side headlight failed during the 16:00 to 24:00 shift.	-	-
6-Dec-16	Vehicle	235	-	Check engine light. Limp mode.	-	-
1-Oct-16	Vehicle	200	In progress	Reversing camera and loading light mount damaged when reversed into premises	OIC stated he was arguing with his son whilst reversing into his residence.	Exact date of incident unknown as the OIC has now resigned and we are unsure of the timeframe
6-Dec-16	Vehicle	245	Notified OCS, vehicle out of service	Black smoke intermittently pours out of exhaust - happens both moving and stationary	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
6-Dec-16	Vehicle	210	Contacted OIC, visited workshop but unattended. Spoke to who advised proceed with fault form and he will check it later when replacing bulb (pre arranged)	Horrible squealing noise, when departing hospital - ? Fanbelt	-	Advised Comms and SOS also
6-Dec-16	Vehicle	215	Nil	Stay on left side rear doors snapped off	Nil, stay found on vehicle floor at start of shift	-
6-Dec-16	Vehicle	250	OOS , REPORTED TO OIC	Main LCD control panel not working , see pic emailed to oic	Found this way	-
6-Dec-16	General Equipment	230	Dropped into , mechanic checked system, believes gas is low.	Vehicle 4969 rear a/c defective.	? Low gas	Booked in with Reported by PTO to pick up 4969 tomorrow 7/12/16
6-Dec-16	Defibrillator	195	On monitor test oximetry cable not working and monitor displays error "defective oxi cable". Replaced cable with one from corpuls 1520	Defective oxi cable	Unknown	-
6-Dec-16	Vehicle	200	Reported previously to OIC and mechanic rear tyres require replacement. OIC advised to have mechanic check Which mechanic checked and advised can be used still good for 10 ,000kms.	Wear and tear of rear tyres requiring replacement asap. Tyre technician advised yesterday.	Wear and tear of tyres rear wheels	Tyre check Tuesday 06/12/16.
7-Dec-16	Vehicle	195	-	Vehicle head light out Operational for day use. Brakes feel noticeably slow, strongly recommend brake test. Side step also not working.	-	OIC changed to operational after testing the car and getting light fixed.
7-Dec-16	Vehicle	250	-	Siren not working intermittently Side step not working intermittently Radio not working intermittently	-	-
7-Dec-16	Vehicle	230	-	Stream light polystringer yellow Torch not functioning	-	to repair/replace torch as required a t next visit to workshops.
7-Dec-16	Other Equipment	205	-	Suspected manufacturing fault. Plastic covering intact but no fluid or smell in vial. No evidence of tampering.	-	-

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
6-Dec-16	Vehicle	225	1. fire extinguisher has been ordered, waiting on replacement 2. vehicle booked in to for assessment on steering, step and torches	1. fire extinguisher needs replacing, was used on job. 2. vehicle "pulls" to the left 3. step does not automatically come out, but does retract 4. Torch are not receiving power to re-charge	-	-
7-Dec-16	Vehicle	195	notified OIC.	Side step not operational. Attempted to turn off/on and attempted to push back in, unsuccessful Rear right, stretcher side door hinge latch not latching. Officer attempted to fix but more of bracket snapped off, unable to locate piece	unknown, mid shift Rear door unknown, identified in pre-shift check, but spoke with OIC first to ensure another fault form not already submitted.	-
14-Dec-16	Vehicle	230	NIL	FRONT PASSENGER PLASTIC TRIM HAS COME OFF AND BEEN LEFT IN THE BACK OF THE VEHICLE	UNKNOWN	FOUND IN THIS CONDITION AT START OF SHIFT
14-Dec-16	Vehicle	225	Currently fan has been removed from vehicle.	Mounted fan in pt care area needs to be refastened to mount.	Query loose screws?	-
14-Dec-16	Vehicle	225	-	Rear aircon not working. Unable to operate in a car with no circulating air and 35-40 degree heat. Unpractical	-	-
14-Dec-16	Vehicle	235	-	Equipment door not closing properly can take several attempts to close it. Rear door latch catches on right side latch minimum 2 attempts to open door. Module access door does not unlatch properly requires 2 hands to open door	Solenoid latch failure	Problem could be easily solved by replacing solenoid latches with standard mechanical latches
21-Dec-16	Vehicle	225	-	Side step not closing fully	Ni idea	-
22-Dec-16	Vehicle	245	All necessary action.	Non operational MDT. Ongoing issue.	Faulty software.	-
22-Dec-16	Vehicle	240	Vehicle placed out of service, OC notified, OIC currently contacting vehicle repairer	Vehicle will not start, flat battery. Vehicle on charge overnight. Inverter does not appear to be working.	? inverter not working	-
22-Dec-16	Vehicle	235	-	Module battery not holding charge	Flat battery	-
22-Dec-16	General Equipment	225	-	High pressure hose/gurney - pressure switch not turning off. Switched whole machine off and then wouldn't work straight away again. 10 mins later, it worked again. Shuddering when engine is running whilst in use.	-	-
21-Dec-16	Vehicle	210	Nil	Passenger side rear door latch/ mechanism is loose.	Unknown, where and tear?	Door still closes/ locks, but potential there for it not to.
22-Dec-16	Vehicle	240	Unable to fix needs repair. Light and camera still working.	Rear housing for light and camera cracked and detached. Screws pulled through roof metal.	Reversing into station - contacted roller door	Pictures attached to check list as not an option on fault form.
22-Dec-16	Vehicle	240	Details as per fault form completed by OS	Details as per fault form completed by OS	Details as per fault form completed by OS	-
22-Dec-16	Vehicle	195	Vehicle fault form completed and OIC notified	left fog/driving light cover broken, light still operational	Collision with small kangaroo whilst returning from Cardwell. Kangaroo hit left front of car and bounced away from car. Vehicle was controlled at all times with nil issues after collision. As soon safe to do so, vehicle was pulled over and inspected.	On Inspection by OIC no damage located, all lights working, incorrect vehicle #, should have been 1123.

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
22-Dec-16	Vehicle	185	-	Multi> air conditioner in back intermittent working and when it does it is not overly cold. The air conditioner is falling from the roof screw out. The side passenger door housing the vehicle equipment failing to open intermittently so was unable to	-	The side passenger door housing equipment equipment intermittently unable to open so cannot assess equipment. The back driver side door has no bar to stop door from swinging out into traffic. The open door alarm sound beeps 80% of the time but doors clos
23-Dec-16	Vehicle	240	OIC notified, repaired advised, phone msg left	Battery flat - vehicle won't start	Unknoun (vehicle does have the ability to be charged)	-
23-Dec-16	Vehicle	245	-	Only 1 of the 2 car keys works. The faulty key does not unlock/lock or turn in the ignition to start the car.	-	The ambulance can still be used but only has 1 working key
23-Dec-16	Vehicle	240	Cable removed from vehicle.	Damaged/Frayed 12V toughbook charging cable. Exposed wires.	general wear/tear.	-
23-Dec-16	Vehicle	225	#NAME?	- pager missing - 2 orange travel lights (driver side) N/W	-	-
23-Dec-16	Vehicle	195	plastic cover taped on gauge, don't think it will keep extinguishe from working if it's needed	plastic cover of gauge on fire extinguishe is broken off	not sure what happened, we found the plastic lying on the step in the car, fire extinguisher still secured in holder, does not look as if it had moved, maybe someone "kicked" against it when getting in the car	-
24-Dec-16	Stretcher	245	-	Hydrolic wasnt working. battery was changed over and still faulty	-	serial no. given is the stretcher. n
22-Dec-16	Vehicle	215	Precious fault reports submitted.	Solenoid intermittent on single rear door (often gets stuck in bottom left hand corner and difficult to open), solenoid intermittent on small utility response kit door (passenger side) and often won't close, Rear view mirror requires attaching.	Rear view mirror requires attaching. Mirror located above passenger sunshade. Arm rests missing on patient care chair in rear of vehicle. Air vents broken, cannot be fully closed, in rear cabin. One torch doesn't work.	Nil
25-Dec-16	Defibrillator	195	-	Analyse button initially did not work when pressed. Some anomalies were noted on code summary by officer when analyses did work machine charged up twice stated shock advised then dumped shock stating not advised, only one episode recorded on code.	-	Requested by officer to take machine out of service. Machine passes all tests.
28-Dec-16	Vehicle	230	Fault form completed	Bottom door trim on drivers door loose	Loose for some time probably damaged closing door on something	Vehicle not due for service for some time. I will drop into next week to have it checked. Part replaced at 10/01/2017
31-Dec-16	Vehicle	205	Attempt 240v charge without success; will take to mechanic when open, hopefully 03/01/2017	Suspected auxiliary battery failure	Aux battery not holding charge when engine shut down despite long periods on 240v.	Able to get around fault by running engine of vehicle, so fault not critical.
1-Jan-17	Vehicle	225	-	Siren not working	-	-
3-Jan-17	Vehicle	215	-	Step rattles when the car is turned on and the door is opening.	-	-
3-Jan-17	Vehicle	245	As above	Light on dash suggests water in fuel. have drained the water but the light remains on. will order a new sensor and replace when vehicle not in use.	- confirmed fault resolved 10/1/17	-
3-Jan-17	Vehicle	240	OC and fleet tech notified. to replace battery? Tomorrow Vehicle off road, booked for repair on the 4/1/17	Primary battery not holding charge.	-	Have to continue to operate from this unit as 5273 has MDT issue.
2-Jan-17	Vehicle	245	-	Leaking in roof around A/C vent in heavy rain. Lights in back of vehicle stopped working for a short time.	Water in roof	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
4-Jan-17	Vehicle	235	-	Indicator lever is very loose and does not stay on, so vehicle are unaware that we are turning.	-	-
13-Dec-16	Other Equipment	225	All fuses have been checked but nil faults with fuses found.	FM radio/CD player at first was working but would not eject music CD but now the problem seems to be extended to it will not turn on due to a power supply issue. All fuses have been checked but issue remains.	-	All QAS radio communication works in the ambulance vehicle. Fault is just with the Fm radio/CD player.
5-Jan-17	Vehicle	225	VEHICLE OFF ROAD WAITING TO BE TOWED	SIRENS NOT WORKING WINDOW SCREEN CRACKED ABS WARNING LIGHTS COMES ON AND OFF AUX BATTERY WAS JUST REPLACED	?	-
5-Jan-17	Vehicle	230	Notified Comms Centre / CDS. Proceeded to for assessment. Initially nil fault found. Vehicle returned to paramedics. Limp mode reoccurred upon leaving Reassessed. Fuel filter replaced and returned to paramedics (see below)	Code 1 case had just been completed to Twin Waters without incident. Upon clearing scene the vehicle had been driving fine until entering the Sunshine Motorway. Upon entering the Motorway the Fuel Filter light came on and vehicle entered "limp mode".	Unknown	Upon departing with new fuel filter vehicle entered limp mode once again (refuelling in Nambour). Returned to Diagnostic testing ongoing
5-Jan-17	Vehicle	195	SOS informed of problem at TTH	At scene 1900, automatic locking system not unlocking vehicle despite multiple attempts by both officers. Finally successful. Driver returned to driver's side and front cabin would not unlock. Key needed to be used.	-	This problem has occurred before with new key provided by OIC recently.
5-Jan-17	Vehicle	195	Car is out of service	Power steering has failed 2 times during low speed cornering making steering extremely difficult.	Unknown but vehicle was required to drive through torrential rain prior to and during fault.	-
5-Jan-17	Defibrillator	195	Attempted to turn off and on.	Not printing all leads of ECG on ECG paper. Only printing leads II and aVR.	-	-
6-Jan-17	Vehicle	240	vehicle had new inverter installed.	Vehicle had strong smell of melted plastic while driving. Officer returned to truck after dropping off patient to find unit filled with acrid smoke. Inverter had been used during transport but was turned off prior to smoke filling cabin. Strong smell still	? Inverter malfunction	Vehicle returned to Spring Hill OOS mains off, not plugged in for safety
6-Jan-17	Vehicle	215	Vehicle off road.	Handbrake not working	Unknown	-
3-Nov-16	Vehicle	200	-	Cracked windscreen.	Stones flicked up by cane hauler.	-
3-Nov-16	Vehicle	225	advised OIC	Second battery not holding charge causing side step to not work and unit radio slow to start	Properly poor charging set up	-
3-Nov-16	Vehicle	230	Driven to to be fixed	Brake lights out	-	-
4-Nov-16	Vehicle	215	-	Air conditioning in front intermittently not cooling. Also, when fan speed increased the air output did not increase much. After turning car off for about 5 minutes a/c was cooling again.	-	-
5-Nov-16	Vehicle	185	Nil	Left side puddle light not working	Blown bulb	-
5-Nov-16	Vehicle	225	-	Power stretcher service date exceeded.	-	-
5-Nov-16	Vehicle	215	Glovebox closed - needs to be supported when opened or will fall off	Plastic hinge to glove box broken/screw loose	-	-
7-Nov-16	Stretcher	225	Notified SOS	Out of service date	Service overdue	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
8-Nov-16	Vehicle	230	notified. Comms notified.	Engine light on dash. Limp mode on	?	-
8-Nov-16	Vehicle	240	Fault form completed, OIC notified.	The vehicle engine light is flashing - began this PM. The car feels like it is in partial limp-mode. It has not reverted with instructions in user manual.	Engine fuel light.	could you collect wednesday f or repair please.
5-Nov-16	Defibrillator	230	Replacement defibrillator sourced from Corpuls call centre on a loan basis while unit being checked out	On checking defibrillator, no mission test coming up on screen and defibrillator will not charge. Unit charged up, and all checks performed in the right sequence.	-	-
19-Oct-16	Vehicle	235	none	The windscreen had picked up a crack some weeks ago (3+) and was centre low down. It did not have any big run / cracks so it did not render any problem to our vision. During the pass week or so with the extremely hot days the check started to run and form	? Stone	Have let this slide for a while so to minimise the vehicle off road / maintenance time. Hoped for a mechanical service to get this done.
10-Nov-16	Vehicle	230	Contacted CDS Contacted OIC PUT A NOTE ON CAR SAYING ITS OUT OF SERVICE	Stretcher malfunction when loading patient into car . Legs of base of the system in the car that picks up stretcher failed to line up with the stretcher whilst loading . Stretcher became stuck mid air with patient on it .	-	Day crew 11/10 using 821, nil issues, the incident has happened before when vehicle parked on a slight angle different to stretcher. OIC will continue to monitor Likely not a mechanical fault and stretcher is currently being used without incident.
9-Nov-16	Stretcher	230	Reported by during daily check. OIC swapped with 4903 then took defective stretcher to and got replacement stretcher.	Rear wheels not dropping down properly, need to manually ensure they lock down.	-	Not associated with any active case. DVR completed by but to date not showing in reports.
11-Nov-16	Vehicle	230	CDS notified, asked that dispatcher always dispatch via radio	Pager asset number 11eKA510354 4771 no receiving all cases, 2x code 1 cases not received by pager, CDS notified	-	-
11-Nov-16	Vehicle	195	OCS notified, vehicle tagged out and this fault form raised	Vehicle has gone into a "limp home" mode, with very poor acceleration and a flashing amber engine light on	Unknown	-
11-Nov-16	Defibrillator	245	Unable - replaced cable in entirety with 4 lead cable from training defibrillator at Woodridge station. CDS and OC informed.	ECG 4 lead Red lead LL cut and broken whilst on case	Cut by scissors by accident during management of motorbike rider. CN 8187696	Monitor operational.
12-Nov-16	Vehicle	240	Nil	Flat right rear tyre discovered on return to station at end of shift	Unkown	-
13-Nov-16	Vehicle	245	we have reset the MDT at vehicle switchboard with nil resolution to problem.	MDT states "computer has suffered a fatal error and cannot come out of hibernation".	-	-
14-Nov-16	Vehicle	210	-	Oxygen regulator on bottle one leaking from regulator body.	Recent service.	New bottle fitted and and leak started. Leaking from regulator body, not bodok seal.
7-Dec-16	Vehicle	240	Reported to OIC, repaired by North Lakes	Front Driver's search light requires re-attachment	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
7-Dec-16	Vehicle	240	Follow up with officer the proper use of ERV	North lakes officer drove 494 without unplugging at 1800 7/12. Officer unaware this occurred and OIC found fault at commencement of shift. contact and repaired.	Officer did not unplug vehicle	-
23-Nov-16	Vehicle	230	-	Vehicle reversed into gate, RH tail light damaged and door hold open magnet ripped off.	Driver at fault	Please advise if further panel repairs are required when inspected at
8-Dec-16	Vehicle	215	Door has been repaired before	Passenger sliding door not latching correctly	Track movement	Pressure on the back end of the door required to latch door
5-Dec-16	Vehicle	230	Officer advised to put air in tyres.	Drivers Windscreen Squirter detached from washer arm, Side step retraction intermittent, Tyre Pressure Light activated.	Normal wear and tear	List of faults given to OIC from ACP
9-Dec-16	Vehicle General	210	OIC will contact service centre in the morning.	Right headlight is blown / not operational	Unknown	-
9-Dec-16	Equipment	210	-	Top of kit torn	-	-
5-Dec-16	Vehicle	225	New windscreen ordered and ready to be fitted	Damaged Windscreen	Stones from road surface to fi	t same
8-Dec-16	Vehicle	230	oic notified	Stone chip in lower drivers side of windscreen	?stone from passing oncoming traffic on Cooroy noosa road Thursday afternoon	-
9-Dec-16	Vehicle	230	CDs advised, officer attended scene, Assessment at	Hole in front right corner beside modular power point	RTC	Vehicle taken to to be assessed for operational duties
9-Dec-16	General Equipment	230	Crew contacted cds and taken off 2a to swap vehicles. Out of service sign put inside dash of 724 and oxygen cylinders manually turned off.	Contacted by Caloundra oic who stated 724's oxygen system is faulty. System has used 6 x d size oxygen cylinders in the past week. Vehicle is to be taken off road and assessed by . Oic stated had contacted in regard to this matter.	-	-
10-Dec-16	Vehicle	195	Vehicle taken off road. Notified SOS.	Vehicle turns on and switches off. Error Message: " Brake distribution Error. Visit Workshop"	-	-
9-Dec-16	Vehicle	225	None at this stage. Will require panel work	Fracture of outer & inner skin of rear off side barn boor.	Unit was accidentally reversed into hand rail on stairs at	Single officer responding to pick up a patient post scan at
10-Dec-16	Vehicle	230	-	Cracked windscreen, passenger side	-	-
10-Dec-16	Vehicle	225	Fault reported and vehicle removed from service	Drivers door and rear doors will not lock electronically, were functional last night.	-	-
10-Dec-16	Vehicle	225	-	Drivers door and rear doors will not lock electronically. door open warning light and sound remain on, rear emergency lights switch on randomly. this problem commenced this morning post having vehicle at home on call when everything worked ok.	-	both batteries indicate 14.1 volts on gauge inside vehicle
11-Dec-16	Defibrillator	240	Unit placed out of service	Unable to charge for defibrillation	-	-
11-Dec-16	Vehicle	230	Tyre needs replacing. Likely front end alignment. Reported to OS.	Upon completing vehicle check this am prior to 06:00 hrs shift damage to left sided wheel rims was noted (both front and rear rims - front significantly worse than rear). The front left tyre also had a "chunk" (20 coin size) missing from side wall	Unknown	For safety reasons vehicle should not be driven to missing piece of tyre side wall (potential blowout)
11-Dec-16	Vehicle	225	-	Pre-Christmas Service Inspection. Booked 13/12/2016	-	-
11-Dec-16	General Equipment	225	Charging with 240v charger	Defibrillator does not charging in 3242 vehicle cradle, but charges in other vehicles and 240v. 3242 vehicle charger not working	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
29-Dec-16	Vehicle	240	-	Exhaust fumes heavy and coming into unit. Phoned oc and taken off road and appropriate oos put onto vehicle	-	-
30-Dec-16	Vehicle	245	Reported to OS, Comms, Oic, Manager Vehicle at	Unit left in dirty condition, blood in rear compartment	Thursday driver left unit dirty	-
30-Dec-16	Vehicle	230	-	Vehicle in limp home mode	-	-
30-Dec-16	Vehicle	245	Restart of mdt via main switch	MDT touch screen not working, attempted restart however did not work.	Unknown	-
31-Dec-16	Vehicle	250	Notification	Side step slow to come out when door opens, screw keeps coming out preventing step from closing, metal striking place has come off on base of draws in rear patient care area, preventing draw from locking.	?	-
18-Dec-16	Defibrillator	185	Notified CSO.	Corpuls is giving unrealistic blood pressure readings with great variances in a short time frame. All recommendations on correctly taking a blood pressure were followed with up to 140mmHg variance within one minute of the last blood pressure.	It's a Corpuls.	Corpuls has been left in operation as manual blood pressures are available.
31-Dec-16	Vehicle	215	-	Airconditioning and fan to rear and front of vehicle intermittently stops working for various periods of time when in use, ALSO, battery slow to react "sluggly" when not plugged in or used for a period of time (eg. EA).	-	-
31-Dec-16	Defibrillator	185	Sensor was replaced with spare sensor from stores. Faulty sensor left for OIC in store room.	SPO2 sensor faulty.	General wear.	-
30-Dec-16	Vehicle	215	Troubleshooted	Hema GPS U/S	Unknown	-
1-Jan-17	Stretcher	230	nil	Front wheels not Retracting	Previous pt loaded at steep angle	-
1-Jan-17	Vehicle	230	-	Damaged windscreen	Unknown	-
1-Jan-17	Vehicle	250	Fault form	Air conditioning in the front of Ambulance does not seem to cool down as much as it should, despite being on high and also being on the coolest temperature.	Unknown	Operator error.
2-Jan-17	Vehicle	210	-	Hard to describe - ? creaking in front end when turning steering wheel to the right; doesn't feel right.	-	-
3-Jan-17	Vehicle	210	Cannulation tourniquet placed around kit to help secure closed	Magnetic closing latch for Wall mounted airway kit in rear of vehicle broken	-	-
3-Jan-17	Vehicle	240	-	Fuel cap dropped when refuelling causing plastic to break	-	Fuel cap has been taped up as a temporary fix prior to repair and is functioning . Replaced by
3-Jan-17	Vehicle	230	Nil.	Strange smelling exhaust fumes. Oil below minimum required.	Low oil.	Informed OIC of fault and took vehicle out of service. Was informed that officers are unable to top up oil. Servicing required.
6-Jan-17	Vehicle	240	Fault form complete	Alley lights L/R not working	No	-
6-Jan-17	Defibrillator	240	Job logged with	CF Card Full	-	-
5-Jan-17	Defibrillator	245	We have attempted to unplug cable and plug it back in, we have turned monitor on and off again, we have tried both the paediatric and adult sensors and we have tried several different cables in the same Corpuls3 to nil effect.	SPO2 attachment port is ?defective. Multiple different SPO2 probes not connecting/communicating with Corpuls. unable to read any SPO2s on patients. came up with alarm "defectvie oxi cable"	Unknown.. equipment was working at time of pre-shift check and on first case, then halfway through case, stopped reading.	Equipment deemed not operational due to being unable to get any SPO2 readings on patients.. which would be dangerous if pt is critical/respiratory.

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
6-Jan-17	Vehicle	240	OSU contacted techs arranged	mdt failure	-	-
6-Jan-17	General Equipment	240	Removed from service - stock at station check and MRR advised.	Unopened syringe found to be in four separate pieces with sharp exposed.	-	MRR passed on information to Fleet and Equipment for follow up
17-Dec-16	Defibrillator	235	Pads changed and defibrillator connection checked	Alarming with from memory po post (defib) disconnected. Defibrillator pads were changed and checked to make sure they were correctly put in. Alarm sporadic and not happening all the time	-	-
18-Dec-16	Vehicle	210	Vehicle restart, doors checked.	Side step won't retract	-	-
18-Dec-16	Stretcher	240	Tried different stretcher in vehicle 5-356 locking mechanism and works perfectly - appears only the stretcher above is having issues locking properly into 356	Stretcher not locking in properly - appears locking bolt needs to be adjusted. Appears "too long" (length wise) to lock in correctly	-	No SHE reported completed as not required. Stretcher located Caboolture Plant room floor with OOS paperwork on top . OIC organised on Mon 19th Dec but due to Christmas Period was only collected and replaced on 30th Dec 16
18-Dec-16	Vehicle	235	Taken off road with bonnet up, located on plant room floor for mechanic to look at.	Significant water leak from roof air-con vent on inside of vehicle. Litres of water pouring from roof and caused significant amount of water to leak through back of vehicle.	Vehicle was stationary at lights during onset of storm with large hail stones. It was after a few minutes of this that water started leaking through when vehicle was stationary under cover.	Might be operational, need the mechanic to check first.
18-Dec-16	General Equipment	210	Backup power supply (9V battery) attached and functional	Power supply to safe keypad damaged	Battery fell away from adhesive mount upon opening of safe	-
18-Dec-16	Vehicle	235	Nil	Cracked in windscreen	Unknown, crack in windscreen when started shift	If crack continues to grow will become non operational
18-Dec-16	Vehicle	250	Vehicle was jumped and returned to Coral Gardens where it is on loan	Vehicle on scene at acute case :failed to start	RACQ identified that the emergency battery has failed	Vehicle will start but should have the emergency battery checked/ replaced prior to being placed in service
17-Dec-16	Vehicle	240	-	High temp warning, fan shroud loose and damaged. Fan damaged.	-	-
19-Dec-16	Vehicle	210	Contacting fleet supervisor asap to discuss issue	Nil fluid in radiator bowl	Nil obvious leaks in engine bay or under vehicle	-
19-Dec-16	Vehicle	245	Vehicle taken to , engine has fuel injector issue. picking vehicle up for service	Fuel injector issue	Engine making ticking sound	-
19-Dec-16	Vehicle	230	Advised CDS RACQ called to check vehicle	Does not start	-	ALREADY FIXED BY RACQ
19-Dec-16	Vehicle	240	-	Vehicle in Limp mode	-	A/OIC contacted awaiting for someone to pick up
19-Dec-16	Vehicle	185	OIC emailed. Fault form completed.	Passenger side headlamp unit requires replacing. Vehicle taken to for blown headlamp bulb and bottom mounting legs for the main reflector found to be broken. Reflector and bulb loose and vibrating.	Unknown. Headlamp blown and taken to be changed, fault discovered during replacement.	Auto Electricians said that they can fit new unit if required.
19-Dec-16	Vehicle	230	Fleet Manager advised with and photos forwarded.	Paint and decal scratched with a small dent to Passenger side rear door and panel from minor RTA.	Turning too sharp left from car park and hitting bumper of another parked car.	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
19-Dec-16	Vehicle	215	-	Window seal in back next to stretcher leaking water onto interior cabinets during rain	-	-
19-Dec-16	Vehicle	230	tried to restart vehicle, warning lights still visible. Notify CDS	Several warning lights on dash including brake warning, abs warning light	-	-
19-Dec-16	Defibrillator	250	-	NIBP pumps up multiple times and fails to give reading. Checked against both officers multiple times in pre start without success. Tried a separate cuff.	-	-
19-Dec-16	Vehicle	185	-	Rear view camera requires adjusting up	?	Bolts too tight to adjust by hand
19-Dec-16	Defibrillator	235	-	Unable to detect test box connected to defib port (2x different test boxes), therefore unable to do dump test.	-	-
14-Nov-16	Vehicle	240	-	Tyre pressure light on dashboard illuminated	-	-
12-Nov-16	Vehicle	240	-	Screw in tyre - racq attended - mechanic to check	-	-
11-Nov-16	Vehicle	205	Reported and fault form generated.	cracked front windscreen	bird strike while travelling to course in Longreach	-
11-Nov-16	Vehicle	205	Reported and fault form generated.	cracked front windscreen	bird strike while travelling to course in Longreach	-
15-Nov-16	Vehicle	185	-	Step will not retract without vehicle engine running for some time	-	V 5159
15-Nov-16	Vehicle	215	Nil	1 torch doesn't work, review mirror needs attaching, scoop is out of date due for service 3/4/15	Nil	Review mirror is currently located above sun visor passenger side
15-Nov-16	Vehicle	210	UNIT IS TO BE CHECKED BY QASOIC, AND THEN TAKEN TO .IF NEEDED.	Side step remains stuck in retracted position	-	Discovered earlier today by day crew.
16-Nov-16	Vehicle	230	Called CDS who called RACQ.	Heard noise from rear tyre during transport into hospital. On arrival rear right tyre inspected and found large screw protruding from tyre. On arrival of RACQ the spare was found to be flat and also have a screw imbedded.	A screw in the tyre while driving.	Spoke to CDS in regards to having no spare who instructed RACQ to take a spare from unit 4774 located next door at Caloundra station. Thus 4774 does not have a spare tyre.
16-Nov-16	Vehicle	230	-	No spare tyre. CDS directed RACQ to take spare from unit 4774 to replace damaged tyre on 4775 as this vehicles spare was also damaged.	The inaction to replace the spare tyre on 4775 many weeks ago despite this crew completing a DVR.	Operational however needs a spare replaced ASAP.
15-Nov-16	Vehicle	210	Flashlight removed from vehicle at this time	Driver side Flashlight not working	?? Could be charging station or flashlight battery	-
16-Nov-16	Vehicle	225	-	Front left fog light casing smashed however light still operational	unknown - noted on vehicle check	-
16-Nov-16	Vehicle	225	No	Pt care drawers don't move, one drawer doesn't close No locks on rear door meaning rear doors cannot be locked open. Dangerous in winds or when vehicle is on angles	Bolt loose under draws. Bolt tightened and draw moves. Rear locks fitted to door and operational	See above
16-Nov-16	Stretcher	235	Changed battery in stretcher. Ran vehicle while loading, giving a slight improvement.	Power stretcher low power loading and unloading.	Appears to be a power issue with the Arms of the loader	-
17-Nov-16	Defibrillator	250	-	Pulse oxy not working	not sure	Stopped working thru the shift
17-Nov-16	Vehicle	215	nil	Side rear door, passenger side will not stay open, rolls back towards you	unknown	-
18-Nov-16	Vehicle	240	MVA form will be completed ASAP and she report also.	Drivers door damaged, buckled and front right panel.	Door clipped by ambulance leaving station.	dr iver of other vehicle. No one it stationary 204.
18-Nov-16	Other Equipment	210	Nil. Turned door off.	Roller door for plant room off tracks. Unable to shut.	Door attempted to close on vehicle.	Door came down on vehicle while sensor beam should have been broken.

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
18-Nov-16	Vehicle	235	After speaking with Fleet tech will have been advised to return vehicle to Ipswich station.	Air suspension not working.	Unknown	Very rough travelling into the city this morning.
24-Dec-16	Vehicle	230	Fault form	Reversing camera doesn't work through MDT: blue screen	-	This issue has been ongoing and still not resolved
24-Dec-16	Vehicle	240	RACQ change tyre	Flat tyre	Screw in tyre	Tyre requires repair or replacement
24-Dec-16	Vehicle	225	-	Check Engine light started flashing on return from Toowoomba. Manual indicated the car was in 'emergency' mode and was safe to drive to a repairer. The vehicle was extremely slow to accelerate over 40 km/hr.	-	Manual indicated possible fuel delivery or ignition problems, so car taken off road.
11-Dec-16	Vehicle	185	nil - horn used as auditory beacon on code 1 response	siren stopped working while attending case	unknown	-
11-Dec-16	Defibrillator	230	Officers reported to OIC but were unable to complete report	On multiple occasions, SPO2 shows Faulty cable after checks completed	-	This has occurred with multiple defibs at Kawana Station. Officers were able to speak with Tech services and rectify the problem but it seems it keeps occurring therefore problem could be elsewhere?? CASE CLOSE ALL DEFIB OPERATIONAL
9-Dec-16	Vehicle	215	-	oxygen leak, appears to be coming from the wall attachment of the 2nd tap	-	-
12-Dec-16	Vehicle	215	Fault form and OIC email.	Music radio in vehicle is not operational.	-	-
12-Dec-16	Vehicle	210	A/OIC notified Fault form raise	? Brake pads worn down "metal in metal sound"	Wear and tear	-
12-Dec-16	Vehicle	215	Used 'blower' around mechanism (to blow out any dust that may have got caught).	Stretcher locking mechanism (in vehicle, drivers side) is intermittently playing up. Need to manually release mechanism to put stretcher in vehicle.	Nil	-
12-Dec-16	Vehicle	185	Switched to 7144	Dispatched to job; turned key wouldn't turn on; checked it was unplugged, checked battery (not empty), checked gear, used emergency start still unable to start vehicle.	Unknown	-
13-Dec-16	Vehicle	215	-	Passenger electric window intermittent operation needs to be lifted to close only works when it feels like it	-	-
9-Dec-16	Stretcher	230	Operational Centre notified and stretcher put out of action and ready to be taken to for inspection Monday 12th of December	without warning, knee raise are of stretcher collapsed with patient on board.	-	original fault form filled in by crew has had an error. Pleae contact for further information if required.
13-Dec-16	Vehicle	205	Notified communication centre, SOS & OIC. All relevant paper work completed	Front left wheel arch has a crack in t & the wheel arch is separating from the main body of the vehicle. There is a dent in the front passenger side door.	A kangaroo decided to jump into the side of the vehicle whilst the vehicle was traveling at approx 80kmh or less at 0001hrs in the morning.	-
13-Dec-16	Defibrillator	240	Attempted to replug cable into machine no effect	Faulty oxygen sensor cable, intermittently working. States faulty Oxi cable	-	-
13-Dec-16	Vehicle	240	-	side step collapsed when stood on. One side of the vehicle side step is detached and unsafe. No step inhibit button to inhibit step.	-	-
6-Jan-17	Defibrillator	210	OIC to contact supplier and order replacment.	Missing shoulder strap to Corpuls Defib / Unit 2292.	Previous officer has no recollection of location / doesnt remeber seeing on the unit all rotation. All vehicle audits - all ok.	Reminder email / education to QAS Blackwater officer not to remove Corpuls 3 accessories / report defects.

RTI RELEASE

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
6-Jan-17	Vehicle	240	Taken to mechanic but unable to diagnose issue in short term, and will required more time to adequately assess fault	Front panel (centre console) not operational including air conditioning.	Unknown but series of electrical anomalies has been presenting itself with this car	Car can be driven ok, but nil air con
5-Jan-17	Vehicle	245	Nil	Rear spoiler on the top of truck, in the middle. damaged.	Officer reversed into the top of a carport at the scene of a job. I believed that there was nil obstructions present.	Really sorry.
6-Jan-17	Vehicle	245	Checked vehicle was plugged in and charging.	Siren is repeatedly chirping when vehicle is parked.	Unknown	Also has a clicking sound coming from charging compartment
7-Jan-17	Other Equipment	185	Have replaced batteries multiple times, charged unit on charging dock	Not holding charge. Have tried multiple fully charged batteries & all activate low battery alarm on handheld.	? faulty connection between handheld unit & battery?	-
8-Jan-17	Vehicle	235	Nil	Side step not functioning, reverse camera working intermittently	Unknown	-
8-Jan-17	Vehicle	225	-	Side door access to patient care area can only be opened from outside and not inside	-	-
8-Jan-17	Vehicle	230	switched on and off several times to reset MDT but no success	MDT boots up but then wont work...stuck at reboot screen	-	-
19-Dec-16	Vehicle	230	Changed battery. No difference. Swapped battery with another vehicle. No difference. Duty Officer attended to troubleshoot.	PowerLoad does not appear to have reliable power. Stretcher not settling into place upon loading. Load arms not operating. No lights on each side of stretcher (yellow/green). Stretcher must be manually loaded and unloaded. Power light not working.	-	Similar episode reported once within last week on same vehicle. Rectified with battery change.
20-Dec-16	Vehicle	245	We checked under the hood, nil leaks noticed, nil damaged noticed to engine. With our limited mechanical knowledge and due to concern that vehicle may not be operational, we have put it out of service.	we noticed a strong engine smell coming from the vehicle. smell only occurring if vehicle driven for more than 10 minutes. The vehicle display showed a warning light signifying that a headlight is low, however nil other warning lights came up on dash.	Unknown cause. Smell simply started whilst we were driving to a case (code 2)	Vehicle had been fine with nil issues upon doing pre shift checks, and as we had not done long drives prior to halfway through the shift, we did not noticed the smell as much.
20-Dec-16	Vehicle	185	Will contact local electrician.	Vehicle battery not charging in the plantroom. Vehicle currently won't start.	Query charging or battery failure	7311 is 4WD Toyota Troopy. Second SJ Unit. Used in wet weather and sometimes used as spare by Innisfail station. Main unit 7184 operational as normal.
19-Dec-16	Vehicle	185	Fault form	Fridge not getting sufficiently cold	Usage	-
19-Dec-16	Vehicle	215	-	Windscreen chip drivers side	probable small object' ? Stone impact windscreen. Unknown date. Noticed on commencement of today's shift.	-
20-Dec-16	Other Equipment	230	Crew attempted to troubleshoot to no avail. Unable to print eARFs.	eARF printer at Sunshine Coast Private Hospital (Ward 2 behind amdin area) reportedly not working. report from QAS Kawana crew to CDS	Unknown	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
20-Dec-16	Vehicle	225	Reported - fixed and still an ongoing problem.	Aircon non operational in back unit.	-	As this is an ongoing problem, in summer . we find it very uncomfortable, hot and not suitable for paramedic or patient and needs to be addressed.
21-Dec-16	Vehicle	225	Fault form	Side step isn't working	-	-
21-Dec-16	Vehicle	215	Reported to OIC	Front left mudguard damaged/torn from main chassis of vehicle; superficial paint transfer/scrape along left side of vehicle.	unknown- discovered by day shift 21/12/16 0645-1845.	Sent to for inspection - may require part ordered
21-Dec-16	Vehicle	210	-	Air conditioning not cooling	-	-
21-Dec-16	Vehicle	210	Nil. Reoccurring issue?	Reverse camera screen - blue screen only, no images appear on screen.	NA	-
21-Dec-16	Vehicle	240	Part ordered 20/12/16	Warning light on dash- check coolant level state that sensor is faulty	Chermside	oic notified
21-Dec-16	Vehicle	195	-	L headlight out on low Beam. High beams working okay.	Unknown, was like this at commencement of shift	-
21-Dec-16	Vehicle	235	Nil action	Airway seat seatbelt in rear of ambulance jammed....not working.	-	Will require repair before being used after dark
22-Dec-16	Vehicle	215	Sway bar rubbers replaced suspension inspected	Passenger side rear suspension appears lower than drivers side rear. Unit leaning badly to passenger side when viewed from rear on flat and leave ground	Fraser Island	Oic test drove unit OK
23-Dec-16	Vehicle	210	Comms contacted by phone and advised.	Radio receiving unreadable. Comms can read unit. Incoming transmissions loud static unable to make out any speech.	-	Operational in that it is on and transmitting static, but not useful
15-Dec-16	Vehicle	225	-	Repairs noted during service for repair, replace aux drive belt, main battery, belt idler. Repair to driver seat wear.	-	-
23-Dec-16	General Equipment	245	-	Fire extinguisher missing from vehicle 6403	-	-
23-Dec-16	Vehicle	210	-	Rear door lock is malfunctioning, at times door will not open when unlock button is pressed.	Unknown	-
23-Dec-16	Vehicle	240	ROC AND OIC NOTIFIED, VEHICLE CHECKLIST COMPLETED, 5256 WILL BE THE REPLACEMENT FOR THE NIGHT.	HEADLIGHTS HAVE BLOWN	HEADLIGHTS HAVE BLOWN	-
24-Dec-16	Defibrillator	240	-	Dyring monitoring 12 lead failed and could only read lead II. has happened on previous monitors.	-	-
25-Dec-16	Other Equipment	250	Written fault form completed and put with charger. Charger exchanged with other unit from mechanic workshop, as per instruction from SOS.	Vehicle charger not working. Warning light flashing. Vehicle not starting.	-	-
25-Dec-16	Vehicle	215	The 12 V plug needs to be female adapter needs to be relocated to a position outside the overhead compartment. The opening and shutting the perspex compartment causes the lead to pull out of its connection.	12 V plug (female) for the Corpuls charging system in rear overhead compartment has come away from mountings. It continually has earth lead fall off. Now it's not working at all.	-	-

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
24-Dec-16	Vehicle	240	-	Unit would only start using emergency start. When running multiple warning light on dash turned on and stayed on.	-	-
25-Dec-16	Vehicle	215	SOS aware, unable to rectify fault until mechanics re-open after Christmas break	Flat battery	Flat battery	-
25-Dec-16	Vehicle	215	Comms notified and vehicle left with bonnet up in plant room	L) wiper became detached from wiper blade in heavy rainfall at approx 2130	heavy rain- high speed windscreen wipers	-
24-Dec-16	Vehicle	230	C1 switch pad turned off/on. RACQ attended to check fuses	While driving c1 on the Nicklin Way, the siren ceased. All other electronics operational.	-	Vehicle returned to QAS Maroochydore. CDS and OIC notified.
25-Dec-16	Vehicle	250	SOS NOTIFIED- she report to be completed tomorrow on next shift	Rear right tail light smashed	Reversed into fence-tail light caught on fence.	Replaced r/h/r t/light assmbly.
25-Dec-16	Vehicle	240	Vehicle pulled over and switched off with mains power turned off, key removed and vehicle locked. Vehicle restarted with no engine lights or warning lights illuminated with loss of power still present. vehicle slowly returned 400m to station	Vehicle gone into "limp" mode. No engine or warning light illuminated	Vehicle started as per normal. waiting at rail crossing in mitchelton during code 1 response when accelerating vehicle dramatically lost power during gear change between 1st and 2nd gear. No engine light or warning lights illuminated.	#NAME?
25-Dec-16	Vehicle	195	Movement vehilce away from the post	Minor damage passenger side module and footstep rubber cover ripped & possible mount broken/damaged though still operates	Hitting a gate post driving forwards	SHE and Motor Vehicle Accident Report submitted and reported to SOS
25-Dec-16	Vehicle	195	Vehicle tagged out of service	Side step not working every time door is opened. Rear air conditioning vents dripping water onto stretchers.	Unknown	-
25-Dec-16	Vehicle	210	-	Right headlight blown	-	-
26-Dec-16	Defibrillator	250	-	Pulse ox defective cable. Cable from machine. No available replacement cables.	-	Corpulse in OIC office awaiting part.
26-Dec-16	Vehicle	250	Nil	Driver's seat unable to be moved forward enough to adequately reach foot pedals. Patient care chair also unable to be moved forward making it difficult to reach patient care draws and monitor- can't use seat belt as must reach forward out of chair.	Unknown	-
26-Dec-16	Defibrillator	215	tried several cables and finger sensors - nil working. Swapped Corpuls to PTS vehicle for the evening,	SpO2 cable not working	no	Other sections (BP, ECG) working on Corpuls just not Spo2
27-Dec-16	Vehicle	215	Fault form	Side step only coming out half way.	-	-
25-Dec-16	Vehicle	240	NA	CHARGING PLUG AT FRONT OF VEHICLE IS MISSING	NOT REMOVED BEFORE SOMEONE DRIVING AWAY	NA

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
28-Dec-16	Vehicle	210	CAPCOM OCS informed of the incident and replacement stretcher used for remainder of shift.	Stretcher collapse during the loading of the patient at half height. Head end collapsed, mechanism was locked in and function tested. Patient had been sitting on the bed for approximately 1 minute prior to the collapse. No injury to the patient.	Locking mechanism failure	Stretcher asset number QCR07781 top and QCR07782 base both with a service due date of 12/16
28-Dec-16	Vehicle	240	Contacted repairer	Hot air from air con only after repair for same this morning	Unknown	-
28-Dec-16	Vehicle	195	Nil	Stretcher battery has failed. Initial operation (unloading) normal. Once placed on stretcher operation stalled with voltage reading 4. Operation continued using charger with success. Comms notified.	Ni	-
6-Jan-17	Vehicle	225	-	Siren not working	-	-
6-Jan-17	Vehicle	205	Booked in with mechanic in Jericho - Due 10/01/17	B Service	-	-
6-Jan-17	Vehicle	240	Vehicle fault report.	Clips that hold doors open need replacing. Right side clip broken. Left side not holding door open (Rear doors)	Normal wear and tear.	Please check when car is in for next service.
6-Jan-17	Vehicle	210	Door has been closed / secured and it has also been determined that the area can be accessed to replace oxygen if needed from the inside.	Door locking mechanism is broken and skin of door caved in.	While traveling rear oxygen door has opened with great force / flung against the vehicle and then closed rapidly resulting in the actuator / door mechanism of the door being damaged and skin of the door being damaged / caving in due to the force.	Vehicle is operational. Photos sent to the Manager of Operational readiness as unable to upload images.
6-Jan-17	Vehicle	230	Reported to CDS, OIC and taken off road	Rear cabinet has come away from wall attachments and is hanging over stretcher. Presents a collapse risk for any patient or paramedic in fear of vehicle	Unknown cause, noticed when going over bumpy road, loud rattle occurring in rear of vehicle.	-
7-Jan-17	Vehicle	240	-	Passenger front indicator globe blown during shift, side mirror indicator works and passenger rear indicator works fine.	-	-
7-Jan-17	Vehicle	245	Attempted to re-inflate at Service station. when back at Logan West air was heard escaping, large hole observed in tire tread.	Flat rear right tire. Can hear air escaping, visible hole.	Unknown. Warning dash light came on while driving.	-
7-Jan-17	General Equipment	195	none (other than fault report), radio is working fine so far	black cable that covers the small colored cables on the radio's handheld piece is damaged and therefore exposing those cables	not sure, possibly wear and tear	-
7-Jan-17	Vehicle	195	Tried using the metal key inside but still unable to lock or unlock door to load or unload stretcher	Key not working. Unable to lock or unlock	-	Sos informed and advised to make vehicle out of service.
7-Jan-17	Vehicle	230	NA	Passenger sliding door does not lock into hinge to stay open - door slams shut when vehicle is on incline Mobile phone charger does not work No badge on back door	-	-
7-Jan-17	Vehicle	225	#NAME?	- pager missing - 2 orange travel lights driver side N/W - SatNav N/W (touchscreen & 'find address' function N/W) - sidestep N/W	#NAME?	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
8-Jan-17	Defibrillator	195	Shut machine down ,pulled all cables out and turned back on with no luck. Transported pt and then put machine through a test mode again. New test showed no problems and did show correct wave lengths . Machine taken out of service after talking to SOS	Upon a job tried to take 12 lead but did not register on any Leeds	Unknown	-
8-Jan-17	Vehicle	210	Multiple tests with keys and locking mechanism Resetting GPS, checking wiring	GPS not turning on Patient compartment side door not locking	-	GPS is not operational, side door opens and closes but does not lock
9-Jan-17	Vehicle	245	attended and fault cleared with nil further action required.	Warning on dash came on stating to visit workshop whilst driving back to station	-	-
9-Jan-17	Vehicle	230	Vehicle checked at	Reverse camera view shows only white	-	Fault reported by night crew day crew found no fault with unit but dropped into at thier request and had it checked. Black & white veiw instead of colour will check it again with next service. 11-1-2017
9-Jan-17	Vehicle	240	-	Oxygen door is stuck and can't be opened. Even the manual key unlock won't work, the emergency release isn't working either.	? that actuator may have failed	-
9-Jan-17	Vehicle	240	-	Reversing camera not working Blue screen only. Appears to an intermintint problem.	-	-
9-Jan-17	Vehicle	240	OIC got one pager reprogrammed to vibrate.	Neither pager vibrates	-	-
9-Jan-17	Vehicle	185	-	Both front and rear AC not working, passenger front seatbelt doesn't operate correctly, livery on bonnet heavily faded. GPS no power to unit.	-	-
9-Jan-17	Vehicle	240	-	Chip to windscreen , approx 20 above front drivers dashboard vent	Stone ???	Assessed by A/OIC 20-1-17 and nil chip present unsure of exact repair date.
23-Dec-16	Vehicle	210	Nil	Airconditioning in the front cabin not cooling. It sounds like the fans are running but little are coming out of the air Vents. The air also does not feel very cold.	-	-
23-Dec-16	Vehicle	240	Comms , Roc , and Acute OS notified , able to drive during the day but query, not at night. Sent E-mail to Caboolture OIC.	Front left drivers head light blown	-	-
23-Dec-16	Vehicle	245	Disconnected the control wires tapped them to the wiring loom and placed damaged retractable step in station shed	Side step damaged and fallen from brackets	Noticed post uturn returning from qfrs standby	Contacted OIC and Fleet manager regarding issue.

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
24-Dec-16	Vehicle	195	Removed and spare from training room placed in 1107 (not used for shift only one job)	Officer using monitor on case noted ECG strip not printing. Only top portion is printing, not even a faint mark for lower portion and leads.	No	No
25-Dec-16	Vehicle	215	-	Transmission failure	-	On loan 502 from maryborough
25-Dec-16	Vehicle General	225	Taken off road	Engine light flashing	Unknown had been function ok for the last 2 shifts.	-
26-Dec-16	Equipment	225	advised OIC	Latch not working rear left side latch where CT-6 is	-	-
26-Dec-16	Vehicle	215	-	Check engine light has come on	-	-
26-Dec-16	Vehicle	250	OOS, at southport station.	High temp / low coolant alarm sounding. Coolant reservoir full.	-	Replaced header tank.
26-Dec-16	Vehicle	250	Technician has been notified, not available until Wednesday.	MDT not working despite crew resetting it from the main switch.	- tech attended station and rectified fault	t
26-Dec-16	Vehicle	250	-	Front cabin of vehicle filled with car fumes.	-	-
26-Dec-16	Defibrillator	210	Turned off and on, tried different test box	Defibrillator pads and test box not connecting to corpuls	-	-
27-Dec-16	Vehicle	190	Unable to self repair	Oxygen portable kit zipper has completely failed	Operational use & old equipment	This has been broken for a considerable time and it is difficult to use in this condition
27-Dec-16	Vehicle	235	Oxygen on second cylinder turned off and A B switch turned to A	Leaking O2 system	-	On checking the vehicle on 26th Dec 16 it was noticed that the O2 cylinder on the front of the vehicle was empty. The cylinder was changed out. On checking the vehicle on the 27th Dec 16, it was again noticed that the oxygen cylinder was empty. Leaking.
27-Dec-16	Vehicle	250	-	Sat Nav not working. Car phone charger not working. Rear door of unit not closing properly	-	-
26-Dec-16	Vehicle	185	Report	Fridge latch U/S. Has come apart	Unknown. Found during vehicle check the day prior	-
27-Dec-16	Vehicle	230	Manual reboot, continuous running of engine to ensure auxiliary battery charged. Fault is still occurring. This is the are fault that has occurred on multiple occasions over the last 3-6 months and has been reported numerous times.	MDT continuously rebooting, now appears to be staying on and randomly turning off to blank screen. Requiring multiple engine restarts. Crew unable to use MDT to log on, Comms notified.	-	-
26-Dec-16	Vehicle	230	Notified OIC Buderim & completed vehicle fault form	Toughbook charger broken. Plastic housing socket in car has cracked at screws - not charging.	? perished plastic.	No toughbook charger.
27-Dec-16	Vehicle	215	-	Passenger side back door not clipping open. Side patient care door not clipping open	-	-
27-Dec-16	Vehicle	210	Tried some trouble shooting but still not working.	Corpuls charger on wall of grab and go locker is not working (no light illumination). Corpuls is not charging.	unknown	Can remove Corpuls from vehicle and place on desktop charger if required and than return back to vehicle for use.

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
27-Dec-16	Vehicle	225	RACQ contacted and vehicle taken off road	LHR tyre noted to be flat. Changed by racq. Upon removal tyre noted to be scrubbed on inner edge. This faulty tyre is located under the vehicle in the spare location. RACQ investigated other tyre. RHR tyre is scrubbed down to wire on inner edge.	May be issues with wheel alignment or camber	Vehicle is located in rear car park at Toowoomba station.
27-Dec-16	Vehicle	240	-	Missing portable radio 501223p2	-	RADIO found at Deception Bay Station 13/2/17
30-Dec-16	Vehicle	215	Have turned vehicle off and let sit for 30 minutes in case condenser is frozen, nil improvement.	Air conditioner not getting cold, only cool. This is occurring both in the front and rear of the vehicle control panel in back set to minimum of 20 degrees yet only getting down to 26. Also, upon startup control panel flickers different numbers ie. 42	-	-
30-Dec-16	Vehicle	245	Notified OS and vehicle will be towed	Vehicle went into Limp mode. Loss of power and vehicle engine warning light came on.	Unknown	-
31-Dec-16	Vehicle	245	Confirmed with have reviewed vehicle and fault corrected	Engine light. Struggling on acceleration	-	-
31-Dec-16	Vehicle	215	Fault form.	Music radio speakers are broken.	Probably music played too loudly or too often.	-
31-Dec-16	Vehicle	245	I put the vehicle off the road due to WH&S concerns, however, the ROC permitted another crew to log into the knowingly faulty vehicle. Thus, nothing has been done to rectify the compromise to staff safety.	MDT turns itself off leading to compromise of staff safety.	-	Also, the Corpulse is missing the adult SpO2 probe. Please replace it.
1-Jan-17	Vehicle	225	Taken out of service	Siren in vehicle stopped working during a code 1 response. It stopped working after been turned off for a few minutes as it was not required and would not turn back on.	-	-
1-Jan-17	Defibrillator	240	Faulty NIBP cuff lead has been replaced, unit now fully functional	Lead to blood pressure cuff broken	Trying to reattach cuff to monitor	Cuff still able to inflate
1-Jan-17	Vehicle	230	Will be available at station tomorrow Monday 2/1/16 at Caloundra Station	Reversing camera not working blue screen only	-	-
1-Jan-17	Vehicle	230	Report issue,	When turning to the right it sounds like beads running through a pipe. This does not do it if the air con is turned off? Air con issue. Noted that front Passager floor is soaked in water	-	vehicle will be available on Thursday 5th or Friday 6th to be looked at if possible.
25-Dec-16	General Equipment	235	Oic noticed	Crack screen on Garmin gps	gps in wrong position for single response officer to operate gps safely ...repositioning of gps can be awkward when bracket is to stiff ... Gps need to be moved higher also so drive is not taking eyes from rd and less need to for gps repositioning ..	-
2-Jan-17	Vehicle	235	Previously reported	Indicator stalk fails to indicate left. The auto cancel does not work on R indication (annoying) however indicator will not stay on when indicating left (road worthy issue)	-	-

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
2-Jan-17	Vehicle	230	Nil capability of reattaching the button	Passenger side window button broken - plastic connection has snapped	Normal wear and tear	As advised by ACP
3-Jan-17	Vehicle	230	Notified Beerwah OIC	MDT GPS not working, car not tracking with comms therefore ?Duress button will not work to full capabilities.	Technician indicated fault may be because of lack of ventilation behind electrical panel where blue MDT box is.	Technician replaced blue box and MDT head in vehicle at station ? Jan 5th making unit operational again. Further work required to add ventilation to panel/ cover
3-Jan-17	Vehicle	240	-	12v plug in front cabin does not appear to be operational	- FYI and repair at next service - thanks	Ema il sent to
3-Jan-17	Vehicle	215	Vehicle taken to	Electric step stops working intermittently throughout shift	? Rock stuck between step and vehicle	state step needs to be taken out and replaced as it appears slightly out of shape.
3-Jan-17	Vehicle	250	RACQ changed to tyre put faulty tyre back as spare	Puncture in spare tyre	unsure what caused the puncture	Vehicle is operational / no operational spare tyre
3-Jan-17	Stretcher	215	Stretcher immediately taken out of service - delivered to mechanic for service.	Green button sticking/jamming when patient is on stretcher. Red lever on head end handle not releasing - sticking, legs had to be pushed down to full extended position with foot.	? Gas struts	Last serviced 13/4/16 - next service due 13/4/17 - service number 1145
3-Jan-17	Vehicle	230	rang Rang CDS.	Lost Module power -Nil access to emergency lights and siren, Nil access to internal lights.	?	-
3-Jan-17	Vehicle	185	Vehicle taken off road	Side door that access patient care area, will not open needs key to open it. Side door that gives access to the gear does not close properly. On a code 1, door came open and oxygen bag nearly hit another car.	-	-
3-Jan-17	Vehicle	240	The step was disconnected so that it could be operated manually	Side step not functioning properly and side door catch is loose	Unknown	-
8-Jan-17	Stretcher	235	vehicle has been removed from service for safety	mechanical motor part in vehicle with not working properly, it wouldnt unload or allow stretcher legs to be dropped or taken up properly, stretcher has been manually loaded into car and is not connected to mechanical motor device in ambulance	unknown cause has been working fine allday.	be aware removal of stretcher needs to be done manually.
8-Jan-17	Vehicle	195	Notified OIC via email as it occurred on weekend a replacement cover has not been organised yet.	Front drivers side fog light cover was found smashed after IHT noticed when cleaning front of vehicle where glass was noted on front bumper.	Unknown ? Rock hit during IHT.	-
8-Jan-17	General Equipment	240	-	BGL erroring and not working when reading blood	-	-
9-Jan-17	Vehicle	230	-	MDT not working again. MDT will not boot now. Fourth issue with 4 weeks.	Uniknown	-
9-Jan-17	Vehicle	240	Fault form	On arrival at station note on dashboard about vehicle not charging. On starting vehicle difficult to turn over - battery low despite being on charge for approx 12 hours over night. Charger was working correctly on vehicle check this am.	Battery not charging/holding charge	If vehicle turned off on scene/ at hospital doubtful if will restart
9-Jan-17	Vehicle	240	OIC notified, workshop notified.	? Aux battery problem. When vehicle turned off and not plugged in, MDT, COMS RADIO and REAR 12V turning off. Aux battery reading 9v, main battery 13v.	N/A	Battery previously tested with nil fault found.
8-Jan-17	Vehicle	225	#NAME?	#NAME?	#NAME?	-
9-Jan-17	Vehicle	215	-	Front suspension sounds like an old horse and cart suspect front sway bar rubbers worn Passenger side window only works when it feels like it not when I need it to Passenger side scan light bracket bent requires straightening	Fraser Island rough tracks and wet beach conditions	Front sway bar bushes replaced

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
9-Jan-17	Vehicle	195	Notified OIC.	Slow to start, query battery problem.	-	Not our operational vehicle, went to change into vehicle and noted same start delay as 1139.
9-Jan-17	Vehicle	195	Vehicle running on idle hold to recharge battery	Slow to start, vehicle side step not working, radios not working when vehicle is turned off, ?battery problem. Left rear brake light not working.	-	-
9-Jan-17	Vehicle	230	oic notified, highlighted on checklist and fault form completed	Reverse camera blurry, possibly filled with water. MDT continuously beeping. MDT not showing street names or letters when attempting to manually input address. Still able to navigate via maps and following purple line, but no literature showing.	unknown	-
6-Jan-17	Vehicle	210	-	240V flap has broken off vehicle	I've asked the crew involved and they say, they "just found it that way". Will ask officers returning tomorrow, who were on the car on Thursday, if they've got any idea what happened.	Operational by pressing 240V override.
9-Jan-17	Vehicle	245	-	Metal arm for draws in rear snapped	Unknown cause	-
9-Jan-17	Vehicle	245	-	Passenger adjustment knob broken so seat cannot be adjusted	-	-
9-Jan-17	Vehicle	240	OIC notified	broken break light at back and minor shattered light casing on R) side of vehicle	unloaded stretcher rolled into vehicle (nil patient)	nil further faults and damage to back lights
29-Dec-16	Vehicle	240	Reported only.	Unit very sluggish on acceleration. No power when stopped on a hill. Every acceleration from a stopped or near stopped position is affected. May be dangerous when negotiating traffic. This was still apparent on Friday 6 January 2017.	Unknown cause.	-
9-Jan-17	Vehicle	230	Vehicle tagged as non operational.	Front cabin air conditioning blowing warm air + rear air conditioning showing "low pressure" message on all digital display panels.	Unknown.	-
9-Jan-17	Vehicle	225	Vehicle booked for inspection	Centre computer failed no emergency lights / sirens / no internal lights in rear/ no air conditioning.	Central computer	-
7-Jan-17	Vehicle	230	-	Rear ac not functioning sufficiently during the day and ? Coolant gas was smelt in vehicle. Low beam needs brightening and won't adjust high enough even when attempted. Rear of vehicle won't lower enough to load stretcher without having to lift it.	-	-
28-Dec-16	Vehicle	185	Filled out fault report form, will inform OIC tomorrow.	Front light out. Little left light,	-	Vehicle is operational, main lights are still working.
28-Dec-16	Vehicle	235	replace solenoid or replace all solenoid latches with mechanical ones	rear door will not open correctly. right rear latch will not release	poor solenoid action	-
28-Dec-16	Vehicle	225	attempted to dislodge and attempted to use switch	Side step into patient care compartment not operational. major trip/fall hazard	no	-
27-Dec-16	Vehicle	240	Contact repairer and officer contacted OIC	No air con	Unknown	-
28-Dec-16	Vehicle	210	-	Front aircon not functioning correctly, intermittently cold however majority of time blows warm air	Unknown	-
27-Dec-16	Vehicle	210	RACQ jump started vehicle and vehicle driven back to station and put on charge for whole day.	Failure to start vehicle by main or aux battery, post sitting at residence while on fatigue.	Flat battery unknown cause, all electrical equipment was turned off, mains, radio and fridge all switched off prior to parking the vehicle.	RACQ states that the main battery was at 11 volts, and that the aux battery was below 5 volts and appeared to only be receiving a small amount of charge.
28-Dec-16	Vehicle	210	-	Blue led flashing emergency light on left side of bonnet mount not working	Unknown	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
28-Dec-16	Other Equipment	230	Remove SIM card, rub on pants and reinstall. - produces intermittent success.	SIM card or phone faulty. Held together with sticky tape. Phone fails to read the card and therefore has no service or contacts.	Unknown.	-
28-Dec-16	Vehicle	240	Replacement of Torch Batteries and Torch Charger Check.	Both torches not working.	The charging holders.	Require torches as we escort residents at night into there dwells a safety issue!!
29-Dec-16	Vehicle	235	Fault report	Drivers side windscreen wiper not make correct contact with windscreen leaving 20cm wide area not being cleared of water in front of drivers face	Unknown	-
28-Dec-16	Vehicle	240	Vehicle is not being used at night	Right headlight not working	-	Vehicle should not be used at night or where lights are required
29-Dec-16	Vehicle	240	-	Vehicle exterior > internal charging cable broken	?driving vehicle and not unplugging charging cable	Vehicle operational but has the risk of incurring a flat battery
29-Dec-16	Vehicle	215	-	Tyre replaced but brake pads require changing and vehicle has no spare tyre	-	-
29-Dec-16	General Equipment	185	We have taken the 02 kit of out 7147 and placed the faulty one in 47 (we have stated this on the whiteboard in the station). The oxygen still works if required, just leaking as well.	02 is leaking from the outlet valve.	-	-
29-Dec-16	Vehicle	240	NA	Key for 505111 was dropped at an incident scene as was run over by multiple other vehicles	Officer dropped key on roadway	The remainder of the key is on the OICs desk. There is still one operational key for the vehicle.
30-Dec-16	Vehicle	245	Tire changed, spare on	flat tire, front passenger side	Concrete	No wrench to remove spare tire
5-Dec-16	Vehicle	225	Windscreen replacement	Star in the lower left windscreen	Stone coming up off a vehicle in front during operating conditions	-
27-Dec-16	General Equipment	240	Contacted Radio Workshops	VOLUME KNOB HAS BEEN COME O	Volume knob has broken.	-
30-Dec-16	Other Equipment	195	Use CH3 in the mean time.	Channel 16 repeater is not working correctly. Vehicle/radios receive messages on CH16 but transmissions back to comms are not happening.	-	Reported to Townsville comms.
29-Dec-16	Vehicle	245	-	Vehicle pulls constantly/vigorously to left. Tracking/wheel alignment needed. Intermittent "clunk" noise from gearbox - this is associated with a judder/sudden loss of momentum, as if the gear box has missed the gear change or fallen out of gear	-	Not on vehicle today so unsure of actual speedo reading
30-Dec-16	Vehicle	240	Left note for OIC also broken part of hand held radio. OIC aware of torches.	Torches not working. Also clip on hand held radio broken (562505P1)	-	-
30-Dec-16	Defibrillator	200	Removed faulty cord and notified SOS	Faulty SpO2 sensor or cable	Unknown	Machine works fine apart from faulty cable
3-Jan-17	Vehicle	215	CDS notified. OIC informed.	Vehicle engine light on, vehicle entered limp mode, engine making unusual sounds.	-	-
4-Jan-17	Vehicle	230	-	Dash warning light for blown lamp, unable to locate the blown lamp. air-suspension to lower rear of truck non-functional. Head lights weak.	-	-
4-Jan-17	Vehicle	230	-	Passenger seatbelt, front: belt jamming, slider for height is jammed.	-	-
4-Jan-17	Vehicle	235	-	Very loose indicator lever	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
4-Jan-17	Vehicle	185	Nil	7289's rear doors working intermittently, unable to open doors from the outside, but able to unlock from the inside	Unknown	-
4-Jan-17	Vehicle	185	-	Side access door intermittently working (green light not flashing), have to press the unlock battle multiple times before it unlocks. Read air suspension still has an air leak sounding noise. Side (drug and O2) door not shutting. Only 1 hand held radio	-	-
4-Jan-17	Vehicle	225	Notify OIC	Side step not extending when side door is opened, master switch is on and side door is fully functional.	Unknown	Fault was recently repaired.
4-Jan-17	Vehicle	185	Fault report	None of the module doors opening (side doors)	Unknown	-
4-Jan-17	Vehicle	230	-	No functioning head lights. Spoke to CDS vehicle to head straight to to fix issue and return to operational status.	-	-
3-Jan-17	Other Equipment	190	No definitive actions.	Adult and paediatric mannequins, are in poor state, holes in lungs, laryngotracheal damage.	General wear and tear.	Train ACPs to use more sophisticated CEU equipment? Replace/repair mannequin for down stairs training room? Advise ACP on proper care of mannequins?
4-Jan-17	Vehicle	240	-	Front left bonnet beacon (blue led) not working	-	-
4-Jan-17	Other Equipment	230	Problem with pager is currently being fixed investigated. Should be fixed today. However, require second pager for unit.	401952 pager not receiving cases or hospital notifications. Also Found by OIC that only 1x pager for vehicle. Crews advised been only 1x pager for unknown period.	-	-
4-Jan-17	Vehicle	200	Notify OIC	Windscreen wipers require changing.	-	-
4-Jan-17	Vehicle	240	Nothing	Rear license plate light not working;	Busted bulb	OIC investigated light. Light now working, does not need to be fixed now. Light still broken. OIC to contact will be attending station today to replace.
4-Jan-17	Vehicle	200	-	Car battery appears to be going flat. Both vehicle radios turn off when car turns off (turns on when car turns on) Interior car lights slow to turn on. Power light comes on when vehicle is being charged. Car has been charged whilst at station.	-	Officer stated Tuesday morning car was having same problem
4-Jan-17	Vehicle	210	-	Mains not working therefore no emergency lights, sirens, ally lights etc. internal lights can be turned on and off from panel in back of vehicle.	-	-
4-Jan-17	Vehicle	195	Nil	Number plate light not working	N/A	-
4-Jan-17	Vehicle	245	has fixed this before. Reported to OIC.	The sensors on the back door need fixing. The alarm keeps going off to say the door is not shut properly and at night time if that occurs the emergency lights flash.	Sensors need fixing.	Thought if we mentioned tonight it might be able to be fixed before shift tomorrow.
4-Jan-17	Vehicle	230	Vehicle towed by	Power steering failure	-	-
5-Jan-17	Vehicle	240	Flat tyre is located on spare wheel bracket. Vehicle still operational, just requires spare to be fixed ASAP	Sustained a flat tyre while in Maryborough, RACQ was called by Comms to change tyre as unable to locate a jack	.? Valve faulty no obvious puncture	-
5-Jan-17	Vehicle	225	-	Front Left Fog light is broken/bulb smashed	Unknown, noticed broken bulb when washing vehicle	-
28-Dec-16	Vehicle	230	Comms and contacted via mobile phone	Vehicle in limp home mode	-	to pick up 4969 from Nambour stn.
28-Dec-16	Vehicle	230	have inspected the step and stated they would need an hour or to fix it.	Side step requires repair	Wear and tear	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
28-Dec-16	Vehicle	250	Not able to extend. Multiple attempts made	Rear chair seat belt does not extend to put on officer or patient	Unknown	-
29-Dec-16	General Equipment	240	-	not logging on or receiving jobs	-	tech worked on mdt but still not working. Vehicle 5367, Caboolture
29-Dec-16	Vehicle	215	-	Seat belt of rear facing seat not working. One torch not working.	-	-
30-Dec-16	Vehicle	225	Taken out of service	Rear AC not blowing cold air	AC US	-
2-Jan-17	Vehicle	225	Nil	Side door will not open lock issue	Lock issue	-
2-Jan-17	Vehicle	195	secondary UHF utilised	Exposed wires on primary UHF radio mic, intermittent radio transmissions to comms	exposed wires to radio mic	radio intermittently operates
2-Jan-17	Vehicle	235	advised job logged, SNI0389038. COMS, FLEET MECH, SOS ALL NOTIFIED.	MDT not working. Radio stuck in maintenance mode with RED screen, unable to transmit or receive.	-	-
1-Jan-17	Vehicle	230	-	Emergency Beacons not working - front roof beacon lighting bar + under windscreen + front bull bar	Possible long duration usage at QFES standby Gympie area (3 hours+) - was definitely working during that period - can be confirmed by CSO on-scene	CDS/OS notified immediately- fault report form completed as soon as practically possible
2-Jan-17	Vehicle	245	CDS contacted and discussed fault	During heavy storm weather damage occurred to 601444. Which when 'mains' is turned on, the internal lights continually and spontaneously switch on and off repeatedly every second.	Storm damage	-
3-Jan-17	Defibrillator	240	Onsite Service Call, Replaced Printer and checked if operational. Defib placed back in service	Printer door won't close properly therefore printing cannot occur	Dropped by crew member	-
3-Jan-17	Vehicle	240	notified and job logged.	MDT is turning off when vehicle is not running or plugged in. MDT restarts after vehicle is started.	N/A	-
2-Jan-17	Vehicle	185	On fatigue changed into 7106	Slow air leak drivers side front tyre of 7305	Something small in tyre	Slow leak , good to dangerous within 48 hrs. from said he can sort it when you give the ok and I can get it there
3-Jan-17	Vehicle	240	workshops	rht headlight blown	-	Vehicle taken to and headlight replaced
4-Jan-17	Vehicle	230	RACQ changed tire	Flat tyre	Roof screw	Spare tyre needs fixing
7-Jan-17	Vehicle	230	MDT master switch turned off and on again - nil change.	MDT Screen Frozen.	-	-
8-Jan-17	Vehicle	240	-	Upon starting vehicle "ESP fault, return to workshop" flashing on display. After reinserting key to restart big red ! And "brake distribution fault" on screen.	Unknown cause	Vehicle appears to handle normally still.
8-Jan-17	Defibrillator	230	n/a unable to locate new lead	DEFECTIVE OXI CABLE, Red indicating light last no more than 10 seconds then turns off	-	had a similar problem last night when i back up a kawana crew advised crew to complete a defect form
7-Jan-17	Vehicle	195	Inspected by an auto electrician	The air conditioning unit on the roof of the rear module was making loud crackling noises and squirting water & ?smoke from the roof of the vehicle. However, the air conditioning module is still working and delivering cold air into the rear module.	Unknown. The vehicle has done 2 x patient transfers between Ingham and Townsville in the last 2 days during very heavy rainfall.	Air conditioner still working, however also still making crackling noises.
9-Jan-17	Vehicle	210	Notify mechanic	Rear doors not locking when use remote to lock doors ?electrical error fault also next service due 181067km	Found on check	-
9-Jan-17	Vehicle	210	-	Stair chair sliding mechanism broken/unstable. Can still access stair chair, however not locking in.	Unknown	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
27-Dec-16	Vehicle	195	SOS contacted. Officers re-attempted locking and unlocking of vehicle (keylock) and were successful.	At TTH, both officers attempted to unlock the vehicle without success (keylock). Key then used successfully to open the vehicle but then vehicle would not lock again using the keylock once the doors were shut.	-	Oic replaced key
28-Dec-16	Vehicle	230	Nil referred to	Side step on passenger side will not open fully	Vehicle reversed into culvert during wet weather in early hours - culvert edge not seen by officers - didn't know step damaged till later	-
29-Dec-16	Vehicle	250	-	Rear fridge not working and cooling. Fixed rear split that the corpulse cabinet attaches to that was fixed with silicon is splitting again.	-	-
22-Dec-16	Vehicle	235	Mechanic notified	Engine stays on	-	-
29-Dec-16	Vehicle	240	-	Unit sluggish on take off (loss of power as described in last report). The issue is not as developed as last time however if like last time it will get worse.	-	-
30-Dec-16	Vehicle	215	Taken off road	Significant lean to drivers side. Found when checking car for shift, not used.	-	-
30-Dec-16	Vehicle	215	-	Seat behind drivers seat (airway seat) seatbelt not working	-	-
30-Dec-16	Vehicle	230	Towed to nam brakes	Battery light came on dashboard. Rear air con stopped. Vehicle stopped and unable to restart.	-	Speedo unknown
31-Dec-16	Defibrillator	195	Taken out of service until problem has been rectified.	Debfibrillator electrodes are loose and not connecting. Would not connect to unit and we tried different defib pads to ensure that it just wasn't the insitu pads	Guessing the amount of times that we push in and pull out the defibrillator pads on the corpuls	Repaired 6 Jan 2017
31-Dec-16	Vehicle	185	A second fuse was used to no effect.	Emergency lights have a short in them, fuse has blown & replacement fuse has blown as well.	Short in wiring	Vehicle taken off line due to short in wiring & a burnt smell being present at the time.
31-Dec-16	General Equipment	240	Connections checked, leads checked for breakages. Paed Pt care lead swapped and checked - all failed. OIC on RDO, unable to obtain replacement. Lead swapped with working lead on Bribie Island Corpuls #1 located in OIC vehicle.	Oximeter passed user test at commencement of shift, several intermittent failures on multiple cases - main cable fault.	Unkown	Oximeter cable damaged and swapped with new cable - now working. A/OIC
31-Dec-16	Vehicle	240	SOS/ROC notified and RACQ notified	Accidental refuel with unleaded petrol	-	-
31-Dec-16	Other Equipment	230	Now on OIC desk	Pager U/S coming up with error message: EEPROM no init ! or EEPROM error !	as above	-
1-Jan-17	Defibrillator	235	corpuls taken off road and new corpuls taken from 6602 to replace for the remainder of shift	Spo2 probe broken and not functioning	unknown	-
1-Jan-17	Vehicle	240	None from the crew. Relevant supervisors informed	Reclining head section of the power stretcher will not lay flat. Currently stuck a and incline of approx 20 degrees. Oil leaking from the hydraulic ram which controls the head end of the stretcher	Unknown	has loaned Redcliffe ambulance station unit 5229 a powered stretcher. will be swapped back once stretcher has been fixed.
31-Dec-16	Vehicle	250	Placed OOS CDS/ SOS painting informed	Rear door will not unlock from outside, side step does not fully deploy, drivers seatbelt reel faulty	As found	Vehicle is in Poor condition in general some obvious (old?) damage to RR hand corner above R bumper may effect R door operation

RTI RELEASE

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
1-Jan-17	Vehicle	230	Fault form filled in	Rear air conditioning not working ie; hot air is coming out. Makes it a very hot working space especially during hot days	Not known	-
1-Jan-17	Vehicle	220	Needs to be reviewed by a mechanic. Nil actions taken at this point due to public holidays	Nil airbag suspension for the rear axle. Airbags are unable to be pumped up.	Unknown	-
1-Jan-17	Vehicle	230	informed Duty OIC	Not for code 1 driving. Siren Not working.	-	-
1-Jan-17	Vehicle	245	All fluids checked, nil leaks/low level found. Unable to clear fault. Vehicle out of service.	Check engine light illuminated.	-	-
1-Jan-17	Other Equipment	230	Vehicle currently only being used if nothing else left	Pager not receiving pages, only one pager for this vehicle	Pager u/s and also requires a 2nd pager for this vehicle	-
26-Dec-16	Other Equipment	215	Nil, door is still supported by top right hinge.	Bottom right oxygen tank enclosure door, pin that holds hinge together has broken	Wear and tear	-
26-Dec-16	Vehicle	205	N/A	Damage to driver door panel.	Kangaroo strike.	-
28-Dec-16	Vehicle	195	-	Side Step not operational	-	-
29-Dec-16	Vehicle	235	-	MDT keeps blinking on and off, unable to log on, have used the kill switch but still not working	-	-
29-Dec-16	Vehicle	240	Towed to mechanic	Vehicle would not start	-	-
29-Dec-16	Vehicle	185	Informed SOS, have kept car on idle hole	Car battery ...? Faulty. Had to use emergency start twice during the shift. The car has always been on charge back at station and the plug was definitely on.	-	-
1-Jan-17	Defibrillator	225	confirmed pulse oximeter plugged in, and cable without defect	pulse oximeter fault, with it NOT reading NOR working intermittently, and becoming more frequent; with messages: "Defective Oxi cable" or "Oxi cable loose" or "Oxi sensor loose" or "Oxi: Interference" show up in Alarms and/or Code Summary	unknown	defibrillator currently in vehicle 4603
1-Jan-17	Vehicle	230	nil	Front Beacons not working	Unknown- car has been sitting at station with note not to use for past two days. Unknown when or where fault occurred	-
3-Jan-17	Vehicle	250	Attempted to clean tracks and slide step back in.	Side step intermittently getting 'stuck' in the outward position. Directed to take vehicle out of service by CDS and SOS.	Not known	-
4-Jan-17	Vehicle	250	-	MDT and all charging points not working, including defibrillator.	-	-
5-Jan-17	Other Equipment	230	Attempt to locate pager, OIC emailed, CDS notified, fault form completed.	Missing pager unable to locate in station	-	All ready reported and new pagers ordered waiting there arrival
4-Jan-17	Vehicle	240	Notified OIC	Back latch on boot will not open back. Cannot gain access or open back.	Unknown - seems locking mechanism not working	-
5-Jan-17	Vehicle	185	as above recycled numerous times - fan doesnt engage therefore no cooling in rear module	rear A/C fan not working / or intermittent and suction not working in rear module	unknown, initially worked then despite "recycling" a/c through settings to auto position did not work	its too hot and humid to work in a vehicle with no aircon and uncomfortable for patients. AUTHORITY V 5112.
5-Jan-17	Vehicle	225	Booked into on 09.01.17 for service	One month past service due date	- advised	-
4-Jan-17	Vehicle	240	attempted to tighten remaining screws, they keep working loose	reversing camera not working, stone chip in windscreen, screws from filter cover in patient care compartment loose and/or missing - filter cover not secure	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
5-Jan-17	Vehicle	240	Turning Master MDT switch on and off several times. Spare put on by RACQ. Tyre repaired by	MDT Failure	-	-
4-Jan-17	Vehicle	240		Flat left rear tyre	Nail in tread	-
5-Jan-17	Vehicle	250		Side step not extending or retracting.	Unknown	Replace side step.
5-Jan-17	Vehicle	225	OIC phoned>>> RACQ and MOC CCS phoned>>> RACQ arrived 30 minutes later, assessed battery life (states in fine health) but states that there is a leak causing the battery to die. Vehicle jumpstarted with nil issue and returned back to station.	Battery died during on call prior to shift commencement.	Potentially the cover over the plug to charge the car battery is not engaging properly causing the battery to loose charge over long periods of time.	Mechanic stated that vehicle should go to an auto-electrician to find exactly where power loss is occurring despite having all main power supply turned off during the evening.
27-Dec-16	Vehicle	180	RACQ	Vehicle not starting while at officer Residence on call / fatigue. once changed electronics in rear of vehicle eg fridge operation, emergency lights, rear compartment lights etc not working (29th).	flat battery and loose wiring.	Vehicle taken to on thursday 29th of dec 2016 and loose wiring found. both batteries assessed and found to be suitable. recommended that vehicles be placed on charge when at residences.
5-Jan-17	Defibrillator	225	#NAME?	#NAME?	-	- defibrillator swapped with one in 3366 for the shift
1-Nov-16	Vehicle	195	Booked into	Rear a/c not working error code LP	-	-
1-Nov-16	Vehicle	230	Wheel housings x 4 visually inspected & flushed with high pressure water; squeak continues. No action taken regarding radio speaker. No action taken regarding cigarette lighter socket.	Primary concern is the wheel assembly noise suspecting something is caught up in same; high risk of further damage. GWN radio speaker audio quality is not clear & sounds very poor. No power from cigarette lighter preventing in-car Toughbook charging.	Unknown causes of all reported faults.	-
31-Oct-16	Vehicle	240	CONTACT REPAIRER	KNOCKING NOISE ON ACCELERATION	-	-
1-Nov-16	Vehicle	235	-	Back left barn door has broken door handle	Unknown sector spare was broken when picked up by Laidley crew	-
2-Nov-16	Vehicle	215	SOS and OIC notified, vehicle taken 'off road' and returned to Bundaberg station	D size cylinder leak in wire connecting to rear oxygen port of vehicle	unknown	-
2-Nov-16	Vehicle	210	Reported	Rear Right hand door stay broke at bend in steel.	Pressure on door when door stay engaged	Vehicle still operational
3-Nov-16	Vehicle	245	-	Engine Light flashing: Nil acceleration of vehicle above 1500rpm	Unknown. Ongoing issue with vehicle it was already peeling off, but the Spitwater pressure washer broke off a piece	CDS and SECOMM Notified at time of event. Vehicle removed from service.
4-Nov-16	Vehicle	235	-	QAS decal on rear window is peeling off	-	Decal needs to be replaced please
4-Nov-16	Defibrillator	250	Replaced with new cable	Exposed wires of spo2 cable - patient cable not sensor cable	-	Defibrillator operational with new cord, old cord not operational

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
4-Nov-16	General Equipment	245	Have taken vehicle to mechanics several times to have antenna locked in place. Believe Qas techs have looked at it several times too	OLD MDT - Vehicle tracking issues, doesn't get coverage in some areas especially around Parkinson, Calamvale and Algester. Also other areas around Brisbane	Unknown cause ?antenna problem. Old MDT	-
4-Nov-16	Vehicle	195	Repaired	Air conditioning unit in rear of module is falling down on right side - currently held on with tape.	No screws left in unit.	-
4-Nov-16	Vehicle	225	SOS notified	Water/ dirt droplets in reverse camera obstructing vision	-	-
4-Nov-16	Vehicle	250	A new charger is required to charge the car, or RACQ required to jump start the vehicle.	No Power.	No Power, as the vehicle has not been charged or driven for at least a week	currently unoperational, but with charging can be operational soon.
5-Nov-16	Vehicle	235	Vehicle off-road.	Alarm constantly activates to check coolant levels / coolant low. Coolant levels are at 'max' when checked. No leaks apparent.	-	Parked in Redbank Station
6-Nov-16	Vehicle	225	Did attempt to reset the battery which worked for about 30 mins prior to breaking again	No aircon in rear. Blows hot air. Unsafe for staff in back due to stifling heat	rear evaporator switch continues to turn off. This is a known problem for which many fault forms have been filled out with nil action taken.	-
6-Nov-16	Vehicle	240	Mains turned off and on, all cable connection checked.	MDT stopped working towards the end of shift, unable to receive any data.. black screen of death with a line through the middle. Turned MDT mains off on back on, all Comms communication was made via radio.	It occurred when the screen was turned and appeared to be cable related... all connection were checked, unable to resolve fault.	A/OIC , reset MDT this morning and now working.
7-Nov-16	Vehicle	230	-	Reversing camera not working	-	-
8-Nov-16	Vehicle	210	Defect form. I'm not an autoelectrician	Reversing camera not working	A faulty reversing camera ?	I didn't not break it, it was like that when I got it.
8-Nov-16	Vehicle	235	MDT has been reset via master switch with nil effect	MDT not working	Unknown	Vehicle still in use. Contact/updates via radio
8-Nov-16	Vehicle	250	OIC has spoken to fleet tec and and vehicle camera is now	Revere camera not functional	Poor quality of camera	vehicle was temporarily at Helensvale. OIC is unsure whether fault has been rectified.
8-Nov-16	Vehicle	230	OIC notified	Phone will no charge in vehicle or in station 4773	?	-
1-Nov-16	Vehicle	210	-	Bottom drawer slide broken	Rivets have snapped	-
29-Dec-16	Vehicle	235	Antenna left in mechanics lodge on hole	Found antenna from front port on wind screen wiper unsure how it was broken	Unknown	-
1-Nov-16	Stretcher	230	removed from service. Swapped with alternate stretcher from ramp. Fault form completed. UNIT 902 rego 540 TLQ	Leg elevation U/S - no harm to pt. NO STR COLLAPSE	unknown. Knee section unable to be raised and locked into a knee flexed position. Reported by Noosa ACP pay number	Placed at ramp and signed as such.
29-Dec-16	Vehicle	210	Mirror has been repositioned & secured until replacement becomes available.	Passenger side mirror damaged by fenced narrow driveway entry. Small mirror on bottom broken, plastic casing for indicator light broken/missing & hinge damaged. Indicator light, blind spot sensor & adjustment mechanism for big mirror still functional.	Operator error when reversing vehicle into position. Mirror just clipping the top of the fence post.	-
30-Dec-16	Vehicle	225	-	Door lock pins broken missing	-	-
31-Dec-16	Vehicle	185	-	Fan belt broken - loss of power steering	-	Vehicle parked at Smithfield Station

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
31-Dec-16	Vehicle	230	Switched the main MDT switch on and off. Nil success.	MDT not working. Locked on Black screen with only Duress button illuminated.	Unknown.	This is the 3rd issue with the MDT within 4 weeks. Same issues being experienced with MDT freezing and blue screen when reversing.
1-Jan-17	Vehicle	245	Notified ROC who advised to return vehicle to station provided nil further issues occurred. Successfully returned to station, placed out of service. Warning lamps persist as soon as engine started.	LOW WATER and HIGH TEMP warning alarm and lights on switch panel - COOLANT WARNING lamp on dash. Coolant reservoir appears to be full.	Unknown cause - nil leaks noted from vehicle, coolant reservoir appears full, nil other warnings on dash. Possible faulty sensor/false alarm?	Vehicle had been at station for a few hours prior to event - had nil further issues earlier in the day.
1-Jan-17	Vehicle	250	-	Side step not working	-	Just stopped working
1-Jan-17	Vehicle	230	-	Back aircon not working	-	On auto a/c turns off
31-Dec-16	Vehicle	240	supervisors notified - nil other action taken	Vehicle overheating w/ coolant leak obvious	unknown	the vehicle was not fitted with any operational equipment ---- ALSO speedo was not recorded, but was above 160000kms
2-Jan-17	Vehicle	210	Have tried troubleshooting the problem with no success	Rear air conditioner unit not working effectively, has the letters LP flashing whilst trying to cool down	Unknown	Using fans and full blasting air con from the front assists in cooling vehicle
2-Jan-17	Vehicle	185	Taken off road.	Faulty alternator. O2 kit leaking from external connector. Replacement torch required.	General wear and tear.	-
2-Jan-17	Vehicle	230	Told OIC	Only one pager and it doesn't receive pages. MDT turns off when car turned off.	?Car not plugged in after use	Previously submitted fault form by OIC
2-Jan-17	Vehicle	245	-	Smart Bar indent	Rear end RTC - see claims form and/or she report for more details	-
2-Jan-17	Vehicle	240	Got in contact with OIC and completed form	Dint/scrape on Right side roller Drivers side rear door clip not clipping door open	Pole in narrow driveway	-
2-Jan-17	Vehicle	215	-	Pulls hard to the left. Clucking sound/feeling when turning left	-	-
3-Jan-17	Vehicle	210	Nil unable to stop water.	Whilst on shift experienced rain. Water was leaking into the vehicle from the side windows. Appears water is entering from the rear drivers side lower seal, rear passenger side leaking from top seal.	Unknown	Vehicle can be considered operational if weather forecasts suggests no rain.
3-Jan-17	Vehicle	240	Vehicle taken to for investigation	Yellow engine light flashing in dash	Unknown	Until fault assessed vehicle not operational
3-Jan-17	Vehicle	240	Sent to mechanics for assessment of fault	Engine light flashing, vehicle has difficulty accelerating up hills	-	Fixed today at If not tape the door falls open when driving causing a loud bang. May cause babies to be prematurely delivered or incontinence of patients.
3-Jan-17	Vehicle	185	Duct tape - Orange in colour	Broken hinge for internal rubbish bin/sharps container drawer door.	General wear	V 5113
1-Nov-16	Vehicle	210	Fault form	No emergency lights	Unknown, broken switch	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
2-Nov-16	Vehicle	245	We have attempted to turn MDT off and on again (via the reset switch) and have attempted to log crew off and on again (with assistance from Op Centre). Nil changes to fault.	MDT touch screen ceased working. MDT appears to update with status changes (when change is carried out by Op Centre), however unable to press any status/clearing/notification buttons on MDT.	unknown. Fault was noticed when attempting to press "on Scene" on a case.	Vehicle is not operational due to MDT being completely unusable, and remaining on the screen that appears when a job is cleared, with constant beeping.
2-Nov-16	Vehicle	205	Nil at his time, fault report generated and reported to BSM Central West.	Rear tyres are low on tread, require replacing	-	-
16-Nov-16	Vehicle	200	Checked connection of powerpoint, ? loose and therefore not charge, have disconnected and reconnected powerpoint and will check again shortly to see if it will unlock.	Back compartment unable to be unlocked. ? battery problem. Car has been plugged into charge.	-	-
16-Nov-16	Vehicle	245	Might need a technician to review	Stretcher malfunction on preshift check, loading mechanism stuck half way out vehicle, attempted troubleshooting to no success, vehicle put out of service.	Unknown	-
16-Nov-16	Vehicle	230	Air conditioning unit reset & reviewed by earlier in day however, fault returned.	Air conditioning in rear of unit not working.	?	Air unit working intermittently & not reliable.
17-Nov-16	Vehicle	200	Fault report completed, SOS notified	Engine warning light, and vehicle acceleration is reduced. Gearbox gear changing seems more "jerky".... engine is overall less responsive	Happened while driving normally.	-
16-Nov-16	Vehicle	250	Fault form completed. Station OIC to be notified when he is at station next, and the mechanic as appropriate.	Side step not functioning.	Driving down a driveway of a property. Whilst entering the driveway the step has made contact with the edge of the driveway. On arrival back to station it was noted the step was no longer functioning.	The vehicle is still fully operational however the step is just not working.
17-Nov-16	Vehicle	185	-	Vehicle 7162. Air con in rear does not stay cool while vehicle is stationary and gets very warm. Once vehicle is moving air con cools down again.	-	-
18-Nov-16	Vehicle	210	Emergency start needed to start vehicle, OCS notified	Not starting normally, ?battery, "emergency start" needed	Unsure, unit had been connected to power source while at station, came back from service yesterday.	Had been on charge all day and most of night before fault occurred
21-Nov-16	Vehicle	200	-	Cracked windscreen	Low flying bird struck windscreen on highway	-
24-Nov-16	Vehicle	240	Notified OIC, vehicle placed out of service.	Clunking noise heard in front when turning wheels and driving slowly, can be felt through steering wheel. Screeching sound heard when braking.	Repaired by mechanic	-

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
24-Nov-16	Vehicle	200	Notify SOS... defect report... mechanic on leave till next week.	1) Pt care compartment doors lock and are difficult to unlock.. side door: locks each time it's closed.. need to re-lock, then unlock x2 to unlock.. Rear door: cannot remotely unlock... requires opening from inside compartment each time; 2) see below	2) airbag suspension non functional if not lowered within a minute or so of turning off ignition.; the above door fault is long standing and has not yet been able to be corrected.... I believe fix has previously been attempted?	If crew not familiar with how to problem solve fault... there is a potential that pt's can be locked inside the pt care compartment, unable to be retrieved.
31-Oct-16	Vehicle	195	taken directly to RACQ	front headlight U/S	n/a	Fixed same day
25-Nov-16	Vehicle	215	Batteries done yesterday and used VHF radio due to very good reception but last night VHF was poor and then unable to turn UHF on and then VHF finally became better with reception.	VFH radio - keeps cutting in and out and UHF radio will not turn on and only beeps every 10 seconds - we took vehicle to for load test and possible replace and they replaced both batteries and rest of day used VHF radio only good receipt	Unknown	-
25-Nov-16	Vehicle	205	Put on charge on Wednesday midday. retested today - no power.	No battery power	-	-
5-Nov-16	Vehicle	240	vehicle turned off and then turned on - engine light still remains on - vehicle manual states vehicle not operational.	Engine light came on during short Code 1 - first case of shift. All checks done and vehicle check list completed prior to case.	Unknown	Vehicle taken out of service at completion of case - given another case prior to returning to station approx 20 extra km driven at 50kph
7-Nov-16	Vehicle	210	-	Radio bracket on dash is broken and disconnected	Unknown what caused the fault	-
7-Nov-16	General Equipment	250	-	Sat nav in 6598 freezes on screen. Unable to input data or update address.	-	-
7-Nov-16	Vehicle	225	NA	Cracked windscreen	Rock from oncoming truck	-
8-Nov-16	Stair Chair	195	Submit form	Unable to open stair chair	Unknown	New model of stair - different locking system in comparison to previous model. Nil injury or incident occurred.
8-Nov-16	Other Equipment	210	-	The male connection that connects the charging cable to the charging socket for the Corpuls located in the side storage area of the ambulance was found disconnected and upon closer inspection the male connection is broken and needs replacing.	What must have occurred is that the cord has become caught and when the bracket & Corpuls were pulled out of vehicle, pressure was applied to the male connection causing damage	-
9-Nov-16	Vehicle	195	Changed vehicles, marked out of order, called OCS	Engine light came on while driving	-	-
10-Nov-16	Vehicle	260	Notified OIC	#NAME?	-	-
9-Nov-16	Vehicle	240	Vehicle ignition was turned off and back on again and vehicle was good. This happened 3 - 4 times during shift.	Vehicle has gone into L1mp mode numerous times during shift.	Unknown	-
10-Nov-16	Vehicle	225	? Fault Report submitted	- as per on-the-fly handover advice, 08/11/16, this unit's A/C N/W	#NAME?	Vehicle operational until rear AC repaired booked for Nov 24
10-Nov-16	General Equipment	240	notified OIC	mdt has dislodged from bracket	poorly secured to bracket. Bracket has been overly tightened inhibiting rotation.	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
10-Nov-16	Vehicle	230	Crews asked to attend to have this assessed, crews making attempts to do this, Comms stopping crews due to coverage.	Side step doesn't work 4771	Unknown	-
11-Nov-16	Vehicle	225	-	#NAME?	-	-
12-Nov-16	Stretcher	215	Off road. SOS notified. COMMS notified	Unloading stretcher from vehicle. Green button and lever became jammed. Stretcher rolled out of vehicle and collapsed to the ground. No patient on board. Nil injuries to any crew or patient.	-	-
12-Nov-16	Vehicle	225	-	- as above, with rear A/C N/W	-	Vehicle operational until rear AC repaired booked for Nov 24
12-Nov-16	General Equipment	240	Not able to	MDT not working, keeps flashing on and off. Started doing this at lunch time.	Possibly wiring?	Have alerted Comms that this has happened been keeping them updated via radio.
12-Nov-16	Vehicle	225	-	Side patient access door opens every time vehicle has been locked and is then unlocked	vehicle outside during thunderstorm and fault appeared after that event.	-
12-Nov-16	Vehicle	230	Vehicle placed out of service	Main switch electrical fault	N/k	-
13-Nov-16	Vehicle	240	OCS contact d	Check engine light on	-	Extra faults - fridge not working Broken slider for bins - SHARP hazard
14-Nov-16	Vehicle	215	Gone to for servicing.	Rear door latch dodgy. Multiple presses to release catch. Rear suspension compressor making grinding noises. Batteries need load testing.	-	-
14-Nov-16	Vehicle	210	HAS GOT OFFICER CARRYING OUT SOME TEST TO TRY AND FIND WEATHER IT BE DOOR OR TYRE ALARM.	Alarm sounded intermittently whilst driving.	STRETCHER LOAD RAMP BEING HELD BACK BY STRETCHER WHEEL. WHEEL WAS IN WRONG POSITION.	-
11-Nov-16	Vehicle	215	Replace second battery	Second battery - losing charge, vehicle losing power support in back after approx 3mins, Starting battery for vehicle ok	faulty battery - faulty charging system	-
11-Nov-16	Vehicle	215	-	Noticed Vehicle over last 4 shifts - have a "surge or miss" at low speed periodically. The car feels to "pull back" briefly,	? Fuel injector issue/	-
11-Nov-16	Vehicle	215	None	Seat belt in seat behind driver rear compartment not working , not retracting , cant pull out or use	unknown	Found doing vehicle check re submitting still not fixed restricts usage of that seat when escorts req etc
12-Nov-16	Vehicle	215	vehicle labelled as unoperational at station, comms notified, this form submitted	On arrival at bundaberg station, lights controlled by mains switchboard where flickering uncontrollably whether switches where in on or off position. Lasted approximately 1 minute before self resolving. Reoccurred several times, nil interventions.	? rain after driving through heavy storm	note: windscreen chip
13-Nov-16	Other Equipment	195	Taken out of service	Power cable damaged	Cable caught in driver side door when closed	-
13-Nov-16	Vehicle	230	resetting the MDT	MDT keeps turning off- has required multiple resets	-	-
13-Nov-16	Vehicle	230	Nothing	Orange engine fault light, whilst on hot run to RTC; left unit running whilst on job and had not self extinguished. Still on following ignition off, wait, then back on. No limp mode entered, travelled well. ??? re preglow plug light activation.	???	-
13-Nov-16	Vehicle	230	Mains switch turned off and vehicle unplugged. CDS notified about issue	Switch board located at front of vehicle in centre console, all lights flickering. When mains switch turned on, noise can be heard coming from centre console.	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
14-Nov-16	Vehicle	225	Contact BSU for replacement battery or phone Had and head of workshop inspect vehicle and they seem to think it is an issue with the engine immobiliser. Unable to rectify the fault.	Mobile phone not charging	Battery fault	Phone began to function as normal following a clean of the terminals at station. Monitoring phone function and a spare phone has been received should it need to be replaced. Vehicle was used for a case at 3am no issues at all. It did not start after it was plugged back in. All dash lights come on and vehicle had been working fine previously.
12-Nov-16	Vehicle	245		Doesn't start.	Unsure.	
14-Nov-16	Vehicle	250	OIC notified	Faulty step to side access to rear cabin	-	-
14-Nov-16	Vehicle	240	-	Missing O2 nozzle - OIC aware and sourcing from other stations Part of roof has come loose requires screw to put back in place	-	-
14-Nov-16	Vehicle	215	Reported once identified.	Rear air conditioning not working effectively and cooling rear of vehicle. System is blowing air but not at the desired temperature setting.	Unknown	Apparently aircon was playing up towards the end of last week but not reported. Showing an inside temp of 18 degrees on the display panel and outside temp of 45 degrees.
17-Nov-16	Vehicle	240	The panel was clipped back together and it works fine...however there is a small metal plate that has come away from the inside.	Fault is with the MDT. The front face came off and a small metal plate fell out...the face was able to be clipped back in place and secure and the MDT functions....the plate is not back in place however.	When officer turned the screen the front panel seperated from the back panel (clipped together).	-
17-Nov-16	Vehicle	215	reported , vehicle out of service	diesel leaking from under bonnet	unknown	-
17-Nov-16	Vehicle	200	Notify OIC, Notify SOS	Side door has come off it's railing system, and is unable to be safely closed	Door has slipped from internal fitting track.... rubber tracking loose	Vehicle repaired 17.11.16
17-Nov-16	Vehicle	235	Notification to mechanic	Battery not turning over. You need to start car with emergency start button. Left front wheel query a bearing or a shock is gone. The wheel is making an unusual noise. MDT navigation system only works sometimes.	-	-
18-Nov-16	Vehicle	205	-	SRS light on dash / ? Overdue for routine service	Dash light has been reported and on for months and not repaired	-
17-Nov-16	Vehicle	250	Took to the mechanic at Southport who replaced bracket/hinge	Back door bracket/hinge broken so unable to keep door open	Broken nrocket/hinge	-
18-Nov-16	Vehicle	245	-	Nil MDT, nil sirens	-	-
1-Nov-16	Defibrillator	240	Switched to manual mode DCCS delivered SOS and OIC notified.	In SAED mode monitor failed to identify course VF. Delayed defibrillation	Unknown - pad placement was appropriate.	Have kept copies of a 30 second print out and summary.
3-Nov-16	Vehicle	210	Tyre inflated, and vehicle booked in for tyre repair.	Tyre deflated rear passenger side. Bottom fog lights cracked and not working.	Found during vehicle checklist at commencement of shift.	-
29-Oct-16	Vehicle	215	readjustment of hand	Handbrake of 4345 needs to applied firmly	readjustment needed - QFES driver - mechanic by trade	Spoken to - this prior to submitting a Fault form
3-Nov-16	Vehicle	225	-	Electrical Fault - rear module will not unlock unless vehicle is going. Leak in windscreen washer bottle - water drains in a short space of time. Diesel / oil smell when first driving for short period of time then odour disappears	-	Reported to OIC
4-Nov-16	Vehicle	250	-	Vehicle pulling to the left while driving requires a wheel alignment.	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
5-Nov-16	Vehicle	210	Tape.	Plastic lining on bottom of rear door falling off. 1 screw missing, 2 screw holes cannot hold screws.	-	-
5-Nov-16	Vehicle	240	Reported to OC and fault report completed	Screw in right rear tyre - slow puncture	The screw	-
7-Nov-16	Stretcher	215	Nil	Loose control knob	-	-
7-Nov-16	Vehicle	210	All buttons pressed to try and restore the reverse camera but blue screen remains	Blue screen on reversing camera. No picture displayed	Unknown	-
8-Nov-16	Vehicle	210	-	Cannulation cabinet swinging around freely. Seat belt Press button (rear facing) cracked.	-	-
7-Dec-16	Vehicle	230	Nothing as yet as car is being serviced tomorrow 8/12/16	Rear touch panel, eg lights not working, have to operate from front drivers touch panel	-	-
1-Dec-16	Vehicle	230	On vehicle report form last week.	Reverse camera not working. When car in reverse blue screen comes on.	-	Vehicle went in for service but came back still the same. Unsure if camera has been looked at.
9-Dec-16	Vehicle	215	-	Side step broken	?hit gutter?	-
9-Dec-16	Vehicle	225	Attempted to clean step however the step is an enclosed mechanism- unable to clean inside	Vehicle side step- is working but has minimal movement	unknown	Able to manually pull out and push back in.
9-Dec-16	Vehicle	185	and vehicle service	Vehicle Airconditioning is barely cold. Problem with break - requiring full compression of break pedal to slow vehicle ?air in break	-	OIC aware of issue
10-Dec-16	Vehicle	250	None	Siren non operational...was working commencement of shift failed during code 1 response to case	Unknown	-
10-Dec-16	Vehicle	215	Cables checked	VHF radio microphone in front is not working, appears to have no power to it.	Unknown	-
10-Dec-16	Vehicle	225	Using manual override switch on emergency panel to link batteries together and force charge	..? Auxiliary battery flat due to on call / fatigue break causing radios to stop working.	Long time without charging on call	-
10-Dec-16	Vehicle	225	-	Reverse camera not working properly. Unable to see anything on the screen whilst reversing.	Unknown.	Vehicle is operational but camera needs to be fixed.
11-Dec-16	Vehicle	235	Nil	Auxiliary battery going flat, accessory devices including interior lighting then not usable unless engine on.	Unknown, ? Faulty battery	-
10-Dec-16	Vehicle	225	VEHCILE IS PARKED AT WANDOAN GARAGE TO BE ACCESSED TOMORROW BY MECHANIC	ABS WARNING AND ANTI SKID LIGHTS ON DASH ?BRAKES NEED CHECKING	?	WILL CALL TOMORROW WITH GARAGE RESULTS
7-Nov-16	Vehicle	210	temporary fix with zippy tie no working well	Drivers side windscreen washer broken	no	-
7-Nov-16	Vehicle	225	car taken off road	Electrics - Siren stopped working, lights flickering, aircon not working, radio not working	unknown	System checked, all clear, crews need to ensure they are turning off all electric as required.
8-Nov-16	Vehicle	225	fault form, notify OIC	Left headlight not working	unknown	-
27-Nov-16	Vehicle	245	SOS at LCH attempted to fix using spare parts in his vehicle but was unable to do so.	Rear emergency beacons missing screws - bouncing around when travelling at highway speed. Right headlight out and side step also not working intermittently.	Unknown, noticed when travelling on motorway. Headlight noted by warning on dash and side step did not work on scene at second job.	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
27-Nov-16	Vehicle	195	SHE report completed, SOS made aware.	While exiting the driveway of patients unit complex type residence (driving in a forward direction), the electric gate closed on left side rear of ambulance. Damage noted to black rubber stopper on left side of vehicle and minor detail damage approx 30cm	Electric gate closed while ambulance vehicle exiting gate. ?nil sensor on gate	-
27-Nov-16	Defibrillator	250	OIC infomred, cord replaced	pulse oximete core fault	unknown	new cord working
27-Nov-16	Defibrillator	235	we have tried to realign print paper, wiggle leads incase not connected properly, turned on and off to reset	printer failed to work and wouldnt print anything apart from top line	? cause	cooms made aware of need to change corpul and requirement for fort report, SOS also made awre as needed some assitance in locating a different machine
28-Nov-16	Vehicle	230	-	Side step not working and is sticking out even with side door shut	-	-
28-Nov-16	Vehicle	245	Notified Afcom and vehicle checklist electronically.	As per above.	As per above.	-
28-Nov-16	Vehicle	195	-	Rear driver side light out	-	-
30-Nov-16	Defibrillator	240	tried swapping the probe end for a different one - no change. Will try to get a replacement trunk cable (the cable end that plugs into the monitor) from Spring hill station	Spo2 not working. Gives error message "oxi cable defective" on screen. Red light still emits from probe. Does not give SPO2 or pulse rate reading.	unknown	Roma st station has no replacement trunk cables and no spare defibrillators in case of malfunction. This faulty defib was in 5126 *update = managed to get a replacement cable from spring hill station. Spo2 now works. Will leave faulty cord at ROMA S
30-Nov-16	Vehicle	185	Fault form only to record incident.	Bullseye crack approx 20mm in top left corner of front windscreen.	Passing truck flicked up a small rock.	Travelling from Innisfail to Tully to cover shift. A/OIC informs me that chip is extremely minimal . No further action required on this matter.
30-Nov-16	Vehicle	215	-	Small chip on L side of windscreen	No idea - just saw it when we logged on today	-
30-Nov-16	Vehicle	195	-	Mercedes badge missing from the rear doors on start of shift. Sliding left side door latch not holding door open	-	-
30-Nov-16	Defibrillator	240	Been replaced with spare at station and OIC notified	Defective oxi-cable	-	-
30-Nov-16	General Equipment	250	The machine has been reset and two separate sats probes have been plugged in - neither working, suggesting it may be the Corpuls itself that is faulty.	Saturation probe is faulty on Corpuls. It has been working fine during the first half of the shift and now is not picking up any information, nor is the infrared light on.	Unknown	The same thing happened with this Corpuls machine on Monday, so the sats probe was taken out of service.
1-Dec-16	General Equipment	185	Take vehicle for run to charge nil success	Garment sat Nav battery low then turns off	.?	May need new one . Specifically one of those ones from the 4WD unit Â¿Â¿ I'm in Millaa till Monday then back in malanda.....n
3-Dec-16	Vehicle	200	-	Cracked windscreen passenger side minor	Stone from passing car	-
3-Dec-16	Vehicle	240	Tried various ways to start, fan stays on even when key removed from vehicle until unplugged	Unable to start vehicle unplugged, also ignition issue even when connected to power source.	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
4-Dec-16	Vehicle	185	car driven to cairns (closest) station for further checking/repair	battery died during operational of vehicle > unknown cause	-	Inspection of Unit on morning of 5/12/2016 reveal nothing wrong with the vehicle. Returned to Edmonton station - operational. OIC Edmonton to advise staff that they MUST include an odometer reading when submitting a fault report.
2-Nov-16	Vehicle	230	Contacted comms. Contacted Nambour	small side door on vehicle that is used to access drugs and equipment will not shut or lock.	?	Fault has no effect on actual operation of vehicle. Fault is a security risk.
2-Nov-16	Vehicle	230	Fault form	As Per notes accompanied to GPS.	-	-
4-Nov-16	Defibrillator	230	Device taken off road and OIC informed.	Corpuls would not allow use to select 'test mission'.	-	Device from vehicle 401851.
4-Nov-16	Vehicle	225	Checked air vents and air intake for blockage. Nothing noted.	Airconditiining is not cold and not blowing at full strength.	-	-
3-Nov-16	Vehicle	200	fault form lodged - mechanic to be made aware	Rear aircon not working properly. Taking up to 20 minutes to begin working	unknown	-
5-Nov-16	Vehicle	215	Fault report	Rear scan light on passenger side taken off cab by low branch.	While doing sporting special for colour run Maryborough, driving along narrow bush track a low branch caught the rear scan light and broke it off.	-
6-Nov-16	Vehicle	240	OC notified, OS attended, RACQ attended to replace and OIC notified to have spare fixed.	Flat front passenger tyre.	Found flat.	-
6-Nov-16	Vehicle	235	-	Side door step not working, even after cleaning and silicone spray	-	-
6-Nov-16	Vehicle	215	Vehicle taken off road, OCS notified and fault form completed and forwarded to OIC BBG.	D cylinder oxygen leaking. Nil oxygen reaching internal port inside vehicle. Despite troubleshooting and changing O2 nil O2 reaching internal port. Vehicle non-operational. SOS attempting to fix issue.	O2 distribution line blown off port valve. SOS attempting to fix issue.	-
6-Nov-16	Vehicle	215	SOS notified, fault form completed, vehicle due for service monday 7/11/16 for same issue perhaps?	Internal lights in 4418 not working, electrical fault?	nil	-
7-Nov-16	General Equipment	230	Requires technician	Overhead projector in the Maroochydore training room is functioning but there is a visual distortion/spray affect, that appears across the screen (bottom RHS across and up to the top of screen). Distortion appears when the first image by view sonic is on	Unknown	Operational but not for much longer, the visual distortion makes reading the screen very difficult and appears like white 'snow' across the screen. Unit mounted in the ceiling
7-Nov-16	Vehicle	215	Services have been contacted and will come to the station 08-11-2016 and assess while he is at the station completing another job.	Divers seatbelt not retracting fully	It appears radio technicians may have not put cover on properly and caught the mechanism not letting it contract.	-

RTI Released

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
6-Nov-16	Vehicle	240	contacted and will look at it today 7/11/16	Engine light is on & flashing and vehicle went into limp mode	-	-
7-Nov-16	Vehicle	195	OIC Notified. Fleet Manager Notified. Vehicle booked into Wednesday 09/11/2016 for repair.	S.R.S. warning light on constantly.	unknown	no SHE report required.
7-Nov-16	Other Equipment	185	A/OIC aware.	Front screen damaged and U/S	Was reported by another Officer as dropped	Request replace with Samsung phone
7-Nov-16	Vehicle	230	-	Reversing Camera not working	-	Camera has power, only displays blue screen
7-Nov-16	Vehicle	230	Try to have unit plugged into 240 power at all times at station and when on EA. And turn main power switch off.	Battery faulty, after sitting for a period of time not running power is lost to MDT and red light showing on module battery screen.	? Faulty battery or charging system.	-
8-Nov-16	Vehicle	240	-	Engine fault vehicle with loss of power on acceleration when driving. Seen at North lakes torque ford who report a turbo issue and vehicle to go off road. Vehicle management aware. Roc aware	-	Vehicle having a routine service 10.11.16
8-Nov-16	Vehicle	230	Vehicle fault form, insurance form, contacted OIC	Load lights and rear view mirror unmounted from rear of vehicle. Still attached to vehicle by wires, rear view camera still operational.	Vehicle was being reversed in patients driveway. Vehicle was being guided. There was an awning that covered the driveway which was deceptively short and wasn't in view of rear view camera or mirrors. Car needed to be revved to get over driveway curb and	then once it cleared the curb ran into the awning/gutter which the load lights got stuck on.
8-Nov-16	Vehicle	245	make this fault form	Rear compartment aircon not working	N/A	Only noticed 8/11/16
3-Nov-16	Vehicle	240	mechanic was at station about to take 5123 for service. Crew had to take 5123 instead of 5073 due to lack of other vehicles. (5124 not operational also) Mechanic said he would look at 5073 while he was there.	AUXILIARY BATTERY LOW? MDT TURNED ITSELF OFF AND	unit left unplugged.	-
4-Nov-16	Vehicle	225	Booked in to for replacement	Large chip in windscreen.	Crazy airborne rock.	-
3-Nov-16	Vehicle	200	request sent to Mackay LASN. Mechanic	Stone chip in windscreen extending across windscreen	stone chip	-

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
4-Nov-16	Vehicle	210	Low priority / repair / review soon. IS WAITING FOR CREW TO GET BACK ON STATION AN CALL. WILL CARRY OUT A FEW CHECKS.	The steering wheel adjustment system is not operational. The lever is able to be moved but the steering wheel cannot be lowered or riased to suit driver height.	Unknown	-
4-Nov-16	Vehicle	250	taken off road, CCS and SOS informed of fault. Nil OIC on station.	Engine light on	unknown	-
4-Nov-16	Vehicle	245	This report to OIC	Rear air conditioning blowing hot air. Cabin air conditioning not working well.	N/a	-
8-Nov-16	Vehicle	185	-	External doors unable to be opened. The only way for doors to be opened is from the inside using the manual handles.	-	-
9-Nov-16	Vehicle	240	-	MDT not booting up.	-	-
9-Nov-16	Vehicle	225	-	2 stars in windscreen	-	-
9-Nov-16	Vehicle	225	Email sent to readiness coordinator as vehicle will be in Toowoomba tomorrow to see if it can be repaired while in there.	Air Conditioning not working	-	-
11-Nov-16	Vehicle	240	Non today due to workload unable to get to workshops to test and replace. MDT works if headlights are left on.	MDT failure	Main Battery failure. Ambulance has been on 240v charge overnight	Has been placed on power for weekend and placed as spare vehicle.
13-Nov-16	Vehicle	230	Notified CDS and tried finding switch in vehicle to reset MDT but unable to find. Plugged vehicle into charge but still no power getting to MDT.	MDT not turning on	-	MDT working at start of shift and received a case on it. After returning to station from being out local, MDT shut down and then unable to turn on. After leaving vehicle plugged in for 30 minutes and turning ignition on, MDT has turned back on.
12-Nov-16	Vehicle	250	None, the step will not retract.	Side step broke when stepped on and will not retract	Broke when stepped on by Officer	-
11-Nov-16	Vehicle	250	The has organised towing. The vehicle has been towed to for assessment and awaiting quote to be fixed.	Driver side panel damage. external electrical plug broken, and vehicle therefore unable to restart.	6522 was reversed into by a car blocking the clearway outside Coral Gardens station of Friday 11.11.2016	All documentation has previously been completed
14-Nov-16	Vehicle	240	-	While driving on code 1 case this pm car developed a high pitch whining sound from rear of car which became worse over time and worse with higher speeds.	-	-
17-Nov-16	Vehicle	230	Defect lodged; vehicle marked as non-operational.	Complete MDT failure.	Unknown.	-
19-Nov-16	Vehicle	225	-	Cover on driver's seat base is wearing through on outside edge.	General wear and tear.	-

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
19-Nov-16	Vehicle	245	Reported 18/11	No mdt	Not turning on	-
19-Nov-16	Vehicle	245	Roc and Comms notified job logged with mdt support	No mdt	Not turning on	-
19-Nov-16	Vehicle	215	Took unit to Normal tyre supplier and he removed the damaged tyre and replaced with a used spare. A new tyre has been order. Unit operational	Flat tyre	Rock on dirt road	-
21-Nov-16	Defibrillator	210	replacement being bought to rectify issue	BP cuff lead that connects the cuff to the machine has a broken distal end (end which connects to the cuff) plastic support is broken off	found on vehicel check	will need to see if can but the plastic clip or need to replace the whole lead.
21-Nov-16	Vehicle	240	Called ROC, advised to call and log it. They called back and said vehicle to be taken off road and left at station for technician to come out tomorrow. Notified ROC and OIC.	MDT power issues. Switches off intermittently.	-	-
5-Nov-16	Vehicle	185	Turned vehicle off and on, it runs normally. Turned vehicle off and on again, problem returns.	Vehicle losing power when accelerating, won't go faster than 40 km/h. Aircon not very cold - set at 19 degrees.	Unknown	-
3-Nov-16	Vehicle	195	-	The front wheel rubbing seems to be unsafe. It's underneath the wheel guard	-	-
4-Nov-16	General Equipment	195	OIC checked to confirm not operational	Garmin GPS will not turn on. Discussed with OIC who confirmed GPS not working, unknown cause	-	located in 1120.
6-Nov-16	Vehicle	240	Charging through the inverter	Defibrillator bracket not charging monitor. Needs to be plugged into inverter to charge.	-	-
6-Nov-16	Vehicle	185	Attempted to fault find checking switches and fuses. Also RACQ attempted to repair but needs the vehicle in his workshop on Monday	Siren u/s	Was repaired last week. Has broken again	-
9-Nov-16	Vehicle	225	LOCAL MECHANIC TO INSPECT.	FAULTY POWER STEP - WILL NOT RETRACT AND FAULTY CABIN LIGHT - DRIVERS AREA.	POSSIBLE STONE OR ROCK CAUGHT IN STEP.	Repaired - rocks in step.
10-Nov-16	Vehicle	215	Taken to for testing.	Auxiliary battery unit 347 showing low amperage after being off charge overnight, 9.5 vaults.	-	-
10-Nov-16	Vehicle	260	Completed vehicle check list accurately and reported all faults/fails to	All listed above	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
9-Nov-16	Vehicle	225	NIL/Report	Rear air-conditioner leaks water when it is running in rear compartment on to /Floor/or person sitting in chair.	NIL	NIL
10-Nov-16	Vehicle	210	QAS OIC HAS CARRIED OUT TEMP REPAIR.	Roof A/C vent in the rear of vehicle broken - directional fins have broken off.	-	-
11-Nov-16	Stretcher	215	Stretcher taken out of service and taken to	Stretcher collapsed to ground from loading height as patient sat on it.	-	-
12-Nov-16	Vehicle	185	Visual inspection by to check operational	Brake pad warning light on on dash. visual check done by following conversation with AOIC vehicle still operational as pads appear ok, but replacement parts on order and will be fitted asap	-	awaiting parts
9-Oct-16	Vehicle	215	Should have done a 3 point turn to go through opening straighter next time.	Decal scrap damage on side door at rear on drivers side	Drove into HBH to drop off paperwork when case came in and drove vehicle between another ambulance and a concrete post and nearly got through when side wheel hit gutter and lurched over scrapping rear door on drivers side.	Report not done before as when washing car later same day the panel was wet and that disguised the scrap marks making it trivial at time and recently looked at it and decided a report was right action to do.
14-Nov-16	General Equipment	245	OIC Springwood has contacted service party and regulator has been changed over	Unable to get oxygen flow throughout from either D size cylinder.	state D size regulator required repair due to wear.	attended 14/11/16 and replaced one regulator noting other would also need servicing shortly so have completed required maintenance ahead of next scheduled inspection in January 2017
14-Nov-16	Vehicle	240	-	MDT turns off even when driving. MDT still turning off brought the day. Would sometimes reset itself, however by end of the shift would not turn back on.	-	-
16-Nov-16	Vehicle	210	Nil	Reverse camera screen blue screen with no picture	Unknown	-
16-Nov-16	Vehicle	240	OSU, OIC, OC, Dispatcher notified. OIC REQUEST UNIT TO BE RETURNED TO STATION FOR WORK TO BE COMPLETED TODAY.	MDT fault. Screen randomly going blank with message of lost signal. On screen returning it takes approximately 1 minute for connection to return.. This is occurring randomly and in different locations.	unknown.	-
17-Nov-16	Defibrillator	210	Defib taken off line, defected, located in computer room	SpO2 connection cable and monitor not working	No	-
5-Dec-16	Vehicle	245	-	Nearside door ram door strut on rear door broke off connection. Bent attaching bracket and unable to close rear door. Comms and ROC made aware	-	-
3-Dec-16	Vehicle	225	Fault report to OIC.	Chip on windscreen with crack spreading across windscreen.	Stone kicked up by passing truck	-
5-Dec-16	Vehicle	245	-	Reverse camera not producing image on MDT screen	-	-
5-Dec-16	Vehicle	185	None	Oil level warning light on, oil level very low	-	Warning light came on after several hours on road, oil level checked and confirmed to be low.
6-Dec-16	Vehicle	195	Fault report	Right hand rear door rubber stopper and surrounding structure damage	Unknown	Damage not noted on initial vehicle checklist. Unknown occurrence or origin of damage.
6-Dec-16	Vehicle	240	-	Nail in passenger rear tyre-tyre flat	Nail in tyre	OC called tonight and informed- RACQ organised to come and change tyre
7-Dec-16	Vehicle	240	Nil action able to be taken by crew. Likely caused by loose wiring/connection.	Panel where Corpuls charger plugs in is loose. Approx 15mm movement in panel when pressed. Resulting in Corpuls not charging. Creating risk of Corpuls going flat during shift	Unknown	Discussed with OC Who agreed vehicle to be marked non-operational.
6-Dec-16	Other Equipment	230	Pulled battery in and out and re turn Ned on still the same	Cannot read screen has abnormal unreadable screen	Unknown	OIC to arrange delivery of broken phone to Caloundra LASN office for repairs or replacement.

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
7-Dec-16	Defibrillator	250	-	SpO2 lead is fraying even more than previous.	Unknown	I had been told weeks ago the fraying chord had been reported but it seems the fraying is increasing therefore I am completed this.
7-Dec-16	Vehicle	240	Yes Comms advised, workshops on route to investigate	Passenger side cabin door unable to be closed as door is jammed in open position	? Wear and tear	TFNL Removed LHF ap - Requires Part To Be Ordered
7-Dec-16	Vehicle	250	-	Intermittent red warning light of "brake force distribution?" Intermittent yellow warning light of "ESP deactivated"	-	Officer spoke with who advised vehicle is still serviceable and to take car to mechanics for assessment. Unable to get to mechanics due to high workload.
7-Dec-16	Stretcher	230	Stretcher has been taken to for repairs, and replaced with a fully functioning one.	Whilst pushing the stretcher with patient on it , the head end of the stretcher suddenly without warning collapsed to the ground.	Unknown	Completed by officer camp
7-Dec-16	Vehicle	230	to fix radio fault. MDT not operational on way back to Buderim station	Vehicle had no radio at the start of the shift, with MDT turning itself on and off. One transfer carried out from Caloundra to Nambour hospital, then taken to Functional code 2 only.	Unknown electrical fault	-
7-Dec-16	Vehicle	245	Return to pst?	Out of service, warning light "elec. power steering pump!"	No idea	A/OIC notes - siren broken in vehicle.
7-Dec-16	Vehicle	195	-	Reported to SOS at time of fault.	-	-
7-Dec-16	Vehicle	235	Nil	L side headlight globe is not functioning	Blown bulb	Will try and meet fleet coord at commencement of shift on 8/12/16 1300hrs start unless he comes to Springfield and changes the bulb before shift commences.
7-Dec-16	Stair Chair	210	Have been unable to reconnect the silver bolts connecting the red handle to the rest. Stair chair has now been defected and taken out of service.	The rear red horizontal latch which allows you to unlock the above head handle has disconnected from one side >> hence you can't get the handle up	NA	Fault was found before the stair chair was used to extricate the pt. Another crew was called to provide another stair chair.
7-Dec-16	Vehicle	185	-	Left head lamp blown	-	-
7-Dec-16	Vehicle	245	Towed to with repairing vehicle	Whilst driving on highway vehicle made loud hissing noise, reduced engine power, engine light came on. Attempted to let engine cool and restart but problem persisted.	-	ROC notified, vehicle towed to PST.
8-Dec-16	Vehicle	230	Turned MDT off at control panel for 30 seconds then again for 3 minutes. Tried to drive to see if tracking but not working.	MDT won't power on	-	Car was used by same crew yesterday and when finished shift car was working properly. Car can be logged on at Comms but nothing on screen in car.
10-Nov-16	Vehicle	240	Blinker still works, fault form raised	Small crack in drivers side indicator/Mirror	Reversing in tight space at Wesley hospital and touched a pipe.	Guide was being used at the time.
10-Nov-16	-	210	taken to child's tyres and checked. No obvious reason why and tyre deemed safe. Will keep checking it	R rear tyre losing pressure	unknown	-
10-Nov-16	Vehicle	230	Call CDs and notify oic	Engine light came on during IHT at 2000. Slight clunking through lower gears.	-	drove back to station without difficulty

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
10-Nov-16	Vehicle	245	Corpuls removed from vehicle and replaced.	Initially corpuls testing worked, however during course of shift error occurred "Error of module restart P-box" and was unusable.	Unknown	scheduled to attend Springwood station 15/11/16 to repair or take unit for repair and leave loan item. 15/11/16 - Technician attended and identified faulty CF card which has been replaced
10-Nov-16	Defibrillator	245	Needs new hook	Hook that connects defibrillator to the rest of the machine has been snapped off prior to our arrival. This is causing the defibrillator to not sync to the rest of the machine.	Snapped hook	-
12-Nov-16	Vehicle	250	Vehicle taken out of service, SOS notified, fault form completed	The metal wheel brace for foot end of the power stretcher has buckled and does not allow the stretcher to be pushed. When the stretcher is raised to full height it is unbalanced and wheel does not touch the ground. Can't be secured in car correctly	Occurs when stretcher was lowered to offload patient	-
14-Nov-16	Vehicle	240	Light removed, covered electrical plug. OC advised and requested to attend metro ford - approved. OIC advised.	R) front side light sheered off mount	Unknown how damage occurred. Damage identified whilst completing vehicle check	-
14-Nov-16	Vehicle	225	Unable to be rectified by crew.	Pin that holds back rear barn door on passenger side is sheared off. No side latch on this model either so door cannot be secured when open.	unknown	Operational only if one crew member or bystander can hold the door, particularly in high winds (such as today.)
14-Nov-16	General Equipment	225	Fault form	Pager missing from 3133	-	-
14-Nov-16	Vehicle	215	Cleaned reversing camera in case dirt was affecting reading	Constant alarm beeping on reversing camera and giving inaccurate distance readings	Nil	-
14-Nov-16	Stretcher	215	Tried taking stretcher in and out a few times, raising and lowering etc but to no avail.	Found stretcher with a fault. When pulling stretching from vehicle, rear legs do not lock into place.	Nil	Service due 25/10/17.
14-Nov-16	Vehicle	240	Tape used to hold partly closed to stop opening further whilst driving.	Bottom drawer will not close. ?something stuck behind drawer, unable to access without removal of drawer.	Found as is.	-
14-Nov-16	Stretcher	235	This form	Stitching has split at top of stretcher	Act of god	Stretcher from 6607
15-Nov-16	Vehicle	240	-	Warning light on dash board states "SRS restraint system visit workshop" with picture on dash (photo attached)	-	-
15-Nov-16	Stretcher	235	-	Stretcher stopped moving while removing it from ambulance with patient on it. Unable to manually remove or return stretcher to the vehicle	-	-
15-Nov-16	Vehicle	240	Contacted repairer for fix with upcoming service	Floor bracket charger not attached to floor	Feet knocked the charger off the floor	-
16-Nov-16	Vehicle	230	Fault reported to A/OIC	4773 pager not working	-	Replaced battery now working
16-Nov-16	Vehicle	230	Fuses looked at and form completed	Emergency beacons failing to operate (front and top) back appear to be working	-	Taken off road as being dispatched to code 1s
16-Nov-16	Vehicle	240	fault reprot	Paint damage only to right rear	leaving outpatients transit lounge scraped pillar	-
17-Nov-16	Vehicle	210	Nil	Window washer container blue cap broken in half. Only half cap on container.	Unknown	-
2-Nov-16	Vehicle	200	Mechanic resetting computer, clearing fault.	Engine light activated on dash - ongoing issue, vehicle does not accelerate or change gears properly.	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
4-Nov-16	Defibrillator	200	Nil action taken.	Spo2 cable split open exposing internal wires. Date of when damage occurred Unknown, damage noted during pre-shift check. Spo2 probe still works.	General wear and tear.	Damage noted during pre-shift check.
5-Nov-16	Vehicle	210	OIC HAS MADE CONTACT WITH FOR REPAIRS .	Sat Phone USB connection fault. Unit switches on, displays "USB not connected" then switches off.	-	-
5-Nov-16	Vehicle	240	Tried replacing battery and turning off and on with no change	Portable radio 1 is malfunctioning, continuously turns on and off	-	-
5-Nov-16	Vehicle	200	Car plugged into main electricity source, didn't make any difference.	Main switch (in drivers compartment) which works lights, sirens etc will not turn on.	Unknown	-
5-Nov-16	Vehicle	245	-	R) side middle of lower vehicle panel hit support barrier in South Brisbane station, causing a crack/hole in the vehicle.	Driver inexperience with dual stretcher-miscalculation of turning in with the size of the vehicle.	-
6-Nov-16	Vehicle	185	-	Siren is u/s. Stretcher is U/S. vehicle defects reported to SOS . RACQ assessed vehicle but couldn't repair and needed to be attended to on Monday	-	-
6-Nov-16	Stretcher	185	-	Piston for head elevation on head end of stretcher not remaining in position. When utilised with patient, head continues to deflate to supine position	Defect hydraulic piston	-
6-Nov-16	Vehicle	215	-	chip in windscreen	unknown noticed on Saturday the 5/11/2016 while on a job	-
8-Nov-16	Vehicle	215	Nil as yet, still operational	Left sided rear compartment handle broken, ? Spring broken	unsure, was found like this a commencement of shift.	-
9-Nov-16	Vehicle	230	Nil checked tyres	Vehicle unstable wandering and swaying.	Unknown	Feels dangerous to drive
13-Nov-16	General Equipment	250	Charged on 6561 dock and still 5% charge	Corpulent not charging. Found to be on 5% charge while on 6525 charge dock. Moved to 6561 charge dock and still 5% charge.	-	-
17-Nov-16	Vehicle	240	Mechanic contacted inspecting this morning at station	Rear emergency beacons/light bar not working	-	-
18-Nov-16	Vehicle	240	Repairer contacted and aware - ?faulty light as only came on once then once unit restarted nil issues since. Brake pads checked and ok.	Brake pad wear light has illuminated	Worn brake pads?	-
18-Nov-16	Vehicle	235	Reported fault last week. Had email stating MDT was fixed. Is not working now.	MDT not operational.	Unknown	Currently running on radio dispatch and updates
19-Nov-16	Defibrillator	245	Turned machine off and on, unplugged SPO2 sensor from machine, tried other sensor	SPO2 error - "Defective Oxi Cable"	Unknown	-
19-Nov-16	Vehicle	195	-	Right headlight not working.	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
17-Nov-16	Vehicle	195	Tried to correct problem with no success	Rear lower right square warning light not working. Also oxygen low alarm & test not working.	-	-
21-Nov-16	Vehicle	195	Tagged out of service - Email to OIC, vehicle fault form filled out note left in vehicle,	Side equipment door mechanism jarring intermittently. Tagged out of service due to inability to access Corpuls when door does not open.	-	-
21-Nov-16	General Equipment	215	equipment removed and put at OIC door.	Suction unit defective ??broken filter, nil alternative filters on station as O2 kit trial bag.	unknown	-
22-Nov-16	Vehicle	225	Vehicle has been booked into for replacement	Tyre replacement x 4	-	Vehicle Returned for correct tyres to be fitted. Contacted dealer 1 Dec 2015
22-Nov-16	Vehicle	250	MDT restarted multiple times, nil success	Gps fault on mdt not tracking states antenna fault	Unsure	-
22-Nov-16	Vehicle	240	Fault report	Passenger side headlight burnt out	-	-
22-Nov-16	Vehicle	230	-	Vehicle MDT not tracking, comes up with GPS signal error message frequently	-	-
17-Nov-16	Vehicle	230	Mechanical investigation	Vehicle continue to pull multiple time in either direction at random intervals. Was off road last week for same issue. Feels like heavy winds blowing vehicle around however it is worse than normal and today there was very little wind or gusty wind.	Unknown feels like rear wheels have directional issues	Steering is fine, back end swings around more noticeable at >70km/h nil effect from wind
18-Nov-16	General Equipment	240	-	MDT broken from bracket (2nd time)	-	Vehicle 5245
18-Nov-16	Vehicle	225	Taken off road, fault form completed	When accelerator is pressed there is a severe shuddering in the front end of vehicle. Worse when going up a hill. Sounds like you are going over rumble strips or a corrugated road.	Unknown	-
18-Nov-16	Vehicle	215	Lights kept off	Led strip lighting flashing continuously whilst on	-	-
19-Nov-16	Vehicle	240	Drive the vehicle with headlights on.	MDT shut down on several occasions.	Workshops are aware of the fault.	-
21-Nov-16	Vehicle	240	-	RTC	-	-
21-Nov-16	Vehicle	230	Turned on/off. CDS/ OIC informed	MDT/ GPS navigation not working	-	-
21-Nov-16	Vehicle	230	Contacted CDS, HLO to see if fault could be rectified at	-	-	-
21-Nov-16	Vehicle	230	Was told they don't deal with MDT issues. Fault form completed and OIC informed. O.I.C connected keypad to MDTrebooted and was operational again 22/11/16, discussions with OCU.	MDT stopped working after first job dispatched. Machine turned off three times (for 2 minutes) each time. Display says "delete restoration data and proceed to system boot menu"	-	-
21-Nov-16	Defibrillator	245	Pulled apart and tried several times to reconnect all three parts unsuccessfully	Back third not connecting	-	-

RTI Released

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
22-Nov-16	Vehicle	185	-	* back drivers side door not holding open, falls closed while attempting to load/unload stretcher * pt care drawers aren't latching closed, coming open during transit * bin latch is broken, bin sliding out of compartment during transit Back door issues. Passenger rear door is getting caught on the back bumper/ledge. The driver side rear door clunks when opened all the way. Feels like a loose hinge at the top?	-	-
23-Nov-16	Vehicle	210	Defect fault form Taken out of service,		No idea, noticed when at RH unloading both stretchers.	NA
25-Nov-16	Defibrillator	245	left with OIC	Co2 not sensing	-	-
25-Nov-16	Vehicle	245	Check power steering fluid.	Power steering making grinding noise when wheel is turned	Unknown	-
28-Nov-16	Stretcher	200	Stretcher marked non operational and has been taken off road to be assessed by mechanic.	Stretcher collapsed at the feet end when patient was getting on stretcher at hospital.	-	SHE report to be completed.
28-Nov-16	Vehicle	240	Vehicle Report Form & OIC notified	Star crack in R) windscreen - 50c piece size	Stone hit windscreen whilst driving on D'Aguilar Highway - flung by passing truck.	-
29-Nov-16	Vehicle	225	#NAME?	#NAME?	#NAME?	#NAME?
30-Nov-16	Vehicle	185	Slow oil leak. outer bearing seal Passenger side rear wheel. an be repaired during next service. Will be added to next service	is not leaking to a point where vehicle needs to be fixed outside of normal service/running pattern.	Normal use	to repair at next service due.
30-Nov-16	Vehicle	230	Officers tried to locate fuse box to check fuse - not located and then advised OIC of fault.	Rear Airconditioning not working.	Unknown	Rear Aircon only effected. Front compartment air con working ok. Safety check has been booked for the 12th December 2016.
1-Dec-16	Vehicle	225	-	Annual Christmas safety check	-	New Aux Battery installed due to failure of current battery, new radiator reservoir installed due to leaking and new fan belt and pulley system needed due to damaged pulley.
4-Dec-16	Vehicle	250	Nil	Side step broken, goes in and out but when you step on it it flops forward, like the back brace is broken	N/a	N/a
3-Dec-16	Vehicle	250	Nil	Air- conditioning in front cab is only working intermittently. There is a reduced air flow from the fan.	Unknown	-
1-Nov-16	Vehicle	210	Nil	Straps missing on top of main kit cabinet at sliding door entrance of vehicle	Unknown	Need new straps to safely tie down equipment if needed
4-Nov-16	Stretcher	230	Have logged a job with and they will make contact over next 24 hrs to have mechanic out to look at stretcher	stretcher feels like it is rubbing and getting caught as you pull it out and put it back in. It feels to run freely until the last 3rd of the track.	-	Power pro technician inspected the unit and said something small had fallen into the track causing the damage. Repaired now.
6-Nov-16	Vehicle	250	SOS called RACQ	L rear tyre has large piece of metal wedged in it	driving to case	RACQ changed tyre & flat tyre has been placed back underneath car, waiting for repair
7-Nov-16	-	230	-	Windscreen damage, drivers side approx 100mm crack 4785	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
7-Nov-16	Vehicle	230	able to pull over at nearby service station and inflate to 60 psi (limit of pump), did not decrease much in pressure during this case. Unable to rectify engine warning light despite turning vehicle off and then back on again.	While driving code 1 on first case of the day, vehicle has displayed low pressure in L rear wheel, approx 59psi. Also while driving today engine warning light has come on.	unknown, pressure has not really changed much so ? slow leak	Vehicle warning light is known repeat problem.
17-Nov-16	Vehicle	230	notified CDS	The drivers side windscreen has a stone chip and a crack in it.	unknown, as I found it when I logged on at 12:00 today.	-
18-Nov-16	Vehicle	240	Was reported by OIC that the MDT unit was replaced and problem rectified. Same problem occurring.	Reverse camera displays blue screen on MDT. Intermittent issue though doesn't work majority of the time. Was reported by OIC to have been fixed, but is not.	-	The MDT functions correctly however the reverse camera doesn't display most of the time.
19-Nov-16	General Equipment	215	SOS notified, leads placed in OIC office and replaced in Corpulse	lead V6 in ECG leads unreadable on ECG, nil visible damage.	unknown	-
19-Nov-16	Vehicle	195	Mechanic needed	Side door is getting jammed, with excessive force taken to close it.	Looks like rubber that sliding door wheel runs along is jamming.	-
19-Nov-16	Defibrillator	230	OIC sent email, unknown actions by officer to rectify.	Printer intermittently functioning as per note on machine as per ACP K Cleveland.	-	Duty OIC completing fault form as machine left on OIC desk.
20-Nov-16	Vehicle	215	-	At start of shift a large crack was found at the bottom of the windscreen and going across half the windscreen. Vehicle is still legal to drive as it is below the drivers vision. Also found faulty is the pass side front parking bulb.	-	Unknown if previous crew has already completed a vehicle defect form.
21-Nov-16	Vehicle	210	Ensure door is locked. Placed folded paper between door and switch to ensure switch is in retracted position.	Plastic has broken off from battery door. Resulting in door alarm regularly going off even though door is closed/locked as the missing piece allows the switch to extent and create alarm signal.	Unknown	QAS OIC HAS CARRIED OUT A TEMP REPAIR, WILL BE REPAIRED ON THE NEXT AVAILABLE TRIP INTO ROCKHAMPTON.
27-Nov-16	Vehicle	215	Fault form completed	'SRS' warning light on dash, already taken to and had it reset, advised if it illuminated again and complete fault form.	Unknown	-
28-Nov-16	Vehicle	235	-	Side step not working	-	-
29-Nov-16	Vehicle	215	-	SRS light is on	-	-
4-Dec-16	Defibrillator	215	Corpuls taken out of vehicle	Oximetry monitor fault - no reading using both adult and paediatric connection	-	-
3-Dec-16	Defibrillator	195	-	Spo2 is not working	-	-

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
5-Dec-16	General Equipment	210	The bracket was tested several times to ensure it would release the corpuls. It was found that the lever moves very slowly and sometimes does not lock in completely or only locks in on one side. At present lever and bracket are working though	During preshift check, officer was unable to remove corpuls from bracket, it was stuck. With a lot of assistance from second officer we were able to remove corpus. The red handle has also broken off the lever to remove the corpuls from bracket.	Not known	-
3-Nov-16	Vehicle	210	-	Drivers side headlight burnt out	-	Worked this morning.
4-Nov-16	Vehicle	240	-	As per pre checklist. Front indicator, Powering down inappropriately, Clicking noise when rear aircon is on.	-	-
5-Nov-16	Vehicle	240	fault reported	Left break light not working	Unknown	-
5-Nov-16	Vehicle	225	Nil	Driver Seat not able to adjust forward.. hand dial spinning freely. Potential for dangerous driving position	?	-
7-Nov-16	Vehicle	240	Oic has been informed	Reverse camera not working, only blue screen	possible relationship to incident on Saturday night where rear was hit by	-
7-Nov-16	Vehicle	230	-	MDT not operational won't turn on	-	Verbally reported to cds and oic
7-Nov-16	Vehicle	240	Seen at today - recommended be taken to for repairs - taken at 15:30- aware	Aircon blowing hot air - only cooling while driving	-	-
8-Nov-16	Vehicle	225	Reported.	Apparent rear air bag air leak. Occurred late in shift.	-	-
8-Nov-16	Vehicle	235	Disconnected battery	Battery smoking	? Overcharging	-
8-Nov-16	Vehicle	195	Notified Fleet manager 9/11/2016	Very rough ride front and back of vehicle. Whilst on a case Tuesday 8/11/2016 around 19:30 crossed a tram line crossing and the ride was extremely rough.	suspect suspension requires attention.	booked in for investigation 10/11/2016
13-Nov-16	Vehicle	240	-	Left hand side brake and tail light not working	Possible blown bulb	Discussed situation with SOS who said to leave the ambulance in operational status
13-Nov-16	Vehicle	250	Battery fully charged, still not working	Siren not working	-	-
13-Nov-16	Vehicle	245	Sent to for repairs	Aircon compressor failure	Part failure	-
14-Nov-16	Vehicle	210	Tried to replace through stores, no spares.	SPO2 connector at corpuls end is defective.	-	-
14-Nov-16	Vehicle	205	Reported to Fleet Manager	Damage to sill panel on driver side under windscreen.	Unknown driver, date or time of damage. Only noted this am due to light and location. Difficult to see unless in right position or light angle.	Does not require repair in immediate future. Does not affect vehicle operation or response capability.
15-Nov-16	Vehicle	210	QAS OIC WILL CHECK AND ADVISE.	O2 sensor not functioning	-	-
15-Nov-16	Vehicle	215	mentioned to mechanic 16/11/16 who suggested the latch connection may need loosening	Latch on small rear door (where oxygen and primary response kits are kept) doesnt always work when closing door., 2 air conditioning vents in rear cabin closed with tape.	nil	Power steering fluid needed a top up by mechanic 16/11/16.

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
17-Nov-16	Vehicle	240	Mechanic contacted inspecting this morning at station	Rear emergency beacons/light bar not working	-	-
17-Nov-16	Defibrillator	210	Cord taken from other machine. Faulty one left for OIC.	Pulse oximetry faulty. Cord that goes from the machine to probe adapter is not working. Finger probe ok.	-	-
18-Nov-16	Vehicle	225	None	Power to corpuls monitor not working	None	But not charging, charging bracket replaced
18-Nov-16	Vehicle	225	None	Power to corpuls monitor not working	None	But not charging, new fuse placed in bracket
18-Nov-16	Defibrillator	210	Fault report completed.	Blood pressure cuff lead damaged at connection used to change BP cuffs.	Unknown. Fault noticed during application of blood pressure cuff on scene.	Blood pressure cuff still working and able to take accurate blood pressure therefore machine left in service.
19-Nov-16	Vehicle	240	ROC (advised. As discussed with the ROC, Unit able to respond if needed, depending on case may not be able to transport if continuous treatment needed. Will need to assess pt first, if Tx crew needed.	Treatment chair stuck in turned, position, unable to turn seat back to fwd position	Unknown, red lever works but seat won't turn, unsure if the locking pin is releasing to enable seat to turn back.	-
2-Nov-16	Vehicle	220	fault report and reported to SOS / Station OIC	Oxygen door on driver side of vehicle will not open via the push button. You can only open this door from the inside of the patient care cabin via the manual release handle	? faulty switch	Vehicle is still fully operational, as this issue has a work around and doesn't interfere with patient care or response times. It is an inconvenience for vehicle checks and changing O2 bottles. Minor issue that could be fixed by an onsite tech.
5-Nov-16	Vehicle	225	Vehicle returned to PROSTON Station. Unit 4615 now operational vehicle for PROSTON Station. Comms notified.	Air conditioning not working in rear of vehicle. When vehicle check completed earlier in the day air con working ok. It was on a case that the motor appeared to cut out. Aircon motor keeps cutting out a few seconds after turned on each time.	Not known	Vehicle operates otherwise but no air conditioning in back patient care module.
6-Nov-16	Vehicle	240	Turned the Back AC unit off and on several times at the main control pannel and AC pannel . This did not fix fault.	Back compartment AC not working.	-	The back compartment temperature reached 39 degrees C while transporting a Pt from Closeburn to Samford Station on Saturday 6/11/2016
8-Nov-16	Vehicle	215	-	Stretcher door unable to be opened from outside. Staff have to enter via side door to release rear hatch door.	-	-
9-Nov-16	Vehicle	225	Vault form	The adjustment knob for driver seat back of chair broken and not working. Plus a late tear on the door side of the drivers seat	Unknown was like this upon using car in the morning	-
12-Nov-16	Vehicle	235	-	Vehicle went into limp mode whilst transporting a patient. Vehicle turned off then on again, but did not fix problem	-	-
12-Nov-16	Vehicle	235	-	Side step does not operate automatically has to be done manually appears belts are broken	-	-
13-Nov-16	Vehicle	210	QAS OIC IS DEALING WITH THIS.	Also one hospital swipe key only	-	-
16-Nov-16	Other Equipment	230	requested replacement	Not making phone calls or recieving calls	nil	New hand set issued 16-11-16
18-Nov-16	Vehicle	230	-	Door open alarm going off when no door is open > happening very frequently despite ensuring all doors are closed. When looking on vehicle diagram on the console screen no doors appear open except for occasional flashing of the kit door (which is closed).	-	-

RTI RELEASE

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
25-Nov-16	Vehicle	225	Booked for service 25/11/2016	Due for 45,000km service.	-	Nil
20-Nov-16	Vehicle	215	Battery kept on charge when not in use	Intermittent start fault and main battery not holding charge	Failing battery and ignition switch	Vehicle operation but may fail
21-Nov-16	Vehicle	250	-	Auxiliary battery problems Mdt and radio turning off after a short time	-	-
23-Nov-16	Vehicle	210	-	Defibrillator battery charger not working, front left grill light not working	-	-
23-Nov-16	Defibrillator	200	Defibrillator off road, fault report, contact SOS	Monitored pt showing VF rhythm when clearly not... precheck this am was fine, and fault unable to be replicated afterwards,... intermittent Lead fault?	? Lead fault ?	-
23-Nov-16	Vehicle	185	Report	Side door structural crack worsening. Side and rear door bowed allowing exhaust gases to enter cabin. Rear door seal rubber destroyed. Rear diff leak, tool kick panel clip broken. Patient care consumables divides missing. Low draw hinge u/s	Operational usage. Vehicle age	Both door problems have been prior reported
23-Nov-16	Vehicle	210	Nil	Driver seat worn	Wear & tear	-
22-Nov-16	Stretcher	185	Fault form and SHE report completed.	When arm is extended to load or unload stretcher, it sometimes does not lock and will not stay extended.	Unknown	Stretcher still safe to use and operational.
24-Nov-16	Vehicle	245	Reviewed electrical system/battery by Performance Steering and Tuning. Vehicle now operational.	Electrical fault - Following not working - MDT, radio, interior lights, side step	-	-
23-Nov-16	Vehicle	240	OIC advised mechanic - issue been resovled	Unlock button on set of keys not working	-	-
24-Nov-16	Vehicle	195	SRR raised by OIC	Rear inner door handle missing ?	Unknown	Difficult to open
5-Nov-16	Vehicle	230	No	Reversing camera has water condensation inside housing, blurring vision when backing	Water	OIC advises
7-Nov-16	Vehicle	240	reported to OIC	Damage to Front right of Module	unknown found vehicle with damage upon returning to work Mon 7/11/16 Last time I saw 5543 the unit was at workshops On Thu 3/11/16	Damage not caused by myself damage found upon inspection this morning
7-Nov-16	Vehicle	215	Fault form completed.	Box hanging down near back axel, passenger side. Has electrical wires running to it.	-	-
7-Nov-16	Vehicle	215	Fault form completed	Box hanging down near win at back axel, passenger side. Connected by wires.	-	-
8-Nov-16	Stretcher	240	Notified OIC and fault form complete.	Battery went dead yesterday. Had to switch battery. Stretcher not charging once loaded.	Unsure to why it isn't charging once loaded.	OIC Checked battery swapped out cleaned area and all charging ok. No problem identified and will monitor
9-Nov-16	Vehicle	235	A tourniquet is holding it on	The top right equipment box (oxygen masks) has welds broken and is coming off the wall	-	-
12-Nov-16	Vehicle	240	-	Engine light on. Struggling going up hills	-	attended and repaired fault. vehicle operational again.
14-Nov-16	Stretcher	200	-	When trying to put the stretcher in 'free wheel' mode the designated right foot control not functioning.	-	'Free wheel' mode still able to be selected with lever under the head end of stretcher.
15-Nov-16	Vehicle	210	WAITING FOR ACCIDENT REPORT FROM ROO STRIKE, QAS OIC IS CHECKING OUT CORPULS CHARGER AND WILL NOTIFY OF FINDINGS.	Front grill flasher. Not working, corpuls battery charger not working	-	QAS OIC HAS HAD CORPULS PROBLEM REPAIRED

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
16-Nov-16	Defibrillator	230	reattachment was attempted but it was clear the pins and the connection were broken	12 lead cables broken off at connection point to Defib	Whilst moving the patient the 12 lead cables became tangled and the connection point broke off.	Oic replaced lead, fault corrected
14-Nov-16	Vehicle	240	Contact QAS Workshops Manager for replacment / repair	Garmin not working	Unknown	Single officer repsonse vehicle - delay to case and danger for code 1 driving with using paper based system
16-Nov-16	Vehicle	195	Reported to Fleet Manager, who advised to go to when able.	R rear park light U/S.	unknown	-
16-Nov-16	Defibrillator	185	Changed to another defibrillator. Faulty unit left outside OIC office	Not charging	-	-
16-Nov-16	Vehicle	210	Nil QAS OIC HAS CHECKED, DOOR WILL NOT LOCK, BOOKED INTO ,17/11/16.	Side L) door will not lock	unknown	-
16-Nov-16	Vehicle	185	OIC report.	Crack in windshield has become significantly worse after traveling on bumpy road. Crack has traveled another 20cm, total length approx 70cm in a zigzag shape. Second existing crack approx 20cm comes off the base of the first one.	Travelling on bumpy road. Unknown original cause.	Care needs to taken on bumpy roads. Note - this is the second report created as the original seems to have disappeared after logging on.
22-Nov-16	Vehicle	250	Notified Comms, OS and mechanic.	Sirens not working. Batteries fully charged, appears to be wiring as other switches on lower dash faulty at times too.	-	-
22-Nov-16	Vehicle	245	switched off MDT unit several times to allow for re-boot, still faulty. Reported to Comms via radio	MDT SAT-NAV. MDT works normally and nil issues. However SAT-NAV constantly has a ?mark over the image of the globe and will not locate vehicle on map system nor will it find addresses/route to addresses	found like this	Vehicle and MDT portion of unit are operational, but mapping system not. Officers using iPads to navigate to address
23-Nov-16	Defibrillator	185	No action taken to rectify fault	ETCO2 cable damaged. Plug and protective casing around connected pins has piece broken off. One connector pin has been broken off, therefore the CO2 cable does not input to the corpuls. No readings are obtainable.	Cause of fault is unknown	OIC Notified via phone at 0720 23/11/2016. 'Out of Order' tag with details of fault placed on device.
26-Nov-16	Vehicle	250	Vehicle taken off operational duties	Grinding sound passenger side rear wheel - significant when braking	Wheel and suspension appears intact, possible brake pad issue / replacement needed?	Can be driven
2-Feb-17	Stretcher	205	Stretcher removed from service.	Foot lowering handle noted to be broken.	Unknown.	-
8-Feb-17	Vehicle	240	-	Rear compartment chest of drawers...the drawers locks do not keep the drawers closed and this may cause an injury as the drawers are not secure.	-	-
8-Feb-17	Vehicle	210	None	Star in centre lower area of windscreen	Unknown -found on vehicle check	Nil cracks noted yet.
8-Feb-17	Vehicle	195	Nil	Engine oil light flashing whilst driving Reading light above passenger not secured or illuminating Torches are both flat and do not appear to charge in the vehicle	Too much oil. Rough paramedics. Unknown.	-
9-Feb-17	Vehicle	210	N/A	When driving vehicle and turning corners a loud "klunc" noise can be heard from back of truck.	Unknown	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
9-Feb-17	Vehicle	230	Attempts to reboot the Mdt, further attempts to drive and recharge the battery from alternator unsuccessful. Attempts to use the mains override and emergency start also failed to reboot the MDT	MDT failure	? Backup battery, vehicle was plugged in and on charge overnight	to firstly check power supply. Then send to OSU if required. -
9-Feb-17	Vehicle	240	Notified Comms. Talked to operations supervisor .Transfer patients to different vehicle completed this report	Right mid-glass panel smashed by projectile from road grass cutting operations on freeway	Projectile from grass cutter hitting window	Name of other party. Time 0915 hrs grass cutter operator Contact details
9-Feb-17	Vehicle	235	-	Passenger side spotlight has blown	-	-
9-Feb-17	Vehicle	225	new battery	car not starting	flat battery	-
9-Feb-17	Vehicle	235	mechanic has been notified, car will be placed out of service at night when another truck becomes available	Operational during the day but not at night as the interior lights aren't working properly	Unknown	-
9-Feb-17	Vehicle	185	Lodge fault report	12 volt charger u/s in front cabin, unable to charge GPS unit.	Unknown AUTHORITY V 5233	-
9-Feb-17	Stretcher	230	Stretcher removed from service at Gympie Station and note indicating out of service. SHE report pending	Loading a large patient from Medical Centre and when she sat on stretcher head end collapsed from medium height. Officer had hand behind stretcher easing landing. No injury received and proceeded to GGH.	Unknown, stretcher functioning prior to return from service. Last stretcher service 30/05/16 service number 1176	Vehicle just returned from service when dispatched on case. No injury to patient or crew
7-Feb-17	Vehicle	230	Taken to by crew - fixed already	Side step non-operational	-	Completed
9-Feb-17	Vehicle	240	Notified call centre and roc	Flat right back tyre	-	-
9-Feb-17	Vehicle	215	Nil	Fuel gauge playing up. Reads 1 bar down when just filled, goes up and down, etc	Nil	-
10-Feb-17	Vehicle	200	Unable to rectify with headlight scroll	Right head light "dipped" causing poor night vision.	-	-
10-Feb-17	Vehicle	215	Pager was given to Bundaberg OIC	4405 vehicle pager does not turn on despised changing the batteries	-	4405 mobile phone works well
10-Feb-17	Vehicle	195	Notified SOS, marked out of service, vehicle checklist faults notified.	Gps not working, vehicle air conditioner freezer and stops blowing air. Worked for the first 60mins then froze. Windscreen water pump not working. Unable to clean the windscreen of bugs while driving in the highway. Very dangerous. Taken offline.	-	-
11-Feb-17	Vehicle	230	Reported to	Officer clipped sign ripping off drivers side wing mirror	-	VEHICLE OFF ROAD
12-Feb-17	Vehicle	240	-	Following refuel of vehicle with Diesel engine light started flashing consistently.	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
12-Feb-17	Vehicle	245	Discontinued using inverter ran cotton battery	Inverter keeps tripping when mansell neo cot plugged in while in transit from lady cell to Ipswich and then on return from Ipswich back to lady cell to hospital.	Unknown	-
6-Feb-17	Vehicle	210	-	air suspension rear continue wanting to imply	taken to work shop	-
6-Feb-17	Vehicle	210	notify mechanic	interior dome light panel switch not working on Passenger side next to attendant seat and the doors open flashes on the control panel in front of car to say there is a door open but all doors appear closed - no audible tone	found on vehicle check this am	-
7-Feb-17	Vehicle	250	SOS & mechanic witnessed fault on GCUH ramp, manual step activation unsuccessful, advised to take vehicle off road at completion of shift and is organising new step & tow for following day 8/2/2017.	Side step not retracting	Malfunction	OIC aware at end of shift.
7-Feb-17	Vehicle	245	fault form	transmission problems ? vehicle has a shunting noise sometimes when driving	transmission ?	-
7-Feb-17	Vehicle	210	-	Passenger side spotlight/ "drive light" not functioning. Driver side fine.	Unknown	-
7-Feb-17	Vehicle	245	It is an intermittant fault. Previously we have had a technician spend 2 hours at station fixing this issue. It is becoming a daily occurance even some gaffer tape would solve the short term issues and get it back on-road.	The side hatch/doors to access the first aid/defib etc keeps coming open whilst in transit. this has the potential to do damage to other vehicle and pedestrians.	The maginetic latch keeps letting go.	-
8-Feb-17	Vehicle	200	Tucked it away	Rubber seal around side door access to kits coming off	Wear and tear	Unit 2241
8-Feb-17	Vehicle	230	see above	MDT wont boot up - black screen with writing - OIC attempted to reset with keyboard but no change	-	OIC called MDT Fault Line
8-Feb-17	Vehicle	240	Car turned off and back on, same alerts raised.	Wheel picture with visit workshop, ESP visit workshop, and brake distribution visit workshop, all appeared on dashboard	-	ROC notified and advised to return to station. Screw in tyre. Tyre needed replacing.
8-Feb-17	Vehicle	230	Turned off and on	Reverse camera on the MDT won't work.	-	Black screen on the MDT when the vehicle is put into reverse.
8-Feb-17	Vehicle	235	Out of service	Rear interior lights intermittently work and defibrillator doesn't charge while in cradle - upon start of shift, defib has 50min of battery remaining.	-	SOS aware
8-Feb-17	General Equipment	210	OIC informed and SIM card transferred to another phone	Unit 2234 mobile turned itself off while on a job despite having full battery.	-	-
8-Feb-17	Vehicle	235	-	Passenger windscreen wiper rubber of frame	-	-
8-Feb-17	Vehicle	240	OIC informed	Patient monitor/Reversing camera unit not functional	Not known	-
8-Feb-17	Defibrillator	230	Towel under	Definitely charging bracket not charging, connection to defibrillator faulty	Wear and tear	-
7-Feb-17	Vehicle	240	notified workshops to check during vehicle service today	Alarm in rear cabin coming from back electronics/fuse cabinet: appears that it could be related to house battery not holding charge as MDT shuts down when parked for a short period	wear and tear/age	If vehicle battery is seen to, this fault form is created as per procedure

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
10-Feb-17	Vehicle	195	Out of service. OCS notified.	Engine dashboard light started blinking whilst driving and fuel smell on arrival at hospital.	Book says possible exhaust or fuel injection issue.	Felt ok driving and no issues starting. Just the light and the transient one off smell of exhaust in the back.
10-Feb-17	Vehicle	235	Unknown	Side step is damaged, will not work	Unknown	Noticed during vehicle check. Unknown when it happened.
10-Feb-17	Vehicle	240	Kit has been taped up to be functional	Wall mounted airway kit needs replacing.	Manufacturing fault	-
9-Feb-17	Defibrillator	210	-	Pulse ox isn't working	Unknown	-
10-Feb-17	Vehicle	215	Nil	Stretcher locking latch mechanism faulty in rear cabin, drivers side	Nil	Vehicle dropped off at 10/2/17.
10-Feb-17	Vehicle	225	-	6 month service due	-	Front passenger side hub stiff. Aircon Intermittant issue with cold and rear touch screen not working (patient care seat).
30-Jan-17	Other Equipment	230	Unit has been replaced several times. The last visit from technician was to recommend a fan system to unit in overhead compartment	MDT in ambulance 4917 continues to loose power. This has been a persistent issue from overheating issues and has been seen by technicians several times	Overheating	Please fast track recommended repair advise to unit
31-Jan-17	Vehicle	245	Ensured AC cover closed, magnet cleaned. OIC Beaudesert assisted at time and nil further issues with inability to start vehicle.	Unable to start vehicle due to car saying external AC cable plugged in	-	Still unable to start vehicle despite above for a period of time. Vehicle eventually started and were able to return vehicle to Beenleigh.
31-Jan-17	Vehicle	235	SOS notified, OIC and SOS emailed with details, SHE report completed, Other occupant of the car was given details. Vehicle taken off road	Reversed into another car in a car park during a job	Reversed into a car	-
31-Jan-17	Vehicle	210	Submitting a fault form now	All four side lights (alley lights and scene lights) and rear light not working	Unknown	Whilst doing routine pre-shift car check this evening it was noted that those lights were not turning on
31-Jan-17	General Equipment	250	emailed resource readiness coordinator	Sim Pad not turning on- light changes to green indicating power source is connected but screen will not turn on	unknown-	-
1-Feb-17	Vehicle	185	Issue has been reported. Parts have been ordered and technician awaiting arrival of parts to rectify the fault	Stretcher loader fails to operate under load	?? Battery or other part failure	-
1-Feb-17	Vehicle	225	Attempted to turn car off and on again multiple times with nil effect - able to get back to station at approximately 40km/hr and with extremely slow acceleration (dangerous)	Unable to accelerate appropriately	Car is going into 'limp' mode - engine warning light appearing and losing acceleration capabilities.	-

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
1-Feb-17	Vehicle	250	Contacted ambulance mechanic who stated it needs to go to a panel beater. Notified SOS who notified OCS.	Rear door usually has an operational left and right clip/lock. Right side clip is not locking door down, resulting in loose door.	Ongoing issue.	-
1-Feb-17	Vehicle	210	-	Displaying service A due 2600, as per photo	-	-
1-Feb-17	Vehicle	235	System has been restarted numerous times. Vehicle has been left on charger throughout days and still failing. Spoke with Fleet Manager and advised of actions prior.	MDT and radio shut down intermittently and frequently.	Possible fault in alternator, possible battery	Vehicle taken to Ipswich 04/02/2017 and swapped for unit 6674.
2-Feb-17	Vehicle	235	-	Pager faulty (cap code - 0427149) nil sound, only vibrates	-	-
2-Feb-17	Vehicle	215	Nil	Passenger front window switch broken, but usable. Needs replacing	Unknown found during checks.	-
2-Feb-17	Vehicle	190	Unable to contact OIC - liaised directly with who advised they will fix now - Unit is currently at being repaired.	Front Passengers Side Headlight Out	Unknown.	-
2-Feb-17	Vehicle	230	diagnosed fault, part to be ordered.	Lamp u/s in rear drivers side array	-	353MED
2-Feb-17	Vehicle	250	-	All doors in rear cab lock and unable to open. Regardless of engine running or not. Only able to open manually with handles once inside vehicle. Doors jamming.	-	CDS and OCS notified. Vehicle to be left at Runaway Bay station.
2-Feb-17	Vehicle	235	-	MDT receiving jobs but GPS not working	-	-
2-Feb-17	Vehicle	240	No idea	The lights in the back of the car will not stay on.	Noted two weeks ago but not sure if previously reported as personally not worked on this vehicle for considerable period	-
3-Feb-17	Stretcher	240	Belt strap cut	Left trim on pax front door plastic clips broken so trim loose and flapping	Belt was stiff, had slight damage	-
3-Feb-17	Vehicle	245	Notified roc who was trying to arrange Nambour workshop to attend to see if they can rectify problem	Air conditioner front operating panel will not reduce rear air conditioner temp below 32 degrees this fault was identified while under taking retrieval to nambour	Unknown	-
3-Feb-17	Vehicle	210	car has been defected / taken off road and OIC notified	Vehicle is making a "rumble" noise and vibration felt throughout car- worse on full lock of steering wheel but also when driving in straight line	unknown	-
4-Feb-17	Vehicle	245	Attempted to reattach bracket but unable to do so.	Third draw in walk station draws in rear cabin does not shut. Appears a metal brackets is loose preventing the locking / latching mechanism from functioning properly.	Unknown. Fault found at start of shift.	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
5-Feb-17	Vehicle	210	defected	The back suspension of vehicle was very rough at times when going over bumps on the Yeppoon to Rockhampton road this morning. Same problem identified 2 days ago which was investigated at the workshop.	unknown	It was uncomfortable siting in the back of vehicle which was noticable for the patients as well.
3-Feb-17	Vehicle	235	Radio and charger were fixed a year ago but stopped again. Advised Fleet Technitian	Flashing beacons not working - initially Two white lights on bonnet, one on number bar driver's side but now only one white light not working on bonnet. One white flashing light not working on passenger side rear. Phone charger & AM radio not working.	Unknown	-
5-Feb-17	General Equipment	225	Taken off road	Car radio not working 3183	-	-
5-Feb-17	-	240	Replaced from stores	Spo2 sensor failure	-	-
5-Feb-17	Vehicle	230	Advised to drive vehicle by CDS to Noosa station and swap with a car	Nil air conditioning working in the rear compartment. Oil messages on front dash	Unknown	-
6-Feb-17	Vehicle	240	OC notified and he contacted RACQ	? Dead battery	? Main switch being left on	-
6-Feb-17	Vehicle	210	Unable to rectify	Side access door to rear doesn't lock and unlock electrically. Can be manually locked.	-	-
4-Feb-17	Vehicle	235	This form	1/ water is dripping from air conditioner unit on roof of patient care cab. Dripping over bed and over work station. 2/ chip to windscreen left side	1/ not known why air conditioning is leaking, possibly blocked drain pipe 2/ probably a stone or obese moth	-
5-Feb-17	Vehicle	235	-	Unable to accelerate - when applying acceleration air con fan increased & accelerated decreased	-	-
4-Feb-17	Vehicle	225	Spoken to OIC, will organise tyre repair	Spare tyre flat, needs to be repaired and attached to vehicle	Screw in tyre	-
6-Feb-17	Vehicle	230	Reported	Airconditioning unit spraying water and leaking badly in rear of vehicle	Unknown	-
6-Feb-17	Vehicle	235	N/A - require repair	Vehicle found to have broken plastic indicator light surround on right side mirror.	Unknown - found this way beginning of shift.	-
6-Feb-17	Vehicle	210	-	Rear Suspension continuously deflating and won't re inflate	-	-
6-Feb-17	Vehicle	210	Equipment removed from vehicle	Pulse Oximetry not reading	-	-
6-Feb-17	Vehicle	215	-	VHF radio keeps cutting out when trying to transmit messages to Comms	-	-
6-Feb-17	Vehicle	240	Previous request for wheel balance	Vibration front of vehicle when traveling speed greater than 80 Klum /hr	Vehicle requires wheel balance	I do not consider this vehicle safe for high way or code 1 driving . Return to station and swap vehicles
6-Feb-17	Vehicle	195	Due to time of day (approx 1800hrs) and busy operational tempo, vehicle was tagged out and marked as un-operational SOS and OCS notified and crew logged into new vehicle.	Engine cut out whilst vehicle was stationary at a set of traffic lights. Vehicle immediatly started successfully however red bitterly light appeared on dash.	? Battery fault	Post stall and dash light appearing car drove normally with nil issues however was tagged out pending mechanical/ electrical review.
8-Feb-17	Vehicle	235	-	The vehicle operational radio is functioning, however the speaker is not working and nothing can be heard when transmitting or receiving messages.	Unknown, however there is some scratching noises that can be heard that sound as though it may be a loose wire connection.	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
7-Feb-17	Defibrillator	230	Placed out of service - OIC notified - alert notice placed in vehicle - Equipment defect notice completed.	Printer paper door unhinged and fails to close effectively.	Defib was situated on the back of the stretcher on the harness to carry equipment on. On loading the stretcher into the ambulance the defib fell from the stretcher on to the floor of the ambulance a height of approximately 30cm	has taken defective corpuls and delivered a Replacement Corpuls Loan unit 51. Damaged Corpuls may take a week or so. Service Request number 6014858.
12-Feb-17	Vehicle	235	-	Right low lbs am light is out.	-	-
12-Feb-17	Vehicle	185	This fault form	Pod battery always flat, doesn't seem to hold charge after being on charge all night.	Query battery faulty or charging system faulty	crew did not take unit to have battery replaced. job closed. nfad
13-Feb-17	Vehicle	240	OIC informed service department. Crew to take vehicle in when operationally available.	Vehicle fridge does not operate properly. Was reported prior to last service and stated it is working. Fridge appears to only operate when vehicle is running; Does not operate when vehicle is shut off, nor when it is plugged in at station.	-	Whs issue as crew cannot rely on it for food safety.
13-Feb-17	General Equipment	230	Reposition charge cord - nil effect	4821 Garmin is inoperable and requires repair or replacement	Possibly charging cord	821 has the old MDT with no GPS mapping. OIC contacted faulty garmin charging socket replaced. Unit appears to be working now.
13-Feb-17	General Equipment	245	-	MDT shutting down	-	-
13-Feb-17	Vehicle	240	OIC, ROC and COMMS informed, crew were told to proceed to when available to.	Emergency and h/lights intermittently working	Unknown	Crew attended earlier due to aircon leaking, all lights working on prior cases before visiting nova ford.
14-Feb-17	Vehicle	210	Car is on charge at station	Car did not start on EA.	Battery does not sound like its too healthy	-
13-Feb-17	Vehicle	240	management was advised so the problem can be fixed	Engine light came on and was flashing and there was a unusual noise coming from the turbo	unknown	-
14-Feb-17	Vehicle	225	Tyre scheduled to be repaired replaced ASAP	Flat tyre whilst on CN 8496813. Rear Drivers side tyre.	Possibly sharp stone gravelled road on route to case.	All appropriate person notified, all relevant forms completed.
15-Feb-17	Vehicle	210	-	Blue cap for window washer water missing.	Unknown	-
15-Feb-17	Defibrillator	250	Notified OIC and taken out of service.	Test dump delivered but nil print out afterwards, Printer wont print and just says 'Print Aborted'. Nil SPO2 tracing or light on probe. Nil ECG tracing when connected to test box.	-	-
15-Feb-17	Vehicle	225	-	Electric side step has failed to operate. When sliding door opened and switch manually operated the motor appears to start operating but step won't extend.	-	-
15-Feb-17	Defibrillator	240	put in new spo2	spo2 cable defective	-	swapped cable with oic at chermshire so we could have an operational defib
10-Feb-17	Vehicle	240	Vehicle repaired at work shop on 10/02/2017	Sliding door left side faulty	Loose bracket	Unable to access this program until 15/02/2017 due to iPad issues.
16-Feb-17	Vehicle	185	Report to SOS and completed fault form.	Interior front control panel faulty. Rear light switch missing. A/C control panel not working for rear A/C	First shift back post days off.	Both lights and A/C are able to be switched on from rear of vehicle. V 5273. VEHICLE WILL BE TAKEN TO TAG MONDAY 20/2/2017.
15-Feb-17	Vehicle	225	Recharged.	Back aircon isn't functioning.	No	-
16-Feb-17	Vehicle	220	vehicle taken to auto electrician	Aircon fan in dash remaining on when vehicle is turned off	nil known cause	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
16-Feb-17	Vehicle	180	Beacon screwed back in but screws not gripping, will require some type of filler and/or adhesive. Will get to repair.	Rear driver side beacon, small one attached to side of pod, came out while washing vehicle.	Corrugations and one screw missing.	Beacon still working.
16-Feb-17	Vehicle	235	-	Crack to front windscreen previously reported however crack is now approximately 50cms in length	-	-
16-Feb-17	Vehicle	195	Nil	Right headlight blown	Unknown	Not suitable for night driving
10-Feb-17	Vehicle	225	-	45,00km/ 6 month service due	-	-
10-Feb-17	Vehicle	230	vehicle checked by O.i.C MDT does not come on at all. off road for weekend. Blue box replaced behind side door as well as MDT head. Appears to be a heat related issue.	MDT lost power while enroute to first job and could not be restarted.	-	MDt now functioning, ZIPS all ok on Corpuls, mobile phone charged.
10-Feb-17	Stretcher	185	Sos notified. Stretcher now appears to raise correctly however it has not been tested under similar patient load. SOS asked for vehicle to be taken off road until a reason for fault can be identified.	Stretcher engaged into carriage and green lights illuminated. Vehicle was on very slight sideways gradient, with loading arms central to stretcher. Loading arms appeared to pull stretcher towards vehicle whilst retracting legs. Did not fully retract.	Pt estimated over 110kg. Slight sideways gradient did not appear to be at fault. Stretcher has had battery changed several times this week by paramedics. I am led to believe that the loading carriage had battery replaced recently as well.	Incident occurred on scene and patient had to be transferred across to EA officer's stretcher and vehicle, causing a delay in transport and an interruption in the treatment of patient. VEHICLE & STRETCHER ARE LOCATED AT MAREEBA QAS.
10-Feb-17	Vehicle	230	Contacted CCS	MDT fail	Unknown	Requires technician to reboot system with keyboard interface.
11-Feb-17	Stretcher	230	Swapped with spare stretcher at NGH. Defect stretcher now located at NGH. HLO aware.	Trolley veering to the left when pushed feet first	-	-
11-Feb-17	Vehicle	225	-	Front drivers light and cover u/s	-	-
11-Feb-17	Vehicle	200	-	Starring of windscreen on passenger side.	Officer was hitting a mozzie on inside of windscreen which caused long starring of windscreen.	-
11-Feb-17	Stretcher	245	Stretcher was in 601463. Stretcher has been replaced with working stretcher from Beenleigh Station under Direction of OS and SOS. Faulty stretcher is currently at Beenleigh Station and signed appropriately.	Stretcher gets speed wobbles at low speed ? Related to head end wheel assembly loose at an unknown point.	Nil incident occurred. Fault noticed whilst taking stretcher back to vehicle after off loading patient at hospital.	-
11-Feb-17	Vehicle	245	RACQ contacted to change tyre. Spare replaced by PST	R) rear tyre has roofing screw in it. Changed by RACQ - damaged tyre is now in position of spare as per OIC Beaudesert Mahoney.	Unknown - noticed by Beaudesert OIC at LCH	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
12-Feb-17	Stretcher	225	-	Metal guard for operating handle broken.	Student was attempting to load the stretcher back in the ambulance, she was confused and tried to place it in backwards. Before I was able to stop her she had attempted to push it in and accidentally broke said part.	-
12-Feb-17	Vehicle	195	-	Continually goes into limp mode - decreased acceleration, max speed turtle	-	-
11-Feb-17	General Equipment	195	-	The fire extinguisher for 1405 fell off the wall and landed on the ground whilst at hospital. The fitting for the cradle was screwed into fibre glass and has just come lose and has also fallen off	-	-
12-Feb-17	General Equipment	240	Report before stated problem was fixed.	Mdt still turns itself but this it won't restart unless you turn the vehicle off then on.	Electrical fault	-
11-Feb-17	Vehicle	185	Attempted both keys including spare.	Intermittent central locking fault. Unable to disengage lock with both vehicle keys. Need to utilise manual key to unlock door. Vehicle still starts	-	-
9-Feb-17	-	240	Called OC, crew taken out of service, returned to station to swap defibrillators and faulty defibrillator left outside OIC's office with a note to advise.	V6 lead not reading or showing on Corpuls screen or 12-lead ecg strip When vehicle is stationed or running in the back of the vehicle and front compartment has a very strong solvent smell when locked up and worse when vehicle is not running. It also appears to come through the aircon as well.	Unknown. V6 worked on pre-shift check and on first job but then wouldn't work after that. Removed wire to check it was clean, nil obvious or visible damage, 12-lead ecg done on a crew member but V6 still not working.	-
12-Feb-17	Vehicle	230	OIC notified as well as sos and opcen. Vehicle taken off road	MDT shuts down due to battery being drained	Vehicle had previous issues with it	Due to very hot day may also have a contributing factor but currently the smell is causing headaches
12-Feb-17	Vehicle	235	Reset button and vehicle being on jobs gained enough power	MDT shuts down due to battery being drained	-	Appears to be an ongoing power issue with the vehicle
3-Feb-17	Vehicle	200	Spoken with local mechanic who measured battery levels and advised to speak with regarding new batteries.	Battery issue - when the vehicle is started, the computer, vehicle radios and audio systems turn on, then approx 20 sends later, they all turn off. Also, rear module power (including rear AC) turn off. After 10-30seconds, they all return to normal.	Second battery not holding charge. Tested with local mechanic both batteries at 14.2v, however, when the vehicle off with only LED lights in the patient care module and Comms radio on, the battery dropped quickly to 11.2 and continued dropping.	Main battery was marked 4K (2014-November) and the second battery appears to be older than that. No issues starting the car, but when with the vehicle off at MBH and trying to use the radio, the radios shut off. Further info in email to LASN mechanic.
3-Feb-17	Defibrillator	245	Replacement spo2 connecting cord being used, faulty part removed from service, reported via this fault form	Spo2 connective defective, warning message on corpuls when used	Nil known	Nil
3-Feb-17	Stretcher	185	Fault Unable to be rectified.	Fault with activation / locking of gas strut legs.	Unknown	M1 Stretcher Out of Service at CBH
3-Feb-17	Vehicle	240	Plastic bracket repositioned as a temporary measure to enable use	Cigarette lighter plastic bracket in vehicle broken resulting in connection slipping inside compartment at times and being unable to be used.	Found in this manner	scheduled for repair at next service
4-Feb-17	Vehicle	235	-	Fuel gauge faulty = inconsistant with km travelled and bars down. Has under read and over read.	-	As long as odometer re-set each time (and it isn't) then managing this refueling at ?350-400km would keep a safe practise until fixed.
4-Feb-17	Vehicle	240	Unknown refer to below statement	A/C Leaks like a Darwin Storm in the wet season if A/C is on and side door is left open... MDT also has intermintent fault	Unknown... ?blocked A/C drainage Unkown ... Loss connection in MDT	Apparently these have been ongoing problems and have been reported and investigated by

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
4-Feb-17	Vehicle	240	-	The left stretcher appears to of lost power. We Replaced battery and stretcher is not being obstructed by anything and it still is not locking down at foot end. The head end is locking in enough for stretcher to not move around in transport but the foot	end is not locked in at all....	Officer had a look at unit and noticed power load was turned off. Stretcher functioning normally.
5-Feb-17	Vehicle	230	Nil. Cupboard held to wall manually (by hand) during Tx of pt when came loose during transport.	Rear overhead cupboards (driver side) falling from roof. Dangerous to patient and officers.	Screws sheared or snapped off. Obviously inadequate screws used for cupboard weight. Second time same fault for same vehicle.	-
5-Feb-17	Vehicle	230	-	Vehicle rear cupboard fell from wall during case. Vehicle taken off road mid-shift and fault form generated. Comms advised.	-	-
5-Feb-17	Vehicle	225	Nil at this stage.	Multiple faults to be rectified. Radiator coolant header tank leaking, has been previously washed off but staining and liquid has come back around the joining seem. Coolant had to be added at start of shift.	Maintenance.	Reversing sensors continually sounding when in reverse and no objects are in the surrounding area. Rear right oxygen cupboard screws are falling out and cupboard is falling off the roof. LED lights falling off the roof. Refrigerator not cooling.
5-Feb-17	Vehicle	235	Zip ties used to secure the box under the ambulance but will need proper long term fix. Photos being sent to mechanic for Monday.	Plastic box with electrical wires has broken off the two screws that held it to the underbody of the rear of the ambulance. Have used zip ties to hold it up for now.	Unsatisfactory method of securing with two screws. Possibly came off going over bumps in track.	For short term.
5-Feb-17	Vehicle	235	Radio was reset, turned up and down in volume, and transmission inhibit turned on and off with nil resolution of issue	The vehicle radio will transmit however nothing is heard through the speak inside the vehicle. All other aspects of radio appear to be working as per normal	Unknown. Was noted at the start of shift.	Vehicle can still be used with portable radios turned up loud to hear transmissions
5-Feb-17	Vehicle	235	-	Missing internal oxygen window lid - so that when sitting in the chair behind the driver, arm and objects can fall into oxygen cyclinder compartment. Also, back of oxygen gauge on R/D cyclinder is also missing.	-	Could we please order a replacement lid at the earliest. Thanking you in advance.
5-Feb-17	Vehicle	240	Report for for next service	Due to vibration in steering wheel I believe vehicle requires a wheel alignment and balance	Unknown	Noticed when first started to drive vehicle
6-Feb-17	Vehicle	230	Removed from service & "out of service" tag placed on car	Rear A/C unit leaking internally Right rear indicator routinely failing Module work lights are failing to illuminate occassionally Module step alarming with door closed/step retracted + intermittantly partially extending/retracting repeatedly	Several electrical issues affecting vehicle operational + rear air conditioner unit leak	-
2-Feb-17	Other Equipment	235	Nil no equipment to rectify	601672 has no charging facilities for iPads, there is one outlet that is used for the tough book. This unit should have sufficient charging station to maintain charge in tough book, iPads and mobile phone.	Not known	-
9-Feb-17	Vehicle	210	Nil to this point	Left headlight U/S	-	-
8-Feb-17	Vehicle	215	Vehicle was taken to the mechanic to be repaired	Vehicle radio, light and sirens malfunctioning during the day, worsening when vehicle was off	-	Vehicle is now operational
9-Feb-17	Vehicle	245	-	Headlights not working	-	-
10-Feb-17	Vehicle	245	Vehicle off road	Headlights not working	-	-
9-Feb-17	Vehicle	245	-	Headlight not working	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
10-Feb-17	Defibrillator	250	Reported and I'm 9/2/2017 was returned to service after being checked however problem continues to occur.	Not charging in back of ambulance.	-	-
10-Feb-17	Defibrillator	240	reported to	screw missing from paper roll bracket causing printer paper to be loose and jam when roll low	missing screw	-
10-Feb-17	Vehicle	240	Called	Will not start - Was left unplugged after incident on 9/2 and would not start when Tow Truck arrived.	-	-
10-Feb-17	Vehicle	185	Checked fuses and switches.	Automatic side step not working.	Unknown	Previously reported to this officer by other officer several weeks ago. Presumed to have been reported by that person. Unknown if form has already been submitted. V 5237.
10-Feb-17	Vehicle	230	Run engine to charge phone. (No wall chargers for phones on station).	Mobile phone flat at start of shift despite vehicle being plugged in to mains, and phone plugged into phone charger.	Vehicle phone charger should charge phone whenever it is plugged in. Not only while engine is running, as is currently the case.	Charger will only charge when ignition is on. Charger/ lead available at station to plug inot computer. more multi point usb chargers on order by Fleet to be placed in cupboard where keys ar kept.
10-Feb-17	Vehicle	230	-	Corpus blood pressure cuff compartment has a broken zip.	Pockets for blood pressure cuffs, etc, all 2 sizes too small.	-
11-Feb-17	Other Equipment	215	Tried charging for extended period	Torches not operational	Unknown	-
11-Feb-17	Vehicle	240	Reported to Comms and note left in car for OIC monday morning. MDT was powering on when OIC in on Monday. Not sure what the issue was maybe main switch not turned on?	MDT unit is not powering on.	-	-
13-Feb-17	Vehicle	215	-	Drivers seat upholstery deteriorated	Normal use	-
11-Feb-17	Vehicle	225	Nil	Leak to (L) front tyre - Nil defect completed.	unkown	-
13-Feb-17	General Equipment	250	-	MDT powers down every time the ignition is switched off and will not restart without resetting from the mains. Vehicle 6524	-	-
13-Feb-17	Vehicle	230	Reset master switch	Electrics in back of vehicle faulty. Post rain vehicle electrics failed. No lights in rear and no suction vent fan on and unable to be turned off	Possible water leaking onto electrics	CDS notified. Vehicle drivable but no functional as ambulance. Fixed and returned from on 14/2. Now at Maroochydore but returning to Coolum today
13-Feb-17	Other Equipment	245	Replaced faulty parts	Toughbook charger is not working in car	-	-
13-Feb-17	Vehicle	185	Sign of rear of pt care seat stating risk	Rear suspension or hydrolics are lower back of vehicle too low causing extra lifting to be required, particularly with larger patients and caused the front legs of stretcher to not click into place-hazard!!!	-	She report lodged . V 5271. OIC CAIRNS TO ARRANGE UNIT TO GO TO
13-Feb-17	Vehicle	230	Tried to visualise cause of fault, unable to do so.	Side step is functioning, however makes a loud grinding noise and appears to have difficulty when moving in and out. Nil obvious obstruction on inspection. Scrape has appeared on right side of step.	Unknown	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
16-Feb-17	Vehicle	205	The kangaroo was pronounced dead at the scene, meeting criteria for rapid discontinuation of resuscitation (massive craniofacial destruction). No action required for vehicle to remain roadworthy.	A kangaroo jumped out from the road shoulder and struck the vehicle just behind the front passenger's side door causing what appears to be cosmetic damage to the panel between the door and the front of the module.	A former kangaroo	-
17-Feb-17	Vehicle	240	report	Steering alignment out - vehicle pulls to left	-	Steering not corrected at last service Tuesday Wednesday 15/16 February
17-Feb-17	Vehicle	210	Unit is still in service / repaired replaced when returned to QAS Rockhampton.	Garmin Navi Satalite system. The information on the unit when inputted does not correspond to what buttons are pressed. You type in a letter and get another.	Software issue / need for update?	Satalite system is still operational just difficult to use.
17-Feb-17	Vehicle	215	Fault form	Pt care seatbelt will not extend. Multiple attempts completed with nil success.	-	-
16-Feb-17	Vehicle	195	-	Drivers side tail light out. Rear left door not remaining open with opening latch.	-	-
18-Feb-17	Vehicle	240	-	Aircon in drivers cabin only intermittently working. Makes whirring noise when not working.	-	-
18-Feb-17	Vehicle	245	notifying OIC	Rear Left Indicator light casing smashed	Light casing was hit by a tree branch whilst reversing	-
18-Feb-17	Vehicle	210	Tires filled with air but warning light still on	Tire pressure light on and headlight out	-	-
17-Feb-17	Defibrillator	210	Turned on/off. Attempted to use different EtCO2 device.	CO2 not working/registering.	-	Located outside OIC office
18-Feb-17	Stretcher	210	SOS advised and vehicle to go to rocky for repairs.	Oil leak evident from stretcher traveller. Same problem as last week after repairs.	Unknown	Nothing to report as only an oil leak. No injuries or staff or patient involvement.
18-Feb-17	Vehicle	215	Attempted to reconnect it to roof, alerted OIC	Strip of fluoro lighting on the roof in the treating section of the ambulance has detached from one end. Light still works.	unknown	-
18-Feb-17	Vehicle	185	Unknown. I believe Fault forms have been submitted	Automatic step into rear cabin	Unknown	Due to no step. It's rather a high climb up into rear cabin. I have spoken to this morning, they advise that they fixed a loose wire in the step last week. OIC to take it back today.
18-Feb-17	Vehicle	230	Reported & hand holds in use with the unit clear communication with comms	Main radio won't turn on	Unknown ? Power to unit	-
18-Feb-17	Defibrillator	245	Removed product from service, filed fault report form	Spo2 not working, 12 lead ecg not reading, blood pressure cuff not inflating	unknown cause, found on start of shift inspection	-
18-Feb-17	General Equipment	195	Functioning torches sourced	Only one functioning torch.	??issue with charging bracket	-
18-Feb-17	Vehicle	225	-	Vehicle suction pump not operating, won't turn on.	-	Checked all fuses. Suction motor won't turn on. Portable oxygen/ suction to be used as back up.
18-Feb-17	Vehicle	215	Portable radios being used for last hour of shift	Radio faults as above	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
18-Feb-17	Vehicle	245	Notified roc	Rear air conditioner leaking water out of vents above both patient care stretchers	-	-
18-Feb-17	Vehicle	240	None. Called OC who advised to slowly drive back to station and do fault report.	Loud clunk from rear of car and loss of power on acceleration	First happened when accelerating from stationary into a round about.	Car is drivable but sometimes when taking off from stationary fault continually occurs and car takes a long time to get to speed.
18-Feb-17	Vehicle	240	ROC notified. Vehicle towed.	24ltrs Unleaded fuel put in by error.	Unintentionally put wrong fuel in. 10 hrs into a 12hr shift with no break.	Error recognised prior to starting vehicle.
18-Feb-17	Vehicle	195	RACQ changed tyre	Front drivers side tyre flat	Unknown	Flat tyre now spare and needs to be repaired
18-Feb-17	Vehicle	210	Vehicle taken off road	Rear camera not working	?? Wiring fault	-
18-Feb-17	Vehicle	210	Taken off road	Reverse camera not working, only showing a blue screen when the vehicle is put into reverse	-	-
12-Feb-17	Vehicle	240	Vehicle towed to Mitchelton station, ROC to organise further towing to workshops	Whilst driving at approx. 40km/hr, a notable 'clunk' sound was heard upon further acceleration, followed by a complete loss of power. Vehicle was parked, engine stopped, vehicle locked and restarted multiple times - nil resolution of fault.	Unknown	Turbo Issue awaiting consultation with Mercedes Benz
13-Feb-17	Vehicle	225	-	Stretcher wheel and spare tyre	-	-
13-Feb-17	Vehicle	240	report	Front cabin video screen for rear cabin camera/reversing camera is not operating - no power on unit	Faulty product / connectivity - loss of power	-
13-Feb-17	Vehicle	215	Fault form.	Mobile phone for vehicle charges and works only intermittently. Mains switches are broken, in particular the rear light/drive switch is snapped off causing the rear load light to be intermittently stuck on.	MOBILE PHONE - ? battery issues. MAINS SWITCHES - ? An overzealous person using the mains switches or someone too strong.	-
13-Feb-17	Defibrillator	240	Removed from service and replaced with spare set.	V6 lead not reading.	Unknown	-
13-Feb-17	Vehicle	210	Nil	Passenger side drivers light not working	Unknown	-
14-Feb-17	Vehicle	245	Turned off and on at base still happens	MDT keeps turning off while driving randomly. This happened while driving code 1a the met turned off twice and had to pull over to use alternative gps which delayed on scene time	Unknown	It is sometimes operational but when it randomly turns off it is no longer operational.
14-Feb-17	Vehicle	240	-	side step will not come out	-	-
15-Feb-17	Vehicle	235	-	Dash warning light comes on displaying brake distribution warning	-	-
15-Feb-17	Vehicle	245	-	MDT turns itself off repeatedly during the shift, while vehicle running. Sometimes on way to jobs, other times on way to hospital. Also reversing sensor emits constant screech while vehicle reversing and reversing camera not available while MDT off	-	-
16-Feb-17	General Equipment	210	-	All zippers broken not not functional.	-	-
16-Feb-17	Vehicle	225	Truck driven to Crows Nest ambulance station and swapped with another vehicle. OIC notified.	Vehicle operational at beginning, side step non-functional. Drove to Toowoomba and back to Crows Nest. Battery light turned on, power steering stopped working. Vehicle checklist not submitted yesterday due to workload. Vehicle speedometer unknown.	?Drive belt broken	-
15-Feb-17	Vehicle	180	have removed panel and will repair or replace.	Control panel fault, moisture inside panel. Rear compartment, front drivers side panel.	Unknown how moisture entered.	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
17-Feb-17	Defibrillator	230	Interchanged the lead/pulse oximeter with a working one but will still not work (both sections). OIC informed.	Pulse oximetry not working/ won't read.	-	-
17-Feb-17	Stretcher	230	Stretcher tested at scene and taken to Nambour brakes during shift. No spare. Swapped with spare at NGH	Stretcher failed to remain on lowest height foot end.	Unsure, stretcher moved through higher cogs and appeared to lock into lowest cogs before collapse to ground on foot end	-
18-Feb-17	Vehicle	185	SOS notified and vehicle to go to rocky until problem fixed.	Airway seat seatbelt locked and not retracting.	-	Rest of Car operational we will not put any persons in that seat. V NUMBER TO BE ADVISED TO
18-Feb-17	Vehicle	210	fault report	Oil leak evident from stretcher traveller.	Unknown	-
18-Feb-17	Vehicle	215	Advised roc	Small crack in windscreen on L hand side	unknown - was there when we logged onto shift	-
18-Feb-17	Vehicle	245	Notified roc	Inverter keeps tripping with mansell neo cot plugged in while the vehicle is travelling at 100km/hr when inverter reset it keeps tripping mansell neo cot. Previous fault report submitted for same problem.	Apparently advised operator error but not operator error actual fault with inverter considering car was travelling between hospitals at the time and the same in this case.	-
19-Feb-17	Vehicle	245	Reported via this fault form	C size oxygen draw broken latches causing loud banging noise when travelling greater than 60km/hr	Unknown found at crew inspection	-
19-Feb-17	Vehicle	195	-	L scan light US, R outer bonnet mounted red strobe US	Unknown, unknown	-
17-Feb-17	Vehicle	235	-	Rear camera displays blue screen only	unknown	-
4-Feb-17	Vehicle	245	FAULT REPORT	LEFT HEADLIGHT BLOWN	FUSE?	5297 Left Head Light has been blown for over the past 2 - 3 weeks, unsure if a fault report has already been generated. This still requires actioning as it's dim at night with only one head light.
6-Feb-17	Vehicle	230	-	large chip in bottom of windscreen - drivers side	unknown	Vehicle going to for servicing tomorrow 07/02/2017
6-Feb-17	Vehicle	210	Unable to rectify	Side door corpuls bracket doesn't lock into stowed position	-	-
6-Feb-17	Vehicle	180	-	Left Back door - Hinge section loose	Door guide between hinges has come off, preventing it to open further instead of as it is designed to open to its specification limit	-
6-Feb-17	Vehicle	210	Notified - mechanic will attend Station tomorrow to rectify problems	Vehicle will only start by auxiliary start only. - defibrillator rails in grab and go locker would not go back in without manual assistance.	-	-
7-Feb-17	Vehicle	225	Mechanical service rectification required on parts, steering and AM/FM radio head unit. Parts on order by repairer. vehicle is still operational for use. Prevenative maintenance.	6 Month Service and Inspection. Inspect non operation AM/FM Radio unit - Blank Screen.	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
6-Feb-17	Stretcher	225	Stretcher has been removed from service and replaced.	Stretcher collapsed while loading patient.	Not known. Stretcher had been checked by QAS (driver) at the time of lowering the stretcher in the pt's driveway.	Stretcher checked a cleared for full duty.
6-Feb-17	Vehicle	215	Spoke to mechanic late today who advised to bring in tomorrow - at this time fault was only intermittent, by 2000hrs fault was constant.	Rear door sensors constantly activating which means rear emergency lights constantly flash.	-	-
7-Feb-17	Vehicle	235	-	Was allocated this vehicle from SOS Ipswich for replacement of 602667 (broken down)... Informed next day that it was also unoperational? Noted side doors (when unlocked) would not open on button - must use turn access..	-	-
7-Feb-17	Vehicle	205	Booked for service 15/02/17	C Service	-	-
7-Feb-17	Vehicle	205	Booked in for 14/02/17	D Service	-	-
7-Feb-17	Vehicle	240	OIC notified, accident claim form completed.	Minor damage to top rear (R) side of vehicle. Dent sustained during slow reverse into low lying gutter of house whilst setting up for difficult extrication of pt. No issues with opening/ closing rear doors. Nil damage to property.	Low level gutter.	-
7-Feb-17	Vehicle	240	-	Battery changed	-	-
7-Feb-17	Vehicle	235	-	Right front headlight blown	Electrical	-
8-Feb-17	Defibrillator	250	Removed from service	blood in section 2 electronic area, may have got into battery area or	No fault reported yet , unable to get blood out. on cleaning keeps running red	corpuls will be moved to coolangatta station for engineer visit 9/2/17 to be checked
8-Feb-17	Vehicle	185	Also as above	Second car radio keeps powering on and off. This makes the portables not work. Changed the second car battery that powers this radio. The battery was faulty however the fault is still present. Might be a faulty power connection to the radio.	As above	I put no because it powers off e wry 10 seconds intermittent. ACTION TO BE TAKEN:- OIC TO LOG A BOSS JOB FOR PSBA TO INSPECT THE VEHICLE IN CAIRNS.
9-Feb-17	Vehicle	240	None	Passenger rear mud flap damage/split	Unknown	-
9-Feb-17	Vehicle	245	PST changed globe	Blown left headlight	-	-
9-Feb-17	Vehicle	230	-	Removable container for bin liner of the bin from rear compartment is missing and requires replacing in order to be able to safely remove its rubbish.	-	-
9-Feb-17	Vehicle	185	-	Rear left door, broken latch that keeps door open at 90degrees.	-	SMITHFIELD OIC TO ARRANGE FOR UNIT TO GO TO FOR REPAIR. V 5236.
9-Feb-17	Vehicle	185	Waited a few hours and turned car back on and it worked, however if occurring on jobs the car will not be secured.	Front passengers window automatically goes down and is intermittent in going back up.	Unknown	SMITHFIELD OIC TO HAVE UNIT TAKEN TO FOR REPAIR. V 5235. VEHICLE HAS BEEN DECOMMISSIONED.
13-Feb-17	Vehicle	195	Marked out of service. Fault form completed.	Officer driving vehicle at time at completion of shift. Went to drive into gate at rear of station. Noticed was too close to R side of vehicle due to double stretcher turning circle. Went to reverse out of driveway to realign. continued below	R sided mirror collided with yellow swipe post. Has collided, and ? Swung back to crack mirror with ? Hyper extension of review mirror joint.	-
13-Feb-17	-	250	-	Vehicle 6551 left headlight out	-	-
13-Feb-17	Vehicle	250	-	Left side headlight out	-	-
14-Feb-17	Vehicle	225	-	Windscreen chips, not repairable.	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
14-Feb-17	Vehicle	240	Air conditioner turned off and floor mopped up	Air conditioner vent in the rear compartment is leaking water	-	Monitor AC. Nil further issues reported
14-Feb-17	Vehicle	215	N/a	1- Occasional irritating feedback noise from (we think) the air con unit. It is unpredictable, suddenly occurring numerous times within a short period.	Unknown	-
13-Feb-17	Vehicle	215	notified	2- the back door frequently will not open from the outside, requiring an officer to open from inside.	-	-
14-Feb-17	Equipment	215	Radio left with oic	front module airconditioner not working	-	-
14-Feb-17	Vehicle	185	Radio left with oic	Caused feedback when transmitting	-	-
14-Feb-17	Vehicle	185	Notified OIC	A clunking sound can be heard coming from front right hand side of vehicle, as well as a vibration being felt through the accelerator pedal.	V 5270.	-
14-Feb-17	Vehicle	235	None able. Attempted to rectify situation by reversing vehicle and manual removal of stone w no success	Small crack in middle of windscreen. Does not obstruct view of road.	Stone thrown up from car hit windscreen.	-
14-Feb-17	Vehicle	230	None able. Attempted to rectify situation by reversing vehicle and manual removal of stone w no success	Suspected large stone caught in front drivers side brake calliper .. loud screeching noise when driven	See above. Was driven on dirt road at time of occurrence	-
14-Feb-17	Equipment	185	None	Duress camera system in unit 7172 randomly turns on. Unable to turn off. Also the reversing alarm when reversing remains constantly on. As if your running over something.	Unknown but these things have been occurring since duress camera install	V 5270.
15-Feb-17	Vehicle	225	Reported faults	Persistent belt like squeal under throttle, Left sliding door catch not automatically engaging to hold door open. Emergency light mount, bottom of windscreen loose on left side.	General wear and tear.	-
15-Feb-17	Vehicle	230	-	Reverse camera not working	t	o check camera otherwise report to OSU
15-Feb-17	Vehicle	230	1/ The "Pole" is not safe to use, & will result in a fall from the rear of the vehicle. No action to rectify this fault is possible & will require the workshop to repair	1/ Rear yellow "grab pole" has fractured between the pole & mounting flange. 2/ Rear, forward facing Attendant seat armrest loose	1/ possibly caused by movement & vibration between upper & lower cabinets. 2/ General wear & tear has loosened the mounting screws of the Attendant seat armrest	The pole is only used when entering the rear compartment from the rear of vehicle. This entry is a hazard, so all entry is via the side door
15-Feb-17	Vehicle	215	reported veh off road	burning smell from engine coming through to drivers compartment no visible reason	no	-
15-Feb-17	Vehicle	245	Replaced with officer's own unit.	Garmin Portable GPS continually shutting down, requires re-start and re-programming. Unit requires replacement.	Age of unit	-
16-Feb-17	Equipment	235	towel and air dried	Pager not working	Pager was accidentally dropped into a esky full of water at Ipswich Hospital	Left in OIC pigeonhole
15-Feb-17	Defibrillator	250	Removed from service, fault form completed	monitoring dropping in and out	Unknown	-
16-Feb-17	Stretcher	240	-	stretcher fault. No power to base. Unable to load or unload.	Power failure	Unit 501232
16-Feb-17	Vehicle	240	-	Despite been on charge vehicle won't start	-	-
17-Feb-17	Vehicle	210	-	As discussed with on Friday, reverse camera sensors constantly beeping. Slight dent on rear step piece that could be the cause of the sensors being out of position. Tried to reposition sensors in the past, but it keep on doing the same.	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
17-Feb-17	Vehicle	210	Nil. Door needs to be opened fully to latch on magnet on side off vehicle to remove and place stretcher back into vehicle safely.	Left back stretcher entry doors latch broken as discussed with on Friday. Door does not stay open When latched. Waiting for new part at to fix vehicle.	-	-
19-Feb-17	Vehicle	245	attended and repaired	Blown L headlight	-	-
19-Feb-17	Vehicle	185	SOS notified, vehicle incident happened at the front of Gordonvale station, vehicle back in Gordonvale plant room	Vehicle seems to be in limp mode, not able to go faster then 40kph. Vehicle was being driven when accelerating up to speed limit there was a crack/clunk sound herd and vehicle would not accelerate above 40kph.	? broken drive belt of some description, there is a slipping sound coming from the engine bay area	V 5275 vehicle being towed to workshop this morning
19-Feb-17	Vehicle	210	Nil	R) headlight out	Unknown	-
19-Feb-17	Vehicle	235	-	Engine light started flashing when proceeding on a case	-	-
20-Feb-17	Vehicle	215	Drop in to servo to add air to tyre	Slow leak in passenger side rear tyre needed to have 15psi added during shift	Unknown	-
20-Feb-17	Vehicle	235	oic emailed & sent photos	corpuls charger broken and not charging corpuls, Needs to be replaced	No	-
19-Feb-17	Vehicle	210	-	Windscreen washer function not working - water not getting through	Found when using vehicle on loan.	-
20-Feb-17	Defibrillator	195	Removed and re-inserted ecg leads from machine. Reconnected ecg leads to patient, used new ecg electrodes out of unopened packed	Attached all 12 leads and only lead 2 appeared on screen. Unable to gain 12 lead.	Maybe faulty leads or internal error with machine	Attempted to replaced leads once back at station, unsure of whether this was successful. However, surely with less then 12 months use, the leads need replacement.
20-Feb-17	Vehicle	195	-	Side step feels unstable when standing on. Corner and one side of step appears to have been damaged previously. Step is still operational.	-	-
21-Feb-17	Vehicle	215	-	Spo2 missing from corpulse, one of the LED light strips coming off the roof in the back. Also the corpulse bracket is very loose.	-	-
21-Feb-17	Stretcher	215	Taken out of service for assessment.	Stretcher would not raise to full height - carrying 207kg pt on RFDS bariatric stretcher and bridge with equipment.	Weight	-
21-Feb-17	Vehicle	225	Arrange with OIC to get a wheel alignment and suspension check tomorrow. The vehicle has been taken off road tonight	Suspension problem	While proceeding on a code 1 I was manoeuvring around heavy traffic when I clipped a traffic island. The angle of the impact felt hard causing the car to lurch. The car still steers straight however the front left wheel seems to be angled inwards at the t	-
22-Feb-17	Vehicle	240	Notify OIC	Fault light illuminates on dash, queries brakes	Unknown	Nil
22-Feb-17	Vehicle	240	-	Unit lost power during operation previous day, now won't charge at station, keys won't start engine	-	-
23-Feb-17	Vehicle	230	OIC, COMMS notified	Rear aircon not working.	Temp set too low to reset aircon.	-
23-Feb-17	Defibrillator	245	OIC provided replacement kit	The zip at the blood pressure end, the tab has broken off.	-	-
23-Feb-17	Vehicle	215	Inform OIC vehicle to be taken to auto electrician next week.	Rear switch panel Not working	No	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
24-Dec-16	Defibrillator	235	Replaced faulty BP cable on 03-01-2017. Corpuls operational.	Connector which joins the BP cuff to main hose is crushed on hose side. BPcuff will not lock into connector.	-	Monitor/ defibrillator works ok. Need to use manual BP cuff.
19-Feb-17	Vehicle	215	Reported	Rubber seal from rear drop down door (L side) has partially separated from unit.	Unknown	-
19-Feb-17	Stretcher	240	OC notified and fault form completed - no SHE report completed as nil need to	Stretcher not unlocking properly - difficult to unlock stretcher. Mechanism located within vehicle does not appear to be locking when removing stretcher from vehicle. Lifting arm does not appear to lock when attempting to load stretcher into vehicle	No idea - query due to the weight of pts transported	As noted no SHE report completed as no near miss or incident occurred whilst using stretcher. repaired pins in power load.
19-Feb-17	Vehicle	225	Vehicle taken off road	Air conditioning unit fell from ceiling while transporting a pt	-	-
19-Feb-17	Vehicle	195	Use of secondary driving lights	Front passenger headlight not functioning. Warning on dash	-	-
20-Feb-17	Vehicle	235	Vehicle removed from service.	Patient module unable to be locked, module entrance door. Previously defected for same as unable to secure vehicle with drugs onboard. Rear air conditioner not working again.	-	-
19-Feb-17	Vehicle	245	Reported	A/C not working in rear of vehicle	-	-
20-Feb-17	Vehicle	185	Fault form	Duress camera blue screen only and ad fan performing low	.? authority V 5285.	-
22-Feb-17	Vehicle	205	Booked in for service 22/02/17	D type Service	-	-
21-Feb-17	Vehicle	250	INSpected by QAS mechanic. ADvised to put out of service and notify OIC to arranged tow back to repairer who put new one on 2 weeks ago	Side step not retracting back in	UNKnown	-
21-Feb-17	Vehicle	210	-	Rear door not opening from outside of vehicle. Officers required to open door from inside of vehicle.	-	-
21-Feb-17	General Equipment	225	-	Defib cradle not charging the defib. Need cradle repair	-	-
22-Feb-17	General Equipment	210	-	Not working - after making sure that torch had been sitting in charging station correctly, still not working after 24 hr on charge	-	-
22-Feb-17	Vehicle	215	Comms notified taken to for repair	Won't start racq called taken to	-	-
22-Feb-17	Stretcher	240	None, no field of expertise in repairing this fault.	Bottom portion = The front legs will not lock after second docking point unless red lever is physically locked.	No, newly serviced stretcher	Stretcher serviced morning of 22.2.17. Crew found to be faulty after service and swapped with spare. Did not use prior to swapping.
22-Feb-17	-	240	Tried turning the car off and on as well as inspecting the MDT however the MDT did not power up.	MDT not operational.	-	This car has had issues with the MDT in the past.
22-Feb-17	General Equipment	235	SOS contacted informed.	Today, Back roller door only working manually. Not activating with ANY of the remotes. (battery changed in rear door remote on wall but still nil activation afterwards.)	unknown	rear roller door is usable but can only activate once in station manually. This is a problem for EA station that EA officers may need to access stn for quick restocks whilst on call.
22-Feb-17	Vehicle	245	temp fix waiting repair	Unit 5165 has a problem with the suction unit. The white bracket accommodating the red suction housing had been installed too low by the manufacturer. This results in the suction hose being occluded	vehicle design	-
22-Feb-17	Vehicle	210	Notified OIC	Air conditioning unit overhead in module is cracked/screws missing/falling off roof	-	-
22-Feb-17	Vehicle	200	-	Car entered limp mode on code 1. Car would not go over 50km/hr engine light flashing. No obvious cause	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
22-Feb-17	Vehicle	245	-	Car difficult to start - requires accelerator to engine to turn over. When slowing to stop car turn off however lights/electrics still on. Side step not working.	-	-
23-Feb-17	Other Equipment	215	-	Not turning on ?not charging in cradle	-	-
23-Feb-17	Other Equipment	215	-	No pages recieved	-	-
23-Feb-17	General Equipment	215	Nil	Doesn't work	-	-
9-Feb-17	Vehicle	240	-	Screw located at n rear right tire, causing tire to leak.	Screw in rear right tire	MN OC NOTIFIED, NOTE LEFT ON VEHICLE ADVISING VEHICLE NOT OPERATIONAL.
9-Feb-17	Vehicle	245	-	5025 won't start, clicking noise when turning over	-	-
9-Feb-17	Vehicle	210	defected the vehicle	Rear air bag suspension is not working - not inflating constantly deflated causing rough ride - no comfort.	day shift did not report any thing, but first case on night shift the vehicle drive to hospital with pt on board (walked into ambulance) the air bag was down and very rough ride. no compressor noise heard at all	when arrive back on Nth Rton station the compressor was audible attempting to pump up the airbag suspension extremely slowly. changed into 2263 for rest of shift
10-Feb-17	Vehicle	245	Notified opcn	Inverter want turn on keeps flickering when testing at start of shift	Unknown	-
10-Feb-17	Vehicle	245	Notified opcn	Inverter want turn on keeps flickering when testing at start of shift	Unknown	-
9-Feb-17	General Equipment	235	We checked once enroute with pt on way back through but cord had been taken. Acting OIC Rosewood informed -SOS informed via OIC.	Lost vehicle electrical cord	After unplugging from unit 6643 to go on a job, cord must have got caught on departure in back top lighting framework of 6643. Not visualised by me, CCP officer saw cord on rd at roundabout. All on code 1, unable to stop. Not there later enroute.	-
3-Feb-17	Vehicle	230	OIC advised.	Metal Stretcher strike plate on drivers side of rear cabin is not fitted correctly. Screws and plate are lifted and catching on the stretcher wheels when unloading stretcher.	Incorrect attachment to vehicle or cabin movement has loosen the fitting.	This fault picked up as Stretcher fault fail in vehicle check. Fault is actual a vehicle fitting fault and not a stretcher fault.
10-Feb-17	Vehicle	185	-	Xband radios intermittently turning off. Appears to be random times.	? Power issue	Comms notified that portable contact may be intermettan. A/OIC to log a BOSS job to have radios looked at by PSBA.
10-Feb-17	Vehicle	210	-	Vehicle stretcher locking mechanism unit leaking oil on floor.	-	-
10-Feb-17	Vehicle	215	Organised repairs with the 16/02/16.	for 120,000 km service due. Also emergency lights mounted on bonnet are working, however both are dim.	Unknown.	-
10-Feb-17	Vehicle	215	Fault form and OIC notified.	Screw/nail in cars rear left tyre.	Crew drove over the screw/nail?	-
11-Feb-17	Vehicle	235	See previous report	Outstanding faults have not been fixed?????. Toggle switches and drivers seat	See previous report	Just.....
10-Feb-17	Vehicle	245	None at this stage. attended and screwed unit to roof.	The overhead aircon unit in the rear of the vehicle has begun to separate and come off the ceiling of the vehicle.	-	-
11-Feb-17	Vehicle	235	Has been reported multiple times, still not resolved.	MDT CONTINUES TO SHUT DOWN AND RADIO ENTER's MAINTENANCE MODE WITH A RED SCREEN AND IS NON FUNCTIONAL.	?? Voltage issue. When vehicle is off 240volts for any period of time on cases the MDT and radio enter a low power state even with the vehicle running with the idle hold engaged. They only come back on after a period of 10-15mins of driving.	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
11-Feb-17	Vehicle	210	Various changes were attempted including internal and recycled air, changing fan speeds, and temp setting, turning on and off rear and front A/C seperately, to no avail	A/C faulty. When left idling the A/C will cool normally. Once car is being driven the A/C blows only hot air. Car was used for 6 hours and coolest rear cabin reached was 38 C down from the initial 43 C. Front cabin was like a sauna.	Unknown	Mechanically vehicle is OK and can be used, if required. Will only be used if necessary.
11-Feb-17	Vehicle	195	-	Back door is not central locking- the mechanism seems to have slipped and do will sometimes not open. There is also no rear view mirror . And no waste bin in the back which s unhygenic.	-	-
11-Feb-17	Vehicle	230	Have tried to return seat to neutral position....won't go	front passenger seat stuck in a forward position	Seat slid forward to get to MDT reset switch	-
11-Feb-17	Vehicle	185	Unable to rectify the problem	Automatic step on the patient care entry is faulty.	Unknown	V 5259.
11-Feb-17	Vehicle	185	Fault form completed	Automatic side step for patient care entry is not working. Faulty	Unknown	V 5259
15-Feb-17	Vehicle	240	-	Drivers seat back rest adjuster dial broken	-	-
16-Feb-17	Vehicle	210	-	Front indicators not working/ no bulbs	-	-
17-Feb-17	Vehicle	225	Contractor notified fault report completed and staff made aware of issue	Intermittent reverse camera function	-	Repair booked with contractor for March 2 with service
16-Feb-17	General Equipment	210	Nil. Will call CQ readiness coordinator post fault form. Emerald station has spare.	Piece missing from extension joining leg to yellow ferno scoop stretcher.	Unknown. Scoop found post cleaning of significant RTC scene broken.	-
17-Feb-17	Vehicle	210	Defect notice and OIC will orgniase for it to be reviewed locally.	Streamlight 20XP - LED. Both in car Torch chargers are non-operational. Do not charge torches when batterys are dead. No lights active on torch charger system.	Poor contact / loose wiring / may require refitting.	One torch is charged / alternative torches can be access.
15-Feb-17	Stretcher	240	Removed from service and reported to contractor for repair	Head end does not click in when lowered at every available level	-	Stretcher was from a Caboolture Vehicle who collected a spare from Roma Street
17-Feb-17	Vehicle	240	Turning the car on and off again	Engine light on	-	-
17-Feb-17	Vehicle	245	-	No phone, one pager, one set of keys, empty o2, no stock in drug kit	-	-
17-Feb-17	Stretcher	230	Defect report; defect tag placed on stretcher; Out of service	Unknown	Head end of stretcher collapsed (second lowest setting from ground) as patient sat on stretcher.	-
17-Feb-17	Vehicle	225	Nil at this stage.	Blue flashing light on bonnet is not working.	Blown bulb.	-
17-Feb-17	Vehicle	240	The technician has looked at the problem a few weeks ago	Comms advise that they are not able to track the vehicle on their system	-	-
17-Feb-17	Vehicle	240	Vehicle Fault Report	Drivers seatbelt does not tension and retract properly	Unknown	Seatbelt not retracting could be unroadworthy
17-Feb-17	Vehicle	240	-	Right headlight out	-	-
18-Feb-17	Defibrillator	210	-	CF card almost full	-	-

RTI Released

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
18-Feb-17	Vehicle	195	tried override switch, tried wriggling and pushing/pulling, does not move at all	side step not working (not even making a sound)	found unoperational on start of shift	-
19-Feb-17	Vehicle	240	-	Squeaking vibrating noise when turned on. ? Like fanbelt noise	Just started when car turned on at beginning of shift	-
18-Feb-17	Vehicle	215	-	Engine hard to start unit lacks power outside turbo rpm range	-	-
19-Feb-17	Defibrillator	210	fault form	No Paediatric BP cuff in monitor, unable to locate in vehicle	missing	not currently using monitor, able to use monitor from other vehicle
19-Feb-17	General Equipment	210	fault form	Torch on drivers side not working	faulty	-
20-Feb-17	Vehicle	240	Attempted to clear tracks of debris, and extend/retract using switch.	Vehicle side step stuck - not deploying. No issues with step earlier in night.	-	-
20-Feb-17	Vehicle	215	None	Side step not working.	Not known, discovered at start of shift.	-
20-Feb-17	General Equipment	240	FEO replacement arranged	The wall mounted airway kit/bmv kit is unable to be secured safely, potential missile objects	Unknown, ? Magnetic strip that would normally secure it is missing??	-
17-Feb-17	Vehicle	230	referred to so as they can organise repair	crack on windscreen- drivers side. Approx 8-10 cms long.	-	-
20-Feb-17	Defibrillator	210	Spo2 cord has been re plugged in. Still not working	Spo2 monitor not working	-	-
21-Feb-17	Defibrillator	195	Taken out of service	Intermittent operation of defib. Also, a clicking noise in the defib once shock delivered	-	-
23-Feb-17	Vehicle	215	OIC ,fleet informed booked into auto electrician next week	Both rear main switch panels not working in rear compartment including suction.	Unknown	-
24-Feb-17	Vehicle	210	As above+ this report	Siren and warning devices not sounding	Fuses checked but unable to detect fault "? Relay, or fusable link or wiring	-
24-Feb-17	Vehicle	225	-	Aircon not working in rear. Ride extremely jarring for pts and paramedic... ? Airbags inconsistent or Shock absorbers not working.	-	-
24-Feb-17	Vehicle	210	Fault form and left the faulty one in he oic tray	Torch is missing and the only one present is broken	Found on vehicle check	Used the ones from 2263 for the night shift
24-Feb-17	Defibrillator	200	Taken out of vehicle to be charged via extension cord	Not charging in vehicle, tried charging in another vehicle and did not charge	-	-
24-Feb-17	Vehicle	250	Restart and turn car on and off.	Emergency lights and modal power control in front of vehicle not functioning from 2200	Unknown	Vehicle plugged in but not turned on (flat batteries).
26-Feb-17	Vehicle	185	-	Stitching failed on base of passenger seat, foam exposed, roadworthy item.	Old age, overdue for replacement	OIC to purchase seat covers for vehicle.
26-Feb-17	Vehicle	205	Vehicle to be taken to workshop on Monday.	Large multidirectional crack in centre of windscreen.	Unknown, vehicle windscreen observed to have several small stone chips at most recent check but today a large defect has appeared.	Vehicle mechanically sound and serviceable. Would probably not pass a roadworthy check but can be used if absolutely necessary.
26-Feb-17	Vehicle	195	-	Vehicle jack storage cover in patients foot well missing. Vehicle jack exposed	-	-
27-Feb-17	Vehicle	240	Nil	Strong smell of burning plastic from unit. No smell detected inside cabin or rear of unit.	Unknown	-
28-Feb-17	Vehicle	185	-	Attendant seat needs t bolted down properly	-	V 5315.

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
1-Mar-17	Stretcher	240	Stretcher replaced with spare at station.	Red Release lever on head end of stretcher not engaging when lowering stretcher, the lever has to be pushed down to lock it in	Unknown	-
1-Mar-17	Vehicle	240	-	Front airbag switch not operating properly it has an intermittent fault. Airbags are not raising up quickly and it is causing for a rough ride in rear of vehicle. Car stereo not working ? Blown fuse. Fuel cap is broken around the edges and needs replacing	Unknown	-
28-Feb-17	Other Equipment	230	-	Mobile phone charger damaged. Will not fit into phone.	-	-
1-Mar-17	Vehicle	225	Informed OIC	Drivers side fog light damaged, plastic cover and globe both broken, not working	not known	Observations suggest might just need cover and globe replaced.
21-Feb-17	Vehicle	240	turn MDT power off/on nil change	MDT error message..... troubleshooting has not fixed it. I've noticed over past few days that 'maps' would not load when I would select 'route to scene'. The MDT was operational at 17:00 going on call last PM....error msg noted this AM at 07:00	nil external USB device has ever been plugged into the MDT. This error message has occurred previously and required a technician reinstall MDT software.	Vehicle sitting at Samford station.. duty officer has logged onto 5402.
21-Feb-17	Vehicle	225	booked in to auto electrician for 27/2/17	Side step of 4WD is non functional	electrical fault	-
23-Feb-17	Defibrillator	250	put back together and now charging however unable to determine if battery fault or just user error.	Patient care box alert with flat battery, trouble shooted and everything taken apart and put back together and still not charging. monitor failed on case. charging post further trouble shoot.	positioning of patient care box in regards to other monitor items	-
23-Feb-17	Vehicle	240	drove vehicle to mechanic	Soft brakes possible low brake fluid - unsafe to drive code 1 and at high speed	low brake fluid or worn brake pads	-
20-Feb-17	Vehicle	225	Nil	Airbag suspension very slow to reset. Air compressor runs for extended time. Rear load hight switch does not work, front switch does	Unknown, possible compressor or airline fault	Officers reluctant to use the lowering mechanism due to having to wait for extended periods to have suspension return to drive height
23-Feb-17	Vehicle	200	Checked fluid levels, no problem identified	Unknown alarm signaling constantly while driving	Not known	The alarm is only sounding post being on E/A, meaning not on charge for an extended period of time. OIC.
23-Feb-17	Stretcher	185	Appropriate people notified, OIC got stretcher back in	During taking the stretcher out the stretcher did not engage and lift and then froze in position approx 40 cm out of vehicle. No green or orange flashing indicator lights were noted to work at any time and manual release did not work	Unknown	Waiting for to allocate job number to so that inspection/repairs can be carried out.
23-Feb-17	Vehicle	200	Duty Officer & Comms have been notified. Duty Officer currently attempting to rectify fault.	Door hinge lock broken on R) back door.	Officer attempted to pull door shut without removing hinge	-
16-Feb-17	Vehicle	245	Was advised to go to for door but can't be fixed. Take a few hours. Mentioned Adair con but I told him I would put in fault report about both.	1. Side Door not opening wires all broken. Was working this morning. 2. Air Con vent if lying in the back is dripping on patients in the afternoon on the Left side. Told Mechanic as we are at about Side door and it apparently has been reported	-	-
23-Feb-17	Vehicle	215	Notified OIC and fault form completed.	Where stretchers sit in unit when locked into place has caused a divet underneath the small wheels, making it difficult to pull stretcher out, it is not streamline as normal to remove stretcher especially when pt is loaded on stretcher.	-	-
23-Feb-17	Vehicle	190	Using over ride switch	Step For Module entrance not retracting when door closed	-	No Visible damage. has been cleaned with pressure cleaner with no results.

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
24-Feb-17	Vehicle	240	-	Low coolant warning. Coolant overflow redo our not serviceable	-	-
24-Feb-17	Vehicle	240	-	Coolant overflow reservoir	-	-
24-Feb-17	Defibrillator	210	-	SpO2 not working	Faulty cable from machine end	-
24-Feb-17	Vehicle	210	-	REAR DRIVERS DOOR LATCH BROKEN. DOOR UNABLE TO BE LATCHED IN THE 1/2 OPEN POSITION.	-	-
24-Feb-17	Vehicle	190	Booked into 4wd cloncurry	Side door not unlocking with key, requires manual unlocking by climbing through rear or front doors	-	-
24-Feb-17	Vehicle	185	Nil	Clip holding stair chair broken.	-	V 5294. Crew will do drive by for repair.
24-Feb-17	Vehicle	185	-	Left side sliding door doesn't always lock into place when opened. Results in the door rolling back onto us.	-	OIC to arrange unit to go to . V 5295.
24-Feb-17	Vehicle	185	-	Left front, electric window control cover missing, unsure if this will further impact its functionality.	-	V 5296. Smithfield OIC to arrange vehicle to go to for repair.
12-Feb-17	Vehicle	245	Taken off road - OC notified - replaced with 501184, equipment from 552 moved to 184. Unable to take for repair (Sunday).	Engine light flashing - unable to accelerate, poor performance, not changing gears.	-	Vehicle had similar incident on 10/2 - taken to who stated issue with air intake sensor - bow to clear fault but advised crew that if it occurred again car would require further servicing.
12-Feb-17	Vehicle	245	Fault form, tyre replaced	Nail in drivers side rear tyre	Nail	-
12-Feb-17	Vehicle	230	OIC sos and opcen notified	Vehicle when in use or not has a strong solvent smell and also comes out through the aircon. Staff and pts have noticed this smell and is causing sickness.	Previous faults to vehicle	Please note, this car was left at CALOUNDRA station yesterday. Please check as it may well still be there and not at Nambour
12-Feb-17	Vehicle	240	-	Front and rear air conditioner (front especially) blew hot air after loading and departing with pt. After clear of pt there was no improvement and OCS notified, who was by chance at RBH. Returned to station out of service for vehicle change	-	-
12-Feb-17	Defibrillator	240	The leads were unplugged and replugged, connections to pt checked	12 lead monitoring of a pt returned a rhythm of vf/vt when the initial 4 lead showed n.s.r. The heart rate was 250+, which was not the case.After disconnecting and reconnecting, the rhythm was still recorded.	-	-
12-Feb-17	Defibrillator	210	complete fault report & taken out of service.	V6 chest lead not recording any data.	unknown.	Out of unit 2288.
12-Feb-17	Vehicle	195	checked fuses all ok notified Fleet Manager and SOS and OCS Notified ROC and despatch, to be taken	Front Air conditioning fan not working, all indicator lights are working and air coming out of vents when moving is cool but little flow. Rear compartment working as normal.	unknown	Vehicle left at Ingham Station for access to repairs.
13-Feb-17	Vehicle	240	OIC informed. Taking	Air Conditioning not working	Nil known	Found to be operator error - switch in wrong posn
13-Feb-17	Vehicle	240	vehicle to Zupps	Fridge not working	-	-
11-Feb-17	Vehicle	245	This report	Drivers side headlight not functioning.	Burnt bulb is my guess	-
13-Feb-17	Defibrillator	240	Oxisensor has been replaced	Defective oxisensor	-	-
13-Feb-17	Vehicle	210	Replacement bulb purchased from and replacement bulb fitted.	Blown passenger side low beam bulb. Bulb blew while in use this morning	-	-
12-Feb-17	Vehicle	240	Oic advised	Fridge in vehicle not working. Switch seems to be tripping.	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
13-Feb-17	Vehicle	195	manual latch operating correctly as a temporary workaround	Side access door electronic opener not engaging locking/unlocking mechanism	-	-
13-Feb-17	Vehicle	195	Cleaned printer head, checked printer door. OK still occurring intermittently	Corpuls 3 not printing correctly. ? printer jam.	-	Fault cannot be reproduced
14-Feb-17	Vehicle	210	Fault form	Defib door closed but control panel says open door. Internal dome light not working inside panel next to attendant seat	Resubmit fault form from last week when found	-
13-Feb-17	Vehicle	215	-	Broken light indicator is on. The broken light is believed to be the L) tail light	-	-
14-Feb-17	Vehicle	240	OIC has been notified.	Right hand arm rest foam on patient care seat not there, and driverside back door latch on inside of vehicle is broken. Photos have been sent to OIC.	-	Photos have been sent to OIC.
16-Feb-17	Vehicle	225	mechanical will service	Service due	-	-
14-Feb-17	Vehicle	245	MDT initially reset after 1st activation - however advised by Comm Centre it continues to self activate every few minutes.	MDT fault - continuous self activation of duress alarm	-	-
14-Feb-17	Vehicle	195	SOS notified and crew returned to station to change vehicles.	ABS and breaking warning lights appeared during transport for first case. SOS notified and crew returned to station to change vehicles.	-	-
15-Feb-17	Vehicle	235	Out of service	Known fault - interior lights not working and defib not charging	-	-
17-Feb-17	Stretcher	240	Replaced and Removed from vehicle. Fault report.	Head end - when lowering stretcher a lot of force is required to initially adjust the height as it seems to be sticking.	Unknown.	no fault occurred - noted by crew to be sticking
20-Feb-17	Vehicle	205	contacted. Current servicing centre is no longer doing the servicing on QAS vehicles	Service B required	-	-
21-Feb-17	Vehicle	195	-	Attendant seat seatbelt non operational	-	-
20-Feb-17	Vehicle	240	OIC notified.	Wall mounted suction isn't working. MDT doesn't get signal in plant room, Narangba area, Wavell Heights (multiple streets), Chermside (Gympie road and Webster road, Rode road), Nephrocare. MDT's in other vehicles are able get reception in these areas.	-	Suction is not operational.
20-Feb-17	Vehicle	195	taken to RACQ pads checked 7mm , with new pad ordered	Brake sensor	water & wear	awaiting new pads
18-Feb-17	Vehicle	200	Reported to OIC	Sat Phone is not operational, BGAN - error, " Sattilite not found". Sattilite on top of the vehicle is not appear to be working, (nil sound)	-	Vehicle is still operational.

Request Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
21-Feb-17	Vehicle	230	Fault report. Front air conditioning switched to recirculated, didn't make much difference	Rear air conditioning not cooling effectively, front also to a degree.	-	-
21-Feb-17	Vehicle	215	Vehicle off road due to stretcher	Unable to extend seat belt on pt care seat. Seat belt jammed	-	-
21-Feb-17	Vehicle	235	N/A	Sliding door intermittently not opening from outside	Unknown, temporarily self-resolved	-
21-Feb-17	Vehicle	225	Comms notified, moved to 3366 for remainder of shift. Fault form completed	Radio not working, double beep followed by error message 'antenna problem'. Comms stating they receive transmission with nil audible voice	unknown	Fault cleared on radio - nil issues since
22-Feb-17	Vehicle	215	Fault form competed. OIC and Comms informed	Pager not receiving pages	-	-
22-Feb-17	Vehicle	195	Nil	Vehicle fridge not functioning	unknown	Vehicle is operational.
23-Feb-17	Vehicle	225	Vehicle placed out of service until a technician can inspect and rectify.	Brake fluid reservoir below minimum and brake warning light activated.	-	-
23-Feb-17	Vehicle	240	take to mechanic	Low brake fluid brakes feel soft unsafe to drive code 1 not engaging/disengaging correctly in vehicle, not lowering/raising wheels when loading/unloading from vehicle	Possible low brake fluid brakes feel soft	-
19-Feb-17	Stretcher	245	manual override	Low engine Oil light remained alluminated all shift.	unknown	6467 OOS
24-Feb-17	Vehicle	245	Fault Report submitted	5297 pagers not going off at Station. only mobile phones.	-	-
25-Feb-17	Vehicle	245	-	Engine light flashing. Speed will not exceed 60 km/h.	-	-
25-Feb-17	General Equipment	195	Sourced working torch from other operational vehicle	Torch Inoperable	? Battery pack	-
25-Feb-17	Vehicle	245	OSU attended and repaired	Nil power to MDT	Broken cable and blown fuse	-
26-Feb-17	Vehicle	240	Spoke to ROC, take back to station	Alarm sounding after trying to get the inverter to work	Unsure	-
26-Feb-17	Vehicle	235	-	Vehicle off road due to MDT not working. Would appear the battery isn't charging	-	-
27-Feb-17	Vehicle	240	Contacted OIC AND ROC RACQ to start battery and to be driven to Caboolture for battery change	Dead battery at hospital	-	-
27-Feb-17	General Equipment	240	OIC advised. OSU advised. OpCen advised. Isolation switch reset with no result	MDT not functional. Not turning on	Unknown	-
27-Feb-17	Vehicle	240	Inspected by service provider who need to order appropriate e part/s	Warning Light - Battery/Alternator visit workshop	? Faulty alternator	-

RTI RELEASE

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
27-Feb-17	Stretcher	185	Out of service at	Legs would not retract unit 7158	Unknown	She to follow shortly associated with case at TO ISSUE CAIRNS A WORK ORDER SO THAT INSPECTION/REPAIR CAN BE UNDERTAKEN.
27-Feb-17	Defibrillator	235	-	Spo2 fault at connection	-	Toogooloowah monitor at rosewood station in 6662
28-Feb-17	Vehicle	245	OIC notified	Rear door right hand side not latching. Latch pin on the yellow handle (attached to the door) broken. Found this way at the start of shift.	-	Vehicle is due for service at PST tomorrow.
27-Feb-17	Vehicle	185	Try to turn off camera head unit in the front - unsuccessful. Tried to turn off vehicle ignition, but turns back on when vehicle restarted.	Retrofitted rear cabin camera will not turn off once it has been activated, even after the vehicle has been turned off and on again.	unknown	OIC to have unit taken to . Advise repairer to contact for advice if he needs it. V 5322.
28-Feb-17	Vehicle	225	-	1) The reversing camera screen remains switched on constantly a bright blue. It still works as a reversing camera screen when you select reverse, but goes back to bright blue screen when not reversing. 2) Crack on the right lower windscreen.	-	-
28-Feb-17	Vehicle	240	Nil	Rear step is unsteady	Went up steep driveway of ? Caught back step whilst doing so.	-
1-Mar-17	Vehicle	245	-	The reversing camera not functioning. FM radio not functioning	-	-
21-Feb-17	Vehicle	225	Inspected for visible damage, nil evident	Passenger Side Bonnet Beacon Light Not Functional. Vehicle Still Operational.	n/a, observation of daily vehicle checklist	-
23-Feb-17	Vehicle	210	Unit taken off road	Aux power faulty. Not charging despite being plugged in or idle hold. Car radio kept turning off. O2 kit leaking unable to find leak. Kink visible in hose.	-	-
24-Feb-17	Vehicle	205	Requested replacements approx 6 months ago from CW LASN Manager, Business Support	Damaged bullbar indicator covers.	-	Frequently damaged item from minor kangaroo strikes + airborne stones when passing vehicles on unsealed roads.
24-Feb-17	Other Equipment	240	Nil	1. Siren has no mixed mode - possible speaker failure 2. Interior lights in patient compartment, failure of several lights	Failure	-
24-Feb-17	Vehicle	225	Reported	Step makes grinding noise when deploying. Fridge fan makes noise when switched on but will get cold over time.	Unknown	-
25-Feb-17	Vehicle	240	-	Passenger sun visor broken	plastic clip holding in bolt snapped when opening visor	-
26-Feb-17	Vehicle	210	Nil	Water dispenser on windscreen wipers not working	Has not worked past few days	Can't find fault
26-Feb-17	Vehicle	245	Completed defect notice	Front right hand wheels of stretcher bent continuing to rub when pushing stretcher found this fault while conducting stretcher check Prestart inspection and also advised by night shift that wheel squeaking and difficult to push.	Brakes left on while loading stretcher	-
26-Feb-17	Vehicle	240	OC Contacted and vehicle taken off road	Intermittent siren and possibly lights unable to respond under Code 1 conditions	No idea	Intermittent sirens whilst driving Code 1 unsure if beacons are cutting out as well however due to officer safety this vehicle taken off road.
26-Feb-17	Defibrillator	210	-	SpO2 not working	-	-
26-Feb-17	Vehicle	185	Contact SOS RACQ attended and changed with spare. OIC to repair tomorrow	Slow leaking tyre, rear left	-	Mossman OIC taking tyre to for repair even date. V 5314.

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
26-Feb-17	Vehicle	215	-	?? loose steering arm/sway bar in front L wheel. Broken D cylinder securing screw on bracket.	-	-
26-Feb-17	Defibrillator	195	-	BP cuff does not work. It inflates but then comes up with error "pneumatic blockage". This occurred with both the red and blue cuffs.	-	-
20-Feb-17	Defibrillator	240	-	CF card almost full.	Use.	Still in operational circulation.
27-Feb-17	Vehicle	250	Nil	Drivers side rear door stay broken off. Door cannot be secured open.	-	In windy conditions the door can swing open quite fast and cause significant injury to officers or bystanders.
27-Feb-17	General Equipment	245	-	In car torch not working - doesn't appear to be charging whilst in car.	-	-
27-Feb-17	Vehicle	240	OIC notified & truck seen to by mechanics at	While driving out the 3rd roller door of Sandgate station, we stopped to enter an address for the job we were proceeding to and the roller door has come down onto the middle of the truck (denting the aircon cover).	Possible fault with the roller door sensor	-
27-Feb-17	Vehicle	185	-	Rear aircon fans not working, aircon seems to cycle on, but no air moved, no noise from the fans. Settings on display indicate a/c working.	-	V 5315.
27-Feb-17	Vehicle	215	Reported to OIC	Vehicle won't turn on. Emergency start won't work and over ride switch also not working	-	-
27-Feb-17	Vehicle	230	Officers reported to OIC.	Side door to rear component unable to lock. Also Battery cupboard door keeps alarming that its open.	-	-
27-Feb-17	Vehicle	230	Report only unit functional	Auxiliary battery powering radio and other electrical components of unit shutting down when not powered. Siren beeps intermittently. Believe battery faulty needs replacing	Auxiliary battery not holding charge	Nil
27-Feb-17	Vehicle	230	Fault form	Reverse camera does show on MDT when reversing.	? Reverse camera casing needs cleaning/sealing	Please rectify next service
15-Feb-17	Vehicle	225	Taken off road. CDS informed.	Pre glow indicator light came on when starting and vehicle struggled to idle, and when applied accelerator vehicle stalled. Took several attempts to restart and sounded as if was struggling to idle again.	-	-
14-Feb-17	Vehicle	235	-	Driver's side headlight is out - needs new bulb	-	This is night shift vehicle so headlights are crucial
15-Feb-17	Vehicle	210	Notify mechanic and replaced	Bent yellow stay back drivers side door	Found on vehicle check	Working well
15-Feb-17	Vehicle	250	-	Permanent " loss of power " mode " Low tyre pressure warning light " On "	-	-
15-Feb-17	Vehicle	215	notified osc, who rang racq as vehicle was at mbh and would not start in safe mode due to high temp alarm. vehicle left to cool for 20 minutes, restarted, drove unit back to station 500mts, repco mechanics collected unit at this time.	1.vehicle would not start due to high temp alarm 2. break distribution red warning light intermittently comes on dash 3. esp amber warning light intermittently comes on dash 4. vehicle pulls to the left when steering wheel control is relaxed by driver	unknown fault causes. Water reservoir was full, oil level was on minimum marking.	-
15-Feb-17	Vehicle	210	-	Rear aircon panel not working	-	-
15-Feb-17	Vehicle	210	-	Drivers door sensor faulty	-	-
7-Feb-17	Vehicle	225	Parts ordered by repairer	Return vehicle for repairs due to parts identified for replacement during service. Front steering component wear. Control arm	Steering / suspension wear	-
16-Feb-17	Vehicle	225	-	Air con not working in the back, fan working but not cooling	-	-
16-Feb-17	Vehicle	225	-	Aircon in rear of vehicle not cooling	-	-
16-Feb-17	Vehicle	210	Nil	Shoulder harness missing main stretcher	Missing quite some time	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
17-Feb-17	Vehicle	225	-	Side step broken	-	-
17-Feb-17	Vehicle	215	Fault form, OIC notified or car taken to mechanic	Engine light on and idle hold doesn't work. Also decals peeling off bonnet.	? Idle hold being used in hot weather. ? Wear and tear for decal peeling.	-
17-Feb-17	Defibrillator	210	-	Jog dial is illuminated in 'blue' and the message "CF card almost full" appears in upper left corner.	-	-
18-Feb-17	Vehicle	195	Nil	Left headlight blown	Unknown	-
18-Feb-17	Vehicle	195	took vehicle out of service and completed fault report	whilst driving and stationery battery light keeps coming on intermittently - not sure which one	unknown	As well as battery light on - alarm sounding everytime we go around a corner and come to a stop - multiple doors have been opened and closed to find fault.
18-Feb-17	Vehicle	195	Vehicle tagged and crew checked into another operational vehicle.	Vehicle coolant over heating warning light activated	-	-
18-Feb-17	General Equipment	230	Removed from service, hole marked	Hole in white air hose	-	Hole in air hose marked, near connection to regulator
19-Feb-17	Vehicle	245	Checked to ensure compartments and equipment was secured, Nil viable damage or fault. Car stopped and pt transferred to another crew.	Extreme Rattling heard and felt from in/underneath rear compartment when driving above 40kmh. Unknown cause.	unknown.	-
19-Feb-17	Vehicle	210	-	Side step failing to retract after side door opening, override switch not responsive.	-	-
19-Feb-17	Vehicle	235	Has been turned off and then back on with no change, fault form raised	MDT not working	No	-
19-Feb-17	Vehicle	230	-	Globe warning light when brake applied. flashing ? 8100 service required. Tail light not working? globe. Drivers torch not operational ? not charging. Oxygen leak - unable to be located	-	-
19-Feb-17	Vehicle	225	-	Rear suspension airbags are either very slow or not working	-	-
19-Feb-17	Vehicle	235	Master switch has been turned off then on again, same fault occurs	MDT not working again. It is flickering between "Powered by SIGTEC" screen and a Blue screen with white writing. Never opens to log on screen	-	Notified LARU Comms and SOS that I changed vehicle to one with an operational MDT as 6868 was not tracking either.
27-Feb-17	Vehicle	250	Nil	Siren not working, broken siren switch.	-	-
27-Feb-17	Defibrillator	235	Showed the SOS at start of shift, left defibrillator out the door of OIC.	Corpuls would not preform a test dump, indicating that the defibrillator had to be connected	?? Broken connection point were defibrillator brakes apart.	-
28-Feb-17	Vehicle	225	Nil	L rear door won't stay open as latch appears to be broken	U/K	-
28-Feb-17	Vehicle	245	-	Unable to drive code 1	-	-
28-Feb-17	Vehicle	250	-	Side step intermittently not working	Unknown	-
1-Mar-17	Vehicle	185	Alpha officer changed out of vehicle into operational vehicle	faulty mains panel operating emergency lights has moisture in it.	moisture	code 2 response only, vehicle currently on EA from officer residence. OIC to take unit to for investigation. V 5323.

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
1-Mar-17	Vehicle	185	Readiness coordinator to be notified and vehicle to be inspected by appropriate technicians	Rear door right side catch will not release. Door can only be opened from the inside. Windscreen wash bottle has a leak	Unknown	Although vehicle is classed as operational, consideration must be given to patient welfare as rapid extrication from the vehicle in an emergency . UNIT TO BE TAKEN TO EVEN DATE. V 5323.
23-Feb-17	Vehicle	240	I have advised OIC and did a fault form Comms informed, ROC requested to go to to have	Broken sun visor. Driver side.	As I went to use the visor it broke	-
24-Feb-17	Vehicle	245	brakes checked	Brakes slow to respond when braking	-	-
24-Feb-17	Vehicle	245	-	Front right dipped light (low beam headlight) not working.	Unknown - alert shown up on dashboard	-
23-Feb-17	Vehicle	185	Emailed OIC and fault form generated	Cracked windscreen. First noticed at 12:00 on 24/02/17. Crack approx 8cm long at base of passenger side.	Possible stone chip	Officer to submit an insurance claim & email to <QASLASNCAH.ReadinessCoordinator@ambulance.qld.gov.au> in order for replacement windscreen to be arranged.
24-Feb-17	Vehicle	215	Have organised servicing and tyre replacement for the 2/03/17.	80,000km service required. 2 rear tyres require replacement.	N/A	-
25-Feb-17	General Equipment	195	Taken offline	Spare temperature probe from unit 116, not working, showing incorrect temperature.	Unknown	-
24-Feb-17	Defibrillator	210	fault form and replaced with one out of 2229	leak in BP blue cuff	not working on shift during cases - did not pump up past 140 systolic	technical came to NR stn today so left a note for him to check out the NIBP issue and he found the leak and left a note for OIC
26-Feb-17	Vehicle	230	Nil at this time	Driver side brake light is not working	?blown bulb	-
26-Feb-17	Vehicle	240	OCS notified, car left on charge	Car placed in plantroom to clean/vacuum. Car turned off, when turning back on, will not start. Car fully charged ? starter motor issues.	-	-
27-Feb-17	Vehicle	235	-	Flashing light at rear above bumper is not working properly	Unknown	-
27-Feb-17	Stretcher	185	Ensure 2 people unload stretcher and reported to prevent potential stretcher drop when off loading from vehicle	The legs at the head end of the stretcher are not automatically locking into place when unloading the stretcher from the vehicle and have to being physically pushed back to lock into place.	Unknown	Near miss/hazard but no stretcher drop occurred. FAULT TO BE REPORTED TO THEN OIC SMITHFIELD TO ARRANGE STRETCHER TO BE TAKEN TO FOR INSPECTION/REPAIR.
27-Feb-17	Vehicle	230	Checked adjustment - does not appear to be cause of fault.	Patient attendant chair loose.	Not known	-
27-Feb-17	Vehicle	230	None	Rear aircon not working	-	-
27-Feb-17	Vehicle	240	ROC advised. Vehicle checklist updated	Brake pad wear warning - safety risk. ROC advised, vehicle made OOS	Warn brake pads	-
27-Feb-17	Stretcher	230	CCS notified and stretcher taken out of service	Head end legs did not fully extend when unloading patient from vehicle and stretcher collapsed with patient on it.	?	-
28-Feb-17	Vehicle	230	nil	Driver door bent back on hinges	Door pushed backwards by trailer on moving vehicle	-
28-Feb-17	Vehicle	245	-	Engine light showing. OIC notified	-	-
28-Feb-17	Vehicle	185	Vehicle being taken to by OIC for inspection	Engine light intermittently coming on. Vehicle appears to be driving ok.	Unknown. Found on vdi 27/2.17. This is not the usual Corpuls3 on the IFT vehicle. This is recorded as South Brisbane 9	Fault actually reported by night shift officer . States a fault form was created however it has not shown in the system. V 5314. OIC Gordonvale will take unit to even date.
27-Feb-17	Defibrillator	245	-	Main cable from monitor to pulse oximetry probe is frail and out casing split	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
28-Feb-17	Defibrillator	190	Remove from service until replacement Battery is recieved	Battery needs replacing as indicated by the machine itself	N/A	Tagged & Tested 09/2016
27-Feb-17	Vehicle	245	-	On VDI for 27.2.17, mobile phone would not switch on - showed 'low battery' warning. Phone was on charge all day. On VDI 28.2.17, phone will still not turn on. No mobile phone communications available via this method for Comms/hospital contacts	-	-
23-Feb-17	Defibrillator	210	-	Sats probe/oxy cable not working. Corpus states "oxy cable defective"	Unknown	-
24-Feb-17	Vehicle	245	Car turned on and off, masters turned on and off, inverted turned on, plugged into power back at station.	The emergency lights and one head light isn't working. Can't drive code one safely.	Unknown.	-
24-Feb-17	Vehicle	240	Vehicle driven to Caboolture Station and parked. ROC Advised	Warning message "Battery/Alternator visit workshop"	Unknown	-
24-Feb-17	Vehicle	245	Notified supervisor and vehicle returned to station out of service as per instruction	Flashing warning light on instrument cluster (vehicle manual says vehicle operating in emergency mode) occurred whilst driving, vehicle lost significant accelerating power whilst driving, unable to reach normal road speeds, worse on ascent	-	-
24-Feb-17	Vehicle	240	-	Left headlight bulb out	-	-
25-Feb-17	Vehicle	225	Reported fault.	Reversing camera has an intermittent fault. Camera not turning off when vehicle placed in drive, constant distracting voice warnings.	-	Fault occurs frequently.
25-Feb-17	Vehicle	230	SIM card and battery removed and replaced	Phone not operational	-	-
26-Feb-17	Vehicle	195	-	Rear compartment air conditioner not producing "cold air" Warning Light	-	-
27-Feb-17	Vehicle	240	Faults reported	MDT not functional	Unknown	-
28-Feb-17	Vehicle	195	Nil	Wiper washer motor not working	U/K	-
1-Mar-17	Vehicle	185	NA	Air conditioner vent above back door entrance has fallen down. Looks like 2 clips have broken off so can not be put back into place.	Unsure	SMITHFIELD OIC TO HAVE UNIT TAKEN TO FOR REPAIR. V 5321.
28-Feb-17	Other Equipment	230	referred to for replacement	cannot call out on or answer phone when it rings	-	-
19-Feb-17	Vehicle	195	Sos notified and car taken of road.	Engine light began flashing while driving code 1 to a job and car stopped revving and unable to gain speed. Side step also it working properly.	-	-
19-Feb-17	Vehicle	215	OIC notified via email, fault report complete, documented on vehicle checklist (mechanics not open to drop in)	Side step not functioning	Unknown, was recorded in vehicle checklist	-
19-Feb-17	Vehicle	245	The stretcher is operational with nil issues after replacing the battery.	Power stretcher appears to not be charging whilst loaded in the vehicle. On two occasions the stretcher has failed to operate, however this was solved by changing over the battery.	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
20-Feb-17	Vehicle	185	-	Left indicator faulty (signal comes up on dash board) and indicator sounds quicker. Also, there is a hazard symbol on the dashboard	Will notify OIC on return to station	V 5294.
20-Feb-17	Vehicle	230	OIC informed	Crack on back bumper passenger side	Unknown	-
20-Jan-17	Vehicle	240	Nil	Siren volume very low and intermittently not working at all. Works after vehicle is turned off and on again	No	battery tested no fault found, nil fault could not be replicated
20-Feb-17	Vehicle	220	SOS and OCS notified, vehicle to local repairer	Windscreen damage	Bird strike whilst responding to case	-
20-Feb-17	Vehicle	245	Checked fuses. Nil blown identified	OIC aware. A/C not operational	-	-
20-Feb-17	Vehicle	230	Driven to	Limp mode activated	Unknown	-
20-Feb-17	Vehicle	240	Turn off the MDT	GPS is faulty in the vehicle. the gps will freeze enroute to cases. At times it has sent me to the wrong address eg right name but close instead of street. At times it is the right street wrong number and may be a couple of km out.	-	-
20-Feb-17	Vehicle	245	Send to pst the morning of 21/2. fault has been reported to	External power cable cover come off (black cover)	Washing the vehicle.	The black cover is in the drivers side drink bottle holder on the dashboard.
21-Feb-17	Vehicle	235	to	guard under front left tyre is loose and occasionally rubbing on L tyre	-	-
21-Feb-17	Vehicle	250	Nil	Rear right door does not hold open, mechanism seems broken to ensure it doesn't swing back and hit paramedics and patients	-	-
21-Feb-17	Vehicle	210	-	?electrical fault. Back air conditioning not working all the time, turning itself off	-	-
23-Feb-17	Vehicle	240	Notified mechanic	Oil leak from rear Diff. Found at start of shift.	Unknown	-
23-Feb-17	Defibrillator	230	Changed cable nil difference (only from connector to probe, do not have round plug to connection cable)	Pulse ox cable fault, nil pulse ox available	-	-
23-Feb-17	Vehicle	215	Nil	Engine light on	-	-
23-Feb-17	Vehicle	210	Multiple attempts to switch on/off vis dash mounted switch.	Refrigerator not working. Digital temp display reading 25 degrees.	-	Fault detected on vehicle check. May be a fuse however unsure where fuse is located.
23-Feb-17	Vehicle	250	-	-	-	-
20-Feb-17	Vehicle	240	contacted for jump start and an email sent to the officer who left vehicle un-operatiuonal and informed of their error	Flat battery	Vehicle left after watchhouse shift not on charge and with the master left on	Jump started successfully and charging when not in use

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
23-Feb-17	Vehicle	210	MDS contacted striker company, issue ongoing fault with hydraulics in stretchers and would eventually need to be fixed. Discussed with Emerald OIC to arrange XPS flap and hydraulic hose to be fixed following phone call to auto technician	1. Aircon works intimately on long code 1's 2. Smaller hydraulic hose on automatic stretcher leaking oil 3. Left XPS flap when loading stretcher has cracked Rear A/c not working, went to , checked with from query fan has broken?	MDS identified leaking hydraulic hose, known fault identified by striker company	Serial number 150441173
24-Feb-17	Vehicle	185	/ notified		unknown, stopped mid job	Heat in back of vehicle unsuitable for pt transport. authorised to attend Mission Beach to repair. V 5293.
28-Feb-17	Vehicle	230	Tried to close locker a couple of times. Limited to no effect.	Side locker door will not close.	Unknown, was working during shift, does not close after pulling drug kit out of locker at end of shift. Did not forcefully open or close locker. Vehicle not operational as equipment would be likely to fall out of locker whilst driving.	-
28-Feb-17	Vehicle	230	Vehicle towed	Sudden massive oil leak	-	-
28-Feb-17	Stretcher	245	OIC is aware, stretcher has been removed. Comms is aware	The stretcher has a flashing orange light, presumably it isnt charging properly	Not known	-
28-Feb-17	Vehicle	245	Attempted hard resets with no success	Vehicle does not appear to be charging properly on 240V. Was plugged in on arrival but battery showing 11V. MDT issues with log on. Shown logged on at Comms but not on MDT. ?Power related	Unknown. Working yesterday. Not logging on today at start of shift	-
28-Feb-17	Defibrillator	210	I was able to get the defibrillator locked in however may become an larger issue over time	Fault is with the corpuis bracket in the vehicle. The charging magnet is loose and preventing the unit from locking into the cradle.	Unknown	Officer Potentially injured herself whilst trying to lock the defibrillator in place and identify the fault
28-Feb-17	Vehicle	215	Manually tried to switch locking mechanism but unable to move it	Drivers seat locked into down position, therefore no movement when going over bumps and potholes.	Not known	Nil
26-Feb-17	Vehicle	210	RACQ Mount Morgan changed to spare	back left hand tyre had a punture	? sharp rock	-
24-Feb-17	Vehicle	240	OC notified, vehicle taken off road.	Power stretcher loading platform will not lock into position when pulled out to load/unload stretcher.	Unknown - found in this condition.	Considered dangerous to use on uneven terrain, as it repeatedly runs away from the operator if let go. Will not remain in place for loading stretcher.
25-Feb-17	Vehicle	240	-	cracked windscreen, lower section passenger side	? rock from passing heavy vehicle.	spoken to at ,will arrange for repair.
27-Feb-17	Defibrillator	225	-	Unable to perform a monitor check as the defibrillator will not go into check mode when test box connected.	-	Defib removed from service and fault tag attached.
20-Feb-17	Defibrillator	240	-	CF card full	Use.	Still in operational circulation.
28-Feb-17	Vehicle	240	Completed fault form	Passengers side headlight not working	-	-
25-Feb-17	Defibrillator	235	Unplugged and, replugged. checked cable but no obvious damage found.	SpO2 Sat. Cable" Defective"	Unknown. found during start of shift check.	Taken from vehicle 606

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
25-Feb-17	Defibrillator	235	nil. advised by alpha to report to have card wiped.	Defib. states error "CF Card Full"	unknown. found during start of shift check.	This defib was a spare which I went to use when the previous defib on vehicle 606 failed.
24-Feb-17	Vehicle	225	Vehicle taken off road	Airbags have failed - not lifting vehicle. Side access door intermittently fails to open from either the inside or outside. This is creating a risk as Officers have to exit the unit from the rear door. Radio and Siren intermittently fail	Unknown	-
28-Feb-17	Vehicle	240	-	Rear loading step bent up/damaged	Unknown, found at start of shift after days off	-
13-Jan-17	Vehicle	230	-	Reverse camera screen blue	-	-
13-Jan-17	Vehicle	240	Attempted to switch off MDT at control panel behind rear seat without success.	MDT not working, screen stating an error. Unable to exit error screen shot.	-	OIC Checked vehicle no fault found. NIL MDT Issues identified
13-Jan-17	Vehicle	215	This form	I believe the axillary battery is not working. That is side step, fridge and front control panel not always working	.battery	Also side door to rear of vehicle does not lock!!!!!!!!!!!! Can be opened when the vehicle is locked by manually turned the latch
12-Jan-17	Vehicle	240	OIC contacted and car for review at work shop today	Air conditioner is not blowing cold air. It takes about 10 minutes to start cooling the car	-	-
14-Jan-17	General Equipment	225	-	Batteries are being depleted in less than one hour.	-	-
14-Jan-17	Vehicle	230	RACQ called - OCS notified - second unit activated to transport patient. - Unity placed OOS	Flat rear left tyre. - Replaced with spare - Spare tyre is flat and nut locking rings have been removed.	Unit picked up a screw on the way to a case.	Nut locking rings are on the floor in the front of the vehicle.
15-Jan-17	Vehicle	230	OCS notified and defective vehicle report submitted.	Spare tyre is flat and needs replacing.	Unit's tyre picked up a screw enroute to a case.	-
15-Jan-17	Vehicle	195	None	All lights and the siren going on intermittently of their own accord, unable to turn off.	During driving a large amount of water has poured out a hole in the plastic cowling behind the head mount radio onto the back of switchboard below.	-
15-Jan-17	Vehicle	240	Reported to the ROC and	Hand break alarm constantly beeping, not registering the disengagement of hand break.	Just occurred after leaving a scene and disengaging the hand break. Constantly beeped and warning light flashed all the way to hospital.	OIC notes - Crew did not properly sign vehicle as out of service, night shift used the vehicle with no fault reported ? operator error. Night shift however did report that the drivers side headlight is out and needs a bulb replacement.
16-Jan-17	Vehicle	225	Physical damage to area, no action taken, needs to be fixed by mechanic	Side door not working, electrical issue causing grinding of motor which has damaged track the door moves on	Unknown	-
16-Jan-17	Vehicle	245	-	Reverse camera is not working, shows a blue screen. When the vehicle changes gears there is a shudder and the vehicle jerks around.	-	-
16-Jan-17	Vehicle	240	Notified OIC	Side step not going in or out	Unknown	-
16-Jan-17	Other Equipment	230	-	Mobile phone not turning on. Plugged in confirmed working charger for at least 30 min and the phone still would not turn on.	-	Advised Caloundra IOC and notified cds
17-Jan-17	Vehicle	230	OIC contacted	Battery flat despite being plugged into charger.	? Charger. On plugging back in charger made audible click and turned off 5-6 times before resuming charging.	-

RTI RELEASE

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
18-Jan-17	Vehicle	215	Batteries tested auxiliary failed contacted and battery being brought out to replace us battery.	Auxiliary battery failed causing radios to work intermittently.	Failed battery	-
18-Jan-17	Stretcher	230	Crew advised Comms , removed from service , left at NGH with HLO	Stretcher wheels not locking properly when removing from rear of vehicle	-	N/A
18-Jan-17	Stretcher	240	Manual release used, battery replaced	Loading arms would not lower/release stretcher	-	Working appropriately post fault
18-Jan-17	Vehicle	210	Reported.	When turning vehicle in left direction there is a ribbing noise coming from vehicle. Difficult to ascertain whether from or rear. Vehicle feels stable to drive and no vibrating.	Unknown. Fault found when vehicle taken on first case.	-
17-Jan-17	Vehicle	240	Vehicle to be sent for repair when suitable. Officer counselled re driving habits.	Panel damage to drivers side of vehicle.	Poor driving care. Officer side swiped pole at a nursing home when turning in a driveway.	-
17-Jan-17	Vehicle	195	Tyre refilled with air and tyre pressure returned to 60kpi	Dash displaying tyre pressure low to Rear L) tyre. SOS notified and advised to refill tyre with air, tyre pressures normal after this. Dash display reappeared following day with rear L) tyre pressure low again.	?slow leak in L) rear tyre.	-
13-Jan-17	Vehicle	240	Override switch used, door retracted but issue reoccurred	Passenger side door failed to retract.	-	Day crew used vehicle and reported no issue with step deploying or retracting
13-Jan-17	Vehicle	245	-	While coming to stop at traffic lights: all warning lights on dash illuminated and the engine shut down. Able to restart car (key turn of 15sec) however vehicle very sluggish and heavy to drive. Happened twice, able to get car to safe location.	-	Car towed to PST organised by OCS Brisbane.
14-Jan-17	Vehicle	245	Parked at station. Bulb replaced by PST. MDT operational after vehicle left on charge	Left tail light; MDT stopped functioning	?blown bulb & ?loose cable	-
15-Jan-17	Vehicle	210	Reported	Stitching on drivers seat upright has perished and come away from material.	-	-
15-Jan-17	Vehicle	225	-	Reversing camera does not work	Unknown	-
14-Jan-17	Vehicle	235	report to fleet technician	module battery is dead ,vehicle smells strongly off Sulfur gas ..	Dead battery	-
16-Jan-17	Defibrillator	225	Check the CO2 connections and restarted the corpuls. Nil changed error still displayed.	!!!!Error CO2 Module. This occurred while conducting user test. Nil CO2 reading displayed.	-	-
16-Jan-17	Vehicle	195	1. Have a second torch for the time being 2. Reported	1.Rechargeable torch gone flat charger is working looked at battery and battery is leaking paper like substance has come out of the battery. 2. 12V power outlet in center console not working	1. unknown 2. unknown	Contacting Fleet coordinator for both.
15-Jan-17	Vehicle	205	Booked in to be fixed on the 18/1/2017 at	Left work light not working	unknown	Vehicle is operation the light is not operational
16-Jan-17	Vehicle	250	Rectify by mechanic and auto electrical	Battery not charging and oil low	-	Repaired by and

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
15-Jan-17	Vehicle	195	attempted to adjust all accessible fittings with no success	D size O2 leak	-	Booked into 17/1/17
16-Jan-17	Vehicle	240	Tyre replaced	FRONT R) tyre blowout while driving.	Faulty tyre as per RACQ	-
16-Jan-17	Vehicle	245	Nil	Minor cosmetic damage to front bull bar	Minor collision in heavy traffic, nose to tail as 2 vehicles ahead stopped suddenly	No damage to other car, driver was happy that no damage had happened and did not ask for gas details
16-Jan-17	Vehicle	200	Notified mechanic SOS and . Put unit of road. will look at it Tuesday 17/1/17.	Accidentally wrong fuel put in unit .i.e. Vortex 98 instead of Diesel.	Wrong fuel put in unit. human error on part of Officer	Human error.
17-Jan-17	Vehicle	240	Vehicle is going to for investigation.	Airconditioning in the front of the vehicle is not working at all. No air is coming through the vents. Second to this, the back rear door button to release the latches is sticking and making it hard to open. With this, the door is difficult to close.	Unknown	-
17-Jan-17	Vehicle	230	This report again	MDT loosing power all the time have to re boot several times during shift, GPS function not working	Re- accuring fault over past two years	-
17-Jan-17	Vehicle	240	OIC aware - vehicle to be sent for service 19/1/17	Left upper indicator light not flashing - all other indicator lights functional	-	-
17-Jan-17	Vehicle	210	Fault form, OIC informed.	Drivers side mirror loose, unable to visualise traffic behind vehicle as mirror drops during transit.	-	-
19-Jan-17	Vehicle	240	OIC notified, other key is all good	1 x set of keys remote not working	possible battery issue?	-
17-Jan-17	General Equipment	250	Nil fault form created - OIC now completing form	Crew have reported that rear fridge in 6557 is not working	-	Vehicle is still operational. Fridge is not working.
16-Jan-17	Vehicle	250	OIC completing form	Crew have reported suction unit in rear compartment of vehicle is not working - crew did not submit fault fom	-	-
19-Jan-17	Stretcher	195	attempt to drop arms more then one time to get lifter arms to drop properly. Advised and attempted to demonstrate to OIC	power lifter arms not dropping fully ? fault. Works on multiple attempts when trying to remove stretcher. Nil fault with power stretcher itself	unknown cause	-
11-Jan-17	Vehicle	210	notify CCR	minor crack in drivers side reverse light casing	unknown reported via vehicle check this morning	reverse light still works - marked as fault on vehicle checklist form
11-Jan-17	Vehicle	250	tried to be contacted- nil answer but voicemail left.	stretcher broken. r contacted with nil answer,voice mail left to contact . SOS witness to all of above with photographic evidence.	Unsure	-
11-Jan-17	Vehicle	230	Vehicle off road. nil	Front Beacons not working again, same issues as last week.	unknown	-
11-Jan-17	Vehicle	210	Crew notified COM's, coms tried to get in contact with fleet manager but was unsuccessful, Coms spoke to SOS and informed crew to put vehicle off road until fault is rectified	Fuel system warning light, came on during transport to hospital c/s#8386001	unknown	Vehicle had been turned off and back on at hospital and light still remained on. Nil mechanical problem found with vehicle, or drive ability, vehicle operating normally.

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
11-Jan-17	Vehicle	235	-	Internal light will only stay on for a few seconds before switching off again	?low battery	-
11-Jan-17	Vehicle	235	-	Side step not coming all the way out	-	-
11-Jan-17	Vehicle	230	Took car to mechanics but unable to find cause of problem. Vehicle taken off road	Rear aircon not working Aircon only working in front compartment	Unknown cause	-
11-Jan-17	Vehicle	230	Vehicle taken to repair for	Rear air conditioning not working	-	-
12-Jan-17	Vehicle	215	-	Coolent container empty and fluid leaking out from under the car	-	-
12-Jan-17	Vehicle	245	Tried emergency start. Tried to open close 240v flap. Multiple attempts to turn vehicle on.	On scene once pt loaded in vehicle, car would not start. Emergency start attempted with no effect.	Unknown	-
10-Jan-17	Vehicle	215	A/OIC notified	Front bumper Left side of vehicle has small indentation	Unknown cause. Officer running out of vehicle does not recall hitting anything. Dent noticed while washing vehicle.	-
12-Jan-17	Vehicle	245	Is report	Rear compartment aircon not working.	No	Car was serviced earlier that day - PST attended and issue resolved
6-Jan-17	Vehicle	240	-	Brakes do not feel safe. You must step on the brake pedal with excessive force.	-	Vehicle does not feel safe enough to be driven code 1.
13-Jan-17	Stretcher	235	-	Stretcher is not charging when in car	-	-
13-Jan-17	General Equipment	210	Used another keyboard with same problem. Swapped the monitors from another computer and the computer works. Plugged in the monitor to another computer - same problem. Not turning on.	Model # - L225WT. Computer monitor is not turning on. When the computer is shut down and restarted it goes to a completely blank screen. When it does work, unable to use the keyboard attached.	Noticed when Keyboard wasnt working.	Located Outside OIC office - South Rockhampton Station
12-Jan-17	Vehicle	210	Nil	Star to passenger side of windscreen	Rock thrown from oncoming car	-
15-Jan-17	Vehicle	210	None, notified CCS, defected vehicle	While driving at low speeds around a round about all power shut off and steering became stiff. Unable to steer, all lights shut off, radio stopped working. Service A is overdue by 1000k sign came up after event.	-	-
16-Jan-17	Vehicle	240	Roc notified	Brake lights not working	Back left and right brake lights not working	-
16-Jan-17	Vehicle	240	Problem reported to OIC	Indicator clear lens was discovered broken by dayshift. Air conditioner in front cabin not operating properly.	Unknown when lens was broken. Day crew had finished nightshift on 12/01/2017 and lens was fine. When driving the vehicle noticed that air con wasn't working properly.	-
19-Jan-17	General Equipment	240	Notified OIC Northlakes vehicle taken to mechanics for review	Air conditioner rear cabin in-effective flow	? Re-gas	Vehicle regassed by mechanic.
18-Jan-17	Other Equipment	230	Fault form	Phone holder connection plastic part completely snapped off	Phone holder connection part was loose when shift commenced	-

RTI Released

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
19-Jan-17	Vehicle	195	Comms and SOS notified. OIC attended scene to assist.	Fuel card not 'working' despite correct odometer reading and vehicle PIN entered multiple times. Caltex S/Station machine advised PIN incorrect and was declined. Crew advised to submit fault form and card to OIC.	-	-
20-Jan-17	General Equipment	195	Suction hose un-kinked and cable tied away from insertion point to inhibit further kinkage.	Onboard suction unit failing to suction after basic trouble shooting	Vehicle taken to local service provider and assessed. Upon inspection, suction hose was kinked.	Vehicle now operational
22-Jan-17	Vehicle	215	Nil	Running slide for back passenger cab door loose and rattling	Wear and tear	-
22-Jan-17	Vehicle	240	fault form completed	rear step damage/bent	??/ found during vehicle checks	OIC reported fault to Workshops - visit to yet to be organised.
22-Jan-17	Vehicle	225	tried to visualise the fault and compare to drivers door and looks normal	Passenger Side Door VERY hard to close, ?hinge broken	opened the door to enter vehicle, went to close door and heard a crack	passenger door is able to close, however is tough
23-Jan-17	Vehicle	240	Reset - OSU to be consulted in hours	MDT freezing repeatedly	-	OSU notified - awaiting technician to fix. 23-1-17
24-Jan-17	Defibrillator	225	- pulse ox lead/s connected properly, appear intact, without defect, with red light working - 2 other distal pulse ox lead ends connected, but Alarm messages still show - 3 modules connected properly	- pulse ox not reading; with alarm messages: "Defective Oxi cable" or " Oxi cable loose" or "Oxi sensor loose" - upon powering off, in shutdown mode it shows a fullscreen msg to check that the modules are connected	#NAME?	- when distal pulse ox ends connected to another Corpuls3, all were working and without fault - Corpuls3 in 3164 out of service (in OIC office), and replaced with defibrillator in 3366 (now without defibrillator)
24-Jan-17	Stretcher	230	Stretcher taken out of service and left at Nambour General Hospital	Red fold out adjustment lever at head end not functioning, not connected to label	Unknown cause	Nil patient involvement, nil collapse
24-Jan-17	Defibrillator	250	Taken out of service	Electrical artifact when doing ecg unable to filter just constant vertices lines	-	-
25-Jan-17	Vehicle	235	Replacement	Wall mounted airway kit needs replacement	Held together with a safety belt	-
25-Jan-17	Vehicle	235	-	Side door sometimes doesn't latch back	-	-
25-Jan-17	Vehicle	225	Vehicle fault form to OIC	Unit number 3287.. -Front wheel ailment is need the vehicle keeps on pulling to the left when driving. & front USB isn't charging iPad(s) - under gps driver side Glovebox hard to open clip is not clipping in Rear window decal blocks use of inside mirr	Not sure	Mirror m walker. Vehicle sent ot for front end alligment. Regarding the mirrors and corperate stickers these are state based issues. Officers drivining these new trucks need to adjust there driving habits to suit the new vehicle and con
25-Jan-17	General Equipment	195	Changed cable	SpO 2 sensor cable faulty	N/A	-
25-Jan-17	Vehicle	235	replace windscreen next service	crack to left lower windscreen	rock	-
25-Jan-17	Vehicle	190	Vehicle was taken to mechanics () in and battery was replaced. Vehicle is now starting without any problems.	When starting vehicle it sounded as though starter battery was failing/needs changing.	Battery required changing.	Vehicle now operational and starting normally.
27-Jan-17	Vehicle	225	-	Rear panel not working that controls suction	-	Vehicle Operational

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
28-Jan-17	Vehicle	225	-	Windscreen washer jet broken on drivers side wiper arm.	-	Wiper works but washer does not spray water onto windscreen
28-Jan-17	Vehicle	235	-	When closing door, the door locks in as if it's closed, however appears ajar. Does not line up with latch, visible gap in the door between door and car. Does not happen every time. Video will be emailed to fleet technician.	-	-
28-Jan-17	Vehicle	225	Notified SOS and he attended the scene address collected /gave details, Covered window in plastic, tagged keys "do not use", parked vehicle out the back of station awaiting repair.	Drivers side rear window smashed/missing due to incident on job. CN# 08440225	Collision with low awning.	-
29-Jan-17	Vehicle	250	-	Vehicle dirty inside & out; no Large Corpluse / paediatric BP cuff / rear fridge door broken; oxy viva zip broken ; poor working stock in rear cupboards	-	-
19-Jan-17	Vehicle	195	Advised and demonstrated to OIC	Front drivers seat backrest adjuster not working, unable to adjust back rest. ? road worthy status.	unknown	-
19-Jan-17	Vehicle	225	Conversation with the Mechanic from I as they will pick up and investigate problem and rectify.	Making load rubbing/ grinding noise possible from drive train or gears ??? needs further investigation .	Unknown at occurred whilst driving under normal driving conditions.	-
19-Jan-17	Other Equipment	225	-	Pager no receiving pages for jobs	-	-
20-Jan-17	Vehicle	240	A/OIC informed.	Damage to passenger side rear wheel arch.	Unknown, vehicle found with damage at commencement of shift	-
20-Jan-17	Vehicle	210	Vehicle defected	Side step crushed as vehicle became lodged by side step on large rock while attempting to reach patient. Side step no longer functioning.	The large rock	Step no longer operating therefore vehicle non operational- WHS risk
21-Jan-17	Vehicle	235	-	Engine light in 602667 stays on	-	-
21-Jan-17	Vehicle	225	car taken off road	QASleft from TBH for a job and engine light came on that wasn't there prior and the car was limited in its speed	unknown	car was functioning fine prior
21-Jan-17	Stretcher	215	Removed from service	Strut for head rest leaking oil and not returning to supine position.	Obese patient during long transfer.	Stretcher located at Bundaberg plant room. Marked non operational.
25-Jan-17	Defibrillator	230	OIC CDS notified. Corpuls taken off road Defib taken from unit 4812 as directed	Corpuls is not charging when on bracket. We have tried it on other vehicles brackets no also tried the 240v socket via PowerPoint and also does not charge.	-	-
25-Jan-17	Vehicle	230	None	Missing passenger side running light behind passenger door	Unknown	Afternoon shift crews requested to drop into replaced or it will be replaced at next service. to have light
25-Jan-17	Other Equipment	230	Knob from 405793P2 swapped as temporary replacement and GWN notified of fault to provide replacement for 793 by O.I.C A received in mail and replaced by O.i.C	Missing channel selection knob from top of radio	Unknown	401752P2 serial no. 481CPZA692

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
26-Jan-17	Vehicle	185	We have tied down the door with a bandage to get back to station. Will tag out vehicle tonight. Have notified SOS and Reef Com	Latch of side door where drugs and oxygen are located won't catch and door remains open...	- mechanic and could not fault door	s on inspection 27/1/2017.
26-Jan-17	Defibrillator	190	N/A	Defective Oxi cable.	Unknown	N/A
27-Jan-17	General Equipment	230	carrying yellow drug kit separately to response kit, this form	Zip to secure drug kit left broken, zip completely off unable to secure yellow drug kit inside response kit	Age of kit? general wear and tear	kit was obviously broken on prior shift, unsure if form was done at the time where zip wouldn't function (yellow kit was not in response kit during this mornings car check)
28-Jan-17	Vehicle	245	-	MDT is unable to be used in this Vehicle	-	-
28-Jan-17	Vehicle	245	-	MDT not working. Unable to log on or see jobs on the screen. Screen coming up with an error asking to restart computer	-	-
28-Jan-17	Vehicle	245	-	Front radio not working. Crew/comms can still be contacted via portable radios	-	-
28-Jan-17	Vehicle	230	Nil	Crack from thrown stone in left side of windscreen	Officer advised that a stone was thrown from a car in front whilst driving on a code one to Noosa today resulting in crack to windscreen	Happened during day shift officer driving
28-Jan-17	Vehicle	240	Roc notified told to drive back to station if able and racq will be organised for tomorrow.	Puncture in tyre.	-	Spare tyre has been used and flat tyre is located under the vechile. Vehicle is being serviced on the 01.02.2017 and the tyre will be change then.
29-Jan-17	Vehicle	220	Reset the safety switch and circuit breaker. Contacted the Duty Officer to advise of the issue. Will check the vehicles charge in a few hours time	Batteries are flat	Charging lead tripped its safety switch and vehicle was not charging	-
28-Jan-17	Vehicle	200	-	Rear air conditioner leaking into module near rear door; spitting water out of unit onto outside rear door	-	-
10-Jan-17	Vehicle	195	Vehicle taken out of service	Side oxygen door will not close. Spring in the latch is broken	Unknown	-
10-Jan-17	Vehicle	225	Vehicle off road OCS notified contractor notified and taken to for repair, replaced with Murgon 3366	AC roof module thermostat fans faulty	Roof module AC thermostat fans centre and off side faulty, centre fan noisy operation visibly unbalanced possible fan spindle bearings worn and off side fan intermittent function will start with manual assistance. Rear AC not cooling and shut down 10 min	-
11-Jan-17	General Equipment	210	Reporting a fault	Female end of extension cord to charge vehicle damaged	It got run over when backing 2151 into bay of garage	Currently using one extension cord to charge two vehicles (swapping back and forth)

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
13-Jan-17	Vehicle	240	report, A/OIC spoke to officer who stated drives fine just concerned about long term tyre wear. Vehicle second day on road only 390kms - fleet technical officer - advised OIC to close fault form and will be checked at first service	steering pulls slightly to the left	miss alignment	Hi Of course. Same people all the time that find something wrong. No it has just had an inspection done prior to release. We will check it on the service next month. Regards Fleet Technical Officer
13-Jan-17	General Equipment	240	report	rear cabin driver's side suction unit has no vacuum generated	possibly not connected	passenger side suction unit works. Officer educated as to how to function suction on this vehicle and that there is a lever/switch to change which suction unit is activated. Both suction units working normally.
12-Jan-17	Vehicle	210	Report, changing settings, has been set at 16 degrees for 2 days	Air conditioning problem	Not working properly in front of vehicle,	-
14-Jan-17	Vehicle	215	Auto electrician will be contacted on Monday.	Control panel fault, switches working intermittently.	Known fault, components have been replaced in the past. Continual problem.	-
14-Jan-17	Vehicle	235	Alerted CDS and attempting to fix however not successful	Black cap on the exterior 240v outlet in drivers side broken off when attempting to unplug power to drive vehicle.	-	-
14-Jan-17	Vehicle	235	-	Internal lights flickering	Power related	-
14-Jan-17	Vehicle	215	Tried all connections were in place nil faults found	Corplus vehicle cradle not charging corplus	unknown, not charging from start of shift	-
16-Jan-17	Vehicle	180	local mechanic to fix.	Stainless steel plate on floor where stretcher enters has lifted and fallen off.	wear and tear	booked in to fix 17.01.2017
16-Jan-17	General Equipment	240	-	Mdt turns itself on and off with occasionally turns off and difficulty resetting.	Battery / electrical fault	-
19-Jan-17	Vehicle	185	Tried emailing but she is on leave. I've sent an email to another email address in absent.	Main switch is not working. When you try to turn it on it flashes a few times then activate the siren without the siren switch being turned on.	Unkown	-
19-Jan-17	Vehicle	235	-	Rear air conditioner not function properly. Minimal flow from vents even when fan on high, air not cooling, control unit indicating outside temp is 12 degrees. Rear compartment hot and stuffy.	-	-
19-Jan-17	Vehicle	240	Fill out default form	Misalignment of rear door , gap top right side	Unknown discovered on vehicle check start of shift	Unknown when damage occurred by reporting officer
20-Jan-17	Vehicle	225	Nil	Side step not working, retracted under vehicle	Unknown	Multiple occurrence ++
19-Jan-17	General Equipment	240	OIC Notified and he notified	Sharps container/holster fell from PRK and is now lost. Magnet not strong enough to hold sharps containers in place.	-	OIC attached sharps containers to PRK's using cable time as per instruction from MRR
20-Jan-17	Vehicle	240	-	Rear A/C control panel (in drivers cabin) switches off intermittently whilst driving. Rear module A/C control panel working normally	-	-
20-Jan-17	Defibrillator	225	Put spare defibrillator in vehicle	Hinge on printer latch broken	Unknown	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
28-Jan-17	Vehicle	250	Vehicle has been towed to Southport Stn for repair.	Vehicle would not accelerate over max speed 20kmh following vehicle engine start after dispatch to job. Entered mode described as 'limp mode'. Unable to rectify with turning off and restarting vehicle.	Not known.	-
30-Jan-17	Vehicle	215	Will take vehicle to	Air conditioning not working intermittently. On two occasions today when starting vehicle after collecting patients the rear air conditioning unit did not start. The first time the rear a/c started working after hitting a bump in the road.	-	At approximately 10.00am we were advised by crew using this vehicle last week that this was an issue last week and that vehicle had been to mechanics but as issue was intermittent problem and it did not fault there issue was unable to be rectified.
31-Jan-17	Vehicle	250	-	Inner side panel missing. Windscreen sensor ?? Unstuck. Garage remote u/s. fridge u/s. 6303 tuffbook multi buttons missing. Poor ride in back ? Suspension issue.	-	All of this has been reported in the past. Unsure if any rectifying action has been taken.
31-Jan-17	Vehicle	215	Nil	Rear door storage basket broken Combi carrier storage compartment lid strut is broken	Unknown vehicle found in broken condition	-
31-Jan-17	Vehicle	210	-	The right side small fond magnifying side mirror has come off and is lost.	Unknown	-
2-Feb-17	Vehicle	245	-	Vehicle lost power on a corner, dash lights came on, no power steering. Engine stalled. This has been a recurrent fault in this vehicle however frequency is increasing	-	Previous incidents of same fault seemed to occur when vehicle was stationary however this time vehicle was in motion at speed of approx 50km/hr
2-Feb-17	Vehicle	180	OIC notified.	Water leaking into rear cabin during heavy rain. Water noticed on floor under the combi carrier and on the wall near the fan above the monitor.	Age/wear and tear: Lots of external cracking/paint chipping around the entire frame. also to investigate leaks at the door, and where module window to the drivers cab is.	-
2-Feb-17	Vehicle	240	Vehicle ignition turned off, MDT switch turned off, waited, turned on but not MDT power.	MDT and vehicle radio functioning at start of shift but shut down during idle hold.	-	Vehicle battery 11v, module battery 12v Aux battery replaced 9th Feb 17
3-Feb-17	Vehicle	215	Parked it.	ABS light on and Brake distribution red warning light illuminated continuously on the dash	-	-
3-Feb-17	Vehicle	215	Vehicle taken off road fault form completed and OIC notified.	Rear air conditioner is not working.	Unsure	-
3-Feb-17	Defibrillator	225	Removed from service	NIBP tube connection not connecting to cuff.	-	On OIC desk
2-Feb-17	Vehicle	200	Have taken vehicle off road	Stretcher loading arm not working	Unknown	-
3-Feb-17	Vehicle	240	None.	Cigarette lighter in front and rear don't work so unable to charge iPads, phone and more importantly the tough book as spare batteries are scarce.	Unknown but has been reported many times before.	The tough book being charged during the shift in car is important as the spare battery situation is an issue.
3-Feb-17	Vehicle	210	to be assessed by tyre repair provider	uneven tyre wear noted during start of shift checks	tyres out of balance	-
2-Feb-17	Vehicle	215	-	Pass side low beam bulb blown	-	-
3-Feb-17	Vehicle	250	-	Spoke to Fleet Tech and was asked to take it back to B'Heads Station and place off Rd.	-	-
3-Feb-17	Vehicle	240	Attempted to remount unsuccessfully	Guard at base of front passenger door loose	Unknown	-
3-Feb-17	-	185	stretcher has been left at Cairns Base Hospital ED, well labelled	M1 stretcher (#110541453) missing 'collet locking clip' from bolt or bar on mechanism controlling raising and lowering back section of stretcher	unknown, not noticed on stretcher with checks on Thursday.	Stretcher swapped and left at Cairns Base so clip can be easily fitted on inspection
5-Feb-17	Vehicle	230	Been advised by CDS to drive vehicle to Noosa station and swap vehicles	Rear compartment air conditioner is not working even after several attempts at resolving the problem	Unknown	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
5-Feb-17	Vehicle	240	Vehicle turned off, attempted to restart.	Engine shuddered, banged, vehicle then stalled on way to code 1 - exiting plant room.	Unknown	OIC notified
10-Jan-17	Vehicle	230	Light removed	Pulling out of Gympie Dem ambulance bay and front right hand work light got clipped but the angled support and broke work light off	Pulling out of Gympie Dem ambulance bay and front right hand work light got clipped but the angled support and broke work light off. Because of the angle of roof support it was out of view above the mirror. Officer thought he was clear but could not see	-
10-Jan-17	Vehicle	250	Reported in person a few times	Drivers chair does not slide all the way ? Track twisted. Side step also not retracting intermittent. Stretcher missing track and whilst driving along drops down as it does when off loading the stretcher, doesn't seem secure. Also feels like the brakes	Been like it since new reported a few times to oic and machanic but 6 months on still not repaired	Feels like the brakes are on the stretcher and is heavier to than other stretchers, doesn't seem to line up properly.
12-Jan-17	Vehicle	225	Fault form Not being utilised, currenly located at	Ventilation in rear compartment is not working. Buttons of ventilation and suction are switched around - suction is working	-	-
12-Jan-17	Vehicle	185	Requires front tyre replacement.	Requires front tyre replacement.	Wear and tear	-
12-Jan-17	Vehicle	210	Went to to have them assess the problem. They said pump is not working. They state there is no fuse in line to pump. Currenly off road and located at for unrelated repair.	Wiper Fluid Pump not working.	-	Can we order a piece at or do you want to send one to them?
12-Jan-17	Vehicle	185	Drivers side front tyre has bulging area, causing vehicle to vibrate/shudder whilst under power.	Drivers side front tyre has bulging area, causing vehicle to vibrate/shudder whilst under power.	Wear and tear.	Requires front tyre replacement.
2-Jan-17	Vehicle	195	Vehicle booked into inspection.	Reversing camera operation intermittent.	Unknown.	-
13-Jan-17	Vehicle	240	-	MDT sound and reversing camera not working.	- attended and repaired	-
15-Jan-17	Vehicle	230	OIC notified	Phone charger is broken charging port to phone has broken off and wires are exposed.	Unknown cause and date	Charging phone during time at station.. car charger not operational
15-Jan-17	Vehicle	200	-	L) head light not working dangerous to operate at night	Unknown	To be used exclusively during the day
16-Jan-17	Vehicle	235	-	Toggle switch works intermittently, no tension	-	Persistence is required to turn on interior rear light
16-Jan-17	Stretcher	245	Stretcher taken out of service, patient transferred to hospital bed immediately after incident. Removed from service, repaired by and replaced	Back legs of stretcher failed to click in, red button/latch wasn't self locking back into place at foot end of stretcher	-	-
17-Jan-17	Vehicle	245	attended to replace bulb	R front indicator globe blown	-	-
17-Jan-17	Vehicle	230	Report completed.	Reversing camera shows only bright white light when reversing at night time.	Camera too sensitive to ambient light from vehicle and street lights?	-
17-Jan-17	Vehicle	225	Booked in for fault	? Power issue battery charge and ability to keep power	Battery	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
18-Jan-17	Vehicle	240	Arrangements are being made to attend	Spare tyre has screw in it	-	-
19-Jan-17	Vehicle	210	Have local Mechanical Service centre review issue, with a view to repair if possible.	The primary equipment compartment door will not close properly. It requires significant energy to close and does not always lock. ? issue with locking mechanism.	General wear and tare / Poor quality roads / Vibration.	-
19-Jan-17	Vehicle	230	Comms advised , advised crew not to drive vehicle, vehicle to be towed to for further review	Vehicle began to shake violently when placed in reverse then again when driving forwards	-	-
19-Jan-17	Vehicle	215	-	Slow leak in rear drivers side tyre. 5psi/day	-	-
19-Jan-17	Vehicle	190	Replacement plastic housing to be fitted.	Blinker casing on left mirror smashed - blinker still working.	? Happening whilst parked out the front of Officer residence whilst on EA	Nil fault - vehicle damage
29-Jan-17	General Equipment	210	OIC QAS Blackwater replaced the unit with spare / training kit form QAS Blackwater	The PRK for Unit 2179 / 547SMT - Medication compartment is broken / torn and Zippers no operational. The backpack section /straps are not able to be secured.	Unknown / overuse.	QAS OIC Rockhampton notified / QAS Rockhampton Unit.
29-Jan-17	Vehicle	240	Fault was rectified previously. It worked for week and half. Worked one day not the next.	Reverse camera not coming up on MDT again. Blue screen only.	-	Sensors work video does not.
31-Jan-17	Vehicle	210	-	Turning at light into station when a loud noise occurred under vehicle. Also when driving on front drive side feels like it rubbing against something.	-	-
1-Feb-17	Vehicle	245	OIC informed	Drivers side rear door opening catch broken door does not stay open	metal fatigue	-
2-Feb-17	Vehicle	235	-	Suction units operating but very poorly. Suction only operating at unit base but not at tube end	-	-
2-Feb-17	Vehicle	235	-	No GPS Side step not functioning	-	-
3-Feb-17	Vehicle	185	Needs workshop attention	1. Seatbelt for rear facing seat not retracting. 2. Catch for rear left door broken-door unable to be held open 3. Unable to change position/height of shoulder strap for driver seatbelt	-	V NUMBER TO BE ADVISED.
3-Feb-17	Vehicle	195	Is at	Airbags not inflating	Airbags	-
3-Feb-17	Vehicle	215	Nil,	Airconditioning in both front and rear cabins intermittently not working. For rear cabin, control panel flickers showing an array of temperatures, with nil chilled air blowing. Then system in most instances rights itself. Front cabin different issues.	Nil	Similar issues to what was fixed late last year.

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
3-Feb-17	Vehicle	210	As the plastic part was sticking out half in place it has been removed and tape placed on the corner of the step to make it safe.	The plastic corner of the side step has dislodged.	NA	-
3-Feb-17	Vehicle	230	Requires technician	Mdt going into sleep mode frequently. To often to be normal acceptable operation, also effects reversing camera.	-	-
6-Feb-17	Defibrillator	225	Pulled modules apart several times. Removed batteries for period of time.	Red alarm - Module Restarts (P-Box)	-	Contacted - Awaiting call back from .
7-Feb-17	Vehicle	210	new plastic cover	Light cover of rear back left (passenger side) brake light cracked	reversed into letter box	sorry mate
6-Feb-17	Vehicle	230	This form	Dry powder fire extinguisher used on Monday 6 February - requires recharging/replacement	Use of the fire extinguisher on a truck fire	-
7-Feb-17	Vehicle	225	OIC notified	Front L) emergency flasher U/S	wear and tear	-
7-Feb-17	Vehicle	210	notify oic Nth Rton	yellow strut metal bar Drivers side rear door jam is missing - only broken part is place.	found on vehicle check - found 3 broken bars in the vehicle when searching for the part	-
7-Feb-17	Vehicle	245	OIC was contacted and arranged for vehicle to be repaired 8/2/17	rear aircon stopped working 1.5 hrs before end of shift	???	-
7-Feb-17	Defibrillator	235	-	Would not recognise defibrillator tester, states unconnected, unable to perform test on corpuls. 2x testers used without success.	-	-
7-Feb-17	Vehicle	250	-	No key on both key rings to secure the vehicle in regard to Drug management code of practice, and vehicle security. Remote locking does not lock the rear cabin side door. Rear suspension lowering switch does not consistently work	Unable to secure vehicle.	-
7-Feb-17	General Equipment	215	Isolated cable from use. to be tagged out when arriving at station.	15A male end of extension cable destroyed.	Failed to disconnect cable from vehicle prior driving. Magnet power socket sensor failure.	-
8-Feb-17	Vehicle	245	ROC and OIC notified	Vehicle is in limp mode and engine light is on	-	-
2-Feb-17	Vehicle	240	Fault form and accident claim forms filled out	Star shaped crack R) lower front windscreen	Object ? Rock struck windscreen whilst being driven on Gympie road highway	-
20-Jan-17	Vehicle	240	Taken to	When getting in to start vehicle, when 240v plug removed, both MDT and radio noted to be not functioning and vehicle would not start with dash message saying 240v attached. Bypass switch used and vehicle started but still no radio or MDT. Approx 10 mins l	-	-
20-Jan-17	General Equipment	240	Mechanic notified and to pick up for repair 20/1/17	Vehicle charger not working, on investigation charging plug on lead not connected adn wires severed.	Unknown	Replacement charger installed.
19-Jan-17	Vehicle	225	Normal cleaning, and checking of switches.	Side step not working. May already have been reported.	Probable impaction of granite sand and grit. Step unit is sealed and does not allow for easy routine removal of local granite sand.	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
20-Jan-17	Vehicle	225	Nil spare cables on station, cut cord has been taped and labelled. Nil spare units to swap, remains in operational unit.	Spo2 cable on corpus cut/spilt= exposed wires	Unknown	-
20-Jan-17	Vehicle	240	Faults report submitted informed ROC informed OIC	Check oil light illuminated and stayed on, upon visual inspection oil slightly below minimum mark on dipstick. Vehicle directed to be driven to Chermide stn and swapped with 562505	8116 vehicle fault report submitted stating 562152 was 5000km over due for a Service. Vehicle servicing due at 210,000km could be reason for low oil.	-
22-Jan-17	Vehicle	240	nil effct on driver vision. nil repair at this stage	Cracked wind shield. +_3mm	-	-
22-Jan-17	Vehicle	185	-	Connection under bonnet for windscreen wiper is faulty/old and won't now won't stay connected. Water function on wipers not working	-	-
22-Jan-17	Vehicle	230	-	Phone and pager have on two occasions not received messages whilst on buderim station...one instance was a station move and one was for a code one. Phone turned off and on again and eventually received message however pager never received message	-	Devices not operational due to intermittently not working however no other devices able to replace on weekend
23-Jan-17	Vehicle	230	OIC has contacted and arranged for the crew to drop in today 23/01/17 so see if any parts are needed for the fix. Part also needed for door. Belt is ordered. Operational.	Siren tone - weak and distorted, perhaps water in the system?	Unknown	will book 827 in for a service as soon as the parts have arrived to fix sliding door and siren issue. Vehicle is still operational.
22-Jan-17	Vehicle	230	fault form	vehicles fine. I have and swapped and tested the 902 base charging plate in 903 and it does not charge. This leads me to believe it is a plug/fuse problem.	I noticed the 903 round charging at the middle of the base plate is loose and has come off . I'm no auto electrician however I think This could have shorted the fuse???	This relates to the Corpuls power supply.
23-Jan-17	Vehicle	225	Unit taken to mechanics to be repaired/ made safe.	Fan in rear cabin. Fan mount snapped, fan hanging by wiring.	Probable vibration metal fatigue.	-
21-Jan-17	Vehicle	240	-	engine warning light flashing, loss of power while driving	-	-
23-Jan-17	Vehicle	185	Door still operation however will not hold half open.	Left rear door catch not engaging.	Fatigue	-
22-Jan-17	Vehicle	205	Battery replaced 23/01/17	Faulty battery	-	-
23-Jan-17	General Equipment	240	New one and a gps system	Mdt continually turns itself on and off.	Electric or Battery	-
23-Jan-17	Defibrillator	240	-	Broken printer door	Corpuls dropped on ground from stretcher during pt extrication	-
15-Jan-17	Vehicle	190	Vehicle booked into mechanic to have filters changed	Smell coming from AC	Deceased body	-
24-Jan-17	Vehicle	225	Will be taken to today?	No power steering fluid	-	-

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
24-Jan-17	Defibrillator	240	Out of service	Corpuls not registering when electrodes plugged in and therefore not charging or able to deliver defibrillation shock.	Found while teaching student to use equipment.	Fault found midshift, user test passed this AM 07:25 by QAS officer
24-Jan-17	Vehicle General Equipment	230	-	MDT fault. Initially frozen on home screen despite turning of at master switch. Now showing black screen with message "computer can't come out of hibernation"	-	-
25-Jan-17	Equipment	180	return equipment to cairns area office	portable radio hand piece not transmitting	-	-
10-Jan-17	Vehicle	200	-	Main access door to patient care module is inoperable from the inside of the compartment.	-	Temporary repair to side door completed by , replacement door handle being sourced.
2-Jan-17	Vehicle	225	Inspected by from 3 Jan to 9 Jan 2017 and pannel shop Quote on 9th Jan 2016. Unit parked at Highfields station for repaires etc	Damage to front of vehicle (inc windscreen drivers side)	driven into fence Happy Valley Road Cabarlah QLD 4352	OIC holding key for unit in Office
10-Jan-17	Vehicle	240	-	Catch on drivers side rear door not working. Car pulls to the left when driving	-	AOIC Note - Rear loading door, catch for yellow latch broken, door unable to stay open unless extended past side of vehicle. Requires replacement of catch. Vehicle serviced 6th of Jan, nil issues with tyres or wheel alignment reported.
10-Jan-17	General Equipment	185	Tried to clean terminal points in area and tried new batteries with no luck.	Batteries leaked into battery area, now doesn't work	Leaked batteries	-
10-Jan-17	Vehicle	240	Spoke to OIC and she has requested that we try and take the car to to get it replaced.	Right headlight not working	? Blown bulb	-
11-Jan-17	Vehicle	210	OIC to replace with Bulbs supplied.	Blown left headlight.	Unknown / investigated previously no aetiology determined.	-
11-Jan-17	Vehicle	210	OIC to reset and if occurs agian have diagnostics conducted.	tyre pressure light indicator active	Issue with this evehcile / repeatred diagnostics / no setioogy found as cause.	-
10-Jan-17	Vehicle	240	Nil	LED light inside boot has been dislodged -held on by tape	Unknown- was present on the car when I started rotation	OIC requested I place this fault report
11-Jan-17	Vehicle	240	Two new batteries placed in	Had lunch came back to complete dead batteries as per racq test	Not known	Spoke to roc IOC and pts
11-Jan-17	Defibrillator	215	Tech support contacted and repair organised	Unit is not charging	-	-
17-Jan-17	Vehicle	180	Took 7316 (250VDC) to - fault identified 17.01.2017	Back Right Tyre flat	Possibly slow leak, cause unknown	Fault identified and fault completed 17.01.2017
17-Jan-17	Vehicle	240	-	CombiCarrier cabinet gas strut broken, number plate lamp out, driver front headlight indicator out, handbrake cover broken	Unknown, found during vehicle check	-
16-Jan-17	Vehicle	240	OIC contacted to have fault fixed	Charging cable plug broken	Vehicle charging cable connected without driver knowing. OIC responding to 1A and drove forward leading to the breaking of the car side charging plug.	Vehicle repaired.

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
17-Jan-17	Vehicle	250	Attempted to extend but nothing will allow it to.	Rear seatbelt not extending to be able to be used. Fault form #7620 submitted in 12/2016 for same issue.	Nil	#7620 fault form submitted in 12/2016 with a reply email response to say it was fixed in 12/2016.
17-Jan-17	Vehicle	240	Reported to OIC	1. Damage to R) side of vehicle unknown cause or driver approx date Sat 07/01/17 2. Rear R) Break light does not illuminate when breaks applied 3. Reverse camera does not work intermittently when vehicle in reverse 4. 5000km over due for service	Unknown	A number of faults outstanding with 562152
18-Jan-17	Vehicle	225	Nil action taken.	Scrape to lower right side of vehicle and small orange light ripped off when mechanic was manoeuvring the vehicle in a tight bay to change tyre.	Unfamiliar with driving and manoeuvring large vehicle into work bay.	Small side orange light has been removed, therefore no longer working.
17-Jan-17	Vehicle	180	Booked in for mechanic to repair.	Minor oil leak from transmission case.	No	-
19-Jan-17	Vehicle	240	-	Drivers side seat belt will not retract. The seat belt stays loose and is dangerous to the driver. Also the GPS is not functional. The directions are not shown, the GPS seems to be stuck on one location.	-	-
19-Jan-17	Vehicle	240	Taken of road	Gap in rear door ,now worse after doing IFT and opening door 5 times ,when door is shut right strut is visible through gap	Unknown damage to right side of vehicle occurred earlier this week	Top right side of door lining coming away from main frame that holds door on
21-Jan-17	Vehicle	210	-	Upon inspection of rear module, the rear electronic control panel was hanging off the wall, the silicon appears to have separated and control was hanging by its wires. Tape has been applied to keep control unit on the wall as a temporary measure.	? possibly heat	-
21-Jan-17	Vehicle	235	Oil on floor has been mopped and cleaned. Leak still occurring monitoring the oil via dip stick	Oil leak	-	Will take unit on EA Sunday night and bring unit into Ipswich Monday whilst attending training and the vehicle can be fixed during this time
21-Jan-17	Vehicle	230	Nil	Warning light brake pads have reached operational limits	Normal use wear and tear	-
21-Jan-17	Vehicle	230	None, Zip tag replaced at station by O.i.C/ Staff	Defibrillator zip non-functional on BP cuff pocket. Zip needs new pull cord. Existing is missin	Unknown	-
21-Jan-17	Vehicle	235	-	Reversing camera has a blue screen. Suspension in unit is rough and uncomfortable both patent ride and front cabin. Passenger seat suspension caused aggravation of lower back injury	-	-
20-Jan-17	Vehicle	240	Called ROC	MDT is not tracking properly, unsure how to fix it. Comms can't tell where our vehicle is, think it is at whichever hospital or station we were last at. ROC didn't know what to do either.	-	-
23-Jan-17	Vehicle	225	Nil, fuel cap is still in place but requires replacement for security	Front fuel cap is not able to be locked with key	No, I returned to today and found that the fuel cap was unlocked and does not lock with the key, requires a new fuel cap which will then have to be locked with another key	-
23-Jan-17	Vehicle	225	-	Passenger rear door won't open and second stretcher can not be loaded/unloaded	-	-
23-Jan-17	Other Equipment	230	Loss form also submitted via Desportal BSG. Fleet Manager notified and he has arranged replacement phone.	Phone is in poor condition, the back falls off and does not hold a charge, frequently going flat which compromises the Op Centre contacting staff. Phone has not been wilfully damaged, due to age it requires replacing.	Age, wear and tear.	Phone has not been sent for repair as it is still being used but it needs to be replaced
24-Jan-17	Vehicle	240	Calling the OIC	Left light not working in the front of vehicle	No	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
24-Jan-17	Vehicle	195	Comms/SOS notified, coolant level checked, attended for check. Mechanic ?? sensor problem., coolant level ok and nil damage or leaks noted.	On arrival at Home Hill QAS (case 8427894) approx 1500 a yellow coolant warning light was noted on the dash. Comms/SOS notified. Coolant level checked, noted above minimum level.	-	-
24-Jan-17	Vehicle	240	-	Left rear indicator blown. Tyre pressure warning light on, pressure checked to be correct	-	-
24-Jan-17	Vehicle	185	This fault form, oic made aware	Left rear door retaining clip broken, door is not able to be locked in open position. Door slams officers in back if on slightest incline when loading or unloading stretcher.	Wear and tear/ old age, metal fatigue	Clip needs replacing
25-Jan-17	Vehicle	235	Radio has been restarted multiple times without any improvement.	Car Radio not sending or receiving any transmissions. Front compartment radio.	26-01-2017: OIC spoke with Officer & the fault have been resolved. The rear radio handset was off it's cradle. Once the handset was placed back into the cradle the front radio is now working.	Communications required via portable radios. Op Cen Notified.
26-Jan-17	Vehicle	235	Report	Siren not working - air horn not working Rear aircon control panel in front works intermittently Rear suspension extremely rough	-	-
27-Jan-17	Vehicle	230	Operations and MDT electronics tech notified of fault and are arranging time and place to rectify fault.	MDT INOPERATIVE	nil	-
27-Jan-17	Vehicle	225	nil	Passenger side headlight blown	-	-
27-Jan-17	Vehicle	230	-	GPS Not working. Ongoing issue been investigated previously by . Not resolved	-	-
27-Jan-17	Vehicle	210	-	Hinge on rear door broken	-	-
27-Jan-17	Vehicle	240	The stretcher has been left at the Caboolture ambulance station until it is repaired.	Left powered Stryker stretcher legs not fully retracting when pushing " - " button while loading. Stretcher is unable to safely load into vehicle as it cannot correctly lock into place. Vehicle loader tested using other stretcher and had no issues.	-	Stretcher can be lowered to ground level safely, however when loading, cannot fully retract legs. ROC has been notified
11-Jan-17	Vehicle	200	Attempted to reset GPS with no success.	Garmin GPS faulty, continually restarts, unable to progress to menu. Unable to be used as GPS.	-	GPS replaced
11-Jan-17	Stretcher	195	pt (fully restrained) assessed for injuries, SOS and Comms notified, stretcher taken offline and replaced	case 8383357 1420 stretcher drop as unloading pt carpark mental health	upslope bitumen, front legs failed to deploy	-
12-Jan-17	Stretcher	230	Partially taped rip	Integrity of mattress topper ripped infection hazard	Wear and tear	-
14-Jan-17	General Equipment	215	Shaking, pat dry, put on top of aircon vent.	Pager for unit 4411 slipped out of wet hands and landed into a bucket of hot soapy water.	Comms dispatching cases	Pager recovered fine - no further action
15-Jan-17	Vehicle	240	Vehicle marked OOS. OIC advised	Nil electrics to vehicle. Key inserted into ignition - nil electrics, nil engine turn over. Vehicle plugged in. Nil master switch or emerg start function.	Unknown	-
15-Jan-17	Stretcher	245	Stretcher seems to be working ok but needs to be cleared by tech.	Stretcher became stuck while loading large pt onto lever.	Loading large pt onto lever - pt was leaning to the L side which caused stretcher to get stuck under sliding part of lever	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
15-Jan-17	Vehicle	245	Corpuls put at OIC door with 'out of service' note attached. I took the corpuls from out of service vehicle 5264 for use during the shift.	During start of shift check I found the vehicle 5266 Corpuls not printing correctly. It looks like it's run out of ink. Printing appears faded and most of printout missing.	Appears to have run out of ink.	-
15-Jan-17	Vehicle	245	Called October and put note on bored at station	Leaking internally where aircon vents are	-	-
16-Jan-17	Vehicle	200	Duty officer and Comms centre notified, vehicle taken off road.	Vehicle siren permanently ceased working whilst engaged on a code one job.	Unknown	-
16-Jan-17	Vehicle	210	-	Fan belt is squealing when engine is started or engine is running.	-	-
17-Jan-17	Vehicle	235	Powered vehicle off and on again. Turned main MDT switch on and off. Ensured main cord to MDT attached correctly.	MDT not starting up.	Unknown. Noticed at start of shift check. Was working yesterday however noticed it rebooted twice while on cases.	-
17-Jan-17	Vehicle	240	reported to OIC	bonnet opener driver front fallen off intact in vehicle on dash board	unknown found when arrived on duty	can operate manually but not good as could break the opener doing this requires re-attachment
18-Jan-17	Defibrillator	215	monitor damage and replace when appearing to fault.	Black LA) ECG connector has had some of its black protective covering broken. Nil issues to functionality as of yet... in 4412	(ab)use	-
18-Jan-17	Vehicle	225	Nil	Loses power when turn key Step won't come out	Has happened before but battery was replaced and fault not investigated	-
18-Jan-17	Vehicle	225	Nil	No power when turning key even after charging	Reoccurring fault not investigated	-
17-Jan-17	Vehicle	250	-	Rear air conditioning not working.	-	Front cabin working.
18-Jan-17	Vehicle	185	Nil	The Main switch is not turning on. When you do press the main switch the screen blinks a few times and then the siren comes on with it being off on the panel.	Unkown	-
18-Jan-17	Stretcher	210	Stretcher taken off road.	Stretcher used for pt weighing approx 200kg	-	Stretcher taken out of vehicle 2185 and put on station near outside laundry for review. Spare stretcher from 2286 placed into 2185 in mean time
19-Jan-17	Defibrillator	240	-	Bracket that hold corpuls together has broken. This occurred while it was hanging on stretcher bracket behind head.	-	-
19-Jan-17	Vehicle	245	FAULT REPORT	STRANGE SOUND AND HIGH REV'S. SOUND COMING FROM ENGINE, ? TIMING BELT, FEELS HEAVY AND SLUGGISH AROUND BRAKES	NIL	-
19-Jan-17	Vehicle	245	FAULT REPORT	FUNNY/STRANGE SOUND COMING FROM UNDER BONNET IN ENGINE. ? TIMING BELT, REVVING HIGH. BRAKES FEEL SLUGGISH AND I WOULD NOT BE COMFORTABLE DRIVING THIS VEHICLE IN CODE ONE CONDITIONS.	NIL	UNSURE IF SAFE TO CONTINUE DRIVING WITH THE ABOVE SOUNDS.
25-Jan-17	Defibrillator	240	Replaced patient cable	Faulty SPO2 sensor	Apparently damaged patient cable	No visible damage to cable
25-Jan-17	Vehicle	240	Tyre replaced	Nail in rear right tyre	-	-
25-Jan-17	Vehicle	200	Duty officer notified, she report filled out	Very mor dent in rear step silver bar	Reverse into pole	-
25-Jan-17	Defibrillator	215	changed brightness in settings with no effect. Monitor taken from 4417. Broken defib placed on OIC desk.	Back-light not working. Screen functioning however no brightness.	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
25-Jan-17	Vehicle	195	Notified SOS. And OCS	Airbag in the suspension went bang.	-	-
27-Jan-17	Vehicle	245	tried ringing the OIC, message left on his phone ... Comms notified and last job was reassigned.	when removing stretcher for last case of the day, the R/H side rear door strut attachment broke off at the top, leaving only the left strut attached to the door. The door won't stay open and is very hard to lift, also doesn't close properly.	wear and tear ...age	-
28-Jan-17	Vehicle	185	Taken off road	Mains fault intermittently not working. Also breaks are spongy and needs attention ASAP	-	-
28-Jan-17	Vehicle	245	AOIC has referred matter on to for rectification as issue affects all new ambulances.	No charging plug in the front cab to charge ipad	-	-
29-Jan-17	Vehicle	225	-	Front module panel not working won't turn on. Main power supplied to rear cab however nil power or function to front module screen. No sirens/lights or aircon	Unkown	-
29-Jan-17	Vehicle	215	notified	check engine and glow plug lights on. Also ? brakes spongy as per Daily vehicle checklist	nil	Can be driven. non operational until rectified
29-Jan-17	Stretcher	235	Stretcher has been taken out of service for maintenace	Rear legs of stretcher did not adequately unfold to support a patient	Unknown - ?sticky mechanism	Stretcher appears to be functional when tested without a patient. However, reflective arrows when stretcher fully raised to not meet.
30-Jan-17	Vehicle	210	This report	Vehicle locking mechanism failure		When LOCKED, back door and side entry door of module still accessible. Driver door remains locked until back or side door are opened, then unlocks also. All other doors remain locked until vehicle is unlocked
30-Jan-17	Vehicle	185	Taped on to prevent damage to wiring.	Front driver side flasher bracket broken, currently held on with tape.	Plastic bracket possibly brittle from sun/age.	Nil.
30-Jan-17	Vehicle	235	nil - seat needs recover and arial appears stuck unable to release.	Tear to driver seat base, arial motor running with no arial movement.	-	-
30-Jan-17	Vehicle	240	OOS	Whilst driving the Engine Light started to flash. Vehicle was turned on and off multiple times with no change. OC notified and vehicle taken to and ' said that he was able to clear the warning light if returned the take off road.	? Vehicle exhaust issue	-
30-Jan-17	Vehicle	215	Will have to be taken to the auto electrician when someone is available to do so.	Main switch panel working intermittently again.	Unknown	-
30-Jan-17	Vehicle	215	-	Main switch panel working intermittently, spotlights switch , rear arcon switch and when scan lights etc are switched on the panel does not light up to indicate switch/ scan light is on.	-	-
30-Jan-17	Vehicle	250	spoke with Mick Skea who will arrange for auto electrician to come out to station tomorrow	vehicle dashboard notification indicates that the external power is still connected. this is not the case, power cord disconnected and power light not showing. flap appears to be closed properly	unknown	CDS aware.
29-Jan-17	Vehicle	230	-	Transmission not changing gears properly will not maintain speed up hill maximum speed 100kph and engine fault light on dash aluminated	-	-
30-Jan-17	Stretcher	245	This report, spoken to OIC.	Upper stretcher buttons not working.	Found during vehicle checks yesterday.	I will complete the SHE report as soon as I can.

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
31-Jan-17	Vehicle	225	None, new deep cell battery fitted.	When driving back from Brisbane vehicle lost aircon and radio connection.	Don't know. Low battery power resulted in this fault.	When driving back from Brisbane noticed aircon stopped working as it got super hot. Heard a clicking sound from rear aircon unit.
10-Jan-17	Stretcher	240	Battery changed using vehicle spare, resulting in return to normal function.	Power failure in lifting, rapidly losing power during lift before stopping prior to loading height. This is the second time this fault has occurred. Vehicle overheating / high temp warning . While idling, also came on going up hill.	This is as a result of stretcher not charging while in the docked position. Battery charging light does however flash while docked.	-
11-Jan-17	Vehicle	250	Coolant level ok	Also side door not sliding freely.	-	-
13-Jan-17	Vehicle	225	-	Driver side battery door compartment sensor alarming even when door closed.	-	-
13-Jan-17	Vehicle	210	-	The outer cannister of the vehicle suction has come away from the red section of the suction (the part with the on off tap (see picture) MDT not working completely black screen. Unable to receive any job details.	It was found during pre-shift checks today, but we think it may have occurred yesterday when a post arrest pt was Tx to Rockhampton, with suction used.	Update at 11:37 Sat...we've borrowed the suction unit from PTO unit 2641 at Rocky, to keep 2190 going over the weekend.
17-Jan-17	Vehicle	240	OIC reported to OSU service dept contacted and Service Technician will attend QAS Biggenden on 17/01/2017 to rectify fault.	-	Unkown contact and repaired on same day.	-
16-Jan-17	Stretcher	215	-	On trying to operate stretcher, the stretcher legs would not extend with button - error code 62 on LCD screen	Unknown	Stretcher found to be faulty prior to any Patient involvement. SHE report not completed.
17-Jan-17	Vehicle	225	None, front end alignment done, new front light ordered.	Front left hand bull bar light broken, unit pulls to left when driving, rear tyres need valve extenders, tyre pressure needs checking as ride is very rough	New vehicle, unknown about light may have been a stone	-
20-Jan-17	Vehicle	185	Auto Electricians have inspected the vehicle and suggested it be referred back to manufacturer.	Flashing Lights and sirens turning on when using the radio. Master switch only way to turn it off again.	Possible moisture in circuits. Previously repaired for same fault. 12mths ago.	-
21-Jan-17	Vehicle	230	DVR form submitted,	SRS warning light illuminated at all times when engine is turned on. CDS advised off road to be reviewed by mechanic.	-	-
21-Jan-17	Vehicle	185	-	Air conditioning unserviceable	-	Vehicle operational, however, air con u/s, so too hot to use
21-Jan-17	Vehicle	230	oCS notified. dVR completed.	Back door will not open. Vehicle stalled at fuel station. Will not start	unknown	-
21-Jan-17	General Equipment	200	The ampoule has been removed from service and Mackay Duty Officer has been notified via email.	Approximately half the contents of the ampoule is missing. The dark colour of the label would indicate the fluid has leaked out.	The seal of the ampoule remains intact, but the screw top lid appears to be cross threaded.	Photos of the ampoule have also been forwarded to Mackay SOS
22-Jan-17	Vehicle	195	Tried to inflate but unable to	Flat right front back tyre what more than that	No	-
21-Jan-17	Vehicle	230	Fault form, plugging vehicle in.	Vehicle has been plugged and turned on and battery still having problems. First code one the MDT and radio stopped working enroute and siren went dull. Today internal lights fading	-	Battery monitor has bottom reading 'lo' and doesn't increase when plugging vehicle in
22-Jan-17	Other Equipment	230	OIC searched for pager unable to locate - all crews interviewed and emailed unknown where pager is located.	Misplaced Pager	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
23-Jan-17	Vehicle	185	-	External access door to the cabin will not open. Door is unlocked with the light on. Car was charged overnight. Will not open even with vehicle on. Same problem was reported last week.	-	mechanic and could not fault unit doors when inspecting on 27/1/2017.
23-Jan-17	Vehicle	215	New clutch fitted	Clutch slipping under load in soft sand Stater only engages every third turn of the key	Operational environment	-
21-Jan-17	Vehicle	195	Out of service for nightshift (due to safety issue)	L headlight blown	-	-
24-Jan-17	Vehicle	240	Mechanic contacted and vehicle jumpstarted and driven to remain on charge as much as possible.	Flat battery.	Faulty charging.	Repaired 24/1/17
6-Jan-17	Vehicle	195	Taken to repairers	240 volt requires checking	Nil	-
10-Jan-17	Vehicle	240	-	Refrigerator not working, passenger side tail light not working	-	-
11-Jan-17	Vehicle	235	-	Unit radio not sending or receiving..... error message when attempting to transmit. Fm radio also poor reception ? Related.	Problem found on first job.	-
12-Jan-17	Vehicle	245	Took torch out of holder, informed ROC and OIC. Torch was extremely hot to touch.	1400- driver side torch in holder started to heat up , with smoke and fumes entering the cab. Pulled car over and took "HOT" torch out of charger. Aired vehicle out, then continued with patient to hospital. No side effects to patient from fumes noted.	-	-
13-Jan-17	Vehicle	240	VOR	Vehicle smoking extensively - black smoke entering cabin, oil/diesel? leaking from exhaust on to rear of ambulance.	-	-
13-Jan-17	Vehicle	245	Isolated all power and ensured all lights and radios turned off. Left to continue charging.	Flat battery	?	-
13-Jan-17	-	245	-	Vehicle 501169 step broken	Doctor exiting vehicle, step gave way. Nil injuries, step contacting ground	-
15-Jan-17	Vehicle	210	N/A	Passenger side rear door seal is broken. Unable to close door properly.	Unknown	Photo in checklist for 15/1/2017
15-Jan-17	Vehicle	185	-	External access door to cabin is not opening. Car is unlocked and light on unlocking button is alright, however door is not unlatching. Car was charged overnight.	-	-
15-Jan-17	General Equipment	245	-	Old MDT - issues with tracking that are persistent and ongoing. Also poor coverage in general response areas ((Parkinson, Calamvale, Algester). This provides a safety risk to officers and operational issue due to poor AVL	-	-
15-Jan-17	Vehicle	230	A plastic bag is placed into the unit when one is available. Vehicle checked at have ordered a replacement bin which should be replaced with service today 25-01-17	Bin in rear of vehicle has no Insert from which it's rubbish may be emptied.	Has been missing from vehicle for several weeks. Was cracked / broken before being removed from use.	To empty the bin one must remove the rubbish using ones hand to remove the waste piece by piece which can contain contaminated items or misplaced sharps. This presents an unacceptable risk to crews every day. It is the only bin available in the vehicle.
15-Jan-17	Vehicle	230	Report completed	Front right parking light u/s	Blown bulb	-
15-Jan-17	Vehicle	230	Complete report.	SPO2 lead has damage to cable.	Unknown	-
15-Jan-17	Vehicle	235	Nil at this stage	One battery is flat, can start on Aux battery but can't start on other battery.	The car was plugged in on power. There have been some hot days recently.	Can run on aux battery but best to get battery fixed due to use on EA and not plugged into power.

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
17-Jan-17	Vehicle	240	Reported and placed out of service	Low oil, low coolant, tyres need replacing	-	-
16-Jan-17	Vehicle	190	Cloncurry 4WD has ordered new light to be installed pending arrival	Rear L brake light not working	-	-
18-Jan-17	Vehicle	225	Sos informed, car towed to for assessment.	Noise from under bonnet, followed by steam/smoke and an acidic smell from unit	-	-
18-Jan-17	Vehicle	225	-	Chipped windscreen	Not known	-
19-Jan-17	Vehicle	230	checked charger in car and in 405793 where it worked OK 24-1-17 discussed with Brakes charging socket and fuses to be checked at when vehicle on afternoon shift 25-1-17 .	Corpuls charger in vehicle not working, nil power from vehicle 12 volt supply plug.	was present at start of shift - unknown when issue began	Vehicle rostered for night shifts - on charge on 240 volt charger when not in use for shift. Plug socket in vehicle found to have broken wires inside fixed at with vehicle service
19-Jan-17	Vehicle	225	Book service	Due for 20000 service as reach the 6 month interval by time	Routine service	-
19-Jan-17	Vehicle	240	I talked to my OIC at the station about it	The reverse camera is not working at all	No	-
24-Jan-17	Defibrillator	245	Taken off vehicle in oic Jimboomba office. phoned and given oic number. Stated they would call oic	No battery inserted (defibrillator) error message in top bar	Don't know	Be and 4 lead monitor worked. Unsure of operational ability of machine. Unplugged and replugged defibrillator pads, turned machine on & off, no diff noted
11-Jan-17	Vehicle	225	I ring my OIC and drove the vehicle back to station	Requires 4 new tires	-	4 tyre to be fitted on Friday.
11-Jan-17	Vehicle	240	PTS dispatch and informed	Air suspension not working in the back on vehicle	N/A	-
12-Jan-17	Vehicle	230	-	Flat battery	240 V supply cable not fully plugged in.	-
11-Jan-17	Vehicle	240	-	The air-conditioning control knob that changes the temperature for the front half of the vehicle (furthest right) is jammed at full cold.	Unknown - returned from service not working	Speed odometer approximate
13-Jan-17	Vehicle	245	Comms advised, RACQ requested to start	Flat battery	Main switches left on	RACQ attended and started vehicle
20-Jan-17	Stretcher	245	OIC notified. Recorded sound and sent to	Right side red handle for retracting head section of stretcher is snapped in two. Audible sound from front wheels. This sound is pronounced whilst accelerating between 40-60kms.	Possible issues when loading uneven surface.	-
21-Jan-17	Vehicle	210	-	Cracked windscreen, lower left corner approx 30cm in length.	Unknown	-
22-Jan-17	Vehicle	235	Defect report and notified OIC	Side door step not retracting when door is closed/ vehicle in operation.	nil	-
23-Jan-17	Vehicle	210	notified OIC	Brake light not working. Been assessed by ...needs a new LED assembly.	Unknown	-
23-Jan-17	Vehicle	240	Referred to for repair. Notified acting Fleet Co-ordinator.	Air conditioner in Module is not blowing air.	-	Vehicle tagged OOS and to be picked up 24/1. Awaiting parts 7/2/17.
24-Jan-17	Vehicle	225	ordinator.	Drivers side low-beam out. MDT mount faulty.	-	Taken off road due to patient safety concerns.
24-Jan-17	Vehicle	240	Nil	-	-	-

RTI Release

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
24-Jan-17	General Equipment	250	Notification	On/Off button missing	Discovered to be missing on commencement of shift	-
25-Jan-17	Defibrillator	240	placed other corpuls monitors in cradle, all charge. have placed faulty corpuls in other vehchle cradles and will still not charge. contacted service provider for repair	corpuls not charging in cradle. charge light will come on if base of unit is slightly lifeted while in cradle.	-	-
25-Jan-17	Vehicle	190	liased with for trouble shooting over the phone. They have informed me that they will liase with the BM for part ordering. Part has arrived from LASN office 2/2/17.	fuel filter leaking	-	-
25-Jan-17	Vehicle	240	AUTO-ELECTRICAN	Side step sagging. Front cab Emergency light PANEL not working e.g: Rear interior light switch, A/C Rear switch, and the entire PANELS 'back-lit' light is not working. Critical for night shifts! 12Volt power in front cab not working.	UNKNOWN	-
25-Jan-17	Vehicle	230	Fault report form filled	Side step not extending out	Not known	-
27-Jan-17	Vehicle	235	Fleet advised.	Rear door not unlocking, has to be opened from inside. Rear door sensors faulty activating rear beacons unexpectedly. Side door to patient module unable to be secured lock faulty.	-	-
27-Jan-17	Vehicle	240	Notified communication centre.	Foot step not going back in.	-	-
27-Jan-17	Vehicle	225	-	Unable to charge corpuls, vehicle could be used however corpuls must be charged externally in station.	-	-
27-Jan-17	Vehicle	225	Replaced seals at bottles and checked all visible connections for leaks.	Rear "D" size O2 leaking. Bottles are turned off and within 2 hrs low O2 alarm is sounding. Have replaced both seals at bottles and checked connections at hoses. No obvious leaks at flow meters and connections at wall.	-	-
28-Jan-17	Defibrillator	230	Unplugged and replugged the lead. Check to see if red light showing on sensor, which it was.	SpO2 lead not registering pulse oximetry	Unknown cause	Everything else works except the faulty lead. Unit located in 4859.
29-Jan-17	Vehicle	240	Turned car on and off.	Engine light on dash	-	-
10-Jan-17	Vehicle	215	-	Windscreen chip drivers side	-	-
9-Jan-17	Vehicle	230	Advised CDS	Front right corner stoved in, extensive damage	Hit a large kangaroo	-
13-Jan-17	Defibrillator	210	Tested another lead from a different machine and EtCO2 works fine.	EtCO2 not registering waveform.	-	New lower lead required.

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
16-Jan-17	Vehicle	215	has ordered replacement set belt and observation seat cover. Rear door oiled however they have suggested removing door and cleaning dust from hinges. Rear door stay glued and to be monitored	1. Front passenger seatbelt is worn, out of shape and not retracting correctly 2. Rear front facing passenger observation seat is missing the seat belt retractor cover 3. Rear compartment drivers side door squeaky and back door stay loose	Unknown Vehicle was involved in a rear end impact collision in 2016	feel that the front passenger seat belt would fail vehicle roadworthy, however vehicle is still operational with 2nd officer sitting in rear of vehicle.
17-Jan-17	Vehicle	240	Part has been ordered?	Broken cable in boot disabling vehicle tracking		-
20-Jan-17	Vehicle	195	Fleet notified	Vehicle was repaired yesterday but again failed to open door to rear module side entry. Found charge indicator light under 240v plug flashing every 2seconds . Reported to oic and fleet manager	Unknown ? Charging unit	-
20-Jan-17	Vehicle	210	Defect Form completed Previous fault form #7056 on the 4/12/16 completed and no action has been taken	Mechanism to alter position and angle of the driver seat is broken.	When completing vehicle checks, noticed the handle was missing and had been placed in the side of the door. On closer inspection to the inside of the handle there are multiple stress breaks to the plastic.	Photo included in email sent 1918 20/1/17
4-Dec-16	Vehicle	235	as of yet	Reversing camera not working, showing blue screen when cars in reverse	-	-
23-Jan-17	Vehicle	225	nil	Transmission fluid below acceptable level.	-	-
23-Jan-17	Vehicle	245	attended to replace bulb	Front left headlight blown	-	-
25-Jan-17	Vehicle	215	- Contact Nambour OIC. ON	Passenger window frozen in up position Suspect door switch / electrics problem	Fraser Island	-
25-Jan-17	Stretcher	230		Backrest not functioning.	Gas strut defective	4969 353MED - stretcher left at Nambour General Hospital.
25-Jan-17	Vehicle	225	Nil	Bolt housing broken on plate near front L wheel	Unknown	-
28-Jan-17	Vehicle	195	-	Vehicle not charging when plugged in. Tried different power cables and different plugs, still doesn't charge	-	-
28-Jan-17	Vehicle	210	-	Height adjustments lever on drivers seat broken	-	-
28-Jan-17	Vehicle	240	ROC notified and vehicle taken back to spring hill station.	Air Conditioning not working in rear of ambulance, Aircon working fine in front cabin however not flowing out vents in the back of ambulance.	AC fan unit in back module failed.	Vehicle drives fine however taken out of service due to climate at this time of year making working air con essential for safety of staff and patients.
29-Jan-17	Vehicle	235	- Notified SOS was advised to let OIC deal with it	More toggle switches are becoming very loose on light panel	-	At the moment, so spare units at stn due to other breakdowns
30-Jan-17	Vehicle	225	when she starts.	Bonnet can't be opened due to bonnet release lever not working	-	-
30-Jan-17	Vehicle	215	-	Leaking water over the patient care seat and the stretchers. Appears to be coming from roof and ?light fixtures	Unkown	-
31-Jan-17	Defibrillator	250	Fault form completed + email to OIC	Blue alarm- "CF card almost full" Rear reversing camera sensors not working correctly, also air conditioning in front cabin not working effectively.	-	From vehicle 6512.
31-Jan-17	Vehicle	210	-	MDT shuts down without warning	Unknown	-
31-Jan-17	Vehicle	240	Checked at		-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
1-Feb-17	Vehicle	200	-	Crack in windscreen	-	-
10-Jan-17	Stretcher	250	Replaced stretcher at hospital	Back wheels did not extend when pulling out.	Not sure.	SHE report completed and investigated
11-Jan-17	Vehicle	240	Car taken to mechanic. Battery replaced.	Module/Aux battery not holding charge. Drops to low moment the ignition is turned off.	-	-
17-Jan-17	Vehicle	185	and SOS notified.	? Rear axle bearing fault. On return transfer from Cairns - Atherton along Kennedy Highway on a straight and smooth stretch of road vehicle, the vehicle was continuously shuddering in the the rear at speeds up to 100km/h.	N/A	Complaint received from patient regarding uncomfortable ride, due to shuddering, and condition of QAS vehicle maintenance and safety, as he was a career truck driver.
18-Jan-17	Vehicle	210	Vehicle taken out of service and reported.	Damage to rear bumper bar and top rear right side. Reverse sensor still attached but swinging freely and picks up anything in close proximity when reversing..	Accident form to be submitted by Officer on return to work tomorrow..	-
18-Jan-17	Vehicle	235	Supposedly was fixed, clearly not. Checked again 5min before fault report submitted again. Previous Hazard ID form raised.	Rear sliding door still loose and likely to cause injury to persons. Passenger side sliding door is continuing to close without timfluence from human intervension and when time taken to lock in open position it closes unexpectedly on any incline.	Dont know what caused it.	-
21-Feb-17	Vehicle	240	RACQ called to jump start	Flat battery	? Excess electrical load during short period of engine off	Will be operational after RACQ jump start, plan to charge battery via alternator
18-Jan-17	Vehicle	190	-	Exposed wires on crossband UHF radio hand piece	-	-
18-Jan-17	Defibrillator	245	Reported via this form, contacted OIC,	12 lead ecg cord broken at socket, part of socket still remains in port, unable to extract	Whilst loading power stretcher into ambulance cord hooked into chair and broke	Nil
20-Jan-17	Vehicle	245	Notified and spoke to as vehicle is due for service on Monday the 23rd.	Approximately 30 min into the shift, noticed crack in front windscreen drivers side. Crack getting worse while driving. Also notified Comms.	-	-
20-Jan-17	Vehicle	245	Fault sheet completed replaced door components and bin rails replaced	Electronic side door not working, cable belt has snapped, door is unable to be fully closed at times	Side door was in perfect working order at completion of arvo shift on Thursday, unknown what has happened during Friday IHT shift	-
23-Jan-17	Vehicle	210	-	The top right rear break light is not working.	-	-
22-Jan-17	Vehicle	235	Nil	MDT, radio, beacons and siren turn themselves off while driving. Radio, beacons and sirens usually every 5 minutes or so	Unknown however when items turn off there is a click sound from the radio and also from behind the rear passengers seat	No effect on vehicle driving however missing sit reps from crews and several episodes of lights and sirens Turing off mid intersection while driving code 1
24-Jan-17	Vehicle	240	OIC notified ROC recommended workshop in am	?flat battery RACQ attended stated flat on testing// plugged in o/night with master switch off //drove fine until stationary for period, today.	?flat battery RACQ reported probable cause and suggested new battery	-
24-Jan-17	Vehicle	240	reported to ROC / OIC	?flat battery won't start after stationary for periods past 2 days (recharged by RACQ) RACQ suggested new battery	RACQ stated flat battery	-
24-Jan-17	Vehicle	230	-	In car phone charger not working	-	-
25-Jan-17	Vehicle	235	Replacement	Work lights are out rear right left side	Burnt out led's	-
25-Jan-17	General Equipment	220	internitant fault only - able to be resored by deactivating master switch- alternative secondary and tertiary communications available	intermitant radio fault	Effected by Master switch - radio fault noted when master switch is on	persistant known fault

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
25-Jan-17	Vehicle	225	Fault report completed	Faulty R scan L scan toggle switch in drivers compartment overhead console	Back up Murgon driver stated this am that switch suddenly came loose and stopped working when turning off	-
25-Jan-17	Vehicle	205	-	Service A required	-	-
10-Jan-17	Vehicle	180	Auto electrician notified and available to collect vehicle	Module touch pads in rear of vehicle require checking. panel closest to side access door blank screen and panel beside rear facing patient care seat show buttons but just beep when pressed functions do not respond eg turn on vent fan or adjust lights etc.	unknown	Auto electrician collected vehicel at 9:30 10/1/17
10-Jan-17	Vehicle	210	tried to report yesterday, but did not have access to computer	Drivers side scan light detached / fell off	alleged officer drove into the station and did not give enough clearance into getting into the bay and took the scan light off against the pillar of building	will get to do a SHE report and accident insurance form when next of duty. i submitted this form on his behalf as not working today (ADB course) and i needs to be rectified.
14-Jan-17	Stretcher	210	-	Holes/tears in the mattress	Unknown	-
15-Jan-17	Vehicle	230	N/A	In-car stereo/radio - not able to pick up any radio stations- sounds insignificant BUT when driving 2hrs + for transports to Brisbane - station coverage of 1 hr+ it is very relevant for staff comfort and for fatigue resistance.	N/A	-
15-Jan-17	Vehicle	210	Checked button in vehicle is pressing in properly, all parts of wiper blades still attached, holes in wipers where water jet comes from are not blocked and poured hot water on them incase of simple blockage, water under bonnet full	Wiper Blades - water jet not working	NA	-
15-Jan-17	Vehicle	185	Numerous attempts to lock/unlock veh	Rear door - right hand electronic lock sticking, meaning door can only be opened from the inside	-	-
17-Jan-17	Vehicle	235	comms, OIC and SOS notified	left front headlight blown	unknown	-
17-Jan-17	Vehicle	195	Nil	Air conditioning in the front of the vehicle not working	Unknown	Air conditioning in the rear of the vehicle is working
24-Jan-17	Vehicle	180	mechanic checked and reporting quote to fix problem	noise in front end of vehicle from wheel ? right side, but at time both. Also when going over bumps noise is worse.	local rough roads	-
25-Jan-17	Vehicle	180	will contact fleet	side scanners lights only work when vehicle is stationary	? fuse ? electrical	-
26-Jan-17	Vehicle	250	Unit taken apart and re connected. Unit still not working	Wall mounted suction unit not working	-	-
27-Jan-17	Vehicle	240	Crew advised ROC. Vehicle towed to holding yard.	Truck lost all engine power and would not change gears. The car would not go above 20km/h. Crew attempted to limp the car back to station inline with conversation with the ROC however the engine began to whistle after slowly climbing an incline.	Unknown cause whilst driving. Nil smoke, nil engine lights, nil visible fluid leaks under the bonnet / car body.	-
28-Jan-17	Defibrillator	250	Machine OOS	CF card full	-	-
28-Jan-17	Vehicle	240	-	MDT not turning on	-	OIC reported to OSU

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
29-Jan-17	Vehicle	230	Fault form last week, took to , diagnosed fault, had a service - ? Fixed identified fault, failed today, fault form completed today, notified OCS, removed vehicle from service & request additional assessment at	Mains power battery fault. Losing power and not charging on mains power. Charging via alternator only.	stated damaged fuse last week when we reported it & took it in for assessment.	-
29-Jan-17	Vehicle	245	-	Stretcher release button not releasing. Stretcher stuck in vehicle.	-	-
29-Jan-17	Defibrillator	240	Removed from the vehicle and reported the fault	Pulse ox failed during patient treatment. It initially had a reading then stopped working. Nil light at the probe.	Unknown	OIC replaced cable with station spare
29-Jan-17	Vehicle	250	OIC notified. Fault form completed	Glove box detached from dashboard	Unknown. Like this when first utilised	-
30-Jan-17	Vehicle	245	Temporary repair to re-attach screen to body of unit	MDT screen has separated from body of unit.	Possibly heat related as vehicle is parked outside station and windscreen is exposed to full sun. Expansion of unit due to heat possible cause.	-
25-Jan-17	Vehicle	210	-	Right side lower front beacon on bull bar staying and not flashing	-	-
29-Jan-17	Vehicle	250	Powered down the MDT and re-started.	Sat Nav not working on MDT.	-	Using QAS issued iPad Maps to assist Navigate to cases with UBD.
29-Jan-17	Vehicle	230	Pulled over, turned the vehicle off, back on again. No change.	In limp mode. Engine light flashing.	Unknown.	Vehicle currently parked at QAS Nambour.
29-Jan-17	Vehicle	195	Fault form filled out, not operational tag placed on key hook	Enroute to TTH with a pt, driver noticed burnt like smell coming through the air con vents.	Possible over heating?	Hood of engine lifted at TTH. Bonnet hot to touch and smelt burning, SOS advised, Returned to station to change into another vehicle.
30-Jan-17	Vehicle	200	Fault form completed/vehicle checklist.	Front Left Drive Light (low beam) not working.	N/A	-
30-Jan-17	Vehicle	230	-	Tissue box holder in rear compartment missing.	-	-
30-Jan-17	Vehicle	250	Radio and MDT Restarted on its own. Sos notified, contacted technicians ? Aux battery issue, advised by sos to take vehicle off road on completion of shift and will be looked at by technician the following day.	Main radio and MDT powered down while vehicle idling @ GCUH and would not turn on. Fault witnessed by sos . (restarted when returning to station)	? Aux battery	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
30-Jan-17	Vehicle	205	Took the vehicle into who replaced the reserve battery and put the original battery on charge overnight to see if it will hold a charge	Reserve battery with low charge and does not seem to hold a charge	Maybe old battery and very little vehicle movement, only around town	The reserve battery looks like it was last replaced in 2015 but the main battery was replaced at the end 2016
30-Jan-17	Vehicle	215	nil	Front passenger mud flap broken.	Attempting to reverse into steep downwards sloping narrow driveway at a residence at the Hummock, hit passenger mud flap on steep guttering, breaking mud flap. Poor visibility due to night time (2250hrs), nil street lights and narrow uneven divided road.	Please refer to vehicle checklist for photos
31-Jan-17	Vehicle	235	nil	Vehicle engine line on, vehicle nil power on acceleration, high revs.	??	-
31-Jan-17	Vehicle	210	-	Front vehicle display screen (battery; oxygen etc.) is dead, however all lights and sirens are working and vehicle still operational.	-	-
31-Jan-17	Vehicle	195	-	Rattle in front left suspension area. Problem when braking at low speed while forward motion and reverse.	-	-
31-Jan-17	Vehicle	235	Towels have been placed over the areas.	Vent from air conditioner in rear compartment was leaking water onto assessment kit are y seat.	Leaky air conditioner	-
31-Jan-17	Stretcher	240	The vehicle has been put out of service	Whilst loading the and retracting the legs with a pt on board the stretcher appeared To drop suddenly and the stretcher and pt was caught and stopped from falling further	Unsure	The SHE report was completed at the end of shift Tuesday 31 January 2017. The Caboolture OIC - was notified today at start of shift Wednesday 01 February 2017.
1-Feb-17	Vehicle	235	Vehicle taken off road. Sos notified who told the fleet team	Vehicle warning light stated we had to stop the car as the coolant temp was too high. Nil steam or issues with the use of the car. Nil fluid leaks noticed at the beginning of shift	Unknown	-
1-Feb-17	Vehicle	230	Taken vehicle off road	Smell of fumes from recent repair in back cabin of vehicle resulting in officer developing a headache during a transfer from Noosa hospital to SCPH case number 8453821	-	-
1-Feb-17	Vehicle	250	the MDT unit had been turned off but power supply is not cut to equipment.	MDT failure- message reads "the last attempt to resume the system from its previous location failed. attempt to resume again?"	-	-
2-Feb-17	Vehicle	210	-	Vehicle pulling to left when driving	unknown	-
2-Feb-17	Vehicle	240	This report	Drivers side rear door to stretcher. Locking latch to keep door open damaged and requires repair	N/a	-
3-Feb-17	Vehicle	225	-	Crack in windscreen, Single 1 strobe not working at rear of vehicle, Windscreen Wiper blades persish	Unknown	-
21-Jan-17	Vehicle	245	Have reset the MDT main switch in the oxygen locker, have also done a hard reset of the MDT control box behind the passenger seat but error screen reappears.	MDT is frozen on error scree. Please see attached photo.	-	-
24-Jan-17	Vehicle	210	-	power steering fluid reading on cold minimum - not due for a service until July 2017	-	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
1-Feb-17	Vehicle	190	Repair/Replacement.	1: Multiple electric window buttons broken - 2: Yellow running light on drivers side near fuel filling point is not attached properly (falling out) - 3: Tissue holder broken.	Wear and tear.	-
1-Feb-17	Vehicle	195	Taken to mechanic	Engine warning light flashing	-	-
1-Feb-17	Vehicle	225	Booked in with local Auto electrical workshop for service this should make the vehicle operational until then vehicle has been taken off line.	Vehicles central display is not working this means there are no light, siren or rear compartment power	Electrical short	-
2-Feb-17	Vehicle	235	-	Driver seat falling apart on seat area, starting to lean to the right	-	Still waiting for toggle switches to be replaced as per previous fault form last week
2-Feb-17	Stretcher	225	mil	Stretcher not adjusting height for easy removing from vehicle and loading into vehicle	-	-
2-Feb-17	General Equipment	250	Attempted syncing and resetting computer	Computer freezes on requesting to print screen	-	-
2-Feb-17	Vehicle	210	Nil Comms notified and fault form lodged	Interior lights of back cabin non operational. Light switch on front cab panel showing grey and not turning on.	Unknown	-
2-Feb-17	Vehicle	210	Nil Comms notified and fault form lodged	Interior lights of back cabin non operational. Light switch on front cab panel showing grey and not turning on.	Unknown	-
2-Feb-17	Vehicle	235	Pressing all buttons on module. Pushing module all the way back into the truck. Pulling up and down on the arms. Loading and unloading the module.	Arms of stretcher module are jammed up. Happened during offloading pt at hospital. This fault makes it impossible to load stretcher into vehicle.	Unknown	-
2-Feb-17	Vehicle	200	fault form	1. L head light not working 2. brake pad wear sign noted on screen 3. missing a torch from within vehicle	??	-
2-Feb-17	Vehicle	230	-	Left headlight not working	-	Vehicle not roadworthy
3-Feb-17	General Equipment	250	Removed from service & replaced with spare	Damage to oxygen dial on regulator	Unknown. Was found like this when checking vehicle	-
3-Feb-17	Stretcher	230	Taken off road, contacted CDS Stretcher at NGH	Stretcher removed from vehicle and placed to half height at both ends, pt on spine board, placed on stretcher - when weight was rested onto stretcher head end of stretcher collapsed from half height to ground level.	-	Put did not sustain any injuries as an impact of this, had spinal precautions in situ however
4-Feb-17	Vehicle	240	OIC organised with mechanic to repair	Vehicle two way radio will not turn on unless holding emergency start button and radio on button. ? Faulty auxiliary battery. Red light noted to be on switchboard for mains. When plugged into 240v to charge, orange charging light comes on. Phoned OC	-	Able to be used if required. Turn radio on by pressing emergency start button and radio on button at same time.
3-Feb-17	Vehicle	215	New Toyota starter relay ordered by service provider 6/2/2017 relay will then be transported to	Vehicle won't start suspect starter relay other components of starter system already changed	Wiring to start	relay repaired

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
5-Feb-17	Vehicle General	235	Use portable radios	Car radio doesn't have sound when transmissions coming through. ?loose wiring as sound of movement whilst driving and works okay when pressure applied to speaker	-	-
3-Feb-17	Equipment	230	Nil	Unable to start up. Will not do start up repair	-	-
5-Feb-17	Vehicle	230	Nil. requires mechanical attention. Cds notified and car out of service on return to Station	1. Primary reason - Air conditioning system not working in rear of vehicle. Nil fan activity. 2. Additional issue- side sliding door mechanism to keep door open faulty. Door unable to stay open without manual input. "Turn signal left" message, indicator flashing quickly when activated. Also, "ESP - visit workshop" message showing	1. Unknown 2. Unknown	-
13-Jan-17	Vehicle	240	-	Service Due - Service D required	-	Vehicle taken to and indicator fixed.
25-Jan-17	Vehicle	205	-	-	-	-
26-Jan-17	Vehicle	195	Spoken with OIC. Car has been taken off road and due for service	No monitor in vehicle due to fault.	SpO2 monitor in another vehicle. Had to be swapped out.	Defib now placed in vehicle repaired.
24-Jan-17	Vehicle	210	in Rockhampton	Warning light came on dash - break pads need replacing Windscreen washer leaking. Refilled 0830 and half empty by 1520 with lost water under vehicle.	-	-
27-Jan-17	Vehicle	225	-	-	-	-
27-Jan-17	Vehicle	195	Reported	Both windscreen washer hoses broken Defibrillator found outside OIC office; oxyviva fixed with unit from training room; Vehicle dirty ++. OIC contacted	Unknown found when driving and tried to use washers	-
28-Jan-17	Vehicle	250	-	MDT not working	-	-
21-Feb-17	Vehicle	240	Vehicle fault report	-	-	-
28-Jan-17	Vehicle	210	-	Side step no longer working, even with using the manual override switch	-	-
30-Jan-17	Vehicle	250	Notified SOS and vehicle has been taken out of service to be returned to station	Stretcher battery/ charger in Side door appears to have exploded/leaked acid with evident acid staining all over the floor of side storage including the spare battery and charger.	Unknown but appears to have happen some time ago as the acid has crystallised	-
30-Jan-17	Vehicle	210	Radio turned off and on, several radio checks done and no reply.	Radio communication not working. Capcomm can be heard but cannot hear unit 2198 calling. Front passenger window not working of either driver side or passenger side switch, intermittent sometimes will work	-	-
29-Jan-17	Vehicle	215	None	Issues when trying to unload stretcher - gets stuck	Faulty switch	-
30-Jan-17	Stretcher	240	-	-	-	-
27-Jan-17	Vehicle	240	Replacement	Both back tyres blew but have since been repaired Vehicle radio cycles off and on without warning - potentially serious issue if on a critical case	Possibly heat	Tyres replaced at on Friday 27/1/2017 at 16.30
30-Jan-17	Vehicle	235	-	-	Found at shift commencement	-
30-Jan-17	Vehicle	245	Spoke to OC, fault form completed, too late in the day to take to	Flashing engine light on dashboard. Loss of power	Contamination of AdBlue (according to manual)	-
9-Jan-17	Vehicle	240	Reported to OIC, vehicle sent for new bracket to be measured and made	MDT still obstructing reverse camera, vehicle been taken for new bracket fitting - August 16 but still waiting for fitting of new bracket	Initial installation of MDT	Not safe due to back window being obstructed so reversing hazard. SEVA contacted and advised Bracket made and booked for fitting Monday 30/1/17. New fitting plate attached off setting MDT camera now not obstructed.
30-Jan-17	Vehicle	250	Mechanic aware	AC unit not working in rear	-	-
30-Jan-17	Vehicle	250	Nil	Damage to front lower section near the number plate	Striking a wallaby	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
30-Jan-17	Vehicle	245	Turn car on and off and pressed the on button montior disconnected and reconnected >> new dump box also tested	Front radio won't turn on	No	-
31-Jan-17	Defibrillator	215	removed from acute unit	DEFIBRILLATOR will not charge to deliver a shock	unknown	replacement module utilised from 4409 >> 4418
31-Jan-17	Vehicle	185	-	vehicle stretcher loader fails when the stretcher has any significant weight on it, i.e. a patient	Possible vehicle battery failure under load?	-
31-Jan-17	Stretcher	185	-	vehicle loader fails operate fully when under load. If stretcher is loaded with more than 60 kg, the loader fails to lift the stretcher high enough for loading	-	Stretcher is fully operational.
31-Jan-17	Vehicle	250	Sos OIC aware	faulty. Slide/lift mechanism failed while on two cases now only working intermittently.	Unknown	-
31-Jan-17	Vehicle	250	booked	faulty. Slide/lift mechanism failed while on two cases now only working intermittently.	Unknown	-
31-Jan-17	General Equipment	230	Phone has been restarted without change	Phone does not work. States' No SIM detected, emergency calls only	-	OIC has checked phone and rectified issue. Phone now working and is operational. No further action required.
31-Jan-17	Vehicle	245	Informed OIC	MDT down information button not working properly- hard to press. Old mdt style - button on the bottom, second from the right which is used to scroll down through the case information.	-	OSU attended 2/2 and replaced front panel and buttons
25-Jan-17	Vehicle	240	Repaired	Faulty INVERTER e.g when plugging in port-a-cot works for 2sec then turns off. Unable to be used for retrievals until its fixed.	No	THIS IS NOW THE SPARE STRU UNIT, HENCE IS ESSENTIAL IN PROVIDING NEO-RESCUE TRANSPORT SERVICES
31-Jan-17	Vehicle	225	Car taken off rd	A/C not working, car radio not working, PowerPoint not working	-	-
28-Jan-17	Vehicle	180	Checked by KP Auto Electrics, awaiting replacement light.	Rear passenger side brake light not working.	General usage.	-
31-Jan-17	Other Equipment	250	-	Toughbook AP8896 off 601561 won't start up	-	-
31-Jan-17	Vehicle	235	-	Indicators not working	Broken indicator lever.	-
31-Jan-17	Stretcher	225	Stretcher has been removed from service. Tagged out of service. Replaced with spare stretcher.	Left hand brake assembly bent, preventing operation of brake. Brake binding during use. Top of stretcher functional.	Not known, noticed during routine check.	SHE system not responding at time of report.
1-Feb-17	Vehicle	210	Nil	Squealing noise coming from engine bay under revs (sounds like a pulley bearing).	Has been intermittent and considerably less severe however today it appears to be more prominent.	-
1-Feb-17	Vehicle	215	Vehicle fault form.	Idle hold function doesn't work.	Idle hold function being used.	-
1-Feb-17	Vehicle	215	-	L) scan light keeps flashing on and off when driving. Broken light indicator is showing on the dashboard.	-	Reflective plastic coming off from multiple areas on the vehicle
2-Feb-17	Other Equipment	180	contacted, fault explained. they have advised it be sent to them for assessment/repair. sent 2/2/17 via australia post.	Antenna split at top	Unknown - found during vehicle check	-

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
2-Feb-17	Vehicle	210	-	Front Airconditioner not working, blowing hot air	-	-
3-Feb-17	Vehicle	235	glass has been secured and vehicle taken off road OCS and SOS informed of incident	dent to Back door passenger side with broken glass window	reversed into a wooden pole which had a metal hook screw in it	-
4-Feb-17	Vehicle	215	Nil	Broken Beacon Cover glass	Hitting the roadside roller door at the airport when the roller came down with vehicle moving into the building.	Comms notified, spoke with SOS M Low. SOS requested the vehicle to be taken off road.
4-Feb-17	Vehicle	240	Completed vehicle check list and fault form.	Crack in passenger side of windscreen	Driving code 1 down D'aguilar highway passing truck which flicked rock up to windscreen	Windscreen replaced on 15th Feb 17
4-Feb-17	Vehicle	245	Needs to be assessed by a mechanic Vehicle taken to PST on Monday 6/2 for assessment with nil fault found and advised to return if happens again. Vehicle will be re-assessed should fault reappear.	Intermittently will make and can feel a large clunk noise from the front left hand of the engine area after the car is placed in reverse then accelerating. There is no issues reversing or changing between the gears. It doesn't not happen every time	Unknown? The car is stopped completely before changing into reverse or drive. Nil concerns while driving or while reversing. It seems to make the noise like it is engaging something in the front wheel after moving about 10cm	-
4-Feb-17	Vehicle	230	Plugged in to 240v charging station at station. MDT switch turned off and then on to attempt to reset. Fuses removed and reinserted to attempt to reset. Both battery lights green. Fault form created.	MDT not functioning. displays error code: 'Reboot and select proper boot device or insert Boot media in selected boot device and press a key.	Unknown.	-
1-Feb-17	Defibrillator	240	Replaced item OIC ADVISED	Spo2 leads frayed wires exposed	-	-
3-Feb-17	Vehicle	205	New fuel card was on OIC desk (OIC was on sick leave). Now in the vehicle. Old card destroyed. Officer replaced face mask.	Fuel card expired. Adult face mask deflated.	Extreme heat known to cause issue with face masks.	-
4-Feb-17	Defibrillator	210	OIC notified	Internal car charging cord for corpuls3 has been 'crimped' exposing internal wiring	? Accidentally wrapped around base of corpuls cradle- causing cord to be compressed and tearing of outer case .	Corpuls3 operational -charging cord non operational
4-Feb-17	Vehicle	250	-	Rear air conditioning unit in vehicle not working	Just stopped working while vehicle being used for daily duties.	-
4-Feb-17	Vehicle	250	-	Air conditioning in rear of vehicle not working. Front air conditioning working.	-	-
5-Feb-17	Vehicle	235	Fault form completed	12 volt charging point in front cabin not working.	Unknown	-
5-Feb-17	Vehicle	235	Taken off road	Engine overheating. Temperature is 120 despite being full of coolant. Car losing power up hill. Warning light for tyre pressure continues to come on despite normal tyre pressure	-	-
4-Feb-17	Vehicle	195	Fault form filled	Patient care seat armrest not able to be adjusted.	General wear and tear	Seat is fine, just the armrest is faulty

Date Fault Occurred	Item Type	Lasn	Action Taken	Fault Description	Fault Cause	Additional Comments
6-Feb-17	Vehicle	240	-	Vehicle pulls to the left	-	-
6-Feb-17	Vehicle	230	Notify CDS, call and make our way there	No indicators, warning lights blazing, no fuel gauge,	.?	-
6-Feb-17	Vehicle	195	Fault report filed, and reported to O.I.C.	R hand light over Pt. stretcher U/S.	Unknown	-
6-Feb-17	Vehicle	230	Contacted , vehicle towed	Car filled with petrol	-	-
6-Feb-17	Vehicle	230	Car engine turned off and restarted with same result. Exterior check of tyres - nil	Warning lights on dash - ABS and safety features not working.	-	-
7-Feb-17	Vehicle	195	damage or flat tyres	Driver side barn door stopper broken.	Wear & tear.	-
7-Feb-17	Vehicle	210	Nil			-
7-Feb-17	General Equipment	220	Master switch turned off nil effect, second vehicle and station radio tested with similar fault noted ?? Repeater issue. Secondary and tertiary communications of SAT phone and SAT PTT and mobile phone available	Radio fault - unable to transmit receive, vehicle radio or handheld (x-band) reported to Comms, incident logged with radio tech,	Recurring intermittent fault - previously reported	-
7-Feb-17	General Equipment	220				401821 has registration no. 913WBI and is currently located at QAS Maroochydore marked OOS. Please note there is a MDT fault for this vehicle that has also been logged with on 8 Feb 2017. 9 Feb visited unit and repaired MDT while at
8-Feb-17	Vehicle	230	Fault form created, OIC notified. OIC forwarded form to the call centre.	Stretcher cradle intermittent power dropout. Officers have to put pressure on the power load section in an attempt to get contact and make the load lights stay green. They are working intermittantly. SN power load cradle: 150439128 SN stretcher: 160241312	N/A	-
8-Feb-17	Vehicle	225	-	Suspension airbags not inflating ?leak	-	Vehicle still operational although extremely rough ride in back.
7-Feb-17	Vehicle	240	Araldited (2 pack resin glue) used to reattach broken chip of fibreglass	Slight damage to left rear upper corner of module	Struck by closing plant room door	-
8-Feb-17	Vehicle	225	Fault form	Back right brake light out. And dash light for the brake pads.	??	-
8-Feb-17	General Equipment	210	Removed from service and taking to get replacement as per OIC conversation with resource readiness coordinator.	Oxygen regulator gauge stuck indicating full.when doing vehicle check today 8/2/17.	Unknown	-
8-Feb-17	Vehicle	205	skirting tucked back in where possible	Skirting to sliding step ripped/pulled out	Kangaroo strike	requires professional repair
8-Feb-17	Vehicle	205	cylinders turned off - able to be turned on from within vehicle if required for use.	Slow leak to vehicle o2.	-	-

RTI Release