Progress Report #1 for period to 24 October 2012 Prepared by Industry Capability Network (Queensland) Ltd

This report details the assistance provided during the above period by ICN (Qld) to Lend Lease in the delivery and implementation of the Local Industry Participation Plan (LIPP) for the Sunshine Coast University Hospital in accordance with the Local Industry Policy (LIP).

1. Liaison with the Project on LIP Issues

ICN met with Queensland Health (Sam Betros) in May 2011 to discuss the project ICN services, and LIP procedures and issues. ICN assisted QH in the development of the LIPP for the project and provided an evaluation report to QH on project bidders' LIP plan submissions in March 2012.

2. Liaison with Lend Lease on LIP Compliance

Lend Lease met with ICN to establish processes and procedures for management of the project's obligations to the LIP. It was decided that ICN will provide support on number of services covering.

- Development of LIPP
- Implementation of the LIPP (capability searches on contestable packages)**
- Presenting at briefing sessions
- Registering companies via ICN Gateway
- Verification of source of manufacture and service provision in subcontracts
- Business matching
- Progress reporting (Monthly) and final LIPP Outcomes reporting (at end of project)

**(Contestable items or packages are those that could potentially be sourced locally or overseas but do not include designated items such as concrete supply earthworks, etc, which it is assumed will always be supplied from sources local to the project. Nor do they include items that have no chance of being manufactured in Australia, ea turbines)

3. Tier Barometer

Tier Barometer is an on-line self-assessment tool developed by ICN and the State Government. It provides participating companies with an assessment of their tier level in terms of supply to major projects. The tool is used by the project to analyse the basic capabilities of potential suppliers during the registration process.

4. Work Packages

Queensland and Australian capability, content and capacity will be considered for all the work packages. The first batches of trades were published in Gateway website. Work Packages issued to date:

Any Opportunities Crossover Roads Preload Sediment Control Site Security

Potential subcontractors will be given an indication of the size and generic nature of the project, and questioned regarding their capability, capacity to carry out the work, code compliance, and previous work history. Reports will be sent to Lend Lease detailing local companies which have the capability and capacity to carry out the work for each of the above packages. The primary objective of the Local Industry Policy is to ensure that competitive local companies are given full, fair and reasonable opportunity to tender for work packages. This objective will be achieved if the companies nominated by ICN, and other local companies that Lend Lease is aware of, are given full,

fair and reasonable consideration in the establishment of the tender list, and if a reasonable number of local companies are subsequently invited to tender. Lend Lease Intends to apply this requirement.

5. Information Sessions

ICN supported Lend Lease in delivering briefing sessions as proposed in their LIP plan covering:

Monday 3rd September 2012 - Civil, Infrastructure, Structure & Landscaping

Monday 17th September 2012 - Services

Monday 24th September 2012 - Roof & Façade

Monday 8th October 2012 - Fit out & Finishes

Monday 15th October 2012 - Furniture Fittings & Equipment (FF&E)

Lend Lease also presented at the General Briefing Sessions along with ICN on 13, 14, 16 and 20th of August 2012.

Lend Lease project managers attended a briefing presentation by the members of the Cleantech Industries group of companies on 24th September 2012.

6. Source of Supply

As subcontracts begin to be awarded, the source of manufacture or service provision for contestable packages will be validated and verified in discussion with the corresponding subcontractors. The aggregate value awarded to Queensland and Australian industry will be estimated, and these figures will be broken down into "Local", "Regional" and "SE Queensland" components.

7. Reporting

Reports on companies nominated for the trade packages listed above will be forwarded to Lend Lease.

Chris Martin

Manager - Commercial Projects

ICN Queensland

Lend Lease



Sunshine Coast University Hospital: Local Industry Participation

A Division of QMI Solutions

Progress Report #2 for period to 28 November 2012 Prepared by Industry Capability Network (Queensland) Ltd

This report details the assistance provided during the above period by ICN (Qld) to Lend Lease in the delivery and implementation of the Local Industry Participation Plan (LIPP) for the Sunshine Coast University Hospital in accordance with the Local Industry Policy (LIP).

1. Liaison with the Project on LIP Issues

ICN met with Queensland Health (Sam Betros) in May 2011 to discuss the project, ICN services, and LIP procedures and issues. ICN assisted QH in the development of the LIPP for the project and provided an evaluation report to QH on project bidders' LIP plan submissions in March 2012.

2. Liaison with Lend Lease on LIP Compliance

Lend Lease met with ICN to establish processes and procedures for management of the project's obligations to the LIP. It was decided that ICN will provide support on number of services covering:

- Development of LIPP
- Implementation of the LIPP (capability searches on contestable packages)**
- Presenting at briefing sessions
- Registering companies via ICN Gateway
- Verification of source of manufacture and service provision in subcontracts
- Business matching
- Progress reporting (Monthly) and final LIRP Outcomes reporting (at end of project)

**(Contestable items or packages are those that could potentially be sourced locally or overseas but do not include designated items such as concrete supply, earthworks, etc, which it is assumed will always be supplied from sources local to the project. Nor do they include items that have no chance of being manufactured in Australia, eg turbines)

3. Tier Barometer

Tier Barometer is an on-line self-assessment tool developed by ICN and the State Government. It provides participating companies with an assessment of their tier level in terms of supply to major projects. The tool is used by the project to analyse the basic capabilities of potential suppliers during the registration process.

4. Work Packages

Queensland and Australian capability, content and capacity will be considered for all the work packages. The first batches of trades were published in Gateway website. Work Packages issued to date:

Any Opportunities

Crossover Roads

Preload

Sediment Control

Site Security

Scaffolding (Carpark 2)

Concrete Supply (Carpark 2)

Concrete Pumping (Carpark 2)

Formwork (Carpark 2)

Reinforcement Fixing (Carpark 2)

Hydraulics (Carpark 2)

Kawana Way Duplication (Carpark 2)

Concrete Placing (Carpark 2)

Potential subcontractors will be given an indication of the size and generic nature of the project, and questioned regarding their capability, capacity to carry out the work, code compliance, and previous work history. Reports will be sent to Lend Lease detailing local companies which have the capability and capacity to carry out the work for each of the above packages. The primary objective of the Local Industry Policy is to ensure that competitive local companies are given full, fair and reasonable opportunity to tender for work packages. This objective will be achieved if the companies nominated by ICN, and other local companies that Lend Lease is aware of, are given full, fair and reasonable consideration in the establishment of the tender list, and, subject to meeting pre-qualification criteria, a reasonable number of local companies are subsequently invited to tender. Lend Lease intends to apply this requirement.

761 companies have registered to date.

Crossover Road Construction: 20 companies registered. Lend Lease have awarded this contract to the following company. Details are as follows:

SHADFORTH'S CIVIL ENGINEERING CONTRACTORS PTY LTD

99 Sandalwood Lane FOREST GLEN, QLD Australia 4556

Phone: +07 5442 3955 Fax: +07 5442 3988

Web: www shadcivil com au

5. Information Sessions

ICN supported Lend Lease in delivering briefing sessions as proposed in their LIP plan covering:

Monday 3rd September 2012 - Civil, Infrastructure, Structure & Landscaping

Monday 17th September 2012 - Services

Monday 24th September 2012 - Roof & Facade

Monday 8th October 2012 - Fit out & Finishes

Monday 15th October 2012 - Furniture Fittings & Equipment (FF&E)

Lend Lease also presented at the General Briefing Sessions along with ICN on 13, 14, 16 and 20th of August 2012.

Lend Lease project managers attended a briefing presentation by the members of the Cleantech Industries group of companies on 24th September 2012.

6. Source of Supply

As subcontracts begin to be awarded, the source of manufacture or service provision for contestable packages will be validated and verified in discussion with the corresponding subcontractors. The aggregate value awarded to Queensland and Australian industry will be estimated, and these figures will be broken down into "Local", "Regional" and "SE Queensland" components.

7. Reporting

Reports on companies nominated for the trade packages listed above will be forwarded to Lend Lease.

Chris Martin Manager – Commercial Projects ICN Queensland





A Division of OMI Solutions

Progress Report #3 for period to 31 January 2013 Prepared by Industry Capability Network (Queensland) Ltd

This report details the assistance provided during the above period by ICN (Qld) to Lend Lease in the delivery and implementation of the Local Industry Participation Plan (LIPP) for the Sunshine Coast University Hospital in accordance with the Local Industry Policy (LIP).

1. Liaison with the Project on LIP Issues

ICN met with Queensland Health (Sam Betros) in May 2011 to discuss the project, ICN services, and LIP procedures and issues. ICN assisted QH in the development of the LIPP for the project and provided an evaluation report to QH on project bidders' LIP plan submissions in March 2012.

2. Liaison with Lend Lease on LIP Compliance

Lend Lease met with ICN to establish processes and procedures for management of the project's obligations to the LIP. It was decided that ICN will provide support on number of services covering:

- Implementation of the LIPP (capability searches on contestable packages)
- Presenting at briefing sessions
- Registering companies via ICN Gateway
- Verification of source of manufacture and service provision in subcontracts
- Business matching
- Progress reporting (Monthly) and final NPP Outcomes reporting (at end of project)

3. Tier Barometer

Tier Barometer is an on-line self-assessment tool developed by ICN and the State Government. It provides participating companies with an assessment of their tier level in terms of supply to major projects. The tool is used by the project to analyse the basic capabilities of potential suppliers during the registration process.

4. Contestable Packages

Queensland and Australian capability, content and capacity will be considered for all the work packages. The following activities have been undertaken:

- An ICN officer has been assigned full time to the project.
- Detailed Business Matching has been carried out by ICN. 14 work packages have been managed in this way.
 These are listed at Attachment A.
- 998 registrations against work packages on Gateway have been received
- Some 60 Trade Packages have been awarded. These are listed at Attachment's.

Potential subcontractors will be given an indication of the size and generic nature of the project, and questioned regarding their capability and capacity to carry out the work, code compliance, and previous work history. Reports will be sent to Lend Lease detailing local companies which have the capability and capacity to carry out the work for each of the above packages. The primary objective of the Local Industry Policy is to ensure that competitive local companies are given full, fair and reasonable opportunity to tender for work packages. This objective will be achieved if the companies nominated by ICN, and other local companies that Lend Lease is aware of, are considered in the establishment of the tender list, and, subject to meeting pre-qualification criteria, a reasonable number of local companies are subsequently invited to tender. Lend Lease intends to apply this requirement.

6. Prototype Building

A prototype showcase building was erected in record time. This enabled focus group to provide input in to the final design in a cost effective manner.

7. Information Sessions

ICN supported Lend Lease in delivering briefing sessions as proposed in their LIP plan covering:

Monday 3rd September 2012 - Civil, Infrastructure, Structure & Landscaping

Monday 17th September 2012 - Services

Monday 24th September 2012 Roof & Façade

Monday 8th October 2012 - Fit out & Finishes

Monday 15th October 2012 - Furniture Fittings & Equipment (FF&E)

Lend Lease also presented at the General Briefing Sessions along with ICN on 13, 14, 16 and 20th of August 2012.

Lend Lease project managers attended a briefing presentation by the members of the Cleantech Industries group of companies on 24th September 2012.

8. Efforts to engage with Local Companies include:

Press release by Health Minister, radio interviews by Project Director, Newspaper articles in CM and Sunshine Coast Daily followed up by substantial advertisements in the same newspapers on 19th January. Support articles followed from SSC Council and local councillors.

As a result of the above information sessions and the advertising campaign almost 1000 registrations have been received with close to 100 companies listing after the newspaper advertisements.

9. Source of Supply

As subcontracts begin to be awarded, the source of manufacture or service provision for contestable packages will be validated and verified in discussion with the corresponding subcontractors. The aggregate value awarded to Queensland and Australian industry will be estimated, and these figures will be broken down into "Local", "Regional" and "SE Queensland" components.

10. Reporting

Reports on companies nominated for the trade packages listed above will be forwarded to Lend Lease.

Chris Martin
Manager – Commercial Projects
ICN Queensland

/ Folymany 2013

Attachme	nt A:
Enquiries	
PR.0051.01	Crossover Road Construction
TP.0231.01	reload
TP.0320.01	ediment control
PR0059 Site	Security
644.2.TP173	2.01 - CP2 - Hydraulics
644.2.TP062	0.01 - CP2 - Reinforcement Fixing
644.2.TP053	0.01 - CP2 - Formwork
644.2.TP042	2.01 - CP2 - Concrete Pumping
644.2.TP042	0.01 - CP2 - Concrete Placing
644.2.TP041	0.01 - CP2 - Concrete Supply
644.2.TP006	0.01 - CP2 - Scaffolding
645,TP3230	01 - Kawana Way Duplication
641.TP.0230	.01 - RIE - Bulk Earthworks and Fill
641.TP.3230	.01 - RIE - Roads & Infrastructure Services
	9.01 - CP2 - Carpark Control System
640.PR0033	01 - PRW - Temporary Hydraylies
640.PR0056	01 - PRW - Rubbish Removal

ATTACHMENT B:			
Business Engagement:			
Successful Subcontractor	Trade Packages	- SEQ - South East	Source of Suppl
		GLD - REQ - Regional	
Bulltsmart Modular Mining Pty Ltd	Modular Prototype Suite	AUS	C
Shadforths Civil Pty Ltd	CP2 Early Works	REQ	L
Wagstaff Piling QLD Pty Ltd	Test Piling	SEQ	L
EVS Group Australia Pty Ltd	Site Security	SEQ	L
Nilsen QLD Pty Ltd	Temporary Electrical CP2 & Prototype	SEQ	C
Calty Constructions	Protoype Marketing Rigging and Marketing Deck	SEQ	L
Kyana Pty Lid	Temporary Hydraulics	SEQ	С
Gordon Clements Nominees Pty Ltd T/A C		SEQ	L
	Site Probing Works - 55 Probe Locations	SEQ	L
Wagstaff Piling		SEQ	C
Quality Choice Signs	Re skin to existing Biliboard	SEC	© ,
Fencepac	Site Perimeter Security Ferice - Stage 1		
Fredon QLD Pty Limited	SCUH - Nambour Site	SEQ	<u>c</u>)
Shadforths	Crossover road Construction	SEQ	<u> </u>
Underground Pipe and Cable Location Pty	Detect inground services prior to digging fence	9EQ	C
02 Environmental Pty Ltd	Environmental and Sediment Monitoring	SEQ	<u>L</u>
Shadforths	Supply & replace Road Base - Site Accommodation	(SEC)	L.
Calty	Prototype Building Foundations	S/ECI /	L
Scapeshape Pty Ltd	Palmtree re-location	SEC	L
O&J Services	Site Shed Cleaning	SEQ	L
Floor cover QLD - AK	Installation of unyl and carpet to the Prototype Suite	SEQ	С
A CONTRACTOR OF THE CONTRACTOR		SEQ	С
Quality Choice Signs	Signage	SEQ	C
The trustee for The SJ & DY Eade Family	Supply and install shade cloth to SCUH Site		C
Regson Fabrication	Suppy & Install 2 Gate Closures	SEQ	
Orange Hire Pty Ltd	Supply & Hire of Perimeter Fencing	SEQ	L.
Franspacific Industries Pty Ltd	Site Sewerage Tank Pump Out	SEQ	С
Iniversal Cranes Sunshine Coast Pty Ltd	Mobile Crane Hire	SEQ	L
Siemens	Prototype Security	IMP	C
Merlon (t/a Statewide Communications)	Prototype Nurse Call & PES	AUS	С
ABS Courier Services	Courier charges	SEQ	L
T/s Imaging Centre Pty Limited	Colour prints and colour copies	SEQ	L
Coates Hire Operations Pty Ltd	Portable toilets	SEQ	С
	Hiring Conference Hall	SEQ	L
Sunshine Coast Regional Council		SEQ	L
Energex Limited	Energex Detailed Design		C
ATF Sunshine Coast and Total Site Set Up	(SEQ	<u> </u>
Evolution Tratic Control	Provide traffic Controller	SEQ	C
Worldwide Online Printing Market Street	Maeterplan Poster	SEQ	L.
ucid Edge PTY LTD	Video conversions from AVI to MWV+ YouTube upload X2	AUS	L
Combined Security Services /	Security Guards	SEQ	L
XLA Piper	Professional fees	AUS	L
reenbins	Size 8-8/n	SEQ	L
AySite Design	Consultation Manager setup fee	AUS	L
Metro Express	2 Containers sent from GCUH to SCUH	SEQ	С
rumpf Med Australia Pty Ltd	3x3 Combination light set & Trumpf Serv Pendants for Ope		C
		IMP	C
arjohuntleigh (TATE)	Medica Beds and Patient Lifting System		C
Arunta Plastics (QLD) Pty Ltd	Cultural Heritage Induction	SEQ	L
3 James	Supply and install of windows and external doors to Prototy		
ATF Services Pty Ltd	femp Fencing	SEQ	L
Rebotic Automation Group	AGV Advisory Services	AUS	С
nergy Crane Services Pty	Transport Items to SCUH site	SEQ	L
nergex Limited	Temporary Electrics supply South	SEQ	L
pence Door	Supply doors and frame	SEQ	С
ON Queensland	Lipp services	SEQ	Ļ
Coates Hire Operations Pty Ltd		SEQ	L
	Supply of Bulk Potable and Non-Potable Water	SEQ	L
Cyana Projects Pty Ltd			L.
leverfail Springwater Limited	Supply of Potable Water to Site until Feb 13	SEQ	
Steve Ryan t/as Rix Ryan Photography P/	Photograph Palm removal & monthly images	SEQ	-
Dunckers Pty Ltd	Supply of Site Accomkmodation Cleaning Products	SEQ	L
Bizfurn Express	Supply and Install of office furniture for Prototype Suite	SEQ	С
Suncoast Water Carriers	Re-Fill 2 x 10000L Water Tanks + 1 Additional Visit	SEQ	L
larvey Norman	Supply of kitchen fridge and microwave	SEQ	C
Mooloolaba Surf Life Saving Supporters	SCUH Christmas Party	SEQ	L
	<u> </u>	•	





A Division of OMI Solutions

Progress Report #5 for period to 28 March 2013 Prepared by Industry Capability Network (Queensland) Ltd

This report details the assistance provided during the above period by ICN (Qld) to Lend Lease in the delivery and implementation of the Local industry Participation Plan (LIPP) for the Sunshine Coast University Hospital in accordance with the Local Industry Policy (LIP).

1. Liaison with the Project on LIP issues

ICN met with Queensland Health (Sam Betros) in May 2011 to discuss the project, ICN services, and LIP procedures and issues. ICN assisted QH in the development of the LIPP for the project and provided an evaluation report to QH on project bidders' LIP plan submissions in March 2012.

2. Liaison with Lend Lease on LIP Compliance

Lend Lease met with ICN to establish processes and procedures for management of the project's obligations to the LIP. It was decided that ICN will provide support on number of services covering:

- Implementation of the LIPP (capability searches on contestable packages)
- Presenting at briefing sessions
- Registering companies via ICN Gateway
- Verification of source of manufacture and service provision in subcontracts
- Business matching
- Progress reporting (Monthly) and final LIPP Outcomes reporting (at end of project)

3. Tier Barometer

Tier Barometer is an on-line self-assessment tool developed by ICN and the State Government. It provides participating companies with an assessment of their tier level in terms of supply to major projects. The tool is used by the project to analyse the basic capabilities of potential suppliers during the registration process.

4. Contestable Packages

Queensiand and Australian capability, content and capacity will be considered for all the work packages. The following activities have been undertaken:

- An ICN officer has been assigned full time to the project.
- Detailed Business Matching has been carried out by ICN. 71 work packages have been managed in this way.
 These are listed at Attachment A.
- 1214 registrations against work packages on Gateway have been received
- 72 orders have been awarded. These are listed at Attachment B.

Potential subcontractors will be given an indication of the size and generic nature of the project, and questioned regarding their capability and capacity to carry out the work, code compliance, and previous work history. Reports will be sent to Lend Lease detailing local companies which have the capability and capacity to carry out the work for each of the above packages. The primary objective of the Local Industry Policy is to ensure that competitive local companies are given full, fair and reasonable opportunity to tender for work packages. This objective will be achieved if the companies nominated by ICN, and other local companies that Lend Lease is aware of, are considered in the establishment of the tender list, and, subject to meeting pre-qualification criteria, a reasonable number of local companies are subsequently invited to tender. Lend Lease intends to apply this requirement.

6. Prototype Building

A prototype showcase building was erected in record time. This enabled focus group to provide input in to the final design in a cost effective manner.

7. Local Industry Participation

Lend Lease Project Director has personally provided project work scope and Lend Lease supplier engagement approach information to a number of larger Australian Manufacturers who have asked for more information. These include in the past month The GWA Group; The Laminex Group; Spence Doors and Rockcote Industries. In the latter company time was dedicated to a site inspection of their manufacturing facilities.

To date, 56 out of a total of 66 orders placed on the project have been to South East Queensland (SEQ) Companies.

8. Information Sessions

ICN supported Lend Lease in delivering briefing sessions as proposed in their LIP plan covering:

Monday 3rd September 2012 - Civil, Infrastructure, Structure & Landscaping

Monday 17th September 2012 - Services

Monday 24th September 2012 - Roof & Façade

Monday 8th October 2012 - Fit out & Finishes

Monday 15th October 2012 - Furniture Fittings & Equipment (FF&E)

Lend Lease also presented at the General Briefing Sessions along with ICN on 13, 14, 16 and 20th of August 2012.

Lend Lease project managers attended a briefing presentation by the members of the Cleantech industries group of companies on 24th September 2012.

Lip Progress Report #5 Seuh Mar20139 P8.772

9. Efforts to engage with Local Companies include:

Press release by Health Minister, radio interviews by Project Director, Newspaper articles in CM and Sunshine Coast Daily followed up by substantial advertisements in the same newspapers on 19th January. Support articles followed from SSC Council and local councillors.

As a result of the above information sessions and the advertising campaign almost 1000 registrations have been received with close to 100 companies listing after the newspaper advertisements.

10. Source of Supply

As subcontracts begin to be awarded, the source of manufacture or service provision for contestable packages will be validated and verified in discussion with the corresponding subcontractors.

11. Reporting

Business matching reports on companies nominated for the trade packages listed at Attachment A are being provided to Lend Lease.

Peter Robinson General Manager ICN Queensland

Attachment A:

Enquiries

PR.0051.01 Crossover Road Construction

TP.0231.01 Preload

TP.0320.01 Sediment control

PRO059 Site Security

644.2.TP1732.01 - CP2 - Hydraulics

644.2.TP0620.01 - CP2 - Reinforcement Fixing

644.2.TP0530.01 - CP2 - Formwork

644.2.TP0422.01 - CP2 - Concrete Pumping

644.2.TP0420.01 - CP2 - Concrete Placing

644.2.TP0410.01 - CP2 - Concrete Supply

644.2.TP0060.01 - CP2 - Scaffolding

645.TP3230.01 - Kawana Way Duplication

641.TP.0230.01 - RIE - Bulk Earthworks and Fill

641.TP.3230.01 - RIE - Roads & Infrastructure Services

644.2.TP2239.01 - CP2 - Carpark Control System

640.PR0033.01 - PRW - Temporary Hydraulics

640.PR0056.01 - PRW - Rubbish Removal

644.2.TP0832.01 - CP2 - Waterproofing

644,2.TP2330.01 - CP2 - Electrical

640.PR0042.01 - PRW - Tower Cranes, Hoists & Crews

644.2.TP0631.01 - CP2 - Post Tensioning

642.TP.2030.01 - MHB - Vertical Transportation

643.1.TP2030.01 - FMC - Vertical Transportation

643.2.TP2030.01 - MHU - Vertical Transportation

644.1.TP2030.01 - CP1 - Vertical Transportation

640.PR0041.01 - PRW - Mobile Cranes

644.2.TP1830.01 - CP2 - Mechanical

644.2.TP1712.01 - CP2 - Water Tanks

640.PR0021.02 - PRW - Site Fencing

640.PR0046.01 - PRW - Temporary Plant & Equipment

640.PR0022.06 - PRW - Temporary Onsite Canteen and Catering Services

640.PR0022.05 - PRW - Temporary Carpentry Site Accommodation Areas

644.1.TP0530.01 - CP/1 - Formwork

642.TP.0530.01 - MHB - Formwork

643.2.TP0530.01 - MHU - Formwork

643.1.TP0530.01 - FMC - Formwork

643.1.TP2310.01 - FMC - Site Wide HV Equipment Supply Only

642.TP2335.02 - PRW - Uninterruptable Power Supply Units (UPS) & Maintenance

644.1.TP0330.02 - CP1 - Pile Cut-off

643.2.TP0330.02 - MHU- Pile Cut-off

643.1.TP0330.02 - FMC - Pile Cut-off

642.TP.0330.03 - MHB - Sheet Piling

642.TP.0330.02 - MHB - Pile Cut-off

643.1.TP0330.03 - FMC - Sheet Piling

644.1.TP0620.01 - CP1 - Reinforcement Fix

Lip Progress Report #5 Scuh Mar20139 P8.772

642.TP.0620.01 - MHB - Reinforcement Fix 642.TP.0631.01 - MHB - Post Tensioning 643.1.TP0620.01 - FMC - Reinforcement Fix 643.1.TP0631.01 - FMC- Post Tensioning 643.2.TP0620.01 - MHU - Reinforcement Fix 644.1.TP0631.01 - CP1 - Post Tensioning 640 PR0052.01 - PRW - Safety Precautions (PPE) 642.TP.0832.01 - MHB - Waterproofing Inground 642.TP.0832.02 - MHB - Waterproofing Roofs & Decks 642.TP.0832.03 - MHB - Temporary Waterproofing 643.1.TP0832.01 - FMC - Waterproofing & Tanking 643.1.TP3832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.2.TP0832.01 - MHU - Waterproofing 644.1.TP0832.01 - CP1 - Waterproofing 642.TP2335.01 - PRW - Site Wide LV Equipment Supply 641.TP0410.01 - RIE - Concrete Supply 642.TP.0420.01 - MHB - Concrete Place & Finish CP1.TP2335.01 - CP1/CP2 - Light Fitting Supply 640.PR0033.03 - PRW - Temporary Hydraulics Site Wide Reticulation 641.TP1732.01 - RIE - Water & Fire Mains reticulation 642.TP.0422.01 - MHB - Concrete Pumping 643.1.TP2312.01 - FMC - HV Generator Supply 642.TP.0431.01 - MHB - Precast Concrete 644.2.TP0830.01 - CP2 - Blockwork 640.PR0032.02 - PRW - Main Site Office & Accommodation Temporary Electrical 642.TP.0060.01 - MHB - Scaffolding

Attachment B:				
Business Engagement		LIPP Categorisation	Source of Supp	У
Subcontractor	Reason	SEQ - South East QLD REQ - Regional QLD AUS - Reat of Australia	C- Contestable L - Loca	PostGode
Builtsmart Modular Mining Pty Ltd	Modular Prototype Suite	AUS	С	2250
Shadforths Civil Pty Ltd	CP2 Early Works	REQ	L	4556
Wegstaff Pding QLD Pty Ltd	Test Pilling	SEQ	L	4060
EVS Group Australia Pty Ltd	Site Security	SEQ	L	4350
Nilsen QLO Pty Ltd	Temporary Electrical CP2 & Prototype	SEQ	С	4170
Calty Constructions	Protoype Marketing Rigging and Marketing Deck	SEQ	L	4556
Blue Glue Pty Ltd	Blue Glue	AUS	L	2113
Kyana Pty Ltd	Temporary Hydraulics	SEQ	C	4567
Gordon Clements Nominees Pty Ltd T/A Calt		SEQ	L	4556
Wagstaff Piling	Site Probing Works - 55 Probe Locations	SEQ) L	4060
Quality Choice Signs	Re skin to existing Biliboard	SEQ (//	C	4575
Fencepac	Site Perimeter Security Fence - Stage 1	SEQ	// c	4556
Fredon QLD Pty Limited	SCUH - Nambour Site	SEA	С	4119
Shadforths	Crossover road Construction	(S\$Q	L	4556
Underground Pipe and Cable Location Ptv Ltd	Detect Inground services prior to digging fence	SEQ)	С	4553
O2 Environmental Pty Ltd	Environmental and Sediment Monitoring	SEQ	Ł	4573
Shadforths	Supply & replace Road Base - Site Accommodation	SEQ	L	4556
Calty	Prototype Building Foundations	SEQ.	L	4556
Scapeshape Pty Ltd	Paimtree re-location	\$EQ	L	4211
D&J Services	Site Shed Cleaning	SEQ	į.	4011
Floor cover QLD - AK	Installation of vinyl and carpet to the Prototype Suite	SEQ	C	
Quality Choice Signs	Signage	SEQ	C	4575
The trustee for The SJ & DY Eade Family Tru	Supply and install shade cloth to SCUH Site	SEQ	С	4570
Regson Fabrication	Suppy & Install 2 Gate Closures	SEQ	C	4556
Orange Hire Pty Ltd	Supply & Hire of Perimeter Fencing	SEQ	Ĺ	2760
Transpacific Industries Pty Ltd	Site Sewerage Tank Pump Out	SEQ	С	4064
Universal Cranes Sunshine Coast Pty Ltd	Mobile Crane Hire	SEQ	L	4556
Siemens	Prototype Security	IMP	С	4006
Merion (t/a Statewide Communications)	Prototype Nurse Call & PES	AUS	С	4113
Ken Wilson & Associates Pty Ltd T/a KWA	Prototype Curtain & IV racks	SEQ	С	4163
Coates Hire Operations Pty Ltd	Portable toilets	SEQ	L	4131
Energex Limited	Energex Detailed Design	SEQ	L	4558
ATF Sunshine Coast and Total Site Set Up	Supply & Install crowd control barriers	SEQ	С	4000
Evolution Traffic Control	Provide traffic Controller	SEQ	L	4558
Lucid Edge PTY LTD	Video cornersions from AVI to MWV+ YouTube upl		С	4014
Worldwide Online Printing Warket Street	Mesterplan Poster	SEQ	L	4000
Lucid Edge PTY LTD	Video Conversions from AVI to MWV +	AUS	C	2010
Combined Security Services	Security Guards	SEQ	<u> </u>	4575
DLA Piper	Professional fees	AUS	<u> </u>	4000
Graenbins	Size 8 Bin	SEQ	L	4074
Metro Express	2 Containers sent from GCUH to SCUH	SEQ	L	4106
Trumpf Med Australia Pty Ltd	3x3 Combination light set & Trumpf Serv Pendants for Operating Suite	IMP	С	2067
Arjohuntleigh	Medical Beds and Patient Lifting System	IMP	C_	6163
Arunta Plastics (QLD) Pty Ltd	Cultural Heritage Induction	SEQ		3134
G James	Supply and install of windows and external doors to		L.	4556
ATF Services Pty Ltd	Temp Fencing	SEQ	L L	4558
Robotic Automation Group	AGV Advisory Services	AUS	c	2127
Energy Crane Services Pty	Transport Items to SCUH site	SEQ	L	4034
Energex Limited	Temporary Electrics supply South	SEQ	L	4006
Spence Door	Supply doors and frame	SEQ	L	4556
Coates Hire Operations Pty Ltd		SEQ	С	4131

Pro Concrete Pumping	Concrete Pumping to CP2	860		4220
Delco Steel	Reinforcement Fix to CP2	SEQ	C	4178
ast Coast Concrete Contractors	Concrete Place and Finish to OP2	Msw	L L	2485
nelom	Install Formwork to CP2	/ () SEQ		4173
Seavis & Bartele Pty Ltd	Temp Hydraulics (Site Wide)	() N SEP	C	4013
Wagstaff Piling	Precest Plling & Shear Piling	See		4060
Shadforth Civil Engineering	Cut to Fill Civil Works	SEP		4556
Bhamrock Civil	Bulk Civil Works Pre-Load	SEO	L	4076
The Trustee for The McGreal Family Trust T/A Immediate Response First Aid	First Aid Supplies to the SCUH Private Car Park First Aid Shed & First Aid Training on an a as needs basis	SEC	1	4556
Multimedia Technology	Panegonic Interactive Panetocom "Title L" Multi Touch Interactive Whiteboard	SEC 7/	C	4006
	Corporate Charges	SEQ	L	
Viridian	Supply and deliver of Mirrors for Prototype Suite	AUS	С	4173
Quality Choice Signs Pty Ltd	Hard Hat Stickers	SEQ	С	4551
Midmed	Supply and install of examination couch	SEQ	C	4570
Amalgamated Pest Control	Redback Pest Control to SCUH Site Offices	SEQ	L	4561
Bizfum Express	Supply and Install of office furniture for Prototype Suit	SEQ	С	4557
Harvey Norman	Supply of kitchen fridge and microwave	SEQ	C	4575
Suncoast Water Carriers	Re-Fill 2 x 10000L Water Tanks + 1 Additional Visit	SEQ	L	4551
Bizfum Express	Supply and install of office furniture for Prototype Suit	SEQ	С	4561
Dunckers Pty Ltd	Supply of Site Accomodation Cleaning Products	SEQ	L, L,	4560
Steve Ryan t/as Rix Ryan Photography P/L	Photograph Palm removal & monthly images	SEQ	L	4215
Neverfail Springwater Limited	Supply of Potable Water to Site until Feb 13	SEQ	4127	
Kyana Projects Pty Ltd	Supply of Bulk Potable and Non-Potable Water SEQ			4567





A Division of QMI Solutions

Sunshine Coast University Hospital: Local Industry Participation

Progress Report #6 for period to 29 April 2013
Prepared by Industry Capability Network (Queensland) Ltd

This report details the assistance provided during the above period by ICN (Qld) to Lend Lease in the delivery and implementation of the Local Industry Participation Plan (LIPP) for the Sunshine Coast University Hospital in accordance with the Local Industry Policy (LIP).

1. Liaison with the Project on LIP Issues

ICN met with Queensland Health (Sam Betros) in May 2011 to discuss the project, ICN services, and LIP procedures and issues. ICN assisted QH in the development of the LIPP for the project and provided an evaluation report to QH on project bidders' LIP plan submissions in March 2012.

2. Liaison with Lend Lease on LIP Compliance

Lend Lease met with ICN to establish processes and procedures for management of the project's obligations to the LIP. It was decided that ICN will provide support on number of services covering:

- Implementation of the LIPP (capability searches on contestable packages)
- Presenting at briefing sessions
- Registering companies via ICN Gateway
- Verification of source of manufacture and service provision in subcontracts
- Business matching
- Progress reporting (Monthly) and final LIPP Outcomes reporting (at end of project)

3. Tier Barometer

Fier Barometer is an on-line self-assessment tool developed by ICN and the State Government. It provides participating companies with an assessment of their tier level in terms of supply to major projects. The tool is used by the project to analyse the basic capabilities of potential suppliers during the registration process.

4. Contestable Packages

Queensland and Australian capability, content and capacity will be considered for all the work packages. The following activities have been undertaken:

- An ICN officer has been assigned full time to the project.
- Detailed Business Matching has been carried out by ICN. 99 work packages have been managed in this way.
 These are listed at Attachment A.
- 1253 registrations against work packages on Gateway have been received
- 72 orders have been awarded in March. These are listed at Attachment 8. The Attachment B was not
 updated for April.

Potential subcontractors will be given an indication of the size and generic nature of the project, and questioned regarding their capability and capacity to carry out the work, code compliance, and previous work history. Reports will be sent to Lend Lease detailing local companies which have the capability and capacity to carry out the work for each of the above packages. The primary objective of the Local Industry Policy is to ensure that competitive local companies are given full, fair and reasonable opportunity to tender for work packages. This objective will be achieved if the companies nominated by ICN, and other local companies that Lend Lease is aware of, are considered in the establishment of the tender list, and, subject to meeting pre-qualification criteria, a reasonable number of local companies are subsequently invited to tender. Lend Lease intends to apply this requirement.

6. Prototype Building

A prototype showcase building was erected in record time. This enabled focus group to provide input in to the final design in a cost effective manner.

7. Local Industry Participation

Lend Lease Project Director has personally provided project work scope and Lend Lease supplier engagement approach information to a number of larger Australian Manufacturers who have asked for more information. These nclude in the past month The GWA Group; The Laminex Group; Spence Doors and Rockcote Industries. In the latter company time was dedicated to a site inspection of their manufacturing facilities.

To date, 56 out of a total of 66 orders placed on the project have been to South East Queensland (SEQ) Companies.

8. Information Sessions

ICN supported Lend Lease in delivering briefing sessions as proposed in their LIP plan covering:

Monday 3rd September 2012 - Civil, Infrastructure, Structure & Landscaping

Monday 17th September 2012 - Services

Monday 24th September 2012 - Roof & Façade

Monday 8th October 2012 - Fit out & Finishes

Monday 15th October 2012 – Furniture Fittings & Equipment (FF&E)

Lend Lease also presented at the General Briefing Sessions along with ICN on 13, 14, 16 and 20th of August 2012.

Lend Lease project managers attended a briefing presentation by the members of the Cleantech Industries group of companies on 24th September 2012.

9. Efforts to engage with Local Companies include:

Press release by Health Minister, radio interviews by Project Director, Newspaper articles in CM and Sunshine Coast Daily followed up by substantial advertisements in the same newspapers on 19th January. Support articles followed from SSC Council and local councillors.


As a result of the above information sessions and the advertising campaign almost 1000 registrations have been received with close to 100 companies listing after the newspaper advertisements.

10. Source of Supply As subcontracts begin to be awarded, the source of manufacture or service provision for contestable packages will be validated and verified in discussion with the corresponding subcontractors. 11. Reporting Business matching reports on companies nominated for the trade packages listed at Attachment A are being provided to Lend Lease. Peter Robinson General Manager ICN Queensland

Attachment A:
Enquiries
PR.0051.01 Crossover Road Construction
TP.0231.01 Preload
TP.0320.01 Sediment control
PRC059 Site Security
644.2.TP1732.01 - CP2 - Hydraulics
644.2.TP0620.01 - CP2 - Reinforcement Fixing
644.2.TP0530.01 - CP2 - Formwork
644.2.TP0422.01 - CP2 - Concrete Pumping
644.2.TPO420.01 - CP2 - Concrete Placing
644.2.TP0410.01 - CP2 - Concrete Supply
644.2.TP0060.01 - CP2 - Scaffolding
645 TP3230.01 - Kawana Way Duplication
641.TP.0230.01 - RIE - Bulk Earthworks and Fill
541.TP.3230.01 - RIE - Roads & Infrastructure Services
644.2.TP2239.01 - CP2 - Carpark Control System
640.PR0033.01 - PRW - Temporary Hydraulics
640.PR0056.01 - PRW - Rubbish Removal
644.2.TP0832.01 - CP2 - Waterproofing
644.2.TP2330.01 - CP2 - Electrical
640.PR0042.01 - PRW - Tower Cranes, Hoists & Crews
644.2.TP0631.01 - CP2 - Post Tensioning
642.TP.2030.01 - MHB - Vertical Transportation
643.1.TP2030.01 - FMC - Vertical Transportation
643.2.TP2030.01 - MHU - Vertical Transportation
644.1.TP2030.01 - CP1 - Vertical Transportation 640.PR0041.01 - PRW - Mobile Cranes
644.2.TP1830.01 - CP2 - Mechanical
644.2.TP1712.01 - CP2 - Weenanical
640.PR0021.02 - PRW - Site Fencing
J40.PRO046.01 - PRW - Temporary Plant & Equipment
640.PR0022.06 - PRW - Temporary Onsite Capteen and Catering Services
640.PR0022.05 - PRW - Temporary Carpentry Site Accommodation Areas
644.1.TP0530.01 - CP1 - Formwork
642.TP.0530.01 - MHB - Formwork
643.2.TP0530.01 - MHU - Formwork
643.1.TP0530.01 - FMC - Formwork
643.1.TP2310.01 - FMC - Site Wide HV Equipment Supply Only
642.TP2335.02 - PRW - Uninterruptable Power Supply Units (UPS) & Maintenance
644.1.TP0330.02 - CP1 - Pile Cut-off
643.2.TP0330.02 - MHU- Pile Cut-off
643.1.TP0330.02 - FMC - Pile Cut-off
642.TP.0330.03 - MHB - Sheet Piling
642.TP.0330.02 - MHB - Pile Cut-off
643.1.TP0330.03 - FMC - Sheet Piling
644.1.TP0620.01 - CP1 - Reinforcement Fix

642.TP.0620.01 - MHB - Reinforcement Fix
642.TP.0631.01 - MHB - Post Tensioning
643.1.TP0620.01 - FMC - Reinforcement Fix
643.1.TP0631.01 - FMC- Post Tensioning
643.2.TP0620.01 - MHU - Reinforcement Fix
644.1.TP0631.01 - CP1 - Post Tensioning
640.PR0052.01 - PRW - Safety Precautions (PPE)
642.TP.0832.01 - MHB - Waterproofing Inground
642.TP.0832.02 - MHB - Waterproofing Roofs & Decks
642.TP.0832.03 - MHB - Temporary Waterproofing
643.1.TP0832.01 - FMC - Waterproofing & Tanking
643.1.TP3832.01 - FMC - Waterproofing & Tanking - Roofs & Decks
643.2.TP0832.01 - MHU - Waterproofing
644.1.TP0832.01 - CP1 - Waterproofing
642.TP2335.01 - PRW - Site Wide LV Equipment Supply
341.TP0410.01 - RIE - Concrete Supply
642.TP.0420.01 - MHB - Concrete Place & Finish
CP1.TP2335.01 - CP1/CP2 - Light Fitting Supply
640.PR0033.03 - PRW - Temporary Hydraulics Site Wide Reticulation
641.TP1732.01 - RIE - Water & Fire Mains reticulation
642.TP.0422.01 - MHB - Concrete Pumping
643.1.TP2312.01 - FMC - HV Generator Supply
642.TP.0431.01 - MHB - Precast Concrete
644.2.TP0830.01 - CP2 - Blockwork
640.PR0032.02 - PRW - Main Site Office & Accommodation Temporary Electrical
640.PR0022.02 - PRW - Temporary Lunch Sheds/ Ablutions / Containers / Other Sheds
642.TP.0060.01 - MHB - Scaffolding
644.2.TP1131.01 - CP2 - Facade / Screens
644.2.TP1330.01 - CP2 - General Carpentry
640.PR0022.07 - PRW - Pest Control
S40.PR0023.03 - PRW - Temporary Site Signage
640.PR0033.02 - PRW - Main Site Office Accommodation Temporary Hydraulics
640.PR0022.04 - PRW - Site Office Fitout & Furniture
640.PR0056.02 - PRW - Site Office Cleaning
643.1.TP0410.01 - FMC - Concrete Supply
643.1.TP0420.01 - FMC Concrete Place
643.1.TP0422.01 - FMC - Concrete Pumping
643.1.TP0431.01 - FMC - Precast Concrete
643.2.TP0410.01 - MHU - Concrete Supply
643.2.TP0420.01 - MHU - Concrete Placing
643.2.TP0422.01 - MHU - Concrete Pumping
644.1.TP0410.01 - CP1 - Concrete Supply
644 1.TP0420.01 - CP1 - Concrete Place
644.1.TP0422.01 - CP1 - Concrete Pumping
643.1.TP0060.01 - FMC - Scaffolding
644.1.TP0060.01 - CP1 - Scaffolding
642.TP.0830.01 - MHB - Blockwork
643.1.TP0830.01 - FMC - Blockwork

643.2.TP0830.01 - MHU - Blockwork	
644.1.TP0830.01 - CP1 - Blockwork	
640.PR0054.01 - PRW - Site Photography	
644.2.TP3030.01 - CP2 - Painting & Line Marking	
644.1.TP3030.01 - CP1 - Painting & Line Marking	
644.2.TP1030.01 - CP2 - Structural Steelwork	



Attachment B:	1			
Business Engagement		LIPP Categorisation	Source of Supply	
Subcontractor	Reason	SEQ - South East QLD FIEQ - Regional QLD AUS - Riest of Australia	C- Contestable L - Local	PostCode
Builtsmart Modular Mining Pty Ltd	Modular Prototype Suite	AUS	С	2250
Shadforths Clvil Pty Ltd	CP2 Early Works	REQ	L	4556
Wagsteff Piling OLD Pty Ltd	Test Piling	SEQ	L	4060
EVS Group Australia Pty Ltd	Site Security	SEQ	L	4350
Nisen QLD Pty Ltd	Temporary Electrical CP2 & Prototype	SEQ	С	4170
	Protoype Marketing Rigging and Marketing Deck	SEQ	L	4558
Calty Constructions	Blue Giue	AUS	i	2113
Blue Glue Pty Ltd	Temporary Hydraulics	SEQ	C	4567
Kyana Pty Ltd Gordon Clements Nominees Pty Ltd T/A Calt		SEQ	L	4556
		SEQ /		4060
Wagstaff Piling	Site Probing Works - 55 Probe Locations Re skin to existing Billboard	SEQ /	() c	4575
Quality Choice Signs	Site Perimeter Security Fence - Stage 1	SEQ.	/ c	4556
Fencepac	SCUH - Nambour Site	SEO	c	4119
Fredon QLD Pty Limited	Crossover road Construction	SEQ	L	4556
Shadforths		<u> </u>	C	4553
	Detect Inground services prior to digging fence Environmental and Sediment Monitoring	SEQ	L	4573
O2 Environmental Pty Ltd	Supply & replace Road Base - Site Accommodation		L	4556
Shadiorths		SEQ		4556
Calty	Prototype Building Foundations	SEQ.	<u> </u>	
Scapeshape Pty Ltd	Palmiree re-location	SEQ	L	4211
D&J Services	Site Shed Cleaning	SEQ	L	4011
Floor cover QLD - AK	Installation of vinyl and carpet to the Prototype Sulte	SEQ	С	
Quality Choice Signs	Signage	SEQ	С	4575
The trustee for The SJ & DY Eade Family Tru	Supply and install shade cloth to SOUH Site	SEQ	С	4570
Regson Fabrication	Suppy & Install 2 Gate Closures	SEQ	С	4556
Orange Hire Pty Ltd	Supply & Hire of Perimeter Fencing	SEQ	L	2760
Transpacific Industries Pty Ltd	Site Sewerage Tank Pump Out	SEQ	С	4064
Universal Cranes Sunshine Coast Pty Ltd	Mobile Crane Hire	SEQ	L	4556
Siemens	Prototype Security	IMP	С	4006
Merion (t/a Statewide Communications)	Prototype Nurse Call & PES	AUS	С	4113
Ken Wilson & Associates Pty Ltd T/a KWA E	Prototype Curtain & N Tracks	SEQ	С	4163
Coates Hire Operations Pty Ltd	Portable toilets	SEQ	L	4131
Energex Limited	Energex Detailed Design	SEQ	L	4558
ATF Sunshine Coast and Total Site Set Up	Supply & Install crowd control parriers	SEQ	С	4000
Evolution Trafic Control	Provide traffic Controller	SEQ	L	4558
Lucid Edge PTY LTD	Video conversions from AVI to MWV+ YouTube uplo	AUS	C	4014
Worldwide Online Printing Market Street	Masterplan Poster	SEQ	L	4000
Lucid Edge PTY LTD	Video Conversions from AVI to MWV +	AUS	С	2010
Combined Security Services	Security Guards	SEQ	L	4575
DLA Piper	Professional fees	AUS	L	4000
Greenbins	Size 8 Bin	SEQ	L	4074
Metro Express	2 Containers sent from GCUH to SCUH	SEQ	L	4106
Trumpi Med Australia Pty Ltd	2x3 Combination light set & Trumpi Serv Pendants for Operating Suite	IMP	С	2067
Arjohuntleigh	Medical Beds and Patient Lifting System	IMP	С	6163
Arunta Plastics (QLD) Pty Ltd	Cultural Heritage Induction	SEQ		3134
G James	Supply and install of windows and external doors to F	SEQ	L	4556
ATF Services Pty Ltd	Temp Fencing	SEQ	L	4558
Robotic Automation Group	AGV Advisory Services	AUS	С	2127
Energy Crane Services Pty	Transport items to SCUH site	SEQ	L	4034
	Temporary Electrics supply South	SEQ	L	4006
Energex Limited	Supply doors and frame	SEQ	L	4556
Spence Door	and the same of th	SEQ	- - -	4191

Kyana Projects Pty Ltd	Supply of Bulk Potable and Non-Potable Water	SEQ		4567
Nevertail Springwater Limited	Supply of Potable Water to Site until Feb 13	SEQ	C	4127
Steve Ryan t/as Rix Ryan Photography P/L	Photograph Palm removel & monthly images	SEQ	L	4215
Dunckers Pty Ltd	Supply of Site Accomodation Cleaning Products	SEQ	L	4560
Bizfum Express	Supply and install of office furniture for Prototype Suit	SEQ	C	4561
Suncoast Water Carriers	Re-Fill 2 x 10000L Water Tanks + 1 Additional Visit	SEQ	L	4551
Harvey Norman	Supply of kitchen fridge and microwave	SEQ	C	4575
Bizfum Express	Supply and install of office furniture for Prototype Suit	SEQ	С	4557
Amalgamated Pest Control	Redback Pest Control to SCUH Site Offices	SEQ	L	4561
Midmed	Supply and install of examination couch	SEQ	C	4570
Quality Choice Signs Pty Ltd	Hard Hat Stickers	SEQ	С	4551
Vincian	Supply and deliver of Mirrors for Prototype Suite	AUS	C	4173
	Corporate Charges	SEQ	L	
Multimadia Technology	Panescric Paeracilis Penelcoard Wide CS' Multi Touch Enteractive Wildsboard	seq (7)	/\ c	4006
The Trustae for The McGreal Family Trust 1/A immediate Response First Aid	First Art Supplies to the SCUH Privide Car Park First Aid Shed & First Aid Training on an es needs basis			4556
Sharnspok CAII	Sulk CM Works Pre-Load		L	4076
Fractions Call Engineering	Cut to FII Civil Works	- SEG /	L	4556
Vacated Piling	Proceet Pling & Sheer Pling	/ SED/		4060
Seeks & Bartole Ply Ltd	Temp Hydraulice (Site Wide)	(SEG	C	4013
Schoolin	ristal Formwork to CP2)//)8F6	LANGE	4173
East Coast Concrete Contractors	Concrete Place and Finish to CP2	NSW	L	2485
Delay Steel	Reinforcement Fix to CP2	7 SEQ	G	4178
te Cenciule Pumping	Concrete Purp ring to CP2	85Q		4220





A Division of QMI Solutions

Progress Report #7 for period to 31 May 2013 Prepared by Industry Capability Network (Queensland) Ltd

This report details the assistance provided during the above period by ICN (Qld) to Lend Lease in the delivery and implementation of the Local Industry Participation Plan (LIPP) for the Sunshine Coast University Hospital in accordance with the Local Industry Policy (LIP).

1. Liaison with the Project on LIP Issues

ICN met with Queensland Health (Sam Betros) in May 2011 to discuss the project, ICN services, and LIP procedures and issues. ICN assisted QH in the development of the LIPP for the project and provided an evaluation report to QH on project bidders' LIP plan submissions in March 2012.

2. Liaison with Lend Lease on LIP Compliance

Lend Lease met with ICN to establish processes and procedures for management of the project's obligations to the LIP. It was decided that ICN will provide support on number of services covering:

- Implementation of the LIPP (capability searches on contestable packages)
- Presenting at briefing sessions
- Registering companies via ICN Gateway
- Verification of source of manufacture and service provision in subcontracts
- Business matching
- Progress reporting (Monthly) and final LIPP Outcomes reporting (at end of project)

3. Tier Barometer

Tier Barometer is an on-line self-assessment tool developed by ICN and the State Government. It provides participating companies with an assessment of their tier level in terms of supply to major projects. The tool is used by the project to analyse the basic capabilities of potential suppliers during the registration process.


4. Contestable Packages

Queensland and Australian capability, content and capacity will be considered for all the work packages. The following activities have been undertaken:

- An ICN officer has been assigned full time to the project.
- Detailed Business Matching has been carried out by ICN. 131 work packages have been managed in this way.
 These are listed at Attachment A.
- 1279 registrations against work packages on Gateway have been received
- 65 early works have been awarded in March. These are listed at Attachment β.
- 11 work packages have been awarded so far and they are listed at Attachment C.

Potential subcontractors will be given an indication of the size and generic nature of the project, and questioned regarding their capability and capacity to carry out the work, code compliance, and previous work history. Reports will be sent to Lend Lease detailing local companies which have the capability and capacity to carry out the work for each of the above packages. The primary objective of the Local Industry Policy is to ensure that competitive local companies are given full, fair and reasonable opportunity to tender for work packages. This objective will be achieved if the companies nominated by ICN, and other local companies that Lend Lease is aware of, are considered in the establishment of the tender list, and, subject to meeting pre-qualification criteria, a reasonable number of local companies are subsequently invited to tender. Lend Lease intends to apply this requirement.

6. Source of Supply



Lend Lease has advised that out of 76 Purchase Orders, 65 were awarded for early works and 11 for Work Packages listed on the ICN Gateway Project webpage. These were to companies that registered interest via ICN. As far as practicable, the measurement of industry participation focuses on the actual source of supply rather than the location through which the order is placed. The location in which services are provided, materials manufactured or where value adding takes place is indicative of the actual source of supply. Of the 11 Work Package contracts that have been awarded, eight were won by South East Queensland (SEQ) companies, one by Regional Queensland and two by New South Wales companies.

7. Prototype Building

A prototype showcase building was erected in record time. This enabled focus group to provide input in to the final design in a cost effective manner.

8. Local Industry Participation

Lend Lease Project Director has personally provided project work scope and Lend Lease supplier engagement approach information to a number of larger Australian Manufacturers who have asked for more information. These include in the past month The GWA Group; The Laminex Group; Spence Doors and Rockcote Industries. For the latter company time was dedicated to a site inspection of their manufacturing facilities.

9. Information Sessions

ICN supported Lend Lease in delivering briefing sessions as proposed in their LIP plan covering:

Monday 3rd September 2012 - Civil, Infrastructure, Structure & Landscaping

Monday 17th September 2012 - Services

Monday 24th September 2012 - Roof & Façade

Monday 8th October 2012 - Fit out & Finishes

Monday 15th October 2012 - Furniture Fittings & Equipment (FF&E)

Lend Lease also presented at the General Briefing Sessions along with ICN on 13, 14, 16 and 20th of August 2012.

Lend Lease project managers attended a briefing presentation by the members of the Cleantech Industries group of companies on 24th September 2012.

Lend Lease took part in a Local Business expo on 10th May 2013.

10. Efforts to engage with Local Companies include:

Press release by Health Minister, radio interviews by Project Director, Newspaper articles in CM and Sunshine Coast Daily followed up by substantial advertisements in the same newspapers on 19th January. Support articles followed from SSC Council and local councillors.

As a result of the above information sessions and the advertising campaign almost 1000 registrations have been received with close to 100 companies listing after the newspaper advertisements.

11. Source of Manufacture

As subcontracts begin to be awarded, the source of manufacture or service provision for contestable packages will be validated and verified in discussion with the corresponding subcontractors.

12. Reporting

dusiness matching reports on companies nominated for the trade packages listed at Attachment A are being provided to Lend Lease.

Chris Martin
Manager - Commercial Programs
ICN Queensland

	
Attachment A:	
Enquiries	
PR.0051.01 Crossover Road Construction	640.PR0056.02 - PRW - Site Office Cleaning
TP.0231.01 Preload	643.1.TP0410.01 - FMC - Concrete Supply
TP.0320.01 Sediment control	643.1.TP0420.01 - FMC - Concrete Place
PRO059 Site Security	643.1.TPQ422.01 - FMC - Concrete Pumping
644.2.TP1732.01 - CP2 - Hydraulics	643.1.TPO431.01 - FMC - Precast Concrete
644.2.TP0620.01 - CP2 - Reinforcement Fixing	643.2.TP0410.01 - MHU - Concrete Supply
644.2 TP0530.01 - CP2 - Formwork	643.2.TPO420.01 - MHU - Concrete Placing
644.2.TP0422.01 - CP2 - Concrete Pumping	643.2.TPO422.01 - MHU - Concrete Pumping
644.2.TP0422.01 - CP2 - Concrete Planting	644.1.TP0410.01 - CP1 - Concrete Supply
<u> </u>	644.1.TP0420.01 - CP1 - Concrete Place
644.2.TP0410.01 - CP2 - Concrete Supply	644.1.TP0422.01 - CP1 - Concrete Place
644.2 TP0060.01 - CP2 - Scaffolding	
645 TP3230.01 - Kawana Way Duplication	643.1.TP0060.01 - FMC - Scaffolding
641.TP 0230.01 - RIE - Buik Earthworks and Fill	644.1.TP0060.01 - CP1 - Scaffolding
641.TP.3230.01 - RIE - Roads & Infrestructure Services	642.TP.0830.01 - MHB - Blockwork
644.2.TP2239.01 - CP2 - Carpark Control System	643.1.TP0830.01 - FMC - Blockwork
640.PR0033.01 - PRW - Temporary Hydrautics	643.2.TP0830.01 - MHU - Blockwork
640,PR0056.01 - PRW - Rubbish Removal	644.1 TP0830.01 - CP1 - Blockwork
644.2.TP0832.01 - CP2 - Waterproofing	640.PR0054.01 - PRW - Site Photography
644.2.TP2330.01 - CP2 - Electrical	644.2.TP3030.01 - CP2 - Painting & Line Marking
640.PR0042.01 - PRW - Tower Cranes, Hoists & Crews	644.1-TP3030.01 - CP1 - Painting & Line Marking
644.2.TP0631.01 - CPZ - Post Tensioning	644,2.TP1030.01 - CP2 - Structyral Steelwork
642.TP.2030 01 - MHB - Vertical Transportation	644,1.TP1030.02 - CP1 - Structural Steelwork
643.1 TP2030.01 - FMC - Vertical Transportation	642 TP.2230.01 - MHB - Building Maintenance Unit
643.2.TP2030.01 - MHU - Vertical Transportation	643.2.TP1631.01 - MHU - Reofing-Bult-up / Membrane
644.1.TP2030.01 - CP1 - Vertical Transportation	642,TP.1630.01 - MHB Roof & Metal Clariding
640 PR0041.01 - PRW - Mobile Cranes	642.TP.1636.01 - MHB - Wall Cladding Systems
644.2.TP1830.01 - CP2 - Mechanical	642.TP 1032.01 - MH B - Facage Framing
644.2.TP1712.01 - CP2 - Water Tanks	642 TP 1132 01 - MHB - Short Froms
640.PR0021.02 - PRW - Site Fencing	642 TP. 1135.02 - MHB Sugshades & Light Shelves
640.PR0046.01 - PRW - Temporary Plant & Equipment	642.TP.1131/01 MMB / Metal Windows
640,PR0022.06 - PRW - Temporary Onsite Canteen and Catering Services	642 TP.1631.01 MHB -Roofing-Built-up / Membrane
640.PR0022.05 - PRW - Temporary Offsite Canteer and Catering Services	642.TA 171201 - MHB Tanks & Pumps Supply
	643-2 TP1710.01 - MHU - Sanitaryware & Tapware Supply
644.1.TP0530.01 - CP1 - Formwork	642.TP.3/22.03. MHB - Sanitaryware & Tapware Supply
642.TP.0530.01 - MHB - Formwork	642-TP 1232-01 - MHB - Balustrades & Handrails
643,2.TP0530.01 - MHU - Formwork	
643.1.TP0530.01 - FMC - Formwork	642_TP.1230,01 MHB - Metalwork
643.1 TP2310.01 - FMC - Site Wide HV Equipment Supply Only	6(2.7° 1/235.01 - MHB - Metal Louvres
642.TP2335.02 - PRW - Uninterruptable Power Supply Units (UPS) & Maintenance	
644.1.TP0330.02 - CP1 - Pile Cut-off	643.1.TP1630.01 - FMC - Roof Metal Sheeting
643.2.TP0330.02 - MHU- Pile Cut-off	643:1-TP1636.01 - FMC - Facade Cladding
643.1.TP0330.02 - FMC - Pile Cut-off	643.1.TP1032.01 - FMC - Facade Framing
642,TP.0330.03 - MHB - Sheet Piling	642.TF.1030.01 - MHB - Structural Steelwork
642.TP.0330.02 - MHB - Pile Cut-off	643.1.TP1135.01 - FMC - Sunshades and Light Shelves
643.1.TP0330.03 - FMC - Sheet Piling	643.1 TP1810.02 - FMC - Mechanical Services - Chiller Supply
644.1.TP0620.01 - CP1 - Reinforcement Fix	643.1.TP1810.03 - FMC - Mechanical Services - Cooling Tower Supply
642.TP.0620.01 - MHB - Reinforcement Fix	643.1.TP1810.04 - FMC - Mechanical Services - AHU Supply
642 TP:0631.01 - MHB - Post Tensioning	643.1 TP1810.01 - FMC - Mechanical Services - Tanks
643.1.TP0620.01 - FMC - Reinforcement Flx	643.1.TP1231.01 - FMC - Bajustrades & Handrails
643.1.TP0631.01 - FMC- Post Tensioning	643.1 TP1235.01 - FMC - Metal Louvres
643,2.TP0620.01 - MHU - Reinforcement Fix	643.1 TP1432.01 - FMC - Curtains & Blinds
644.1.TP0631.01 - CP1 - Post Tensioning	The second secon
	643.1.TP1230.01 - FMC - Metalwork
	643.1.TP1230.01 - FMC - Metalwork 643.1.TP1030.01 - FMC - Structural Steelwork
640.PR0052.01 - PRW - Safety Precautions (RPE)	643,1.TP1030.01 - FMC - Structural Steelwork
640.PR0052.01 - PRW - Safety Precautions (RPE) 642.TP.0832.01 - MHB - Waterproofing Inground	
640.PR0052.01 - PRW - Safety Precautions (RPE) 642.TP.0832.01 - MHB - Waterproofing Inground 642.TP.0832.02 - MHB - Waterproofing Roofs & Decks	643,1.TP1030.01 - FMC - Structural Steelwork
640.PR0052.01 - PRW - Safety Precautions (RPE) 642.TP.0832.01 - MHB - Waterproofing Inground 642.TP.0832.02 - MHB - Waterproofing Roofs & Decks 642.TP.0832.03 - MHB - Temporary Waterproofing	643,1.TP1030.01 - FMC - Structural Steelwork
640.PR0052.01 - PRW - Safety Precautions (RPE) 642.TP.0832.01 - MHB - Waterproofing Inground 642.TP.0832.02 - MHB - Waterproofing Roofs & Decks 642.TP.0832.03 - MHB - Temporary Waterproofing 643.1.TP0832.01 - FMC - Waterproofing & January	643,1.TP1030.01 - FMC - Structural Steelwork
640.PR0052.01 - PRW - Safety Precautions (RPE) 642.TP.0832.01 - MHB - Waterproofing Inground 642.TP.0832.02 - MHB - Waterproofing Roofs & Decks 642.TP.0832.03 - MHB - Temporary Waterproofing 643.1.TP0832.01 - FWC - Waterproofing & Tanking - Roofs & Decks	643,1.TP1030.01 - FMC - Structural Steelwork
640.PR0052.01 - PRW - Safety Precautions (RPE) 642.TP.0832.01 - MHB - Waterproofing Inground 642.TP.0832.02 - MHB - Waterproofing Roofs & Decks 642.TP.0832.03 - MHB - Temporary Waterproofing 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.1.TP3832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.2.TP0832.01 - MHU - Waterproofing	643,1.TP1030.01 - FMC - Structural Steelwork
640.PR0052.01 - PRW - Safety Precautions (PPE) 642.TP.0832.01 - MHB - Waterproofing Inground 642.TP.0832.02 - MHB - Waterproofing Roofs & Decks 642.TP.0832.03 - MHB - Temporary Waterproofing 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.2.TP0832.01 - MHU - Waterproofing 644.1.TP0832.01 - CP1 - Waterproofing	643,1.TP1030.01 - FMC - Structural Steelwork
640.PR0052.01 - PRW - Safety Precautions (PPE) 642.TP.0832.01 - MHB - Waterproofing Inground 642.TP.0832.02 - MHB - Waterproofing Roofs & Decks 642.TP.0832.03 - MHB - Temporary Waterproofing 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.1.TP0832.01 - MHU - Waterproofing 644.1.TP0832.01 - CP1 - Waterproofing 642.TP0832.01 - PRW - Skte Wide LV Equipment Supply	643,1.TP1030.01 - FMC - Structural Steelwork
640.PR0052.01 - PRW - Safety Precautions (PPE) 642.TP.0832.01 - MHB - Waterproofing Inground 642.TP.0832.02 - MHB - Waterproofing Roofs & Decks 642.TP.0832.03 - MHB - Temporary Waterproofing 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.2.TP0832.01 - MHU - Waterproofing 644.1.TP0832.01 - CP1 - Waterproofing 642.TP2335.01 - PRW - Site Wide LV Equipment Supply 641.TP0410.01 - RIE - Concrete Supply	643,1.TP1030.01 - FMC - Structural Steelwork
640.PR0052.01 - PRW - Safety Precautions (PPE) 642.TP.0832.01 - MHB - Waterproofing Inground 642.TP.0832.02 - MHB - Waterproofing Roofs & Decks 642.TP.0832.03 - MHB - Temporary Waterproofing 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.2.TP0832.01 - MHU - Waterproofing 644.1.TP0832.01 - CP1 - Waterproofing 642.TP2335.01 - PRW - Site Wide LV Equipment Supply 641.TP0410.01 - RIE - Concrete Supply 642.TP.0420.01 - MHB - Concrete Place & Finish	643,1.TP1030.01 - FMC - Structural Steelwork
640.PR0052.01 - PRW - Safety Precautions (PPE) 642.TP.0832.01 - MHB - Waterproofing Inground 642.TP.0832.02 - MHB - Waterproofing Roofs & Decks 642.TP.0832.03 - MHB - Temporary Waterproofing 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.2.TP0832.01 - MHU - Waterproofing 644.1.TP0832.01 - CP1 - Waterproofing 644.1.TP0832.01 - PRW - Site Wide LV Equipment Sypply 641.TP0410.01 - RIE - Concrete Supply 642.TP.0420.01 - MHB - Concrete Place & Finish CP1.TP2335.01 - CP1/CP2 - Light Fitting Supply	643,1.TP1030.01 - FMC - Structural Steelwork
640.PR0052.01 - PRW - Safety Precautions (PPE) 642.TP.0832.01 - MHB - Waterproofing Inground 642.TP.0832.02 - MHB - Waterproofing Roofs & Decks 642.TP.0832.03 - MHB - Temporary Waterproofing 643.1.TP.0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.1.TP3832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.2.TP0832.01 - MHU - Waterproofing 644.1.TP0832.01 - CP1 - Waterproofing 644.1.TP0832.01 - PRW - Site Wide LV Equipment Supply 642.TP.0420.01 - RIE - Concrete Supply 642.TP.0420.01 - MHB - Concrete Place & Finish CP1.TP2335.01 - CP1/CP2 - Light Fitting Supply 640.PR0033.03 - PRW - Temporary Hydraulics Site Wide Reticulation	643,1.TP1030.01 - FMC - Structural Steelwork
640.PR0052.01 - PRW - Safety Precautions (PPE) 642.TP.0832.01 - MHB - Waterproofing Inground 642.TP.0832.02 - MHB - Waterproofing Roofs & Decks 642.TP.0832.03 - MHB - Temporary Waterproofing 643.1.TP.0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.1.TP3832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.2.TP0832.01 - MHU - Waterproofing 644.1.TP0832.01 - CP1 - Waterproofing 644.1.TP0832.01 - PRW - Site Wide LV Equipment Supply 642.TP.0420.01 - RIE - Concrete Supply 642.TP.0420.01 - MHB - Concrete Place & Firish CP1.TP2335.01 - CP1/CP2 - Light Fitting Supply 640.PR0033.03 - PRW - Temporary Hydraulics Site Wide Reticulation 641.TP1732.01 - RIE - Water & Fire Mains reticulation	643,1.TP1030.01 - FMC - Structural Steelwork
640.PR0052.01 - PRW - Safety Precautions (PPE) 642.TP.0832.01 - MHB - Waterproofing Inground 642.TP.0832.02 - MHB - Waterproofing Roofs & Decks 642.TP.0832.03 - MHB - Temporary Waterproofing 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.2.TP0832.01 - MHU - Waterproofing 644.1.TP0832.01 - CP1 - Waterproofing 644.1.TP0832.01 - PRW - Site Wide LV Equipment Supply 642.TP0430.01 - RIE - Concrete Supply 642.TP.0420.01 - MHB - Concrete Place & Firish CP1 TP2335.01 - CP1/CP2 - Light Fitting Supply 640.PR0033.03 - PRW - Temporary Hydraulics Site Wide Reticulation 641.TP1732.01 - RIE - Water & Fire Mains reticulation 642.TP.0422.01 - MHB - Concrete Pumping	643,1.TP1030.01 - FMC - Structural Steelwork
640.PR0052.01 - PRW - Safety Precautions (PPE) 642.TP.0832.01 - MHB - Waterproofing Inground 642.TP.0832.02 - MHB - Waterproofing Roofs & Decks 642.TP.0832.03 - MHB - Temporary Waterproofing 643.1.TP.0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.1.TP3832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.2.TP0832.01 - MHU - Waterproofing 644.1.TP0832.01 - CP1 - Waterproofing 644.1.TP0832.01 - PRW - Site Wide LV Equipment Supply 642.TP.0420.01 - RIE - Concrete Supply 642.TP.0420.01 - MHB - Concrete Place & Firish CP1.TP2335.01 - CP1/CP2 - Light Fitting Supply 640.PR0033.03 - PRW - Temporary Hydraulics Site Wide Reticulation 641.TP1732.01 - RIE - Water & Fire Mains reticulation	643,1.TP1030.01 - FMC - Structural Steelwork
640.PR0052.01 - PRW - Safety Precautions (PPE) 642.TP.0832.01 - MHB - Waterproofing Inground 642.TP.0832.02 - MHB - Waterproofing Roofs & Decks 642.TP.0832.03 - MHB - Temporary Waterproofing 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.2.TP0832.01 - MHU - Waterproofing 644.1.TP0832.01 - CP1 - Waterproofing 644.1.TP0832.01 - PRW - Site Wide LV Equipment Supply 642.TP0430.01 - RIE - Concrete Supply 642.TP.0420.01 - MHB - Concrete Place & Firish CP1 TP2335.01 - CP1/CP2 - Light Fitting Supply 640.PR0033.03 - PRW - Temporary Hydraulics Site Wide Reticulation 641.TP1732.01 - RIE - Water & Fire Mains reticulation 642.TP.0422.01 - MHB - Concrete Pumping	643,1.TP1030.01 - FMC - Structural Steelwork
640.PR0052.01 - PRW - Safety Precautions (PPE) 642.TP.0832.01 - MHB - Waterproofing Inground 642.TP.0832.02 - MHB - Waterproofing Roofs & Decks 642.TP.0832.03 - MHB - Temporary Waterproofing 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.1.TP0832.01 - FMC - Waterproofing 644.1.TP0832.01 - CP1 - Waterproofing 642.TP2335.01 - PRW - Site Wide LV Equipment Supply 642.TP0410.01 - RIE - Concrete Supply 642.TP.0420.01 - MHB - Concrete Place & Firish CP1 TP2335.01 - CP1/CP2 - Light Fitting Supply 640.PR0033.03 - PRW - Temporary Hydraulics Site Wide Reticulation 641.TP1732.01 - RIE - Water & Fire Mains reticulation 642.TP.0422.01 - MHB - Concrete Pumping 643.1.TP2312.01 - FMC - HV Generator Supply	643,1.TP1030.01 - FMC - Structural Steelwork
640.PR0052.01 - PRW - Safety Precautions (PPE) 642.TP.0832.01 - MHB - Waterproofing Inground 642.TP.0832.02 - MHB - Waterproofing Roofs & Decks 642.TP.0832.03 - MHB - Temporary Waterproofing 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.2.TP0832.01 - MHU - Waterproofing 644.1.TP0832.01 - CP1 - Waterproofing 644.1.TP0832.01 - CP1 - Waterproofing 644.TP04332.01 - RIE - Concrete Supply 641.TP0410.01 - RIE - Concrete Supply 642.TP.0420.01 - MHB - Concrete Place & Finish CP1 TP2335.01 - CP1/CP2 - Light Fitting Supply 640.PR0033.03 - PRW - Temporary Hydraulics Site Wide Reticulation 641.TP1732.01 - RIE - Water & Fire Mains reticulation 642.TP.0431.01 - MHB - Concrete Pumping 643.1.TP2312.01 - FMC - HV Generator Supply 644.TP.0431.01 - MHB - Precast Concrete 644.2.TP0830.01 - CP2 - Blockwork 640.PR0032.02 - PRW - Main Site Office & Accommodation Temporary Electrical	643.1.TP1030.01 - FMC - Structural Steelwork 643.1.TP2236.01 - FMC - Kitchen / Laundry Equipment
640.PR0052.01 - PRW - Safety Precautions (PPE) 642.TP.0832.01 - MHB - Waterproofing Inground 642.TP.0832.02 - MHB - Waterproofing Roofs & Decks 642.TP.0832.03 - MHB - Temporary Waterproofing 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.2.TP0832.01 - MHU - Waterproofing 644.1.TP0832.01 - CP1 - Waterproofing 644.1.TP0832.01 - CP1 - Waterproofing 644.TP04332.01 - RIE - Concrete Supply 641.TP0410.01 - RIE - Concrete Supply 642.TP.0420.01 - MHB - Concrete Place & Finish CP1 TP2335.01 - CP1/CP2 - Light Fitting Supply 640.PR0033.03 - PRW - Temporary Hydraulics Site Wide Reticulation 641.TP1732.01 - RIE - Water & Fire Mains reticulation 642.TP.0431.01 - MHB - Concrete Pumping 643.1.TP2312.01 - FMC - HV Generator Supply 644.TP.0431.01 - MHB - Precast Concrete 644.2.TP0830.01 - CP2 - Blockwork 640.PR0032.02 - PRW - Main Site Office & Accommodation Temporary Electrical	643.1.TP1030.01 - FMC - Structural Steelwork 643.1.TP2236.01 - FMC - Kitchen / Laundry Equipment
640.PR0052.01 - PRW - Safety Precautions (PPE) 642.TP.0832.01 - MHB - Waterproofing Inground 642.TP.0832.02 - MHB - Waterproofing Roofs & Decks 642.TP.0832.03 - MHB - Temporary Waterproofing 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.2.TP0832.01 - MHU - Waterproofing 644.1.TP0832.01 - CP1 - Waterproofing 642.TP2335.01 - PRW - Site Wide LV Equipment Supply 641.TP0410.01 - RIE - Concrete Supply 642.TP.0420.01 - MHB - Concrete Place & Finish CP1 TP2335.01 - CP1/CP2 - Light Fitting Supply 640.PR0033.03 - PRW - Temporary Hydraulics Site Wide Reticulation 641.TP1732.01 - RIE - Water & Fire Mains reticulation 642.TP.0422.01 - MHB - Concrete Pumping 643.1.TP2312.01 - FMC - HV Generator Supply 642.TP.0431.01 - MHB - Precast Concrete 644.2.TP0830.01 - CP2 - Blockwork 640.PR0032.02 - PRW - Main Site Office & Accommodation Temporary Electrical 640.PR0022.02 - PRW - Temporary Lunch Sheds / Ablutions / Containers / Other S	643.1.TP1030.01 - FMC - Structural Steelwork 643.1.TP2236.01 - FMC - Kitchen / Laundry Equipment
640.PR0052.01 - PRW - Safety Precautions (PPE) 642.TP.0832.01 - MHB - Waterproofing Inground 642.TP.0832.02 - MHB - Waterproofing Roofs & Decks 642.TP.0832.03 - MHB - Temporary Waterproofing 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.2.TP0832.01 - MHU - Waterproofing 644.1.TP0832.01 - CP1 - Waterproofing 644.1.TP0832.01 - CP1 - Waterproofing 644.1.TP0832.01 - PRW - Site Wide LV Equipment Supply 641.TP0410.01 - RIE - Concrete Supply 642.TP.0420.01 - MHB - Concrete Place & Finish CP1 TP2335.01 - CP1/CP2 - Light Fitting Supply 640.PR0033.03 - PRW - Temporary Hydraulics Site Wide Reticulation 641.TP1732.01 - RIE - Water & Fire Mains reticulation 642.TP.0431.01 - MHB - Concrete Pumping 643.1.TP2312.01 - FMC - HV Generator Supply 644.TP.0431.01 - MHB - Precast Concrete 644.2.TP0830.01 - CP2 - Blockwork 640.PR0032.02 - PRW - Main Site Office & Accommodation Temporary Electrical 640.PR0022.92 - PRW - Temporary Lunch Sheds / Ablutions / Containers / Other S 642.TP.0060.01 - MHB - Scaffolding	643.1.TP1030.01 - FMC - Structural Steelwork 643.1.TP2236.01 - FMC - Kitchen / Laundry Equipment
640.PR0052.01 - PRW - Safety Precautions (PPE) 642.TP.0832.01 - MHB - Waterproofing Inground 642.TP.0832.02 - MHB - Waterproofing Roofs & Decks 642.TP.0832.02 - MHB - Temporary Waterproofing 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.1.TP0832.01 - FMC - Waterproofing 644.1.TP0832.01 - CP1 - Waterproofing 644.1.TP0832.01 - PRW - Site Wide LV Equipment Supply 642.TP0832.01 - PRW - Site Wide LV Equipment Supply 642.TP.0420.01 - MHB - Concrete Supply 642.TP.0420.01 - MHB - Concrete Place & Firish CP1 TP2335.01 - CP1/CP2 - Light Fitting Supply 640.PR0033.03 - PRW - Temporary Hydraulics Site Wide Reticulation 641.TP1732.01 - RIE - Water & Fire Mains reticulation 642.TP.0422.01 - MHB - Concrete Pumping 643.1.TP2312.01 - FMC - HV Generator Supply 642.TP.0431.01 - MHB - Precast Concrete 644.2.TP0830.01 - CP2 - Blockwork 640.PR0032.02 - PRW - Main Site Office & Accommodation Temporary Electrical 640.PR0022.02 - PRW - Temporary Lunch Sheds / Ablutions / Containers / Other S 642.TP.0060.01 - MHB - Scaffolding 644.2.TP131.01 - CP2 - Facade / Screens	643.1.TP1030.01 - FMC - Structural Steelwork 643.1.TP2236.01 - FMC - Kitchen / Laundry Equipment
640.PR0052.01 - PRW - Safety Precautions (PPE) 642.TP.0832.01 - MHB - Waterproofing Inground 642.TP.0832.02 - MHB - Waterproofing Roofs & Decks 642.TP.0832.03 - MHB - Temporary Waterproofing 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.1.TP0832.01 - FMC - Waterproofing 644.1.TP0832.01 - CP1 - Waterproofing 644.1.TP0832.01 - CP1 - Waterproofing 642.TP2335.01 - PRW - Site Wide LV Equipment Supply 642.TP.0420.01 - MHB - Concrete Supply 642.TP.0420.01 - MHB - Concrete Place & Finish CP1 TP2335.01 - CP1/CP2 - Light Fitting Supply 640.PR0033.03 - PRW - Temporary Hydraulics Site Wide Reticulation 641.TP1732.01 - RIE - Water & Fire Mains reticulation 642.TP.0422.01 - MHB - Concrete Pumping 643.1.TP2312.01 - FMC - HV Generator Supply 642.TP.0431.01 - MHB - Precast Concrete 644.2.TP.0431.01 - MHB - Precast Concrete 644.2.TP0830.01 - CP2 - Blockwork 640.PR0032.02 - PRW - Main Site Office & Accommodation Temporary Electrical 640.PR0032.02 - PRW - Main Site Office & Accommodation Containers / Other S 642.TP.0060.01 - MHB - Scaffolding 644.2.TP1331.01 - CP2 - Facade / Screens 644.2.TP1331.01 - CP2 - General Carpentry	643.1.TP1030.01 - FMC - Structural Steelwork 643.1.TP2236.01 - FMC - Kitchen / Laundry Equipment
640.PR0052.01 - PRW - Safety Precautions (PPE) 642.TP.0832.02 - MHB - Waterproofing Inground 642.TP.0832.02 - MHB - Waterproofing Roofs & Decks 642.TP.0832.03 - MHB - Temporary Waterproofing 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.1.TP0832.01 - MHU - Waterproofing 644.1.TP0832.01 - CP1 - Waterproofing 642.TP0832.01 - PRW - Site Wide LV Equipment Supply 642.TP.0420.01 - MHB - Concrete Supply 642.TP.0420.01 - MHB - Concrete Place & Firish CP1 TP2335.01 - CP1/CP2 - Light Fitting Supply 640.PR0033.03 - PRW - Temporary Hydraulics Site Wide Reticulation 641.TP1732.01 - RIE - Water & Fire Mains reticulation 642.TP.0422.01 - MHB - Concrete Pumping 643.1.TP2312.01 - FMC - HV Generator Supply 642.TP.0431.01 - MHB - Precast Concrete 644.2.TP0830.01 - CP2 - Blockwork 640.PR0032.02 - PRW - Temporary Lunch Sheds / Ablutions / Containers / Other S 644.2.TP1331.01 - CP2 - Facade / Screens 644.2.TP1330.01 - CP2 - General Carpentry 640.PR0022.07 - PRW - Pest Control	643.1.TP1030.01 - FMC - Structural Steelwork 643.1.TP2236.01 - FMC - Kitchen / Laundry Equipment
640.PR0052.01 - PRW - Safety Precautions (PPE) 642.TP.0832.01 - MHB - Waterproofing Inground 642.TP.0832.02 - MHB - Waterproofing Roofs & Decks 642.TP.0832.03 - MHB - Temporary Waterproofing 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.1.TP0832.01 - FMC - Waterproofing 644.1.TP0832.01 - CP1 - Waterproofing 644.1.TP0832.01 - PRW - Site Wide LV Equipment Supply 642.TP2335.01 - PRW - Site Wide LV Equipment Supply 642.TP.0420.01 - MHB - Concrete Supply 642.TP.0420.01 - MHB - Concrete Place & Firish CP1 TP2335.01 - CP1/CP2 - Light Fitting Supply 640.PR0033.03 - PRW - Temporary Hydraulics Site Wide Reticulation 641.TP1732.01 - RIE - Water & Fire Mains reticulation 642.TP.0422.01 - MHB - Concrete Pumping 643.1.TP2312.01 - FMC - HV Generator Supply 642.TP.0431.01 - MHB - Precast Concrete 644.2.TP.0830.01 - CP2 - Blockwork 640.PR0032.02 - PRW - Main Site Office & Accommodation Temporary Electrical 640.PR0032.02 - PRW - Temporary Lunch Sheds / Ablutions / Containers / Other S 642.TP.0060.01 - MHB - Scaffolding 644.2.TP1331.01 - CP2 - Facade / Screens 644.2.TP1330.01 - CP2 - General Carpentry	643.1.TP1030.01 - FMC - Structural Steelwork 643.1.TP2236.01 - FMC - Kitchen / Laundry Equipment

Attachment B:				
		I IDD Onto profession	0	
Business Engagement		LIPP Categorisation ISEQ - South East QLD	Source of Supply C-Contestable	20.10.1
Subcontractor	Resson	REQ - Regional OLD AUS - Rest of Australia RIP - Imported	L - Local	PostCode
Builtament Modular Mining Pty Ltd	Modular Prototype Suite	AUS	С	2250
Shadforths Civil Pty Ltd	CP2 Early Works	REQ	L	4556
Wagstaff Plling QLD Pty Ltd	Test Piling	SEQ	L	4060
EVS Group Austrelia Pty Ltd	Site Security	SEQ	L	4350
Nilsen QLD Pty Ltd	Temporary Electrical CP2 & Prototype	SEQ	С	4170
Cally Constructions	Protoype Marketing Rigging and Marketing Deck	SEQ	Ļ	4556
Blue Gize Pty Ltd	Blue Glue	AUS	L	2113
Kyana Pty Ltd	Temporary Hydraulics	SEQ	С	4567
Gordon Clemente Nominees Pty Ltd T/A Cally Constructions	Covered Walkways and paths	SEQ	L.	4556
Wagstaff Piling	Site Probing Works - 55 Probe Locations	SEQ	L	4060
Quality Choice Signs	Re skin to existing Billboard	SEQ	С	4575
Fencepac	She Perimeter Security Fence - Stage 1	SEO	С	4556
Fredon CLD Pty Limited	SCUH - Nambour Site	SEQ (//	С	4119
Shadforths	Crossover road Construction	sec_V/)	L	4556
Underground Pipe and Cable Location Pty Ltd	Detect inground services prior to digging fence	SEC	С	4553
O2 Environmental Pty Ltd	Environmental and Sediment Monitoring	\$EQ	L	4573
Shadforths	Supply & replace Road Base - Site Accommodati		L	4556
Calty	Prototype Building Foundations Palmires re-location	SER	L.	4556
Scapshape Pty Ltd		SEO	L	4211
D&J Services	Site Shed Cleaning	SEQ.	L	4011
Floor cover QLD - AK	Installation of vinyl and carpet to the Prototype S	SEQ	С	
Quality Choice Signs	Signage	SEQ.	С	4575
The trustee for The SJ & DY Eade Family Trust T/A Vismark	Supply and install shade cloth to SCUH Site	SEQ	C	4570
Regson Fabrication	Suppy & Install 2 Gate Closures	SEQ	C	4556
Orange Hire Pty Ltd	Supply & Hire of Perimeter Fencing	SEQ	L .	2760
Transpecific Industries Pty Ltd	Site Sewerage Tank Pump Out Mobile Crane Hire	SEQ	С	4064
Universal Cranes Sunshine Coast Pty Ltd	Prototype Security	SEQ	L	4556
Siemens	Prototype Nurse Call & PES	IMP-	С	4006
Merion (t/a Statewide Communications)	Prototype Curtain & IV Tracks	AUS	C	4113
Ken Witson & Associates Pty Ltd T/a KWA Blinds	Portable tollets	SEQ	c	4163
Coales Hire Operations Pty Litt	Energex Detailed Design	SEQ:	L	4131 4558
Energex Limited ATF Sunshine Coast and Total Site Set Up	Supply & Install crowli column barriers	SEQ	C	4000
Evolution Trafic Control	Provide traffic Controlor	SEQ		4558
Lucid Edge PTY LTD	Video conversions from AVI to MVV+ YouTube	AUS	C	4014
Worldwide Online Printing Market Street	Masterplan Poster	SEQ	L	4000
Lucid Edge PTY LTD	Video Conversions from AVI to MWV +	AUS	c	2010
Combined Security Services	Security Guards	SEQ	L	4575
DLA Piper	Professional fees	AUS	L	4000
Graenbins	Size 8 Bin	SEQ	L	4074
Metro Express	2 Containers sen Kom GCUH to SCUH	SEQ	L	4106
Trumpf Med Australia Pty Ltd	9x3 Combination light set & Trumpf Serv	IMP	c	2087
Ariohundeigh	Medical Beds and Patient Lifting System	IMP	č	6163
Arunta Plastics (QLD) Pty Ltd	Outural Heritage Induction	SEQ	U	3134
7 James	Supply and install of windows and external doors	SEQ	L	4556
TF Services Pty Ltd	Temp Fencing	SEQ	L	4558
Robotic Automation Group	AGV Advisory Services	AUS	c	2127
Energy Crane Services Pty	Transport Items to SCUH site	SEQ	Ľ	4034
Energex Limited	Temporary Electrics supply South	SEQ	- L	4006
Spence Door	Supply doors and frame	SEQ	L	4556
Coates Hire Operations Pty Ltd		SEQ	ċ	4131
(yane Projects Pty Ltd	Supply of Bulk Potable and Non-Potable Water	SEQ		4567
Nevertail Springwater Limited	Supply of Potable Water to Site until Feb 13	SEQ	C	4127
Sieve Ryan t/as Rix Ryan Photography P/L	Photograph Palm removal & monthly images	SEQ	L	4215
Durickers Pty Ltd	Supply of Site Accomodation Cleaning Products	SEQ	L	4560
Sizfum Express	Supply and Install of office furniture for Prototype	SEQ	c	4561
Suncoast Water Carriers	Re-RII 2 x 10000L Water Tanks + 1 Additional Vis	SEQ	ĭ	4551
larvey Norman	Supply of kitchen fridge and microwave	SEQ	c	4575
Szium Express	Supply and install of office furniture for Prototype	SEQ	ŏ †	4557
Amalgamated Pest Control	Redback Pest Control to SCUH Site Offices	SEQ	Ľ	4561
Admed	Supply and install of examination couch	SEQ	c	4570
	Hard Hat Stickers	SEQ	c	4551
Quality Choice Signs Pty Lid				
Quality Choice Signs Pty Ltd //ridien	Supply and deliver of Mirrors for Prototype Suite	AUS	C I	4173
Quality Choice Signs Pty Ltd //ridian	Supply and deliver of Mirrors for Prototype Suite Corporate Charges	AUS SEO	C	4173
firidian	Supply and deliver of Mirrors for Prototype Suite Corporate Charges Multi Touch interactive Whiteboard	AUS SEQ SEQ	L C	4006

Attachment C:				
Business Engagement		LIPP Catagorisation	Source of Supply	
Subcontractor	WorkPackage	SEQ - South East QLD REQ - Regional QLD AUS - Rest of Australia	C- Contestable L - Local	PoetCode
Sharrock Civil	Bulk Civil Works Pre-Load	SEQ	L	4076
Shedforth Clvll Engineering	Cut to Fill Civil Works	REQ	L	4556
Wagstaff Piling	Precast Piling & Shear Piling	\$EQ	L	4060
Beavis & Bartels Pty Ltd	Temp Hydraulics (Site Wide)	SEQ	C	4013
Oneform	Install Ferniwork to CP2	SEQ	L	4173
East Coast Concrete Contractors	Concrete Place and Finish to CP2	NSW	L	2485
Delco Steel	Reinforcement Fix to CP2	NSW	С	4178
Pro Concrete Pumping	Concrete Pumping to CP2	SEQ	L	4220
FIP Electrical (Qid) Pty Ltd	Electrical Installation to CP2	SEQ	С	4144
VT Services	Tower Crane to CP2	SEQ	L	4074
Tacoma Plumbing and Drainage	Hydraulics to CP2	SEQ	С	4573





A Division of QMI Solutions

Progress Report #8 for period to 30 June 2013 Prepared by Industry Capability Network (Queensland) Ltd

This report details the assistance provided during the above period by ICN (Qld) to Lend Lease in the delivery and implementation of the Local Industry Participation Plan (LIPP) for the Sunshine Coast University Hospital in accordance with the Local Industry Policy (LIP).

1. Liaison with the Project on LiP Issues

ICN met with Queensland Health (Sam Betros) in May 2011 to discuss the project. ICN services, and LIP procedures and issues. ICN assisted QH in the development of the LIPP for the project and provided an evaluation report to QH an project bidders' LIP plan submissions in March 2012.

2. Liaison with Lend Lease on LIP Compliance

Lend Lease met with ICN to establish processes and procedures for management of the project's obligations to the LIP. It was decided that ICN will provide support on number of services covering:

- Implementation of the LIPP (capability searches on contestable packages)
- Presenting at briefing sessions
- Registering companies via ICN Gateway
- Verification of source of manufacture and service provision in subcontracts
- Business matching
- Progress reporting (Monthly) and final LIPR Outcomes reporting (at end of project)

3. Tier Barometer

Tier Barometer is an on-line self-assessment tool developed by iCN and the State Government. It provides articipating companies with an assessment of their tier level in terms of supply to major projects. The tool is used by the project to analyse the basic capabilities of potential suppliers during the registration process.


4. Contestable Packages

Queensland and Australian capability, content and capacity will be considered for all the work packages. The following activities have been undertaken:

- An ICN officer has been assigned full time to the project.
- Detailed Business Matching has been carried out by ICN. 146 work packages have been managed in this way.
 These are listed at Attachment A.
- 1305 registrations against work packages on Gateway have been received
- 65 early works have been awarded in March. These are listed at Attachment B.
- 21 work packages have been awarded so far and they are listed at Attachment C.

Potential subcontractors will be given an indication of the size and generic nature of the project, and questioned regarding their capability and capacity to carry out the work, code compliance, and previous work history. Reports will be sent to Lend Lease detailing local companies which have the capability and capacity to carry out the work for each of the above packages. The primary objective of the Local Industry Policy is to ensure that competitive local companies are given full, fair and reasonable opportunity to tender for work packages. This objective will be achieved if the companies nominated by ICN, and other local companies that Lend Lease is aware of, are considered in the establishment of the tender list, and, subject to meeting pre-qualification criteria, a reasonable number of local companies are subsequently invited to tender. Lend Lease intends to apply this requirement.

6. Source of Supply



Lend Lease has advised that out of 86 Purchase Orders, 65 were awarded for early works and 21 for Work Packages listed on the ICN Gateway Project webpage. These were to companies that registered interest via ICN. As far as practicable, the measurement of industry participation focuses on the actual source of supply rather than the location through which the order is placed. The location in which services are provided, materials manufactured or where value adding takes place is indicative of the actual source of supply. Of the 21 Work Package contracts that have been awarded, 17 were won by South East Queensland (SEQ) companies, one by Regional Queensland and three by New South Wales companies.

Prototype Building

A prototype showcase building was erected in record time. This enabled focus group to provide input in to the final design in a cost effective manner.

8. Local Industry Participation

Lend Lease Project Director has personally provided project work scope and Lend Lease supplier engagement approach information to a number of larger Australian Manufacturers who have asked for more information. These include in the past month The GWA Group; The Laminex Group; Spence Doors and Rockcote Industries. For the latter company time was dedicated to a site inspection of their manufacturing facilities.

9. Information Sessions

ICN supported Lend Lease in delivering briefing sessions as proposed in their LIP plan covering:

Monday 3rd September 2012 - Civil, Infrastructure, Structure & Landscaping

Monday 17th September 2012 - Services

Monday 24th September 2012 - Roof & Façade

Monday 8th October 2012 - Fit out & Finishes

Monday 15th October 2012 - Furniture Fittings & Equipment (FF&E)

Lend Lease also presented at the General Briefing Sessions along with ICN on 13, 14, 16 and 20th of August 2012.

Lend Lease project managers attended a briefing presentation by the members of the Cleantech Industries group of companies on 24th September 2012.

Lend Lease took part in a Local Business expo on 10th May 2013.

CN - Evan Flower - presented to the Gympie Major Project Opportunities Forum on the project on 18th June 2013.

10. Efforts to engage with Local Companies include:

Press release by Health Minister, radio interviews by Project Director, Newspaper articles in CM and Sunshine Coast Daily followed up by substantial advertisements in the same newspapers on 19th January. Support articles followed from SSC Council and local councillors.

As a result of the above information sessions and the advertising campaign almost 1000 registrations have been received with close to 100 companies listing after the newspaper advertisements.

To date over 1300 companies have registered interest in work packages.

11. Source of Manufacture

As subcontracts begin to be awarded, the source of manufacture or service provision for contestable packages will 'e validated and verified in discussion with the corresponding subcontractors.

12. Reporting

Business matching reports on companies nominated for the trade packages listed at Attachment A are being provided to Lend Lease.

Chris Martin Manager - Commercial Programs ICN Queensland

ne20139 P8 772

Attachment A:	
Enquiries -	
PR.0051.01 Crossover Road Construction	640.PR0056.02 - PRW - Site Office Cleaning
TP.0231.01 Preload	643 1.TP0410.01 - FMC - Concrete Supply
TP.0320.01 Sediment control	643.1 TP0420.01 - FMC - Concrete Place
PR0059 Site Security	643.1.TP0422,01 - FMC - Concrete Pumping
644 2 TP1732.01 - CP2 - Hydraulics	643.1.TP0431.01 - FMC - Precest Concrete
644.2.TP0620.01 - CP2 - Reinforcement Fixing	543.2 TP0410.01 - MHU - Concrete Supply
644.2 TP0530.01 - CP2 - Formwork	643.2.TP0420.01 - MHU - Concrete Placing
644.2.TP0422.01 - CP2 - Concrete Pumping	643.2 TPD422.01 - MHU - Concrete Pumping
644.2 TP0420.01 - CP2 - Concrete Placing	844.1 TP0410.01 - CP1 - Concrete Supply
644.2.TP0410.01 - CP2 - Concrete Supply	644.1.TP0420.01 - CP1 - Concrete Place
644 2 TP0060.01 - CP2 - Scaffolding	644.1.TP0422.01 - CP1 - Concrete Pumping
645 TP3230.01 - Kawana Way Duplication	643.1.TP0060.01 - FMC - Scaffolding
641.TP 0230.01 - RIE - Bulk Earthworks and Fill	644.1 TP0060.01 - CP1 - Scaffolding
641.TP 3230.01 - RIE - Roads & Infrastructure Services	642 TP.0830.01 - MHB - Blockwork
644.2.TP2239.01 - CP2 - Carpark Control System	643.1.TP0830.01 - FMC - Blockwork
640, PRO033.01 - PRW - Temporary Hydraulics	543.2.TP0830.01 - MHU - Blockwork
640.PR0056.01 - PRW - Rubbish Removal	644.1.TP0830.01 - CP1 - Blockwork
644.2 TP0832.01 - CP2 - Waterproofing	640.PR0054.01 - PRW - Site Photography
644.2.TP2330.01 - CP2 - Electrical	644.2 TP3030.01 - CP2 - Painting & Line Marking
640.PR0042.01 - PRW - Tower Cranes, Hoists & Crews	644.1.TP3030.01 - CP1 - Painting & Line Marking
644 2,TP0631.01 - CP2 - Post Tensioning	644.2 TP1030.01 - CP2 - Structural Steelwork
642 TP.2030.01 - MHB - Vertical Transportation	644,1 TP1030.02 - CP1 - Structural Steely or
643.1.TP2030.01 - RMC - Vertical Transportation	642 TP 2230.01 - MHB - Building Maintenance Upit
543.2 TP2030.01 - TWC - Vertical Transportation	643.2.TP1631 01 - MHU - Roofing-Built-up / Memorane
644.1.TP2030.01 - CP1 - Vertical Transportation	642.TP 1630.01 - MH5 - Roof & Metal Cladding
640. PR0041.01 - PRW - Mobile Cranes	642.TP. 1636.01 - MHB - Wall Cladding Systems
644.2 TP1830.01 - CP2 - Mechanical	642.TP.1032.01 - MHB - Facade Framma
644.2.TP1712.01 - CP2 - Water Tanks	642 TP 1132.01 - MHB - Shop Fronts
640.PR0021.02 - PRW - Site Fencing	642 TP 1135.02 - MHB Sunshades & Sunt Shelves
640.PR0046.01 - PRW - Temporary Plant & Equipment	642.TP.1131.01 - MHB - Wetal Windows
640.PR0022.06 - PRW - Temporary Onsite Canteen and Catering Services	642.TP 1632.01 - MHB - Noting-Built-up / Membrane
640.PR0022.05 - PRW - Temporary Carpentry Site Accommodation Areas	642 TP.1712.01 MHB Tanks & Purpos Supply
644.1.TP0530.01 - CP1 - Formwork	643.2.TP1710.01 - MNU - Santap ware & Tapware Supply
642 TP:0530.01 - MHB - Formwork	642.TP.1732.02 - MHB - Sanitaryware & Tapware Supply
643.2.TP0530.01 - MHU - Formwork	642 TP 1231.01 - MHB Balustrades & Handrails
643.1.TP0530.01 - FMC - Formwork	642 TB 1220.03 - MHZ - Metalwork
643 1.TP2310.01 - FMC - Site Wide HV Equipment Supply Only	642.TP.135.01 MHB Metal Louvres
642_TP2335.02 - PRW - Uninterruptable Power Supply Units (UPS) & Maintenance	
644.1.TP0330.02 - CP1 - Pile Cut-off	643.1.TP1630.01 - FMC - Roof Metal Sheeting
643.2.TP0330.02 - MHU- Pile Cut-off	643 1 TP1636.01 - FMC - Facade Cladding
643_1,TP0330,02 - FMC - Pile Cut-off	643 1 TP1032.01 - FMC - Facade Framing
642.TP.0330.03 - MHB - Sheet Piling	642 TP 1030 01 - MHB - Structural Steelwork
642 TP.0330.02 - MHB - Pile Cut-off	643. 1. TP1135.01 - FMC - Sunshades and Light Shelves
643.1.TP0330.03 - FMC - Sheet Piling	643-1 TP1810.02 - FMC - Mechanical Services - Chiller Supply
644.1 TP0620.01 - CP1 - Reinforcement Fix	843.1/TP1810:03 - FMC - Mechanical Services - Cooling Tower Supply
642.TP.0620.01 - MHB - Reinforcement Fix	643.1.TP1810.04 - FMC - Mechanical Services - AHU Supply
642.TP.0631.01 - MHB - Post Tensioning	643 1 TP1810.01 - FMC - Mechanical Services - Tanks
643.1.TP0620.01 - FMC - Reinforcement Flx	643.1 TP1231.01 - FMC - Balustracies & Handrails
643.1.TP0631.01 - FMC- Post Tensioning	643.1.TP1235.01 - FMC - Metal Louvres
643.2. TP0620.01 - MHU - Reinforcement Fix	643 1 TP1432.01 - FMC - Curtains & Blinds
644.1 TP0631.01 - CP1 - Post Tensioning	643 1 TP1230.01 - FMC - Metalwork
640.PRO052.01 - PRW - Safety Precautions (PPE)	643.1 TP1030.01 - FMC - Structural Steelwork
642_TP.0832.01 - MHB - Waterproofing Inground	643.1.TP2236.01 - FMC - Kitchen / Laundry Equipment
642.TP 0832.02 - MHB - Waterproofing Roofs & Decks	642.TP.1637.01 - MHB - Coolrooms & Cleanrooms
642.TP.0832.03 - MHB - Temporary Waterproofing	643.1.TP1637.01 - FMC - Coolrooms & Cleanrooms
643. 1. TP0832.01 - FMC - Waterpreofing & Tanking	644.1.TP1630.01 - CP1 - Roofing
643.1.TP3832.01 - FMC - Waterproofing & Tanking - Roofs & Decks.	643.2.TP1630.01 - MHU - Roofing & Metal Cladding
643.2.TP0832.01 - MHU - Waterproofing	643.2.TP1636.01 - MHU - Wall Cladding Systems
644.1 TP0832.01 - CP1 - Waterproofing	643.1.TP1131.01 - FMC - Metal Windows
642.TP2335.01 - PRW - Site Wide LY Equipment Supply	644.1.TP1131.01 - CP1 - Facade / Screens
641.TPO410.01 - RIE - Concrete Supply	643.2.TP1032.01 - WHU - Facade Framing
642.TP.0420.01 - MHE - Concrete Place & Finish	644.1.TP1235.01 - CP1 - Metal Louvres
CP1.TP2335.01 - CP1/CP2 - Light Fitting Supply	543.2.TP1131.01 - MHU - Metal Windows
640.PR0033.03 - PRW - Temporary Hydraulics Site Wide Reticulation	644.2.TP0057.01 - CP2 - Final Clean
641.TP1732.01 - RIE - Water & Fire Mains reticulation	643.2.TP1135.01 - MHU - Sunshades & Light Shelves
642 TP.0422.01 - MHB - Concrete Pumping	643.2.TP1230.01 - MHU - Metalwork
643.1.TP2312.01 - FMC - HV Generator Supply	543.2 TP1235.01 - MHU - Metal Louvres
642.TP.0431.01 - MHB - Precast Concrete	643.1.TP2235.01 - FMC - Dock Levelers
644.2 TP0830.01 - CP2 - Blockwork	
640.PR0032.02 - PRW - Main Site Office & Accommodation Temporary Electrica	
640.PR0022.02 - PRW - Temporary Lunch Sheds / Ablutions / Containers / Other	Sheds
642.TP.0060.01 - MHB - Scaffolding	
644.2.TP1131.01 - CP2 - Facade / Screens	
644.2.TP1330.01 - CP2 - Facade / Screens 644.2.TP1330.01 - CP2 - General Carpentry	
IGAN DRANCO NO. PRW. Part Control	
640.PR0022.07 - PRW - Pest Control	
640.PR0022.07 - PRW - Pest Control 640.PR0023.03 - PRW - Temporary Site Signage 640.PR0033.02 - PRW - Main Site Office Accommodation Temporary Hydraulics	Lip Progress Report #8 Scuh J

Attachment 3:				
Business Engagement		I INC Colombia		
Subcontractor	Resson	LIPP Categorisation SEQ - South East QLD	Source of Suppli	7
		REQ - Regional QLD AUS - Rest of Australia MRP - Imported	L - Local	PostCod
Bullismart Modular Mining Pty Ltd	Modular Prototype Suite	AUS	c	2250
Shadforths Civil Pty Ltd	CP2 Early Works	REQ	- L	4556
Wagstaff Piling QLD Pty Ltd EVS Group Australia Pty Ltd	Test Piling	SEQ	L	4060
Nilsen QLD Pty Ltd	Site Security	SEQ		4350
Calty Constructions	Temporary Electrical CP2 & Prototype Prototype Marketing Rigging and Marketing Dec	SEQ	С	4170
Blue Glue Pty Ltd	Blue Glue	- PLG	L	4556
Kyana Pty Liti	Temporary Hydraulics	AUS	L L	2113
Gordon Clements Nominees Pty Ltd T/A Cally Constructions	Covered Walkways and paths	SEQ SEQ	C	4567
Wagstaff Piling	Site Probing Works - 55 Probe Locations	SEO	L L	4556
Quality Choice Signs	Re skin to existing Bithoard	SEQ /	√ c	4080 4575
Fencepac	Site Perimeter Security Fence - Stage 1	sto //	C	4556
Fredon QLD Ply Limited Shadforths	SCUH - Nambour Site	SEQ	/ c	4119
Inderground Pipe and Cable Location Pty Ltd	Crossover road Construction	\$EQ	L	4556
22 Environmental Pty Ltd	Detect inground services prior to digging fence	SEC	C	4553
Shadforths	Environmental and Sediment Monitoring Supply & replace Road Base - Site Accommodal	SEO	L	4573
Caty	Prototype Building Foundations		L	4556
Scapeshape Pty Ltd	Paintree re-location		L	4556
08J Services	Site Shed Cleaning	SEC	<u> </u>	4211
foor cover QLD - AK	Installation of vinyl and carpet to the Prototype Si	NSEQ.	<u> </u>	4011
Quality Choice Signs	Signage	SEQ	C	4676
he trustee for The SJ & DY Eade Family Trust T/A Vismark	Supply and install shade cloth to SCUIT Site	SEQ	C	4575 4570
legson Fabrication	Suppy & Install 2 Gate Closures	SEQ	C	4556
wange Hire Pty Lid	Supply & Hire of Perimeter Fencing	SEQ	Ĭ	2760
ranspacific Industries Pty Ltd	Site Sewerage Tank Pume Out	SEQ	C	4064
niversal Cranes Sunshine Coast Pty Ltd	Mobile Crane Hire	SEQ	L	4556
eriners lerion (t/a Statewide Communications)	Prototype Security	IMP	С	4006
en Wilson & Associates Pty Ltd T/a KWA Blinds	Prototype Nurse Call & PES	AUS	С	4113
cates Hire Operations Pty Ltd	Prototype Curtain & IV/Tracks Portable toilets	SEQ	C	4163
nergex Limited	Energex Detailed Design	SEQ	L	4131
IF Sunshine Coast and Total Site Set Up	Supply & Install crowd control parriers	SEQ	L	4558
rotation Traffic Control	Provide traffic Controller	SEQ	С	4000
cid Edge PTY LTD	Video conversions trem AVI to MWV+ YouTube	SEQ	L L	4558
orkhwide Online Printing Market Street	Masterplan Poster	SEQ	C L	4014
cid Edge PTY LTD	Video Conversions from AVI to MWV +	AUS	C	2010
Imbined Security Services	Security Guards	SEQ	L	4575
A Ploer	Professional fees	AUS	i i	4000
eenbins	Size 8 Bin	SEQ	L	4074
Prof Med Austrata Ply Ltd	2 Containers sent from GCUH to SCUH	SEQ	L	4108
oftuntleigh	GG Combination light set & Trumpf Serv	IMP	С	2067
anta Plastics (QLD) Pty Ltd	Medisal Beds and Patient Lifting System	IMP	С	6163
lames	Cultural Psyltage Induction Supply and install of windows and external doors	SEQ		3134
F Services Pty Ltd	Temp Fencing	SEQ	L	4556
botic Automation Group	AGV Advisory Services	SEQ	L	4558
argy Crane Services Pty	Transport Hems to SCUH site	AUS	C	2127
argex Limited	Temporary Electrics supply South	SEQ SEQ	L	4034
ance Door	Supply doors and frame	SEQ	L	4006
ales Hire Operations Pty Ltd		SEQ	_ L	4556
ma Projects Pty Ltd	Supply of Bulk Potable and Non-Potable Water	SEQ	c	4131 4567
erfall Springwater Limited	Supply of Potable Water to Site until Feb 13	SEQ	С	4127
e Ryan Vas Rix Riyan Photography P/L	Photograph Palm removal & monthly images	SEQ	L	4215
ickers Pty Ltd	Supply of Site Accomodation Cleaning Products	SEQ	L	4560
urn Express coast Water Carriers	Supply and Install of office furniture for Prototype	SEQ	С	4561
vey Norman	Re-Fill 2 x 10000L Water Tanks + 1 Additional VI	SEQ	L	4551
urn Express	Supply of kitchen fridge and microwave	SEQ	С	4575
Igamated Pest Control	Supply and Install of office furniture for Prototype	SEQ	C	4557
med	Redback Pest Control to SCUH Site Offices Supply and install of examination couch	SEQ	L	4561
lity Choice Signs Pty Ltd	Hard Hat Stickers	SEQ	C	4570
fan	Supply and deliver of Mirrors for Prototype Suite	SEQ	С	4551
	Corporate Charges	AUS	С	4173
timedia Technology	Multi Touch Interactive Whiteboard	SEQ SEQ	C	
ponse First Aid				4006

Attachment C:		1 mm instrumentantian	Source of Supply	
Business Engagement Bubocitractor	Worl@ackage	LIPP Categorisation SEQ - South East QLD REQ - Regional QLD AUS - Rest of Australia	C-Cortestable 1 Local	PostCacie
Sharmrock Civil	Bulk Civil Works Pre-Load	SEQ	L	4076
hadroth Civil Engineering	Cut to Fill Civil Works	REQ	1	4556
Vagstaff Piling	Precast Piling & Shear Piling	SEQ	<u> </u>	4060
	Temp Hydraulics (Site Wide)	ŞEQ	С	4013
leaves & Bartels Pty Ltd	Install Formwork to CP2	SEQ	L	4173
ast Coast Concrete Contractors	Concrete Place and Finish to CP2	NSW	L	2485
	Reinforcement Fix to CP2	NSW	С	4178
Delco Steel	Concrete Pumping to CP2	SEQ	L	4220
Pro Concrete Pumping	Electrical Installation to CP2	SEQ	C	4144
FIP Electrical (Old) Pty Ltd	Tower Crane to CP2	SEQ	Ĺ	4074
/T Services	Hydraulics to CP2	SEQ	С	4573
facoma Plumbing and Dramage	EVS GROUP AUSTRALIA PTY LTD	NSW	С	2077
PR0059 Site Security	UNISPAN AUSTRALIA PTY LTD	SEQ	C	4207
644.2.TP0060.01 - CP2 - Scaffolding	Boral Construction Materials (QLD)	SEQ		4059
844.2,TP0410.01 - CP2 - Concrete Supply	OTIS ELEVATOR COMPANY PTY LTD	SEQ	1 7	4101
642.TP,2030.01 - MHB - Vertical Transportation	OTIS ELEVATOR COMPANY PTY LTD	SEQ	4 <	4101
643.1.TP2030.01 - FMC - Vertical Transportation	OTIS ELEVATOR COMPANY PTY LTD	SEQ	70	4101
843.2.TP2030.01 - MHU - Vertical Transportation		SEQ	1	4101
844.1.TP2030.01 - CP1 - Vertical Transportation	OTIS ELEVATOR COMPANY PTY LTD	SEQ	11/6-	4207
644.2.TP0632.01 - CP2 - Waterproofing	Polyseal Waterproofing QLD Pty Ltd	SEQ	V /c) /	4207
644.2.TP0631.01 - CP2 - Post Tensioning	STRUCTURAL SYSTEMS (NORTHERN) PTY LTD	SEQ		4559
340.PR0022.08 - PRW - Vending Machines - CP2	QLD Drink and Snack Machines	352	\ 	





A Division of QMI Solutions

Progress Report #9 for period to 31 July 2013 Prepared by Industry Capability Network (Queensland) Ltd

This report details the assistance provided during the above period by ICN (Qld) to Lend Lease in the delivery and implementation of the Local Industry Participation Plan (LIPP) for the Sunshine Coast University Hospital in accordance with the Local Industry Policy (LIP).

1. Liaison with the Project on LIP issues

iCN met with Queensland Health (Sam Betros) in May 2011 to discuss the project, ICN services, and LIP procedures and issues. ICN assisted QH in the development of the LIPP for the project and provided an evaluation report to QH on project bidders' LIP plan submissions in March 2012.

2. Liaison with Lend Lease on LIP Compliance

Lend Lease met with ICN to establish processes and procedures for management of the project's obligations to the LIP. It was decided that ICN will provide support on number of services covering:

- Implementation of the LIPP (capability searches on contestable packages)
- Presenting at briefing sessions
- Registering companies via ICN Gateway
- Verification of source of manufacture and service provision in subcontracts
- Business matching
- Progress reporting (Monthly) and final LNPP Outcomes reporting (at end of project)

3. Tier Barometer

Tier Barometer is an on-line self-assessment tool developed by ICN and the State Government. It provides participating companies with an assessment of their tier level in terms of supply to major projects. The tool is used by the project to analyse the basic capabilities of potential suppliers during the registration process.


4. Contestable Packages

Queensland and Australian capability, content and capacity will be considered for all the work packages. The following activities have been undertaken:

- An ICN officer has been assigned full time to the project.
- Detailed Business Matching has been carried out by ICN. 148 work packages have been managed in this way.
 These are listed at Attachment A.
- 1323 registrations against work packages on Gateway have been received
- 65 early works have been awarded in March. These are listed at Attachment B.
- 23 work packages have been awarded so far and they are listed at Attachment C.

Potential subcontractors will be given an indication of the size and generic nature of the project, and questioned regarding their capability and capacity to carry out the work, code compliance, and previous work history. Reports will be sent to Lend Lease detailing local companies which have the capability and capacity to carry out the work for each of the above packages. The primary objective of the Local Industry Policy is to ensure that competitive local companies are given full, fair and reasonable opportunity to tender for work packages. This objective will be achieved if the companies nominated by ICN, and other local companies that Lend Lease is aware of, are considered in the establishment of the tender list, and, subject to meeting pre-qualification criteria, a reasonable number of local companies are subsequently invited to tender. Lend Lease intends to apply this requirement.

6. Source of Supply



Lend Lease has advised that out of 86 Purchase Orders, 65 were awarded for early works and 23 for Work Packages listed on the ICN Gateway Project webpage. These were to companies that registered interest via ICN. As far as practicable, the measurement of industry participation focuses on the actual source of supply rather than the location through which the order is placed. The location in which services are provided, materials manufactured or where value adding takes place is indicative of the actual source of supply. Of the 23 Work Package contracts that have been awarded, 19 were won by South East Queensland (SEQ) companies, one by Regional Queensland and three by New South Wales companies.

7. Prototype Building

A prototype showcase building was erected in record time. This enabled focus group to provide input in to the final design in a cost effective manner.

8. Local Industry Participation

Lend Lease Project Director has personally provided project work scope and Lend Lease supplier engagement approach information to a number of larger Australian Manufacturers who have asked for more information. These include in the past month The GWA Group; The Laminex Group; Spence Doors and Rockcote Industries. For the latter company time was dedicated to a site inspection of their manufacturing facilities.

ICN supported Lend Lease in delivering briefing sessions as proposed in their LIP plan covering:

Monday 3rd September 2012 - Civil, Infrastructure, Structure & Landscaping

Monday 17th September 2012 - Services

Monday 24th September 2012 - Roof & Façade

Monday 8th October 2012 – Fit out & Finishes

Monday 15th October 2012 – Furniture Fittings & Equipment (FF&E)

Lend Lease also presented at the General Briefing Sessions along with ICN on 13, 14, 16 and 20th of August 2012.

Lend Lease project managers attended a briefing presentation by the members of the Cleantech Industries group of companies on 24th September 2012.

Lend Lease took part in a Local Business expo on 10th May 2013.

ICN – Evan Flower – presented to the Gympie Major Project Opportunities Forum on the project on 18th June 2013.

10. Efforts to engage with Local Companies include:

Press release by Health Minister, radio interviews by Project Director, Newspaper articles in CM and Sunshine Coast Daily followed up by substantial advertisements in the same newspapers on 19th January. Support articles followed from SSC Council and local councillors.

As a result of the above information sessions and the advertising campaign almost 1000 registrations have been received with close to 100 companies listing after the newspaper advertisements.

To date over 1323 companies have registered interest in work packages.

11. Source of Manufacture

As subcontracts begin to be awarded, the source of manufacture or service provision for contestable packages will be validated and verified in discussion with the corresponding subcontractors.

12. Reporting

Business matching reports on companies nominated for the trade packages listed at Attachment A are being provided to Lend Lease

Evan Flower
Capability Services Manager
ICN Queensland

Attachment A:	
Enquiries	
PR.0051.01 Crossover Road Construction	640.PR0056.02 - PRW - Site Office Cleaning
TP.0231.01 Preload	643.1.TP0410.01 - FMC - Concrete Supply
TP.0320.01 Sediment control	643.1.TP0420.01 - FMC - Concrete Place
PRO059 Site Security	643.1.TP0422.01 - FMC - Concrete Pumping
644.2.TP1732.01 - CP2 - Hydraulics	643.1.TP0431.01 - FMC - Precast Concrete
644.2.TP0620.01 - CP2 - Reinforcement Flxing	643.2.TP0410.01 - MHU - Concrete Supply
644.2.TP0530.01 - CP2 - Formwork	643.2.TP0420.01 - MHU - Concrete Placing
644.2.TP0422.01 - CP2 - Concrete Pumping	643.2.TP0422.01 - MHU - Concrete Pumping
644.2.TP0420.01 - CP2 - Concrete Placing	644.1.TP0410.01 - CP1 - Concrete Supply
644.2.TP0410.01 - CP2 - Concrete Supply	644.1.TP0420.01 - CP1 - Concrete Place
644.2.TP0060.01 - CP2 - Scaffolding	644.1.TP0422.01 - CP1 - Concrete Pumping
645.TP3230.01 - Kawana Way Dupiication	643.1.TP0060.01 - FMC - Scaffolding
641.TP.0230.01 - RIE - Bulk Earthworks and Fill	644.1.TPC060.01 - CP1 - Scaffolding
641.TP.3230.01 - RIE - Boaks & Infrastructure Services	642.TP.0830.01 - MHB - Blockwork
	643.1.TP0830.01 - FMC - Blockwork
544.2.TP2239.01 - CP2 - Carpark Control System	
40.PR0033.01 - PRW - Temporary Hydraulics	643.2.TP0830.01 - MHU - Blockwork
40.PR0056.01 - PRW - Rubbish Removal	644.1.TP0830.01 - CP1 - Blockwork
44.2.TP0832.01 - CP2 - Waterproofing	640.PR0054.01 - PRW - Site Photography
44.2.TP2330.01 - CP2 - Electrical	644.2.TP3030.01 - CP2 - Painting & Line Marking
40.PR0042.01 - PRW - Tower Cranes, Hoists & Crews	644.1.TP3030.01 - CP1 - Painting & Line Marking
544.2.TP0631.01 - CP2 - Post Tensioning	644.2.TP1030.01 - CP2 - Structural Steekwork
42.TP.2030.01 - MHB - Vertical Transportation	644.1.TP1030.02 - CP1 - Structural Steelwork
543.1.TP2030.01 - FMC - Vertical Transportation	642.TP.2230.01 - MHB - Building Maintenance Unit
543.2.TP2030.01 - MHU - Vertical Transportation	643.2.TP1631.01 - MHU -Roofing-Built-up / Miembrane
544.1.TP2030.C1 - CP1 - Vertical Transportation	642.TP,1630.01 - MHB - Roof & Metal Cladding
540.PR0041.01 - PRW - Mobile Cranes	642,TP,1636.01 - MHB - Wall Cladding Systems
544.2.TP1830.01 - CP2 - Mechanical	642. TP. 1032.01 - MHB - Facade Praming
544.2.TP1712.01 - CP2 - Water Tanks	642.TP.1132.01 MHB - Shop Fronts
540.PR0021.02 - PRW - Site Fencing	642.TP.1135.07 - MHB Synshades & Light Shelves
640.PR0046.01 - PRW - Temporary Plant & Equipment	642.TR:1131.01 - MHB - Metal Windows
640.PR0022.06 - PRW - Temporary Onsite Canteen and Catering Services	642/TP.1631.01 MHB Boofing-Built-up / Membrane
40.PR0022.05 - PRW - Temporary Carpentry Site Accommodation Areas	642.TP-1712.01 - MHB - Tanks & Pumps Supply
44,1,TP0530.01 - CP1 - Formwork	643.2.TP1/10.01 MHU - Sanitaryware & Tapware Supply
42.TP.0530.01 - MHB - Formwork	642-7P.1732.02 MHB) Sanitaryware & Tapware Supply
43.2.TP0530.01 - MHU - Formwork	642, TP-1231 01 - MN6 - Balustrades & Handrails
43.1.TP0530.01 - FMC - Formwork	642 TP /23001 MHB - Metalwork
	42. TP. 1235/01 MHB - Metal Louvres
643.1.TP2310.01 - FMC - Site Wide HV Equipment Supply Only 642.TP2335.02 - PRW - Uninterruptable Power Supply Units (UPS) & Maintenance	
	643.1.1P1630.01 - FMC - Roof Metal Sheeting
644.1.TP0330.02 - CP1 - Pile Cut-off	
	643.1.TP1636.01 - FMC - Facade Cladding
643.1.TP0330.02 - FMC - Pile Cut-off	643.1.TP1032.01 - FMC - Facade Framing
542.TP.0330.03 - MHB - Sheet Piling	642.TP.1030.01 - MHB - Structural Steelwork
542.TP.0330.02 - MHB - Pile Cut-off	643.1.TP1135.01 - FMC - Sunshades and Light Shelves
543.1.TP0330.03 - FMC - Sheet Piling	343.1.TP1810.02 - FMC - Mechanical Services - Chiller Supply
544.1.TP0620.01 - CP1 - Reinforcement Fix	643.1.TP1810.03 - FMC - Mechanical Services - Cooling Tower Supply
542.TP.0620.01 - MHB - Reinforcement Fix	643.1.TP1810.04 - FMC - Mechanical Services - AHU Supply
542.TP.0631.01 - MHB - Post Tensioning	643.1.TP1810.01 - FMC - Mechanical Services - Tanks
543.1,TP0620.01 - FMC - Reinforcement Fix	643.1.TP1231.01 - FMC - Balustrades & Handrails
543.1.TP0631.01 - FMC- Post Tensioning	643.1.TP1235.01 - FMC - Metal Louvres
543.2.TP0620.01 - MHU - Reinforcement F/x	643.1.TP1432.01 - FMC - Curtains & Blinds
544.1.TP0631.01 - CP1 - Post Tensioning	643.1.TP1230.01 - FMC - Metalwork
540.PR0052.01 - PRW - Safety Precautions (RPE)	643.1.TP1030.01 - FMC - Structural Steelwork
542.TP.0832.01 - MHB - Waterproofing inground	643.1.TP2236.01 - FMC - Kitchen / Laundry Equipment
42.TP.0832.02 - MHB - Waterproofing Roofs & Decks	642.TP.1637.01 - MHB - Coolrooms & Cleanrooms
642.TP.0832.03 - MHB - Temporary Waterproofing	643.1.TP1637.01 - FMC - Coolrooms & Cleanrooms
43.1.TP0832.01 - FMC - Waterproofing & Tanking	644.1.TP1630.01 - CP1 - Roofing
43.1.TP3832.01 - FMC - Waterproofing & Tanking - Roofs & Decks	643.2.TP1630.01 - MHU - Roofing & Metal Cladding
43.2.TP0832.01 - FMC - Waterproofing & Tacking - Roots & Decks	643.2.TP1636.01 - MHU - Wall Cladding Systems
	643.1.TP1131.01 - FMC - Metal Windows
544.1.TP0832.01 - CP1 - Waterproofing	644.1.TP1131.01 - FMC - Metal Windows 644.1.TP1131.01 - CP1 - Facade / Screens
542.TP2335.01 - PRW - Site Wide LV Equipment Supply	
341.TP0410.01 - RIE - Concrete Supply	643.2.TP1032.01 - MHU - Facade Framing
42.TP.0420.01 - MHB - Concrete Place & Finish	644.1.TP1235.01 - CP1 - Metal Louvres
P1.TP2335.01 - CP1/CP2 - Light Fitting Supply	643,2.TP1131.01 - MHU - Metal Windows
40.PR0033.03 - PRW - Temporary Hydraulics Site Wide Reticulation	644.2.TP0057.01 - CP2 - Final Clean
341.TP1732.01 - RIE - Water & Fire Mains reticulation	643.2.TP1135.01 - MHU - Sunshades & Light Shelves
542.TP.0422.01 - MHB - Concrete Pumping	643.2.TP1230.01 - MHU - Metalwork
43.1.TP2312.01 - FMC - HV Generator Supply	643.2.TP1235.01 - MHU - Metal Louvres
642.TP.0431.01 - MHB - Precast Concrete	643.1.TP2235.01 - FMC - Dock Levelers
544.2.TP0830.01 - CP2 - Blockwork	644.1.TP1230.03 - CP1 - General Metalwork
540. PR0032.02 - PRW - Main Site Office & Accommodation Temporary Electrica	643.2.TP3530.01 - MHU - Temporary Carpentry
540.PR0022.02 - PRW - Temporary Lunch Sheds / Abjutions / Containers / Other	
642.TP.0060.01 - MHB - Scaffolding	
542.TP.0060.01 - MHB - Scaffolding 544.2.TP1131.01 - CP2 - Facade / Screens	
542.TP.0060.01 - MHB - Scaffolding 544.2.TP1131.01 - CP2 - Facade / Screens 544.2.TP1330.01 - CP2 - General Carpentry	
542.TP.0060.01 - MHB - Scaffolding 544.2.TP1131.01 - CP2 - Facade / Screens 544.2.TP1330.01 - CP2 - General Carpentry 640.PR0022.07 - PRW - Pest Control	
642.TP.0060.01 - MHB - Scaffolding 644.2.TP1131.01 - CP2 - Facade / Screens 644.2.TP1330.01 - CP2 - General Carpentry 640.PR0022.07 - PRW - Pest Control 640.PR0023.03 - PRW - Temporary Site Signage	
640.PR0022.02 - PRW - Temporary Lunch Sheds / Abiutions / Containers / Other 642.TP.0060.01 - MHB - Scaffolding 644.2.TP1131.01 - CP2 - Facade / Screens 544.2.TP1330.01 - CP2 - General Carpentry 640.PR0022.07 - PRW - Pest Control 640.PR0023.03 - PRW - Temporary Site Signage 640.PR0033.02 - PRW - Main Site Office Accommodation Temporary Hydraulics 640.PR0032.04 - PRW - Site Office, Fitout & Fymiture	Lip Progress Report #9 Scub July 2013 (3)9 F

Attachment B				
Business Engagement		LIPP Categorisation	Source of Supply	
Subcontractor	Proceedit	SEQ. Seath East IND REQ - Regional QLD AUS - Reat of Australia IMP - Imported	C. Contestable L. Locat	PostGode
Builtsmart Modular Mining Pty Ltd	Modular Prototype Suite	AUS	С	2250
Shadforths Civil Pty Ltd	CP2 Early Works	REQ	L	4556
Wagstaff Piling QLD Pty Ltd	Test Piling	SEQ	L	4060_
EVS Group Australia Pty Ltd	Site Security	SEQ	L	4350
Nilsen QLD Pty Ltd	Temporary Electrical CP2 & Prototype	SEQ	C	4170
Calty Constructions	Protoype Marketing Rigging and Marketing Deck	SEQ	L	4556 2113
Blue Glue Pty Ltd	Blue Glue Temporary Hydrautics	AUS SEQ	L _	4567
Kyana Pty Ltd	Covered Walkways and paths	SEQ	L L	4556
Gordon Clements Nominees Pty Ltd T/A Calty Constructions	Site Probing Works - 55 Probe Locations	SEQ	L	4060
Wagstaff Piling Quality Choice Signs	Re skin to existing Biliboard	9EQ / /	C	4575
Fencepac	Site Perimeter Security Fence - Stage 1	SEC	C	4556
Fredon QLD Pty Limited	SCUH - Nambour Site	SEQ	С	4119
Shadforths	Crossover road Construction	SEC		4556
Underground Pipe and Cable Location Pty Ltd	Detect inground services prior to digging fence	SEC	C	4553
O2 Environmental Pty Ltd	Environmental and Sediment Monitoring	SEA	L	4573
Shadforths	Supply & replace Road Base - Site Accommodati		L	4556
Calty	Prototype Building Foundations	SEQ	L	4556
Scapeshape Pty Ltd	Palmtree re-location	SEQ	L	4211
D&J Services	Site Shed Cleaning	SEQ	L	4011
Floor cover QLD - AK	Installation of vinyl and carpet to the Prototype Se	SEQ SEQ	C	4675
Quality Choice Signs	Signage Supply and install shade cloth to SCUA Site	SEQ	C	4570
The trustee for The SJ & DY Eade Family Trust T/A Vismark	Supply and install snade cloth to SCOH Site	SEQ	C	4556
Regson Fabrication	Supply & Histali 2 Galle Closures Supply & Hire of Perimeter Fencing	SEQ	L	2760
Orange Hire Pty Ltd	Site Sewerage Tank Pump Out	SEQ	C	4064
Transpacific Industries Pty Ltd Universal Cranes Sunshine Coast Pty Ltd	Mobile Crane Hire	SEQ	L	4556
Siemens	Prototype Security	IMP	C	4006
Merlon (t/a Statewide Communications)	Prototype Nurse Call & PES	AUS	C	4113
Ken Wilson & Associates Pty Ltd T/a KWA Blinds	Prototype Curtain & IV Tracks	SEQ	С	4163
Coates Hire Operations Pty Ltd	Portable toilets	SEQ	L	4131
Energex Limited	Energex Detailed Design	SEQ	L	4558
ATF Sunshine Coast and Total Site Set Up	Supply & Install crowd control barriers	SEQ	С	4000
Evolution Trafic Control	Provide traffic Controller	SEQ	L	4558
Lucid Edge PTY LTD	Video conversions from AVI to MWV+ YouTube	AUS	С	4014
Worldwide Online Printing Market Street	Masterplay Poster	SEQ	L	4000
Lucid Edge PTY LTD	Vides Conversions from AVI to MWV +	AUS	C	2010
Combined Security Services	Security Guards	SEQ	L	4575
DLA Piper	Professional lees	AUS SEQ	L	4000
Greenbins	Containers sent from GCUH to SCUH	SEQ	<u>_</u>	4106
Metro Express	3x3 Combination light set & Trumpf Serv	: iMP	C	2067
Trumpf Med Australia Pty Ltd	Medical Peds and Patient Lifting System	IMP	c	6163
Arichuntleigh Arunta Plastics (QLD) Pty Ltd	Cultural Heritage Induction	SEQ		3134
G James	Supply and install of windows and external doors	SEQ	L	4556
ATF Services Pty Ltd	Temp Fencing	SEQ	L	4558
Robotic Automation Group	AGV Advisory Services	AUS	С	2127
Energy Crane Services Pty	Transport !terns to SCUH site	SEQ	L	4034
Energex Limited	Temporary Electrics supply South	SEQ	HE.	4006
Spence Door	Supply doors and frame	SEQ	L	4556
Coates Hire Operations Pty Ltd		SEQ	С	4131
Kyana Projects Pty Ltd	Supply of Bulk Potable and Non-Potable Water	SEQ		4567
Neverfail Springwater Limited	Supply of Potable Water to Site until Feb 13	SEQ	C	4127
Steve Ryan t/as Rix Ryan Photography P/L	Photograph Palm removal & monthly images Supply of Site Accompdation Cleaning Products	SEQ	i.	4215 4560
Dunckers Pty Ltd	Supply and Instal of office furniture for Prototype	SEQ SEQ	C	4561
Bizfurn Express	Re-Fill 2 x 10000L Water Tanks + 1 Additional Vi		L	4551
Suncoast Water Carriers	Supply of kitchen fridge and microwave	SEQ	c	4575
Harvey Norman Bizfurn Express	Supply and Install of office furniture for Prototype		c	4557
Amalgamated Pest Control	Redback Pest Control to SCUH Site Offices	SEQ	L	4561
Midmed	Supply and instal of examination couch	SEQ	C	4570
Quality Choice Signs Pty Ltd	Hard Hat Stickers	SEQ	С	4551
Viridian	Supply and deliver of Mirrors for Prototype Suite		С	4173
	Corporate Charges	SEQ	L	
Multimedia Technology	Multi Touch Interactive Whiteboard	SEQ	C _	4006
Response First Aid	Park First Aid Shed & First Aid Training on	SEQ	L	4556

Attachment C					
Business Engagement		LIPP Categorisatio	n Source of Supply	1	
Subcontractor	WorkPackage	SEQ - South East GLD . REQ - Regional QLD AUG - Bast of Australia	C-Contestade L - Local	PostOcce	Values of Goods and Services
Shamrock Civil	Bulk Civil Works Pre-Load	SEQ	L	4076	s.47(3)(b)
Shadforth Civil Engineering	Cut to Fill Civil Works	REQ	L	4556	
Wagstaff Pilling	Precast Piling & Shear Piling	SEQ	L	4060	
Beavis & Sartels Pty Ltd	Temp Hydraulics (Site Wide)	SEQ	C	4013	
Oneform	Install Formwork to CP2	SEQ	1 1	4173	
East Coast Concrete Contractors	Concrete Place and Finish to CP2	NSW	<u>L</u>	2485	
Delco Steel	Reinforcement Fix to CP2	NSW	С	4178	
Pro Concrete Pumping	Concrete Pumping to CP2	SEQ	L	4220	
FIP Electrical (Old) Pty Ltd	Electrical Installation to CP2	SEQ	С	4144	
VT Services	Tower Crane to CP2	SEQ	L	4074	
Tacoma Plumbing and Drainage	Hydraulics to CP2	SEQ	C	4573	
EVS GROUP AUSTRALIA PTY LTD	PR0059 Site Security	NSW	С	2077	o 47(2)(b)
UNISPAN AUSTRALIA PTY LTD	644.2.TP0060.01 - CP2 - Scaffolding	SEQ	C /	4207	s.47(3)(b)
Boral Construction Materials (QLD)	644.2.TP0410.01 - CP2 - Concrete Supply	SEQ	L /	1 4 059	
OTIS ELEVATOR COMPANY PTY LTD	642.TP.2030.01 - MHB - Vertical Transportation	SEQ	c	4101	
OTIS ELEVATOR COMPANY PTY LTD	643.1.TP2030.01 - FMC - Vertical Transportation	SEQ	C	4101	
OTIS ELEVATOR COMPANY PTY LTD	643.2.TP2030.01 - MHU - Vertical Transportation	SEQ		4101	
OTIS ELEVATOR COMPANY PTY LTD	644.1.TP2030.01 - CP1 - Vertical Transportation	SEQ	1/2/	4101	
Polyseal Waterproofing QLD Pty Ltd	644.2.TP0832.01 - CP2 - Waterproofing	SEQ	(6/	4207	
STRUCTURAL SYSTEMS (NORTHERN) PTY LTD	644.2.TP0631.01 - CP2 - Post Tensioning	SEQ	C	4207	
QLD Drink and Snack Machines	640.PR0022.08 - PRW - Vending Machines - CP2	SEQ		4559	┙
Regson Fabrications	641.TP1230.01 - CP2 - Façade	SEQ		4556	
Custom Shades Pty Ltd	641.TP1633.00 - CP2 - Shade Structure	SEQ /		4173	┙





A Division of QMI Solutions

Progress Report #10 for period to 31 August 2013 Prepared by Industry Capability Network (Queensland) Ltd

This report details the assistance provided during the above period by ICN (Qld) to Lend Lease in the delivery and implementation of the Local Industry Participation Plan (LIPP) for the Sunshine Coast University Hospital in accordance with the Local Industry Policy (LIP).

1. Liaison with the Project on LIP Issues

ICN met with Queensland Health (Sam Betros) in May 2011 to discuss the project, ICN services, and LIP procedures and issues. ICN assisted QH in the development of the LIPP for the project and provided an evaluation report to QH on project bidders' LIP plan submissions in March 2012.

2. Liaison with Lend Lease on LIP Compliance

Lend Lease met with ICN to establish processes and procedures for management of the project's obligations to the LIP. It was decided that ICN will provide support on number of services covering:

- Implementation of the LIPP (capability searches on contestable packages)
- Presenting at briefing sessions
- Registering companies via ICN Gateway
- Verification of source of manufacture and service provision in subcontracts
- Business matching
- Progress reporting (Monthly) and final LTRP Outcomes reporting (at end of project).

3. Tier Barometer

Tier Barometer is an on-line self-assessment tool developed by ICN and the State Government. It provides participating companies with an assessment of their tier level in terms of supply to major projects. The tool is used by the project to analyse the basic capabilities of potential suppliers during the registration process.

4. Contestable Packages

Queensland and Australian capability, content and capacity will be considered for all the work packages. The following activities have been undertaken:

- An ICN officer has been assigned full time to the project.
- Detailed Business Matching has been carried out by ICN. 163 work packages have been managed in this way. These are listed at Attachment A.
- 1360 registrations against work packages on Gateway have been received
- 65 early works have been awarded in March. These are listed at Attachment B.
- 25 work packages have been awarded so far and they are listed at Attachment C

Potential subcontractors will be given an indication of the size and generic nature of the project, and questioned regarding their capability and capacity to carry out the work, code compliance, and previous work history. Reports will be sent to Lend Lease detailing local companies which have the capability and capacity to carry out the work for each of the above packages. The primary objective of the Local Industry Policy is to ensure that competitive local companies are given full, fair and reasonable opportunity to tenger for work packages. This objective will be achieved if the companies nominated by ICN, and other local companies that Lend Lease is aware of, are considered in the establishment of the tender list, and, subject to meeting pre-qualification criteria, a reasonable number of local companies are subsequently invited to tender. Lend Lease intends to apply this requirement.

6. Source of Supply



Lend Lease has advised that out of 86 Purchase Orders, 65 were awarded for early works and 25 for Work Packages listed on the CN Gateway Project webpage. These were to companies that registered interest via ICN. As far as practicable, the measurement of industry participation focuses on the actual source of supply rather than the location through which the order is placed. The location in which services are provided, materials manufactured or where value adding takes place is indicative of the actual source of supply. Of the 25 Work Package contracts that have been awarded, 21 were won by South East Queensland (SEQ) companies, three by New South Wales companies and one by South Australia.

7. Prototype Building

A prototype showcase building was erected in record time. This enabled focus group to provide input in to the final design in a cost effective manner.

8. Local Industry Participation

Lend Lease Project Director has personally provided project work scope and Lend Lease supplier engagement approach information to a number of larger Australian Manufacturers who have asked for more information. These include The GWA Group; The Laminex Group; Spence Doors and Rockcote Industries. For the latter company time was dedicated to a site inspection of their manufacturing facilities.

ICN supported Lend Lease in delivering briefing sessions as proposed in their LIP plan covering:

Monday 3rd September 2012 - Civil, Infrastructure, Structure & Landscaping

Monday 17th September 2012 – Services

Monday 24th September 2012 - Roof & Façade

Monday 8th October 2012 - Fit out & Finishes

Monday 15th October 2012 - Furniture Fittings & Equipment (FF&E)

Lend Lease also presented at the General Briefing Sessions along with ICN on 13, 14,16 and 20th of August 2012.

Lend Lease project managers attended a briefing presentation by the members of the Cleantech Industries group of companies on 24th September 2012.

Lend Lease took part in a Local Business expo on 10th May 2013.

ICN – Evan Flower – presented to the Gympie Major Project Opportunities Forum on the project on 18th June 2013.

10. Efforts to engage with Local Companies include:

Press release by Health Minister, radio interviews by Project Director, Newspaper articles in CM and Sunshine Coast Daily followed up by substantial advertisements in the same newspapers on 19th January. Support articles followed from SSC Council and local councillors.

As a result of the above information sessions and the advertising campaign almost 1000 registrations have been received with close to 100 companies listing after the newspaper advertisements.

To date over 1360 companies have registered interest in work packages.

11. Source of Manufacture

As subcontracts begin to be awarded, the source of manufacture or service provision for contestable packages will be validated and verified in discussion with the corresponding subcontractors.

12. Reporting

Business matching reports on companies nominated for the trade packages listed at Attachment A are being provided to Lend Lease.

Evan Flower
Capability Services Manager
ICN Queensland

Attachment A:		<u> </u>
Enquiries		
PR.0051.01 Crassover Road Construction	640.PR0056.02 - PRW - Site Office Cleaning	643.1.TP2630.01 - FMC - Ceilings and Partitions
TP.0231.01 Prefoad		644.2.TP1311.01 - CP2 - Door and Frame Supply
		643.2.TP2930.01 - MHU - Internal Glazing
TP.0320.01 Sediment control	V-15/12/17 V-15/12	
PR0059 Site Security		643.2.TP3030.01 - MHU - Painting
644.2.TP1732.01 - CP2 - Hydraulics		643.1.TP3030.01 - FMC - Painting
644.2.TP0620.01 - CP2 - Reinforcement Flxing		643.2.TPZ630.01 - MHU- Ceilings and Partitions
644.2.TP0530.01 - CP2 - Formwork	643.2.TPO420.01 - MHU - Concrete Placing	644.1.TPZ630.01 - CP1 - Ceilings and Partitions
644.2.TP0422.01 - CP2 - Concrete Pumping	643.2.TP0422.01 - MHU - Concrete Pumping	
	644.1.TP0410.01 - CP1 - Concrete Supply	
644.2,TP0420.01 - CP2 - Concrete Placing		
644.2.TP0410.01 - CP2 - Concrete Supply	644.1.TP0420.01 - CP1 - Concrete Place	
644.2.TP0060.01 - CP2 - Scaffolding	644.1.TP0422.01 - CP1 - Concrete Pumping	
645.TP3230.01 - Kawana Way Duplication	643.1.TP0060.01 - FMC - Scaffolding	
641.TP.0230.01 - RIE - Bulk Earthworks and Fili	644.1.TP0060.01 - CP1 - Scaffolding	<u> </u>
641.TP.3230.01 - RIE - Roads & Infrastructure Services	642.TP.0830.01 - MHB - Blockwork	
644.2.TP2239.01 - CP2 - Carpark Control System	643.1.TP0830.01 + FMC - Blockwork	
640,PR0033.01 - PRW - Temporary Hydraulics	643.2.TP0830.01 - MHU - Blockwork	
	644.1.TP0830.01 - CP1 - Blockwork	
640.PR0056.01 - PRW - Rubbish Removal		/
644.2.TP0832.01 - CP2 - Waterproofing	640.PR0054.01 - PRW - Site Photography	/////
644.2.TP2330.01 - CP2 - Electrical	644.2.TP3030.01 - CP2 - Painting & Line Marking	
640.PR0042.01 - PRW - Tower Cranes, Hoists & Crews	644.1.TP3030.01 - CP1 - Painting & Line Marking	\ \ /
644.2.TP0631.01 - CP2 - Post Tensioning	644.2.TP1030.01 - CP2 - Structural Steelwork	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
642.TP.2030.01 - MHB - Vertical Transportation	644.1.TP1030.02 - CP1 - Structural Steelwork	
643.1.TP2030.01 - FMC - Vertical Transportation	642.TP.2230.01 - MHB - Building Maintenance Unit	
	643.2.TP1631.01 - MHU - Roofing-Bullt-up / Membrane	
643.2.TP2030.01 - MHU - Vertical Transportation		
644.1.TP2030.01 - CP1 - Vertical Transportation	642,TP,1630,01 - MHB - Roof & Metal Cladding	\cap
640.PR0041.01 - PRW - Mobile Cranes	642.TP.1636.01 - MHB - Wall Cladding Systems	<u> </u>
644.2.TP1830.01 - CP2 - Mechanical	642.TP.1032.01 - MHB - Facade Framing	~ /
644.2,TP1712.01 - CP2 - Water Tanks	642.TP.1132.01 - MHB - Shop Fronts	/
640.PR0021.02 - PRW - Site Fencing	642.TP.1135.02 - MHB - Sunshades & Light Shelves	
	642.TP.1131.01 - MHB - Metal Windows	
640.PR0046.01 - PRW - Temporary Plant & Equipment		7
640.PR0022.06 - PRW - Temporary Onsite Canteen and Catering Services	642.TP.1631.01 - MHB - Roofing-Built-up / Membrane	
640.PR0022.05 - PRW - Temporary Carpentry 5lte Accommodation Areas	642,TP.1712.01 - MHB - Tanks & Pumps Supply	· · · · · · · · · · · · · · · · · · ·
644.1.TP0530.01 - CP1 - Formwork	643,2.TP1710.01 - MHU - Sanitaryware & Tapware Supply	
642.TP.0530.01 - MHB - Formwork	642.TP.1732.02 - MHB - San(taryware & Tapware Supply	
643.2,TP0530.01 - MHU - Formwork	642.TP.1231.01 - MHB - Bajustrades & Handrails	
643.1,TP0530.01 - FMC - Formwork	642.TP.1230.01 - MHB - Metalwork	
643.1, TP2310.01 - FMC - Site Wide HV Equipment Supply Only	642.TP.1235.01 - MHB - Metal Louvrey	
	642.TP.1232.01 - MHB - Movement coints	
642.TP2335.02 - PRW - Uninterruptable Power Supply Units (UPS) & Maintenance		···
644.1.TP0330.02 - CP1 - Pile Cut-off	643,1,TP1630.01 - FMC - Roof Metal Sheeting	
643.2.TP0330.02 - MHU- Pile Cut-off	643.1.TP1636.01 - FMC - Facade Cladding	
643.1.TP0330.02 - FMC - Pile Cut-off	643.1.TP1032.01 - FMC - Facade Framing	
642.TP.0330.03 - MHB - Sheet Pillng	642.TP.1030.01 - MHB - Structural Steework	
642, TP.0330.02 - MHB - Pile Cut-off	643.1.TP1135.01 - FMC - Sunshapes and Light Shaves	
643,1,TP0330.03 - FMC - Sheet Piling	643.1.TP3810.02 - FMC - Mechanical Services Chille Supply	
Land a management of the same		
644.1.TP0620.01 - CP1 - Reinforcement Fix	643.1.TP3810:03 - FMC - Mechanical Services - Cooling Tower Supply	
642.TP.0620.01 - MHB - Reinforcement Flx	643.1.TP3810.03 - FMC - Mechanical Services - Gaoling Tower Supply 643.1.TP1810.04 - FMC - Mechanical Services - AHU Supply	
642.TP.0620.01 - MHB - Reinforcement Flx 642.TP.0631.01 - MHB - Post Tensioning	643.1.TF1810.03 - FMC - Methenical Services - Opoline Tower Supply 643.1.TF1810.04 - FMC - Methenical Services - AHU Supply 643.1.TF1810.04 - FMC - Methanical Services - Tanjs	
642.TP.0620.01 - MHB - Reinforcement Flx	643.1.TP1810.03 - FMC - Mechanical Services - Gooling Tower Supply 643.1.TP1810.04 - FMC - Mechanical Services - AHU Supply 643.1.TP1810.05 - FMC - Mechanical Services - Tanje 643.1.TP1294.01 - FMC - Bijustrades - Ljandrajile 643.1.TP1294.01 - FMC - Bijustrades - Ljandrajile	
642.TP.0620.01 - MHB - Reinforcement Fix 642.TP.0631.01 - MHB - Post Tensioning 643.1.TP0620.01 - FMC - Reinforcement Fix	643.1.TP1810.03 - FMC - Mechanical Services - Apoling Tower Supply 643.1.TP1810.04 - FMC - Mechanical Services - AHU Supply 643.1.TP1810.07 - FMC - Mechanical Services - Tanjo 643.1.TP1230.01 - EMC - Bajustrades & Handralle 643.1.TP1235.07 - FMC - Mechanical Services - Tanjo	
642.TP.0620.D1 - MHB - Reinforcement Fbx 642.TP.0631.D1 - MHB - Post Tensioning 643.1.TP0620.D1 - FMC - Reinforcement Fix 643.1.TP0630.D1 - FMC - Post Tensioning	643.1.TP1810.03 - FMC - Mechanical Services - Apoling Tower Supply 643.1.TP1810.04 - FMC - Mechanical Services - AHU Supply 643.1.TP1810.07 - FMC - Mechanical Services - Tanjo 643.1.TP1230.01 - EMC - Bajustrades & Handralle 643.1.TP1235.07 - FMC - Mechanical Services - Tanjo	
642.TP.0620.01 - MHB - Reinforcement Fbx 642.TP.0631.01 - MHB - Post Tensioning 643.1.TP0620.01 - FMC - Reinforcement Fix 643.1.TP0631.01 - FMC - Post Tensioning 643.2.TP0631.01 - FMC - Post Tensioning 643.2.TP0620.01 - MHU - Reinforcement Fix	643.1.TP1810.03 - FMC - Meethinical Services - Copoling Tower Supply 643.1.TP1810.04 - FMC - Meethinical Services - HU Supply 643.1.TP1810.07 - FMC - Meethinical Services - Tanjo 643.1.TP124.01 - EMC - Bajustrades & Handrall 643.1.TP124.01 - FMC - Meethinical Services - Copoling Tower Supply 643.1.TP124.32.01 - FMC - Cuberra & Binds	
642.TP.0620.01 - MHB - Reinforcement Fbx 642.TP.0631.01 - MHB - Post Tensioning 643.1.TP0631.01 - FMC - Reinforcement Fix 643.1.TP0631.01 - FMC - Post Tensioning 643.2.TP06320.01 - MHU - Reinforcement Fbx 644.1.TP0631.01 - CP1 - Post Tensioning	643.1.TP1810.03 - FMC - Meethinical Services - Gooling Tower Supply 643.1.TP1810.04 - FMC - Meethinical Services - AHU Supply 643.1.TP1810.04 - FMC - Mechanical Services - Table 643.1.TP1810.01 - FMC - Baustrades & Handralle 643.1.TP123.01 - FMC - Baustrades & Handralle 643.1.TP123.02 - FMC - Megal Louvres 643.1.TP1230.01 - FMC - Cutains & Blands 643.1.TP1230.01 - FMC - Metalwork	
642.TP.0620.01 - MHB - Reinforcement Fbx 642.TP.0631.01 - MHB - Post Tensioning 643.1.TP0630.01 - FMC - Reinforcement Fix 643.1.TP0631.01 - FMC - Post Tensioning 643.2.TP0620.01 - MHU - Reinforcement Fbx 644.1.TP0631.01 - CP1 - Post Tensioning 644.1.TP0631.01 - CP1 - Post Tensioning 644.1.TP0631.01 - CP1 - Post Tensioning 649.PR005.01 - PRW - Sefety Precautions (PPE)	643.1.TP1810.03 - FMC - Mechanical Services - Cooling Tower Supply 643.1.TP1810.04 - FMC - Mechanical Services - AH1 Supply 643.1.TP1810.04 - FMC - Mechanical Services - Tanjs 643.1.TP1210.01 - EMC - Bijustrades Bulandralle 643.1.TP1210.01 - EMC - Bijustrades Bulandralle 643.1.TP1235.01 - FMC - Metal Louwes 643.1.TP1235.01 - FMC - Cutama & Bilade 643.1.TP1235.01 - FMC - Metalwork 643.1.TP1235.03 - FMC - Structural Streetwork	
642.TP.0620.D1 - MHB - Reinforcement Fbx 642.TP.0631.D1 - MHB - Post Tensioning 643.1.TP0620.D1 - FMC - Reinforcement Fix 643.1.TP0620.D1 - FMC - Post Tensioning 643.2.TP0620.D1 - MHU - Reinforcement Fix 644.1.TP0633.D1 - CP1 - Post Tensioning 644.1.TP0633.D1 - CP1 - Post Tensioning 645.D1 - Post Tensioning 646.PR0052.D1 - PRW - Safety Precautions (PPE) 646.TP.0832.D1 - MHB - Waterproofing Inground	643.1.TP1810.03 - FMC - Mechanical Services - Copoling Tower Supply 643.1.TP1810.04 - FMC - Mechanical Services - AriU Supply 643.1.TP1810.07 - FMC - Mechanical Services - Tanjo 643.1.TP129.01 - EMC - Belustrades & Handrall 643.1.TP129.01 - EMC - Belustrades & Handrall 643.1.TP129.01 - FMC - Metall Louvres 643.1.TP129.01 - FMC - Metallwork 643.1.TP129.01 - FMC - Metallwork 643.1.TP123.01 - FMC - Structural Steelwork 643.1.TP223.01 - FMC - Kitchen / Laundry Equipment	
642.TP.0620.D1 - MHB - Reinforcement Flx 642.TP.0631.01 - MHB - Post Tensioning 643.1.TP06320.01 - FMC - Reinforcement Flx 643.1.TP0632.0.01 - FMC - Post Tensioning 643.2.TP0620.00 - MHU - Reinforcement Flx 644.1.TP0633.01 - CP1 - Post Tensioning 640.PR0052.01 - PRW - Safety Precautions (\$PE) 642.TP.0832.01 - MHB - Waterproofing Inground 642.TP.0832.02 - MHB - Waterproofing Roofs & Decks	643.1.TP1810.03 - FMC - Meethnical Services - Cooling Tower Supply 643.1.TP1810.04 - FMC - Meethnical Services - AHU Supply 643.1.TP1810.04 - FMC - Mechanical Services - Table 643.1.TP1810.07 - FMC - Balustrades & Handrall 643.1.TP123.01 - FMC - Balustrades & Handrall 643.1.TP1235.02 - FMC - Megal Louves 643.1.TP12350.01 - FMC - Cuterine & Blinds 643.1.TP12350.01 - FMC - Structural Steelwork	
642.TP.0620.D1 - MHB - Reinforcement Fbx 642.TP.0631.D1 - MHB - Post Tensioning 643.1.TP0620.D1 - FMC - Reinforcement Fix 643.1.TP0620.D1 - FMC - Post Tensioning 643.2.TP0620.D1 - MHU - Reinforcement Fix 644.1.TP0633.D1 - CP1 - Post Tensioning 644.1.TP0633.D1 - CP1 - Post Tensioning 645.D1 - Post Tensioning 646.PR0052.D1 - PRW - Safety Precautions (PPE) 646.TP.0832.D1 - MHB - Waterproofing Inground	643.1.TP1810.03 - FMC - Mechanical Services - Cooling Tower Supply 643.1.TP1810.04 - FMC - Mechanical Services - AH1 Supply 643.1.TP1810.05 - FMC - Mechanical Services - Tanjo 643.1.TP1810.05 - FMC - Mechanical Services - Tanjo 643.1.TP1820.01 - FMC - Mechanical Services - Tanjo 643.1.TP1820.01 - FMC - Mechanical Services - Tanjo 643.1.TP1820.01 - FMC - Cutains & Bilinds 643.1.TP1820.01 - FMC - Cutains & Bilinds 643.1.TP1820.01 - FMC - Structural Steelwork 643.1.TP1820.01 - FMC - Structural Steelwork 643.1.TP1830.01 - FMC - Mechanical Services 643.1.TP1837.01 - FMC - Cooling ms & Cleanrooms 643.1.TP1837.01 - FMC - Cooling ms & Cleanrooms	
642.TP.0620.01 - MHB - Reinforcement Fbx 642.TP.0631.01 - MHHB - Post Tensioning 643.1.TP0630.01 - FMC - Reinforcement Fix 643.1.TP0631.01 - FMC - Post Tensioning 643.2.TP0620.01 - MHU - Reinforcement Fix 643.1.TP0631.01 - CPL - Post Tensioning 644.1.TP0631.01 - CPL - Post Tensioning 640.PR0052.01 - PRW - Safety Precautions (PPE) 642.TP.0832.01 - MHB - Waterproofing Inground 642.TP.0832.03 - MHB - Waterproofing Roofs & Decks 642.TP.0832.03 - MHB - Waterproofing Roofs & Company Waterproofing	643.1.TP1810.03 - FMC - Meethnical Services - Cooling Tower Supply 643.1.TP1810.04 - FMC - Meethnical Services - AHU Supply 643.1.TP1810.04 - FMC - Mechanical Services - Table 643.1.TP1810.07 - FMC - Balustrades & Handrall 643.1.TP123.01 - FMC - Balustrades & Handrall 643.1.TP1235.02 - FMC - Megal Louves 643.1.TP12350.01 - FMC - Cuterine & Blinds 643.1.TP12350.01 - FMC - Structural Steelwork	
642.TP.0620.D1 - MHB - Reinforcement Fbx 642.TP.0631.D1 - MHB - Post Tensioning 643.1.TP0620.D1 - FMC - Reinforcement Fix 643.1.TP0620.D1 - FMC - Post Tensioning 643.2.TP0620.D1 - MHU - Reinforcement Fbx 644.1.TP0631.D1 - CP1 - Post Tensioning 644.1.TP0631.D1 - CP1 - Post Tensioning 644.TP.0832.D1 - MHB - Waterproofing Inground 642.TP.0832.D2 - MHB - Waterproofing Roofs & Decks 642.TP.0832.D3 - MHB - Temporary Waterproofing 643.1.TP0832.D1 - FMC - Waterproofing & Tanking 643.1.TP0832.D1 - FMC - Waterproofing & Tanking	643.1.TP1810.03 - FMC - Meethnical Services - Copoling Tower Supply 643.1.TP1810.04 - Mr.C. Mechanical Services - AriU Supply 643.1.TP1810.07 - FMC - Meethanical Services - Tanjo 643.1.TP129.01 - EMC - Balustrades - Handrall 643.1.TP129.01 - EMC - Balustrades - Handrall 643.1.TP129.01 - FMC - Metallouves 643.1.TP129.01 - FMC - Metallouves 643.1.TP129.01 - FMC - Structural Steelwork 643.1.TP1220.01 - FMC - Structural Steelwork 643.1.TP1220.01 - FMC - Structural Steelwork 643.1.TP1637.01 - FMB - Coolinoms & Cleanrooms 642.TP1637.01 - FMB - Coolinoms & Cleanrooms 644.1.TP1637.01 - FMB - Coolinoms & Cleanrooms 644.1.TP1630.01 - CP1 - Rhourg	
642.TP.0620.D1 - MHB - Reinforcement Flx 642.TP.0631.01 - MHB - Post Tensioning 643.1.TP0630.D1 - FMC - Reinforcement Flx 643.1.TP0630.D1 - FMC - Post Tensioning 643.2.TP0620.D1 - FMC - Post Tensioning 643.2.TP0620.D1 - MHU - Reinforcement Flx 644.1.TP0631.D1 - CP1 - Post Tensioning 640.PR0052.D1 - PRW - Safety Precautions (\$PE) 642.TP.0832.D1 - MHB - Waterproofing Inground 642.TP.0832.D2 - MHB - Waterproofing Roofs & Decks 642.TP.0832.D3 - MHB - Temporary Waterproofing 643.1.TP0832.D1 - FMC - Waterproofing & Tanking 643.1.TP0832.D1 - FMC - Waterproofing & Tanking - Roofs & Decks	643.1.TP1810.03 - FMC - Meethnical Services - Gooling Tower Supply 643.1.TP1810.04 - FMC - Meethnical Services - AHU Supply 643.1.TP1810.04 - FMC - Mechanical Services - AHU Supply 643.1.TP180.07 - FMC - Mechanical Services - Tanja 643.1.TP183.07 - FMG - Mechanical Services - Tanja 643.1.TP183.07 - FMG - Mechanical Services - Blads 643.1.TP183.07 - FMG - Mechanical Street 643.1.TP183.01 - FMG - Mechanical Street 643.1.TP183.01 - FMG - Structural Street 643.1.TP183.01 - FMG - Structural Street 643.1.TP183.01 - FMG - Mechanical Street 643.1.TP183.01 - FMG - Mechanical Street 643.1.TP183.01 - FMG - Cooling Street 643.1.TP183.01 - FMG - Mechanical Street 644.1.TP1630.01 - MHU - Roofing & Metal Cladding	
642.TP.0620.01 - MHB - Reinforcement Flx 642.TP.0631.01 - MHB - Post Tensioning 643.1.TP0632.0.01 - FMC - Reinforcement Fix 643.1.TP0630.01 - FMC - Post Tensioning 643.2.TP0620.01 - FMC - Post Tensioning 643.2.TP0620.01 - MHU - Reinforcement Fix 644.1.TP0631.01 - CPL - Post Tensioning 640.PR0052.01 - PRW - Safety Precautions (FPE) 642.TP.0832.01 - MHB - Waterproofing Inground 642.TP.0832.02 - MHB - Waterproofing Roofs & Decks 642.TP.0832.03 - MHB - Temporary Waterproofing 643.1.TP0832.01 - FMC - Waterproofing & Tanking 643.1.TP0832.01 - FMC - Waterproofing & Tanking 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.2.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.2.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.2.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks	643.1.TP1810.03 - FMC - Meethinical Services - Cooling Tower Supply 643.1.TP1810.04 - FMC - Meethinical Services - AHU Supply 643.1.TP1810.04 - FMC - Mechanical Services - AHU Supply 643.1.TP123.01 - FMC - Bajustrades - Standrall 643.1.TP123.02 - FMC - Meghal Louvres 643.1.TP123.03 - FMC - Cutarins & Bilade 643.1.TP123.04 - FMC - Cutarins & Bilade 643.1.TP123.00 - FMC - Cutarins & Bilade 643.1.TP123.00 - FMC - Structural Steelwork 643.1.TP123.00 - FMC - Structural Steelwork 643.1.TP123.00 - FMC - Structural Steelwork 643.1.TP163.00 - FMS - Cooling as Cleanrooms 643.1.TP163.00 - CP1 - Roundry Edulment 644.1.TP163.00 - CP1 - Roundry 645.1.TP163.00 - MHU - Roofing & Metal Cladding 643.2.TP1630.01 - MHU - Roofing & Metal Cladding 643.2.TP1630.01 - MHU - Roofing & Metal Cladding 643.2.TP1630.01 - MHU - Wall Cladding Systems	
642.TP.0620.01 - MHB - Reinforcement Fbx 642.TP.0631.01 - MHHB - Post Tensioning 643.1.TP0631.01 - FMC - Reinforcement Fix 643.1.TP0631.01 - FMC - Post Tensioning 643.2.TP0620.01 - FMC - Post Tensioning 643.2.TP0620.01 - MHU - Reinforcement Fbx 644.1.TP0631.01 - CP1 - Post Tensioning 644.1.TP0631.01 - CP1 - Post Tensioning 642.TP.0832.01 - MHB - Waterproofing Inground 642.TP.0832.02 - MHB - Waterproofing Rofs & Decks 642.TP.0832.03 - MHB - Temporary Waterproofing 643.1.TP0832.01 - FMC - Waterproofing & Tanking 643.1.TP0832.01 - FMC - Waterproofing & Tanking 643.1.TP0832.01 - MHU - Weterproofing 643.1.TP0832.01 - MHU - Waterproofing 643.1.TP0832.01 - MHU - Waterproofing 644.1.TP0832.01 - MHU - Waterproofing	643.1.TP1810.03 - FMC - Meetenrical Services - Cooling Tower Supply 643.1.TP1810.04 - FMC - Mechanical Services - AHU Supply 643.1.TP1810.07 - FMC - Mechanical Services - AHU Supply 643.1.TP123.07 - FMC - Baustraders - Handrall 643.1.TP123.07 - FMC - Baustraders - Handrall 643.1.TP123.00 - FMC - Metal Louvres 643.1.TP123.00 - FMC - Metalwork 643.1.TP123.00 - FMC - Structural Steelwork 643.1.TP123.00 - FMC - Structural Steelwork 643.1.TP123.00 - FMC - Structural Steelwork 643.1.TP123.01 - FMC - Metalwork 643.1.TP1637.01 - FMC - Mortalwork 644.1.TP1637.01 - FMC - Coolinoms & Cleanrooms 644.1.TP1630.01 - CP1 - Roufing 644.1.TP1630.01 - CP1 - Roufing 643.1.TP123.001 - MHU - Roofing & Metal Cladding 643.2.TP1313.01 - MHU - Wall Cladding Systems 643.1.TP1513.01 - FMC - Metal Windows	
642.TP.0620.D1 - MHB - Reinforcement Flx 642.TP.0631.01. * MHB - Post Tensioning 643.1.TP0630.01 - FMC - Reinforcement Flx 643.1.TP0630.01 - FMC - Post Tensioning 643.2.TP0620.01 - FMC - Post Tensioning 643.2.TP0620.01 - MHU - Reinforcement Flx 644.1.TP0631.01 - CP1 - Post Tensioning 640.PR0052.01 - PRW - Safety Precautions (\$PE) 642.TP.0832.01 - MHB - Waterproofing Inground 642.TP.0832.03 - MHB - Waterproofing Roofs & Decks 642.TP.0832.03 - MHB - Temporary Waterproofing 643.1.TP0832.01 - FMC - Waterproofing & Tanking 643.1.TP0832.01 - FMC - Waterproofing & Tanking 643.1.TP0832.01 - FMC - Waterproofing & Tanking 644.2.TP0832.01 - FMC - Waterproofing & Tanking 644.2.TP0832.01 - PMC - Waterproofing & Tanking - Roofs & Decks 642.TP.0832.01 - PMC - Waterproofing & Tanking - Roofs & Decks 643.2.TP0832.01 - PMC - Waterproofing & Tanking - Roofs & Decks 643.2.TP0832.01 - PMC - Waterproofing & Tanking - Roofs & Decks 644.2.TP0832.01 - PMC - Waterproofing	643.1.TP1810.03 - FMC - Meethnical Seyloos - Gooling Tower Supply 643.1.TP1810.04 - FMC - Meethnical Seylons - AHU Supply 643.1.TP1810.04 - FMC - Meethnical Services - AHU Supply 643.1.TP1810.07 - FMC - Meethnical Services - Tanjo 643.1.TP183.07 - FMG - Well Louves 643.1.TP183.07 - FMG - Well Louves 643.1.TP183.07 - FMG - Well Louves 643.1.TP183.01 - FMG - Cutering & Blads 643.1.TP183.01 - FMG - Structural Streetwork 643.1.TP183.01 - FMG - Soolrooms & Cleanrooms 643.1.TP1630.01 - FMG - Well - Meethnical Streetwork 643.1.TP1630.01 - MHU - Roofing & Metal Cladding 643.2.TP1630.01 - MHU - Wall Cladding Systems 643.1.TP183.01 - FMC - Metal Windows 644.1.TP183.01 - FMC - Metal Windows 644.1.TP183.01 - FMC - Metal Windows 644.TP183.00 - CP1 - Facade / Screens	
642.TP.0620.01 - MHB - Reinforcement Fbx 642.TP.0631.01 - MHHB - Post Tensioning 643.1.TP0631.01 - FMC - Reinforcement Fix 643.1.TP0631.01 - FMC - Post Tensioning 643.2.TP0620.01 - FMC - Post Tensioning 643.2.TP0620.01 - MHU - Reinforcement Fbx 644.1.TP0631.01 - CP1 - Post Tensioning 644.1.TP0631.01 - CP1 - Post Tensioning 642.TP.0832.01 - MHB - Waterproofing Inground 642.TP.0832.02 - MHB - Waterproofing Rofs & Decks 642.TP.0832.03 - MHB - Temporary Waterproofing 643.1.TP0832.01 - FMC - Waterproofing & Tanking 643.1.TP0832.01 - FMC - Waterproofing & Tanking 643.1.TP0832.01 - MHU - Weterproofing 643.1.TP0832.01 - MHU - Waterproofing 643.1.TP0832.01 - MHU - Waterproofing 644.1.TP0832.01 - MHU - Waterproofing	643.1.TP1810.03 - FMC - Meethinical Services - Cooling Tower Supply 643.1.TP1810.04 - FMC - Meethinical Services - AHU Supply 643.1.TP1810.04 - FMC - Meethinical Services - AHU Supply 643.1.TP1820.01 - FMC - Baustrades S. Handralle 643.1.TP123.01 - FMC - Baustrades S. Handralle 643.1.TP123.02 - FMC - Megal Louvres 643.1.TP123.03 - FMC - Cuterins & Blinds 643.1.TP123.04 - FMC - Metalwork 643.1.TP123.00 - FMC - Structural Streetwork 643.1.TP123.00 - FMC - Kitchen / Laundry Equipment 643.1.TP123.00 - FMC - Structural Streetwork 643.1.TP163.01 - FMS - Cooling ms & Cleanrooms 643.1.TP163.01 - FMS - Cooling ms & Cleanrooms 644.1.TP163.01 - MHB - Cooling ms & Cleanrooms 643.1.TP163.01 - MHB - Cooling S. Metal Cladding 643.2.TP163.01 - MHU - Wall Cladding Systems 643.1.TP133.01 - FMC - Metal Windows 644.1.TP133.01 - FMC - Metal Windows 644.1.TP133.01 - FMC - Metal Windows 644.1.TP133.01 - FM - Facade / Screens	
642.TP.0620.01 - MHB - Reinforcement Flx 642.TP.0631.01 - MHB - Post Tensioning 643.1.TP0630.01 - FMC - Reinforcement Flx 643.1.TP0630.01 - FMC - Post Tensioning 643.1.TP0630.01 - FMC - Post Tensioning 643.1.TP0630.01 - CPL - Post Tensioning 644.1.TP0631.01 - CPL - Post Tensioning 640.PR0052.01 - PRW - Safety Precautions (FPE) 642.TP.0832.01 - MHB - Waterproofing Inground 642.TP.0832.02 - MHB - Waterproofing Roofs & Decks 642.TP.0832.03 - MHB - Temporary Waterproofing 643.1.TP0832.01 - FMC - Waterproofing & Tanking 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 644.TP.01.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 645.2.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 646.TP04.01 - RIB - Concrete Supply	643.1.TP1810.03 - FMC - Meethnical Seyloos - Gooling Tower Supply 643.1.TP1810.04 - FMC - Meethnical Seylons - AHU Supply 643.1.TP1810.04 - FMC - Meethnical Services - AHU Supply 643.1.TP1810.07 - FMC - Meethnical Services - Tanjo 643.1.TP183.07 - FMG - Well Louves 643.1.TP183.07 - FMG - Well Louves 643.1.TP183.07 - FMG - Well Louves 643.1.TP183.01 - FMG - Cutering & Blads 643.1.TP183.01 - FMG - Structural Streetwork 643.1.TP183.01 - FMG - Soolrooms & Cleanrooms 643.1.TP1630.01 - FMG - Well - Meethnical Streetwork 643.1.TP1630.01 - MHU - Roofing & Metal Cladding 643.2.TP1630.01 - MHU - Wall Cladding Systems 643.1.TP183.01 - FMC - Metal Windows 644.1.TP183.01 - FMC - Metal Windows 644.1.TP183.01 - FMC - Metal Windows 644.TP183.00 - CP1 - Facade / Screens	
642.TP.0620.01 - MHB - Reinforcement Fbx 642.TP.0631.01 - MHHB - Post Tensioning 643.1.TP0631.01 - FMC - Reinforcement Fix 643.1.TP0630.01 - FMC - Reinforcement Fix 643.1.TP0631.01 - FMC - Post Tensioning 643.2.TP0620.01 - MHU - Reinforcement Fbx 644.1.TP0631.01 - CP1 - Post Tensioning 644.1.TP0631.01 - CP1 - Post Tensioning 642.TP.0832.01 - MHB - Waterproofing Inground 642.TP.0832.02 - MHB - Waterproofing Roots & Decks 642.TP.0832.03 - MHB - Waterproofing & Tanking 643.1.TP0832.01 - FMC - Waterproofing & Tanking 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.2.TP032.01 - MHB - Waterproofing 644.1.TP0832.01 - FMC - Waterproofing 644.1.TP0832.01 - PMV - Ste Wide LV Equipment Supply 644.1.TP0832.01 - RIE - Concrete Suply 642.TP.042.0.01 - MHB - Concrete Place & Finish	643.1.TP1810.03 - FMC - Meethinical Services - Cooling Tower Supply 643.1.TP1810.04 - FMC - Meethinical Services - AHU Supply 643.1.TP1810.04 - FMC - Meethinical Services - AHU Supply 643.1.TP1820.01 - FMC - Baustrades S. Handralle 643.1.TP123.01 - FMC - Baustrades S. Handralle 643.1.TP123.02 - FMC - Megal Louvres 643.1.TP123.03 - FMC - Cuterins & Blinds 643.1.TP123.04 - FMC - Metalwork 643.1.TP123.00 - FMC - Structural Streetwork 643.1.TP123.00 - FMC - Kitchen / Laundry Equipment 643.1.TP123.00 - FMC - Structural Streetwork 643.1.TP163.01 - FMS - Cooling ms & Cleanrooms 643.1.TP163.01 - FMS - Cooling ms & Cleanrooms 644.1.TP163.01 - MHB - Cooling ms & Cleanrooms 643.1.TP163.01 - MHB - Cooling S. Metal Cladding 643.2.TP163.01 - MHU - Wall Cladding Systems 643.1.TP133.01 - FMC - Metal Windows 644.1.TP133.01 - FMC - Metal Windows 644.1.TP133.01 - FMC - Metal Windows 644.1.TP133.01 - FM - Facade / Screens	
642.TP.0620.01 - MHB - Reinforcement Flx 642.TP.0631.01 - MHB - Post Tensioning 643.1.TP0631.01 - FMC - Reinforcement Flx 643.1.TP0631.01 - FMC - Post Tensioning 643.2.TP0620.01 - FMC - Reinforcement Flx 643.1.TP0631.01 - CP1 - Post Tensioning 640.TP063.01 - RMB - Water - Reinforcement Flx 640.TP063.01 - RMB - Water - Reinforcement Flx 642.TP.0832.01 - MHB - Water - Reinforcement Flx 642.TP.0832.03 - MHB - Water - Reinforcement Flx 643.1.TP0632.03 - MHB - Water - Reinforcement Flx 643.1.TP0632.03 - MHB - Temporary Water - Roofs & Decks 642.TP.0832.03 - MHB - Temporary Water - Roofs & Decks 643.1.TP0632.01 - FMC - Water - Water - Roofs & Decks 643.1.TP0632.01 - FMC - Water - Water - Roofs & Decks 643.1.TP0632.01 - RMB - Water - Water - Roofs & Decks 643.1.TP0632.01 - CP1 - Water - Water - Roofs & Decks 643.1.TP0632.01 - RMB - Soncrete Supply 644.1.TP0633.01 - RW - Site Wide LV Equipment Supply 642.TP.042.0.01 - MHB - Concrete Place & Finish CP1.TP233.5.01 - CP1/CP2 - Light Fitting Supply	643.1.TP1810.03 - FMC - Meetenical Services - Cooling Tower Supply 643.1.TP1810.04 - FMC - Mechanical Services - Arti Supply 643.1.TP1810.04 - FMC - Mechanical Services - Arti Supply 643.1.TP1810.07 - FMC - Mechanical Services - Tenide 643.1.TP183.01 - FMC - Cooling - Services - Bilade 643.1.TP183.01 - FMC - Metallucures 643.1.TP183.01 - FMC - Metallucure 643.1.TP183.01 - FMC - Structural Streetwork 643.1.TP183.01 - FMC - Structural Streetwork 643.1.TP183.01 - FMC - Structural Streetwork 643.1.TP183.01 - FMC - Metallucure 642.TP.1637.01 - MHB - Cooling - Se Cleanrooms 643.1.TP183.01 - FMC - Structural Streetwork 643.1.TP183.01 - FMC - Metallucure 643.1.TP183.01 - FMC - Metallucure 643.1.TP183.01 - FMC - Metall Windows 644.1.TP183.01 - FMC - Metal Windows 644.1.TP183.01 - FMC - Metal Windows 644.1.TP183.05 - CP1 - Facade / Screens 643.2.TP131.05 - CP1 - Facade / Screens 643.2.TP131.01 - MHU - Metal Lowres	
642.TP.0620.01 - MHB - Reinforcement Flx 642.TP.0631.01 - MHB - Post Tensioning 643.1.TP0630.01 - FMC - Reinforcement Flx 643.1.TP0630.01 - FMC - Post Tensioning 643.1.TP0630.01 - FMC - Post Tensioning 643.1.TP0630.01 - MHU - Reinforcement Flx 644.1.TP0631.01 - CP1 - Post Tensioning 640.PR0052.01 - PRW - Safety Precautions (FPE) 642.TP.0832.02 - MHB - Waterproofing Inground 642.TP.0832.02 - MHB - Waterproofing Roofs & Decks 642.TP.0832.03 - MHB - Temporary Waterproofing 643.1.TP0832.01 - FMC - Waterproofing & Tanking 644.1.TP0832.01 - FMC - Waterproofing 644.1.TP0832.01 - CP1 - Waterproofing 644.TP04335.01 - PRW - Site Wide LV Equipment Supply 642.TP0420.01 - MHB - Concrete Place & Finish CP1.TP0335.01 - CP1/CP2 - Light Fitting Supply 640.PR003.03 - PRW - Temporary Hydraulics Site Wide Reheulphion	643.1.TP1810.03 - FMC - Meethinical Seyricos - Cooling Tower Supply 643.1.TP1810.04 - FMC - Meethinical Services - AHU Supply 643.1.TP1810.04 - FMC - Meethinical Services - AHU Supply 643.1.TP1825.05 - FMC - Meethinical Services - Table 643.1.TP123.01 - EMC - Bajustrades & Handrall 643.1.TP1235.02 - FMC - Megal Louves 643.1.TP1235.01 - FMC - Cuteins & Blinds 643.1.TP1235.01 - FMC - Structural Steelwork 643.1.TP1630.01 - CP1 - Roughg 644.TP1630.01 - CP1 - Roughg 645.2.TP1630.01 - MHU - Worling & Metal Cladding 646.1.TP135.01 - FMC - Metal Windows 646.1.TP135.01 - FMC - Metal Windows 648.2.TP1635.01 - CP1 - Metal Louves 643.2.TP135.01 - CP1 - Tacade / Screens 643.2.TP135.01 - FMC - Metal Windows 643.2.TP135.01 - FML - Facade Framing 644.1.TP135.01 - FMC - Metal Louves 643.2.TP1310.1 - MHU - Metal Louves 643.2.TP1310.1 - MHU - Metal Louves 643.2.TP1310.1 - MHU - Metal Windows 643.2.TP0350.01 - CP2 - Final Clean	
642.TP.0620.01 - MHB - Reinforcement Fbt 642.TP.0631.01 - MHB - Post Tensioning 643.1.TP0631.01 - FMC - Reinforcement Fix 643.1.TP0631.01 - FMC - Reinforcement Fix 643.1.TP0631.01 - FMC - Post Tensioning 643.2.TP0620.02 - MHU - Reinforcement Fbt 644.1.TP0631.01 - CP1 - Post Tensioning 644.1.TP0631.01 - CP1 - Post Tensioning 642.TP.0832.01 - MHB - Waterproofing Inground 642.TP.0832.01 - MHB - Waterproofing Roofs & Decks 642.TP.0832.02 - MHB - Waterproofing Roofs & Decks 642.TP.0832.03 - MHB - Temporary Waterproofing 643.1.TP0832.01 - FMC - Waterproofing & Tanking 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.1.TP0832.01 - MHB - Waterproofing & Tanking - Roofs & Decks 643.2.TP0832.01 - MHB - Waterproofing & Tanking - Roofs & Decks 643.1.TP0832.01 - MHB - Waterproofing & Tanking - Roofs & Decks 642.TP0832.01 - MHB - Waterproofing & Tanking - Roofs & Decks 642.TP0832.01 - RE - Waterproofing & Tanking - Roofs & Decks 642.TP0330.01 - RE - Concrete Supply 642.TP.0420.01 - MHB - Concrete Place & Finish CP1.TP2335.01 - CP1-CP2 - Light Fitting Supply 640.PR0033.03 - PRW - Temporary Hydraulics Site Wide Rehculskion 641.TP173.2.01 - RE - Water & Fire Mains reticulation	643.1.TP1810.03 - FMC - Meethanical Seyrics - Cooling Tower Supply 643.1.TP1810.04 - FMC - Mechanical Services - Art U Supply 643.1.TP1810.04 - FMC - Mechanical Services - Art U Supply 643.1.TP1820.01 - EMC - Baustraders - Handrall 643.1.TP1820.01 - FMC - Melal Louvres 643.1.TP1830.01 - FMC - Melal Louvres 643.1.TP1830.01 - FMC - Metalwork 643.1.TP1830.01 - FMC - Structural Steelwork 643.1.TP1830.01 - FMC - Structural Steelwork 643.1.TP1830.01 - FMC - Structural Steelwork 643.1.TP1830.01 - FMC - Metalwork 644.1.TP1630.01 - CP1 - Roufing 643.1.TP183.01 - FMC - Metal Windows 644.1.TP183.01 - FMC - Metal Windows 644.1.TP183.01 - FMC - Metal Windows 643.2.TP183.01 - FMC - Metal Louvres 643.2.TP133.01 - MHU - Facade Framing 644.1.TP1830.01 - CP1 - Metal Louvres 643.2.TP133.01 - MHU - Metal Windows 643.2.TP133.01 - MHU - Metal Windows 643.2.TP133.01 - MHU - Sunshades & Light Shelves	
642.TP.0620.01 - MHB - Reinforcement Flx 642.TP.0631.01. * MHB - Post Tensioning 643.1.TP0630.01 - FMC - Reinforcement Flx 643.1.TP0630.01 - FMC - Post Tensioning 643.2.TP0620.01 - FMC - Reinforcement Flx 643.1.TP0631.01 - CP1 - Post Tensioning 643.2.TP0620.01 - MHU - Reinforcement Flx 644.1.TP0631.01 - CP1 - Post Tensioning 640.PR0052.01 - RMB - Waterproofing Reinforcement Flx 642.TP.0832.02 - MHB - Waterproofing Inground 642.TP.0832.03 - MHB - Waterproofing Roofs & Decks 642.TP.0832.03 - MHB - Temporary Waterproofing 643.1.TP0632.03 - MHB - Waterproofing & Tanking 643.1.TP0632.01 - FMC - Waterproofing & Tanking 643.1.TP0632.01 - FMC - Waterproofing & Tanking 644.2.TP0632.01 - PMW - Stew Modern Supply 644.1.TP0632.01 - CP1 - Waterproofing 644.2.TP0632.01 - MHB - Concrete Supply 642.TP.040.01 - RIE - Concrete Supply 640.PR0033.03 - PRW - Temporary Hydraulics Site Wide Reinculation 641.TP1732.01 - RIE - Water & Fire Mains reticulation 641.TP1732.01 - RIE - Water & Fire Mains reticulation	643.1.TP1810.03 - FMC - Meetenical Services - Cooling Tower Supply 643.1.TP1810.04 - FMC - Meetenical Services - AHU Supply 643.1.TP1810.04 - FMC - Meetenical Services - AHU Supply 643.1.TP1810.07 - FMC - Meetenical Services - Tenide 643.1.TP183.07 - FMC - Meetenical Services - Tenide 643.1.TP183.07 - FMG - Meetenical Services - Blads 643.1.TP183.07 - FMC - Meetenical Steelwork 643.1.TP183.01 - FMC - Cooling - Services - Blads 643.1.TP183.01 - FMC - Meetenical Steelwork 643.1.TP183.01 - FMC - Meetenical Steelwork 643.1.TP183.01 - FMC - Meetenical Steelwork 643.1.TP183.01 - FMC - Meetenical Services - Meetenic	
642.TP.0620.01 - MHB - Reinforcement Flx 643.TP.0631.01 - MHB - Post Tensioning 643.1.TP0630.01 - FMC - Reinforcement Flx 643.1.TP0630.01 - FMC - Reinforcement Flx 643.1.TP0630.01 - FMC - Post Tensioning 643.1.TP0630.01 - MHU - Reinforcement Flx 644.1.TP0631.01 - CP1 - Post Tensioning 640.PR0052.01 - PRW - Safety Precautions (FPE) 642.TP.0832.02 - MHB - Waterproofing Inground 642.TP.0832.02 - MHB - Waterproofing Roofs & Decks 642.TP.0832.03 - MHB - Temporary Waterproofing 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 642.TP0833.01 - PRW - Temporary Hydraulics Site Wide Reficulation 642.TP0422.01 - MHB - Concrete Pumping 643.1.TP3321.01 - RMC - Water & Fire Malns reticulation 643.1.TP03321.01 - FMC - Water & Fire Malns reticulation 643.1.TP03321.01 - FMC - Water & Fire Malns reticulation 643.1.TP03321.01 - FMC - HW Generator Supply	643.1.TP1810.03 - FMC - Meethinical Services - Cooling Tower Supply 643.1.TP1810.04 - FMC - Meethinical Services - AHU Supply 643.1.TP1810.04 - FMC - Meethinical Services - AHU Supply 643.1.TP183.00 - FMC - Meethinical Services - Table 643.1.TP123.01 - EMC - Balustrades & Handrall 643.1.TP123.01 - FMC - Meghal Louwes 643.1.TP123.01 - FMC - Metalwork 643.1.TP123.01 - FMC - Metalwork 643.1.TP123.01 - FMC - Metalwork 643.1.TP123.01 - FMC - Structural Steelwork 643.1.TP123.01 - FMC - Structural Steelwork 643.1.TP123.01 - FMC - Structural Steelwork 643.1.TP163.01 - FMC - Structural Steelwork 643.1.TP163.01 - FMC - Cooling as Cleanrooms 644.1.TP163.01 - FMC - Cooling as Metal Cladding 643.1.TP163.01 - FMC - Metal Windows 644.1.TP13.01 - FMC - Metal Windows 644.1.TP13.01 - FMC - Metal Windows 643.2.TP163.01 - CP1 - Facade / Screens 643.2.TP163.01 - MHU - Facade Framing 644.1.TP123.56 - CP1 - Metal Louwes 643.2.TP10.10 - MHU - Wetal Windows 644.2.TP10.10 - MHU - Wetal Windows 644.2.TP10.10 - MHU - Wetal Windows 643.2.TP123.01 - MHU - Sunshades & Light Shelves 843.2.TP123.01 - MHU - Metal Windows 644.2.TP123.01 - MHU - Metal Windows 644.2.TP123.01 - MHU - Sunshades & Light Shelves 843.2.TP123.01 - MHU - Metal Louwes 643.2.TP123.01 - MHU - Metal Windows 643.2.TP123.01 - MHU - Metal Windows	
642.TP.0620.01 - MHB - Reinforcement Flx 642.TP.0631.01. * MHB - Post Tensioning 643.1.TP0630.01 - FMC - Reinforcement Flx 643.1.TP0630.01 - FMC - Post Tensioning 643.2.TP0620.01 - FMC - Reinforcement Flx 643.1.TP0631.01 - CP1 - Post Tensioning 643.2.TP0620.01 - MHU - Reinforcement Flx 644.1.TP0631.01 - CP1 - Post Tensioning 640.PR0052.01 - RMB - Waterproofing Reinforcement Flx 642.TP.0832.02 - MHB - Waterproofing Inground 642.TP.0832.03 - MHB - Waterproofing Roofs & Decks 642.TP.0832.03 - MHB - Temporary Waterproofing 643.1.TP0632.03 - MHB - Waterproofing & Tanking 643.1.TP0632.01 - FMC - Waterproofing & Tanking 643.1.TP0632.01 - FMC - Waterproofing & Tanking 644.2.TP0632.01 - PMW - Stew Modern Supply 644.1.TP0632.01 - CP1 - Waterproofing 644.2.TP0632.01 - MHB - Concrete Supply 642.TP.040.01 - RIE - Concrete Supply 640.PR0033.03 - PRW - Temporary Hydraulics Site Wide Reinculation 641.TP1732.01 - RIE - Water & Fire Mains reticulation 641.TP1732.01 - RIE - Water & Fire Mains reticulation	643.1.TP1810.03 - FMC - Meetenical Services - Cooling Tower Supply 643.1.TP1810.04 - FMC - Meetenical Services - AHU Supply 643.1.TP1810.04 - FMC - Meetenical Services - AHU Supply 643.1.TP1810.07 - FMC - Meetenical Services - Tenide 643.1.TP183.07 - FMC - Meetenical Services - Tenide 643.1.TP183.07 - FMG - Meetenical Services - Blads 643.1.TP183.07 - FMC - Meetenical Steelwork 643.1.TP183.01 - FMC - Structural Steelwork 643.1.TP183.01 - FMC - Meetenical Services - Steel Services -	
642.TP.0620.01 - MHB - Reinforcement Flx 642.TP.0631.01 - MHB - Post Tensioning 643.1.TP0631.01 - FMC - Reinforcement Flx 643.1.TP0630.01 - FMC - Reinforcement Flx 643.1.TP0630.01 - FMC - Post Tensioning 643.1.TP0631.01 - CP1 - Post Tensioning 644.1.TP0631.01 - CP1 - Post Tensioning 644.1.TP0631.01 - CP1 - Post Tensioning 640.PR0052.01 - PRW - Safety Pracautions (PPE) 642.TP.0832.02 - MHB - Waterproofing Inground 642.TP.0832.03 - MHB - Waterproofing Roofs & Decks 642.TP.0832.03 - MHB - Waterproofing & Tanking 643.1.TP0332.01 - FMC - Waterproofing & Tanking 643.1.TP0332.01 - FMC - Waterproofing & Tanking 643.1.TP0332.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.1.TP0332.01 - PRW - Ste Wide LV Equipment Supply 644.1.TP0332.01 - RE - Concrete Supply 642.TP.042.01 - RIB - Concrete Place & Finish CP1.TP2335.01 - CP2-CP2 - Light Fitting Supply 642.TP.0430.01 - RIB - Concrete Place & Finish CP1.TP2335.01 - REI - Water & Fire Mains reticulation 642.TP.0432.01 - MHB - Concrete Pumping 643.1.TP3312.01 - RIE - Water & Fire Mains reticulation 642.TP.0432.01 - MHB - Goncrete Pumping 643.1.TP3312.01 - FMC - Water & Fire Mains reticulation 642.TP.0432.01 - MHB - Goncrete Pumping 643.1.TP3312.01 - FMC - Water & Fire Mains reticulation 642.TP.0431.01 - MHB - Precast Concrete	643.1.TP1810.03 - FMC - Meethanical Seyvics - Cooling Tower Supply 643.1.TP1810.04 - FMC - Mechanical Services - Art U Supply 643.1.TP1810.04 - FMC - Mechanical Services - Art U Supply 643.1.TP1820.01 - EMC - Baustraders - Handrall 643.1.TP123.01 - FMC - Baustraders - Handrall 643.1.TP123.01 - FMC - Metal Louvres 643.1.TP123.01 - FMC - Metalwork 643.1.TP123.01 - FMC - Metalwork 643.1.TP123.01 - FMC - Suctional Steelwork 643.1.TP123.01 - FMC - Suctional Steelwork 643.1.TP123.01 - FMC - Metalwork 643.1.TP183.01 - FMC - Metalwork 644.1.TP163.01 - FMC - Metalwork 644.1.TP163.01 - MHU - Wall Cladding Systems 643.2.TP1131.01 - FMC - Metal Windows 644.1.TP123.03 - FMC - Metal Windows 644.1.TP123.04 - FMC - Metal Windows 643.2.TP1131.01 - MHU - Facader Framing 644.1.TP123.01 - CP1 - Metal Louvres 643.2.TP1131.01 - MHU - Metal Windows 643.2.TP1131.01 - MHU - Metal Windows 643.2.TP1131.01 - MHU - Metal Windows 643.2.TP1315.01 - MHU - Sunshades & Light Shelves 643.2.TP1315.01 - MHU - Metal Louvres 643.2.TP1235.01 - MHU - Weltal Windows 643.2.TP1235.01 - MHU - Metal Worker	
642.TP.0620.D1 - MHB - Reinforcement Fix 643.TP0631.01 - MHB - Post Tensioning 643.1.TP0631.01 - FMC - Reinforcement Fix 643.1.TP0631.01 - FMC - Post Tensioning 643.1.TP0631.01 - FMC - Post Tensioning 643.1.TP0631.01 - CP1 - Post Tensioning 643.1.TP0632.01 - MHU - Reinforcement Fix 644.1.TP0631.01 - CP1 - Post Tensioning 640.PR0052.01 - PRW - Safety Precautions (PPE) 642.TP.0832.01 - MHB - Waterproofing Inground 642.TP.0832.03 - MHB - Waterproofing Roofs & Decks 642.TP.0832.03 - MHB - Temporary Waterproofing 643.1.TP0832.01 - FMC - Waterproofing & Tanking 643.1.TP0832.01 - FMC - Waterproofing & Tanking 643.1.TP0832.01 - FMC - Waterproofing 643.1.TP0832.01 - FMC - Waterproofing 644.1.TP0832.01 - FMC - Waterproofing 644.1.TP0832.01 - CP1 - Waterproofing 644.1.TP0832.01 - CP2 - Waterproofing 644.1.TP0832.01 - CP2 - Waterproofing 644.1.TP0832.01 - CP2 - Waterproofing 644.1.TP0832.01 - RMC - Wide LV Equipment Supply 642.TP.0420.01 - MHB - Concrete Pumping 644.1.TP1732.01 - RIE - Water & Fire Mains reticulation 641.TP1732.01 - RIE - Water & Fire Mains reticulation 641.TP1732.01 - MHB - Concrete Pumping 643.1.TP3312.01 - FMC - HV Generator Supply 644.1.TP0830.01 - CP2 - Blockwork	643.1.TP1810.03 - FMC - Meethnical Seylos- Cooling Tower Supply 643.1.TP1810.04 - FMC - Meethnical Seylos- Alti Supply 643.1.TP1810.04 - FMC - Meethnical Services - Alti Supply 643.1.TP1810.04 - FMC - Meethnical Services - Tanje 643.1.TP183.01 - FMC - Meethnical Services - Tanje 643.1.TP183.01 - FMC - Mehal Louwes 643.1.TP183.01 - FMC - Metalwork 643.1.TP183.01 - FMC - Metalwork 643.1.TP183.01 - FMC - Structural Streetwork 643.1.TP183.01 - FMC - Structural Streetwork 643.1.TP183.01 - FMC - Metalwork 644.1.TP183.01 - FMC - Metal Windows 643.1.TP1813.01 - FMC - Metal Windows 643.1.TP1813.01 - FMC - Metal Lowres 643.2.TP1813.01 - MHU - Metal Lowres 643.2.TP123.00 - MHU - Metal Lowres 643.2.TP123.00 - MHU - Metal Lowres 643.1.TP123.00 - MHU - Metal Lowres 643.1.TP123.01 - FMC - General Metalwork	
642.TP.0620.01 - MHB - Reinforcement Flx 642.TP.0631.01 - MHB - Post Tensioning 643.1.TP0631.01 - FMC - Reinforcement Flx 643.1.TP0630.01 - FMC - Reinforcement Flx 643.1.TP0631.01 - FMC - Post Tensioning 643.1.TP0631.01 - CP1 - Post Tensioning 643.1.TP0632.01 - MHB - Reinforcement Flx 643.1.TP0632.01 - MHB - Waterproofing Inground 642.TP.0832.01 - MHB - Waterproofing Roofs & Decks 642.TP.0832.02 - MHB - Waterproofing Roofs & Decks 642.TP.0832.03 - MHB - Waterproofing & Tanking 643.1.TP0832.01 - FMC - Waterproofing 643.1.TP0832.01 - FMC - Waterproofing 644.1.TP0832.01 - FMC - Waterproofing 642.TP04335.01 - PRW - Site Wide LV Equipment Supply 642.TP0430.01 - MHB - Concrete Place & Finish CP1.TP0335.01 - CP1/CP2 - Light Fitting Supply 642.TP0430.01 - MHB - Concrete Place & Wide Reinculation 642.TP042.01 - MHB - Concrete Pumpling 643.1.TP3312.01 - RIC - Water & Fire Mains reticulation 642.TP042.01 - MHB - Concrete Pumpling 643.1.TP3312.01 - FMC - HV Generator Supply 642.TP0431.01 - MHB - Precast Concrete 644.2.TP0830.01 - CP2 - Blockwork	643.171810.03 - FMC - Mechanical Seylos - Gooling Tower Supply 643.171810.04 - FMC - Mechanical Seylos - HU Supply 643.171810.07 - FMC - Mechanical Seylos - HU Supply 643.171810.07 - FMC - Mechanical Seylos - HU Supply 643.1719.35.07 - FMC - Bolustrades - Handrall 643.1719.35.01 - FMC - Metall Louvres 643.1719.35.01 - FMC - Metallwork 643.1719.35.01 - FMC - Metallwork 643.1719.35.01 - FMC - Structural Steelwork 643.1719.35.01 - FMC - Goolnoms & Cleanrooms 644.171630.01 - FMC - Goolnoms & Cleanrooms 643.2719.35.01 - FMC - Metal Windows 644.1713.10 - CP1 - Roufing & Metal Cladding 643.2719.30.01 - MHU - Roufing & Metal Cladding 644.17113.10 - CP1 - FMC - Metal Windows 644.17113.10 - CP1 - FMC - Metal Windows 644.17113.10 - CM1 - FMC - Metal Windows 643.2719.30.01 - MHU - Metal Windows 643.2719.30.01 - MHU - Metal Windows 643.2719.30.01 - CP2 - Inal Clean 643.2719.30.01 - CP3 - Gooling Clean 643.2719.30.01 - CP3 - Gooling Clean 643.2719.30.01 - MHU - Metal Windows 643.2719.30.01 - CP3 - Gooling Clean 643.2719.30.01 - CP3 - Gooling Clean 643.2719.30.01 - MHU - Metal Windows 643.2719.30.01 - MHU - Wetal Windows 643.2719.30.01 - MHU - Wetal Windows	
642.TP.0620.01 - MHB - Reinforcement Flx 642.TP.0631.01 - MHB - Post Tensioning 643.1.TP0630.01 - FMC - Reinforcement Flx 643.1.TP0630.01 - FMC - Post Tensioning 643.2.TP0620.01 - FMC - Post Tensioning 643.2.TP0620.01 - MHU - Reinforcement Flx 644.1.TP0631.01 - CP1 - Post Tensioning 640.PR0052.01 - PRW - Safety Procautions (\$PE) 642.TP.0832.03 - MHB - Waterproofing Inground 642.TP.0832.03 - MHB - Waterproofing Roofs & Decks 642.TP.0832.03 - MHB - Waterproofing & Tanking 643.1.TP0832.01 - FMC - Waterproofing & Tanking 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.1.TP0832.01 - FMC - Waterproofing 643.1.TP0832.01 - FMC - Waterproofing 644.1.TP0832.01 - CP1 - Waterproofing 644.2.TP.042.01 - CP1 - Waterproofing 642.TP.040.01 - RIE - Concrete Place & Finish CP1.TP2335.01 - PRW - Site Wide LV Equipment Supply 640.PR0033.03 - PRW - Temporary Hydraulics Site Wide Rehculation 642.TP.042.01 - MHB - Concrete Place & Finish CP1.TP2335.01 - RIE - Water & Fire Mains reticulation 642.TP.042.01 - MHB - Concrete Pumping 643.TP.042.01 - MHB - Concrete Pumping 643.TP.781.01 - FMC - HV Generator Supply 642.TP.042.01 - MHB - Concrete Pumping 643.TP.042.01 - MHB - Concrete Pumping 643.TP.042.01 - MHB - Concrete Pumping 644.TP.042.01 - MHB - Concrete Pumping 645.TP.042.01 - MHB - Concrete Pumping 646.TP.042.01 - MHB - Concrete Pumping 647.TP.042.01 - MHB - Concrete Pumping 648.TP.042.01 - MHB - Concrete Pumping 649.TP.042.01 - MHB - Concrete Pumping 640.PR0032.02 - PRW - Main Site Office & Commodation Temporary Electrical 640.PR0032.02 - PRW - Main Site Office & Commodation Temporary Electrical	643.1.TF1810.03 - FMC - Meethanical Seyrics - Cooling Tower Supply 643.1.TF1810.04 - FMC - Mechanical Seyrics - Art U Supply 643.1.TF1810.04 - FMC - Mechanical Seyrics - Art U Supply 643.1.TF1820.01 - EMC - Balustraders - Handrall 643.1.TF123.01 - FMC - Dalustraders - Handrall 643.1.TF123.01 - FMC - Metal Louvres 643.1.TF123.01 - FMC - Metalwork 644.1.TF163.01 - CF1 - Rourge 644.1.TF163.01 - MHU - Wall Cladding Systems 643.1.TF131.01 - FMC - Metal Windows 644.1.TF123.03 - FMC - Metal Windows 644.1.TF123.04 - FMC - Metal Windows 644.1.TF131.01 - FMC - Metal Windows 643.2.TF1131.01 - MHU - Facade Framing 644.1.TF123.03 - CF1 - Metal Louvres 643.2.TF1131.01 - MHU - Metal Windows 643.2.TF1131.01 - MHU - Metal Windows 643.2.TF1131.01 - MHU - Metal Windows 643.2.TF1135.01 - CF1 - General Metalwork 643.2.TF123.00 - MHU - Metal Worker 643.2.TF133.00 - MHU - Metal Worker 643.2.TF1333.00 - MHU - Metalwork 643.2.TF1333.00 - MHU - Metalwork 643.2.TF1333.00 - MHU - Temporary Carpentry 642.TF1333.00 - MHU - Temporary Carpentry	
642.TP.0620.01 - MHB - Reinforcement Fix 643.1.TP0631.01 - HMB - Post Tensioning 643.1.TP0630.01 - FMC - Reinforcement Fix 643.1.TP0630.01 - FMC - Reinforcement Fix 643.1.TP0631.01 - FMC - Post Tensioning 643.1.TP0631.01 - CP1 - Post Tensioning 643.1.TP0631.01 - CP1 - Post Tensioning 644.1.TP0631.01 - CP1 - Post Tensioning 640.PR0052.01 - RMB - Waterproofing Inground 642.TP.0832.03 - MHB - Waterproofing Inground 642.TP.0832.03 - MHB - Waterproofing Roofs & Decks 642.TP.0832.03 - MHB - Temporary Waterproofing 643.1.TP0832.01 - FMC - Waterproofing & Tanking 643.1.TP0832.01 - FMC - Waterproofing & Tanking 643.1.TP0832.01 - FMC - Waterproofing & Tanking 644.1.TP0832.01 - FMC - Waterproofing 644.1.TP0832.01 - FMC - Waterproofing 644.1.TP0832.01 - PRW - Stew Wide LV Equipment Supply 642.TP.0410.01 - RIE - Concrete Supply 642.TP.0420.01 - MHB - Concrete Place & Finish CP1.TP2335.01 - CP1/CP2 - Light Fitting Supply 640.PR0033.03 - PRW - Temporary Hydraulics Site Wide Reikculption 641.TP1732.01 - RIE - Water & Fire Mains reticulation 641.TP1732.01 - MHB - Concrete Pumping 643.1.TP3312.01 - FMC - HV Generator Supply 642.TP.0431.01 - MHB - Precast Concrete 644.2.TP0830.01 - CP2 - Blockwork 640.PR0032.02 - PRW - Main site Office & Accommendation Temporary Electrical 640.PR0032.02 - PRW - Main site Office & Accommendation Temporary Electrical 640.PR002.02 - PRW - Main site Office & Accommendation Temporary Electrical 640.PR002.02 - PRW - Main site Office & Accommendation Section Office Property - Post Prop	643.1.TP1810.03 - FMC - Meethnical Seylos - Gooling Tower Supply 643.1.TP1810.04 - FMC - Meethnical Seylos - AlU Supply 643.1.TP1810.04 - FMC - Meethnical Services - AlU Supply 643.1.TP1810.04 - FMC - Meethnical Services - Tanje 643.1.TP183.01 - FMC - Chechanical Services - Tanje 643.1.TP183.01 - FMC - Mehal Louwes 643.1.TP183.01 - FMC - Mehal Louwes 643.1.TP183.01 - FMC - Metalwork 643.1.TP183.01 - FMC - Metal Cladding 643.2.TP183.01 - FMC - Metal Windows 644.1.TP183.01 - FMC - Metal Windows 644.1.TP183.01 - FMC - Metal Windows 644.1.TP183.01 - FMC - Metal Windows 643.2.TP1313.01 - FMC - Metal Louwes 643.2.TP1313.01 - FMC - Metal Louwes 643.2.TP1313.01 - MHU - Metal Louwes 643.2.TP1320.01 - MHU - Metal Louwes 643.1.TP235.01 - MHU - Metal Louwes 643.1.TP235.01 - MHU - Metal Louwes 643.1.TP230.01 - MHU - General Metalwork 643.1.TP330.01 - MHB - General Metalwork 643.1.TP330.01 - MHB - General Carpentry 642.TP.1330.01 - MHB - General Carpentry	
642.TP.0620.01 - MHB - Reinforcement Flx 643.1.TP0631.01 - MHB - Post Tensioning 643.1.TP0630.01 - FMC - Reinforcement Flx 643.1.TP0630.01 - FMC - Reinforcement Flx 643.1.TP0631.01 - FMC - Post Tensioning 643.1.TP0631.01 - CP1 - Post Tensioning 643.1.TP0631.01 - CP1 - Post Tensioning 640.TP0631.01 - CP1 - Post Tensioning 640.PR0052.01 - PRW - Safety Precautions (FPE) 642.TP.0832.02 - MHB - Waterproofing Inground 642.TP.0832.02 - MHB - Waterproofing Roofs & Decks 642.TP.0832.03 - MHB - Temporary Waterproofing 643.1.TP0832.01 - FMC - Waterproofing & Tanking 643.1.TP0832.01 - FMC - Waterproofing 644.1.TP0832.01 - PRW - Site Wide LV Equipment Supply 642.TP2335.01 - PRW - Site Wide LV Equipment Supply 642.TP0420.01 - MHB - Concrete Place & Finish CP1.TP2335.01 - CP1/CP2 - Light Fitting Supply 640.PR0033.03 - PRW - Temporary Hydraulics Site Wide Reficulation 641.TP1732.01 - RIE - Water & Fire Mains reticulation 642.TP.0420.01 - MHB - Concrete Pumpling 643.1.TP3312.01 - FMC - HV Generator Supply 644.2.TP.0431.01 - MHB - Poncrete Pumpling 643.1.TP0832.01 - PRW - Temporary Lunch SiRes / Ablutions / Containers / Owier SiRes / Ablutions / Contai	643.171810.03 - FMC - Mechanical Seyrics - Conline Tower Supply 643.171810.04 - FMC - Mechanical Seyrics - HU Supply 643.171810.07 - FMC - Mechanical Services - HU Supply 643.171810.07 - FMC - Mechanical Services - Hu Supply 643.171810.01 - FMC - Mechanical Services - Tanjo 643.171810.01 - FMC - Butstrades - Handrall 643.171913.01 - FMC - Metall Louvres 643.171913.01 - FMC - Metallwork 643.171913.00 - FMC - Metallwork 643.171913.00 - FMC - Structural Steedwork 643.171913.01 - FMC - Soring - Structural Steedwork 643.17191637.01 - FMC - Goring - St Cleanrooms 644.17191637.01 - FMC - Goring - St Cleanrooms 644.17191630.01 - FML - Roofing - Structural Steedwork 643.171913.01 - FMC - Metall Windows 644.171913.01 - FMC - Metall Windows 644.171913.01 - FMC - Metall Windows 643.271913.01 - MHU - Roofing - Structural Steedwork 643.271913.01 - MHU - Metall Windows 644.171913.01 - MHU - Metall Windows 643.271913.01 - MHU - Metall Windows 643.2719135.01 - FMC - Metall Clean 643.2719135.01 - FMC - Metall Clean 643.2719135.01 - FMC - Metall Clean 643.2719135.01 - MHU - Metall Windows 644.1719130.01 - MHB - General Metalwork 643.2719135.01 - MHB - Ferriture 642.77191330.01 - MHB - Ferriture	
642.TP.0620.01 - MHB - Reinforcement Fix 643.1TP602.01 - SML - Rest Tensioning 643.1.TP602.01 - FMC - Rest Tensioning 643.1.TP602.01 - FMC - Rest Tensioning 643.1.TP602.01 - FMC - Rest Tensioning 643.1.TP602.01 - MHB - Reinforcement Fix 643.1.TP602.01 - MHB - Reinforcement Fix 644.1.TP603.10.1 - CP1 - Post Tensioning 640.PR0052.01 - PRW - Safety Precautions (PPE) 642.TP.0832.01 - MHB - Waterproofing Inground 642.TP.0832.02 - MHB - Waterproofing Roofs & Decks 642.TP.0832.03 - MHB - Waterproofing & Tanking - Reofs & Decks 642.TP.0832.01 - FMC - Waterproofing & Tanking - Reofs & Decks 643.1.TP8032.01 - FMC - Waterproofing & Tanking - Reofs & Decks 643.1.TP8032.01 - FMC - Waterproofing & Tanking - Reofs & Decks 643.2.TP0832.01 - PRW - Stew Wide LV Equipment Supply 641.TP0410.01 - RIE - Concrete Place & Finish 642.TP.0420.01 - MHB - Concrete Place & Finish 642.TP.0420.01 - MHB - Concrete Place & Finish 643.TP333.5.01 - CP1/CP2 - Light Fitting Supply 640.PR0033.03 - PRW - Temporary Hydraulics Site Wide Reikculption 641.TP1732.01 - RIE - Water & Fire Mains reticulation 642.TP.043.1.01 - MHB - Precast Concrete 644.2.TP0830.01 - CP2 - Blockwork 640.PR0032.02 - PRW - Main Site Office & Lecommondator Temporary Electrical 640.PR002.02 - PRW - Main Site Office & Lecommondator Temporary Electrical 640.PR002.02 - PRW - Main Site Office & Lecommondator Supply 642.TP.043.01 - MHB - Precast Concrete 644.P.TP0830.01 - CP2 - Blockwork 640.PR0032.02 - PRW - Main Site Office & Lecommondator Supply 642.TP.060.02 - MHB - Seaffolding	643.1.TP1810.03 - FMC - Meethnical Seylos - Gooling Tower Supply 643.1.TP1810.04 - FMC - Meethnical Seylos - AlU Supply 643.1.TP1810.04 - FMC - Meethnical Services - AlU Supply 643.1.TP1810.04 - FMC - Meethnical Services - Tanje 643.1.TP183.01 - FMC - Chechanical Services - Tanje 643.1.TP183.01 - FMC - Mehal Louwes 643.1.TP183.01 - FMC - Mehal Louwes 643.1.TP183.01 - FMC - Metalwork 643.1.TP183.01 - FMC - Metal Cladding 643.2.TP183.01 - FMC - Metal Windows 644.1.TP183.01 - FMC - Metal Windows 644.1.TP183.01 - FMC - Metal Windows 644.1.TP183.01 - FMC - Metal Windows 643.2.TP1313.01 - FMC - Metal Louwes 643.2.TP1313.01 - FMC - Metal Louwes 643.2.TP1313.01 - MHU - Metal Louwes 643.2.TP1320.01 - MHU - Metal Louwes 643.1.TP235.01 - MHU - Metal Louwes 643.1.TP235.01 - MHU - Metal Louwes 643.1.TP230.01 - MHU - General Metalwork 643.1.TP330.01 - MHB - General Metalwork 643.1.TP330.01 - MHB - General Carpentry 642.TP.1330.01 - MHB - General Carpentry	
642.TP.0620.01 - MHB - Reinforcement Flx 642.TP.0631.01 - MHB - Post Tensioning 643.1.TP0631.01 - FMC - Reinforcement Flx 643.1.TP0631.01 - FMC - Post Tensioning 643.2.TP0620.01 - FMC - Post Tensioning 643.2.TP0620.01 - MHU - Reinforcement Flx 644.1.TP0631.01 - CP1 - Post Tensioning 640.PR0052.01 - PRW - Safety Procautions (\$PE) 642.TP.0832.03 - MHB - Waterproofing Inground 642.TP.0832.03 - MHB - Waterproofing Roofs & Decks 642.TP.0832.03 - MHB - Waterproofing & Tanking 643.1.TP0832.01 - FMC - Waterproofing & Tanking 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Roofs & Decks 643.1.TP0832.01 - FMC - Waterproofing 643.1.TP0832.01 - CP1 - Waterproofing 644.1.TP0832.01 - CP1 - Waterproofing 644.2.TP.043.01 - CP1 - Waterproofing 642.TP.040.01 - RIE - Concrete Place & Finish CP1.TP2335.01 - PRW - Site Wide LV Equipment Supply 640.PR0033.03 - PRW - Temporary Hydraulics Site Wide Rehculation 642.TP.040.01 - RIE - Water & Fire Mains reliculation 642.TP.040.01 - RIE - Water & Fire Mains reliculation 642.TP.042.01 - MHB - Concrete Pumping 643.1.TP331.01 - FMC - HV Generator Supply 642.TP.042.01 - MHB - Concrete Pumping 643.1.TP331.01 - FMC - HV Generator Supply 644.TP.042.01 - MHB - Cencrete Pumping 645.TP.042.01 - MHB - Cencrete Pumping 6464.TP.042.01 - MHB - Ferest Concrete 644.1.TP333.01 - CP2 - Blockwork 640.PR0032.02 - PRW - Hein Site Office & Commediator Temporary Electrical 644.1.TP333.01 - CP2 - Seaffolding 644.1.TP333.01 - CP2 - Facade / Screens 644.1.TP333.01 - CP2 - Facade / Screens 644.1.TP333.01 - CP2 - Facade / Screens	643.1.TP1810.03 - FMC - Meethanical Seyrics - Cooling Tower Supply 643.1.TP1810.04 - FMC - Mechanical Services - AHU Supply 643.1.TP1810.05 - FMC - Mechanical Services - AHU Supply 643.1.TP1810.07 - FMC - Mechanical Services - Tanjo 643.1.TP123.01 - FMC - Baustrades - Handrall 643.1.TP123.01 - FMC - Melal Louvres 643.1.TP123.01 - FMC - Metalwork 643.1.TP1637.01 - FMS - Coolinoms & Cleanrooms 643.1.TP1637.01 - FMS - Coolinoms & Cleanrooms 643.1.TP131.01 - FMC - Metal Windows 643.2.TP133.01 - FMC - Metal Windows 644.1.TP1630.01 - MHU - Wall Cladding Systems 643.2.TP133.01 - FMC - Metal Windows 644.1.TP133.01 - FMC - Metal Windows 644.1.TP133.01 - FMC - Metal Windows 643.2.TP133.01 - MHU - Facade Framing 644.1.TP123.05 - CP1 - Metal Louvres 643.2.TP1313.01 - MHU - Wall Windows 643.2.TP1313.01 - MHU - Metal Windows 644.1.TP123.03 - CP1 - Surshades & Light Shelves 843.2.TP1313.01 - MHU - Metal Windows 643.2.TP1313.01 - MHU - Metal Louvres 643.2.TP1313.01 - MHU - Metal Windows 643.2.TP1333.01 - MHU - Metal Windows 644.1.TP1235.01 - CP1 - Final Clean 645.2.TP1333.01 - MHU - Metal Windows 646.2.TP1333.01 - MHU - Beneral Garpentry 642.TP1333.01 - MHB - Folier Shutters	
642.TP.0620.01 - MHB - Reinforcement Fix 643.1TP0631.01 - FMC - Relinforcement Fix 643.1.TP0631.01 - FMC - Relinforcement Fix 643.1.TP0631.01 - FMC - Post Tensioning 643.1.TP0631.01 - FMC - Post Tensioning 643.1.TP0631.01 - CP1 - Post Tensioning 643.1.TP0631.01 - CP1 - Post Tensioning 644.1.TP0631.01 - CP1 - Post Tensioning 640.PR0052.01 - RMB - Waterproofing Inground 642.TP.0832.01 - MHB - Waterproofing Inground 642.TP.0832.03 - MHB - Waterproofing Roofs & Decks 642.TP.0832.03 - MHB - Temporary Waterproofing 643.1.TP0832.01 - FMC - Waterproofing & Tanking 643.1.TP0832.01 - FMC - Waterproofing & Tanking 643.1.TP0832.01 - FMC - Waterproofing & Tanking 643.1.TP0832.01 - FMC - Waterproofing 644.1.TP0832.01 - FMC - Waterproofing 644.1.TP0832.01 - PRW - Stew Wide LV Equipment Supply 642.TP.0410.01 - RIE - Concrete Supply 642.TP.0420.01 - MHB - Concrete Place & Finish CP1.TP2335.01 - CP1/CP2 - Light Fitting Supply 640.PR0033.03 - PRW - Temporary Hydraulics Site Wide Rehculetion 641.TP1732.01 - RIE - Water & Fire Mains reticulation 641.TP1732.01 - MHB - Concrete Pumping 643.1.TP3312.01 - FMC - HV Generator Supply 642.TP.0431.01 - MHB - Precast Concrete 644.2.TP0830.01 - CP2 - Blockwork 640.PR0032.02 - PRW - Main Site Office & Accommagdation Temporary Electrical 640.PR0022.02 - PRW - Main Site Office & Accommagdation Temporary Electrical 644.2.TP1331.01 - CP2 - Facade / Screens 644.2.TP1331.01 - CP2 - General Carpentry 6640.PR0022.02 - PRW - Temporary Lunch Sibels / Ablutums / Containers / Guider Screens 6644.2.TP1330.01 - CP2 - General Carpentry 6644.2.TP1330.01 - CP2 - General Carpentry 6644.2.TP0302.02 - PRW - Pest Control	643.1.TP1810.03 - FMC - Meethnical Seylos - Gooling Tower Supply 643.1.TP1810.04 - FMC - Mechanical Services - Arti Supply 643.1.TP1810.04 - FMC - Mechanical Services - Arti Supply 643.1.TP1810.07 - FMC - Mechanical Services - Tanje 643.1.TP183.00 - FMC - Mechanical Services - Tanje 643.1.TP183.00 - FMC - Mechanical Services - Bilads 643.1.TP183.00 - FMC - Metalwork 643.1.TP183.00 - FMC - Metalwork 643.1.TP183.00 - FMC - Structural Streetwork 643.1.TP183.00 - FMC - Metal Mechanical Streetwork 643.1.TP183.00 - FMC - Metal Streetwork 643.1.TP183.00 - FMC - Metal Windows 644.1.TP183.00 - FMC - Metal Windows 644.1.TP183.00 - FMC - Metal Lowres 643.2.TP131.00 - FMC - Metal Lowres 643.2.TP131.00 - MHU - Metal Lowres 643.2.TP131.00 - MHU - Metal Lowres 643.2.TP123.00 - MHU - Metal Lowres 643.1.TP123.00 - MHU - Metal Lowres 643.1.TP123.00 - MHU - Metal Lowres 643.1.TP123.00 - MHU - General Metalwork 643.1.TP123.00 - MHU - General Metalwork 643.1.TP123.00 - MHB - General Carpentry 642.TP1330.01 - MHB - Cellings and Partitions	
642.TP.0620.01 - MHB - Reinforcement Flx 643.1.TP0631.01 - MHB - Post Tensioning 643.1.TP0630.01 - FMC - Reinforcement Flx 643.1.TP0630.01 - FMC - Reinforcement Flx 643.1.TP0631.01 - FMC - Post Tensioning 643.1.TP0631.01 - CP1 - Post Tensioning 643.1.TP0631.01 - CP1 - Post Tensioning 644.1.TP0631.01 - CP1 - Post Tensioning 640.PR0052.01 - PRW - Safety Precautions (FPE) 642.TP.0832.01 - MHB - Waterproofing Inground 642.TP.0832.02 - MHB - Waterproofing Roofs & Decks 642.TP.0832.03 - MHB - Temporary Waterproofing 643.1.TP0832.01 - FMC - Waterproofing & Tanking 643.1.TP0832.01 - FMC - Waterproofing 644.1.TP0832.01 - PRW - Site Wide LV Equipment Supply 642.TP2335.01 - PRW - Site Wide LV Equipment Supply 642.TP0420.01 - MHB - Concrete Place & Finish CP1.TP2335.01 - RE - Water & Fire Mains reticulation 641.TP1732.01 - RE - Water & Fire Mains reticulation 642.TP.0420.01 - MHB - Concrete Pumpling 643.1.TP3312.01 - FMC - HV Generator Supply 642.TP.0431.01 - MHB - Porcast Concrete 644.2.TP.0430.01 - MHB - Precast Concrete 644.2.TP.0430.01 - MHB - Scaffolding 644.1.TP0830.01 - CP2 - Blockwork 644.2.TP.0830.01 - CP2 - Blockwork 644.2.TP.0830.01 - CP2 - Blockwork 644.2.TP.0802.02 - PRW - Temporary Lunch Sinks / Ahlunkins / Containers / Owler Sinks / Ahlunkins / Containers	643.171810.03 - FMC - Mechanical Seyfics - Copiling Tower Supply 643.171810.04 - FMC - Mechanical Seyfics - Art U Supply 643.171810.07 - FMC - Mechanical Seyfics - Art U Supply 643.171810.07 - FMC - Mechanical Seyfics - Art U Supply 643.171810.07 - FMC - Mechanical Seyfics - Art U Supply 643.171820.01 - FMC - Bolustrades - Handrall 643.171820.01 - FMC - Metal Louvres 643.171820.01 - FMC - Metalwork 643.171820.01 - FMC - Metalwork 643.171820.01 - FMC - Structural Steelwork 643.171820.01 - FMC - Structural Steelwork 643.171820.01 - FMC - Structural Steelwork 643.171830.01 - FMC - Gooling Me Cleanrooms 644.1718630.01 - FM - Cooling Metal Cladding 643.271820.01 - MHU - Roofing & Metal Cladding 643.171820.01 - MHU - Wall Cladding Systems 643.171820.01 - MHU - Wall Cladding Systems 643.171820.01 - MHU - Metal Windows 644.171131.01 - CPI - Facader / Servens 643.271820.01 - MHU - Metal Windows 643.271820.01 - MHU - Metal Windows 644.171131.01 - MHU - Metal Windows 643.271820.01 - MHU - Metal Windows 643.271820.01 - CPI - Inacider / Servens 643.271820.01 - MHU - Metal Windows 642.7712330.01 - MHU - Metal Windows	
642.TP.0620.01 - MHB - Reinforcement Fix 643.1TP0631.01 - FMC - Relinforcement Fix 643.1.TP0631.01 - FMC - Relinforcement Fix 643.1.TP0631.01 - FMC - Post Tensioning 643.1.TP0631.01 - FMC - Post Tensioning 643.1.TP0631.01 - CP1 - Post Tensioning 643.1.TP0631.01 - CP1 - Post Tensioning 644.1.TP0631.01 - CP1 - Post Tensioning 640.PR0052.01 - RMB - Waterproofing Inground 642.TP.0832.01 - MHB - Waterproofing Inground 642.TP.0832.03 - MHB - Waterproofing Roofs & Decks 642.TP.0832.03 - MHB - Temporary Waterproofing 643.1.TP0832.01 - FMC - Waterproofing & Tanking 643.1.TP0832.01 - FMC - Waterproofing & Tanking 643.1.TP0832.01 - FMC - Waterproofing & Tanking 643.1.TP0832.01 - FMC - Waterproofing 644.1.TP0832.01 - FMC - Waterproofing 644.1.TP0832.01 - PRW - Stew Wide LV Equipment Supply 642.TP.0410.01 - RIE - Concrete Supply 642.TP.0420.01 - MHB - Concrete Place & Finish CP1.TP2335.01 - CP1/CP2 - Light Fitting Supply 640.PR0033.03 - PRW - Temporary Hydraulics Site Wide Rehculetion 641.TP1732.01 - RIE - Water & Fire Mains reticulation 641.TP1732.01 - MHB - Concrete Pumping 643.1.TP3312.01 - FMC - HV Generator Supply 642.TP.0431.01 - MHB - Precast Concrete 644.2.TP0830.01 - CP2 - Blockwork 640.PR0032.02 - PRW - Main Site Office & Accommagdation Temporary Electrical 640.PR0022.02 - PRW - Main Site Office & Accommagdation Temporary Electrical 644.2.TP1331.01 - CP2 - Facade / Screens 644.2.TP1331.01 - CP2 - General Carpentry 6640.PR0022.02 - PRW - Temporary Lunch Sibels / Ablutums / Containers / Guider Screens 6644.2.TP1330.01 - CP2 - General Carpentry 6644.2.TP1330.01 - CP2 - General Carpentry 6644.2.TP0302.02 - PRW - Pest Control	643.1.TP1810.03 - FMC - Meethnical Seylos - Gooling Tower Supply 643.1.TP1810.04 - FMC - Mechanical Services - Arti Supply 643.1.TP1810.04 - FMC - Mechanical Services - Arti Supply 643.1.TP1810.07 - FMC - Mechanical Services - Tanje 643.1.TP183.00 - FMC - Mechanical Services - Tanje 643.1.TP183.00 - FMC - Mechanical Services - Bilads 643.1.TP183.00 - FMC - Metalwork 643.1.TP183.00 - FMC - Metalwork 643.1.TP183.00 - FMC - Structural Streetwork 643.1.TP183.00 - FMC - Metal Mechanical Streetwork 643.1.TP183.00 - FMC - Metal Streetwork 643.1.TP183.00 - FMC - Metal Windows 644.1.TP183.00 - FMC - Metal Windows 644.1.TP183.00 - FMC - Metal Lowres 643.2.TP131.00 - FMC - Metal Lowres 643.2.TP131.01 - MHU - Metal Lowres 643.2.TP131.01 - MHU - Metal Lowres 643.2.TP123.00 - MHU - Metal Lowres 643.2.TP123.00 - MHU - Metal Lowres 643.1.TP223.01 - MHU - Metal Lowres 643.1.TP223.01 - MHU - Metal Lowres 643.1.TP233.01 - MHU - General Metalwork 643.1.TP233.00 - MHB - Ferniture 642.TP1330.01 - MHB - General Carpentry 642.TP1330.01 - MHB - Cellings and Partblons	

Attachment B				
Business Engagement		LPP Categorisation	Source of Supply	
Bub contractor	Reason	SEQ - Sauth Bast QLD REQ - Regional QLD AUS - Rest of Australia MP - Imported	C-Contastable L-Local	PásiCode
Builtsmart Modular Mining Pty Ltd	Modular Prototype Suite	AUS	C	2250
Shadforths Civil Pty Ltd	CP2 Early Works	REQ	L	4556
Wagstaff Piling QLD Pty Ltd	Test Piling	SEQ	L	4060
EVS Group Australia Pty Ltd	Site Security	SEQ	L	4350
Nilsen QLD Pty Ltd	Temporary Electrical CP2 & Prototype	SEQ	C	4170
Calty Constructions	Protoype Marketing Rigging and Marketing Deck	SEQ	L	4556
Blue Glue Pty Ltd	Blue Glue	AUS	L	2113
Kyana Pty Ltd	Temporary Hydraulics	SEQ	C	4567
Gordon Clements Nominees Pty Ltd T/A Cality Constructions	Covered Walkways and paths	SEQ	L	4556
Wagstaff Piling	Site Probing Works - 55 Probe Locations	SEQ	L L	4060
Quality Choice Signs	Re skin to existing Billboard	SEQ		4575
Fencepac	Site Perimeter Security Fence - Stage 1	SFQ /		4556
Fredon QLD Pty Limited	SCUH - Nambour Site	SEQ(//	C	4119
Shadforths	Crossover road Construction	sko v	<u>L</u>	4556
Underground Pipe and Cable Location Pty Ltd	Detect inground services prior to digging fence	SEQ.	<u>C</u>	4553
O2 Environmental Pty Ltd	Environmental and Sediment Monitoring	SEQ	L	4573
Shadforths	Supply & replace Road Base - Site Accommodati	SEQ	L	4556
Calty	Prototype Building Foundations	SEQ)	L	4556
Scapeshape Pty Ltd	Palmtree re-location	/sec	<u>L</u>	4211
D&J Services	Site Shed Cleaning	SEC	L	4011
Floor cover QLD - AK	Installation of vinyl and carpet to the Prototype Su	SEQ	C	
Quality Choice Signs	Signage	SEQ	C	4575
The trustee for The SJ & DY Eade Family Trust T/A Vismark	Supply and install shade cloth to SCUH Site	SEQ	c	4570
Regson Fabrication	Suppy & Install 2 Gate Closures	SEQ	C	4556
Orange Hire Pty Ltd	Supply & Hire of Perimeter Fencing	SEQ	L	2760
Transpacific Industries Pty Ltd	Site Sewerage Tank Pump Out	SEQ	С	4064
Universal Cranes Sunshine Coast Pty Ltd	Mobile Crane Hire	SEQ	L	4556
Siemens	Prototype Security	IMP	C	4006
Merlon (t/a Statewide Communications)	Prototype Nurse Call & PES	AUS	C _	4113
Ken Wilson & Associates Pty Ltd T/a KWA Blinds	Prototype Curtain & IV Tracks	SEQ	С	4163
Coates Hire Operations Pty Ltd	Portable toilets	SEQ	L _	4131
Energex Limited	Energex Detailed Design	SEQ	L	4558
ATF Sunshine Coast and Total Site Set Up	Supply & Install crowd control bayriers	SEQ	С	4000
Evolution Trafic Control	Provide traffic Controller	SEQ	L	4558
Lucid Edge PTY LTD	Video conversions from AVI to MWV+ YouTube	AUS	С	4014
Worldwide Online Printing Market Street	Masterplan Poster	SEQ	L.	4000
Lucid Edge PTY LTD	Video Conversions from AVI to MWV +	AUS	С	2010
Combined Security Services	Security Guards	SEQ	L	4575
DLA Piper	Professional fees	AUS	L	4000
Greenbins	Size 8 Bin	SEQ	L	4074
Metro Express	2 Containers sent from GCUH to SCUH	SEQ	L	4106
Trumpf Med Australia Pty Ltd	3 Combination light set & Trumpf Serv	IMP	С	2067
	Medical Beds and Patient Lifting System	IMP	С	6163
Arjohuntleigh	Sultural Peritage Induction	SEQ		3134
Arunta Plastics (QLD) Pty Ltd	Supply and install of windows and external doors	SEQ	L	4556
G James	Temp Fencing	SEQ	L	4558
ATF Services Pty Ltd	AGV Advisory Services	AUS	С	2127
Robotic Automation Group	Transport Items to SCUH site	SEQ	L	4034
Energy Crane Services Pty	Temporary Electrics supply South	SEQ	L	4006
Energex Limited	Supply doors and frame	SEQ	L	4556
Spence Door	market and a second second	SEQ	c	4131
Coates Hire Operations Pty Ltd	Supply of Bulk Potable and Non-Potable Water	SEQ	T	4567
Kyana Projects Pty Ltd	Supply of Potable Water to Site until Feb 13	SEQ	С	4127
Neverfail Springwater Limited	Photograph Palm removal & monthly images	SEQ	L	4215
Steve Ryan t/as Rix Ryan Photography P/L	Supply of Site Accompdation Cleaning Products		L	4560
Dunckers Pty Ltd	Supply and Install of office furniture for Prototype		C	4561
Bizfurn Express	Re-Fil 2 x 10000L Water Tanks + 1 Additional Vi		L	4551
Suncoast Water Carriers	Supply of kitchen fridge and microwave	SEQ	C	4575
Harvey Norman	Supply and Install of office furniture for Prototype		c	4557
Bizfurn Express	Redback Pest Control to SCUH Site Offices	SEQ	<u> </u>	4561
Amalgamated Pest Control	Supply and install of examination couch	SEQ	c	4570
	inchibit and margin or event margin concu		 0	4551
Midmed	Hard Hat Stickare			
Guality Choice Signs Pty Ltd	Hard Hat Stickers	SEQ		
	Supply and deliver of Mirrors for Prototype Suite	AUS	С	4173
Quality Choice Signs Pty Ltd				

Attachment C:						
Business Engagement		LIPP Categorisat		ipply		
Subcontractor	WorkPackage	SEQ - South East QLD BEQ - Regional QLD	G- Contestable L - Local	PostCode	Goods and	Supplier's location
Shamrock Civil	Bulk Civil Works Pre-Load	SEQ	L	4076	s.47(3)	lpswich
Shadforth Civil Engineering	Cut to Fill Civil Works	SEQ	L	4556		Sunshine Coast
Wagstaff Piling	Precast Piling & Shear Piling	SEQ	L	4060		Brisbane Inner City
Beavis & Bartels Pty Ltd	Temp Hydraulics (Site Wide)	SEQ	C	4013		Brisbane - North_
Oneform	Install Formwork to CP2	SEQ	L	4173		Brisbane - East
East Coast Concrete Contractors	Concrete Place and Finish to CP2	Other States	L	2485		NSW
Delco Steel	Reinforcement Fix to CP2	Other States	С	4178		Brisbane - East
Pro Concrete Pumping	Concrete Pumping to CP2	SEQ	L	4220		Gold Coast
FIP Electrical (Qld) Pty Ltd	Electrical Installation to CP2	SEQ	С	4144		Brisbane Inner City
VT Services	Tower Crane to CP2	SEQ	L	4074_		Brisbane - West
Tacoma Piumbing and Drainage	Hydraulics to CP2	SEQ	С	4573		Sunshine Coast
EVS GROUP AUSTRALIA PTY LTD	PR0059 Site Security	Other States	С	2077	\triangleright	NSW
UNISPAN AUSTRALIA PTY LTD	644.2.TP0060.01 - CP2 - Scaffolding	SEQ	С	(207	A7(2)(b)	Gold Coast
Boral Construction Materials (QLD)	644.2.TP0410.01 - CP2 - Concrete Supply	SEQ	L	4059/	s.47(3)(b)	Brisbane Inner City
OTIS ELEVATOR COMPANY PTY LTD	642.TP.2030.01 - MHB - Vertical Transportati	SEQ	C _	4101		Brisbane Inner City
OTIS ELEVATOR COMPANY PTY LTD	643.1.TP2030.01 - FMC - Vertical Transporta	SEQ	/ 1	4101		Brisbane Inner City
OTIS ELEVATOR COMPANY PTY LTD	643.2.TP2030.01 - MHU - Vertical Transports	SEQ	(c/	410		Brisbane Inner City
OTIS ELEVATOR COMPANY PTY LTD	644.1.TP2030.01 - CP1 - Vertical Transporta	SEQ	i c	110/1		Brisbane Inner City
Polyseal Waterproofing QLD Pty Ltd	644.2.TP0832.01 - CP2 - Waterproofing	SEQ	C	42/07		Gold Coast
STRUCTURAL SYSTEMS (NORTHERN) PT	644.2.TP0631.01 - CP2 - Post Tensioning	SEQ /	~ 6	4207		Gold Coast
OLD Drink and Snack Machines	640.PR0022.08 - PRW - Vending Machines -	SEQ	(//5)	4559		Sunshine Coast
Regson Fabrications	641.TP1230.01 - CP2 - Façade	SEQ V	イ/ (゚ロ) ド	4556		Sunshine Coast
Custom Shades Pty Ltd	641.TP1633.00 - CP2 - Shade Structure	SEQ	(4)	4173		Brisbane - East
B41 TP2450 01 - Car Park managemen	Designa Sabar	Other States		9009		SA
641 TP1712-01 - Reinwater Tenks to C		SEQ./	L .	45/5		Sunshine Coast
The state of the s						





A Division of QMI Solutions

Progress Report #11 for period to 30 September 2013 Prepared by Industry Capability Network (Queensland) Ltd

This report details the assistance provided during the above period by ICN (Qld) to Lend Lease in the delivery and implementation of the Local Industry Participation Plan (LIPP) for the Sunshine Coast University Hospital in accordance with the Local Industry Policy (LIP).

1. Liaison with the Project on LIP Issues

ICN met with Queensland Health (Sam Betros) in May 2011 to discuss the project, ICN services, and LIP procedures and issues. ICN assisted QH in the development of the LIPP for the project and provided an evaluation report to QH on project bidders' LIP plan submissions in March 2012.

2. Liaison with Lend Lease on LIP Compliance

Lend Lease met with ICN to establish processes and procedures for management of the project's obligations to the LIP. It was decided that ICN will provide support on number of services covering:

- Implementation of the LIPP (capability searches on contestable packages)
- Presenting at briefing sessions
- Registering companies via ICN Gateway
- Verification of source of manufacture and service provision in subcontracts
- Business matching
- Progress reporting (Monthly) and final LNP Outcomes reporting (at end of project)

3. Tier Barometer

Tier Barometer is an on-line self-assessment tool developed by ICN and the State Government. It provides participating companies with an assessment of their tier level in terms of supply to major projects. The tool is used by the project to analyse the basic capabilities of potential suppliers during the registration process.


4. Contestable Packages

Queensland and Australian capability, content and capacity will be considered for all the work packages. The following activities have been undertaken:

- An ICN officer has been assigned full time to the project.
- Detailed Business Matching has been carried out by ICN. 163 work packages have been managed in this way.
 These are listed at Attachment A.
- 1378 registrations against work packages on Gateway have been received
- 65 early works have been awarded in March. These are listed at Attachment B.
- 29 work packages have been awarded so far and they are listed at Attachment C

Potential subcontractors will be given an indication of the size and generic nature of the project, and questioned regarding their capability and capacity to carry out the work, code compliance, and previous work history. Reports will be sent to Lend Lease detailing local companies which have the capability and capacity to carry out the work for each of the above packages. The primary objective of the Local Industry Policy is to ensure that competitive local companies are given full, fair and reasonable opportunity to tenger for work packages. This objective will be achieved if the companies nominated by ICN, and other local companies that Lend Lease is aware of, are considered in the establishment of the tender list, and, subject to meeting pre-qualification criteria, a reasonable number of local companies are subsequently invited to tender. Lend Lease intends to apply this requirement.

6. Source of Supply



Lend Lease has advised that out of 94 Purchase Orders, 65 were awarded for early works, one for Substructure and 28 for Work Packages listed on the ICN Gateway Project webpage. These were to companies that registered interest via ICN. As far as practicable, the measurement of industry participation focuses on the actual source of supply rather than the location through which the order is placed. The location in which services are provided, materials manufactured or where value adding takes place is indicative of the actual source of supply. Of the 29 Work Package contracts that have been awarded, 24 were won by South East Queensland (SEQ) companies, four by New South Wales companies and one by South Australia.

7. Prototype Building

A prototype showcase building was erected in record time. This enabled focus group to provide input in to the final design in a cost effective manner.

8. Local Industry Participation

Lend Lease Project Director has personally provided project work scope and Lend Lease supplier engagement approach information to a number of larger Australian Manufacturers who have asked for more information. These include The GWA Group; The Laminex Group; Spence Doors and Rockcote Industries. For the latter company time was dedicated to a site inspection of their manufacturing facilities.

ICN supported Lend Lease in delivering briefing sessions as proposed in their LIP plan covering:

Monday 3rd September 2012 - Civil, Infrastructure, Structure & Landscaping

Monday 17th September 2012 – Services

Monday 24th September 2012 – Roof & Façade

Monday 8th October 2012 - Fit out & Finishes

Monday 15th October 2012 - Furniture Fittings & Equipment (FF&E)

Lend Lease also presented at the General Briefing Sessions along with ICN on 13, 14/16 and 20th of August 2012.

Lend Lease project managers attended a briefing presentation by the members of the Cleantech Industries group of companies on 24th September 2012.

Lend Lease took part in a Local Business expo on 10th May 2013.

ICN – Evan Flower – presented to the Gympie Major Project Opportunities forum on the project on 18th June 2013.

10. Efforts to engage with Local Companies include:

Press release by Health Minister, radio interviews by Project Director, Newspaper articles in CM and Sunshine Coast Daily followed up by substantial advertisements in the same newspapers on 19th January. Support articles followed from SSC Council and local councillors.

As a result of the above information sessions and the advertising campaign almost 1000 registrations have been received with close to 100 companies listing after the newspaper advertisements.

To date over 1378 companies have registered interestin work packages.

11. Source of Manufacture

As subcontracts begin to be awarded, the source of manufacture or service provision for contestable packages will be validated and verified in discussion with the corresponding subcontractors.

12. Reporting

Business matching reports on companies nominated for the trade packages listed at Attachment A are being provided to Lend Lease.


Evan Flower
Capability Services Manager
ICN Queensland

AAA		
Attachment A:		
Enquiries	640.PR0056.02 - PRW - Site Office Cleaning	643.1.TP2630.01 - FMC - Ceilings and Partitions
PR.0051.01 Crossover Road Construction TP.0231.01 Preload	643.1.TP0410.01 - FMC - Concrete Supply	644.2.TP1311.01 - CP2 - Door and Frame Supply
TP.0320.01 Sediment control	643.1.TP0420.01 - FMC - Concrete Place	643.2.TP2930.01 - MHU - Internal Glazing
PR0059 Site Security	643.1.TP0422.01 - FMC - Concrete Pumping	643.2.TP3030.01 - MHU - Painting
644.2.TP1732.01 - CP2 - Hydraulics	643.1.TP0431.01 - FMC - Precast Concrete	643.1.TP3030.01 ~ FMC - Painting
644.2.TP0620.01 - CP2 - Reinforcement Fixing	643.2.TP0410.01 - MHU - Concrete Supply	643.2.TP2630.01 - MHU- Ceilings and Partitions
644.2.TP0530.01 - CP2 - Formwork	643.2.TP0420.01 - MHU - Concrete Placing	644.1.TP2630.01 - CP1 - Cellings and Partitions
644.2.TP0422.01 - CP2 - Concrete Pumping	643.2.TP0422.01 - MHU - Concrete Pumping	642.TP.3131.01 - MHB - Mature Trees
644.2.TP0420.01 - CP2 - Concrete Placing	644.1.TP0410.01 - CP1 - Concrete Supply	641.TP3131.01 - CP2 - Soft/Hard Landscaping
544.2.TP0410.01 - CP2 - Concrete Supply	644.1.TP0420.01 - CP1 - Concrete Place	642.TP.2720.01 - MHB - Carpet Laying
644.2.TP0060.02 - CP2 - Scaffolding	644.1.TP0422.01 - CP1 - Concrete Pumping	642.TP.1311.01 - MHB - Doors Supply
645.TP3230.01 - Kawana Way Duplication	643.1.TP0060.01 - FMC - Scaffolding	642.TP.2734.01 - MHB - Epoxy Flooring
641.TP.0230.01 - RIE - Bulk Earthworks and Fill	644.1.TP0060.01 - CP1 - Scaffolding	Any Opportunities - General Clean
641.TP.3230.01 - RIE - Roads & Infrastructure Services	642.TP.0830.01 - MHB - Blockwork	642.TP.1434.01 - MHB - Workstations & Screens
644.2.TP2239.01 - CP2 - Carpark Control System	643.1.TP0830.01 - FMC - Blockwork	Any Opportunities - Painting
640.PR0033.01 - PRW - Temporary Hydraulics	643.2.TP0830.01 - MHU - Blockwork	$-10/\Lambda$
640.PR0056.01 - PRW - Rubbish Removal 644.2.TP0832.01 - CP2 - Waterproofing	644.1.TP0830.01 - CP1 - Blockwork 640.PR0054.01 - PRW - Site Photography	
644.2.TP2330.01 - CP2 - Electrical	644.2.TP3030.01 - CP2 - Painting & Line Marking	
640.PR0042.01 - PRW - Tower Cranes, Hoists & Crews	644.1.TP3030.01 - CP1 - Painting & Line Marking	
644.2.TP0631.01 - CP2 - Post Tensioning	644.2.TP1030.01 - CP2 - Structural Steelwork	
642.TP.2030.01 - MHB - Vertical Transportation	644.1.TP1030.02 - CP1 - Structural Steelwork	
643.1.TP2030.01 - FMC - Vertical Transportation	642.TP.2230.01 - MHB - Building Maintenance	mit
643.2.TP2030.01 - MHU - Vertical Transportation	643.2.TP1631.01 - MHU - Roofing-Built-up/Me	_/_/
644.1.TP2030.01 - CP1 - Vertical Transportation	642.TP.1630.01 - MHB - Roof & Metal Cladding	
640,PR0041.01 - PRW - Mobile Cranes	642.TP.1636.01 - MHB - Wall Cladding Systems	
644.2.TP1830.01 - CP2 - Mechanical	642.TP.1032.01 - MHB - Facade Framing	
644.2.TP1712.01 - CP2 - Water Tanks	642.TP.1132.01 - MHB - Shop Fronts	/
640.PR0021.02 - PRW - Site Fencing	642.TP.1135.02 - MHB - Sunshades & Light Sheh	/es
640.PR0046.01 - PRW - Temporary Plant & Equipment	642.TP.1131.01 - MHB - Metal Wingows	
640.PR0022.06 - PRW - Temporary Onsite Canteen and Cate	642.TP.1631.01 MAR - Roofing-Built-up/ Men	brane
640.PR0022.05 - PRW - Temporary Carpentry Site Accommo		
644.1.TP0530.01 - CP1 - Formwork	643.2.TP1710.01 - MAN - Santaryware & Tapw	
642.TP.0530.01 - MHB - Formwork	642.TP.1732.02 - MHB - Sanitaryware & Tapwai	
643.2.TP0530.01 - MHU - Formwork	642.TP.1231.01 - MHB - Palustrades & Handrail	
643.1.TP0530.01 - FMC - Formwork	642.TP.1230.01 (MMB Metalwork	
643.1.TP2310.01 - FMC - Site Wide HV Equipment Supply On	642.TP.1235.01 - MHB - Metal Louvres	
642.TP2335.02 - PRW - Uninterruptable Power Supply Units		
644.1.TP0330.02 - CP1 - Pile Cut-off	943.1.TP1630.01 - FMC Roof Metal Sheeting	
643.2.TP0330.02 - MHU- Pile Cut-off	642.1.T) 1626.01 - FMC - Facade Cladding	
643.1.TP0330.02 - FMC - Pile Cut-off	643.1.7P1032.01 - FMC - Facade Framing 642.7P.1030.01 - MHB - Structural Steelwork	
642.TP.0330.03 - MHB - Sheet Piling 642.TP.0330.02 - MHB - Pile Cut-off	643 1.TP1135.01 - FMC - Sunshades and Light Sl	anhune.
643.1.TP0330.03 - FMC - Sheet Piling	643.1. P1810.02 - FMC - Mechanical Services -	
644.1.TP0620.01 - CP1 - Reinforcement Fix	643.1.TP1810.03 - FMC - Mechanical Services -	
642.TP.0620.01 - MHB - Reinforcement Fix	643.1.TP1810.04 - FMC - Mechanical Services -	
642.TP.0631.01 - MHB - Post Tensioning	643.1.TP1810.01 - FMC - Mechanical Services -	
643.1.TP0620.01 - FMC - Reinforcement Fix	643.1.TP1231.01 - FMC - Balustrades & Handrai	
643.1.TP0631.01 - FMC- Post Tensioning	643 .TP1235.01 - FMC - Metal Louvres	
643.2.TP0620.01 - MHU - Reinforcement Fix	643.1.TP1432.01 - FMC - Curtains & Blinds	
644.1.TP0631.01 - CP1 - Post Tensioning	643.1.TP1230.01 - FMC - Metalwork	
640, PR0052.01 - PRW - Safety Precautions (PPE)	643.1.TP1030.01 - FMC - Structural Steelwork	
642,TP,0832.01 - MHB - Waterproofing Inground	643.1.TP2236.01 - FMC - Kitchen / Laundry Equi	pment
642.TP.0832.02 - MHB - Waterproofing Roofs & Decks	642.TP.1637.01 - MHB - Coolrooms & Cleanroo	
642.TP.0832.03 - MHB - Temporary Waterproofing	643.1.TP1637.01 - FMC - Coolrooms & Cleanro	oms
643.1.TP0832.01 - FMC - Waterproofing & Tanking	644.1.TP1630.01 - CP1 - Roofing	
643.1.TP3832.01 - FMC - Waterproofing & Tanking - Roofs &	643.2.TP1630.01 - MHU - Roofing & Metal Clad	ding
643.2.TP0832.01 - MHU - Waterproofing	643.2.TP1636.01 - MHU - Wall Cladding System	
644.1.TP0832.01 - CP1 - Waterproofing	643.1.TP1131.01 - FMC - Metal Windows	
642.TP2335.01 - PRW - Site Wide LV Equipment Supply	644.1.TP1131.01 - CP1 - Facade / Screens	
641.TP0410.01 - RIE - Concrete Supply	643.2.TP1032.01 - MHU - Facade Framing	
642.TP.0420.01 - MHB - Concrete Place & Finish	644.1.TP1235.01 - CP1 - Metal Louvres	
CP1.TP2335.01 - CP1/CP2 - Light Fitting Supply	643.2.TP1131.01 - MHU - Metal Windows	
640.PR0033.03 - PRW - Temporary Hydraulics Site Wide Reti	,	l
641.TP1732.01 - RIE - Water & Fire Mains reticulation	643.2.TP1135.01 - MHU - Sunshades & Light She	eives
642.TP.0422.01 - MHB - Concrete Pumping	643.2.TP1235.01 - MHU - Metalwork	
643.1.TP2312.01 - FMC - HV Generator Supply	643.2.TP1235.01 - MHU - Metal Louvres	
642.TP.0431.01 - MHB - Precast Concrete	643.1.TP2235.01 - FMC - Dock Levelers	
644.2.TP0830.01 - CP2 - Blockwork	644.1.TP1230.03 - CP1 - General Metalwork	
640.PR0032.02 - PRW - Main Site Office & Accommodation		
640.PR0022.02 - PRW - Temporary Lunch Sheds / Ablutions /	642.TP.1330.01 - MHB - General Carpentry 642.TP.1433.01 - MHB - Furniture	
642.TP.0060.01 - MHB - Scaffolding 644.2.TP1131.01 - CP2 - Facade / Screens	642.TP.1236.01 - MHB - Purniture 642.TP.1236.01 - MHB - Roiler Shutters	
644.2.TP1131.01 - CP2 - Facade / Screens 644.2.TP1330.01 - CP2 - General Carpentry	642.TP.1332.01 - MHB - Roller Shutters 642.TP.1332.01 - MHB - Doors & Door Frame St	undy
640.PR0022.07 - PRW - Pest Control	642.TP.1332.01 - MHB - Ceilings and Partitions	
640.PR0023.03 - PRW - Temporary Site Signage	642.TP.2930.01 - MHB - Glazing & Mirrors	-
640.PR0033.02 - PRW - Main Site Office Accommodation Te		
640.PR0022.04 - PRW - Site Office Fitout & Furniture	642.TP.3030.01 - MHB - Painting	Lip Progress Report #11 Scuh September20139 P8.772
	1	

Attachment B					
Business Engagement		LIPP Categorisation	Source of Supply		
Subcontractor	Réason	SED - SOUTH END QLD REQ Regional CLD AUS - Piest of Australia IMP Imported	G Comestable L Local	PostCode	Values of Goods or Services supplied
Builtsmart Modular Mining Pty Ltd	Modular Prototype Suite	AUS	С	2250	s.47(3)(b)
Shadforths CIVI Pty Ltd	CP2 Early Works	SEQ	L	4556	
Wagstaff Piling QLD Pty Ltd	Test Pling	SEQ	L	4060	
EVS Group Australia Pty Ltd	Site Security	SEQ	<u>L</u>	4350	
Nilsen QLD Pty Ltd	Temporary Electrical CP2 & Prototype	SEQ	C	4170 4556	
Calty Constructions	Protoype Marketing Rigging and Marketing Deck Blue Glue		<u> </u>	2113	
Dice cree i iy Eld	Temporary Hydraulics	AUS SEQ	C	4567	
Kyana Pty Ltd Gordon Clements Nominees Pty Ltd T/A Calty Constructions	Covered Walkways and paths	SEQ	Ľ	4556	
Wagstaff Pling	Site Probing Works - 55 Probe Locations	SEQ	L	4060	
Quality Choice Signs	Re skin to existing Billboard	SEQ	С	4575	
Fercepac	Site Perimeter Security Fence - Stage 1	SEQ _		4556	
Fredon QLD Pty Limited	SCUH - Nambour Site	SEQ	1/6	4119	
Shadforths	Crossover road Construction	SEQ	/ /)∟ }	4556	
Orlogicala ripo dile contre accessi y	Detect inground services prior to digging fence	SEQ	<i>O</i> 6/	4553	
O2 Environmental Pty Ltd	Environmental and Sediment Monitoring	SEQ	<u></u>	4573	
Shadforths	Supply & replace Road Base - Site Accommodati		<u> </u>	4556	
Calty	Prototype Building Foundations	SEQ	<u> </u>	4556 4211	
Scapeshape Pty Ltd	Palmtree re-location	SEQ	<u> </u>	40-1	
D&J Services	Site Shed Cleaning Installation of vinyl and carpet to the Prototype Su		C C	4011	
Floor cover QLD - AK	Signage	SEQ	c	4575	
Quality Choice Signs	Supply and Install shade cloth to SCUH Site	SEQ	c	4570	
The trustee for The SJ & DY Eade Family Trust T/A Vismark	Suppy & Install 2 Gate Closures	SEQ)	Č	4556	
Regson Fabrication Orange Hire Pty Ltd	Supply & Hire of Perlmeter Fencing	SEQ	L	2760	
Transpacific Industries Pty Ltd	Site Sewerage Tank Pump Out	SEC	С	4064	
Universal Cranes Sunshine Coast Pty Ltd	Mobile Crane Hire	SEQ	L	4556	
Slemens	Prototype Security	IMP	С	4006	
Merlon (t/a Statewide Communications)	Prototype Nurse Call & PES	AUS	С	4113	
Ken Wilson & Associates Pty Ltd T/a KWA Blinds	Prototype Curtain & IV Tracks	SEQ	С	4163	
Coates Hire Operations Pty Ltd	Portable toilets	SEQ	L	4131	
Energex Limited	Energex Detailed Design	SEQ	L	4558	
ATF Sunshine Coast and Total Site Set Up	Supply & Install crowd control barriers	SEQ_	C	4000	
Evalution Traffic Control	Provide traffic Controller	SEQ	L	4558	s.47(3)(b)
Lucid Edge PTY LTD	Video conversions from AV to MW V- You Tube	AUS	C	4014 4000	
Worldwide Online Printing Market Street	Masterplan Poster Video Conversions from AVI to MAV +	SEQ AUS	C	2010	
Lucid Edge PTY LTD	Security Suards	SEQ	L	4575	
Combined Security Services	Professional rees	AUS	L	4000	
DLA Piper Greenbins	Size 8 8 In	SEQ	L	4074	
Metro Express	2 Containers sent from GCUH to SCUH	SEQ	L	4106	
Trumpf Med Australia Pty Ltd	3x3 Combination light set & Trumpf Serv	IMP	С	2067	
Arjohuntleigh	Medical Beds and Patent Lifting System	IMP	C	6163	
Arunta Plastics (QLD) Pty Ltd	Sultural Heritage Induction	SEQ		3134	
G James	Supply and Install of windows and external doors	SEQ	L	4556	
ATF Services Pty Ltd	temp Feriding	SEQ	L	4558	
Robotic Automation Group	AGV Advisory Services	AUS	С	2127	
Energy Crane Services Pty	Transport items to SCUH site	SEQ	L	4034	
Energex Limited	Temporary Electrics supply South	SEQ	L	4006	
Spence Door	Supply doors and frame	SEQ	L	4556 4131	
Coates Hire Operations Pty Ltd	Date Date Date by and him Date big Mater	SEQ	С	4567	
Kyana Projects Pty Ltd	Supply of Bulk Potable and Non-Potable Water Supply of Potable Water to Site until Feb 13	SEQ	С	4127	
Neverfall Springwater Limited	Photograph Palm removal & monthly Images	SEQ	L	4215	
Steve Ryan tras Rix Ryan Photography P/L	Supply of Site Accommodation Cleaning Products	SEQ	L	4560	
Dunckers Pty Ltd Bizfurn Express	Supply and Install of office furniture for Prototype		c	4561	
Suncoast Water Carriers	Re-Fill 2 x 10000L Water Tanks + 1 Additional VI		L	4551	
Harvey Norman	Supply of kitchen fridge and microwave	SEQ	С	4575	
Bizfurn Express	Supply and Install of office furniture for Prototype		С	4557	
Amalgamated Pest Control	Redback Pest Control to SCUH Site Offices	SEQ	L	4561	
Mcmed	Supply and Install of examination couch	SEQ	C	4570	
Quality Choice Signs Pty Ltd	Hard Hat Stickers	SEQ	С	4551	
Viridian	Supply and deliver of Mirrors for Prototype Sulte		С	4173	
	Corporate Charges	SEQ	ļ.	1	
Multimedia Technology	Multi Touch Interactive Whiteboard Park First Aid Shed & First Aid Training on	SEQ SEQ	C	4006 4556	
Response First Aid					

Attachment C:						
Business Engagement		LIPP Categorisation	Source of	Supply		
Subcontractor	WorkPackage	SEQ - South East Q(D) REQ - Regional QLD AUS - Rest of Australia	Contestable L-Local		Goods Value	Supplier's location
Shamrock Civil	Bulk Civil Works Pre-Load	SEQ	L	4076	s.47(3)	lpswich
Shadforth Civil Engineering	Cut to Fill Civil Works	SEQ	L	4556		Sunshine Coast
Wagstaff Piling	Precast Piling & Shear Piling	SEQ	Î L	4060		Brisbane Inner City
Beavis & Bartels Pty Ltd	Temp Hydraulics (Site Wide)	SEQ	С	4013		Brisbane - North
Oneform	Install Formwork to CP2	SEQ	Į L	4173		Brisbane - East
East Coast Concrete Contractors	Concrete Place and Finish to CP2	Other States	L	2485		NSW
Delco Steel	Reinforcement Fix to CP2	Other States	C	4178		Brisbane - East
Pro Concrete Pumping	Concrete Pumping to CP2	SEQ	L	4220		Gold Coast
FIP Electrical (Qld) Pty Ltd	Electrical installation to CP2	SEQ	С	4144		Brisbane Inner City
VT Services	Tower Crane to CP2	SEQ	L	4074		Brisbane - West
Tacoma Plumbing and Drainage	Hydraulics to CP2	SEQ	С	4573	,	Sunshine Coast
EVS GROUP AUSTRAL!A PTY LTD	PR0059 Site Security	Other States	C	2077		NSW
UNISPAN AUSTRALIA PTY LTD	644.2.TP0060.01 - CP2 - Scaffolding	SEQ	C	4207/	()	Gold Coast
Boral Construction Materials (QLD)	644.2.TP0410.01 - CP2 - Concrete Supply	SEQ	L	4059		Brisbane Inner City
OTIS ELEVATOR COMPANY PTY LTD	642.TP.2030.01 - MHB - Vertical Transportation	SEQ		4101	s.47(3)(b)	Brisbane Inner City
OTIS ELEVATOR COMPANY PTY LTD	643.1.TP2030.01 - FMC - Vertical Transportation	SEQ	1/ C/	4101	3.47 (3)(0)	Brisbane Inner City
OTIS ELEVATOR COMPANY PTY LTD	643.2.TP2030.01 - MHU - Vertical Transportation	SEQ	\ c /	4101		Brisbane Inner City
OTIS ELEVATOR COMPANY PTY LTD	644.1.TP2030.01 - CP1 - Vertical Transportation	SEQ	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	4101		Brisbane Inner City
Polyseal Waterproofing QLD Pty Ltd	644.2.TP0832.01 - CP2 - Waterproofing	SEQ /	1/6	4207		Gold Coast
STRUCTURAL SYSTEMS (NORTHERN	644.2,TP0631.01 - CP2 - Post Tensioning	SEQ (/ C >	4207		Gold Coast
QLD Drink and Snack Machines	640.PR0022.08 - PRW - Vending Machines - CF	SEQ V	()c/_	4559		Sunshine Coast
Regson Fabrications	641.TP1230.01 - CP2 - Façade	SEC	$\bigcup_{i \in I} \mathcal{J}_i$	4556		Sunshine Coast
Custom Shades Pty Ltd	641.TP1633.00 - CP2 - Shade Structure	(SEC)	C	4173		Brisbane - East
Designa Sabar	641.TP2430.01 - Car Park management system	Other States	L	5009		SA
ALS	641.TP1712.01 - Rainwater Tanks to CP2	SEQ	/ L	4575		Sunshine Coast
Matchit Blocklaying	644.2 TP0830.01 & 644.1 TP0830.01 * Blockwor	320	L	4559		Sunshine Coast
Wagstaff Piling Old Pty Ltd	641 TP0330.02 - CP1 - Piling	SEC	L	4060		Brisbane
	644.1 TP1830.01 - CP2 - Mechanical	X @/	C	4556		Sunshine Coast
Eastcoast Concrete Contractors	Substructure	/ Other States	С	2485		NSW

Note: Substructure wasn't listed on ICN Gateway website as an opportunity for companies to register through ICN.







A Division of QMI Solutions

Progress Report #12 for period to 31 October 2013 Prepared by Industry Capability Network (Queensland) Ltd

This report details the assistance provided during the above period by ICN (Qld) to Lend Lease in the delivery and implementation of the Local Industry Participation Plan (LIPP) for the Sunshine Coast University Hospital in accordance with the Local Industry Policy (LIP).

1. Liaison with the Project on LIP Issues

ICN met with Queensland Health (Sam Betros) in May 2011 to discuss the project. ICN services, and LIP procedures and issues. ICN assisted QH in the development of the LIPP for the project and provided an evaluation report to QH on project bidders' LIP plan submissions in March 2012.

2. Liaison with Lend Lease on LIP Compliance

Lend Lease met with ICN to establish processes and procedures for management of the project's obligations to the LIP. It was decided that ICN will provide support on number of services covering:

- Implementation of the LIPP (capability searches on contestable packages)
- Presenting at briefing sessions
- Registering companies via ICN Gateway
- Verification of source of manufacture and service provision in subcontracts
- Business matching
- Progress reporting (Monthly) and final LIPP Outcomes reporting (at end of project)

3. Tier Barometer

Tier Barometer is an on-line self-assessment tool developed by ICN and the State Government. It provides participating companies with an assessment of their tier level in terms of supply to major projects. The tool is used by the project to analyse the basic capabilities of potential suppliers during the registration process.


4. Contestable Packages

Queensland and Australian capability, content and capacity will be considered for all the work packages. The following activities have been undertaken:

- An ICN officer has been assigned full time to the project.
- Detailed Business Matching has been carried out by ICN. 191 work packages have been managed in this way.
 These are listed at Attachment A.
- 1391 registrations against work packages on Gateway have been received
- 65 early works have been awarded in March. These are listed at Attachment B.
- 44 work packages have been awarded so far and they are listed at Attachment C

Potential subcontractors will be given an indication of the size and generic nature of the project, and questioned regarding their capability and capacity to carry out the work, code compliance, and previous work history. Reports will be sent to Lend Lease detailing local companies which have the capability and capacity to carry out the work for each of the above packages. The primary objective of the Local Industry Policy is to ensure that competitive local companies are given full, fair and reasonable opportunity to tender for work packages. This objective will be achieved if the companies nominated by ICN, and other local companies that Lend Lease is aware of, are considered in the establishment of the tender list, and, subject to meeting pre-qualification criteria, a reasonable number of local companies are subsequently invited to tender. Lend Lease intends to apply this requirement.

6. Source of Supply



Lend Lease has advised that out of 94 Purchase Orders, 65 were awarded for early works, one for Substructure and 43 for Work Packages listed on the ICN Gateway Project webpage. These were to companies that registered interest via ICN. As far as practicable, the measurement of industry participation focuses on the actual source of supply rather than the location through which the order is placed. The location in which services are provided, materials manufactured or where value adding takes place is indicative of the actual source of supply. Of the 44 Work Package contracts that have been awarded, 37 were won by South East Queensland (SEQ) companies, six by New South Wales companies and one by South Australia.

7. Prototype Building

A prototype showcase building was erected in record time. This enabled focus group to provide input in to the final design in a cost effective manner.

8. Local Industry Participation

Lend Lease Project Director has personally provided project work scope and Lend Lease supplier engagement approach information to a number of larger Australian Manufacturers who have asked for more information. These include The GWA Group; The Laminex Group; Spence Doors and Rockcote industries. For the latter company time was dedicated to a site inspection of their manufacturing facilities.

ICN supported Lend Lease in delivering briefing sessions as proposed in their LIP plan covering:

Monday 3rd September 2012 – Civil, Infrastructure, Structure & Landscaping

Monday 17th September 2012 - Services

Monday 24th September 2012 - Roof & Facade

Monday 8th October 2012 - Fit out & Finishes

Monday 15th October 2012 – Furniture Fittings & Equipment (FF&E)

Lend Lease also presented at the General Briefing Sessions along with ICN on 13, 14, 16 and 20th of August 2012.

Lend Lease project managers attended a briefing presentation by the members of the Cleantech Industries group of companies on 24th September 2012.

Lend Lease took part in a Local Business expo on 10th May 2013.

ICN – Evan Flower – presented to the Gympie Major Project Opportunities Forum on the project on 18th June 2013.

10. Efforts to engage with Local Companies include:

Press release by Health Minister, radio interviews by Project Director, Newspaper articles in CM and Sunshine Coast Daily followed up by substantial advertisements in the same newspapers on 19th January. Support articles followed from SSC Council and local councillors.

As a result of the above information sessions and the advertising campaign almost 1000 registrations have been received with close to 100 companies listing after the newspaper advertisements.

To date over 1391 companies have registered interest in work packages.

11. Source of Manufacture

As subcontracts begin to be awarded, the source of manufacture or service provision for contestable packages will be validated and verified in discussion with the corresponding subcontractors.

12. Reporting

Business matching reports on companies nominated for the trade packages listed at Attachment A are being provided to Lend Lease.


Evan Flower
Senior Consultant - Capability Services
ICN Queensland

tachment A:			
quiries Details		 	
quiryid	Title	+	
			<u> </u>
	PR.0051.01 Crossover Road Construction		640.PR0022.C4 - PRW - Site Office Fitout & Furnit 97314 643.1.TP1531.01 - FMC - Hardware - Sundry
	TP.0231.01 Preload	94500	640. PR0056.02 - PRW - Site Office Cleaning 97330 642. TP.3030.01 - MHB - Painting
	TP.0320.01 Sediment control	94527	7 643.1.TP0410.01 - FMC - Concrete Supply 97432 643.1.TP2630.01 - FMC - Ceilings and Partiti
90995	PROD59 Site Security	94534	643.1.TP0420.01 - FMC - Concrete Place 97433 644.2.TP1311.01 - CP2 - Door and Frame Su
91583	644.2.TP1732.01 - CP2 - Hydraulics		643.1.TP0422.01 - FMC - Concrete Pumping 97443 643.2.TP2930.01 - MHU - Internal Glazing
91584	644.2.TP0620.01 - CP2 - Reinforcement Fixing		7 643.1.TP0431.01 - FMC - Precast Concrete 97446 643.2.TP3030.01 - MHU - Painting
	644.2.TP0530.01 - CP2 - Formwork		643.2.TP0410.01 - MHU - Concrete Supply 97450 643.1.TP3030.01 - FMC - Painting
	644.2.TP0422.01 - CP2 - Concrete Pumping		
	544.2.TP0420.01 - CP2 - Concrete Placing		
	644.2.TP0410.01 - CP2 - Concrete Supply		043.2.TP0422.01 - MHU - Concrete Pumping 97464 644.1.TP2630.01 - CP1 - Cellings and Partition
			644.1.TP0410.01 - CP1 - Concrete Supply 97624 642.TP.3131.01 - MHB - Mature Trees
	644.2.TP0060.01 - CP2 - Scaffolding		644.1.TP0420.01 - CP1 - Concrete Place 97693 641.TP3131.01 - CP2 - Soft/Hard Landscapin
	645.TP3230.01 - Kawana Way Duplication		644.1.TP0422.01 - CP1 - Concrete Pumping 97728 642.TP.2720.01 - MHB - Carpet Laying
	641.TP.0230.01 - RIE - Bulk Farthworks and Fill	94627	643.1.TP0060.01 - FMC - Scaffolding 97863 642.TP-1311.01 - MHB - Doors Supply
92499	641.TP.3230.01 - R!E - Roads & Infrastructure Services	94628	644.1.TP0060.01 - CP1 - Scaffolding 9/864 643, TP, 2734, 01 - MHB - Epoxy Flooring
92500	644.2.TP2239.01 - CP2 - Carpark Control System	94884	642.TP.0830.01 - MHB - Blockwork 7913 Apry Opportunities - General Clean
92677	640.PR0033.01 - PRW - Temporary Hydraulics		643.1.TP0830.01 - FMC - Blockwork 97915 642/TP.1434.01 - MHB - Workstations & Scr
	640.PR0056.01 - PRW - Rubbish Removal		643.2.TP0830.01 - MHU - Blockwork 98075 642:TP.1537.01 - MHB - Signage
	644.2.TP0832.01 - CP2 - Waterproofing		644.1.TP0830.01 - CP1 - Blockwork /98145 644.1.TP0311.01 - CP1 - Door and Frame Su
	644.2.TP2330.01 - CP2 - Electrical		
	640.PR0042.01 - PRW - Tower Cranes, Hoists & Crews		
			644.2.TP3030.01 - CP2 - Painting & Line Marking 98326 642.TP.2732.02 - MHB - Vinyl
	644.2.TP0631.01 - CP2 - Post Tensioning		644.1.TP3030.01 - CP1 - Painting & Line Marking 98348 644.1.TP2732.02 - CP1 - Vinyl Installation
	642.TP.2030.01 - MHB - Vertical Transportation		644.2.TP1030.01 - CP2 - Structural Steebwork 99352 644.1.TP1330.01 - CP1 - General Carpentry
	643.1.TP2030.01 - FMC - Vertical Transportation		644.1.TP1030.02 - CP1 - Structural Steelwork 98354 643.1.TP1330.01 - FMC - Door & Hardware
	643.2.TP2030.01 - MHU - Vertical Transportation		642.TP.2230.01 - MHB - Building Malmenance Un 98468 642.TP.2711.01 - MHB - Floor Mats
	644.1.TP2030.01 - CP1 - Vertical Transportation	95101	643.2.TP1631.01 - MHU - Roof ng-Built up Mem 38473 642.TP.2731.01 - MHB - Insitu Floor Coverin
93297	640.PR0041.01 - PRW - Mobile Cranes	95111	642.TP.1630.01 - MHB - Roof & Metal Classification 98477 642.TP.2735.01 - MHB - Tactile Indicators
	644.2.TP1830.01 - CP2 - Mechanical		642.TP.1636.01 - MHB - Wall Cladding Systems 98495 642.TP.2830.01 - MHB - Tiling
	644.2.TP1712.01 - CP2 - Water Tanks		642.TP.1032.01 - MHB Facade Fraging 98500 643.1.TP2720.01 - FMC - Carpet Install
	640.PR0021.02 - PRW - Site Fencing		642.TP.1132.01 - MHB - 5100 From 5
	640.PR0046.01 - PRW - Temporary Plant & Equipment		642.TP.1135.02 - MHB - Sunyhades & Light Shelves
	640. PR0022.06 - PRW - Temporary Onsite Canteen and Caterir		
	640.PR0022.05 - PRW - Temporary Carpentry Site Accommoda		642.TP. 1131.01 - MMB - Meta/Windows
			642.TP 1631.01 MHB Roofing Built up / Membrane
	644.1.TP0530.01 - CP1 - Formwork		642.TP.1712.Q1 - MH8 - Tanks & Pumps Supply
	642.TP.0530.01 - MHB - Formwork		643.2.TP1710.01 MHU -Sanitaryware & Tapware Supply
	643.2.TP0530.01 - MHU - Formwork	95324	642.TP 2732.02 MHB - Sanita yware & Tapware Supply
	643.1.TP0530.01 - FMC - Formwork	95369	542, P. 1231, 01 - MHB - Balustrades & Handralls
93544	643.1.TP2310.01 - FMC - Site Wide HV Equipment Supply Only	95376	647.TP 1230/01 MHB - Metalwork
	642.TP2335.02 - PRW - Uninterruptable Power Supply Units (U		641, TP. 1285.91 - NHB Metal Louvres
	644.1.TP0330.02 - CP1 - Pile Cut-off		642. P.123Z-01_MHb - Movement Joints
	643.2.TP0330.02 - MHU- Pile Cut-off		643.1.181630.01 - PMC - Roof Metal Sheeting
	643.1.TP0330.02 - FMC - Pile Cut-off		643.1.TP1636.01 - FMC - Facade Cladding
	642.TP.0330.03 - MHB - Sheet Piling		643.4.TP1032.01 - FMC - Facade Framing
	642.TP.0330.02 - MHB - Pile Cut-off		642.TP.1030 01 - MHB - Structural Steelwork
	643.1.TP0330.03 - FMC - Sheet Piling		643.1.TP1135.01 - FMC - Sunshades and Light Shelves
	644.1.TP0620.01 - CP1 - Reinforcement Flx		643.1.TP1810.02 - FMC - Mechanical Services - Chiller Supply
93573	642.TP.0620.01 - MHB - Reinforcement Fix	95456	649, 1.TP1810.03 - FMC - Mechanical Services - Cooling Tower Supply
93574	642.TP.0631.01 - MHB - Post Tensioning	95457	643.1.TP1810.04 - FMC - Mechanical Services - AHU Supply
93575	643.1.TP0620.01 - FMC - Reinforcement Fix	95458	643.1.TP1810.01 - FMC - Mechanical Services - Tanks
	643.1.TP0631.01 - FMC- Post Tensioning		643.1.TP1231.01 - FMC - Balustrades & Handrails
	543.2.TP0620.01 - MHU - Reinforcement Fix		643.1.TP1235.01 - FMC - Metai Louvres
	644.1.TP0631.01 - CP1 - Post Tensioning		643.1.TP1432.01 - FMC - Curtains & Blinds
03591	640.PR0052.01 - PRW - Safety Pregautions (RPE)		643.1.TP133.01 - FMC - Currains & Brings
73301	EAR TO DOOD OF AND MARKET TERROUGHS (RPE)		
93/1/	642.TP.0832.01 - MHB - Waterproofing Inground	95588	643. 1.TP1030.01 - FMC - Structural Steelwork
	642.TP.0832.02 - MHB - Water proofing Roofs & Decks	_	643.1.TP2236.01 - FMC - Kitchen / Laundry Equipment
	642.TP.0832.03 - MHB - Temporary Waterproofing		642.TP.1637.01 - MHB - Coolrooms & Cleanrooms
93720	543.1.TP0832.01 - FMC - Water proofing & Tanking		643.1.TP1637.01 - FMC - Coolrooms & Cleanrooms
93721	543.1.TP3832.01 - FMC - Waterproofing & Tanking - Roofs & D		644.1.TP1630.01 - CP1 - Roofing
	543.2.TP3832.01 - MAU - Waterproofing		643.2.TP1630.01 - MHU - Roofing & Metal Cladding
	644.1.TP0832.01 CP1 Waterproofing		643.2.TP1636.01 - MHU - Wall Cladding Systems
	542,TP2335.01 - RRW - Site Wide LV Equipment Supply		643.1.TP1131.01 - FMC - Metal Windows
	541.TP0410.01 - RIE Concrete Supply	_	
	542.TP.0420.01 - MHB - Coccrete Nace & Finish		644.1.TP1131.01 - CP1 - Facade / Screens
			643.2.TP1032.01 - MHU - Facade Framing
	CP1.TP2335.01 - CP1/CP2 - Light Fitting Supply		644.1.TP1235.01 - CP1 - Metal Louvres
94119[6	540.PR0033.03 - PRW - Temporary Nydraulics Site Wide Reticul		643.2.TP1131.01 - MHU - Metal Windows
	541.TP1732.01 - RIE - Water & Fire Mains reticulation		644.2.TP0057.01 - CP2 - Final Clean
	542.TP.0422.01 - MHB - Concrete Pumping	96151	643.2.TP1135.01 - MHU - Sunshades & Light Shelves
94234 6	543.1.TP2312.01 - FMC - HV Generator Supply		643.2.TP1230.01 - MHU - Metalwork
94256	542.TP.0431.01 - MHB - Precast Concrete		643.2.TP1235.01 - MHU - Metal Louvres
	544.2.TP0830.01 - CP2 - Blockwork		643.1.TP2235.01 - FMC - Dock Levelers
	640.PR0032.02 - PRW - Main Site Office & Accommodation Ter		644.1.TP1230.03 - CP1 - General Metalwork
	640.PR0022.02 - PRW - Temporary Lunch Sheds / Ablutions / Co		
			643.2.TP3530.01 - MHU - Temporary Carpentry
	642.TP.3060.01 - MHB - Scaffolding		642.TP.1330.01 - MHB - General Carpentry
	44.2.TP1131.C1 - CP2 - Facade / Screens		642.TP.1433.01 - MHB - Furniture
	644.2.TP1330.01 - CP2 - General Carpentry	97037	642.TP.1236.01 - MMB - Roiler Shutters
94362 6	540.PR0022.07 - PRW - Pest Control	97039	642.TP.1332.01 - MHB - Doors & Door Frame Supply
94363 6	40.PR0023.03 - PRW - Temporary Site Signage		642.TP.2630.01 - MHB - Cellings and Partitions
	40.PR0033.02 - PRW - Main Site Office Accommodation Temp		642.TP.2930.01 - MH9 - Glazing & Mirrors
!			

Subtrant Modes Mining Pty Lis	Attachment B:				10.11	
Subment Moder Mining Pt Ltd	Business Engagement		LiPP Categorisation	Source of Supply		
Silbarran Modale Mining Py LE Shooter Prototype Side	Subcontractor	Reason	SEQ - South East QLD	C-Cortestable	PostCode	Values of
Standard Maldar Mining Py LE	11		AUS - Rest of Australia	L - Local		
Submert Market Minist PL LS		157 74	MP Imposed	1		
Standard Print Standard S		The date of the control of the contr			0050	
Magnet PRincy CLO Ptp Let 100						S.4/(3)(D
Selection Sele						
Name (CLP Pt List)						
Carlo Communication						
Blac Gale ALS 1 2119						
Vigent Pir List					_	
Cooked Comment Numbers Pt List TAX Cash Constructions					_	
Wagedarf Pring Side Proteing Works - Sir Prote Locatore SEC						
County Charles Signs File shift to existing Billboard SEC C 4576		Site Probing Works - 55 Probe Locations		L	4060	
Size Permister Security Fence - Stage 1 SEQ				C	4575	
Common Fine and Cable Location Pty Ltd	Fencepac	Site Perimeter Security Fence - Stage 1	SEQ	С	4556	
Liebergrouder Pipe and Cabible Location Pip Ltd	Fredon QLD Pty Limited	SCUH - Nambour Site	SEQ	C	4119	
CRE-Informemental Pty Ltd	Shadforths	Crossover road Construction	SEQ	7/1	4556	
Standarden	Underground Pipe and Cable Location Pty Ltd					
Printing	O2 Environmental Pty Ltd			∠ L/		
State Put Put Partimose Pri-List Partimose Pri-Decation Sto L 4211	Shadforths			<u></u>		
Dist. Services Sites Sites Clearing Site Clearing Site Clearing Site Clearing	Calty	71		1		
Page	Scapeshape Pty Ltd	4				
Supply and part Supply and		· · · · · · · · · · · · · · · · · · ·		/	4011	
The trustee for The SJ & DY East Frantly Trust T/A Vismark Supply and Intell alreade ofth in SCUH 1810 SEC C 4500 Region Fabrication Supply & Harte of Pertinent Fereing SEC L 2780 C 4566 C 456				_	4888	
Regent Fabrication		1 0 0				
Comparison Put						
Transpacific Inclustries Pyr Ltd						
Mobile Crane Fire SED						
Prototype Security						
Metron (16 Statewick Communications)	 -					
Prototype Curtelin & IV Tracks						
Coates Hire Operations Pty Ltd						
Energee United		Portable tollets		L	4131	
Evolution Traffic Control	Energex Limited	Energex Detailed Design	SEQ	L	4558	
Lucid Edge PTY LTD Video conversions from AV to YAVVA VALVOR Montrobule Chiline Printing Market Street Materipain Poster SEC L 4000 Lucid Edge PTY LTD Video Cornersions Com AV to YAVVA VALVOR SEC L 4000 Lucid Edge PTY LTD Video Cornersions Com AV to YAVVA AUS C 2010 Cornelina Security Services Security Services Security Services Security Services SEC L 4575 DLA Piper Protessigati legs AUS L 4000 Greenbins Size 8 Jfn SEC L 4074 Water Express 2 Configurers Sert Info CCLH to SC/H SEC L 4074 Water Express 2 Configurers Sert Info CCLH to SC/H SEC L 4074 Water Express 2 Configurers Sert Info CCLH to SC/H SEC L 4074 Water Express 3 Configurers Sert Info CCLH to SC/H SEC L 4000 Through Med Australia PTY Ltd 3x3 Combination light get & Trumpt Serv M/P C 2067 Alphanutrilejih Medical Beds Broy Patibut Lifting System M/P C 6168 Autranta Plastica (CLD) Pty Ltd Cultural Heritage in Patibut Lifting System M/P C 6168 Autranta Plastica (CLD) Pty Ltd Cultural Heritage in Plastica in Patibut Services AUS C 2127 ATT Services Pty Ltd Term Lenning SEC L 4556 ATT Services Pty Ltd Term Lenning SEC L 4556 Probletic Automation Group August Autralia of Windows and external doors SEC L 4556 Penergy Crane Services Pty Ltd Services Supply South SEC L 4004 Energy Crane Services Pty Ltd Supply doors flat frame SEC L 4566 Spence Door Supply doors flat frame SEC L 4566 Spence Door Supply doors flat frame SEC L 4566 Spence Door Supply doors flat frame SEC L 4566 Spence Door Supply of Stat Potable Water to Site until Feb 13 SEC C 4131 Kyana Projecte Pty Ltd Supply of Stat Accomodation Cleaning Products SEC L 4561 Supply of Stat Accomodation Cleaning Products SEC C 4567 Noverfall Syringwater Limited Supply of Stat Accomodation Cleaning Products SEC C 4561 Supply of Stat Accomodation Cleaning Products SEC C 4561 Supply of Stat Accomodation Cleaning Products SEC C 4561 Supply of Stat Accomodation Cleaning Products SEC C 4561 Supply of Stat Accomodation Sec Prototype SEC C 4561 Supply of Sta	ATF Sunshine Coast and Total Site Set Up	Supply & Instali crowd control barriers	SEQ	С	4000	
Worldwide Online Printing Market Street	Evolution Trafic Control	Provide traffic Controller	SEQ	L	4558	s.47(3)(b)
Lucid Edge PTY LTD	Lucid Edge PTY LTD	Video conversions from AV to WWV YouTube	AUS	С	4014	
Combined Security Services	Worldwide Online Printing Market Street		SEQ	L	4000	
Professional Prof	Lucid Edge PTY LTD		AUS		2010	
Size 8 5 Size 9 Size	Combined Security Services					
Metro Express 2 Configiners Sert from GCLFLip SC/MH SEQ L 4108 Trumpt Med Australia Pty Ltd 3x3 Combination light set 8. Trumpt Serv IMP C 2067 Aphorunteligh Medical Bedes 3x4 Pathes Litting System IMP C 6 6163 Anunta Plastics (OLD) Pty Ltd Cultural Heritage Induction SEQ 3134 GUarries Augusty and install or Wirbowles and external doors SEQ L 4556 ATT. Services Pty Ltd Temb_Enering SEQ L 4558 Probatic Automation Group AQV Advisory Services AUS C 2127 Energy Crane Services Pty Transport teims to SCUH site Energy Litting September Services Supply South Seq L 4008 Spence Door Supply doors and frame SEQ L 4556 Coates Fire Operations Pty Ltd Supply Bulk Potable and Non-Potable Water Seq C 4127 Neveral Springwater Limited Spenty Services Seq L 4567 Neveral Springwater Limited Spenty Services Seq L 4567 Steve Ryan fives Rix Ryan Photography Pt Services Sty Ldd Supply of Sits Accommodation Cleaning Products Supply and Install of office furniture for Probulype Seq C 4561 Supply and Install of office furniture for Probulype SEQ C C 457 Supply and Install of office furniture for Probulype SEQ C C 4561 Supply and Install of office furniture for Probulype SEQ C C 4561 Supply and Install of office furniture for Probulype SEQ C C 4561 Supply and Install of office furniture for Probulype SEQ C C 4561 Supply and Install of office furniture for Probulype SEQ C C 4561 Supply and Install of office furniture for Probulype SEQ C C 4561 Supply and Install of office furniture for Probulype SEQ C C 4561 Supply and Install of office furniture for Probulype SEQ C C 4561 Supply and Install of office furniture for Probulype SEQ C C 4561 Supply and Install of office furniture for Probulype SEQ C C 4561 Supply and Install of office furniture for Probulype SEQ C C 4561 Supply and Install of office furniture for Probulype SEQ C C 4561 Supply and Install of office furniture for Probulype SEQ C C 4561 Supply and Install of office furniture for Probulype SEQ C C 4561 Supply and Install of office furniture for Probulype SEQ C C 4561 Supply and In						
Trumpf Med Australia Pty Ltd			 		_	
Arjohursteigh Arunta Plastics (CLD) Pty Ltd Cultural Heritage Induction SEQ 3134 Guartes Guart			 		_	
Arunta Plastos (CLD) Pty Ltd Gulares Supply and install of whitewas and external doors SEQ L 4556 ATF Services Pty Ltd Phobogic Automation Group AQV Achieory Services AUS C 2127 Energy Crane Services Pty Transport leithing SCUH sile Energes Limited Temporary Electrics supply South SEQ L 4004 Energes Limited Temporary Electrics supply South SEQ L 4006 Supply doors and frame SEQ L 4006 Supply of Supply of Suk Potable and Non-Potable Water SEQ C 4131 Kyrana Projects Pty Ltd Supply of Public Vater to Site until Feb 13 SEQ C 4127 Seve Ryan Photography Pti Photograph Palm removal & monthly images SEQ L 4560 Supply of Site Accommodation Cleaning Products SEQ L 4560 Supply of Site Accommodation Cleaning Products SEQ C 4561 Supply of Site Accommodation Cl						
Guarnes Supply and install of windows and external doors SEQ L 4556 ATF Services Pty Ltd Territ Fencing SEQ L 4558 Phobotic Automation Group Automation Group Services Aus C 25127 Energy Crane Services Pty Transport liems to SCUH site SEQ L 4034 Energex Limited Supply doors and frame SEQ L 4006 Spence Door Supply doors and frame SEQ L 4556 Coates Hire Operations Pty Ltd Supply of Bulk Potable and Non-Potable Water SEQ C 4131 Neverfall Springwater Limited Supply of Bulk Potable and Non-Potable Water SEQ C 4127 Sleve Ryan Protography P/I Photography P/I Photography P/I Photograph Palm removal & monthly Images SEQ L 4215 Supply of Site Accomposation Creaning Products SEQ L 4560 Bizfurn Express Supply and Install of office furniture for Prototype SEQ C 4575 Bizrup Ryorman Supply of kitchen fridge and microwave SEQ C 4575 Bizrup Ryorman Supply of kitchen fridge and microwave SEQ C 4576 Bizfurn Express Supply of kitchen fridge and microwave SEQ C 4561 Bizfurn Express Supply of listal of office furniture for Prototype SEQ C 4561 Bizrup Ryorman Supply of kitchen fridge and microwave SEQ C 4576 Bizrup Ryorman Supply of listal of office furniture for Prototype SEQ C 4561 Bizrup Ryorman Supply of listal of office furniture for Prototype SEQ C 4561 Bizrup Ryorman Supply of listal of office furniture for Prototype SEQ C 4561 Bizrup Ryorman Supply and Install of office furniture for Prototype SEQ C 4561 Bizrup Ryorman Supply and Install of office furniture for Prototype SEQ C 4561 Bizrup Ryorman Supply and Install of office furniture for Prototype SEQ C 4561 Bizrup Ryorman Seq C C 4570 Budaty Choice Signs Pty Ltd Hard Hat Stickers SEQ C 4570 Budaty Choice Signs Pty Ltd Hard Hat Stickers SEQ C 4561 Budaty Choice Signs Pty Ltd Hard Hat Stickers SEQ C 4561 Budaty Choice Signs Pty Ltd Hard Hat Stickers SEQ C 4561 Budaty Choice Signs Pty Ltd Hard Hat Stickers SEQ C 4561				C		
ATF Services Pty Ltd Terms Fencing AQV Adhlerry Services AUS C 2127 Farishport Items to SCUH site Energy Crane Services Pty Transport Items to SCUH site Energy Crane Services Pty Transport Items to SCUH site Energy Crane Services Pty Transport Items to SCUH site Energy Crane Services Pty Transport Items to SCUH site Energy Crane Services Pty Transport Items to SCUH site Energy Crane Services Pty Transport Items to SCUH site Energy Crane Services Pty Transport Items to SCUH site Energy Crane Services Pty Transport Items to SCUH site Energy Crane SEQ L 4004 Energy Crane SEQ L 4556 C 4131 Energy Crane SEQ L 4556 Energy Crane Services Pty Ltd Supply of Stuh Potable and Non-Potable Water SEQ C 4131 SEQ C 4131 SEQ C 4127 Steve Flyan trans Rix Riyan Photography Pt Photograph Palm removal & monthly Images SEQ L 4215 Supply of Site Accomodation Cleaning Products SEQ L 4550 Bizrium Express Supply and Install of office furniture for Prototype SEQ C 4551 Harvey Norman Supply of kitchen fridge and microwave SEQ C 4556 Energy C 4557 Energy Collection Energy Collection Supply and Install of office furniture for Prototype SEQ C 4557 Energy Collection Energy Collection Energy Collection Energy Collection Energy C 4557 Energy Collection Energy C 4551 Energy C						
Pobotic Automation Group PGV Advisory Services AUS C 2127 Energy Crane Services Pty Transport Items to SCUH site Energes Limited Temporary Electrics supply South SEQ L 4006 Sepence Door Supply doors and frame SEQ L 4556 Coates Hire Operations Pty Ltd Supply of Bulk Potable and Non-Potable Water SEQ C 4131 Kyana Projects Pty Ltd Supply of Bulk Potable and Non-Potable Water SEQ C 4127 Sever Flyan t/as Fix Ryan Photography P/L Photograph Palm removal & monthly Images SEQ L 4560 Supply and Install of office furniture for Prototype SEQ C 4561 Supply of Richen fridge and microwave SEQ C 4575 Bizfurn Express Supply of Install of exertination couch SeQ C 4570 Redback Pest Control to SCUH Site Offices SEQ C 4570 Quality Choice Signs Pty Ltd Supply and distall of office furniture for Prototype SEQ C 4570 Corporate Online of Micros SEQ C 4173 Supply and Install of exertination couch SEQ C 4570 Quality Choice Signs Pty Ltd Supply and disteller of Mirrors for Prototype SEQ C 4571 Redback Pest Control to SCUH Site Offices SEQ C 4570 Quality Choice Signs Pty Ltd Supply and deliver of Mirrors for Prototype SEQ C 4570 Quality Choice Signs Pty Ltd Multi Touch Interactive Whiteboard SEQ C 4006						
Energy Crane Services Pty Energy Crane Services Pty Energy Limited Energy Limited Energy Limited Energy Electrics supply South Energy Electrics supply South Energy Electrics Supply Goors and frame Energy Coates Hire Operations Pty Ltd Energy Electrics Electrics Supply doors and frame Energy Electrics Electric Supply doors and frame Energy Electric Supply of Bulk Potable Water to Site until Feb 13 Energy Electric Supply of Potable Water to Site until Feb 13 Energy Electric Supply of Electric						
Energex Limited Temporary Electrics supply South SEQ L 4006 Spence Door Supply doors and frame SEQ L 4556 Coates Hire Operations Pty Ltd Supply doors and frame SEQ C 4131 SEQ C 41567 SEQ C 41567 Seq Reverful Springwater Limited Supply of Bulk Potable and Non-Potable Water SEQ Supply of Potable Water to Site until Feb 13 SEQ C 41567 Sever Ryan thas Rix Ryan Photography Pt/ Photograph Palm removal & monthly Images SEQ L 4215 Dunckers Pty Ltd Supply of Site Accomodation Cleaning Products SEQ L 4560 Sizfum Express Supply and Install of office furniture for Prototype SEQ C 4561 Supply of Ritchen fridge and microwave SEQ L 4551 Harvey Norman Supply of Ritchen fridge and microwave SEQ C 4575 Sizfum Express Supply and Install of office furniture for Prototype SEQ C 4567 Amalgamated Pest Control Redback Pest Control to SCUH Site Offices SEQ L 4561 Midmed Supply and Install of office furniture for Prototype SEQ C 4570 Quality Choice Signs Pty Ltd Hard Hat Stickers SEQ C 4571 Supply and deliver of Mirrors for Prototype SEQ C 4571 Sizguand deliver of Mirrors for Prototype SEQ C 4572 Supply and deliver of Mirrors for Prototype SEQ C 4571 Sizguand deliver of Mirrors for Prototype SEQ C 4572 Sizguand deliver of Mirrors for Prototype Size C 4573 Supply and deliver of Mirrors for Prototype Size C 4574 Sizguand deliver of Mirrors for Prototype Size C 4473 Supply and deliver of Mirrors for Prototype Size C 4473 Supply and deliver of Mirrors for Prototype Size C 44066					-	
Spence Door Supply doors and frame SEQ L 4556 Coates Hire Operations Pty Ltd Supply of Bulk Potable and Non-Potable Water SEQ C 4131 Syran Projects Pty Ltd Supply of Bulk Potable water to Site until Feb 13 SEO C 4127 Sever Hyan Phat Six Ryan Photography P/V Photograph Palm removal & monthly Images SEQ L 4215 Dunckers Pty Ltd Supply of Site Accomodation Cleaning Products SEQ L 4560 Bizfurn Express Supply and Install of office furniture for Prototype SEQ C 4561 Suncoast Water Carriers Fe-Fill 2 x 10000L Water Tanks + 1 Additional Vis SEQ C 4575 Bizfurn Express Supply and Install of office furniture for Prototype SEQ C 4575 Supply and Install of office furniture for Prototype SEQ C 4576 Arnalgamated Pest Control Redback Pest Control to SCUH Site Offices SEQ L 4561 Midmed Supply and Install of examination couch SEQ C 4570 Quality Choice Signs Pty Ltd Hard Hat Stickers SEQ C 4173 Corporate Charges SEQ C 44066						
Coates Hire Operations Pty Ltd Kyana Projects Pty Ltd Supply of Bulk Potable and Non-Potable Water SEQ C 4131 Kyana Projects Pty Ltd Supply of Bulk Potable Water to Site until Feb 13 SEC C 4127 Seve Ryan t/as Rix Ryan Photography Pt/ Photograph Palm removal & monthly Images SEC L 4215 Dunckers Pty Ltd Supply of Site Accommodation Cleaning Products SEQ L 4256 Bizfurn Express Supply and Install of office furniture for Prototype SEQ C 4561 Sincoast Water Carriers Re-Fill 2 x 10000L Water Tanks + 1 Additional Vti SEQ L 4551 Harvey Norman Supply of kitchen fridge and microwave SEQ C 4575 Bizfurn Express Supply and Install of office furniture for Prototype SEQ C 4567 Redback Pest Control to SCUH Site Offices SEQ C 4570 Midned Supply and Install of examination couch SEQ C 4551 Hard Hat Stickers SEQ C 4551 Wirldian Supply and deliver of Mirrors for Prototype SicQ C 4173 Corporate Charges Multi Touch Interactive Whiteboard SEQ C 4006						
Kyana Projects Pty Ltd Supply of Bulk Potable and Non-Potable Water SEQ 4567 Neverfull Springwater Limited Sheptly of Potable Water to Site until Feb 13 SEQ C 4127 Sheve Ryan tras Rix Ryan Photography P/I Photograph Palm removal & monthly images SEQ L 4215 Dunckers Pty Ltd Supply of Site Accommodation Cleaning Products SEQ L 4256 Bizfurn Express Supply and Install of office furniture for Prototype SEQ C 4561 Suncoast Water Carriers Institute 1 x 10000L Water Tanks + 1 Additional Vit SEQ L 4551 Harvey Norman Supply of kitchen fridge and microwave SEQ C 4575 Bizfurn Express Supply and Install of office furniture for Prototype SEQ C 4567 Amelgamated Pest Control Redback Pest Control to SCUH Site Offices SEQ L 4561 Midmed Supply and Install of exemination couch SEQ C 4570 Quality Choice Signs Pty Ltd Heard Hat Sitckers SEQ C 4551 Worldian Supply and deliver of Mirrors for Prototype Side Corporate Charges SEQ C 4173 Corporate Charges Multit Touch Interactive Whiteboard SEQ C 4006					4131	
Neverfall Springwater Limited Shepty of Potable Water to Site until Feb 13 SEQ C 4127 Steve Ryan t/as Rix Ryan Photography P/I Photograph Palm removal & monthly images SEQ L 4215 Dunckers Ry Ltd Supply of Site Accomodation Cleaning Products SEQ L 4560 Bizfurn Express Supply and Install of office furniture for Prototype SEQ C 4561 Suncoast Water Carriers Re-Fill 2 x 10000L Water Tanks + 1 Additional Vit SEQ L 4551 Harvey Norman Supply of kitchen fridge and microwave SEQ C 4575 Bizfurn Express Supply and Install of office furniture for Prototype SEQ C 4557 Amalgamated Pest Control Redback Pest Control to SCUH Site Offices SEQ L 4561 Midmed Supply and Install of exemination couch SEQ C 4570 Quality Choice Signs Pty Ltd Hard Hat Stickers SEQ C 4551 Viridian Supply and deliver of Mirrors for Prototype Side Corporate Charges Multi Touch Interactive Whiteboard SEQ C 4006		Supply of Bulk Potable and Non-Potable Water			4567	
Dunckers Pty Ltd Supply of Site Accomodation Cleaning Products Bizfurn Express Supply and Install of office furniture for Prototype SEQ C 4561 Suncoast Water Carriers IRe-Fill 2 x 10000L Water Tanks + 1 Additional Vit SEQ L 4551 Harvey Norman Supply of kitchen fridge and microwave SEQ C 4575 Bizfurn Express Supply and Install of office furniture for Prototype SEQ C 4557 Arnalgamated Pest Control Redback Pest Control to SCUH Site Offices SEQ L 4561 Midmed Supply and Install of examination couch SEQ C 4570 Quality Choice Signs Pty Ltd Hard Hat Stickers SEQ C 4551 Viridian Supply and deliver of Mirrors for Prototype Suite SEQ C 4551 Multi Touch Interactive Whiteboard SEQ C 4006	Neverfall Springwater Limited	Supply of Potable Water to Site until Feb 13	SEQ	С	4127	
Supply and Install of office furniture for Prototype SEQ C 4561 Suncoast Water Carriers Fie-Fill 2 x 10000L Water Tanks + 1 Additional Vis SEQ L 4551 Harvey Norman Supply of kitchen fridge and microwave SEQ C 4575 Supply and Install of office furniture for Prototype SEQ C 4557 Arnelgamated Pest Control Fiedback Pest Control to SCUH Sits Offices SEQ L 4561 Midmed Supply and Install of examination couch SEQ C 4570 Quality Choice Signs Pty Ltd Field Hat Stickers SEQ C 4551 Supply and deliver of Mirrors for Prototype Suite SEQ C 4551 Supply and deliver of Mirrors for Prototype Suite SEQ C 4173 Corporate Charges Multimedia Technology Multi Touch Interactive Whiteboard SEQ C 4006	Steve Ryan t/as Rix Ryan Photography P/V	Photograph Palm removal & monthly images	SEQ	L	4215	
Suncoast Water Carriers Re-Fill 2 x 10000L Water Tanks + 1 Additional Vis SEQ L 4551 Harvey Norman Supply of kitchen fridge and microwave SEQ C 4575 Bizfurn Express Supply and Install of office furniture for Prototype SEQ C 4557 Arnalgamated Pest Control Redback Pest Control to SCUH Site Offices SEQ L 4561 Midmed Supply and Install of examination couch SEQ C 4570 Causity Choice Signs Pty Ltd Hard Hat Stickers SEQ C 4551 Viridian Supply and deliver of Mirrors for Prototype Suite SEQ C 4173 Corporate Charges SEQ L Multimedia Technology Multi Touch Interactive Whiteboard SEQ C 4006 Viridian Vi	Dunckers Pty Ltd	Supply of Site Accomodation Cleaning Products	SEQ	L	4560	
Harvey Norman Supply of kitchen fridge and microwave SEQ C 4575 Bizfurn Express Supply and Install of office furniture for Prototype SEQ C 4557 Amelgamated Pest Control Redback Pest Control to SCUH Sits Offices SEQ L 4561 Midmed Supply and Install of evarnination couch SEQ C 4570 Quality Choice Signs Pty Ltd Hard Hat Stickers SEQ C 4551 Viridian Supply and deliver of Mirrors for Prototype Suite SEQ C 4173 Corporate Charges SEQ L Multi Touch Interactive Whiteboard SEQ C 4006	Bizfurn Express					
Bizfurn Express Supply and Install of office furniture for Prototype SEQ C 4557 Amalgamated Pest Control SEQ L 4561 Midmed Supply and Install of exemination couch SEQ C 4570 Quality Choice Signs Pty Ltd Hard Hat Stickers SEQ C 4551 Viridian Supply and deliver of Mirrors for Prototype Suite SEQ C 4173 Corporate Charges SEQ L Multi Touch Interactive Whiteboard SEQ C 4006	Suncoast Water Carriers				-	
Arnelgamated Pest Control Redback Pest Control to SCUH Site Offices SEQ L 4561 Midmed Supply and Install of examination couch SEQ C 4570 Quality Choice Signs Pty Ltd Hard Hat Stickers SEC C 4551 Viridian Supply and deliver of Mirrors for Prototype Suite SEQ C 4173 Corporate Charges SEQ L Multi Touch Interactive Whiteboard SEQ C 4006	Harvey Norman	- 117				
Supply and Install of examination couch SEQ C 4570	Bizfurn Express	111				
Quality Choice Signs Pty Ltd Heard Hat Stickers SEQ C 4551 Viridian Supply and deliver of Mirrors for Prototype Suite SEQ C 4173 Corporate Charges SEQ L Multimedia Technology Multi Touch Interactive Whiteboard SEQ C 4006					-	
Viridian Supply and deliver of Mirrors for Prototype Suite SEQ C 4173 Corporate Charges SEQ L Multimedia Technology Multi Touch Interactive Whiteboard SEQ C 4006	Midmed					
Corporate Charges SEQ L Multimedia Technology Multi Touch Interactive Whiteboard SEQ C 4006					,	
Multimedia Technology Multi Touch Interactive Whiteboard SEQ C 4006	Viridian				4173	
	Multimadia Tashatikan				4000	

Attachment C:						
Business Engagement		LIPP Categorisation	Source of	Supply		
Subcentractor	Work ² ackage	SEQ - South East QLD REQ - Regional QLD AUS - Rest of Agstralia	Contestable	PostCode	Goods and	Supplier's location
Shamrock Civil	Bulk Civi! Works Pre-Load	SEQ	L	4076	s.47(3)(pswich
Shadforth Civil Engineering	Cut to Fi!l Civil Works	SEQ	L	4556		Sunshine Coast
Wagstaff Piling	Precast Piling & Shear Piling	SEQ	L	4060		Brisbane Inner City
Beavis & Bartels Pty Ltd	Temp Hydraulics (Site Wide)	SEQ	С	4013		Brisbane - North
Oneform	install Formwork to CP2	SEQ	L	4173		Brisbane - East
East Coast Concrete Contractors	Concrete Place and Finish to CP2	Other States	L	2485		NSW
Delco Steei	Reinforcement Fix to CP2	Other States	С	4178		Brisbane - East
Pro Concrete Pumping	Concrete Pumping to CP2	SEQ	L	4220		Gold Coast
FIP Electrical (Qid) Pty Ltd	Electrical Installation to CP2	SEQ	С	4144		Brisbane !nner City
VT Services	Tower Crane to CP2	SEQ	L	4074		Brispane - West
Taccma Plumbing and Drainage	Hydraulics to CP2	SEQ	С	4573		Sunshine Coast
EVS GROUP AUSTRALIA PTY LTD	PR0059 Site Security	Other States	C /	20 77	^	VSW
UNISPAN AUSTRALIA PTY LTD	644.2.TP0060.01 - CP2 - Scaffolding	SEQ	C	4207	1	Gold Coast
Boral Construction Materials (QLD)	644.2.TP0410.01 - CP2 - Concrete Supply	SEQ	L	4059	/	Brisbane Inner City
OTIS ELEVATOR COMPANY PTY LTD	642.TP.2030.01 - MHB - Vertical Transportation	SEQ		4101	s.47(3)(b)	Brisbane Inner City
OTIS ELEVATOR COMPANY PTY LTD	643.1.TP2030.01 - FMC - Vertical Transportation	SEQ	ر ليم /	4101		Brisbane Inner City
OTIS ELEVATOR COMPANY PTY LTD	643.2.TP2030.01 - MHU - Vertical Transportation	SEQ	(Ce	4101		Brisbane Inner City
OTIS ELEVATOR COMPANY PTY LTD	644.1.TP2030.01 - CP1 - Vertical Transportation	SEQ	\c/	4/101		Brisbane Inner City
Polyseal Waterproofing QLD Pty Ltd	644.2.TP0832.01 - CP2 - Waterproofing	SEQ	c/	4207		Gold Coast
STRUCTURAL SYSTEMS (NORTHERN	644.2.TP0631.01 - CP2 - Post Tensioning	SEQ /		4207		Gold Coast
QLD Drink and Snack Machines	640.PR0022.08 - PRW - Vending Machines - CF	SEQ ((c 7	4559		Sunshine Coast
Regson Fabrications	641.TP1230.01 - CP2 - Façade	SEQ V		4556		Sunshine Coast
Custom Shades Pty Ltd	641.TP1633.00 - CP2 - Shade Structure	SEQ	c	4173		Brisbane - East
Designa Sabar	641.TP2430.01 - Car Park management system	Other States	L	5009		SA
ALS	641.TP1712.01 - Rainwater Tanks to CP2	SEQ/	L	4575		Sunshine Coast
Matchif Blocklaying	544 2 TP0830 01 & 644 1 TP0830 01 - Block or	5%C	L	4559		Sunshine Coast
Wagstaff Piling Old Pty Ltd	641 TP0330.02 - CP1 - Piling	SEQ	L	4060		Brisbane
	644 1 TP1630.01 - CP2 - Mechanical	SEQ	C	4556		Sunshine Coast
Eastcoast Concrete Contractors	Substructure	Other States	С	2485		VSW

Note: Substructure wasn't listed on ICN Gateway website as an opportunity for companies to register through ICN.







A Division of QMI Solutions

Progress Report #13 for period to 30 November 2013 Prepared by Industry Capability Network (Queensland) Ltd

This report details the assistance provided during the above period by ICN (Qld) to Lend Lease in the delivery and implementation of the Local Industry Participation Plan (LIPP) for the Sunshine Coast University Hospital in accordance with the Local Industry Policy (LIP).

1. Liaison with the Project on LIP Issues

ICN met with Queensland Health (Sam Betros) in May 2011 to discuss the project, ICN services, and LIP procedures and issues. ICN assisted QH in the development of the LIPP for the project and provided an evaluation report to QH on project bidders' LIP plan submissions in March 2012.

2. Liaison with Lend Lease on LIP Compliance

Lend Lease met with ICN to establish processes and procedures for management of the project's obligations to the LIP. It was decided that ICN will provide support on number of services covering:

- Implementation of the LIPP (capability searches on contestable packages)
- · Presenting at briefing sessions
- Registering companies via ICN Gateway
- Verification of source of manufacture and service, provision in subcontracts
- Business matching
- Progress reporting (Monthly) and final LIPP Outcomes reporting (at end of project)

3. Tier Barometer

Tier Barometer is an on-line self-assessment tool developed by ICN and the State Government. It provides participating companies with an assessment of their tier level in terms of supply to major projects. The tool is used by the project to analyse the basic capabilities of potential suppliers during the registration process.


4. Contestable Packages

Queensland and Australian capability, content and capacity will be considered for all the work packages. The following activities have been undertaken:

- An ICN officer has been assigned full time to the project.
- Detailed Business Matching has been carried out by ICN. 204 work packages have been managed in this way.
 These are listed at Attachment A.
- 1397 registrations against work packages on Gateway have been received
- 65 early works have been awarded in March. These are listed at Attachment 8.
- 48 work packages have been awarded so far and they are listed at Attachment C.

Potential subcontractors will be given an indication of the size and generic nature of the project, and questioned regarding their capability and capacity to carry out the work, code compliance, and previous work history. Reports will be sent to Lend Lease detailing local companies which have the capability and capacity to carry out the work for each of the above packages. The primary objective of the Local Industry Policy is to ensure that competitive local companies are given full, fair and reasonable opportunity to tender for work packages. This objective will be achieved if the companies nominated by ICN, and other local companies that Lend Lease is aware of, are considered in the establishment of the tender list, and, subject to meeting pre-qualification criteria, a reasonable number of local companies are subsequently invited to tender. Lend Lease intends to apply this requirement.

6. Source of Supply



Lend Lease has advised that out of 113 Purchase Orders, 65 were awarded for early works, one for Substructure and 47 for Work Packages listed on the ICN Gateway Project webpage. These were to companies that registered interest via ICN. As far as practicable, the measurement of industry participation focuses on the actual source of supply rather than the location through which the order is placed. The location in which services are provided, materials manufactured or where value adding takes place is indicative of the actual source of supply. Of the 48 Work Package contracts that have been awarded, 41 were won by South East Queensland (SEQ) companies, five by New South Wales companies, one by Victoria and one by South Australia.

7. Prototype Building

A prototype showcase building was erected in record time. This enabled focus group to provide input in to the final design in a cost effective manner.

8. Local Industry Participation

Lend Lease Project Director has personally provided project work scope and Lend Lease supplier engagement approach information to a number of larger Australian Manufacturers who have asked for more information. These include The GWA Group; The Laminex Group; Spence Doors and Rockcote Industries. For the latter company time was dedicated to a site inspection of their manufacturing facilities.

ICN supported Lend Lease in delivering briefing sessions as proposed in their LIP plan covering:

Monday 3rd September 2012 - Civil, Infrastructure, Structure & Landscaping

Monday 17th September 2012 – Services

Monday 24th September 2012 - Roof & Façade

Monday 8th October 2012 – Fit out & Finishes

Monday 15th October 2012 - Furniture Fittings & Equipment (FF&E)

Lend Lease also presented at the General Briefing Sessions along with ICN on 13, 14, 16 and 20th of August 2012.

Lend Lease project managers attended a briefing presentation by the members of the Cleantech Industries group of companies on 24th September 2012.

Lend Lease took part in a Local Business expo on 10th May 2013.

ICN - Evan Flower - presented to the Gympie Major Project Opportunities/Forum on the project on 18th June 2013.

10. Efforts to engage with Local Companies include:

Press release by Health Minister, radio interviews by Project Director, Newspaper articles in CM and Sunshine Coast Daily followed up by substantial advertisements in the same newspapers on 19th January. Support articles followed from SSC Council and local councillors.

As a result of the above information sessions and the advertising campaign almost 1000 registrations have been received with close to 100 companies listing after the newspaper advertisements.

To date over 1397 companies have registered interest in work packages.

11. Source of Manufacture

As subcontracts begin to be awarded, the source of manufacture or service provision for contestable packages will be validated and verified in discussion with the corresponding subcontractors.

12. Reporting

Business matching reports on companies nominated for the trade packages listed at Attachment A are being provided to Lend Lease.

Evan Flower Senior Consultant - Capability Services ICN Queensland

chment A				
urries Details				
Irryid	Tide	Enquiryid Title	Enquiryed Title	
	PR.0051.01 Crossover Road Construction	94450 640. PR0022.04 - PRW - Site Office Fitout & Furniture		TP1531.01 - FMC - Hardware - S
	TP.0231.01 Preload	94506 640.PR0056.02 - PRW - Site Office Cleaning		2.3030.01 - MHB - Painting
	TP.0320.01 Sediment control	94527 643.1.TP0410.01 - FMC - Concrete Supply		TP2630.01 - FMC - Ceilings and
	PRO059 Site Security	94534 643.1.TP0420.01 - FMC - Concrete Place 94536 643.1.TP0422.01 - FMC - Concrete Pumping		TP 1911.01 - CP2 - Door and Fran TP 2930.01 - MHU - Internal Glaz
	644.2.TP1732.01 - CP2 - Hydraulics 644.2.TP0620.01 - CP2 - ReInforcement Flxing	94537 643.1,TPO431.01 - FMC - Concrete Pumping		TP3030.01 - MHU - Painting
	944.2.TP0530.01 - CP2 - Reinforcement Fixing	94538 643.2,TP0410.01 - MHU - Concrete Supply		TP3030.01 - FMC - Painting
	644.2.TP0422.01 - CP2 - Concrete Pumping	94539 643.2.TP0420.01 - MHU - Concrete Placing		TP2630.01 - MHU- Ceilings and
	644.2.TP0420.01 - CP2 - Concrete Placing	94540 643.2,TP0422.01 - MHU - Concrete Pumping		TP263D.01 · CP1 - Ceilings and F
	644.2.TPO410.01 - CP2 - Concrete Supply	94541 644.1.TP0410.01 - CP1 - Concrete Supply		.3131.01 - MHB - Mature Trees
	644.2.TP0050.01 - CP2 - Scaffolding	94542 644,1,TP0420.01 - CP1 - Concrete Place		3131.01 - CP2 - Soft/Hard Lands
	645.TP3230.01 - Kawana Way Duplication	94543 644.1.TP0422.01 - CP1 - Concrete Pumping	97728 642 TE	2.2720.01 - MHB - Carpet Laying
	641.TP.0230.01 - RIE - Bulk Earthworks and Fill	94627 643.1.TP0060.01 - FMC - Scaffolding		-1311.01 - MHB - Doors Supply
	641_TP.3230.01 - RIE - Roads & Infrastructure Services	94628 644.1.TP0060.01 - CP1 - Scaffolding		.2734.01 - MHB - Epoxy Floorin
	644.2.TP2239.01 - CP2 - Carpark Control System	94884 642.TP.0830.01 - MHB - Blockwork		pportunities - General Clean
	640.PR0033.01 - PRW - Temporary Hydraulics	94885 643.1.TP0830.01 - FMC - Blockwork		.1434.01 - MHB - Workstations
	640. PR0056.01 - PRW - Rubbish Removal	94886 643.2.TP0830.01 MHU - Blockwork		1532.01 - MHB - Signage
	644.2.TP0832.01 - CP2 - Waterproofing	94887 644.1.TP0830.01 - CP1 - Blockwork		TP1311.01 - CP1 - Door and Fran
	644.2.TP2330.01 - CP2 - Electrical	94907 640.PR0054.01 - PRW - Site Photography		TP1311.01 - FMC - Door Supply
	640.PR0042.01 - PRW - Tower Cranes, Hoists & Crews	94959 644.2.TP3030.01 - CP2 - Painting & Line Marking		2.2732.02 - MHB - VInyl
	644.2.TP0631.01 - CP2 - Post Tensioning	94960 644.1.TP3030.01 - CP1 - Painting & Line Marking		TP2732.02 - CP1 - Vinyl Installat
	642.TP.2030.01 - MHB - Vertical Transportation	94987 644.2.TP1030.01 - CP2 - Structural Steelwork		TP1330.01 - CP1 - General Carp
	643.1.TP2030.01 - FMC - Vertical Transportation	95031 644.1.TP1030.02 - CP1 - Structural Steelwork		TP1330.01 - FMC - Door & Hard
	643.2.TP2030.01 - MHU - Vertical Transportation	95033 642.TP.2230.01 - MHB - Building Maintenance Unit		.2711.01 - MHB - Floor Mats
93296	644.1.TP2030.01 - CP1 - Vertical Transportation	95101 643.2.TP1631.01 - MHU - Roofing Built-up / Membrane		2.2731.01 - MHB - Insitu Floor C
	640.PR0041.01 - PRW - Mobile Cranes	95111 642 TP.1630.01 - MHB - Roof & Metal Cladding		.2735.01 - MHB - Tactile Indica
	644,2,TP1830.01 • CP2 • Mechanical	95112 642 TP, 1636.01 - MHB - Wall Q adding 5 stems		2830.01 - MHB - Tiling
	644.2.TP1712.01 - CP2 - Water Tanks	95121 642.TP.1032.01 - MHB - Facad Framing		TP2720.01 - FMC - Carpet Instal
	640.PR0021,02 - PRW - Site Fencing	95122 642 TP.1132.01 - MHB - Shop Fronts		.1433.03 - MHB - Furniture - 5e
	640.PR0045.01 - PRW - Temporary Plant & Equipment	95123 642.TP.1135.02 - MHB - Sunshades & Light Shelves		.1433.02 - MHB - Medical Furn
	640.PRO022.06 - PRW - Temporary Onsite Canteen and Catering Services	95124 642.TP.1131.01 - MHB - Metal Windows		.2737.01 - MHB - Wall Protecti
	640.PR(XX22.05 - PRW - Temporary Carpentry Site Accommodation Areas	95193 642.TP.1631.01 MHB- Roofing-Built-up / Membrane		.1433.04 - MHB - Compactus U
	644.1.TP0530.01 - CP1 - Formwork	95318 642.TP.1712.01 - MHL - Tanks & Pamps Supply		TP2732.02 - FMC - Vinyl Install
	642.TP.0530.01 - MHB - Formwork	95319 643.2,TP1710.01 MAU San taryware & Tapware Supply		.1533.01 - MHB - Whitegoods
	643.2.TP0530.01 - MHU - Formwork	95324 642.TP.1732.02 - MHB - Sanitasparare & Tapware Supply		TP 1533.01 - MHU - Whitegoods
	643.1.TP0530.01 - FMC - Formwork	95369 642.TV 1231.01 - NN8 - Balustrades & Handrails		TP1520.01 FMC - Hardware &
	643.1.TP2310.01 - FMC - Site Wide HV Equipment Supply Only	95376 647.TP.1230.61 - MHS - Metalwork		TP2239.01 - CP1 - Carparking Co
	642.TP2335.02 - PRW - UnInterruptable Power Supply Units (UPS) & Maintenance	95392 642.TP 1235.91 - MHD - Metal Louvres		TP2720.01 - MHU - Carpet Layin
	644.1TP0330.02 - CP1 - Pile Cut-off	95411 642.TP. 232.01 MHI - Movement Joints		.3530.01 - MHB - Temporary Ca
	643.2.TP0330.02 - MHU- Pile Cut-off	5436 643 2.TP 163001 - FMC - Boof Metal Sheeting		.1432.01 - MHB - Curtains & Bli
	643.1.TP0330.02 - FMC - Pile Cut-off	95427 643.1.781636.01 - FMC Facade Cladding		TP1432.01 - MHU - Curtains & B
	642.TP.0330.03 - MHB - Sheet Piling	\$5428 643.3 TP1032-91 - FMC - Facade Framing	00302 07002	THE COLUMN
	642.TP.0330.02 - MHB - Pile Cut-off	95429 642.TP.1080.01 - MHB - Structural Steelwork		
	643.1.TP0330.09 - FMC - Sheet Pilling	95432 643.1 TP1135.01 - FMC - Sunshades and Light Shelves		
	644.1.TP0620.01 - CP1 - Reinforcement Fix	95455 843.1.TP 812.02 - FMC - Mechanical Services - Chiller Supply	-	
	642.TP.0620.01 - MHB - Reinforcement Fix	95456 643 LTP1810.03 - FMC - Mechanical Services - Cooling Tower S	ennly	THE PERSON NAMED IN THE PERSON NAMED IN
	642.TP.0631.01 - MHB - Post Tensioning	95457 643.1 TP1810.04 - FMC - Mechanical Services - AHU Supply		- announcement of the coupy pools
	643.1.TP0620.01 - FMC - ReInforcement Fix	95458 643 TP1810.01 - FMC - Mechanical Services - Tanks		
	643,1,TP0631,01 - FMC- Post Tensioning	95-80 647 1.TP1231_01 - FMC - Balustrades & Handralls		THE RESERVE THE PERSON NAMED IN COLUMN 2 I
	643,2,TP0620,01 - MHU - Reinforcement Fix	95543-643.1.TP1235.01 - FMC - Metal Louvres		
	644.1.TP0631.01 - CP1 - Post Tensioning	95555 643.1.TP1432.01 - FMC - Curtains & Blinds		the second of th
	540.PRQ05Z.01 - PRW - Safety Precautions (PPE)	95576 643.1.TP1230.01 - FMC - Metalwork		
	642.TP.0832.01 - MHB - Waterproofing Inground	95588 643.1.TP1030.01 - FMC - Structural Steelwork		
	642.TP.0832.02 - MHB - Waterproofing Roofs & Decks	95592 643.1.TP2236.01 - FMC - Kitchen / Laundry Equipment	 	
	642.TP.0832.03 - MHB - Temporary Waterproofing	95686 642.TP.1637.01 - MHB - Cool rooms & Cleanrooms		
	643.1.TP0832.01 - FMC - Waterproofing & Tanking	95687 643.1.TP1697.01 - FMC - Coolrooms & Cleanrooms		
	643.1.TP3832.01 - FMC - Waterproofing & Tanking - Roofs & Decks	95699 644.1.TP1630.01 - CP1 - Roofing	- 1	
	643.2.TP0832.01 - MHU - Waterproofing & Tanking - Roots & Decks	95700 643.2.TP1630.01 - MHU - Roofing & Metal Cladding	 	THE RESERVE OF THE PARTY OF
	644.1.TP0832.01 - CP1 - Waterproofing	95701 643,2,TP1636.01 - MHU - Wall Cladding Systems		a Martine and a classic Promotion and a second and a second
	642.TP2335.01 - PRW - Site Wide LV Egitigment Supply	95707 643.1.TP1131.01 - FMC - Metal Windows		
	641.TPO410.01 - RIE - Concrete Supply	95777 644.1.7P1131.01 - CP1 - Facade / Streens		
			 	
	542.TP.0420.01 - MHB - Concrete Place & Finish CP1.TP2335.01 - CP1/CP2 - Light Fitting Supply	95778 643.2.TP1032.01 - MHU - Facade Framing 95902 644.1.TP1235.01 - CP1 - Metal Louvres	. ,,	pro region a spengermangermange appropria
	640.PR0033.03 - PRW - Temporary Hydraulis-Site Wide Reticulation	95906 643.2 TP1131.01 - MHU - Metal Windows		
	641.7P1732.01 - RIE - Water & Fire Mains reticulation	96073 644.2.TP0057.01 - CP2 - Final Clean	 	
	642,TP.0422.01 - MHB - Concrete Pumping	96151 643.2.TP1135.01 - MHU - Sunshades & Light Shelves		
	643,1.TP2312.01 - FMC - HV Generator Supply	96159 643.2.TP1230.01 - MHU - Metalwork		and the state of the second section of the section of the second section of the section of the second section of the s
		96169 643.2.TP1235.01 - MHU - Metal Louvres		remark removale as any limited in section
94256	642.TP.0431.01 - MHB - Pressst Concrete 644.2.TP0830.02 - CP2 - Blockwork		 	• •
		96177 643.1.TP2235.01 - FMC - Dock Levelers		
94272	640.PR0032.92 - PRIV - Main Site Office & Accommodation Temporary Electrical	96509 644.1TP1230.03 - CP1 - General Metalwork		- proceedings on experience appropriate of the control of the cont
	640.PR003.02 - RW - Tempor or Lunch Sheds / Ablutions / Containers / Other Sheds	96695 643.2.TP3590.01 - MHU - Temporary Carpentry	- 1	
	642.TP_8050.01 -MHB - 5taffolding	96944 642.TP_1330.01 - MHB - General Carpentry 97023 642.TP_1433.01 - MHB - Furniture		
94285	CALL THE COLUMN CALL COLUMN CALL COLUMN CALL CALL CALL CALL CALL CALL CALL CAL		1	
94285 94320	644.2.TP 131.01 · CP2 - Facade / Screens		****	
94285 94320 94353	644.2.TP1330.01 CP2 - General Carpentry	97037 642.TP.1236.01 - MHB - Roller Shutters		
94285 94320 94353 94362	644.2 P. 134.0.1 - CP2 - Fager / Screens 644.2 P.1330.0b CP2 - General Carpentry 640.PR0022.07 - PRIM- Pest Control 640.PR0023.03 - PRIM- Tengorary Ste Signage			

Attachment B		Waller III and		,	
Business Engagement		LPP Categorisation	Source of Supply		
Supportractor	Region	SEQ - Booth East QLD REQ - Regional QLD	C- Contastable L - Local	PostCode	Values of
· · · · · · · · · · · · · · · · · · ·		AUS - Rest of Australia	L-total		Goods or
		IMP - Imposed			Services supplied
Dulliament Stanlage & Server Direct and	Modular Prototype Suite	AUS	С	2250	s.47(3)(
Bullismart Modular Mining Pty Ltd Shadforths Civil Pty Ltd	CP2 Early Works	SEQ	L	4556	5.47(5)(
Wagstaff Piling QLD Pty Ltd	Test Pling	SEQ	Ĺ	4060	
EVS Group Australia Pty Ltd	Site Security	SEQ	L	4350	
Nilsen CLD Pty Ltd	Temporary Electrical CP2 & Prototype	SEQ	С	4170	
Calty Constructions	Protoype Marketing Rigging and Marketing Deck	SEQ	L	4556	
Blue Glue Pty Ltd	Blue Glue	AUS	L	2113	
Kyana Pty Ltd	Temporary Hydrautics	SEQ	С	4567	
Gordon Clements Nominees Pty Ltd T/A Calty Constructions	Covered Walkways and paths	SEQ	L	4556	
Wagstaff Piling	Site Probing Works - 55 Probe Locations	SEQ	. L	4060	
Quality Choice Signs	Re skin to existing Billboard	SEQ	c	4575	
Fencepac	Site Perimeter Security Fence - Stage 1 SCUH - Nambour Site	SEQ	c	4556 4119	
Fredon QLD Pty Limited	Crossover road Construction	SEQ	- /	4556	
Shadforths Discount Cable Landing Disclare	Detect inground services prior to digging fence	SEQ SEQ	//(c)	4553	
Underground Pipe and Cable Location Pty Ltd O2 Environmental Pty Ltd	Environmental and Sediment Monitoring	SEQ		4573	
Shadforths	Supply & replace Road Base - Site Accommodati		7	4556	
Calty	Prototype Building Foundations	SEQ		4556	
Scapeshape Pty Ltd	Paimtree re-location	SEQ (L	4211	
D&J Services	Site Shed Cleaning	ska) 	4011	
Floor cover QLD - AK	Installation of vinyl and carpet to the Prototype Su		C		
Quality Choice Signs	Signage	SEC	С	4575	
The trustee for The SJ & DY Eade Family Trust T/A Vismark	Supply and Install shade cloth to SCUH Site	SĘQ	Ç	4570	
Regson Fabrication	Suppy & Install 2 Gate Closures	(s∉a /	С	4556	
Orange Hire Pty Ltd	Supply & Hire of Perlmeter Fencing	\$EQ	L	2760	
Transpacific Industries Pty Ltd	Site Sewerage Tank Pump Out	SEQ	С	4064	
Universal Cranes Sunshine Coast Pty Ltd	Mobile Crane Hire	SEQ	L	4556	
Siemens	Prototype Security	IMP	С	4006	
Merion (t/a Statewide Communications)	Prototype Nurse Call & PES	AUS	С	4113	
Ken Wilson & Associates Pty Ltd T/a KWA Blinds	Prototype Curtain & IV Tracks	SEQ	С	4163	
Coates Hire Operations Pty Ltd	Portable toilets	SEQ	L	4131	
Energex Limited	Energex Detailed Design	SEQ	L	4558 4000	
ATF Sunshine Coast and Total Site Set Up	Supply & Install crowd control barriers Provide traffic Controller	SEQ SEQ	C L	4558	s.47(3)(b)
Evolution Traffic Control	Video conversions from AVI to MWV4 You lube	AUS	C	4014	5.47 (3)(b)
Lucid Edge PTY LTD Worklwide Online Printing Market Street	Masterplan Poster	SEQ	L	4000	
Lucid Edge PTY LTD	Video Conversions from AVI to MWV	AUS	c	2010	
Combined Security Services	Security Guards	SEQ	Ľ	4575	
DLA Piper	Professional fees	AUS	ī	4000	
Greenbins	Size 8 Sin	SEQ	L	4074	
Metro Express	2 Containers Sent from GCUH to SCUH	SEQ	L	4106	
Trumpf Med Australia Pty Ltd	3x3 Combination light set & Trumpf Serv	IMP	С	2067	
Arjohuntleigh	Medical Beds and Patient Lifting System	IMP	C	6163	
Arunta Plastics (QLD) Pty Ltd	Cultural Heritage Induction	SEQ		3134	
G James /	Supply and install of windows and external doors	SEQ	L	4556	
ATF Services Pty Ltd	Temp Fencing	SEQ	L	4558	
Rebotic Automation Group	AGV Advisory Services	AUS	С	2127	
Energy Crane Services Pty	Transport Items to SCUH site	SEQ	L	4034	
Energex Limited	Temporary Electrics supply South	SEQ	L	4006	
Spence Door	Supply doors and frame	SEQ	L	4556	
Coates Hire Operations Pty Ltd	Daniel Bull, Daniel and Mr. D. (1) (1)	SEQ	С	4131	
Kyana Projects Pty Ltd	Supply of Bulk Potable and Non-Potable Water	SEQ		4567	
Neverfall Springwater Limited	Supply of Potable Water to Site until Feb 13 Photograph Palm removal & monthly images	SEQ	C	4127 4215	
Steve Ryan t/as Rix Ryan Photography P//	Supply of Site Accommodation Cleaning Products	SEQ SEQ	L ,	4215 4560	
Dunckers Pty Ltd	Supply and Install of office furniture for Prototype		C	4561	
Bizfurn Express Suncoast Water Carriers	Re-Fill 2 x 10000L Water Tanks + 1 Additional Vi			4551	
Harvey Norman	Supply of kitchen fridge and microwave	SEQ	C	4575	
Bizfurn Express	Supply and Install of office furniture for Prototype		č	4557	
Amalgamated Pest Control	Redback Pest Control to SCUH Site Offices	SEQ	L	4561	
Midmed Pest Control	Supply and install of examination couch	SEQ	C	4570	
Quality Choice Signs Pty Ltd	Hard Hat Stickers	SEQ	Č	4551	
Viridian	Supply and deliver of Mirrors for Prototype Suite	SEQ	c	4173	
	Corporate Charges	SEQ	Ĺ		
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				
Multimedia Technology	Multi Touch Interactive Whiteboard	SEQ	С	4006	

Attachment C						
Business Engagement		LIPP Categorisation	Source of	Supply .		
Subcontractor	WorldPackage	SEQ - South East QLD REQ - Regional QLD	Contestable	PostCode	Values of Goods and Services	Supplier's location
Shamrock Civil	Bulk Civil Works Pre-Load	SEQ	L	4076	s.47(3)(b)	Ipswich
Shadforth Civil Engineering	Cut to Fill Civil Works	SEQ	L	4556	` ' ' '	Sunshine Coast
Wagstaff Piling	Precast Piling & Shear Piling	SEQ	i L	4060		Brisbane Inner City
Beavis & Bartels Pty Ltd	Temp Hydraulics (Site Wide)	SEQ	C	4013		Brisbane - North
Oneform	Install Formwork to CP2	SEQ	L	4173		Brisbane - East
East Coast Concrete Contractors	Concrete Place and Finish to CP2	Other States	L	2485		NSW
Delco Steel	Reinforcement Fix to CP2	Other States	С	2000		NSW
Pro Concrete Pumping	Concrete Pumping to CP2	SEQ	į L	4220		Gold Coast
FIP Electrical (Qld) Pty Ltd	Electrical Installation to CP2	SEQ	C	4144		Brisbane Inner City
VT Services	Tower Crane to CP2	SEQ	L	4074		Brisbane - West
Tacoma Plumbing and Drainage	Hydraulics to CP2	5EQ	i c	4573		Sunshine Coast
EVS GROUP AUSTRALIA PTY LTD	PR0059 Site Security	Cither States	Ċ	2077		NSW
UNISPAN AUSTRALIA PTY LTD	644.2.TP0060.01 - CP2 - Scaffolding	SEQ	С	4207		Gold Coast
Boral Construction Materials (QLD)	644.2.TP0410.01 - CP2 - Concrete Supply	SEQ	i i	4059		Brisbane Inner City
OTIS ELEVATOR COMPANY PTY LTD	642.TP.2030.01 - MHB - Vertical Transportation	SEQ	l c	4101	/ /\	Brisbane Inner City
OTIS ELEVATOR COMPANY PTY LTD	643.1.TP2030.01 - FMC - Vertical Transportation	SEQ	c	4/101/	 { 	Brisbane Inner City
OTIS ELEVATOR COMPANY PTY LTD	643.2.TP2030.01 - MHU - Vertical Transportation	SEQ	l c	4101	ו ו	Brisbane Innar City
OTIS ELEVATOR COMPANY PTY LTD	644.1.TP2030.01 - CP1 - Vertical Transportation	SEQ	CT	4101		Brisbane Inner City
 :	644.2.TP0832.01 - CP2 - Waterproofing	SEQ	/ 1/ -	4207		Gold Coast
Polyseal Waterproofing QLD Pty Ltd	644,2.TP0631.01 - CP2 - Post Tensioning	SEQ	//	4207		Gold Coast
STRUCTURAL SYSTEMS (NORTHERN) PTY LTD	640.PR0022.08 - PRW - Vending Machines - CP2	SEQ	10 c	4569		Sunshine Coast
QLD Drink and Snack Machines	841.TP1230.01 - CP2 - Facade	SEQ		4556		Sunshine Coast
Regson Fabrications	[641.TP1633.00 - CP2 - Shade Structure	SEQ		4173		Brisbane - East
Custom Shades Pty Ltd		Citing States	<u> </u>	5009		SA SA
Designa Sabar	641.TP2430.01 - Car Park management system	(EC)	17	4575		Sunshine Coast
ALS	641.TP1712.01 - Rainwater Tanks to CP2	1->//) m	4559	s.47(3)(b)	Sunshine Coast
Matchit Blocklaying	644.2.TP0830.01 & 644.1.TP0830.01 - Blockwork CI	SEQ	/):	4060	(-)(-)	Brisbane
Wagstaff Piling Old Pty Ltd	641.TP0330.02 - CP1 - Piling	SES	1 c	4556		Sunshine Coast
Sunshine Coast Air Conditioning Services	644.1.TP1830.01 - CP2 - Mechanical					NSW Coast
Eastcoast Concrete Contractors	Substructure	$10/\Lambda$	С	2485		11211
Gordon Clements Nominees Pty Ltd T/A Calty Construct			L	4556		Sunshine Coast
Able Security Group	641.TP1510.01 - CP2 - Door Hardware Supply	(SE)	L	4575		Sunshine Coast
Slemens	641.TP2430.01 - CP2 - Security	Other States	С	3153		VIC
Fredon Electrical	641.TP2530.01 - CP2 - ICT	SEQ	С	4119		Logan - Beaudesert
Wagstaff Piling Old Pty Ltd	643.1.TP0330.02 - FMC - Precast Piling	SEQ	L	4060		Brisbane Inner City
ASP Piling Pty Ltd	643.1.TP0330.01 - FMC - Sheet Piling	SEQ	L	4214		Gold Coast
Manly Concrete	643.1.TPD420.01 - FMC - Concrete Plaging	SEQ	L	4173		Brisbane - East
Onestee	643.1.TP0410.01 - FMC - Reo Supply	SEQ	L	4108		Brisbane - South
Bosform Ptv Ltd	643.1,TP0530.01 - FMC Formwork	SEQ	L	4207		Gold Coast
Delco Steel Old Pty Ltd	643.1.TP0620.01 - FMC - Reinforcement Fixing	Other States	L	2000		NSW
A1 Waterproofing & Applications Pty Ltd	643.1.TP0832.01 FMQ - Waterproofing	SEQ	1	4165		Brisbane - East
	MHB Precast	SEQ	C	4215		Gold Coast
Coastcrete	Blockwork	SEQ	1	4559		Sunshine Coast
Matchett		SEQ	C	4339		Brisbane - East
A1 Waterproofing	In ground Waterproofing			4165		Sunshine Coest
640 TP3491-04 GP2 + Senducioping	Panidide		L	3		
840 TP1532 01 - CP2 - Signage	Premier Signs	SEQ	С	4108		Brisbane - South
840 TP1230 01 - CP2 - General Metalwork	Regison Fabrications	SEQ	С	4556		Sunshine Coast
640 TP2030 01 CP2 - Painting	Amalgameted Painting	SEQ	С	4214		Gold Coast
Eastcoast Concrete Contractors	MHB Substructure, incl Pile trimming	Cither States	С	2485		NSW

Note: Substructure wasn't listed on ICN Gateway website as an opportunity for companies to register through ICN.





A Division of QMI Solutions

Progress Report #15 for period to 31 January 2014 Prepared by Industry Capability Network (Queensland) Ltd

This report details the assistance provided during the above period by ICN (Qld) to Lend Lease in the delivery and implementation of the Local Industry Participation Plan (LIPP) for the Sunshine Coast University Hospital in accordance with the Local Industry Policy (LIP).

1. Liaison with the Project on LIP Issues

ICN met with Queensland Health (Sam Betros) in May 2011 to discuss the project, ICN services, and LIP procedures and issues. ICN assisted QH in the development of the LIPP for the project and provided an evaluation report to QH on project bidders' LIP plan submissions in March 2012.

2. Liaison with Lend Lease on LIP Compliance

Lend Lease met with ICN to establish processes and procedures for management of the project's obligations to the LIP. It was decided that ICN will provide support on number of services covering:

- Implementation of the LIPP (capability searches on contestable packages)
- Presenting at briefing sessions
- Registering companies via ICN Gateway
- Verification of source of manufacture and service provision in subcontracts
- Business matching
- Progress reporting (Monthly) and final LTPP Outcomes reporting (at end of project)

3. Tier Barometer

Tier Barometer is an on-line self-assessment too developed by ICN and the State Government. It provides participating companies with an assessment of their tier level in terms of supply to major projects. The tool is used by the project to analyse the basic capabilities of potential suppliers during the registration process.


4. Contestable Packages

Queensland and Australian capability, content and capacity will be considered for all the work packages. The following activities have been undertaken:

- An ICN officer has been assigned full time to the project.
- Detailed Business Matching has been carried out by ICN. 255 work packages have been managed in this way.
 These are listed at Attachment A.
- 1437 registrations against work packages on Gateway have been received
- 65 early works have been awarded in March. These are listed at Attachment B.
- 56 work packages have been awarded so far and they are listed at Atrachment C

Potential subcontractors will be given an indication of the size and generic nature of the project, and questioned regarding their capability and capacity to carry out the work, code compliance, and previous work history. Reports will be sent to Lend Lease detailing local companies which have the capability and capacity to carry out the work for each of the above packages. The primary objective of the Local Industry Policy is to ensure that competitive local companies are given full, fair and reasonable opportunity to tender for work packages. This objective will be achieved if the companies nominated by ICN, and other local companies that Lend Lease is aware of, are considered in the establishment of the tender list, and, subject to meeting pre-qualification criteria, a reasonable number of local companies are subsequently invited to tender. Lend Lease intends to apply this requirement.

6. Source of Supply



Lend Lease has advised that out of 113 Purchase Orders, 65 were awarded for early works, one for Substructure and 55 for Work Packages listed on the ICN Gateway Project webpage. These were to companies that registered interest via ICN. As far as practicable, the measurement of industry participation focuses on the actual source of supply rather than the location through which the order is placed. The location in which services are provided, materials manufactured or where value adding takes place is indicative of the actual source of supply. Of the 56 Work Package contracts that have been awarded, 45 were won by South East Queensland (SEQ) companies, one by Regional Queensland, eight by New South Wales companies, one by Victoria and one by South Australia.

7. Prototype Building

A prototype showcase building was erected in record time. This enabled focus group to provide input in to the final design in a cost effective manner.

8. Local Industry Participation

Lend Lease Project Director has personally provided project work scope and Lend Lease supplier engagement approach information to a number of larger Australian Manufacturers who have asked for more information. These include The GWA Group; The Laminex Group; Spence Doors and Rockcote Industries. For the latter company time was dedicated to a site inspection of their manufacturing facilities.

ICN supported Lend Lease in delivering briefing sessions as proposed in their LIP plan covering:

Monday 3rd September 2012 - Civil, Infrastructure, Structure & Landscaping

Monday 17th September 2012 - Services

Monday 24th September 2012 - Roof & Facade

Monday 8th October 2012 - Fit out & Finishes

Monday 15th October 2012 – Furniture Fittings & Equipment (FF&E)

Lend Lease also presented at the General Briefing Sessions along with ICN on 13, 14,16 and 20th of August 2012.

Lend Lease project managers attended a briefing presentation by the members of the Cleantech Industries group of companies on 24th September 2012.

Lend Lease took part in a Local Business expo on 10th May 2013.

ICN - Evan Flower - presented to the Gympie Major Project Opportunities Forum on the project on 18th June 2013.

10. Efforts to engage with Local Companies include:

Press release by Health Minister, radio interviews by Project Director, Newspaper articles in CM and Sunshine Coast Daily followed up by substantial advertisements in the same newspapers on 19th January. Support articles followed from SSC Council and local councillors.

As a result of the above information sessions and the advertising campaign almost 1000 registrations have been received with close to 100 companies listing after the newspaper advertisements.

To date over 1437 companies have registered interest in work packages.

11. Source of Manufacture

As subcontracts begin to be awarded, the source of manufacture or service provision for contestable packages will be validated and verified in discussion with the corresponding subcontractors.

12. Reporting

Business matching reports on companies nominated for the trade packages listed at Attachment A are being provided to Lend Lease.



Evan Flower
Senior Consultant - Capability Services
ICN Queensland

O
ø
Õ,
8
o.

ocal Industry Particic Attachment A: Enquiries Detai	Local Industry Participation, Sunshine Coast University Hospital: Progress Repon Attachment A: Enquiries Details	Report January 2014	ily 2014 page 5	0	
F	Title	Enguiryid	Title	Enguiryid	TITLE
- 1					Supply
ΨĮ	644.2.TP2330.01 - CP2 - Electrical	94907	640.PR0054.01 - PRW - Site Photography	98155	643.1.TP1311.01 - FMC - Door Supply
پ ب	640.PR0042.01 - PRW - Tower Cranes, Hoists & Crews	94959	644.2.TP3030.01 - CP2 - Painting & Line Markins	98336	MIN - WING - CO CEZZ OT CBA
1		/	644.1.TP3030.01 - CP1 - Painting & Line	2000	(Aux - Clust - 7070 /7
40	644.2.TP0631.01 -CP2 - Post Tensioning	>94960	Marking	98348	644.1.TP2732.02 - CP1 - Vinyl Installation
		7	644.2.TP1030.01 - CP2 - Structural		644.1.TP1330.01 - CP1 - General
ا جه	642.TP.2030.01 - MHB - Vertical Transportation	94987	Steelwork	98352	Carpentry
œ	643.1.TP2030.01 - FMC - Vertical		644.1.TP1030.02 - CP1 - Structural		643.1,TP1330.01 - FMC - Door &
— !	Transportation	95031	Steelwork	98354	Hardware Fixing
Ф	643.2.TP2030.01 - MHU - Vertical	>	642.TP.2230.bt - MHB - Building		
_;	Transportation	95033	Maintenance Unit	98468	642.TP.2711.01 - MHB - Floor Mats
			643.2 TR1631.01 - MHU - Roofing-Built-up/		642.TP.2731.01 - MHB - Jusity Floor
_,	644.1.TP2030.01 - CP1 - Vertical Transportation	95101	Membrane	98473	Coverings
	640. PR0041.01 - PRW - Mobile Cranes	95111	642.TR.1630.01 MHB-Roof & Metal Cladding	98477	642,TP,2735,01 - MHB - Tactile Indicators
,			642.TP.1636.81 - NHB- Wall Cladding		
-	644.2.TP1830.01 - CP2 - Mechanical	95112	Systems	98495	642.TP.2830.01 - MHB - Tiling
	644.2.TP1712.01 - CP2 - Water Tanks	95121	642.TP.1032.01 - MHB - Facade Francing	98500	643.1.TPZ720.01 - FMC - Carpet Install
	640.PR0021.02 - PRW - Site Fencing	95122	642.TP.1132.01 - MHB - Shop Fronts	98585	642.TP.1433.03 - MHB - Furniture - Seating
	640.PR0046.01 - PRW - Temporary Plant &		642.TP.1135.02 - MHB - Sunshades & Light	(642.TP.1433.02 - MHB - Medical
	Equipment	95123	Shelves	7 68086	Furniture
	640.PR0022.06 - PRW - Temporary Onsite				
- 1	Canteen and Catering Services	95124	642.TP.1131.01 - MHB - Metal Windows	98683/	642, TP 2737.01 - MHB - Wall Protection
-	640.PR0022.05 - PRW - Temporary Carpentry		642.TP.1631.01 - MHB - Roofing-Built-up/	ン 	64x TP/1433.04 - MHB - Compactus
ורט	Site Accommodation Areas	95193	Membrane	98706	Unites
بري	644.1.TP0530.01 - CP1 - Formwork	95318	642.TP.1712.01 - MHB - Tanks & Pumps Supply	98794	642.1 TD2727.07 . EMC . Vind hotell
7	Commence of the personal of th	7777	Addas	30/34	043.1.1PZ/32.62 - FIVIC - VIIIVIIISLAN

Local Industry Particip Attachment A: Enquiries Deta	Local Industry Participation, Sunshine Coast University Hospital: Progress Report January 2014	Report Janua	rv 2014 page 5	ď	
Attachn Enquirie				,	
Enquiri	nent A:				
](Enguirxir	Enquiries Details				
	d Title	Enguinzid	Title	Enguiryid	Title
93520	642.TP.0530.01 - MHB - Formwork	95319	643.2.TP1710.01 - MHU - SANITALYWATE & TAPWATE Supply	98820	642.TP.1533.01 - MHB - Whitegoods
л			642.TP.1732.02 - MHB - Sanitaryware &		
93521	643.2.TP0530.01 - MHU - Formwork	95324		98821	643.2.TP1533.01 - MHU - Whitegoods
2588 [/1]	643.1.TP0530.01 -FMC-Foggwork	95369	642.TP.1231.01 - MHB - Balustrades & Handrails	98843	643.1.TP1520.01 - FMC - Hardware & FFE Fixing
٥٩	643.1.TPZ310.01 - FMC - Site Wide HV	2			644.1.TP2239.01 - CP1 - Carparking
93544	Equipment Supply Only	95376/	642.TP.1230.01 - MHB - Metalwork	98993	Control Systems
	642.TP2335.02 - PRW - Uninterruptable Power	DE MORA	AT THE STATE OF THE PARTY OF THE STATE OF TH	[]	
)(Supply Units (UPS) & Maintenance	76865	642, P.1235.01 - MHB - Metal Louyres	76686	643.2.TPZ720.01 - MHU - Carpet Laying
03756	644 1 TD0330 02 -CD1 - Dile Cut-off	95,011	562 TD:1222 ft - MIUR - Markement lointe	00013	642.TP.3530.01 - MHB - Temporary
<u>ം</u>		- Total	643 1 IDI 638 01 - EMC - Boof Matal	77055	Kan To 1400 64 Adub Cudwing 9
93565 Do	643.2.TP6330.02 - MHU- Pile Cut-off	95426	Sheeting	89066	Blinds
cum	643 1 TD0330 02 - EMC - Dila Cut-off	95477	642 1 Toriginal End. End.	5 100	643.2.TP1432.01 - MHU - Curtains & Diesele
	642 TD 6220 62 - MHB - Shoot Diling	05/100	642 1 10102 01 CAM Document	7777	EAS 3 TRO724 At MAIN COMMITTEE STATES
-	950 - 1175 - 117	27450		73.5TO	CHOST INTO - CHONA FIDORING
89268	642.TP.0330.02 - MHB - Pile Cut-off	95429	Steelwork	99219	643.1.TP2731.01 - FMC - Epoxy Flooring
93569	643.1.TP0330.03 - FMC - Sheet Piling	95432	643.1.TP1135.01 - FMC - Sunshades and Light Shelves	99231	643.2.TP1330.01 - MHU - General Carpentry
98572	644.1.TP0620.01 - CP1 - Reinforcement Fix	95455	643.1.TP1810.02 - FMC - Mechanical Services - Chiller Supply	Careta So	643.2.TP2830.01 - MHU - Tiling
			643.1.TP1810.93 - FMC - Mechanical		
955/3	642. IP.0520.01 - MHB - Reintorcement Fix	95456	Services - Cooling Tower Supply	99241	643.1.TP1533.01 - FMC - Whitegoods
93574	642.TP.0531.01 - MHB - Post Tensioning	95457	643.1.TP1810.64 - FMC - Mechanical Services - AHUSupoly	27/264	643 1 TD1235 (1) - EMC - Bollor Shuttors
			643.1.TP1810.01 - FMC - Mechanical		643.1.TP1434.01 - FMC - Workstations &
93575	643.1.TP0620.01 - FMC - Reinforcement Fix	95458	Services - Tanks	99245	Screens

Local Industry Participation, Sunshine Coast University Hospital: Progress Report January 2014					
Attachment A:	nent A:				
Enquirit	Enquiries Details				
Enguityid	j Title	Enguiryid	Title	Enguiryid	Title
			643.1.TP1231.01 - FMC - Balustrades &		643.2.TP1434.01 - MHU - Workstations
93576	643.1.TP0531.01 - FMC- Post Tensioning	95480	Handrails	99260	& Screens
93577	643.2.TP0520.01 - MHU - Reinforcement Fix	95543	643.1.TP1235.01 - FMC - Metal LOUYIES	₽9266	643.1.TP2830.01 - FMC - Tiling
93578	644.1.TP0631.01 - CP1 - Post Tensioning	95555	643.1.TP1432.01 - FMC - Curtains & Blinds	99265	643.2 TP1236.01 - MHU - Roller Shutters
/7	640.PR0552.01 - PRW - Safety Presautions				1531.01 -
93581	(PPE)	95576	643.1.TP1230.01 - FMC - Metalwork	99266	Sundry
	642, 1P.0832.01 - MHB - Waterproofing		643.1.TP1030.01 - FMC - Structural		643.2.TP1531.01 - MHU - Sundry
93/1/	Inground	95588	Steelwork	99267	Hardware
0 2000	642.TP.0832.02 - MHB - Waterproofing Roofs &		643.1.TP2236.01 - FMC - Kitchen / Laundry		
73/18	Decks	95592	Equipment	99301	643.2.TP1433.01 - MHU - Furniture
	642.TP.0832.03 - MHB - Temporary	>	642. TV.1537.51 - MHB - Coolrooms &		
93719		95686	Cleanrooms	99309	643.2.TPZ711.01 - MHU - Floor Mats
	643.1.TP0832.01 - FMC - Waterproofing &		643.1,TR1637.01 - FMC - COOKOOMS &		642.TP.1435.01 - MHB - Folding Doors &
93720		95687	Cleanrooms	99310	Operable Walls
6377	643.1.1P3832.01 - FMC - Waterproofing & Tanking - Poorte & Dooke	95,699	KAA 1 TD1 K20 K1 CD7 Banding	* 1200	643.1.TP1435.01 - FMC - Folding Doors &
	P			1	643 2 TD1425 03 - MULL Colding Doors
93722	643.2.TP0832.01 - MHU - Waterproofing	95700	Cladding	99315	& Operable Walk
93773	644.1.TP0832.01 - CP1 - Waternroofing	95781	643.2.TP1636.01 - MHU - Wall Cladding Systems	31500	ZES TOSTOS DARKET VESTILITATION
	642.TP2335.01 - PRW - Site Wide LV		- Character	NTOTO	643.2 TD2731.01 - MHII - Inchi Eloc
93827	EquipmentSupply	95707	643.1.TP1131.01 - FMC - Metal Windows	99322	
93860	641.TP0410.01 - RIE - Concrete Supply	11156	644.1.TP1131.01 - CP1 - Facade / Screens	5000	643.2.TPZ735.01 - MHU - Tactile Indicators
	642.TP.0420.01 - MHB - Concrete Place &				643. p. TP2737.01 - MHU - Wall
93918	Finish	95778	643.2 TP1032.01 - MHU - Facade Framing	99423	Protection
93938	CP1.TP2335.01 - CP1/CP2- Light Fitting Supply	95902	644.1.TP1235.01 - CP1 - Metal Louvres	99428	643.2 TP3131,01 - MHU - Mature Trees
04110	640.PR0033.03 - PRW - Temporary Hydraulics	20020			642.TP,1520.01 - MHB - Hardware &
24113	SHE WIGH RELICIENCE	22506	043.2.1P1131.01 - MHU - Metal Windows	39494	Ironmongery - Fix

Attachment A.	ent A:				
Enquiries Details	Details				
Enguinyid	Title	Enguiryid	Title	Enquiryid	Title
94122	641.TP1732.01 - RIE - Water & Fire Mains reticulation	96073	644.2.TP0057.01 - CP2 - Final Clean	995,04	642 TD 1531 02 - MHR. Bin Hardware
			643.2.TP1135.01 - MHU - Sunshades & Light		640. PR0053.01 - DRW - Overall Onsite
94130	642.TP.0422.01 - MHB - Concrete Rumping	96151	Shelves	99507	Surveying
94234	643.1.TP2312.01 - FMC - HV Seperator Supply	96159	643.2.TP1230.01 - MHU - Metalwork	99528	642.TP.1531.04 - MHB - Grab Rails
94256	642.TP.0431.01 - MHB - Precast Concrete	96169	643.2.TP1235.01 - MHU - Metal Louyres	99542	643.1.TP1430.01 -FMC-Joinery
94271	644.2.TP0830.01 - CP2 - Blockwork	AETAV/	643.1.TP2235.01 - FMC - Dock Levelers	99695	642.TP.1510.01 - MHB - Door Hardware
	640.PR0032.02 - PRW - Main Site Office &			+	
94272	Accommodation Temporary Electrical	96589	644.1.701230.03 - CP1 - General Metalwork	99708	643.1.TP1510.01 - FMC- Door Hardware
	640.PR0022.02 - PRW - Temporary Lunch	\	643,2.TP3530.01 - MHU - Temporary		643,2,TP1510.01 - MHU - Door Hardware
94283	Sheds/Ablutions/Containers/OtherSheds	96685	Carpentry	99709	Supply
					642.TP.1238.01 - MHB - Metalwork -
94285	642.TP.0050.01 - MHB - Scaffolding	96944	642.TP.1536.01 - MHB - General Carpentry	99733	Stainless Steel
			\ (\)		643.2.TP1238.01 - MHU - Metalwork
94320	644.2.TP1131.01 - CP2 - Facade / Screens	97023	642.19 1433.01 - MHB - Furniture	99736	Stainless Steel
94353	644.2.TP1330.01 - CP2 - General Carpentry	97037	642.TP.1236.DsMHB-Roller Shotters	99740	643.1.TP1238.01 - FMC - Stainless Steel Metalwork
			642.TP.1332.01 - MMB / Doors & Door		
94362	640.PR0022.07 - PRW - Pest Control	97039	Frame Supply		
			642.TP.2630.01 - MHB - Cellings and		
94363	640.PR0023.03 - PRW - Temporary Site Signage	97273	Partitions		_
	640.PR0033.02 - PRW - Main Site Office				
SAAT 5	A compared on the first of the first of the second of the				

Bulltemant Meduler Meining Pty Ltd	Attachment 8					
Research	Rusmess Engagement		LIPP Categorisation	Source of Supply		
September Mode Proposed September		Reason	SED - South East CCD	C- Contentable	PostCoce	Values of
Medium Header Haring Pp Ltd				L=Local		Goods or
Subtrement Mountain Pip List			IMP - Impored			Services
Seadors Author List	The second secon		<u> </u>			supplied
Waggitter Play CLU Ply Ltd				C		s.47(3)(
See Security	Shadforths Civil Pty Ltd		SEQ	L		
Name CDL PPL LIST						
Carly Controllation	EVS Group Australia Pty Ltd					
State Glas				1		
System System Section Sectio						
Geodera Clearers Notifices Py Ltd T/A Calty Constructors Consest Valkeways and parts SEC L 4658	Blue Que Pty Ltd					
Wagesterf Piling Sile Problemy Works - 50 Probe Locations SEC L 4090 Caulty Choice Signs Re sinh to setating Billboard SEC C 4476 Fences Sile Printers Security Frace - Stage 1 SEC C 4456 Fences Sile Printers Security Frace - Stage 1 SEC C 4456 Security Frace - Stage 1 SEC C 4456 Security Frace - Stage 1 SEC C 4456 Security Fences - Stage 1 SEC C 4456 Security Frace - Stage 1 SEC C 4456 Security Fences - Stage 1 SEC C 4457 Security Fences - Stage 1 SEC C 4458 Security Fences - Stage 1 SEC C 4459 Security Fences - Stage 1 Security Fences - Stage						
Castley Choice Signs						
Femourage					-	
Section				 		
Consequence						
Ludder ground Pipes and Cabble Location Pip Ltd Debet Inground services prior to digging fereo SED	rodon dise : 4 =					
December	01/04/01/07					
Specific Name Supply & register Read Base - Site Accommoded SEC	3.00					
Printings Building Foundations				- 7		
Partition of the Policy Partition of the Partition						
Site Shed Cleaning				1		
Floor coner CLD - AK				+		
Supply					4011	
The Ysultee for The SJ. & DY Eade Family Trust TIA Visimark Region Fabrication Supply & Install 2 Gate Supply & Install 2 Gate Supply & Install 2 Gate Supply & Hire of Perimeter Fencing Prototypes Security IMP C 4008 Refer 1 May					Appe	
Supply A Install 2 Gate Closures Sch. C. 4558						
Carage Hire Pty Ltd				 		
Transpecific Industries Pty Ltd						
Limited Cranes Surghine Coast Pty Ltd Mobile Crane Hre	J. L. San			-		
Semens				+		
Merbon (Va Statewide Communications)	Official Grand Gra					
Nem Wilson & Associates Pty Ltd T/a KWA Billinds						
Coetes Hire Operations Pty Ltd						
Energex Limited	7					
ATF Sunshine Coast and Total Site Set Up Supply & Install crowd control benefies SEQ L 4558 C 4000 Evolution Treftic Control Provide braffic Control Video conversions from AVI to (MVV) * YouTube AUS C 4014 Worldwide Online Printing Market Street Worldwide Online Printing Market Street Worldwide Contine Printing Market Street Video Conversions From AVI to (MVV) * YouTube Video Conversions From AVI to (MVV) * YouTube AUS C 2010 Combined State Street Video Conversions From AVI to (MVV) * YouTube AUS C 2010 Combined State Street Video Conversions From AVI to (MVV) * YouTube Video Conversions From AVI to (MVV) * YouTube AUS C 2010 Combined State Street L 4575 BAUS L 4575 DLA Piper Professional Figs AUS L 4000 Greenbing State Street Video Conversions From AVI to (MVV) * WIV) * WIV) SEQ L 4074 Where Express 1 SEQ L 4000 Trumpf Med Australla Pty Ltd 3 Combined State Street Aus Street L 4108 Trumpf Med Australla Pty Ltd 3 Combined Street Medical Bades Air Patable Littling System IMP C 2087 Application Figs Auruta Plastics (QLD) Pty Ltd G James Auruta Plastics (QLD) Pty Ltd Cultural Heritage Industron SEQ L 4558 Robotic Automation Group Auf Adabagy Services AUS C 2127 Transport Items SEQ L 4558 Robotic Automation Group Auf Adabagy Services AUS C 2127 Transport Items SEQ L 4008 Spence Door Auf Adabagy Services AUS C 2127 Transport Items SEQ L 4008 Spence Door Sep C L 4004 Spence Door Sep C L 4558 Spence Door Coates Hire Operations Pty Ltd Supply of Bulk Potable and Non-Potable Water SEQ L 4558 Spence Door Coates Hire Operations Pty Ltd Supply of Site Accommodation Cleaning Products SEQ L 4566 Theory of Prototype SeQ C 4567 Newerfall Springwater Limited Supply of Site Accommodation Cleaning Prototype SEQ C 4575 Durckers Pty Ltd Supply of Site Accommodation Cleaning Prototype SEQ C 4575 Birdyn Terrototype Auf Additional Supply and Install of office furniture for Prototype SEQ C 4576 Additional Supply and Install of office furniture for Prototype						
Evolution Trafic Control Provide Ireffic Controller SEQ L 4558 S Lucid Edge PTY LTD Video conversions from AVI to MWY+ You'tube AUS C 4014 Worldwide Online Printing Market Street Masterplan Poster SEQ L 4000 Lucid Edge PTY LTD Video Conversions from AVI to MWY+ L AUS C 2010 Combined Security Services Security Gylards SEQ L 4575 Lucid Edge PTY LTD Video Conversions from AVI to MWY+ L AUS C 2010 Combined Security Services Security Gylards SEQ L 4575 Lucid Edge PTY LTD Video Conversions from AVI to MWY+ L AUS C 2010 Combined Security Services Security Gylards SEQ L 4575 Lucid Edge PTY LTD Video Conversions from AVI to MWY+ L AUS C 2010 Combined Security Services Security Gylards SEQ L 4575 Lucid Edge PTY LTD Video Conversions from AVI to MWY+ L AUS C 2010 Combined Security Services AUS L 4000 References Security Gylards SEQ L 4074 Alignment Authority Services AUS C 2016 Alignment Authority Services AUS C 2016 Alignment Authority Services AUS C 2017 Alignment Authority Services AUS C 2017 Alignment Authority Services AUS C 2127 Alignment Authority Services AUS C 2127				+		
Lucid Edge PTY LTD		111				s.47(3)(b)
Worldwide Online Printing Market Street Masterplan Poster Video Convergines Fign AVI to MVV- AUS C 2010 Combined Security Services Security Gylands SEQ L 4074 AUS C 2010 Combined Security Services Security Services Professional figs AUS L 4000 Greenblins Size & Size Professional figs AUS L 4000 Greenblins Size & Size L 4074 Meltro Express 2 Configurers Security on GUH-Lin SpUH SEQ L 4074 Meltro Express 2 Configurers Security on GUH-Lin SpUH SEQ L 4074 Aljohundeligh Medical Beds and Patheru Lifting System IMP C 2067 Arjohundeligh Medical Beds and Patheru Lifting System IMP C 6163 Artursta Plastics (OLD) Pty Lid Gulfural Heritage Industrial G James Supply and Install of windows and external doors SEQ L 4556 ATT Services Pty Ltd Temp-Lending SEQ L 4558 Rebotic Automation Group AgV Advisory Services AUS C 2127 Energy Crane Services Pty Transport Items on SCUH site SEQ L 4004 Energes Limited Temporary Electrics supply South SEQ L 4006 Supply doors and frame SEQ L 4006 Supply and frame SEQ L 4006 Supply of Potable Water to Site until Peb 13 SEQ C 4131 Kyana Projecto Pty Ltd Supply of Potable Water to Site until Peb 13 SEQ C 4127 Seve Ryan Vas Rix Ryan Photography Pt/ Photograph Path removal & monthly images SEQ L 4561 Supply of Notable Water to Site until Peb 13 SEQ C 4121 Seve Ryan Vas Rix Ryan Photography Pt/ Photograph Path removal & monthly images SEQ L 4561 Supply of Notable Water to Site until Peb 13 SEQ C 4561 Supply of Notable Water to Site until Peb 13 SEQ C 4561 Supply of Notable Water to Site until Peb 13 SEQ C 4575 Seve Ryan Vas Rix Ryan Photography Pt/ Photograph Path removal & monthly images SEQ L 4561 Supply of Notable Water to Site until Peb 13 SEQ C 4561 Supply of Notable Water to Site until Peb 13 SEQ C 4576 Supply and install of Germinute of Prototype SEQ C 4575 Seve Ryan Vas Rix Ryan Photography Pt/ Photograph Path removal & monthly images SEQ C 4576 Supply			-			5.47 (3)(D)
Lucid Edge PTY LTD						
Combined Security Services						
DLA Piper						
Greenbins Size 8,6in SEQ L 4074 Metro Express 2 Configurers serry from CCUALD SOUH SEQ L 4106 Trumpf Med Australia Pty Ltd 32G Combragion light set & Trumpf Serv IMP C 2067 Anjohundisch Medical Beds and Patient Lifting System IMP C 6163 Arunta Plastics (QLD) Pty Ltd C Cultural Heritage Influentian SEQ 3134 G James Seq L 4556 Art Services Pty Ltd Temp-Encing SEQ L 4556 Robotic Automation Group Services Aus C 2127 Energy Crane Services Pty Transport tiers to SCUH site SEQ L 4004 Spence Door Supply doors and frame SEQ L 4004 Spence Door Supply doors and frame SEQ L 4556 Supply doors and frame SEQ L 4556 Neverfall Springwater Limited Supply of Bulk Potable and Non-Potable Water SEQ C 4131 Neverfall Springwater Limited Supply of Potable Water to Site until Feb 13 SEQ C 4127 Steve Ryan Vas Rix Ryan Photography Pt/ Photograph Pain removal & monthly images SEQ L 4560 Supply of Supply of Supply of Greno Coates Hire Operations Pty Ltd Supply of Potable Water to Site until Feb 13 SEQ C 4127 Steve Ryan Vas Rix Ryan Photography Pt/ Photograph Pain removal & monthly images SEQ L 4560 Supply of Supply and Install of office furniture for Prototype SEQ C 4561 Supply and Install of office furniture for Prototype SEQ C 4561 Supply and Install of office furniture for Prototype SEQ C 4561 Aralgameted Pest Control Redback Pest Control to SCUH Site Offices SEQ C 4561 Midmed Supply and Install of exemination couch SEQ C 4561 Viridian Supply and Install of exemination couch SEQ C 4561 Viridian Supply and Install of exemination couch SEQ C 4561 Viridian Supply and Install of exemination couch SEQ C 4561 Viridian Supply and Install of exemination couch SEQ C 4561 Viridian Supply and deliver of Mirors for Prototype SEQ C 4561 Viridian Supply and deliver of Mirors for Prototype SEQ C 4561						
Metro Express 2 Confinences servicing GCULLID SQUH SEQ						
Trumpf Med Australia Pty Ltd 3x3 Combination light set & Trumpf Serv IMP C 2067 Ariphunfieligh Medical Beds and Patibat Lifting System IMP C 6163 Arunta Plastics (QLD) Pty Ltd Cultural Heritage Induction SEQ 3134 G James Supply and Install of windows and external doors SEQ L 4556 ATF Services Pty Ltd Temb Fencing SEQ L 4558 Robotic Automation Group AgV Advisory Services AUS C 2127 Energy Crane Services Pty Transport Items to SCUH site Energex Limited Temporary Ejectrios supply South SEQ L 4034 Sepone Door Supply doors and frame SEQ L 4006 Supply doors and frame SEQ C 4131 Kyana Projects Pty Ltd Supply of Bulk Potable and Non-Potable Water SEQ C 4127 Steve Ryan t'as Rix Ryan Photography Pt/ Photograph Patri removal & monthly images SEQ C 4215 Dunckers Pty Ltd Supply of Site Accomodation Cleaning Products SEQ C 4561 Supply and Install of office furniture for Prototype SEQ C 4561 Harvey Norman Supply and Install of office furniture for Prototype SEQ C 4561 Aralgamated Pest Control Midmed Supply and Install of effice furniture for Prototype SEQ C 4561 Viridian Supply and leiver of Mirrors for Prototype SEQ C 4561 Viridian Supply and leiver of Mirrors for Prototype SEQ C 4561 Viridian Supply and leiver of Mirrors for Prototype SEQ C 4561 Viridian Supply and leiver of Mirrors for Prototype SEQ C 4561 Viridian						
Arjohunteligh Medical Beds and Patters Lifting System IIMP C 6163 Arjohunteligh Carlos Pity Ltd Cultural Heritage Induction SEQ 3134 G James SEQ L 4556 ATT Services Pity Ltd Temporary Services SEQ L 4556 Robotic Automation Group NGV Advisory Services AUS C 2127 Energy Crane Services Pity Ltd Temporary Services AUS C 2127 Energy Crane Services Pity Transport Items to SCUH site SEQ L 4034 Energex Limited Services Pity Transport Items to SCUH site SEQ L 4036 Energex Limited Supply doors and frame SEQ L 4556 Supply doors and frame SEQ L 4556 Coates Hire Operations Pity Ltd Supply of Bulk Potable Water SEQ C 4131 Kyana Projects Pity Ltd Supply of Potable Water to Site until Feb 13 SeQ C 41131 Neverfall Springwater Limited Supply of Potable Water to Site until Feb 13 SEQ C 4127 Steve Ryan vas Rix Ryan Photography Pit Photograph Path removal & monthly images SEQ L 4216 Dunckers Pity Ltd Supply of Stacomodation Cleaning Products Supply of Stacomodation Cleaning Products Suncoast Water Carriers Supply and Install of office furniture for Prototype SEQ C 4561 Suncoast Water Carriers Supply and Install of office furniture for Prototype SEQ C 4561 Flarvey Norman Supply of Ritchen fridge and microwave SEQ C 4567 Supply and Install of office furniture for Prototype SEQ C 4567 Arralgamated Pest Control Sept Ltd Supply and Install of examination couch SEQ C 4561 Viridian Supply and Install of examination couch SEQ C 4561 Viridian Supply and deliver of Mirrors for Prototype SEQ C 4561 Viridian Supply and Install of examination couch SEQ C 4561 Viridian Supply and deliver of Mirrors for Prototype SEQ C 4561 Viridian						
Arunta Plastics (CLLD) Pty Ltd G James Supply and Install of windows and external doors SEQ. L. 4556 ATF Services Pty Ltd Temps Fencing Robotic Automation Group NoV Advisory Services AUS. C. 21227 Energy Crane Services Pty Items to SCUH site SEQ. L. 4034 Energex Limited Temporally Electrics supply South SEQ. L. 4008 Spence Door Supply doors and frame SEQ. L. 4556 Coates Hire Operations Pty Ltd Supply of Potable and Non-Potable Water SEQ. C. 4131 Kyana Projects Pty Ltd Supply of Potable Water to Site until Feb 13 SEQ. C. 4127 Steve Ryan t/as Rix Ryan Photography Pty Photograph Palm removal & monthly images SEQ. L. 4560 Bizfum Express Supply of Site Accompdation Cleaning Products SEQ. L. 4560 Supply of Nite Accompdation Cleaning Products SEQ. L. 4560 Bizfum Express Supply and Install of office furniture for Prototype SEQ. C. 4557 Arralgameted Pest Control Reddack Pest Control to SCUH Site Offices SEQ. C. 4570 Caulity Choice Signs Pty Ltd Supply and deliver of Mirrors for Prototype SEQ. C. 4571 Caulity Choice Signs Pty Ltd Supply and deliver of Mirrors for Prototype SEQ. C. 4561 Viridian Supply and deliver of Mirrors for Prototype SEQ. C. 4571 Caulity Choice Signs Pty Ltd Supply and deliver of Mirrors for Prototype SEQ. C. 4571 Caulity Choice Signs Pty Ltd Viridian						
G James Supply and Install of windows and external doors SEQ L 4556 ATF Services Pty Ltd Temp-Fencing SEQ L 4558 Robotic Automation Group AQV Advisory Services AUS C 2127 Energy Crane Services Pty Transport Items to SCUH site SEQ L 4034 Energex Limited Services Pty Transport Items to SCUH site SEQ L 4006 Spence Door Supply doors and frame SEQ L 4006 Spence Door Supply doors and frame SEQ L 4556 Coates Hire Operations Pty Ltd Supply doors and frame SEQ C 4131 Kyana Projects Pty Ltd Supply of Bulk Potable and Non-Potable Water SEQ A5667 Neverfail Springwater Limited Supply of Potable Water to Site until Feb 13 SEQ C 4127 Steve Ryan t/as Rix Ryan Photography Pf Photography Pahr removal & morthly images SEQ L 4215 Durnckers Pty Ltd Supply of Site Accomodation Cleaning Products SEQ L 4560 Bizfum Express Supply and Install of office furniture for Prototype SEQ C 4561 Suncoast Water Carriers Re-Fill 2 x 10000L Water Tanks + 1 Additional Vis SEQ C 4576 Bizfum Express Supply and Install of office furniture for Prototype SEQ C 4576 Bizfum Express Supply and Install of office furniture for Prototype SEQ C 4576 Bizfum Express Supply and Install of office furniture for Prototype SEQ C 4577 Arnalgameted Pest Control SCUH Site Offices SEQ L 4561 Viridian Supply and Install of earnination couch SEQ C 4570 Quality Choice Signs Pty Ltd Hard Hat Stickers SEQ C 4561 Viridian Supply and deliver of Mirrors for Prototype SEQ C 4571	7 11/2011/2011/2011					
ATF Services Pty Ltd Temporarity Services Services Pty Ltd Temporarity Services AUS C 2127 Energy Crane Services Pty Transport Items to SCUH site SEQ L 4034 Energex Limited Services Pty Transport Items to SCUH site SEQ L 4034 Energex Limited Supply doors and frame SEQ L 4008 Supply doors and frame SEQ L 4556 Coates Hire Operations Pty Ltd Supply of Bulk Potable and Non-Potable Water SEQ C 4131 Kyana Projects Pty Ltd Supply of Potable Water to Site until Feb 13 SEQ C 4127 Steve Ryan t/as Rix Ryan Photography Pt/L Photograph Palm removal & monthly images SEQ L 4560 Dunckers Pty Ltd Supply of Site Accomdation Cleaning Products SEQ L 4560 Supply and Install of office furniture for Prototype SEQ C 4561 Suncoast Water Cerriers Re-Fill 2 x 10000L Water Tanks + 1 Additional Vil SEQ C 4557 Amalgameted Pest Control Redback Pest Control to SCUH Site Offices SEQ L 4561 Widned Supply and Install of office furniture for Prototype SEQ C 4557 Amalgameted Pest Control Sep L 4561 Viridian Supply and Install of environment ocuch SEQ C 4570 Calelity Choice Signs Pty Ltd Hard Hat Stickers SEQ C 4561 Viridian Supply and deliver of Mirrors for Prototype SEQ C 4561 Viridian Supply and deliver of Mirrors for Prototype SEQ C 4561 Viridian Supply and deliver of Mirrors for Prototype SEQ C 4570						
Robotic Automation Group ACV Advisory Services AUS C 2127 Energy Crane Services Pty Transport Items to SCUH site SEQ L 4034 Energex Limited Temporary Ejectrics supply South SEQ L 4006 Spence Door Coates Hire Operations Pty Ltd Supply doors and frame SEQ C 4131 Kyana Projects Pty Ltd Supply of Bulk Potable and Non-Potable Water SEQ C 4131 Kyana Projects Pty Ltd Supply of Potable Water to Site until Feb 13 SEQ C 4127 Steve Ryan t/as Rix Ryan Photography P/V Photograph Pain removal & monthly images SEQ L 4215 Dunckers Pty Ltd Supply of Site Accommodation Cleaning Products Supply and Install of office furniture for Prototype SEQ C 4561 Supply of Re-Fill 2 x 10000L Water Tanks + 1 Additional Vis SEQ C 4557 Arralgameted Pest Control Redback Pest Control to Scuth Site Offices Supply and Install of office furniture for Prototype SEQ C 4570 Caulity Choice Signs Pty Ltd Supply and Install of examination couch SEQ C 4561 Viridian Supply and Install of Amonth Site Offices SEQ C 4571 Caulity Choice Signs Pty Ltd Supply and Install of examination couch SEQ C 4561 Viridian Supply and Install of Mirrors for Prototype SEQ C 4571 Caulity Choice Signs Pty Ltd Supply and Install of examination couch SEQ C 4571 Caulity Choice Signs Pty Ltd Supply and Install of Mirrors for Prototype SEQ C 4561 Viridian						
Energy Crane Services Pty Transport Items to SCUH site SEQ L 4006 Spence Door Supply doors and frame SEQ L 4056 Coates Hire Operations Pty Ltd Supply of Bulk Potable and Non-Potable Water SEQ C 4566 Neverfall Springwater Limited Supply of Potable Water to Site until Feb 13 SEQ C 4127 Steve Ryan t/as Rix Ryan Photography Pt/ Photograph Palm removal & monthly images SEQ C 4215 Dunckers Pty Ltd Supply of Site Accomodation Cleaning Products Supply and Install of office furniture for Prototype SEQ C 4561 Harvey Norman Supply of kitchen fridge and microwave SEQ C 4567 Redback Pest Control Redback Pest Control to SCUH Site Supply and Install of offices SEQ C 4561 Supply and Install of offices SEQ C 4565 C 4565 C 4566 Supply and Install of office furniture for Prototype SEQ C 4567 C 4567 C 4566 C 4567 C 4561 C 4565 C 4565 C 4565 C 4565 C 4566 C 4566 C 4566 C 4570 C 4561 C 4570 C 4570 C 4573 C 4561 C 4573						
Energex Limited Temporary Electrics supply South SEQ L 4008 Spence Door Supply doors and frame SEQ L 4556 Coates Hire Operations Pty Ltd Supply of Bulk Potable and Non-Potable Water SEQ C 4131 Kyana Projects Pty Ltd Supply of Potable Water to Site until Feb 13 SEQ C 4127 Neverfall Springwater Limited Steve Ryan t/as Rix Ryan Photography Pt/ Photograph Palm removal & monthly images SEQ L 4215 Dunckers Pty Ltd Supply of Site Accomodation Cleaning Products SEQ L 4260 Bizfurn Express Supply and Install of office furniture for Prototype SEQ C 4561 Suncoast Water Carriers Re-Fill 2 x 10000L Water Tanks + 1 Additional Vis SEQ C 4575 Bizfurn Express Supply and Install of office furniture for Prototype SEQ C 4567 Redback Pest Control Supply and Install of office furniture for Prototype SEQ C 4567 Arnalgameted Pest Control Supply and Install of office furniture for Prototype SEQ C 4561 Viridian Supply and Install of evanination couch SEQ C 4570 Caulity Choice Signs Pty Ltd Flard Hat Stickers SEQ C 4473	/ /					
Spence Door Supply doors and frame SEQ L 4556 Coates Hire Operations Pty Ltd Supply of Bulk Potable and Non-Potable Water SEQ 4567 Neverfail Springwater Limited Shapely of Potable Water to Site until Feb 13 SEQ C 4127 Steve Ryan t/as Rix Ryan Photography Pt/Photograph Palm removal & monthly images SEQ L 4215 Dunckers Pty Ltd Supply of Site Accommodation Cleaning Products SEQ L 4216 Supply of Site Accommodation Cleaning Products SEQ L 4560 Sizfum Express Supply and Install of office furniture for Prototype SEQ C 4561 Suncoast Water Carriers Re-Fill 2 x 10000L Water Tanks + 1 Additional Vis SEQ C 4576 Sizfum Express Supply and Install of office furniture for Prototype SEQ C 4576 Sizfum Express Supply and Install of office furniture for Prototype SEQ C 4576 Sizfum Express Supply and Install of office furniture for Prototype SEQ C 4576 Sizfum Express Supply and Install of office furniture for Prototype SEQ C 4576 Amalgameted Pest Control Supply and Install of office furniture for Prototype SEQ C 4561 Viridian Supply and Install of examination couch SEQ C 4570 Calelity Choice Signs Pty Ltd Flard Hat Stickers Supply and deliver of Mirrors for Prototype Size C 4173						
Coates Hire Operations Pty Ltd Supply of Bulk Potable and Non-Potable Water SEQ C 4131 Kyana Projects Pty Ltd Supply of Potable Water to Site until Feb 13 SEQ C 4127 Steve Ryan t/as Rix Ryan Photography Pt/ Photograph Palm removal & monthly images SEQ L 4215 Dunckers Pty Ltd Supply of Site Accomodation Cleaning Products SEQ L 4560 Bizfum Express Supply and Install of office furniture for Prototype SEQ C 4561 Suncoast Water Cerriers Re-Fill 2 x 10000L Water Tanks + 1 Additional Vit SEQ C 4576 Bizfum Express Supply of kitchen fridge and microwave SEQ C 4576 Bizfum Express Supply and Install of office furniture for Prototype SEQ C 4557 Amalgameted Pest Control Redback Pest Control Sep L 4561 Viridian Supply and Install of examination couch SEQ C 4570 Cuality Choice Signs Pty Ltd Hard Hat Stickers SEQ C 4571 C 4561 Viridian						
Kyana Projects Pty Ltd Supply-of Bulk Potable and Non-Potable Water SEQ 4567		Supply doors and frame			-	
Neverfall Springwater Limited Shaply of Potable Water to Site until Feb 13 SEQ C 4127 Steve Ryan t/as Rix Ryan Photography P/V Photograph Pain removal & monthly images SEQ L 4215 Dunckers Pty Ltd Supply of Site Accomodation Cleaning Products SEQ L 4560 Bizfurn Express Supply and Install of office furniture for Prototype SEQ C 4561 Harvey Norman Supply of kitchen fridge and microwave SEQ C 4575 Bizfurn Express Supply and Install of office furniture for Prototype SEQ C 4567 Arralgemeted Pest Control Redback Pest Control to SCUH Site Offices SeQ C 4570 Quality Choice Signs Pty Ltd Flard Hat Stickers Supply and deliver of Mirrors for Prototype SEQ C 4571 C 4570 C 44570 C 44570 C 44570 Supply and deliver of Mirrors for Prototype SEQ C 44571		Supplied Bulk Potable and Non-Potable Motor				
Steve Ryan t/as Rix Ryan Photography PIZ Photograph Palm removal & monthly images SEQ L 4215 Dunckers Pty Ltd Supply of Site Accomodation Cleaning Products SEQ L 4560 Bizfurn Express Supply and Install of office furniture for Prototype SEQ C 4561 Suncoast Water Cerriers Re-Fill 2 x 10000L Water Tanks + 1 Additional Vis SEQ L 4551 Harvey Norman Supply of kitchen fridge and microwave SEQ C 4575 Bizfurn Express Supply and Install of office furniture for Prototype SEQ C 4557 Arnalgameted Pest Control Reddack Pest Control to SCUH Site Offices SEQ L 4561 Midmed Supply and Install of examination couch SEQ C 4570 Quality Choice Signs Pty Ltd Hard Hat Stickers SEQ C 4551 Viridian Supply and deliver of Mirrors for Prototype Site SEQ C 4451						
Dunckers Pty Ltd Supply of Site Accomodation Cleaning Products SEQ L 4560 Bizfurn Express Supply and Install of office furniture for Prototype SEQ C 4561 Suncoast Water Certiers Re-Fill 2 x 10000L Water Tanks + 1 Additional Vis SEQ L 4551 Harvey Norman Supply of kitchen fridge and microwave SEQ C 4575 Bizfurn Express Supply and Install of office furniture for Prototype SEQ C 4557 Arnalgameted Pest Control Redback Pest Control to SCUH Site Offices SEQ L 4561 Widned Supply and Install of examination couch SEQ C 4570 Quality Choice Signs Pty Ltd Hard Hat Stickers SEQ C 4561 Viridian Supply and deliver of Mirrors for Prototype Suite SEQ C 4473						
Bizfurn Express Supply and Install of office furniture for Prototype SEQ C 4561				 		
Suncoast Water Cerriers Re-Fill 2 x 10000L Water Tanks + 1 Additional Vis SEQ L 4551 Harvey Norman Supply of kitchen fridge and microweve SEQ C 4575 Bizfurn Express Supply and Install of office furniture for Prototype SEQ C 4557 Arnalgameted Pest Control Redback Pest Control to Study and Install of examination couch SEQ L 4561 Supply and Install of examination couch SEQ C 4570 Cauality Choice Signs Pty Ltd Hard Hat Stickers SEQ C 4551 Viridian Supply and deliver of Mirrors for Prototype Suite SEQ C 4173	Delitation of the man	11.7				
Harvey Norman Supply of kitchen fridge and microweve SEQ C 4575 Bizfurn Express Supply and Install of office furniture for Prototype SEQ C 4557 Arralgameted Pest Control Redback Pest Control to SCUH Site Offices SEQ L 4561 Midmed Supply and Install of examination couch SEQ C 4570 Quality Choice Signs Pty Ltd Hard Hat Stickers SEQ C 4551 Viridian Supply and deliver of Mirrors for Prototype Suite SEQ C 4173						
Bizfum Express Supply and Install of office furniture for Prototype SEQ C 4557 Amalgamated Pest Control Pedback Pest Control to SCUH Site Offices SEQ L 4561 Midmed Supply and Install of examination couch SEQ C 4570 Cauality Choice Signs Pty Ltd Hard Hat Stickers SEQ C 4561 Viridian Supply and deliver of Mirrors for Prototype Suite SEQ C 4173						
Arrialgemeted Pest Control Ar	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1					
Midmed Supply and Install of examination couch SEQ C 4570 Quality Choice Signs Pty Ltd Hard Hat Stickers SEQ C 4561 Viridian Supply and deliver of Mirrors for Prototype Suite SEQ C 4173						
Quality Choice Signs Pty Ltd Hard Hat Stickers SEQ C 4551 Viridian Supply and deliver of Mirrors for Prototype Suite SEQ C 4173	, disciplination , dec desires.					
Viridian Supply and deliver of Mirrors for Prototype Suite SEQ C 4173						
	and the second s					
	viridian				4110	
	Multimodia Technology	· •			4000	
Multimedia Technology Multi Touch Interactive Whiteboard SEQ C 4006 Response First Aid Park First Aid Shed & First Aid Training on SEQ L 4556						

Attachment C						
Business Engagement		LIPP Categorisation	Source of Supply			
Subcortractor	WorkPaciente	BEO SHERTSHILDED	C Concernation	PostCode	Values of Goods and	Summiliar's Languistics
The state of the s	TOTAL SURE	REQ - Regional GLD AUS - Rest of Authoris	L. Aposti		Services	
Shamrock Clvli	Bulk Civil Works Pre-Load	SEQ	L	4076	s.47(3)(b	Ipswich
Shedforth Civil Engineering	Cut to FIII Civil Works	SEQ	L	4556	5.17(3)(2	Sunshine Coast
Wegslaff Piling	Precast Piling & Shear Piling	SEQ	L	4060	1	Brisbane Inner City
Beavis & Bartels Pty Ltd	Temp Hydraulics (Site Wide)	SEQ	C	4013]	Brisbane - North
Oneform	Install Formwork to CPZ	SEO	L	4173		Brisbane - East
East Coast Concrete Contractors	Concrete Place and Finish to CP2	Other States	L	2485		NSW
Delco Steel	Reinforcement Fix to CP2	Ottom States	C	2000		NSW
Pro Concrete Pumping	Concrete Pumping to CP2	SEQ	L	4220		Gold Coast
FIP Electrical (Old) Pty Ltd	Electrical Installation to CP2	860	C	4144		Brisbane Inner City
VT Services	Tower Crane to CP2	860	125	4074		Brisbane - West
Tacoma Plumbing and Drainage	Hydraulics to CP2	SEQ	C C	4573	-	Sunshine Coast
EVS GROUP AUSTRALIA PTY LTD	PR0059 Site Security	Other Service	С	2077	-	NSW
UNISPAN AUSTRALIA PTY LTD	644,2,TP0060,01 - CP2 - Scaffolding	SEQ	C	4207 4059	-	Gold Coast
Boral Construction Materials (QLD)	644.2 TP0410.01 - CP2 - Concrete Supply	SEQ	L	4059	-	Brisbane Inner City
OTIS ELEVATOR COMPANY PTY LTD	642.TP.2030.01 - MHB - Vertical Transportation 643.1.TP2030.01 - FMC - Vertical Transportation	SEQ SEQ	C	4101	-	Brisbane Inner City Brisbane Inner City
OTIS ELEVATOR COMPANY PTY LTD OTIS ELEVATOR COMPANY PTY LTD	643.2.TP2030.01 - FMC - Vertical Transportation	SEQ	C	4101	-	Brisbane Inner City
OTIS ELEVATOR COMPANY PTY LTD	644.1.TP2030.01 - CP1 - Vertical Transportation	SEQ	c	4107	-	Brisbene Inner City
Polyseal Waterproofing QLD Pty Ltd	844.2.TP0832.01 - CP2 - Weterproofing	SEQ	č	4207	1	Gold Coast
STRUCTURAL SYSTEMS (NORTHERN) PTY LTD	844.2.TP0631.01 - CP2 - Post Tensioning	SEQ	č	4207	1	Gold Coast
QLD Drink and Snack Machines	640,PR0022.08 - PRW - Vending Mechines - CP2	SEQ	c	4550	1	Sunshine Coast
Regson Fabrications	641.TP1230.01 - CP2 - Paçade	SEQ		4556	1	Sunshine Coast
Custom Shades Pty Ltd	641.TP1633.00 - CP2 - Shade Structure	SEQ	C	4173	1	Brisbane - East
Designa Sabar	641.TP2430.01 - Car Park management system	Ottay States	l l	5009	1	SA
ALS	641.TP1712.01 - Rainwater Tanks to CP2	SEQ	1 0	4575		Sunshine Coast
Matchit Blockleying	644.2.TP0830.01 & 644.1.TP0830.01 - Blockwork CP2	SEG	L	4559]	Sunshine Coast
Wagstaff Piling Qld Pty Ltd	641.TP0330.02 - CP1 - Piling	bEQ		4060]	Brisbane
Sunshine Coast Air Conditioning Services	644.1.TP1830.01 - CP2 - Mechanical	SEQ	C	4556		Sunshine Coast
Eastcoast Concrete Contractors	Substructure	Ottop States		2485	s.47(3)(b)	NSW
Gordon Clements Nominees Pty Ltd T/A Calty Constructions	641.TP1330.01 - CP2 - Carpentry	SEO	(L)	4556	3.47 (3)(0)	Sunshine Coast
Able Security Group	641.TP1510.01 - CP2 - Door Hardware Supply	SEQ		4575		Sunshine Coast
Siemens	641.TP2430,01 - CP2 - Security	Citize States		3153		VIC
Fredon Electrical	641.TP2530.01 - CP2 - ICT	SEQ		4119		Logan - Beaudesert
Wagstaff Piling Qld Pty Ltd	643.1.TP0330.02 • FMC • Precast Piling	SEQ		4060		Brisbene Inner City
ASP Piling Pty Ltd	643.1.TP0330.01 - FMC - Sheet Pilling	SEQ	\bigcap / Λ	4214		Gold Coast
Manly Concrete	643.1.TPO420.01 - FMC - Concrete Placing	SEQ	//(L)	4173		Brisbene - East
Onesteel	643.1.TP0410.01 - FMC - Reo Supply	SEQ	V /) L /	4108		Brisbane - South
Bosform Pty Ltd	643.1.TP0530.01 - FMC - Formwork	SEQ	$\mathcal{O}_{\mathcal{I}}$	4207		Gold Cosst
Delco Steel Qld Pty Ltd	643,1.TP0620.01 - FMC - Reinforcement Fixing	Called State	L	2000		NSW
A1 Waterproofing & Applications Pty Ltd	643.1.TP0832.01 - FMC - Waterproofing	SEQ	L	4165		Brisbane - East
Coastcrete	MHB Precast	SEQ	С	4215		Gold Coast
Matchett	Blockwork	SEQ	\ \ \ \ \ \	4559		Sunshine Coast
A1 Waterproofing	la ground Waterproofing	SEQ /	C	4165		Brisbane - East
640.TP3131.01 - CP2 - Landscaping	Penfolds	SEG	L	4553		Sunshine Coast
640.TP1532,01 - CP2 - Signage	Premier Signs	SEQ	С	4108		Brisbane - South
640.TP1230.01 - CP2 - General Metalwork	Regson Fabrications	SEQ	C	4556		Sunshine Coast
640.TP3030,01 CP2 - Painting	Amalgamated Painting	SEQ	c	4214		Gold Coast
	Pickerick Group Pty List			4101		e e chi
Concrete Pamping	Pro Concrete Pumping	5EQ	c .	4220		SEOM
pimwork	Heinrich /	Arc.	1	4207		SEQE
priorete Place	Eastcoast Concrete Contractors	To ar shares	C	2485		NSW
Reo Fex	Delco	Other States	C	2000		NSW
Remporary Hydraulics	Beavis & Bartels Pty Ltd	SEO	3	4080		SEQK
processe Stripply	Holcus	REO	1	4701		REG ON
	Oneseel	5EQ-	Q	4105		DE ON .
MHB Substructure, incl Pile trimming	Eastcoast Concrete Contractors	20×15(A))	C	2,485		NSW

Note: Substructure wasn't listed on JCN Gateway website as an opportunity for companies to register through ICN.





Sunshine Coast University Hospital: Local Industry Participation

A Division of QMI Solutions

Progress Report #16 for period to 28 February 2014 Prepared by Industry Capability Network (Queensland) Ltd

This report details the assistance provided during the above period by ICN (Qld) to Lend Lease in the delivery and implementation of the Local Industry Participation Plan (LIPP) for the Sunshine Coast University Hospital in accordance with the Local Industry Policy (LIP).

1. Liaison with the Project on LIP Issues

ICN met with Queensland Health (Sam Betros) in May 2011 to discuss the project, ICN services, and LIP procedures and issues. ICN assisted QH in the development of the LIPP for the project and provided an evaluation report to QH on project bidders' LIP plan submissions in March 2012.

2. Liaison with Lend Lease on LIP Compliance

Lend Lease met with ICN to establish processes and procedures for management of the project's obligations to the LIP. It was decided that ICN will provide support on number of services covering:

- Implementation of the LIPP (capability searches or contestable packages)
- Presenting at briefing sessions
- Registering companies via ICN Gateway
- Verification of source of manufacture and service provision in subcontracts
- Business matching
- Progress reporting (Monthly) and final LIPP Outcomes reporting (at end of project)

3. Tier Barometer

Tier Barometer is an on-line self-assessment tool developed by ICN and the State Government. It provides participating companies with an assessment of their tier level in terms of supply to major projects. The tool is used by the project to analyse the basic capabilities of potential suppliers during the registration process.

4. Contestable Packages

Contestable items or packages are those that could potentially be sourced locally or overseas but do not include designated items such as concrete supply, earthworks, etc., which it is assumed will always be supplied from sources local to the project. Nor do they include items that have no chance of being manufactured in Australia, eg turbines. LL supplied ICN with the full schedule of subcontract trade packages for the project. ICN subsequently allocated these into contestable and non-contestable packages.


5. Work Packages

Queensland and Australian capability, content and capacity will be considered for all the work packages. The following activities have been undertaken:

- An ICN officer has been assigned full time to the project.
- Detailed Business Matching has been carried out by ICN. 256 work packages have been managed in this way.
 These are listed at Attachment A.
- 1469 registrations against work packages on Gateway have been received
- 65 early works have been awarded in March. These are listed at Attachment B.
- 55 work packages have been awarded so far and they are listed at Attachment C

Potential subcontractors will be given an indication of the size and generic nature of the project, and questioned regarding their capability and capacity to carry out the work, code compliance, and previous work history. Reports will be sent to Lend Lease detailing local companies which have the capability and capacity to carry out the work for each of the above packages. The primary objective of the Local Industry Policy is to ensure that competitive local companies are given full, fair and reasonable opportunity to tender for work packages. This objective will be achieved if the companies nominated by ICN, and other local companies that Lend Lease is aware of, are considered in the establishment of the tender list, and, subject to meeting pre-qualification criteria, a reasonable number of local companies are subsequently invited to tender. Lend Lease Intends to apply this requirement.

6. Source of Supply



Lend Lease has advised that out of 113 Purchase Orders, 65 were awarded for early works, one for Substructure and 55 for Work Packages listed on the ICN Gateway Project webpage. These were to companies that registered interest via ICN. As far as practicable, the measurement of industry participation focuses on the actual source of supply rather than the location through which the order is placed. The location in which services are provided, materials manufactured or where value adding takes place is indicative of the actual source of supply. Of the 55 Work Package contracts that have been awarded, 46 were won by South East Queensland (SEQ) companies, one by Regional Queensland, six by New South Wales companies, one by Victoria and one by South Australia.

7. Prototype Building

A prototype showcase building was erected in record time. This enabled focus group to provide input in to the final design in a cost effective manner.

8. Local Industry Participation

Lend Lease Project Director has personally provided project work scope and Lend Lease supplier engagement approach information to a number of larger Australian Manufacturers who have asked for more information. These include The GWA Group; The Laminex Group; Spence Doors and Rockcote Industries. For the latter company time was dedicated to a site inspection of their manufacturing facilities.

9. Information Sessions

ICN supported Lend Lease in delivering briefing sessions as proposed in their LIP plan covering:

Monday 3rd September 2012 - Civil, Infrastructure, Structure & Landscaping

Monday 17th September 2012 – Services

Monday 24th September 2012 - Roof & Façade

Monday 8th October 2012 - Fit out & Finishes

Monday 15th October 2012 - Furniture Fittings & Equipment (FF&E)

Lend Lease also presented at the General Briefing Sessions along with ICN on 13, 14, 16 and 20th of August 2012.

Lend Lease project managers attended a briefing presentation by the members of the Cleantegn Industries group of companies on 24th September 2012.

Lend Lease took part in a Local Business expo on 10th May 2013.

ICN - Evan Flower - presented to the Gympie Major Project Opportunities Forum on the project on 18th June 2013.

10. Efforts to engage with Local Companies include:

Press release by Health Minister, radio interviews by Project Director, Newspaper articles in CM and Sunshine Coast Daily followed up by substantial advertisements in the same newspapers on 19th January. Support articles followed from SSC Council and local councillors.

As a result of the above information sessions and the advertising campaign almost 1000 registrations have been received with close to 100 companies listing after the newspaper advertisements.

To date over 1469 companies have registered interest in work packages.

11. Source of Manufacture

As subcontracts begin to be awarded, the source of manufacture or service provision for contestable packages will be validated and verified in discussion with the corresponding subcontractors.

12. Reporting

Business matching reports on companies nominated for the trade packages listed at Attachment A are being provided to Lend Lease.

Evan Flower
Senior Consultant - Capability Services
ICN Queensland

92990 644.2.TP0832.01 - CP2 - Waterproofing 93076 644.2.TP0832.01 - CP2 - Electrical 93094 640.PR0042.01 - PRW - Tower Cranes, Hoists & Crews 93205 644.2.TP0631.01 - CP2 - Post Tensioning 93293 642.TP.2030.01 - MHB - Vertical Transportation 93294 643.1.TP2030.01 - MHU - Vertical Transportation 93295 643.2.TP2030.01 - MHU - Vertical Transportation 93296 644.1.TP2030.01 - CP1 - Vertical Transportation	94627 94627 94884 94884 94886 94987 94960 94960 94960 95031 95033	643.1.TP0830.01 - CP1 - Concrete Funiphing 643.1.TP0060.01 - CP1 - Scaffolding 642.TP.0830.01 - MHB - Blockwork 643.1.TP0830.01 - MHU - Blockwork 643.2.TP0830.01 - MHU - Blockwork 643.2.TP0830.01 - CP1 - Blockwork 644.1.TP0830.01 - CP2 - Painting & Line Marking 644.1.TP10830.01 - CP2 - Painting & Line Marking 644.1.TP1080.01 - CP1 - Structural Steelwork 644.1.TP1080.02 - CP1 - Structural Steelwork 642.TP.2230.04 - WHB - Building Maintenance Unit 643.2.TP1631.01 - MHB - Building Built-up / Membrane 643.7.TP1631.01 - MHB - Roof & Metal Cladding
	95112	642.TP.1636.01 - MHB - Wall Cladding Systems
	95121	642.TP.1032.01 - MHB - Facade Framing
1	95141	642.1P.1U32.U1 - MHB - Facade Framing

Lip Progress Report #16 Scuh February201449 P8.772

93513 640.PF 93513 640.PF 93514 640.TP 93520 642.TP 93523 643.1. 93565 642.TP 93565 642.TP 93565 642.TP 93565 643.1. 93572 643.1.7 93574 642.TP 93574 642.TP 93576 643.1.7 93576 643.1.7 93576 643.1.7 93577 642.TP 93577 642.TP 93578 644.1.7 93578 644.1.7 93578 644.1.7 93578 644.1.7	10231 Industry Participation, Sunstine Coast University Hospital: Progress Report February 2014 39511 640.PR00046.01 - PRW - Temporary Plant & Equipment 39513 640.PR0022.05 - PRW - Temporary Onsite Cantreen and Catering Services 39514 640.PR0022.05 - PRW - Temporary Onsite Cantreen and Catering Services 39515 641.TP0530.01 - MHB - Formwork 39526 642.TP0530.01 - MHB - Formwork 39527 643.TP0530.01 - MHB - Formwork 39526 642.TP0330.02 - MHU - File Cut-off 39526 642.TP0330.02 - MHU - File Cut-off 39526 643.TP0330.02 - MHB - Sheet Piling 39526 643.TP0330.02 - MHB - Pile Cut-off 39527 644.TP0330.02 - MHB - Pile Cut-off 39528 643.TP0330.02 - MHB - Pile Cut-off 39536 643.TP0330.02 - MHB - Pile Cut-off 39540 643.TP0330.03 - MHB - Sheet Piling 39571 643.TP0620.01 - FMC - Sheet Piling 39572 644.TP0620.01 - FMC - Reinforcement Fix 39573 643.TP0631.01 - FMC - Reinforcement Fix 39574 642.TP.0631.01 - FMC - Post Tensioning 39577 643.TP0631.01 - FMC - Post Tensioning 39578 644.TP0632.01 - MHB - Post Tensioning 39579 644.TP0632.01 - MHB - Waterproofing Roofs & Decks 39571 642.TP.0832.02 - MHB - Waterproofing Roofs & Decks 39571 642.TP.0832.03 - MHB - Temporary Waterproofing Roofs & Decks 39571 642.TP.0832.03 - MHB - Sheet Piling 39571 642.TP.0832.03 - MHB - Temporary Waterproofing Roofs & Decks 39571 642.TP.0832.03 - MHB - Temporary Waterproofing Roofs & Decks 39571 642.TP.0832.03 - MHB - Temporary Waterproofing Roofs & Decks 39579 643.TP0832.03 - MHB - Temporary Waterproofing Roofs & Decks 39579 643.TP0832.03 - MHB - Temporary Waterproofing Roofs & Decks 39579 643.TP0832.03 - MHB - Temporary Waterproofing Roofs & Decks		642.TP.1135.02 - MHB - Sunshades & Light Shelves 642.TP.1131.01 - MHB - Metal Windows 642.TP.1131.01 - MHB - Metal Windows 642.TP.1131.01 - MHB - Roofing-Built-up / Membrane 642.TP.1712.01 - MHB - Tanks & Pumps Supply 642.TP.1712.01 - MHB - Tanks & Pumps Supply 642.TP.1732.02 - MHB - Sanitaryware & Tapware Supply 642.TP.1732.02 - MHB - Sanitaryware & Tapware Supply 642.TP.1732.01 - MHB - Metal Louvres 642.TP.1233.01 - MHB - Metal Louvres 642.TP.1235.01 - MHB - Metal Louvres 642.TP.1235.01 - MHB - Metal Sheeting 642.TP.1235.01 - MHB - Metal Sheeting 643.T.TP1636.01 - FMC - Roof Metal Sheeting 643.T.TP1630.01 - FMC - Facade Framing 642.TP.1030.01 - FMC - Sunshades and Light Shelves 643.T.TP1810.02 - FMC - Mechanical Services - Cooling Tower Supply 643.T.TP1810.01 - FMC - Mechanical Services - Tanks 643.T.TP1810.01 - FMC - Metal Louvres 643.T.TP123.01 - FMC - Metal Louvres 643.T.TP1231.01 - FMC - Metal Louvres 643.T.TP1235.01 - FMC - Metalwork 643.T.TP1236.01 - FMC - Metalwork 643.TP1237.01 - FMC - Metalwork 643.TP1235.01 - MHB - Coolrooms & Cleanrooms
411	643.1.TP3832.01 - FMC - Waterproofing & Tanking - Roofs & Decks	95687 95699	643.1.TP1637.01 - FMC - Coolrooms & Cleanrooms 644.1.TP1630.01 - CP1 - Roofing
	100 m	95700	643.2.TP1630.01 - MHU - Roofing & Metal Cladding
93723 644.1.T	644.1.TP0832.01 - CP1 - Waterproofing	95701	643.2.TP1636.01 - MHU - Wall Cladding Systems
	642.TP2335.01 - PRW - Site Wide LV Equipment Supply	95707	643.1.TP1131.01 - FMC - Metal Windows
93860 641 TPC	641 TP0410 01 - RIF - Concrete Supply		יייי בדרביים ואוכום אווומסאים

Lip Progress Report #16 Scuh Pebruary201449 P8.772

bage 6

Local Industry Participation, Sunshine Coast University Hospital: Progress Report February 2014

7641. 7P3132.01 - RIE - Landscaping Structures / Carpentry 643.2.TP1135.01 - MHU - Sunshades & Light Shelves 642.TP.1332.01 - MHB - Doors & Door Frame Supply 643.2.TP3130.01 - MHU - Hard / Soft Landscaping 643.2.TP131101 - MHU - Doors & Frames Supply 643.2.TP3530.01 - MHU - Temporary Carpentry 642.TP.2630.01 - MHB - Ceilings and Partitions 643.2.TP1520.01 - MHU - Door Hardware Fix 643.2.TP1436.01 - MHU - Artworks - Internal 644.1.TP1230.03 - CP1 - General Metalwork 641 TP3131.02 - RIE - Plant / Nursery Supply 642.TP.1436.01 - MHB - Artworks - Internal 642.TP.1330.01 - MHB - General Carpentry 643.2.TP1032.01 - MHU - Facade Framing 643.2.TP1131.01 - MHU - Metal Windows 642.TP.2930.01 - MHB - Glazing & Mirrors 643.2.TP1235.01 - MHU - Metal Louvres 643.1.TP1239.01 - FMC - Metal Shelving 643.1.TP2235.01 - FMC - Dock Levelers 642.TP.1236.01 - MHB - Roller Shutters 644.1.TP1235.01 - CP1 - Metal Louvres 641.TP3131.01 - RIE - Soft Landscaping 643.1.TP3130.01 - FMC - Landscaping 643.2.TP1230.01 - MHU - Metalwork 643.2 TP0057.01 - MHU - Final Clean 643.1. P0057.01 - FMC - Final Clean 644.2.TP0057.01 - CP2 - Final Clean 644.1.TP0057.01 - CP1 - Final Clean 642. TP. 0057,01 - MHB - Final Clean 642.TP.1433.01 - MHB - Furniture 643.2.TP1430.01 - MHU - Joinery 642.TP.1430.01 - MIHB - Joinery 99878 96866 95778 92696 96073 96159 96635 97023 90868 93826 96151 96169 96509 96944 97039 86866 96177 97037 97273 99804 53827 76866 99925 99662 97312 99917 99921 99951 29666 99972 99997 640.PR0022.02 - PRW - Temporary Lunch/Sheds / Ablusions / Containers / Other 640.PR0032.02 - PRW - Main Site Office & Acoomy Odation Temporary Electrical 640.PR0033.02 - PRW - Main Site Office Accommodation Temporary Hydrautics 640.PR0033.03 - PRW - Temporary Hydraulics Site Wide Reticulation 641.TP1732.01 - RIE - Water & Fire Mains reticulation 642.TP.1434.01 - MHB - Workstations & Screens 642.TP.0420.01 - MHB - Concrete Place & Finish 640.PR0023.03 - PRW - Temporary Site Signage 643.1.TP2630.01 - FMC - Ceilings and Partitions 644.2.TP1311.01 - CP2 - Door and Frame Supply 643.2.TP2630.01 - MHU- Ceilings and Partitions CP1.TP2335.01 - CP1/CP2 - Light Fitting Supply 644.1.TP2630.01 - CP1 - Ceilings and Partitions 643.1.TP2312.01 - FMC - HV Generator Supply 641.TP3131.01 - CP2 - Soft/Hard Landscaping 643.1.TP1531.01 - FMC - Hardware - Sundry 642.TP.0422.01 - MHB - Concrete Rumping 644.2.TP1330.01 - CP2 - General Carpentry 642.TP.0431.01 - MHB - Precast Concrete 644.2.TP1131.01 - CP2 - Facade / Screens 643.2.TP2930.01 - MHU - Internal Glazing 642.TP.2734.01 - MHB - Epoxy Flooring 642.TP.3131.01 - MHB - Mature Trees 642.TP.2720.01 - MHB - Carpet Laying 642.TP.1311.01 - MHB - Doors Supply 640.PR0022.07 - PRW - Pest Control 644.2.TP0830.01 - CP2 - Blackwork 642.TP.0060.01 - MHB - Scaffolding Any Opportunities - General Clean 643.2.TP3030.01 - MHU - Painting 643.1.TP3030.01 - FMC - Painting 642.TP.3030.01 - MHB - Painting 93918 93938 94122 94130 94234 94256 94119 94283 94285 94320 97314 94271 94272 94353 94363 94415 97330 97432 97433 97443 97446 97454 94362 97450 97464 97624 97693 97728 97863 97864 97913

Document 82

Lip Progress Report #16 Scuh February 201449 P8.772

Local Indus	Local Industry Participation, Sunshine Coast University Hospital: Progress Report February 2014		page 7	
98075	642.TP.1532.01 - MHB - Signage	100003	641.TP1712.01 - RIE - Tanks & Pumps Supply	
98145	644.1.TP1311.01 - CP1 - Door and Frame Supply	100007	642.TP.1531.05 - MHB - Trolleys	
98155	643.1.TP1311.01 - FMC - Door Supply	100020	643.2.TP1030.01 - MHU - Structural Steelwork	
98336	642.TP.2732.02 - MHB - Vinyl	100029	642.TP.1437.01 - MHB - Reception Joinery	
98348	644.1.TP2732.02 - CP1 - Vinyl Installation	100030	643.2.TP1437.01 - MHU - Reception Joinery	
98352	644.1.TP1330.01 - CP1 - General Carpentry	100032	644.2.TP1230.02 - CP2 - General Metalwork	
98354	643.1.TP1330.01 - FMC - Door/& Hardware Fixing	100078	643.1.TP1732.02 - FMC - Greywater Treatment System	
98468	642.TP.2711.01 - MHB - Floor Mats	100079	643.1.TP1532.01 - FMC - Signage	
98473	642.TP.2731.01 - MHB - Insitu Floor Coverings	100449	642.TP1732.061 - MHB - Reverse Osmosis Plant & Equipment	
(C) 98477	642.TP.2735.01 - MHB - Tactile Indicators	99309	643.2.TP2711.01 - MHU - Floor Mats	
98495	642.TP.2830.01 - MHB - Tiling	99310	642.TP.1435.01 - MHB - Folding Doors & Operable Walls	
98500	643.1.TP2720.01 - FMC - Carpet Install	99314	643.1.TP1435.01 - FMC - Folding Doors & Operable Walls	
98585	642.TP.1433.03 - MHB - Furniture - Seating	99315	643.2.TP1435.01 - MHU - Folding Doors & Operable Walls	
68286 (OE)	642.TP.1433.02 - MHB - Medical Furniture	99316	643.2.TP2732.02 - MHU - Vinyl Install	
00 00 00 00	642.TP.2737.01 - MHB - Wall Protection	99322	643.2.TP2731.01 - MHU - Insitu Floor Coverings	
	642.TP.1433.04 - MHB - Compactus Units	39409	643.2.TP2735.01 - MHU - Tactile Indicators	
	643.1.TP2732.02 - FMC - Vinyl Install	99423	643.2.TP2737.01 - MHU - Wall Protection	
	642.TP.1533.01 - MHB - Whitegoods	99428	643.2.TP3131.01 - MHU - Mature Trees	
	643.2.TP1533.01 - MHU - Whitegoods	96494	642.TP.1520.01 - MHB - Hardware & Ironmongery - Fix	
98843	643.1.TP1520.01 - FMC - Hardware & FFE Fixing) (99504 / <	642.TP.1531.02 - MHB - Bin Hardware	
98993	644.1.TP2239.01 - CP1 - Carparking Control Systems	(10566)	640. PR0053.01 - PRW - Overall Onsite Surveying	
98997	643.2.TP2720.01 - MHU - Carpet Laying	99528	542.TP.1534.04 - MHB - Grab Rails	
99012	642.TP.3530.01 - MHB - Temporary Carpentry	99542	643.1(TP4430,01 - FMC - Joinery	
89066	642.TP.1432.01 - MHB - Curtains & Blinds	99695	642. TP. 15.10.02 - MHB - Door Hardware	
99101	643,2,TP1432.01 - MHU - Curtains & Blinds	99708	643.1.TP1510.01 FMC - Door Hardware	
99216	643.2.TP2734.01 - MHU - Epoxy Flooring	99709	643.2.TP1510.01 - MUU - Door Hardware Supply	
99219	643.1.TP2731.01 - FMC - Epoxy Flooring	99733	642.TP.1238.01 - MHB - Metalwork - Stainless Steel	
99231	643.2.TP1330.01 - MHU - General Carpentry	98736	643.2.TP1238.01 - MHU - Metalwork Stainless Steel	
99234	643.2.TP2830.01 - MHU - Tiling	99740	643.1.TP1238.01 - FMC - Stainless Steel Metalwork	
99241	643.1.TP1533.01 - FMC - Whitegoods	7226	641.TP3130.01 - RIE - Hard Landscaping	
99243	643.1.TP1236.01 - FMC - Roller Shutters	99782	642.TP.3130.01 - MHB - Hard & Soft Landscaping	
99245	643.1.TP1434.01 - FMC - Workstations & Screens	99797	642.TP.1239.01 - MHB - Metal Shelving	
99260	643.2.TP1434.01 - MHU - Workstations & Screens	99766	642.TP.1531.01 - MHB - Hardware Sundry	
			Lip Progress Report #16 Soul February 201449 PB 772	

Lip Progress Report #16 Scuh February 201449 P8.772

page 8	643.2.TP1531.01 - MHU - Sundry Hardware	643.2.TP1433.01 - MHU - Furniture					(C)	
	99267	99301			•		Ž)	7
Local Industry Participation, Sunshine Coast University Hospital: Progress Report February 2014		b43.2.1P123b.01 - MHU - Roller Shutters						
Local Indi	99264		14/1]5-0	PO Doc	ument 84		

Attachment B:					
Business Engagement		LIPP Categorisation	Source of Supply	T	
Subcontractor	Reason	REQ - Regional QLD	C-Contestable L:-Local	PostCode	Values of Goods o
		AUS - Rest of Australia IMP - Imported			Services supplied
Arrialgamated Pest Control	Redback Pest Control to SCUH Site Office		L	4561	s.47(3)(b
Arjohuntleigh	Medical Beds and Patient Lifting System	IMP	С	6163	
Arunta Plastics (QLD) Pty Ltd	Cultural Heritage Induction	SEQ		3134	
ATF Services Pty Ltd	Temp Fencing	SEQ	L	4558	
ATF Sunshine Coast and Total Site Set Up Beavis & Bartels Pty Ltd	Supply & Install crowd control barriers Temp Hydraulics (Site Wide)	SEQ SEQ	C	4000	
Bizfurn Express	Supply and Install of office furniture for Pr		C	4013 4561	
Blue Giue Ptv Ltd	Blue Glue	AUS		2113	
Builtsmart Modular Mining Pty Ltd	Modular Prototype Suite	AUS	60	2250	
Calty Constructions	Prototype Building Foundations	SEQ	(1)	4556	
Cally Constructions	Protoype Marketing Rigging and Marketing		___\	4556	
Coates Hire Operations Pty Ltd	Portable toilets	SEQ		4131	
Coates Hire Operations Pty Ltd	General Hire Equipment	SEQ	120	4131	
Combined Security Services	Security Guards	SEQ		4575	
D&J Services	Site Shed Cleaning	SEQ	() () ()	4011	
DLA Piper	Professional fees	AUS	~/·	4000	
Ounckers Pty Ltd	Supply of Site Accomodation Cleaning Pro			4560	
nergex Limited	Energex Detailed Design	SEQ /	L.	4558	
nergex Limited	Temporary Electrics supply South	SEQ SEQ	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	4006	
Energy Crane Services Pty Evolution Trafic Control	Transport Items to SCUH site Provide traffic Controller	SEQ	// <u> </u>	4034	
VS Group Australia Ptv Ltd	Site Security	SEQ		4558	
encepac	Site Perimeter Security Fence - Stage 1	SEG.	C	4350 4556	
loor cover QLD - AK	Installation of vinyl and carpet to the Profe		c	4008	
redon QLD Pty Limited	SCUH - Nambour Site	SEQ	C	4119	
James	Supply and install of windows and external	SEQ	L	4556	
Sordon Clements Nominees Pty Ltd T/A Calty Cons		SES		4556	
reenbins	Size 8 Bin	SEQ	<u> </u>	4074	
larvev Norman	Supply of kitchen fridge and microwave	7 / SEQ	č	4575	
en Wilson & Associates Pty Ltd T/a KWA Blinds	Prototype Curtain & IV Tracks	SEQ	c	4163	
yana Projects Pty Ltd	Supply of Bulk Potable and Non-Potable V	SEQ		4567	
yana Pty Ltd	Temporary Hydraulios	SEQ	С	4567	
ucid Edge PTY LTD	Video conversions from AVI to MWV+ You	AUS	C	4014	
ucid Edge PTY LTD	Video Conversions from AV to MWV +	7 AUS	_ C	2010	- 47(0)(1-
ferlon (t/a Statewide Communications)	Prototype Nurse Sall & PES	AUS	C	4113	s.47(3)(b
fetro Express	2 Containers sent from GCUPNo SCUH	SEQ	L	4106	
fidmed	Supply and install of examination couch	SEQ	C	4570	
fultimedia Technology	83" Multi Touch Interactive Whiteboard	SEQ	С	4006	
leverfail Springwater Limited ilsen QLD Ptv Ltd	Supply of Poteble Water to Site until Feb 1	SEQ	C	4127	
2 Environmental Pty Ltd	Temporary Electrical CP2 & Prototype Environmental and Sediment Monitoring	SEQ	C	4170	
Prange Hire Pty Ltd	Supply & Hire of Perimeter Fencing	SEQ SEQ	L	4573	
huality Choice Signs	Re skinto existing Billboard	SEQ	L C	2760 4575	
huality Choice Signs	Signage	SEQ	C	4575	1
Huality Choice Signs	Hard Har Stickers	SEQ	C	4575	1
egson Fabrication	Suppy & Install & Gate Closures	SEQ	c	4556	
obotic Automation Group	AGV Advisory Services	AUS	C	2127	
capeshape Pty Ltd	Palmtree re-location	SEQ	L	4211	1
hadforths Civil Pty Ltd	Crossover road Construction	SEQ	<u> </u>	4556	
hadforths Civil Pty Ltd	Supply & replace Road Base - Site Accord	SEQ	_ L	4556	
hadforths Civi! Pty Ltd	CP2 Early Works	SEQ	L	4556	
iemens	Prototype Security	iMP .	С	4006	
pence Door	Supply doors and frame	SEQ	L	4556	
teve Ryan t/as Rix Ryan Photography P/L	Photograph Palm removal & monthly image	SEQ	L	4215	
uncoast Water Carriers	Re-Fili 2 x 10000L Water Tanks + 1 Additi	SEQ	L	4551	
mediate Response First Aid	Car Park First Aid Shed & First Aid	SEQ	L	4556	
ne trustee for The S. & DY Eade Family Trust T/A		SEQ	C	4570	
anspacific Industries Pty Ltd	Site Sewerage Tank Pump Out	SEQ	С	4064	
	3x3 Combination light set & Trump! Serv	IMP	С	2067	
	- Paragraph in the control of the co	SEQ	C	4553	
numpf Med Australia Pty Ltd Inderground Pipe and Cable Location Pty Ltd	Detect inground services prior to digging f			1 4550	4
nderground Pipe and Cable Location Pty Ltd niversal Cranes Sunshine Coast Pty Ltd	Mobile Crane Hire	SEQ	<u>L</u>	4556	
nderground Pipe and Cable Location Pty Ltd niversal Cranes Sunshine Coast Pty Ltd iridian	Mobile Crane Hire Supply and deliver of Mirrors for Prototype	SEQ	C	4173	
nderground Pipe and Cable Location Pty Ltd niversal Cranes Sunshine Coast Pty Ltd iridian agstaff Piling	Mobile Crane Hire Supply and deliver of Mirrors for Prototype Site Probing Works - 55 Probe Locations	SEQ SEQ	C L	4173 4060	
nderground Pipe and Cable Location Pty Ltd niversal Cranes Sunshine Coast Pty Ltd iridian	Mobile Crane Hire Supply and deliver of Mirrors for Prototype	SEQ	C	4173	

Attachment C:						
Business Engagement		LIPP Categorisati	Source of Supp	ly		
Subcontractor	WorkPackage	SEC - South Beat GLD		PostCode	Values of Goode and Services	Suppler's locals
A1 Waterproofing	642.TP0832.01 - MHB - In ground Waterproofing	SEQ	С	4165	s.47(3)(b	Brisbane - East
A1 Waterproofing & Applications Pty Ltd	643.1.TP0832.01 - FMC - Waterproofing	SEQ	Ĺ	4165		Brisbane - East
Able Security Group	641.TP1510.01 - CP2 - Door Hardware Supply	SEQ	L	4575		Sunshine Coast
ALS	641.TP1712.01 - CP2 - Rainwater Tanks	SEQ	L	4575		Sunshine Coast
Amalgamated Painting	640.TP3030.01 CP2 - Painting	SEQ	C	4214		Gold Coast
ASP Piÿng Pty Ltd	643.1.TP0330.01 - FMC - Sheet Piling	SEQ	L	4214		Gold Coast
Beavis & Bartels Pty Ltd	MHB - Temporary Hydraulics	SEQ	c	4060		S E Qkd
Boral Construction Materials (QLD)	644.2.TP0410.01 - CP2 - Concrete Supply	SEQ	L	4059		Brisbane Inner C
Bosform Pty Ltd	643.1.TP0530.01 - FMC - Formwork	SEQ	ī	4287	> .	Gold Coast
Coastcrete	642.TP.0431,01 - MHB - Precast	SEQ	c	4218	$\langle \cdot \rangle$	Gold Coast
Custom Shades Pty Ltd	641.TP1633.00 - CP2 - Shade Structure	SEQ	C	4173) <i>)</i>	Brisbane - East
Delco Steel Old Pty Ltd	642.TP0620.01 - MHB - Reo Fix	Other States	C	7 2000	\vee	VSW
Delco Steel Old Ptv Ltd	644.2.TP0620.01 - CP2 - Reinforcement Fix	Other States	Q (2000		NSW
Delco Steel Old Pty Ltd	643.1.TP0620.01 - FMC - Reinforcement Fixing	Offer States	<u> </u>	2000		NSW
Designa Sabar	641.TP2430.01 - CP2 - Car Park management syste			5009		SA
East Coast Concrete Contractors	644.2.TP0420.01 - CP2 - Concrete Place and Finish	Other States		2485		VSW
Eastcoast Concrete Contractors	642.TP0420.02 - MHB - Concrete Place	Other States	(7 ₀ / ₀)	7 2485		VSW
Eastcoast Concrete Contractors	642.TP.0420.01 - MHB - Substructure, incl Pile trimi		/(()	2485		VSW
FIP Electrical (Qld) Pty Ltd	644.2.TP2330.01 - CP2 - Electrical Installation	SEQ		4144		Brisbane Inner C
redon Electrical	641.TP2530.01 - CP2 - ICT	SEQ	7\c\	4119		ogan - Beaudes
Gordon Clements Nominees Pty Ltd T/A		SEQ	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	4556		Sunshine Coast
leinrich	642.TP0530.01 - MHB - Formwork	SEG	기 /: 	4207		S E Old
lolcim	642.TP0410.01 - MHB - Concrete Supply	REG		4701		REG Old
Anly Concrete	643.1.TP0420.01 - FMC - Concrete Placing	SEQ	-	4173		Brisbane - East
Aatchett	642,TP0830,01 - MHB - Blockwork	SEQ	L	4559		Sunshine Coast
Natchit Blocklaying	644.2.TP0830.01 & 644.1.TP0830.01 - Blockwork C		L	4559		Sunshine Coast
Oneform	644.2.TP0530.01 - CP2 - Install Formwork	SEA	L L	4173		Brisbane - East
Onesteel	643.1.TP0410.01 - FMC - Reo Supply	SEQ	L	41/3		
Dnesteel	642.TP0610.01 - MHB - Rec Supply	SEQ	C	4108	s.47(3)(b)	Brisbane - South S E Old
OTIS Elevator Company Pty Ltd	642.TP.2030.01 - MHB - Vertical Transportation	/ SEQ	C			
OTIS Elevator Company Pty Ltd	643.1.TP2030.01 - FMC - Vertical Transportation	SEQ	C	4101		Brisbane Inner C
OTIS Elevator Company Pty Ltd	643.2.TP2030.01 - MHU - Vertical Transportation			4101		Brisbane Inner C
OTIS Elevator Company Pty Ltd	644.1.TP2030.01 - Ninu - Vertical Transportation	SEQ	C	4101		Brisbane Inner Ci
Penfolds	640.TP3131.01 - CR2 - Landscaping	SEQ	С	4101		Brisbane Inner Ci
		SEQ	L 1	4553		Sunshine Coast
Pickwick Group Pty Ltd	PR0057.03 CP2 - General Clean	SEQ	L	4101		S E Qid
olyseal Waterproofing QLD Pty Ltd	644.2.TP#832.01 - CP2 - Waterproofing	SEQ	С	4207		Gold Coast
remier Signs	640.TP 532.01 - CR2 - Signage	SEQ	С	4108		Brisbane - South
ro Concrete Pumping	644.2 TP0422.01 CP2 Concrete Pumping	SEQ	L	4220		old Coast
ro Concrete Pumping	642-TP0422.01 - MHB Concrete Pumping	SEQ	С	4220		S E Qld
LD Drink and Snack Machines	640 PR0022.08 - PRW - Vending Machines - CP2	SEQ	С	4559		Sunshine Coast
legson Fabrications	641.TV 1240.01 - CP2 - Façade	SEQ	L	4556		Sunshine Coast
legson Fabrications	640/1P1230.01 - CP2 - General Metalwork	SEQ	C	4556		unshine Coast
hadforth Civil Engineering	641.TK 0230.01 - RIE - Bulik Earthworks and Fill	SEQ	L	4556		Sunshine Coast
hamrock Civil	641.TP.0230.02 - RIE - Preload	SEQ	L	4076		pswich
ilemens	641.TP2490.01 - CP2 - Security	Other Status	С	3153		/IC
	644.2.TP0631.01 - CP2 - Post Tensioning	SEQ	С	4207		old Coast
unshine Coast Air Conditioning Service		SEQ	С	4556		unshine Coast
	644.2.TP1732.01 - CP2 - Hydraulics	SEQ	С	4573		Sunshine Coast
Inispan Australia Pty Ltd	644.2.TP0060.01 - CP2 - Scaffolding	SEQ	С	4207		old Coast
T Services	Tower Crane to CP2	SEQ	L	4074		risbane - West
Vagstaff Piling Qld Pty Ltd	641.TP0330.02 - CP1 - Piling	SEQ	L	4060		Brisbane
Vagstaff Piling Qld Pty Ltd	643.1.TP0330.02 - FMC - Precast Piling	SEQ	L	4060		risbane Inner Ci
cintral Concreting Pty Ltd	641 21P0420.01 - CP1 - Congrete Place and Prinsf	(H. 1826)	1	4034		EOM
	844.1.TP2930.01 - CP2 - Vertical Transportation	SEQ	C	4000		EOM
	642 TP 0631 01 - MHB - Fost Tensioning	· SEQ	C	4207		E Qid

Note: Substructure wasn't listed on ICN Gateway website as an opportunity for companies to register through ICN.





Sunshine Coast University Hospital: Local Industry Participation

A Division of QMI Solutions

Progress Report #17 for period to 31 March 2014 Prepared by Industry Capability Network (Queensland) Ltd

This report details the assistance provided during the above period by ICN (Qld) to Lend Lease in the delivery and implementation of the Local Industry Participation Plan (LIPP) for the Sunshine Coast University Hospital in accordance with the Local Industry Policy (LIP).

1. Liaison with the Project on LIP Issues

ICN met with Queensland Health (Sam Betros) in May 2011 to discuss the project ICN services, and LIP procedures and issues. ICN assisted QH in the development of the LIPP for the project and provided an evaluation report to QH on project bidders' LIP plan submissions in March 2012.

2. Liaison with Lend Lease on LIP Compliance

Lend Lease met with ICN to establish processes and procedures for management of the project's obligations to the LIP. It was decided that ICN will provide support on number of services covering:

- Implementation of the LIPP (capability searches or contestable packages)
- Presenting at briefing sessions
- Registering companies via ICN Gateway
- Verification of source of manufacture and service provision in subcontracts
- Business matching
- Progress reporting (Monthly) and final LIPP Outcomes reporting (at end of project)

3. Tier Barometer

Tier Barometer is an on-line self-assessment tool developed by ICN and the State Government. It provides participating companies with an assessment of their tier level in terms of supply to major projects. The tool is used by the project to analyse the basic capabilities of potential suppliers during the registration process.

4. Contestable Packages

Contestable items or packages are those that could potentially be sourced locally or overseas but do not include designated items such as concrete supply, earthworks, etc., which it is assumed will always be supplied from sources local to the project. Nor do they include items that have no chance of being manufactured in Australia, eg turbines. LL supplied ICN with the full schedule of subcontract trade packages for the project. ICN subsequently allocated these into contestable and non-contestable packages.


5. Work Packages

Queensland and Australian capability, content and capacity will be considered for all the work packages. The following activities have been undertaken:

- An ICN officer has been assigned full time to the project.
- Detailed Business Matching has been carried out by ICN. 261 work packages have been managed in this way. These are listed at Attachment A.
- 1485 registrations against work packages on Gateway have been received
- 65 early works have been awarded in March. These are listed at Attachment 8.
- 55 work packages have been awarded so far and they are listed at AttachmentsC.

Potential subcontractors will be given an indication of the size and generic nature of the project, and questioned regarding their capability and capacity to carry out the work, code compliance, and previous work history. Reports will be sent to Lend Lease detailing local companies which have the capability and capacity to carry out the work for each of the above packages. The primary objective of the Local Industry Policy is to ensure that competitive local companies are given full, fair and reasonable opportunity to tender for work packages. This objective will be achieved if the companies nominated by ICN, and other local companies that Lend Lease is aware of, are considered in the establishment of the tender list, and, subject to meeting pre-qualification criteria, a reasonable number of local companies are subsequently invited to tender. Lend Lease intends to apply this requirement.


6. Source of Supply



Lend Lease has advised that out of 113 Purchase Orders, 65 were awarded for early works, one for Substructure and 55 for Work Packages listed on the ICN Gateway Project webpage. These were to companies that registered interest via ICN. As far as practicable, the measurement of industry participation focuses on the actual source of supply rather than the location through which the order is placed. The location in which services are provided, materials manufactured or where value adding takes place is indicative of the actual source of supply. Of the 55 Work Package contracts that have been awarded, 46 were won by South East Queensland (SEQ) companies, one by Regional Queensland, six by New South Wales companies, one by Victoria and one by South Australia.

As subcontracts are awarded, the source of manufacture or service provision for contestable packages will be validated and verified in discussion with the corresponding subcontractors. The aggregate value to Queensland and Australian industry will be reported for all packages, and for contestable packages alone. The aggregate value to Queensland and Australian industry of packages awarded so far has been estimated across all trade packages (including both contestable and non-contestable packages) and is currently:

Value of contracts awarded (to date): \$ 152.01 M
Value of components made in Qld in contracts awarded (to date): \$ 148.9 M
Value of components made in other states & NZ in contracts awarded (to date): \$ 0 M
Value of components made overseas in contracts awarded (to date): \$ 2.11 M





These figures are shown graphically in the diagram on the left (top) in terms of the percentage by value of all contracts awarded (contestable and non-contestable), with the Queensland content in the project broken down into Local, South East Queensland, Regional Queensland, Other States and New Zealand, and Overseas figures. The total Queensland content is currently 98.01%.

However, the Local Industry Policy is concerned mainly with contestable contracts as "Local" components are assumed to always be available from sources that are geographically close to the project location. The figures for contestable contracts only are shown in the diagram on the left (bottom), and these figures are included in reports back to the Department of State Development, Infrastructure and Planning (DSDIP). The Queensland content for contestable contracts is currently 93%.

A total of 55 contracts (including 23contestable contracts) have been awarded where the source of manufacture or service provision is predominantly within Queensland. No contract was awarded directly to regional companies, as the project was predominantly based in South East Queensland.

7. Prototype Building

A prototype showcase building was erected in record time. This enabled focus group to provide input in to the final design in a cost effective manner.

8. Local Industry Participation

Lend Lease Project Director has personally provided project work scope and Lend Lease supplier engagement approach information to a number of larger Australian Manufacturers who have asked for more information. These include The GWA Group; The Laminex Group; Spence Doors and Rockcote Industries. For the latter company time was dedicated to a site inspection of their manufacturing facilities.

9. Information Sessions

ICN supported Lend Lease in delivering briefing sessions as proposed in their LIP plan covering:

Monday 3rd September 2012 – Civil, Infrastructure, Structure & Landscaping

Monday 17th September 2012 - Services

Monday 24th September 2012 - Roof & Facade

Monday 8th October 2012 – Fit out & Finishes

Monday 15th October 2012 Furniture Fittings & Equipment (FF&E)

Lend Lease also presented at the General Briefing Sessions along with ICN on 13, 14, 16 and 20th of August 2012.

Lend Lease project managers attended a briefing presentation by the members of the Cleantech Industries group of companies on 24th September 2012.

Lend Lease took part in a Local Business expo on 10th May 2013.

ICN - Evan Flower - presented to the Gympie Major Project Opportunities Forum on the project on 18th June 2013.

10. Efforts to engage with Local Companies include:

Press release by Health Minister, radio interviews by Project Director, Newspaper articles in CM and Sunshine Coast Daily followed up by substantial advertisements in the same newspapers on 19th January. Support articles followed from SSC Council and local councillors.

As a result of the above information sessions and the advertising campaign almost 1000 registrations have been received with close to 100 companies listing after the newspaper advertisements.

To date over 1469 companies have registered interest in work packages.

11. Source of Manufacture

As subcontracts begin to be awarded, the source of manufacture or service provision for contestable packages will be validated and verified in discussion with the corresponding subcontractors.

12. Reporting

- Business matching reports on companies nominated for the trade packages listed at Attachment A are being provided to Lend Lease.
- A summary of LIP progress is shown in Attachment D.
- The six monthly review of overall progress by Lend Lease in delivering on Local Industry Participation Plan commitments is also shown in Attachment E. This covers the period from June to December 2013 and was submitted to Queensland Health on 10th March 2014. Also shown at Attachment F is the template for the letter from Lend Lease to unsuccessful companies.

Evan Flower

Senior Consultant - Capability Services

ICN Queensland

Attachmer	t A r (15 km m m m m kg 1 m m m m m m m m m m m m m m m m m m		
Enquiries D	etails		
Enquiryid	Title	Enquiryid	Title
90992	PR.0051.01 Crossover Road Construction	95588	643.1.TP1030.01 - FMC - Structural Steelwork
90993	TP.0231.01 Preload	95592	643.1.TP2236.01 - FMC - Kitchen / Laundry Equipment
90994	TP.0320.01 Sediment control	95686	642.TP.1637.01 - MHB - Coolrooms & Cleanrooms
90995	PR0059 Site Security	95687	643.1.TP1637.01 - FMC Coolrooms & Cleanrooms
91583	644.2.TP1732.01 - CP2 - Hydraulics	95699	644.1.TP1630.01 - CP1 Ropfing
91584	644.2.TP0620.01 - CP2 - Reinforcement Fixing	95700	643.2.TP1630.01 - MHU Roofing & Metal Cladding
91585	644.2.TP0530.01 - CP2 - Formwork	95701	643.2.TP1636.01 - MHD - Wall Cladding Systems
91586	644.2.TP0422.01 - CP2 - Concrete Pumping	95707	643.179131.01 - FMC - Metal Windows
91587	644.2.TP0420.01 - CP2 - Concrete Placing	95777	644.1771131.01F CP1 - Facade / Screens
91588	644.2.TP0410.01 - CP2 - Concrete Supply	95778	643.2.TP1032.01 - MHU - Facade Framing
91589	644.2.TP0060.01 - CP2 - Scaffolding	95902	644.1.791235.01 - CP1 - Metal Louvres
91877	645.TP3230.01 - Kawana Way Duplication	95906	643.2.TP1131.01 - MHU - Metal Windows
92438	641.TP.0230.01 - RIE - Bulk Earthworks and Fill	96073	644.2.TP0057.01 - CP2 - Final Clean
92499	641.TP.3230.01 - RIE - Roads & Infrastructure Services	96151	643.2.TP1135.01 - MHU - Sunshades & Light Shelves
92500	644.2.TP2239.01 - CP2 - Carpark Control System	96159	643.2.TP1230.01 - MHU - Metalwork
92677	640.PR0033.01 - PRW - Temporary Hydraulics	96169	643.2.TP1235.01 - MHU - Metal Louvres
92681	640.PR0056.01 - PRW - Rubbish Removal	96177	643.1.TP2235.01 - FMC - Dock Levelers
92990	644,2.TP0832.01 - CP2 - Waterproofing	96509	644.1.TP1230.03 - CP1 - General Metalwork
93076	644.2.TP2330.01 - CP2 - Electrical	96635	643.2.TP3530.01 - MHU - Temporary Carpentry
93094	640.PR0042.01 - PRW - Tower Cranes, Hoists & Crews	96944	642.TP.1330.01 - MHB - General Carpentry
93205	644.2.TP0631,01 CP2 Post Tensjoning	97023	642.TP.1433.01 - MHB - Furniture
93293	642.TP.2030.01 - MHB Vertical Transportation	97037	642.TP.1236.01 - MHB - Roller Shutters
93294	643.1.TP2030.01 - FMC - Vertical Transportation	97039	642.TP.1332.01 - MHB - Doors & Door Frame Supply
93295	643.2.TP2030.01 - MHU - Vertical Transportation	97273	642.TP.2630.01 - MHB - Ceilings and Partitions
93296	644.1.TP2030.01 - CP1 - Vertical Transportation	97312	642.TP.2930.01 - MHB - Glazing & Mirrors
93297	540.PR0041.01 - PRW - Mobile Cranes	97314	643.1.TP1531.01 - FMC - Hardware - Sundry
93314	644.2.TP1830.01 - CP2 - Mechanical	97330	642.TP.3030.01 - MHB - Painting
93315	644.2.TP1712.01 - CP2 - Water Tanks	97432	643.1.TP2630.01 - FMC - Ceilings and Partitions
93506	640.PR0021.02 - PRW - Site Fencing	97433	644.2.TP1311.01 - CP2 - Door and Frame Supply

93511	640.PR0046.01 - PRW - Temporary Plant & Equipment	97443	643.2.TP2930.01 - MHU - Internal Glazing
93513	640.PR0022.06 - PRW - Temporary Onsite Canteen and	97446	643.2.TP3030.01 - MHU - Painting
93514	640.PR0022.05 - PRW - Temporary Carpentry Site Accor	97450	643.1.TP3030.01 - FMC - Painting
93516	644.1.TP0530.01 - CP1 - Formwork	97454	643.2.TP2630.01 - MHU- Ceilings and Partitions
93520	642.TP.0530.01 - MHB - Formwork	97464	644.1.TP2630.01 - CP1 - Ceilings and Partitions
93521	643.2.TP0530.01 - MHU - Formwork	97624	642.TP.3131.01 - MHB - Mature Trees
93523	643.1.TP0530.01 - FMC - Formwork	97693	641.TP3131.01 - CP2 - Soft/Hard Landscaping
93544	643.1.TP2310.01 - FMC - Site Wide HV Equipment Suppl	97728	642.TP.2720.01 - MHB - Carpet Laving
93563	642.TP2335.02 - PRW - Uninterruptable Power Supply U	97863	642.TP.1311.01 - MHB - Doors Supply
93564	644.1.TP0330.02 - CP1 - Pile Cut-off	97864	642.TP.2734.04 - 04HB - Epoxy Flooring
93565	643.2.TP0330.02 - MHU- Pile Cut-off	97913	Any Opportunities - General Clean
93566	643.1.TP0330.02 - FMC - Pile Cut-off	97915	642.TP(1434/01 MHB - Workstations & Screens
93567	642.TP.0330.03 - MHB - Sheet Piling	98075	642-TP-1532-01 - MHB - Signage
93568	642.TP.0330.02 - MHB - Pile Cut-off	98145	644.2.7F1311.01 - CP1 - Door and Frame Supply
93569	643.1.TP0330.03 - FMC - Sheet Piling		643.1.TP1311.01 - FMC - Door Supply
93572	644.1.TP0620.01 - CP1 - Reinforcement Fix	98336	642.TP.2732.02 - MHB - Vinyl
93573	642.TP.0620.01 - MHB - Reinforcement Fix	98348	644.1.TP2732.02 - CP1 - Vinyl Installation
93574	642.TP.0631.01 - MHB - Post Tensioning	98352	644.1.TP1330.01 - CP1 - General Carpentry
93575	643.1.TP0620.01 - FMC - Reinforcement Fix	98354	643.1.TP1330.01 - FMC - Door & Hardware Fixing
93576	643.1.TP0631.01 - FMC- Post Tensioning	98468	642.TP.2711.01 - MHB - Floor Mats
93577	643.2.TP0620.01 - MHU - Reinforcement Fix	98473	642.TP.2731.01 - MHB - Insitu Floor Coverings
93578	644.1.TP0631.01 - CP1 - Post Terrsioning	98477	642.TP.2735.01 - MHB - Tactile Indicators
93581	640.PR0052.01 - PRW - Safety Presautions (PPE)	98495	642.TP.2830.01 - MHB - Tiling
93717	642.TP.0832.01 - MHB - Waterproofing Inground	98500	643.1.TP2720.01 - FMC - Carpet Install
93718	642.TP.0832.02 / MHB - Waterproofing Roofs & Decks	98585	642.TP.1433.03 - MHB - Furniture - Seating
93719	642.TP.0832.03 MHB - Jemporary Waterproofing	98589	642.TP.1433.02 - MHB - Medical Furniture
93720	643.1.TP0832.01 - FMC - Waterproofing & Tanking	98683	642.TP.2737.01 - MHB - Wall Protection
93721	643.1.TP3832.01 - FMC - Waterproofing & Tanking - Ro	98706	642.TP.1433.04 - MHB - Compactus Units
93722	643.2.TP0832.01 - MHU - Waterproofing	98794	643.1.TP2732.02 - FMC - Vinyi install
93723	644.1.TP0832.01 - CP1 - Waterproofing	98820	642.TP.1533.01 - MHB - Whitegoods
93827	642.TP2335.01 - PRW - Site Wide LV Equipment Supply	98821	643.2.TP1533.01 - MHU - Whitegoods
93860	641.TP0410.01 - RIE - Concrete Supply	98843	643.1.TP1520.01 - FMC - Hardware & FFE Fixing
93918	642.TP.0420.01 - MHB - Concrete Place & Finish	98993	644.1.TP2239.01 - CP1 - Carparking Control Systems
93938	CP1.TP2335.01 - CP1/CP2 - Light Fitting Supply	98997	643.2.TP2720.01 - MHU - Carpet Laying
			· · · · · · · · · · · · · · · · · · ·

94119 6	540.PR0033.03 - PRW - Temporary Hydraulics Site Wide	99012	642.TP.3530.01 - MHB - Temporary Carpentry
94122 6	641.TP1732.01 - RIE - Water & Fire Mains reticulation	99068	642.TP.1432.01 - MHB - Curtains & Blinds
94130 6	642.TP.0422.01 - MHB - Concrete Pumping	99101	643.2.TP1432.01 - MHU - Curtains & Blinds
94234 6	543.1.TP2312.01 - FMC - HV Generator Supply	99216	643.2.TP2734.01 - MHU - Epoxy Flooring
94256 6	642.TP.0431.01 - MHB - Precast Concrete	99219	643.1.TP2731.01 - FMC - Epoxy Flooring
94271 6	544.2.TP0830.01 - CP2 - Blockwork	99231	643.2.TP1330.01 - MHU - General Carpentry
94272 6	540.PR0032.02 - PRW - Main Site Office & Accommoda	99234	643.2.TP2830.01 - MHU - Tiling
94283 6	640.PR0022.02 - PRW - Temporary Lunch Sheds / Abluti	99241	643.1.TP1533.01 - FMC - Whitegopds
94285 6	542.TP.0060.01 - MHB - Scaffolding	99243	643.1.TP1236.01 - FMC Roller Shutters
94320 6	544.2.TP1131.01 - CP2 - Facade / Screens	99245	643.1.TP1434.01 - FMC Workstations & Screens
94353 6	544.2.TP1330.01 - CP2 - General Carpentry	99260	643.2.TP1434.01 - MHU - Workstations & Screens
94362 6	640.PR0022.07 - PRW - Pest Control	99264	643.1 TP2830.01 FMC - Tiling
94363 6	340.PR0023.03 - PRW - Temporary Site Signage	99265	643-2.TP1236-01 - MHU - Roller Shutters
94415 6	40.PR0033.02 - PRW - Main Site Office Accommodatio	99266	6424P.1531.01 - MHB - Hardware Sundry
94450 6	340.PR0022.04 - PRW - Site Office Fitout & Furniture	99267	643_2.TP1531.01 - MHU - Sundry Hardware
94506 6	640.PR0056.02 - PRW - Site Office Cleaning	99301	643.2.TP1433.01 - MHU - Furniture
94527 6	643.1.TP0410.01 - FMC - Concrete Supply	99308	643.2.TP2711.01 - MHU - Floor Mats
94534 6	643.1.TP0420.01 - FMC - Concrete Place	9 9310	642.TP.1435.01 - MHB - Folding Doors & Operable Walls
94536 6	643.1.TP0422.01 - FMC - Concrete Pumping	99314	643.1.TP1435.01 - FMC - Folding Doors & Operable Walls
94537 6	643.1.TP0431.01 - FMC - Precast Concrete	99315	643.2.TP1435.01 - MHU - Folding Doors & Operable Walls
94538 6	543.2.TP0410.01 - MHU - Cøncréte Supply	99316	643.2.TP2732.02 - MHU - Vinyi Instail
94539 6	43.2.TP0420.01 - MHU - Concrete Placing	99322	643.2.TP2731.01 - MHU - Insitu Floor Coverings
94540 6	43.2.TP0422.01 - MHU - Concrete Pumping	99409	643.2.TP2735.01 - MHU - Tactile Indicators
94541 6	644.1.TP0410.01 - CP1 - Concrete Supply	99423	643.2.TP2737.01 - MHU - Wall Protection
94542 6	44.1.TP0420.01 - CP1 - Concrete Place	99428	643.2.TP3131.01 - MHU - Mature Trees
94543 6	644.1.TP0422.01 - CP1 - Concrete Pumping	99494	642.TP.1520.01 - MHB - Hardware & Ironmongery - Fix
94627 6	43.1.TP0060.01 - FMC - Scaffolding	99504	642.TP.1531.02 - MHB - Bin Hardware
94628 6	44.1.TP0060.01 - CP1 - Scaffolding	99507	640.PR0053.01 - PRW - Overall Onsite Surveying
94884 6	42.TP.0830.01 - MHB - Blockwork	99528	642.TP.1531.04 - MHB - Grab Rails
94885 6	43.1.TP0830.01 - FMC - Blockwork	99542	643.1.TP1430.01 - FMC - Joinery
94886 6	643.2.TP0830.01 - MHU - Blockwork	99695	642.TP.1510.01 - MHB - Door Hardware

			<u> </u>
94887	644.1.TP0830.01 - CP1 - Blockwork	99708	643.1.TP1510.01 - FMC - Door Hardware
94907	640.PR0054.01 - PRW - Site Photography	99709	643.2.TP1510.01 - MHU - Door Hardware Supply
94959	644.2.TP3030.01 - CP2 - Painting & Line Marking	99733	642.TP.1238.01 - MHB - Metalwork - Stainless Steel
94960	644.1.TP3030.01 - CP1 - Painting & Line Marking	99736	643.2.TP1238.01 - MHU - Metalwork Stainless Steel
94987	644.2.TP1030.01 - CP2 - Structural Steelwork	99740	643.1.TP1238.01 - FMC - Stainless Steel Metalwork
95031	644.1.TP1030.02 - CP1 - Structural Steelwork	99777	641.TP3130.01 - RIE - Hard Landscaping
95033	642.TP.2230.01 - MHB - Building Maintenance Unit	99782	642.TP.3130.01 - MHB - Hard & Soft Landscaping
95101	643.2.TP1631.01 - MHU - Roofing-Built-up / Membrane	99797	642.TP.1239.01 - MHB Metal Shelving
95111	642.TP.1630.01 - MHB - Roof & Metal Cladding	99804	643.1.TP1239.01 - FMC Metal/Shelving
95112	642.TP.1636.01 - MHB - Wall Cladding Systems	99806	644.1.TP0057.01 - CP1 - Final Clean
95121	642.TP.1032.01 - MHB - Facade Framing	99826	641.TP3131.01 -RIE Soft andscaping
95122	642.TP.1132.01 - MHB - Shop Fronts	99827	641.TP3131.02 RIK - Plant / Nursery Supply
95123	642.TP.1135.02 - MHB - Sunshades & Light Shelves	99828	641.Te3132.01 RLE- Landscaping Structures / Carpentry
95124	642.TP.1131.01 - MHB - Metal Windows		642.TP:9057.01 MHB - Final Clean
95193	642.TP.1631.01 - MHB - Roofing-Built-up / Membrane	99897	643.1.1P00\$7.01 - FMC - Final Clean
95318	642.TP.1712.01 - MHB - Tanks & Pumps Supply	99898	643.2.TP0057.01 - MHU - Final Clean
95319	643.2.TP1710.01 - MHU - Sanitaryware & Tapware Supp	99917	643,2.TP1311.01 - MHU - Doors & Frames Supply
95324	642.TP.1732.02 - MHB - Sanitaryware & Tapware Suppl	99931	642.TP.1430.01 - MHB - Joinery
95369	642.TP.1231.01 - MHB - Balustrades & Handrails	99925	643.2.TP1430.01 - MHU - Joinery
95376	642.TP.1230.01 - MHB - Metalwork	99951	642.TP.1436.01 - MHB - Artworks - Internal
95392	642.TP.1235.01 - MHB - Metal Louvres	99965	643.2.TP1436.01 - MHU - Artworks - Internal
95411	642.TP.1232.01 - MHB - Movement Joints	99967	643.2.TP3130.01 - MHU - Hard / Soft Landscaping
95426	643.1.TP1630.01 - FMC - Roof Metal Sheeting	99972	643.1.TP3130.01 - FMC - Landscaping
95427	643.1.TP1636.01 - FMC - Facade Cladding	99997	643.2.TP1520.01 - MHU - Door Hardware Fix
95428	643.1.TP1032.01 - FMC - Facade Framing	100003	641.TP1712.01 - RIE - Tanks & Pumps Supply
95429	642.TP.1030.01 - MHB - Structural Steelwork	100007	642.TP.1531.05 - MHB - Trolleys
95432	643.1.TP1135.01 - FMC - Sunshades and Light Shelves	100020	643.2.TP1030.01 - MHU - Structural Steelwork
95455	643.1.TP1810.02 - FMC - Mechanical Services - Chiller S	100029	642.TP.1437.01 - MHB - Reception Joinery
95456	643.1.TP1810.03 - FMC - Mechanical Services - Cooling	100030	643.2.TP1437.01 - MHU - Reception Joinery
95457	643.1.TP1810.04 - FMC - Mechanical Services - AHU Sur	100032	644.2.TP1230.02 - CP2 - General Metalwork
95458	643.1.TP1810.01 - FMC - Mechanical Services - Tanks	100078	643.1.TP1732.02 - FMC - Greywater Treatment System
95480	643.1.TP1231.01 - FMC - Balustrades & Handrails	100079	643.1.TP1532.01 - FMC - Signage
95543	643.1.TP1235.01 - FMC - Metal Louvres	100449	642.TP1732.061 - MHB - Reverse Osmosis Plant & Equipment
95555	643.1.TP1432.01 - FMC - Curtains & Blinds	1	642.TP.0410.01 - MHB - Concrete Supply
95576	643.1.TP1230.01 - FMC - Metalwork	100795	640.PR0022.08 - PRW - Vending Machines - CP2

Attachment B					
Business Engagement		LIPP Categorisation	Source of Supply		
Subcontractor	Reason	520 - South 284 910	C-Cortestable	Pos Code	Values of Goods or
Separation (S) defined in		REQ - Regional QLD AUS - Rest of Australia	L - Local		Services supplied
- C.	10	IMP - Imported		1	
Amalgamated Pest Control	Redback Pest Control to SCUH Site Office		L	4561	s.47(3)(b
Arjohuntleigh	Medical Beds and Patient Lifting System	IMP	C	6163	
Arunta Plastics (QLD) Pty Ltd	Cultural Heritage Induction	SEQ		3134	
ATF Services Pty Ltd	Temp Fencing	SEQ	L	4558	
ATF Sunshine Coast and Total Site Set Up	Supply & Install crowd control barriers	SEQ	<u>-</u>	4000	
Beavis & Bartels Ptv Ltd	Temp Hydraulics (Site Wide)	SEQ	C	4013	
Bizfurn Express	Supply and Install of office furniture for Pr		0	4561	
Blue Giue Pty Ltd	Blue Glue	AUS	10	2113	
Builtsmart Modular Mining Pty Ltd	Modular Prototype Suite	AUS	(c)/	2250	
Calty Constructions	Prototype Building Foundations	SEQ	1 7	4556	
Calty Constructions	Protoype Marketing Rigging and Marketing			4556	
Coates Hire Operations Pty Ltd	Portable toilets	SEQ		4131	
Coates Hire Operations Pty Ltd	General Hire Equipment	SEQ	(2)	4131	
Combined Security Services	Security Guards	SEQ		4575	
0&J Services	Site Shed Cleaning	SEQ	77/	4011	
DLA Piper	Professional fees	AUS		4000	
Ounckers Pty Ltd	Supply of Site Accomodation Cleaning Pr		N 7	4560	
nergex Limited	Energex Detailed Design	SEQ		4558	
nergex Limited	Temporary Electrics supply South	SEQ		4006	
nergy Crane Services Pty	Transport Items to SCUH site	SEQ	L	4034	
Evolution Trafic Control	Provide traffic Controller	(\$€Q / / \	L	4558	
VS Group Australia Pty Ltd	Site Security	SEA /	L	4350	
encepac	Site Perimeter Security Fence - Stage 2	SEQ	C	4556	
Toor cover QLD - AK	Installation of vinyl and carpet to the Proto	SEQ	С	4008	
redon QLD Pty Limited	SCUH - Nambour Site	SEQ	С	4119	
James	Supply and install of windows and externe	SEQ	L	4556	
Sordon Clements Nominees Pty Ltd T/A Calty Constr			L	4556	
Greenbins	Size 8 Bin	// SEQ	L	4074	
farvey Norman	Supply of kitchen fridge and microwave	SEQ	С	4575	
Ken Wilson & Associates Pty Ltd T/a KWA Blinds	Prototype Curtain & IV Tracks	SEQ	С	4163	
Kyana Projects Pty Ltd	Supply of Bulk Potable and Non-Potable V			4567	
Kyana Pty Ltd	Temporary Hydraulics	SEQ	С	4567	
ucid Edge PTY LTD	Video conversions from AV to MWV+ You	<i></i>	С	4014	
ucid Edge PTY LTD	Video Conversions from AVI to MWV +	AUS	C	2010	s.47(3)(b)
Merlon (t/a Statewide Communications)	Prototype Nurse Call & PES	AUS	C	4113	
Netro Express	2 Containers sent from GCUN to SCUH	SEQ	L	4106	
fidmed	Supply and install of examination couch	SEQ	C	4570	
Autimedia Technology	83" Molti Touch Interactive Whiteboard	SEQ	C_	4006	
leverfail Springwater Limited	Supply of Patable Weter to Site until Feb	SEQ	<u> </u>	4127	
ilsen QLD Pty Ltd	Temporary Electrical CP2.8 Prototype	SEQ	С	4170	
02 Environmental Pty Ltd	Environmental and Sediment Monitoring	SEQ	L	4573	
Orange Hire Pty Ltd	Supply & Hire of Perimeter Fencing	SEQ	L	2760	
Quality Choice Signs	Re skin to existing Billboard	SEQ	C	4575 4575	
Quality Choice Signs Quality Choice Signs	Signage Hard Hat Stickers	SEQ SEQ	C	4575 4551	
egson Fabrication	Suppy & Install 2 Gate Closures	SEQ	C	4556	
agson Faorication	AGV Advisory Services	AUS	C	4556 2127	
capeshape Ptv Ltd	Palmiree re-location	SEQ	L	4211	
hadforths Civil Pty Ltd	Crossover road Construction	SEQ	L	4556	
hadforths Civil Pty Ltd	Supply & replace Road Base - Site Accord		L	4556	
hadforths Civil Pty Ltd	2P2 Early Works	SEQ	L	4556	
iemens	Prototype Security	IMP	- c	4006	
pence Door	Supply doors and frame	SEQ	L	4556	
teve Ryan t/as Rix Ryan Photography P/L	Photograph Palm removal & monthly image		L	4215	
uncoast Water Carriers	Re-Fill 2 x 10000L Water Tanks + 1 Addition		L	4551	
mmediate Response First Aid	Car Park First Aid Shed & First Aid	SEQ	L	4556	
he trustee for The SJ & DY Eade Family Trust T/A			c	4570	
ranspacific Industries Pty Ltd	Site Sewerage Tank Pump Out	SEQ	C	4064	
umpf Med Australia Pty Ltd	3x3 Combination light set & Trumpf Serv	IMP	C	2067	
nderground Pipe and Cable Location Pty Ltd	Detect inground services prior to digging f		C	4553	
	Mobile Crane Hire	SEQ	L	4556	
niversal Cranes Sunshine Coast Ptv I td			c	4173	
hiversal Cranes Sunshine Coast Pty Ltd	ISUDDA and deliver of Mirrors for Promises		•	7174	
iridian	Supply and deliver of Mirrors for Prototype Site Probing Works - 55 Probe Locations		1	4060	
iridian Vagstaff Piling	Site Probing Works - 55 Probe Locations	SEQ	L L	4060 4060	
hiversal Cranes Sunshine Coast Pty Ltd Fridan Vagstaff Piling Vagstaff Piling QLD Pty Ltd Vorktwide Online Printing Market Street	 		L L	4060 4060 4000	

Business Page		I IBB Cotor	Daymen at D	N.		
Business Engagement		LIPP Categorisati				
Subcontractor	WorkPackage	SEQ - Bouth East QLD REQ - Regional QLD AUS - Rest of Australia MP - Imported	C- Contestable L > Local	PostCode	Velues of Goods	Supplier's location
A1 Waterproofing	642,TP0832,01 - MHB - In ground Waterproofing	SEQ	С	4165	s.47(3)(b	Brisbane - East
	643.1.TP0832.01 - FMC - Waterproofing	SEQ	L	4165		3risbane - East
Able Security Group	641.TP1510.01 - CP2 - Door Hardware Supply	SEQ	Ĺ	4575		Sunshine Coast
ALS	641.TP1712.01 - CP2 - Rainwater Tanks	SEQ	L	4575		Sunshine Coast
Amalgamated Painting	640.TP3030.01 CP2 - Painting	SEQ	C	4214		Gold Coast
ASP Piling Pty Ltd	643.1.TP0330.01 - FMC - Sheet Piling	SEQ	L	4214		Gold Coast
Beavis & Bartels Pty Ltd	MHB - Temporary Hydraulics	SEQ	C	4060		S E Qld
Boral Construction Materials (QLD)	644.2.TP0410.01 - CP2 - Concrete Supply	SEQ	L	4059		Brisbane Inner City
Bosform Pty Ltd	643.1.TP0530.01 - FMC - Formwork	SEQ	L	4287	> .	Gold Coast
Coastcrete	642.TP.0431.01 - Mi-B - Precast	SEQ	C	4215	$\langle \langle \rangle$	Gold Coast
Custom Shades Pty Ltd		SEQ	C	4173	<i>)</i>	Brisbane - East
	641.TP1633,00 - CP2 - Shade Structure		C	2006		VSW
Deico Steel Old Pty Ltd	642.TP0620.01 - MHB - Reo Fix 644.2.TP0620.01 - CP2 - Reinforcement Fix	Other States				
Delco Steel Old Pty Ltd		Other States	- 40	2000		VSW
Delco Steel Old Pty Ltd	643,1,TP0620.01 - FMC - Reinforcement Fixing	Other States	L.	2000/		VSW
Designa Sabar	641.TP2430.01 - CP2 - Car Park management syste	The second second		5009		SA
East Coast Concrete Contractors	644,2.TP0420.01 - CP2 - Concrete Place and Finish	THE SHAPE IN		2485		VSW
Eastcoast Concrete Contractors	642,TP0420.02 - MHB - Concrete Place	Other States	1/9/	2485		NSW
Eastcoast Concrete Contractors	642.TP.0420.01 - MHB - Substructure, incl Pile trimr	Col market	\vee (\circ)	2485		NSW
FIP Electrical (Qld) Pty Ltd	644.2.TP2330.01 - CP2 - Electrical Installation	SEQ		4144		Brisbane Inner City
Fredon Electrical	641.TP2530.01 - CP2 - ICT	SFQ /	// C	4119		ogan - Beaudeser
Gordon Clements Nominees Pty Ltd T/A	 	sto	<u> </u>	4556		Sunshine Coast
Heinrich	642.TP0530.01 - MHB - Formwork	SEO	<u> </u>	4207		S E Qid
Helcim	642,TP0410.01 - MHB - Concrete Supply	REC	L	4701		REG QId
Manly Concrete	643.1,TP0420.01 - FMC - Concrete Placing	SEQ	L	4173		Brisbane - East
Matchett	642.TP0830.01 - MHB - Blockwork) \$50 V	<u>L</u>	4559		Sunshine Coast
Matchit Blocklaying	644.2.TP0830.01 & 644.1.TP0830.01 - Blockwork (L	4559		Sunshine Coast
Oneform	644.2,TP0530,01 - CP2 - Install Formwork	SEA	L	4173		Brisbane - East
Onesteel	643.1.TP0410.01 - FMC - Reo Supply	SEQ	L	4108	s.47(3)(b)	Brisbane - South
Onesteel	642.TP0610.01 - MHB - Reo Supply	SEQ	C	4108	- (-)(-)	3 E Qld
OTIS Elevator Company Pty Ltd	642.TP.2030.01 - MHB - Vertical Transportation	/ SEQ	С	4101		Brisbane Inner City
OTIS Elevator Company Pty Ltd	643.1.TP2030.01 - FMC - Vertical Transportation	SEQ	С	4101		Brisbane Inner City
OTIS Elevator Company Pty Ltd	643.2.TP2030.01 - MHU - Vertical Transportation	SEQ	С	4101		Brisbane Inner City
OTIS Elevator Company Pty Ltd	644.1.TP2030.01 CP1 - Vertical Transportation	SEQ	С	4101		Brisbane Inner City
Penfolds	640,TP3131.01 - CR2 - Landscaping	SEQ	L	4553		Sunshine Coast
Pickwick Group Pty Ltd	PR0057,03 CPZ - General Clean	SEQ	L	4101		S E Qld
Polyseal Waterproofing QLD Pty Ltd	644.2.TP/0832.91 - CP2 - Waterproofing	SEQ	C	4207		Gold Coast
Premier Signs	640.TP 1532:01 - CP2 - Signage	SEQ	С	4108		Brisbane - South
Pro Concrete Pumping	644.2.TV 0422.01 CP2 -Soncrete Pumping	SEQ	L	4220		Gold Coast
Pro Concrete Pumping	642.TR0422,01 - MHB - Copcrete Pumping	SEQ	С	4220		S E Qld
QLD Drink and Snack Machines	648-RR0022.08 - PRW - Vending Machines - CP2	SEQ	С	4559		Sunshine Coast
Regson Fabrications	641.TP1220.01 - CP2 - Façade	SEQ	L	4556		Sunshine Coast
Regson Fabrications	640.TP1230.01 - CP2 - General Metalwork	SEQ	С	4556		Sunshine Coast
Shadforth Civil Engineering	641.TR 0230.01 - RIE - Bullk Earthworks and Fill	SEQ	L	4556		Sunshine Coast
Shamrock Civil	641.TP.0239.02 - RIE - Preload	SEQ	L	4076		pswich
Siemens	641, TP2480,01 - CP2 - Security	Other Street	C	3153		/IC
Structural Systems (Northern) Pty Ltd	644.2.TP0631.01 - CP2 - Post Tensioning	SEQ	C	4207		Gold Coast
Sunshine Coast Air Conditioning Service		SEQ	С	4556		Sunshine Coast
Tacoma Plumbing and Drainage	644.2.TP1732.01 - CP2 - Hydraulics	SEQ	C	4573		Sunshine Coast
Unispan Australia Pty Ltd	644.2.TP0060.01 - CP2 - Scaffolding	SEQ	С	4207		Gold Coast
	Tower Crane to CP2	SEQ	L	4074		Brisbane - West
VT Services Wagstaff Piling Qld Pty Ltd	641.TP0330.02 - CP1 - Piling	SEQ	L	4060		Brisbane
	643.1.TP0330.02 - FMC - Precast Piling		 			
Wagstaff Piling Qid Pty Ltd		SEQ	L	4060		Brisbane Inner City
Admiral Concreting Pty Ltd	641.2 TP0420101 - CPT - Concrete Place and Primar			4634		S E CIX
OTIS Elevator Company Pty Ltd	644.1 TP2030.01 - CP2 - Vertical Transportation	SEQ	C	4000		S E QM
Structural Systems	642 TP 0631-01 - MbB - Post Termioning	SEQ	G -	4307		S E Qlú

Note: Substructure wasn't listed on ICN Gateway website as an opportunity for companies to register through ICN.

ATTACHMENT D: Local Industry Participation Plan Outcomes Report Progress Report to 30-03-2014

Project:

Sunshine Coast University Hospital

Project Proponent:

Queensland Health

Contractor:

Lend Lease

Project Location:

Sunshine Coast

Total Project Value:

\$1.8 Billion

Total Value of Contracts:

\$152,017,221.00

No. of Contracts:

Value of Contracts placed with

\$148,997,910.95

No. of Contracts: 51

0

2

2

Old businesses:

Value of work performed by regional Qld businesses

(included in total Qld figure

above):

\$0.00

No. of Contracts:

Value of work performed with businesses outside Qld but

within Australia/NZ:

No. of Contracts: \$0.00

Value of Work performed by

Overseas Firms:

No. of Contracts:

Tender Evaluation Criteria:

Tender Evaluation Criteria:

These works are subject to the Queensland Government's Local Industry Policy. The successful Contractor is required to provide full, fair and reasonable opportunity to local suppliers and specialist subcontractors when tendering the provision of equipment or services supplied under the scope of works. Contractors are encouraged to use the services of Industry Capability Network (Queensland) ("ICN") to ensure that supply tender invitations meet the requirements of the policy.

Value of Capital Investment:

\$1.8 billion

Employment (FTE)

Construction (FTE):

Operational (FTE):

(calculated using AEC multipier)

Skills Development

Number of courses:

No People Trained:

List of Courses:

Innovation, research and development

Project Innovation (brief summary):

(Innovation is the process of introducing new or significantly improved goods or services and/or implementing new or significantly Improved processes.)

WHS Representative Course, Safe Working at Heights, General Safety Induction

This project has put in place a number of good practice or procedures which have presented opportunities to introduce innovative services, products or processes.

Project Research and Development expenditure (brief summary)

Research and Development systematic, investigative and experimental activity that involves innovation or high technical risk acquiring new knowledge or creating new or improved products, devices, processes or services.)





Sunshine Coast University Hospital: Local Industry Participation

Progress Report #18 for period to 31 April 2014 Prepared by Industry Capability Network (Queensland) Ltd

This report details the assistance provided during the above period by ICN (Qld) to Lend Lease in the delivery and implementation of the Local Industry Participation Plan (LIPP) for the Sunshine Coast University Hospital in accordance with the Local Industry Policy (LIP).

1. Liaison with the Project on LIP Issues

ICN met with Queensland Health (Sam Betros) in May 2011 to discuss the project, ICN services, and LIP procedures and issues. ICN assisted QH in the development of the LIPP for the project and provided an evaluation report to QH on project bidders' LIP plan submissions in March 2012.

2. Liaison with Lend Lease on LIP Compliance

Lend Lease met with ICN to establish processes and procedures for management of the project's obligations to the LIP. It was decided that ICN will provide support on number of services covering:

- Implementation of the LIPP (capability searches on contestable packages)
- Presenting at briefing sessions
- Registering companies via ICN Gateway
- Verification of source of manufacture and service provision in subcontracts
- Business matching
- Progress reporting (Monthly) and final LIPP Outcomes reporting (at end of project)

3. Tier Barometer

Tier Barometer is an on-line self-assessment tool developed by ICN and the State Government. It provides participating companies with an assessment of their tier level in terms of supply to major projects. The tool is used by the project to analyse the basic capabilities of potential suppliers during the registration process.

4. Contestable Packages

Contestable items or packages are those that could potentially be sourced locally or overseas but do not include designated items such as concrete supply, earthworks, etc., which it is assumed will always be supplied from sources local to the project. Nor do they include items that have no chance of being manufactured in Australia, eg turbines. LL supplied ICN with the full schedule of subcontract trade packages for the project. ICN subsequently allocated these into contestable and non-contestable packages.

5. Work Packages

Queensland and Australian capability, content and capacity will be considered for all the work packages. The following activities have been undertaken:

- An ICN officer has been assigned full time to the project.
- Detailed Business Matching has been carried out by ICN. 261 work packages have been managed in this way.
 These are listed at Attachment A.
- 1490 registrations against work packages on Gateway have been received






A Division of OMI Solutions

- 65 early works have been awarded in March. These are listed at Attachment B.
- 57 work packages have been awarded so far and they are listed at Attachment C.

Potential subcontractors will be given an indication of the size and generic nature of the project, and questioned regarding their capability and capacity to carry out the work, code compliance, and previous work history. Reports will be sent to Lend Lease detailing local companies which have the capability and capacity to carry out the work for each of the above packages. The primary objective of the Local Industry Policy is to ensure that competitive local companies are given full, fair and reasonable opportunity to tender for work packages. This objective will be achieved if the companies nominated by ICN, and other local companies that Lend Lease is aware of, are considered in the establishment of the tender list, and, subject to meeting pre-qualification criteria, a reasonable number of local companies are subsequently invited to tender. Lend Lease intends to apply this requirement.

6. Source of Supply



Lend Lease has advised that out of 113 Purchase Orders, 65 were awarded for early works, one for Substructure and 55 for Work Packages listed on the ICN Gateway Project webpage. These were to companies that registered interest via ICN. As far as practicable, the measurement of industry participation focuses on the actual source of supply rather than the location through which the order is placed. The location in which services are provided, materials manufactured or where value adding takes place is indicative of the actual source of supply. Of the 57 Work Package contracts that have been awarded, 48 were won by South East Queensland (SEQ) companies, one by Regional Queensland, six by New South Wales companies, one by Victoria and one by South Australia.

As subcontracts are awarded, the source of manufacture or service provision for contestable packages will be validated and verified in discussion with the corresponding subcontractors. The aggregate value to Queensland and Australian industry will be reported for all packages, and for contestable packages alone. The aggregate value to Queensland and Australian industry of packages awarded so far has been estimated across all trade packages (including both contestable and non-contestable packages) and is currently:

Value of contracts awarded (to date):

Value of components made in Qld in contracts awarded (to date):

Value of components made in other states & NZ in contracts awarded (to date):


Value of components made overseas in contracts awarded (to date):

\$ 166.46 M

163.44 M

Value of components made overseas in contracts awarded (to date):

\$ 2.11 M





These figures are shown graphically in the diagram on the left (top) in terms of the percentage by value of all contracts awarded (contestable and non-contestable), with the Queensland content in the project broken down into Local, South East Queensland, Regional Queensland, Other States and New Zealand, and Overseas figures. The total Queensland content is currently 98.19%.

However, the Local Industry Policy is concerned mainly with contestable contracts as "Local" components are assumed to always be available from sources that are geographically close to the project location. The figures for contestable contracts only are shown in the diagram on the left (bottom), and these figures are included in reports back to the Department of State Development, Infrastructure and Planning (DSDIP). The Queensland content for contestable contracts is currently 93.1%.

A total of 57 contracts (including 24 contestable contracts) have been awarded where the source of manufacture or service provision is predominantly within Queensland. No contract was awarded directly to regional companies, as the project was predominantly based in South East Queensland.





7. Prototype Building

A prototype showcase building was erected in record time. This enabled focus group to provide input in to the final design in a cost effective manner.

8. Local Industry Participation

Lend Lease Project Director has personally provided project work scope and Lend Lease supplier engagement approach information to a number of larger Australian Manufacturers who have asked for more information. These include The GWA Group; The Laminex Group; Spence Doors and Rockcote Industries. For the latter company time was dedicated to a site inspection of their manufacturing facilities.

9. Information Sessions

ICN supported Lend Lease in delivering briefing sessions as proposed in their UP plan covering:

Monday 3rd September 2012 – Civil, Infrastructure, Structure & Landscaping

Monday 17th September 2012 - Services

Monday 24th September 2012 - Roof & Façade

Monday 8th October 2012 - Fit out & Finishes

Monday 15th October 2012 - Furniture Fittings & Equipment (FF&E)

Lend Lease also presented at the General Briefing Sessions along with ICN on 13, 14, 16 and 20th of August 2012.

Lend Lease project managers attended a briefing presentation by the members of the Cleantech Industries group of companies on 24th September 2012.

Lend Lease took part in a Local Business expo on 10th May 2013.

ICN — Evan Flower — presented to the Gympie Major Project Opportunities Forum on the project on 18th June 2013.

10. Efforts to engage with Local Companies include:

Press release by Health Minister, radio interviews by Project Director, Newspaper articles in CM and Sunshine Coast Daily followed up by substantial advertisements in the same newspapers on 19th January. Support articles followed from SSC Council and local councillors.

As a result of the above information sessions and the advertising campaign almost 1000 registrations have been received with close to 100 companies listing after the newspaper advertisements.

To date over 1490 companies have registered interest in work packages.

11. Source of Manufacture

As subcontracts begin to be awarded, the source of manufacture or service provision for contestable packages will be validated and verified in discussion with the corresponding subcontractors.






12. Reporting

- Business matching reports on companies nominated for the trade packages listed at Attachment A are being provided to Lend Lease.
- A summary of LIP progress is shown in Attachment D.

• The six monthly review of overall progress by Lend Lease in delivering on Local Industry Participation Plan commitments is also shown in Attachment E. This covers the period from June to December 2013 and was submitted to Queensland Health on 10th March 2014. Also shown at Attachment 5 is the template for the letter from Lend Lease to unsuccessful companies.







Ara f	. C		A Division of QMI Solutions
Attachmen		*******	
Enquiries D			
Enquiryid		Enquiryid	
90992	PR.0051.01 Crossover Road Construction		643.1.TP1030.01 - FMC - Structural Steelwork
90993	TP.0231.01 Preload		643.1.TP2236.01 - FMC - Kitchen / Laundry Equipment
90994	TP.0320.01 Sediment control	95686	642.TP.1637.01 - MHB - Coolrooms & Cleanrooms
90995	PR0059 Site Security		643.1.TP1637.01 - FMC - Coolrooms & Cleanrooms
91583	644.2.TP1732.01 - CP2 - Hydraulics		644.1.TP1630.01 - C(1 (Ropfing)
91584	644.2.TP0620.01 - CP2 - Reinforcement Fixing		643.2.TP1630,01 - MHU - Roofing & Metal Cladding
91585	644.2.TP0530.01 - CP2 - Formwork	95701	643.2.TP1636.01 - MAD - Wall Cladding Systems
91586	644.2.TP0422.01 - CP2 - Concrete Pumping	95707	643.1.7P1131.01 - FMC - Metal Windows
91587	644.2.TP0420.01 - CP2 - Concrete Placing	95777	644.1771131.01- CP1 - Facade / Screens
91588	644.2.TP0410.01 - CP2 - Concrete Supply	95778	643,2,791032.01 - MHU - Facade Framing
91589	644.2.TP0060.01 - CP2 - Scaffolding	95902	644.1.7P1235.01 - CP1 - Metal Louvres
91877	645.TP3230.01 - Kawana Way Duplication	95986	643,2.TP1131.01 - MHU - Metal Windows
92438	641.TP.0230.01 - RIE - Bulk Earthworks and Fill	96073	644.2.TP0057.01 - CP2 - Final Clean
92499	641.TP.3230.01 - RIE - Roads & Infrastructure Services	96151	643.2.TP1135.01 - MHU - Sunshades & Light Shelves
92500	644.2.TP2239.01 - CP2 - Carpark Control System	96159	643.2.TP1230.01 - MHU - Metalwork
92677	640.PR0033.01 - PRW - Temporary Hydraulics	96169	643.2.TP1235.01 - MHU - Metal Louvres
92681	640.PR0056.01 - PRW - Rubbish Removal	96177	643.1.TP2235.01 - FMC - Dock Levelers
92990	644.2.TP0832.01 - CP2 - Waterproofing	96509	644.1.TP1230.03 - CP1 - General Metalwork
93076	644.2.TP2330.01 - CP2 - Electrical	96635	643.2.TP3530.01 - MHU - Temporary Carpentry
93094	640.PR0042.01 - PRW - Tower Cranes, Hoists & Crews	96944	642.TP.1330.01 - MHB - General Carpentry
93205	644.2.TP0631.01 CP2 Post Tensjoning	97023	642.TP.1433.01 - MHB - Furniture
93293	642.TP.2030.01 - MHB Vertical Transportation	97037	642.TP.1236.01 - MHB - Roller Shutters
93294	643.1.TP2030.01 - FMC - Vertical Transportation	97039	642.TP.1332.01 - MHB - Doors & Door Frame Supply
93295	643.2.TP2030.01 - MHU - Vertical Transportation	97273	642.TP.2630.01 - MHB - Ceilings and Partitions
93296	644.1.TP2030.01 - CP1 - Vertical Transportation	97312	642.TP.2930.01 - MHB - Glazing & Mirrors
	640.PR0041.01 - PRW - Mobile Cranes	97314	643.1.TP1531.01 - FMC - Hardware - Sundry
93314	644.2.TP1830.01 - CP2 - Mechanical	97330	642.TP.3030.01 - MHB - Painting
93315	644.2.TP1712.01 - CP2 - Water Tanks	97432	643.1.TP2630.01 - FMC - Ceilings and Partitions
	640.PR0021.02 - PRW - Site Fencing		644.2.TP1311.01 - CP2 - Door and Frame Supply





A DIvision of QMI Solutions

93511 640 PR002.05 - PRW - Temporary Carpentry Site Acco 97436 643.2 TP2930.01 - MHU - Internal Glazing 93514 640 PR002.05 - PRW - Temporary Carpentry Site Acco 97436 643.2 TP2030.01 - MHU - Painting 93516 644.1 TP030.01 - CP1 - Formwork 93520 644.1 TP030.01 - CP1 - Formwork 93520 642.7 P.0530.01 - MHB - Formwork 93521 643.2 TP0530.01 - MHB - Formwork 97634 643.1 TP0330.01 - MHU - Formwork 97633 641.1 TP3310.01 - FMC - Site Wide HV Equipment Suppl 97583 642.1 TP2330.01 - MHU - Formwork 97633 641.1 TP3310.01 - FMC - Site Wide HV Equipment Suppl 97584 643.1 TP2310.01 - FMC - Site Wide HV Equipment Suppl 97585 642.1 TP2330.02 - PRW - Uninterruptable Power Supply U 97863 642.1 TP2330.02 - PRW - Uninterruptable Power Supply U 97863 642.1 TP2330.02 - PRW - Uninterruptable Power Supply U 97864 643.1 TP0330.02 - MHU - File Cut-off 97931 642.1 TP0330.02 - MHU - File Cut-off 97933 644.1 TP0330.02 - MHB - File Cut-off 97933 644.1 TP0330.03 - MHB - Sheet Piling 98566 643.1 TP0330.02 - MHB - File Cut-off 97935 642.1 TP0330.03 - MHB - File Cut-off 97935 642.1 TP0330.03 - MHB - File Cut-off 97935 644.1 TP0330.03 - MHB - File Cut-off 97936 644.1 TP0330.03 - MHB - File Cut-off 97937 644.1 TP0330.01 - MHB - File Cut-off 97937 644.1 TP0330.01 - MHB - File Cut-off 97937 644.1 TP0330.01 - MHB - File Cut-off 97937 6				
93514 640.PR0022.05 - PRW - Temporary Carpentry Site Acco 97450 643.1TP0330.01 - FMC - Painting 93516 644.1TP0530.01 - CP1 - Formwork 97454 643.2TP2630.01 - MHU - Cellings and Partitions 93520 642.TP.0530.01 - MHU - Formwork 97454 643.1TP2630.01 - CP1 - Ceilings and Partitions 93521 643.2TP0530.01 - MHU - Formwork 97524 642.TP.3131.01 - MHB - Mature Trees 93523 643.1TP0330.01 - FMC - Formwork 97693 641.TP331.01 - CP2 - Soft/Hard Landscaping 93544 643.1TP2330.01 - FMC - Site Wide HV Equipment Supply 97728 642.TP.2772.0.1 - MHB - Grigety Landscaping 93563 642.TP.2335.02 - PRW - Uninterruptable Power Supply U 97863 642.TP.2730.01 - MHB - Grigety Landscaping 93565 643.1TP0330.02 - MHU - Pile Cut-off 97864 642.TP.2734.01 - AMHB - Epoly Flooring 93565 643.1TP0330.02 - MHU - Pile Cut-off 97913 Any Oppoprtunities - General Clean 93566 643.1TP0330.03 - MHB - Sheet Piling 98075 642.TP.1330.03 - MHB - Signage 93568 642.TP.0330.03 - MHB - Pile Cut-off 97915 642.TP.0350.03 - MHB - Signage 93576 642.TP.0330.03 - MHB - Pile Cut-off 93576 643.1TP0330.03 - MHB - Pile Cut-off 93576 644.1TP0330.01 - CP1 - Reinforcement Fix 98357 642.TP.0620.01 - MHB - Reinforcement Fix 98358 642.TP.0630.01 - MHB - Reinforcement Fix 98359 643.1TP0330.01 - CP1 - Reinforcement Fix 98356 643.1TP0330.01 - FMC - Post Tensioning 93576 643.1TP0330.01 - FMC - Post Tensioning 93577 643.2TP0620.01 - MHB - Reinforcement Fix 93578 644.1TP033.00 - FMC - Waterproofing Roofs & Decks 93579 644.1TP033.00 - MHB - Reinforcement Fix 93570 642.TP.032.01 - MHB - Reinforcement Fix 93571 643.1TP033.01 - FMC - Waterproofing Roofs & Decks 93571 643.1TP033.01 - FMC - Waterproofing Roofs & Decks 93572 644.1TP033.01 - MHB - Waterproofing Roofs & Decks 93710 642.TP.032.01 - MHB - Waterproofing Pools 93710 642.TP.033.01 - MHB - Waterproofing Pools 93710 642.TP.033.01 - MHB - Waterproofing Pools 93721 643.1TP033.01 - MHB - Waterproofing Roofs & D				
93516 644.1.TP0530.01 - CP1 - Formwork 97454 643.2.TP2630.01 - MHU - Ceilings and Partitions 93520 642.TP.0530.01 - MHU - Formwork 97464 644.1.TP2630.01 - CP1 - Ceilings and Partitions 93521 643.2.TP0530.01 - MHU - Formwork 97624 642.TP.3131.01 - MHB - Mature Trees 93523 643.1.TP0330.01 - FMC - Site Wide HV Equipment Suppl 97728 642.TP.2730.01 - MHB - Mature Trees 93524 643.1.TP0330.01 - FMC - Site Wide HV Equipment Suppl 97728 642.TP.2720.01 - MHB - Garpet Agring 93563 642.TP2335.02 - PRW - Uninterruptable Power Supply U 97863 642.TP.2720.01 - MHB - Garpet Agring 93565 643.2.TP0330.02 - CP1 - Pile Cut-off 97864 642.TP.2734.01 - MHB - Soot Supply 93565 643.2.TP0330.02 - MHU - Pile Cut-off 97913 Anny Opportunities - General Clean 93566 643.1.TP0330.03 - MHB - Sheet Piling 98075 642.TP,0330.03 - MHB - Sheet Piling 98075 642.TP,0330.03 - MHB - Sheet Piling 98075 642.TP,0330.03 - MHB - Sheet Piling 98155 642.TP,0330.03 - MHB - Pile Cut-off 98155 643.1.TP0330.03 - Pile Cut-off 98				<u> </u>
93520 642.TP.0530.01 - MHB - Formwork 97464 644.1TP2630.01 - CP1 - Ceilings and Partitions 93521 643.2TP0530.01 - MHU - Formwork 97624 642.TP.3131.01 - MHB - Mature Trees 97632 643.1TP0530.01 - FMC - Formwork 97633 641.TP331.01 - CP2 - Soft/Hard Landscaping 93544 643.1TP2310.01 - FMC - Site Wide HV Equipment Suppl 97728 642.TP.2720.01 - MHB (93514	640.PR0022.05 - PRW - Temporary Carpentry Site Accor		<u> </u>
93521 643.1.TP0330.01 - MHU - Formwork 97624 642.TP.3131.01 - MHB - Mature Trees 93523 643.1.TP0330.02 - FMC - Formwork 97633 642.TP.3131.01 - CP2 - Soft/Hard Landscaping 93563 642.TP.333.02 - PRW - Uninterruptable Power Supply 97863 642.TP.3131.01 - MHB - Garpet Leving 93565 643.1.TP0330.02 - CP1 - Pile Cut-off 97864 642.TP.3131.01 - MHB - Poort Supply 93566 643.1.TP0330.02 - MHB - Pile Cut-off 97913 642.TP.0330.02 - MHB - Pile Cut-off 97915 642.TP.0330.03 - MHB - Sheet Piling 98075 642.TP.0330.03 - MHB - Pile Cut-off 98145 642.TP.3330.01 - MHB - Signage 93569 643.1.TP0330.03 - MHB - Pile Cut-off 98155 643.1.TP0330.03 - FMC - Sheet Piling 98365 642.TP.0620.01 - CP1 - Reinforcement Fix 98365 642.TP.0620.01 - CP1 - Reinforcement Fix 98365 642.TP.0620.01 - MHB - Reinforcement Fix 98365 642.TP.0631.01 - FMC - Door Supply 93573 642.TP.0631.01 - FMC - Post Tensioning 98356 643.1.TP0330.01 - FMC - Door & Hardware Fixing 98357 643.1.TP0620.01 - MHB - Reinforcement Fix 98473 642.TP.2731.01 - MHB - Insitu Floor Mats 93577 643.2.TP0620.01 - MHB - Waterproofing 98468 642.TP.2731.01 - MHB - Insitu Floor Coverings 93581 640.PR0052.01 - PRW - Safety Precautions (PPE) 98495 642.TP.2735.01 - MHB - Insitu Floor Coverings 93717 642.TP.0832.01 - MHB - Waterproofing 98580 642.TP.2737.01 - MHB - Medical Furniture 93720 643.1.TP0832.01 - FMC - Waterproofing 98706 642.TP.2737.01 - MHB - Wall Protection 93721 643.1.TP0832.01 - FMC - Waterproofing 98706 642.TP.133.00 - MHB - Wall Protection 93721 643.1.TP0832.01 - FMC - Waterproofing 98806 642.TP.133.01 - MHB - Whitegoods 93827 642.TP.033.01 - FMC - Hardware & FFE Fixing 93828 642.TP.0420.01 - MHB - Concrete P	93516	644.1.TP0530.01 - CP1 - Formwork	97454	643.2.TP2630.01 - MHU- Ceilings and Partitions
93523 643.1.TP0330.01 - FMC - Formwork 97693 641.TP3131.01 - CP2 - Soft/Hard Landscaping 93544 643.1.TP2310.01 - FMC - Site Wide HV Equipment Supply 97728 642.TP.2720.01 · MHB - Garget Leving 93563 642.TP.2335.02 - PRW - Uninterruptable Power Supply 97863 642.TP.2334.01 · MHB - Poor's Supply 93565 643.2.TP0330.02 - CP1 - Pile Cut-off 97913 Any Opportunities - General Clean 93566 643.1.TP0330.02 - FMC - Pile Cut-off 97915 642.TP.2334.01 · MHB - Signage 93567 642.TP.0330.03 · MHB - Sheet Piling 98075 642.TP.3330.01 · MHB - Signage 93568 642.TP.0330.03 - FMC - Sheet Piling 98155 643.1.TP0330.03 - FMC - Sheet Piling 98356 642.TP.0620.01 - CP1 - Reinforcement Fix 98365 642.TP.0620.01 - MHB - Reinforcement Fix 98365 642.TP.0620.01 - MHB - Reinforcement Fix 98365 642.TP.0620.01 - MHB - Reinforcement Fix 98356 643.1.TP0330.01 - CP1 - Spit Presioning 98356 643.1.TP0330.01 - CP1 - Spit Presioning 98468 642.TP.2731.01 - MHB - Floor Mats 93577 643.2.TP0620.01 - MHU - Reinforcement Fix 98473 642.TP.2731.01 - MHB - Insitu Floor Coverings 93578 644.1.TP0631.01 - CP1 - Post Persioning 98468 642.TP.2735.01 - MHB - Insitu Floor Coverings 93717 642.TP.0832.01 - MHB - Waterproofing Roofs & Decks 98585 642.TP.2330.01 - MHB - Tactile Indicators 93717 642.TP.0832.01 - MHB - Waterproofing Roofs & Decks 98585 642.TP.233.01 - MHB - Medical Furniture 93720 643.1.TP0332.01 - FMC - Waterproofing Roofs & Decks 98586 642.TP.233.01 - MHB - Whitegoods 93721 643.1.TP0332.01 - MHB - Waterproofing 98794 642.TP.233.01 - MHB - Whitegoods 93827 642.TP.033.01 - MHB - Whitegoods 93827 642.TP.033.01 - MHB - Concrete Supply 98821 643.TP1533.01 - CP1 - Carparking Control Systems 93836 644.TP0410.01 - RIE - Concrete Place & F	93520	642.TP.0530.01 - MHB - Formwork	97464	644.1.TP2630.01 - CP1 - Ceilings and Partitions
93544 643.1.TP2310.01 - FMC - Site Wide HV Equipment Supply U 97863 642.TP.2720.01 - MHB - Carpet Laring 93563 642.TP2335.02 - PRW - Uninterruptable Power Supply U 97863 642.TP.2311.01 - MHB - Boors Supply 93564 644.1.TP0330.02 - CP1 - Pile Cut-off 97864 642.TP.2734.01 - 6MHB - Epoxy Flooring 93565 643.2.TP0330.02 - MHU - Pile Cut-off 97913 Any Opportunites - General Clean 93566 643.1.TP0330.02 - MHB - Pile Cut-off 97915 642.TP.434003 MHB - Workstations & Screens 93567 642.TP.0330.03 - MHB - Sheet Piling 98075 642.TP.4330.01 - CP1 - Door and Frame Supply 93569 643.1.TP0330.03 - MHB - Pile Cut-off 98156 642.TP.4330.01 - FMC - Door Supply 93569 643.1.TP0330.03 - FMC - Sheet Piling 98155 643.TP0330.03 - FMC - Sheet Piling 98156 642.TP.0530.01 - MHB - Reinforcement Fix 98346 642.TP.231.01 - FMC - Door Supply 93575 642.TP.0620.01 - MHB - Reinforcement Fix 98346 642.TP.230.02 - CP1 - Vinyl Installation 93576 643.TP0630.01 - MHB - Post Tensioning 98468 642.TP.2711.01 - MHB - Floor Mats 98357 643.TP0630.01 - FMC - Post Tensioning 98468 642.TP.2711.01 - MHB - Floor Mats 98357 643.TP0630.01 - FMC - Post Tensioning 98476 642.TP.2713.01 - MHB - Floor Mats 983576 643.TP0630.01 - FMC - Post Tensioning 98476 642.TP.2713.01 - MHB - Floor Mats 983576 643.TP0630.01 - FMC - Post Tensioning 98476 642.TP.2713.01 - MHB - Floor Mats 983576 643.TP0630.01 - FMC - Waterproofing Post 98476 642.TP.2713.01 - MHB - Floor Mats 983576 643.TP0832.01 - FMC - Waterproofing Post 98497 642.TP.2713.01 - MHB - Floor Mats 983576 643.TP0832.01 - FMC - Waterproofing Roofs & Decks 98585 642.TP.1333.01 - MHB - Furniture - Seating 98706 643.TP0832.01 - FMC - Waterproofing & Tanking - Roof 642.TP.1333.01 - MHB - Wall Protection 98706 643.TP0832.01 - FMC - Waterproofing 98709 643.TP0832.01 - FMC - Waterproofin	93521	643.2.TP0530.01 - MHU - Formwork	97624	642.TP.3131.01 - MHB - Mature Trees
93563 642.TP.2335.02 - PRW - Uninterruptable Power Supply U 97863 642.TP.1311.01 - MHB - Booir Supply 93564 644.1.TP0330.02 - CP1 - Pile Cut-off 97864 642.TP.2734.01 - 6MHB - Epoxy Flooring 97856 643.TP0330.02 - MHU - Pile Cut-off 97913 Any Opportunities - General Clean 93566 643.T.TP0330.02 - MHB - Pile Cut-off 97915 642.TP.1330.01 - MHB - Signage 98075 642.TP.1330.01 - MHB - Signage 98075 642.TP.0330.03 - MHB - Sheet Piling 98075 642.TP.1330.01 - CP1 - Door and Frame Supply 93569 643.T.TP0330.03 - FMC - Sheet Piling 98155 643.T.TP0330.03 - FMC - Sheet Piling 98155 643.T.TP0330.03 - FMC - Sheet Piling 98155 643.TP031.01 - FMC - Door Supply 93576 642.TP.0620.01 - MHB - Reinforcement Fix 98366 642.TP.232.02 - MHB - Vinyl 93577 642.TP.0631.01 - MHB - Post Tensioning 98468 642.TP.230.01 - CP1 - General Carpentry 983576 643.T.TP0330.01 - FMC - Post Tensioning 98468 642.TP.2711.01 - MHB - Floor & Hardware Fixing 98576 643.T.TP0631.01 - FMC - Post Tensioning 98468 642.TP.2711.01 - MHB - Institution Coverings 98577 643.T.TP0330.01 - CP1 - Post Tensioning 98477 642.TP.2735.01 - MHB - Institution Coverings 98577 642.TP.0832.01 - PNW - Safety Presoutions (PPE) 98497 642.TP.2735.01 - MHB - Institution Coverings 98581 640.TP.0832.01 - PNW - Safety Presoutions (PPE) 98495 642.TP.233.00 - MHB - Tactile Indicators 98596 643.T.TP0832.01 - MHB - Waterproofing Roofs & Decks 98585 642.TP.133.03 - MHB - Medical Furniture 98590 643.T.TP0832.01 - FMC - Waterproofing & Tanking - Roof 642.TP.2733.01 - MHB - Waterproofing 98589 642.TP.133.01 - MHB - Waterproofing 98589 642.TP.133.01 - MHB - Waterproofing 98590 643.T.TP033.01 - FMC - Vinyl Install 93732 643.T.TP0332.01 - FMC - Waterproofing 98794 643.T.TP233.01 - MHB - Waterproofing 98794 64	93523	643.1.TP0530.01 - FMC - Formwork	97693	641.TP3131.01 - CP2 - Soft/Hard Landscaping
93566 643.2 TP0330.02 - CP1 - Pile Cut-off 93565 643.2 TP0330.02 - MHU - Pile Cut-off 93566 643.1 TP0330.02 - FMC - Pile Cut-off 93566 643.1 TP0330.02 - MHB - Sheet Piling 93567 642.TP.0330.03 - MHB - Sheet Piling 93568 642.TP.0330.03 - MHB - Pile Cut-off 93569 643.1 TP0330.03 - MHB - Pile Cut-off 93569 643.1 TP0330.03 - MHB - Pile Cut-off 93569 643.1 TP0330.03 - FMC - Sheet Piling 93573 644.1 TP0620.01 - CP1 - Reinforcement Fix 93573 642.TP.0620.01 - MHB - Reinforcement Fix 93573 642.TP.0631.01 - MHB - Post Tensioning 93574 642.TP.0631.01 - MHB - Post Tensioning 93576 643.1 TP0631.01 - FMC - Post Tensioning 93576 643.1 TP0631.01 - FMC - Post Tensioning 93577 643.2 TP0620.01 - MHU - Reinforcement Fix 93578 644.1 TP0330.01 - PMC - Post Tensioning 93579 643.1 TP0631.01 - FMC - Post Tensioning 93579 644.1 TP0330.01 - MHB - Reinforcement Fix 93579 644.1 TP0330.01 - FMC - Post Tensioning 93579 644.1 TP0330.01 - FMC - Post Tensioning 93579 644.1 TP0330.01 - FMC - Post Tensioning 93579 644.1 TP0631.01 - CP1 - Post Tensioning 93579 644.1 TP0631.01 - CP1 - Post Tensioning 93579 645.TP.0630.01 - MHB - Reinforcement Fix 93579 645.TP.2730.01 - MHB - Hodicators 93579 646.TP.2730.01 - MHB - Reinforcement Fix 93579 647.TP.2730.01 - MHB - Hodicators 93579 647.TP.2730.01 - FMC - Waterproofing Deround 93710 647.TP.2730.01 - MHB - Waterproofing Stanking - Ro 93710 647.TP.0832.01 - FMC - Waterproofing & Tanking - Ro 93720 647.TP.0832.01 - FMC - Waterproofing Stanking - Ro 93721 648.1.TP0832.01 - FMC - Waterproofing Stanking - Ro 93722 648.2.TP.0832.01 - FMC - Waterproofing Stanking - Ro 93723 644.1.TP0330.01 - PMC - Waterproofing 98580 642.TP.1433.02 - MHB - Wall Protection 93721 647.TP.2335.01 - PMC - Waterproofing Stanking - Ro 93722 647.TP.2335.01 - PMC - Waterproofing 98580 642.TP.1533.01 - MHB - Wall Protection 93723 644.1.TP0330.01 - PMC - Waterproofing 98580 642.TP.1533.01 - MHB - Whitegoods 93827 642.TP.0330.01 - PMC - Waterproofing 98581 643.1.TP1500.01 - FMC - Hardware & FFE Fixing 938860 641.TP0410.01 - RIE - Concrete S	93544	643.1.TP2310.01 - FMC - Site Wide HV Equipment Suppl	97728	642.TP.2720.01 - MHB - Carpet Laying
93566 643.1 TP0330.02 - MHU - Pile Cut-off 93566 643.1 TP0330.02 - FMC - Pile Cut-off 93567 642.TP.0330.03 - MHB - Sheet Piling 93568 642.TP.0330.03 - MHB - Sheet Piling 93568 642.TP.0330.03 - MHB - Pile Cut-off 93579 642.TP.0330.03 - FMC - Sheet Piling 93570 642.TP.0330.03 - FMC - Sheet Piling 93571 642.TP.0620.01 - CP1 - Reinforcement Fix 93573 642.TP.0620.01 - MHB - Reinforcement Fix 93574 642.TP.0631.01 - MHB - Post Tensioning 93575 643.1 TP0630.01 - MHB - Post Tensioning 93576 643.1 TP0630.01 - MHB - Post Tensioning 93576 643.1 TP0630.01 - MHU - Reinforcement Fix 93577 643.2 TP.0631.01 - FMC - Post Tensioning 93578 644.1 TP0631.01 - FMC - Post Tensioning 93579 643.1 TP0630.01 - MHU - Reinforcement Fix 93579 643.1 TP0630.01 - MHU - Reinforcement Fix 93579 644.1 TP0631.01 - CP1 - Post Tensioning 93579 644.1 TP0631.01 - CP1 - Post Tensioning 93579 644.1 TP0631.01 - FMC - Post Tensioning 93579 644.1 TP0631.01 - CP1 - Post Tensioning 93710 642.TP.0330.01 - MHB - Waterproofing Deround 93710 642.TP.0330.01 - MHB - Waterproofing Deround 93710 642.TP.0330.03 - MHB - Waterproofing Stanking - Post Season S	93563	642.TP2335.02 - PRW - Uninterruptable Power Supply U	97863	642.TP.1311.01 - MHB - Doors Supply
93566 643.1.TP0330.02 - FMC - Pile Cut-off 93567 642.TP.0330.03 - MHB - Sheet Piling 93568 642.TP.0330.03 - MHB - Pile Cut-off 93569 643.1.TP0330.03 - FMC - Sheet Piling 93572 644.1.TP0620.01 - CP1 - Reinforcement Fix 93573 642.TP.0630.01 - CP1 - Reinforcement Fix 93573 642.TP.0630.01 - MHB - Post Tensioning 93575 643.1.TP0330.01 - FMC - Operation Fix 93575 643.1.TP0330.01 - FMC - Reinforcement Fix 93576 643.1.TP0620.01 - FMC - Reinforcement Fix 93577 643.1.TP0620.01 - FMC - Reinforcement Fix 93578 644.1.TP0620.01 - FMC - Reinforcement Fix 93579 643.1.TP0330.01 - FMC - Post Tensioning 93570 643.1.TP0330.01 - FMC - Post Tensioning 93571 643.1.TP0620.01 - FMC - Post Tensioning 93571 643.1.TP0631.01 - FMC - Post Tensioning 93578 644.1.TP0631.01 - FMC - Post Tensioning 93579 644.1.TP0631.01 - FMC - Post Tensioning 93571 642.TP.2731.01 - MHB - Insitu Floor Coverings 93578 644.1.TP0631.01 - CP1 - Post Tensioning 93579 644.1.TP0631.01 - CP1 - Post Tensioning 93571 642.TP.2735.01 - MHB - Tactile Indicators 93571 642.TP.0832.01 - MHB - Waterproofing Inground 93717 642.TP.0832.01 - MHB - Waterproofing Roofs & Decks 93719 642.TP.0832.03 - MHB - Temporary Waterproofing 93719 642.TP.0832.03 - MHB - Temporary Waterproofing 93720 643.1.TP0832.01 - MHB - Waterproofing & Tanking 93721 643.1.TP3832.01 - FMC - Waterproofing & Tanking 93722 643.2.TP0832.01 - FMC - Waterproofing 93723 644.1.TP0832.01 - CP1 - Waterproofing 93723 644.1.TP033.01 - MHB - Whitegoods 93827 642.TP.1333.01 - MHB - Whitegoods 938287 642.TP.1333.01 - MHB - Whitegoods 93829 642.TP.1333.01 - CP1 - Waterproofing 93820 642.TP.1333.01 - CP1 - Concrete Supply 93821 643.1.TP1530.01 - CP1 - Carparking Control Systems	93564	644.1.TP0330.02 - CP1 - Pile Cut-off	97864	642.TP.2734.01 - 04HB - Epoxy Flooring
93567 642.TP.0330.03 - MHB - Sheet Piling 98075 642.TP.332.01 - MHB - Signage 93568 642.TP.0330.02 - MHB - Pile Cut-off 98155 643.1.TP131.01 - CP1 - Door and Frame Supply 93569 643.1.TP0330.03 - FMC - Sheet Piling 98155 643.1.TP131.01 - FMC - Door Supply 93572 644.1.TP0620.01 - CP1 - Reinforcement Fix 9836 642.TP.2732.02 - MHB - Vinyl 93573 642.TP.0631.01 - MHB - Reinforcement Fix 98356 644.1.TP233.00 - CP1 - Vinyl Installation 93574 642.TP.0631.01 - MHB - Post Tensioning 98357 643.1.TP0330.01 - FMC - Door & Hardware Fixing 93576 643.1.TP0620.01 - FMC - Reinforcement Fix 98473 643.1.TP1330.01 - FMC - Door & Hardware Fixing 93576 643.1.TP0631.01 - FMC - Post Tensioning 98468 642.TP.2711.01 - MHB - Floor Mats 93577 643.2.TP0620.01 - MHU - Reinforcement Fix 98473 642.TP.2731.01 - MHB - Insitu Floor Coverings 93578 644.1.TP0631.01 - CP1 - Post Tensioning 98477 642.TP.2731.01 - MHB - Insitu Floor Coverings 93581 640.PR0052.01 - PRW - Safety Presautions (PPE) 98495 642.TP.2735.01 - MHB - Tactile Indicators 93717 642.TP.0832.02 - MHB - Waterproofing Inground 98500 643.1.TP2720.01 - FMC - Carpet Install 93718 642.TP.0832.03 - MHB - Jemporary Waterproofing 98589 642.TP.1433.03 - MHB - Femporary Waterproofing 98589 642.TP.1433.03 - MHB - Herriture - Seating 93719 642.TP.0832.01 - FMC - Waterproofing 8 Tanking 9868 642.TP.2737.01 - MHB - Wall Protection 93721 643.1.TP0832.01 - FMC - Waterproofing 98506 642.TP.233.01 - MHB - Whitegoods 93827 642.TP.1333.01 - MHB - Whitegoods 93827 642.TP.1333.01 - MHB - Whitegoods 93827 642.TP.0332.01 - FMC - Vinyl Install 93723 644.1.TP0832.01 - CP1 - Waterproofing 98820 642.TP.1533.01 - MHB - Whitegoods 93820 642.TP.0420.01 - MHB - Concrete Place & Finish 9893 644.1.TP2330.1 - CP1 - Carparking Control Systems	93565	643.2.TP0330.02 - MHU- Pile Cut-off	97913	Any Opportunities - General Clean
93568 642.TP.0330.02 - MHB - Pile Cut-off 93569 643.1.TP0330.03 - FMC - Sheet Piling 93572 644.1.TP0620.01 - CP1 - Reinforcement Fix 93573 642.TP.0620.01 - MHB - Reinforcement Fix 93573 642.TP.0620.01 - MHB - Reinforcement Fix 93574 642.TP.0631.01 - MHB - Post Tensioning 93575 643.1.TP0620.01 - FMC - Reinforcement Fix 93576 643.1.TP0620.01 - FMC - Reinforcement Fix 93577 643.1.TP0620.01 - FMC - Reinforcement Fix 93577 643.1.TP0620.01 - FMC - Post Tensioning 93577 643.2.TP0620.01 - MHU - Reinforcement Fix 98473 642.TP.2731.01 - MHB - Floor Mats 93577 643.2.TP0620.01 - MHU - Reinforcement Fix 98473 642.TP.2731.01 - MHB - Insitu Floor Coverings 93578 644.1.TP0631.01 - CP1 - Post Tensioning 98467 642.TP.2735.01 - MHB - Insitu Floor Coverings 93581 640.PR0052.01 - PRW - Sefety Precautions (PPE) 93717 642.TP.0832.01 - MHB - Waterproofing Roofs & Decks 93719 642.TP.0832.02 - MHB - Waterproofing Roofs & Decks 93719 642.TP.0832.03 - MHB - Temporary Waterproofing 93719 642.TP.0832.03 - MHB - Temporary Waterproofing 93720 643.1.TP0832.01 - FMC - Waterproofing & Tanking 93721 643.1.TP332.01 - FMC - Waterproofing & Tanking - Ro 93722 643.2.TP0832.01 - MHU - Waterproofing & Tanking - Ro 93723 644.1.TP033.01 - MHB - Waterproofing & Tanking - Ro 93724 642.TP.1433.04 - MHB - Compactus Units 93725 642.TP.1433.01 - MHB - Waterproofing & Tanking - Ro 93727 643.1.TP332.01 - CP1 - Waterproofing & Tanking - Ro 93728 642.TP.1433.01 - MHB - Waterproofing & Tanking - Ro 93729 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Ro 93721 643.1.TP332.01 - FMC - Waterproofing & Tanking - Ro 93722 643.2.TP.033.01 - MHB - Waterproofing & Tanking - Ro 93723 644.1.TP033.01 - MHB - Waterproofing & Tanking - Ro 93724 642.TP.1433.01 - MHB - Waterproofing & Tanking - Ro 93725 642.TP.1433.01 - MHB - Waterproofing & Tanking - Ro 93727 642.TP.1433.01 - MHB - Waterproofing & Tanking - Ro 93728 642.TP.1433.01 - MHB - Waterproofing & Tanking - Ro 93729 643.1.TP032.01 - FMC - Waterproofing & Tanking - Ro 93721 643.1.TP032.01 - FMC - Waterproofing & Tanking	93566	643.1.TP0330.02 - FMC - Pile Cut-off	97915	642.TP(1434/01 MHB - Workstations & Screens
93569 643.1.TP0330.03 - FMC - Sheet Piling 93572 644.1.TP0620.01 - CP1 - Reinforcement Fix 93573 642.TP.0620.01 - MHB - Reinforcement Fix 93574 642.TP.0631.01 - MHB - Reinforcement Fix 93575 644.1.TP0330.01 - CP1 - General Carpentry 93575 643.1.TP0330.01 - FMC - Door & Hardware Fixing 93576 643.1.TP0631.01 - FMC - Post Tensioning 93576 643.1.TP0631.01 - FMC - Post Tensioning 93577 643.2.TP0620.01 - MHU - Reinforcement Fix 93577 643.2.TP0620.01 - MHU - Reinforcement Fix 93578 644.1.TP0330.01 - FMC - Door & Hardware Fixing 93578 644.1.TP0631.01 - FMC - Post Tensioning 93578 644.1.TP0631.01 - FMC - Post Tensioning 93578 644.1.TP0631.01 - FMC - Post Tensioning 93578 644.1.TP0631.01 - CP1 - Post Tensioning 93578 644.1.TP0631.01 - CP1 - Post Tensioning 93578 644.1.TP0631.01 - PRW - Safety Presautions (PPE) 93581 640.PR0052.01 - PRW - Safety Presautions (PPE) 93719 642.TP.0832.01 - MHB - Waterproofing Diground 93719 642.TP.0832.02 MHB - Waterproofing Post & Decks 93719 642.TP.0832.03 MHB - Jemporary Waterproofing 93719 643.1.TP0832.03 MHB - Jemporary Waterproofing 93720 643.1.TP0832.01 - FMC - Waterproofing Post & Decks 93721 643.1.TP0832.01 - FMC - Waterproofing 93722 643.1.TP0832.01 - FMC - Waterproofing 93723 644.1.TP0832.01 - FMC - Waterproofing 93724 643.1.TP0832.01 - MHB - Waterproofing 93725 644.1.TP0832.01 - PRW - Safety Presautions (PPE) 93727 644.1.TP0832.01 - FMC - Waterproofing 93728 644.1.TP0832.01 - MHU - Waterproofing 93729 644.1.TP0832.01 - MHU - Waterproofing 93721 643.1.TP0832.01 - FMC - Waterproofing 93722 643.2.TP0832.01 - PRW - Site Wide LV Equipment Supply 93820 642.TP.1533.01 - MHU - Whitegoods 93827 642.TP.0420.01 - MHB - Concrete Supply 98843 643.1.TP1520.01 - FMC - Hardware & FFE Fixing 93938 644.TP.0420.01 - MHB - Concrete Place & Finish 98938 644.TP.0420.01 - MHB - Concrete Place & Finish	93567	642.TP.0330.03 - MHB - Sheet Piling	98075	642-TP.1532.01 - MHB - Signage
93572 644.1.TP0620.01 - CP1 - Reinforcement Fix 93573 642.TP.0620.01 - MHB - Reinforcement Fix 93574 642.TP.0631.01 - MHB - Post Tensioning 93574 642.TP.0631.01 - FMC - Reinforcement Fix 93575 643.1.TP0631.01 - FMC - Reinforcement Fix 93576 643.1.TP0631.01 - FMC - Post Tensioning 93577 643.2.TP0620.01 - MHU - Reinforcement Fix 93578 644.1.TP0631.01 - FMC - Post Tensioning 93578 644.1.TP0631.01 - CP1 - Post Tensioning 93578 642.TP.2731.01 - MHB - Insitu Floor Coverings 93578 642.TP.2735.01 - MHB - Insitu Floor Coverings 93578 642.TP.0832.01 - PRW - Sefety Presuptions (PPE) 93579 642.TP.0832.01 - MHB - Waterproofing Deround 93570 642.TP.0832.01 - MHB - Waterproofing Roofs & Decks 93719 642.TP.0832.02 / MHB - Waterproofing Roofs & Decks 93719 642.TP.0832.03 - MHB - Jemporary Waterproofing 93720 643.1.TP0832.01 - FMC - Waterproofing & Tanking 93721 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Ro 93721 643.1.TP0832.01 - MHU - Waterproofing 93722 643.2.TP0832.01 - MHU - Waterproofing 93723 644.1.TP0832.01 - MHU - Waterproofing 93724 642.TP.1433.04 - MHB - Compactus Units 93725 642.TP.133.01 - MHB - Whitegoods 93727 642.TP.133.01 - MHU - Waterproofing 93728 644.1.TP0832.01 - PRW - Site Wide LV Equipment Supply 93829 642.TP.1533.01 - MHU - Whitegoods 93827 642.TP.1533.01 - MHU - Whitegoods 93827 642.TP.1533.01 - PRW - Site Wide LV Equipment Supply 98843 643.1.TP1520.01 - FMC - Hardware & FFE Fixing 93938 642.TP.0420.01 - MHB - Concrete Supply 98843 644.1.TP239.01 - CP1 - Carparking Control Systems	93568	642.TP.0330.02 - MHB - Pile Cut-off	98145	644.2.TP 1311.01 - CP1 - Door and Frame Supply
93573 642.TP.0620.01 - MHB - Reinforcement Fix 93574 642.TP.0631.01 - MHB - Post Tensioning 93575 643.1.TP0620.01 - FMC - Reinforcement Fix 93575 643.1.TP0620.01 - FMC - Reinforcement Fix 93576 643.1.TP0631.01 - FMC - Post Tensioning 93577 643.2.TP0620.01 - FMC - Post Tensioning 93577 643.2.TP0631.01 - FMC - Post Tensioning 93578 644.1.TP0330.01 - FMC - Door & Hardware Fixing 93577 643.2.TP0631.01 - FMC - Post Tensioning 93578 644.1.TP0631.01 - CP1 - Post Tensioning 93578 644.1.TP0631.01 - CP1 - Post Tensioning 93578 644.1.TP0631.01 - CP1 - Post Tensioning 93579 642.TP.2735.01 - MHB - Insitu Floor Coverings 93571 642.TP.0832.01 - PRW - Sefety Precautions (PPE) 93571 642.TP.0832.01 - MHB - Waterproofing Roors & Decks 93718 642.TP.0832.02 MHB - Waterproofing Roors & Decks 93719 642.TP.0832.02 MHB - Temporary Waterproofing 93720 643.1.TP0832.01 - FMC - Waterproofing & Tanking 93721 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Ro 93721 643.1.TP0832.01 - MHU - Waterproofing 93722 643.1.TP0832.01 - MHU - Waterproofing 93723 644.1.TP0832.01 - CP1 - Waterproofing 93724 644.1.TP0832.01 - CP1 - Waterproofing 93725 642.TP.1333.01 - MHB - Whitegoods 93727 642.TP.2335.01 - PRW - Site Wide LV Equipment Supply 93827 642.TP.1333.01 - MHU - Whitegoods 93827 642.TP.2335.01 - RHE - Concrete Supply 93848 643.1.TP1520.01 - FMC - Hardware & FFE Fixing 93918 642.TP.0420.01 - MHB - Concrete Place & Finish 9893 644.1.TP2239.01 - CP1 - Carparking Control Systems	93569	643.1.TP0330.03 - FMC - Sheet Piling	98155	643.1.TP1311.01 - FMC - Door Supply
93574 642.TP.0631.01 - MHB - Post Tensioning 93575 643.1.TP0620.01 - FMC - Reinforcement Fix 93576 643.1.TP0631.01 - FMC - Door & Hardware Fixing 93576 643.1.TP0631.01 - FMC - Post Tensioning 93577 643.2.TP0620.01 - MHU - Reinforcement Fix 93578 644.1.TP0631.01 - CP1 - Post Tensioning 93578 642.TP.2735.01 - MHB - Insitu Floor Coverings 93581 640.PR0052.01 - PRW - Safety Presautions (PPE) 93582 642.TP.2830.01 - MHB - Tactile Indicators 93583 642.TP.0832.01 - MHB - Waterproofing Roofs & Decks 93585 642.TP.2830.01 - FMC - Carpet Install 93718 642.TP.0832.02 MHB - Waterproofing Roofs & Decks 93585 642.TP.1433.03 - MHB - Furniture - Seating 93719 642.TP.0832.03 MHB - Temporary Waterproofing 93589 642.TP.1433.02 - MHB - Medical Furniture 93720 643.1.TP0832.01 - FMC - Waterproofing & Tanking 93721 643.1.TP3832.01 - FMC - Waterproofing & Tanking - Ro 93722 643.2.TP0832.01 - FMC - Waterproofing 93723 644.1.TP0832.01 - FMC - Waterproofing 93724 643.1.TP2732.02 - FMC - Vinyl Install 93725 642.TP.2335.01 - MHU - Waterproofing 93827 642.TP.1533.01 - MHB - Whitegoods 93827 642.TP.2335.01 - PRW - Site Wide LV Equipment Supply 93828 643.1.TP1520.01 - FMC - Hardware & FFE Fixing 93918 542.TP.0420.01 - MHB - Concrete Place & Finish 93918 542.TP.0420.01 - MHB - Concrete Place & Finish	93572	644.1.TP0620.01 - CP1 - Reinforcement Fix	98336	642.TP.2732.02 - MHB - Vinyl
93575 643.1.TP0620.01 - FMC - Reinforcement Fix 98468 642.TP.2731.01 - MHB - Floor Mats 93576 643.1.TP0631.01 - FMC - Post Tensioning 98468 642.TP.2731.01 - MHB - Insitu Floor Coverings 93578 643.2.TP0620.01 - MHU - Reinforcement Fix 98473 642.TP.2731.01 - MHB - Insitu Floor Coverings 93578 644.1.TP0631.01 - CP1 - Post Tensioning 98495 642.TP.2735.01 - MHB - Tactile Indicators 93581 640.PR0052.01 - PRW - Safety Presautions (PPE) 98495 642.TP.2830.01 - MHB - Tilling 93717 642.TP.0832.01 - MHB - Waterproofing Roofs & Decks 98585 642.TP.1433.03 - MHB - Furniture - Seating 93719 642.TP.0832.03 - MHB - Waterproofing 98589 642.TP.1433.02 - MHB - Medical Furniture 93720 643.1.TP0832.01 - FMC - Waterproofing & Tanking 98683 642.TP.2737.01 - MHB - Wall Protection 93721 643.1.TP3832.01 - FMC - Waterproofing 98706 642.TP.1433.04 - MHB - Compactus Units 93722 643.2.TP0832.01 - MHU - Waterproofing 98794 643.1.TP2732.02 - FMC - Vinyl Install 93723 644.1.TP0832.01 - CP1 - Waterproofing 98820 642.TP.1533.01 - MHB - Whitegoods 93827 642.TP.235.01 - PRW - Site Wide LV Equipment Supply 98821 643.1.TP1520.01 - FMC - Hardware & FFE Fixing 93918 642.TP.0420.01 - MHB - Concrete Place & Finish 9893 644.1.TP239.01 - CP1 - Carparking Control Systems	93573	642.TP.0620.01 - MHB - Reinforcement Fix	98348	644.1.TP2732.02 - CP1 - Vinyl Installation
93576 643.1.TP0631.01 - FMC- Post Tensioning 93576 643.2.TP0620.01 - MHU - Reinforcement Fix 93577 643.2.TP0620.01 - MHU - Reinforcement Fix 93678 644.1.TP0631.01 - CP1 - Post Tensioning 93578 644.1.TP0631.01 - CP1 - Post Tensioning 93581 640.PR0052.01 - PRW - Safety Presautions (PPE) 93717 642.TP.0832.01 - MHB - Waterproofing Inground 93718 642.TP.0832.02 MHB - Waterproofing Roofs & Decks 93719 642.TP.0832.03 MHB - Temporary Waterproofing 93720 643.1.TP0832.01 - FMC - Waterproofing & Tanking 93721 643.1.TP0832.01 - FMC - Waterproofing & Tanking 93722 643.2.TP0832.01 - FMC - Waterproofing 93723 644.1.TP0832.01 - CP1 - Waterproofing 93820 642.TP.1533.01 - MHB - Wall Protection 93721 642.TP0832.01 - FMC - Waterproofing 93820 642.TP.1533.01 - MHB - Whitegoods 93827 642.TP2335.01 - PRW - Site Wide LV Equipment Supply 93828 642.TP.1533.01 - MHU - Whitegoods 93829 644.TP0410.01 - RIE - Concrete Supply 93918 642.TP.0420.01 - MHB - Concrete Place & Finish 93893 644.TP2239.01 - CP1 - Carparking Control Systems	93574	642.TP.0631.01 - MHB - Post Tensioning	98352	644.1.TP1330.01 - CP1 - General Carpentry
93577 643.2.TP0620.01 - MHU - Reinforcement Fix 98473 642.TP.2731.01 - MHB - Insitu Floor Coverings 93578 644.1.TP0631.01 - CP1 - Post Tersioning 98477 642.TP.2735.01 - MHB - Tactile Indicators 93581 640.PR0052.01 - PRW - Sefety Presautions (PPE) 98495 642.TP.2830.01 - MHB - Tiling 93717 642.TP.0832.01 - MHB - Waterproofing Inground 98500 643.1.TP2720.01 - FMC - Carpet Install 93718 642.TP.0832.02 MHB - Waterproofing Roofs & Decks 98585 642.TP.1433.03 - MHB - Furniture - Seating 93719 642.TP.0832.03 MHB - Temporary Waterproofing 98589 642.TP.1433.02 - MHB - Medical Furniture 93720 643.1.TP0832.01 - FMC - Waterproofing & Tanking 98683 642.TP.2737.01 - MHB - Wall Protection 93721 643.1.TP3832.01 - FMC - Waterproofing 98706 642.TP.1433.04 - MHB - Compactus Units 93722 643.2.TP0832.01 - MHU - Waterproofing 98794 643.1.TP2732.02 - FMC - Vinyl Install 93723 644.1.TP0832.01 - CP1 - Waterproofing 98820 642.TP.1533.01 - MHB - Whitegoods 93820 642.TP.1533.01 - MHU - Whitegoods 93820 642.TP.1533.01 - MHU - Whitegoods 93860 641.TP0410.01 - RIE - Concrete Supply 98843 643.1.TP1520.01 - FMC - Hardware & FFE Fixing 93918 642.TP.0420.01 - MHB - Concrete Place & Finish 98993 644.1.TP2239.01 - CP1 - Carparking Control Systems	93575	643.1.TP0620.01 - FMC - Reinforcement Fix	98354	643.1.TP1330.01 - FMC - Door & Hardware Fixing
93578 644.1.TP0631.01 - CP1 - Post Terisioning 93581 640.PR0052.01 - PRW - Safety Presautions (PPE) 93717 642.TP.0832.01 - MHB - Waterproofing Inground 93718 642.TP.0832.02 MHB - Waterproofing Roofs & Decks 93719 642.TP.0832.02 MHB - Temporary Waterproofing 93719 642.TP.0832.03 MHB - Temporary Waterproofing 93720 643.1.TP0832.01 - FMC - Waterproofing & Tanking 93721 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Ro 93722 643.2.TP0832.01 - MHU - Waterproofing 93723 644.1.TP0832.01 - MHU - Waterproofing 93724 645.2.TP.0832.01 - MHU - Waterproofing 93725 642.TP.1533.01 - MHB - Waterproofing 93726 642.TP.1533.01 - MHB - Whitegoods 93827 642.TP2335.01 - PRW - Site Wide LV Equipment Supply 93820 643.1.TP1533.01 - MHU - Whitegoods 93827 642.TP.0420.01 - MHB - Concrete Place & Finish 98993 644.1.TP2239.01 - CP1 - Carparking Control Systems	93576	643.1.TP0631.01 - FMC- Post Tensioning	98468	642.TP.2711.01 - MHB - Floor Mats
93581 640.PR0052.01 - PRW - Safety Presautions (PPE) 98495 642.TP.2830.01 - MHB - Tiling 93717 642.TP.0832.01 - MHB - Waterproofing Deground 98500 643.1.TP2720.01 - FMC - Carpet Install 93718 642.TP.0832.02 MHB - Waterproofing Roofs & Decks 98585 642.TP.1433.03 - MHB - Furniture - Seating 93719 642.TP.0832.03 - MHB - Temporary Waterproofing 98589 642.TP.1433.02 - MHB - Medical Furniture 93720 643.1.TP0832.01 - FMC - Waterproofing & Tanking 98683 642.TP.2737.01 - MHB - Wall Protection 93721 643.1.TP3832.01 - FMC - Waterproofing & Tanking - Ro 98706 642.TP.1433.04 - MHB - Compactus Units 93722 643.2.TP0832.01 - MHU - Waterproofing 98794 643.1.TP2732.02 - FMC - Vinyl Install 93723 644.1.TP0832.01 - CP1 - Waterproofing 98820 642.TP.1533.01 - MHB - Whitegoods 93827 642.TP2335.01 - PRW - Site Wide LV Equipment Supply 98821 643.2.TP1533.01 - MHU - Whitegoods 93860 641.TP0410.01 - RIE - Concrete Supply 98843 643.1.TP1520.01 - FMC - Hardware & FFE Fixing 93918 642.TP.0420.01 - MHB - Concrete Place & Finish 98993 644.1.TP2239.01 - CP1 - Carparking Control Systems	93577	643.2.TP0620.01 - MHU - Reinforcement Fix	98473	642.TP.2731.01 - MHB - Insitu Floor Coverings
93717 642.TP.0832.01 - MHB - Waterproofing Dground 98500 643.1.TP2720.01 - FMC - Carpet Install 93718 642.TP.0832.02 MHB - Waterproofing Roofs & Decks 98585 642.TP.1433.03 - MHB - Furniture - Seating 93719 642.TP.0832.03 - MHB - Jemporary Waterproofing 98589 642.TP.1433.02 - MHB - Medical Furniture 93720 643.1.TP0832.01 - FMC - Waterproofing & Tanking 98683 642.TP.2737.01 - MHB - Wall Protection 93721 643.1.TP3832.01 - FMC - Waterproofing & Tanking - Ro 98706 642.TP.1433.04 - MHB - Compactus Units 93722 643.2.TP0832.01 - MHU - Waterproofing 98794 643.1.TP2732.02 - FMC - Vinyl Install 93723 644.1.TP0832.01 - CP1 - Waterproofing 98820 642.TP.1533.01 - MHB - Whitegoods 93827 642.TP2335.01 - PRW - Site Wide LV Equipment Supply 98821 643.2.TP1533.01 - MHU - Whitegoods 93860 641.TP0410.01 - RIE - Concrete Supply 98843 643.1.TP1520.01 - FMC - Hardware & FFE Fixing 93918 642.TP.0420.01 - MHB - Concrete Place & Finish 98993 644.1.TP2239.01 - CP1 - Carparking Control Systems	93578	644.1.TP0631.01 - CP1 - Post Tensioning	98477	642.TP.2735.01 - MHB - Tactile Indicators
93718 642.TP.0832.02 MHB - Waterproofing Roofs & Decks 93719 642.TP.0832.03 MHB - Temporary Waterproofing 93720 643.1.TP0832.01 - FMC - Waterproofing & Tanking - Ro 93721 643.1.TP3832.01 - FMC - Waterproofing & Tanking - Ro 93722 643.2.TP0832.01 - MHU - Waterproofing & Tanking - Ro 93723 644.1.TP0832.01 - CP1 - Waterproofing 98820 642.TP.1533.01 - MHB - Wall Protection 93724 642.TP.1533.01 - MHB - Wall Protection 93725 642.TP.1433.04 - MHB - Compactus Units 93726 642.TP.1533.01 - MHB - Whitegoods 93827 642.TP.1533.01 - MHB - Whitegoods 93827 642.TP.2335.01 - PRW - Site Wide LV Equipment Supply 93828 642.TP.1533.01 - MHU - Whitegoods 93829 642.TP.1533.01 - MHU - Whitegoods 93820 643.1.TP1520.01 - FMC - Hardware & FFE Fixing 93918 642.TP.0420.01 - MHB - Concrete Place & Finish 98993 644.1.TP2239.01 - CP1 - Carparking Control Systems	93581	640.PR0052.01 - PRW - Safety Presautions (PPE)	98495	642.TP.2830.01 - MHB - Tiling
93719 642.TP.0832.03 MHB - Temporary Waterproofing 98589 642.TP.1433.02 - MHB - Medical Furniture 93720 643.1.TP0832.01 - FMC - Waterproofing & Tanking 98683 642.TP.2737.01 - MHB - Wall Protection 93721 643.1.TP3832.01 - FMC - Waterproofing & Tanking - Ro 98706 642.TP.1433.04 - MHB - Compactus Units 93722 643.2.TP0832.01 - MHU - Waterproofing 98794 643.1.TP2732.02 - FMC - Vinyl Install 93723 644.1.TP0832.01 - CP1 - Waterproofing 98820 642.TP.1533.01 - MHB - Whitegoods 93827 642.TP2335.01 - PRW - Site Wide LV Equipment Supply 98821 643.2.TP1533.01 - MHU - Whitegoods 93860 641.TP0410.01 - RIE - Concrete Supply 98843 643.1.TP1520.01 - FMC - Hardware & FFE Fixing 93918 642.TP.0420.01 - MHB - Concrete Place & Finish 98993 644.1.TP2239.01 - CP1 - Carparking Control Systems	93717	642.TP.0832.01 - MHB - Waterproofing Inground	98500	643.1.TP2720.01 - FMC - Carpet Install
93720 643.1.TP0832.01 - FMC - Waterproofing & Tanking 98683 642.TP.2737.01 - MHB - Wall Protection 93721 643.1.TP3832.01 - FMC - Waterproofing & Tanking - Ro 98706 642.TP.1433.04 - MHB - Compactus Units 93722 643.2.TP0832.01 - MHU - Waterproofing 98794 643.1.TP2732.02 - FMC - Vinyl Install 93723 644.1.TP0832.01 - CP1 - Waterproofing 98820 642.TP.1533.01 - MHB - Whitegoods 93827 642.TP2335.01 - PRW - Site Wide LV Equipment Supply 98821 643.2.TP1533.01 - MHU - Whitegoods 93860 641.TP0410.01 - RIE - Concrete Supply 98843 643.1.TP1520.01 - FMC - Hardware & FFE Fixing 93918 642.TP.0420.01 - MHB - Concrete Place & Finish 98993 644.1.TP2239.01 - CP1 - Carparking Control Systems	93718	642.TP.0832.02 MHB Waterproofing Roofs & Decks	98585	642.TP.1433.03 - MHB - Furniture - Seating
93721 643.1.TP3832.01 - FMC - Waterproofing & Tanking - Ro 98706 642.TP.1433.04 - MHB - Compactus Units 93722 643.2.TP0832.01 - MHU - Waterproofing 98794 643.1.TP2732.02 - FMC - Vinyl Install 93723 644.1.TP0832.01 - CP1 - Waterproofing 98820 642.TP.1533.01 - MHB - Whitegoods 93827 642.TP2335.01 - PRW - Site Wide LV Equipment Supply 98821 643.2.TP1533.01 - MHU - Whitegoods 93860 641.TP0410.01 - RIE - Concrete Supply 98843 643.1.TP1520.01 - FMC - Hardware & FFE Fixing 93918 642.TP.0420.01 - MHB - Concrete Place & Finish 98993 644.1.TP2239.01 - CP1 - Carparking Control Systems	93719	642.TP.0832.03 - MHB - Jemporary Waterproofing	98589	642.TP.1433.02 - MHB - Medical Furniture
93722 643.2.TP0832.01 - MHU - Waterproofing 98794 643.1.TP2732.02 - FMC - Vinyl Install 93723 644.1.TP0832.01 - CP1 - Waterproofing 98820 642.TP.1533.01 - MHB - Whitegoods 93827 642.TP2335.01 - PRW - Site Wide LV Equipment Supply 98821 643.2.TP1533.01 - MHU - Whitegoods 93860 641.TP0410.01 - RIE - Concrete Supply 98843 643.1.TP1520.01 - FMC - Hardware & FFE Fixing 93918 642.TP.0420.01 - MHB - Concrete Place & Finish 98993 644.1.TP2239.01 - CP1 - Carparking Control Systems	93720	643.1.TP0832.01 - FMG - Waterproofing & Tanking	98683	642.TP.2737.01 - MHB - Wall Protection
93722 643.2.TP0832.01 - MHU - Waterproofing 98794 643.1.TP2732.02 - FMC - Vinyl Install 93723 644.1.TP0832.01 - CP1 - Waterproofing 98820 642.TP.1533.01 - MHB - Whitegoods 93827 642.TP2335.01 - PRW - Site Wide LV Equipment Supply 98821 643.2.TP1533.01 - MHU - Whitegoods 93860 641.TP0410.01 - RIE - Concrete Supply 98843 643.1.TP1520.01 - FMC - Hardware & FFE Fixing 93918 642.TP.0420.01 - MHB - Concrete Place & Finish 98993 644.1.TP2239.01 - CP1 - Carparking Control Systems			98706	642.TP.1433.04 - MHB - Compactus Units
93827 642.TP2335.01 - PRW - Site Wide LV Equipment Supply 98821 643.2.TP1533.01 - MHU - Whitegoods 93860 641.TP0410.01 - RIE - Concrete Supply 98843 643.1.TP1520.01 - FMC - Hardware & FFE Fixing 93918 642.TP.0420.01 - MHB - Concrete Place & Finish 98993 644.1.TP2239.01 - CP1 - Carparking Control Systems				643.1.TP2732.02 - FMC - Vinyl Install
93827 642.TP2335.01 - PRW - Site Wide LV Equipment Supply 98821 643.2.TP1533.01 - MHU - Whitegoods 93860 641.TP0410.01 - RIE - Concrete Supply 98843 643.1.TP1520.01 - FMC - Hardware & FFE Fixing 93918 642.TP.0420.01 - MHB - Concrete Place & Finish 98993 644.1.TP2239.01 - CP1 - Carparking Control Systems	93723	644.1.TP0832.01 - CP1 - Waterproofing	98820	642.TP.1533.01 - MHB - Whitegoods
93860 641.TP0410.01 - RIE - Concrete Supply 98843 643.1.TP1520.01 - FMC - Hardware & FFE Fixing 93918 642.TP.0420.01 - MHB - Concrete Place & Finish 98993 644.1.TP2239.01 - CP1 - Carparking Control Systems			98821	643.2.TP1533.01 - MHU - Whitegoods
93918 642.TP.0420.01 - MHB - Concrete Place & Finish 98993 644.1.TP2239.01 - CP1 - Carparking Control Systems			98843	643.1.TP1520.01 - FMC - Hardware & FFE Fixing
			98993	644.1.TP2239.01 - CP1 - Carparking Control Systems





		,	A Division of QMI Solutions
94119	640.PR0033.03 - PRW - Temporary Hydraulics Site Wide	99012	642.TP.3530.01 - MHB - Temporary Carpentry
94122	641.TP1732.01 - RIE - Water & Fire Mains reticulation	99068	642.TP.1432.01 - MHB - Curtains & Blinds
94130	642.TP.0422.01 - MHB - Concrete Pumping	99101	643.2.TP1432.01 - MHU - Curtains & Blinds
94234	643.1.TP2312.01 - FMC - HV Generator Supply	99216	643.2.TP2734.01 - MHU - Epoxy Flooring
94256	642.TP.0431.01 - MHB - Precast Concrete	99219	643.1.TP2731.01 - FMC - Epoxy Flooring
94271	644.2.TP0830.01 - CP2 - Blockwork	99231	643.2.TP1330.01 - MHU - General Carpentry
94272	640.PR0032.02 - PRW - Main Site Office & Accommoda	99234	643.2.TP2830.01 - MHU - Tiling
94283	640.PR0022.02 - PRW - Temporary Lunch Sheds / Abluti	99241	643.1.TP1533.01 - FMC - Whitegoods
94285	642.TP.0060.01 - MHB - Scaffolding	99243	643.1.TP1236,01-FMC Roller Shutters
94320	644.2.TP1131.01 - CP2 - Facade / Screens	99245	643.1.TP1434.01 - FMG - Workstations & Screens
94353	644.2.TP1330.01 - CP2 - General Carpentry	99260	643.2,7P1434.01 4MHU - Workstations & Screens
94362	640.PR0022.07 - PRW - Pest Control	99264	643.1.7P2830.01p FMC - Tiling
94363	640.PR0023.03 - PRW - Temporary Site Signage	9926	643,2,7P1236.01 - MHU - Roller Shutters
94415	640.PR0033.02 - PRW - Main Site Office Accommodatio	99266	642.TP.1531.01 - MHB - Hardware Sundry
94450	640.PR0022.04 - PRW - Site Office Fitout & Furniture	99267	643,2.TP1531,01 - MHU - Sundry Hardware
94506	640.PR0056.02 - PRW - Site Office Cleaning	99301	643.2.TP1433.01 - MHU - Furniture
94527	643.1.TP0410.01 - FMC - Concrete Supply	99309	643.2.TP2711.01 - MHU - Floor Mats
94534	643.1.TP0420.01 - FMC - Concrete Place	9 9310	642.TP.1435.01 - MHB - Folding Doors & Operable Walls
94536	643.1.TP0422.01 - FMC - Concrete Pumping	99314	643.1.TP1435.01 - FMC - Folding Doors & Operable Walls
94537	643.1.TP0431.01 - FMC - Precast Concrete	99315	643.2.TP1435.01 - MHU - Folding Doors & Operable Walls
94538	643.2.TP0410.01 - MHU - Concrete Supply	99316	643.2.TP2732.02 - MHU - Vinyl Instail
94539	643.2.TP0420.01 - MHV - Concrete Placing	99322	643.2.TP2731.01 - MHU - Insitu Floor Coverings
94540	643.2.TP0422.01 - MHU - Concrete Pumping	99409	643.2.TP2735.01 - MHU - Tactile Indicators
94541	644.1.TP0410,01 - CP1 - C oncrete S upply	99423	643.2.TP2737.01 - MHU - Wall Protection
94542	644.1.TP0420.01 CP1 Concrete Place	99428	643.2.TP3131.01 - MHU - Mature Trees
94543	644.1.TP0422.01 - CP1 - Concrete Pumping	99494	642.TP.1520.01 - MHB - Hardware & Ironmongery - Fix
94627	643.1.TP0060.01 - FMC - Scaffolding	99504	642.TP.1531.02 - MHB - Bin Hardware
94628	644.1.TP0060.01 - CP1 - Scaffolding	99507	640.PR0053.01 - PRW - Overall Onsite Surveying
94884	642.TP.0830.01 - MHB - Blockwork	99528	642.TP.1531.04 - MHB - Grab Rails
94885	643.1.TP0830.01 - FMC - Blockwork	99542	643.1.TP1430.01 - FMC - Joinery
94886	643.2.TP0830.01 - MHU - Blockwork	99695	642.TP.1510.01 - MHB - Door Hardware
		_	





	, .		A Division of QMI Solutions
94887	644.1.TP0830.01 - CP1 - Blockwork	99708	643.1.TP1510.01 - FMC - Door Hardware
94907	640.PR0054.01 - PRW - Site Photography	99709	643.2.TP1510.01 - MHU - Door Hardware Supply
94959	644.2.TP3030.01 - CP2 - Painting & Line Marking	99733	642.TP.1238.01 - MHB - Metalwork - Stainless Steel
94960	644.1.TP3030.01 - CP1 - Painting & Line Marking	99736	643.2.TP1238.01 - MHU - Metalwork Stainless Steel
94987	644.2.TP1030.01 - CP2 - Structural Steelwork	99740	643.1.TP1238.01 - FMC - Stainless Steel Metalwork
95031	644.1.TP1030.02 - CP1 - Structural Steelwork	99777	641.TP3130.01 - RIE - Hard Landscaping
95033	642.TP.2230.01 - MHB - Building Maintenance Unit	99782	642.TP.3130.01 - MHB - Hard & Soft Landscaping
95101	643.2.TP1631.01 - MHU - Roofing-Built-up / Membrane	99797	642.TP.1239.01 - MHB Metal Shelving
95111	642.TP.1630.01 - MHB - Roof & Metal Cladding	99804	643.1.TP1239.01 - FMC Wetal Shelving
95112	642.TP.1636.01 - MHB - Wall Cladding Systems	99806	644.1.TP0057.01 - CP1 - Final Clean
95121	642.TP.1032.01 - MHB - Facade Framing	99826	641.TP3131.01 - RIE - Soft Landscaping
95122	642.TP.1132.01 - MHB - Shop Fronts	99827	641.TP3131.02-RIE-Plant / Nursery Supply
95123	642.TP.1135.02 - MHB - Sunshades & Light Shelves	99828	641.TR3132.01 RE-Landscaping Structures / Carpentry
95124	642.TP.1131.01 - MHB - Metal Windows	99896	642.TP.6057.01 MHB - Final Clean
95193	642.TP.1631.01 - MHB - Roofing-Built-up / Membrane	99897	643.1.TP00\$7.01 - FMC - Final Clean
95318	642.TP.1712.01 - MHB - Tanks & Pumps Supply	99898	643.2.TP0057.01 - MHU - Final Clean
95319	643.2.TP1710.01 - MHU - Sanitaryware & Tapware Supp	9991,7	643.2.TP1311.01 - MHU - Doors & Frames Supply
95324	642.TP.1732.02 - MHB - Sanitaryware & Tapware Supp	9991 1	642.TP.1430.01 - MHB - Joinery
95369	642.TP.1231.01 - MHB - Balustrades & Handrajls	99925	643.2.TP1430.01 - MHU - Joinery
95376	642.TP.1230.01 - MHB - Metalwork	<i>\$</i> 9951	642.TP.1436.01 - MHB - Artworks - Internal
95392	642.TP.1235.01 - MHB - Metal Louvres	99965	643.2.TP1436.01 - MHU - Artworks - Internal
95411	642.TP.1232.01 - MHB - Movement Joints	99967	643.2.TP3130.01 - MHU - Hard / Soft Landscaping
95426	643.1.TP1630.01 - FMC - Roof Metal Sheeting	99972	643.1.TP3130.01 - FMC - Landscaping
95427	643.1.TP1636.01 - FMC Facade Cladding	99997	643.2.TP1520.01 - MHU - Door Hardware Fix
95428	643.1.TP1032.01 - FMC - Facade Framing	100003	641.TP1712.01 - RIE - Tanks & Pumps Supply
95429	642.TP.1030.01 MHB Structural Steelwork	100007	642.TP.1531.05 - MHB - Trolleys
95432	643.1.TP1135.01 - FMC - Sunshades and Light Shelves	100020	643.2.TP1030.01 - MHU - Structural Steelwork
95455	643.1.TP1810.02 - FMC - Mechanical Services - Chiller S	100029	642.TP.1437.01 - MHB - Reception Joinery
95456	643.1.TP1810.03 - FMC - Mechanical Services - Cooling	100030	643.2.TP1437.01 - MHU - Reception Joinery
95457	643.1.TP1810.04 - FMC - Mechanical Services - AHU Sup	100032	644.2.TP1230.02 - CP2 - General Metalwork
95458	643.1.TP1810.01 - FMC - Mechanical Services - Tanks	100078	643.1.TP1732.02 - FMC - Greywater Treatment System
95480	643.1.TP1231.01 - FMC - Balustrades & Handrails	100079	643.1.TP1532.01 - FMC - Signage
95543	643.1.TP1235.01 - FMC - Metal Louvres	100449	642.TP1732.061 - MHB - Reverse Osmosis Plant & Equipment
95555	643.1.TP1432.01 - FMC - Curtains & Blinds	100793	642.TP.0410.01 - MHB - Concrete Supply
95576	643.1.TP1230.01 - FMC - Metalwork	100795	640.PR0022.08 - PRW - Vending Machines - CP2
			· · · · · · · · · · · · · · · · · · ·





A Division of QMI Solutions

Attachment B:					
Business Engagement		LIPP Categorisation	Source of Supply		
Sissoniracion	Reason	SEQ - South Elect QLD REQ - Regional QLD AUS - Rest of Australia IMP - Imported	C. Confestable L - Local	PosiCode	Values of Goods of Services supplied
Amalgamated Pest Control	Redback Pest Control to SCUH Site Office	SEQ	L	4561	s.47(3)(b)
Arjohu ntleigh	Medical Beds and Patient Lifting System	<u>IMP</u>	С	6163	
Arunta Plastics (QLD) Pty Ltd	Cultural Heritage Induction	SEQ		3134	
ATF Services Pty Ltd ATF Sunshine Coast and Total Site Set Up	Temp Fencing Supply & Install crowd control barriers	SEQ SEQ	L C	4558 4000	
Beavis & Bartels Ptv Ltd	Temp Hydraulics (Site Wide)	SEQ	C	4013	
Bizfurn Express	Supply and !nstall of office furniture for Pr		C	4561	
Blue Glue Pty Ltd	Blue Gue	AUS	10/	2113	
Buitsmart Modular Mining Pty Ltd	Modular Prototype Suite	AUS	(c / / 1	2250	
Cally Constructions	Prototype Building Foundations	SEQ	(· · ·	4556	
Cally Constructions	Protoype Marketing Rigging and Marketing			4556	
Coates Hire Operations Pty Ltd	Portable toilets General Hire Equipment	SEQ SEQ	(5	4131 4131	
Coates Hire Operations Pty Ltd Combined Security Services	Security Guards	SEQ		4575	
O&J Services	Site Shed Cleaning	SEQ	77/	4011	
DLA Piper	Professional fees	AUS		4000	
Ounckers Pty Ltd	Supply of Site Accomodation Cleaning Pro		A JL	4560	
Energex Limited	Energex Detailed Design	SEQ) \rangle \cdot \text{\rangle}	4558	
Energex Limited	Temporary Electrics supply South	SEQ	U)	4006	
Energy Crane Services Pty	Transport Items to SCUH site	SEQ	L L	4034	
Evolution Trafic Control EVS Group Australia Pty Ltd	Provide traffic Controller Site Security	3EQ /	L L	4558 4350	
EVS Group Australia Pty Ltd Fencepac	Site Perimeter Security Fence - Stage	SEQ	C	4556	
Floor cover QLD - AK	Installation of vinyl and carpet to the Proto		c	4008	
Fredon QLD Pty Limited	SCUH - Nambour Site	SEQ	Č	4119	
3 James	Supply and install of windows and external	SEQ	L	4556	
Sordon Clements Nominees Pty Ltd T/A Calty Constr	Covered Walkways and paths	SEC	L	4556	
Greenbins	Size 8 Bin	// SEQ	L	4074	
Harvey Norman	Supply of kitchen fridge and microvave	SEQ	С	4575	
Ken Wilson & Associates Pty Ltd T/a KWA Blinds	Prototype Curtain & IV Tracks Supply of Bulk Potable and Non-Potable V	SEQ	С	4163 4567	
Kyana Projects Pty Ltd Kyana Pty Ltd	Temporary Hydradiics	SEQ SEQ	С	4567	
ucid Edge PTY LTD	Video conversions from AVI to MWV+ You		Č	4014	
Lucid Edge PTY LTD	Video Conversions from AVI to MWV +	AUS	Č	2010	s.47(3)(b)
Verton (t/a Statewide Communications)	Prototype Nurse Call & RES	AUS	С	4113	
Metro Express	2 Containers sent from GCUN to SCUH	SEQ	Ł	4106	
Vidmed	Supply and install of examination souch	SEQ	C	4570	
Multimedia Technology	83" Multi Touch Interactive Whiteboard	SEQ	C	4006	
Neverfail Springwater Limited Vilsen QLD Pty Ltd	Supply of Potable Water to Site until Feb 1 Temporary Electrical CP2 & Prototype	SEQ SEQ	C	4127 4170	
O2 Environmental Pty Ltd	Environmental and Sediment Monitoring	SEQ	Ĺ	4573	
Orange Hire Pty Ltd	Supply & Hire of Perimeter Fencing	SEQ	L L	2760	
Quality Choice Signs	Re skin to existing Billboard	SEQ	C	4575	
Quality Choice Signs	Signage	SEQ	С	4575	
Quality Choice Signs	Hard Hat Stickers	SEQ	С	4551	
Regson Fabrication	Suppy & Install 2 Gate Closures	SEQ	С	4556	
Robotic Automation Group	AGV Advisory Services	AUS	C	2127	
Scapeshape Pty Ltd Shadforths Civil Pty Ltd	Palmiree re-location Crossover road Construction	SEQ SEQ	L L	4211 4556	
Shadronus Civil Pty Ltd	Supply & replace Road Base - Site Accord		L	4556	
Shadforths Civil Pty Ltd	P2 Early Works	SEQ	L	4556	
Siemens	Prototype Security	IMP	C	4006	
Spence Door	Supply doors and frame	SEQ	L	4556	
Steve Ryan t/as Rix Ryan Photography P/L	Photograph Palm removal & monthly image		L	4215	
Suncoast Water Carriers	Re-Fill 2 x 10000L Water Tanks + 1 Addition		L	4551	
mmediate Response First Aid	Car Park First Aid Shed & First Aid	SEQ	L	4556	
The trustee for The SJ & DY Eade Family Trust T/A \ Transpacific Industries Pty Ltd	Supply and install shade cloth to SCUH Si Site Sewerage Tank Pump Out	SEQ SEQ	C	4570 4064	
rumof Med Australia Pty Ltd	3x3 Combination light set & Trumpf Serv	IMP	c	2067	
Inderground Pipe and Cable Location Pty Ltd	Detect inground services prior to digging f	_	č	4553	
hiversal Cranes Sunshine Coast Pty Ltd	Mobile Crane Hire	SEQ	L	4556	
/iridiar:	Supply and deliver of Mirrors for Prototype		С	4173	
Vagstaff Piling	Site Probing Works - 55 Probe Locations	SEQ	L	4060	
Vagstaff Piling QLD Pty Ltd	Test Piling	SEQ	L	406C	
Vorldwide Online Printing Market Street	Masterplan Poster	SEQ	14.1	4000	
	Corporate Charges	SEQ	<u>L</u>		





A Division of QMI Solutions Attachment C: Business Engagement LIPP Catagorisatic Source of Supply Subcontracto NorkPackage SPAIN SOUTH East AIRD G KONNEGGO PentOnde Veluga of Groom Supplier's Scattern REQ - Regional QLD AUS - Reat of Austral - Local and Services MP - Imported A1 Waterproofing 642.TP0832.01 - MHB - In ground Waterproofing C 4165 Brisbane - East SEO A1 Waterproofing & Applications Pty Ltd 643.1.TP0832.01 - FMC - Waterproofing SEQ C 4165 Brisbane - East Able Security Group 641.TP1510.01 - CP2 - Door Hardware Supply SEQ C 4575 Sunshine Coast 641.TP1712.01 - CP2 - Rainwater Tanks ALS SEQ C 4575 Sunshine Coast Amalgamated Painting 640.TP3030.01 CP2 - Painting SEO 4214 Gold Coast 843 1 TP0330 01 - FMC - Sheet Piënc ASP Pilling Pty Ltd SEQ Gold Coast C 4214 Beavis & Bartels Pty Ltd MHB - Temporary Hydraulics SEQ 4060 SEOM Boral Construction Materia's (QLD) 644.2.TP0410.01 - CP2 - Concrete Supply 4059 SEQ Brisbane Inner City Bosform Ptv Ltd 643.1.TP0530.01 - FMC - Formwork SEQ 4297 Gold Coast L Coastcrete 642 TP 0431 01 - MHB - Precast \$EQ L 4215 Gold Coast Custom Shades Pty Ltd 641.TP1633.00 - CP2 - Shade Structure SEQ 4:73 Brisbane - East 1 Delco Steel Old Pty Ltd 642 TP0620 01 - MHB - Reo Fix 2000 NSW 644.2.TP0620.01 - CP2 - Reinforcement Fix Delco Steel Old Pty Ltd C 2809 NSW 643.1.TP0620.01 - FMC - Reinforcement Flxing Deico Steel Q'd Pty Ltd С Other Street 2000 NSW 641.TP2430.01 - CP2 - Car Park management syst Designa Sabar 5009 SA East Coast Concrete Contractors 644.2.TP0420.01 - CP2 - Concrete Place and Finish Other San C 2485 NSW 2485 Eastcoast Concrete Contractors 642.TP0420.02 - MHB - Concrete Place C NSW Office 545 Eastcoast Concrete Contractors 642.TP.0420.01 - MHB - Substructure, incl Pile frim C 2485 NSW 644.2.TP2330.01 - CP2 - Electrical Installation FIP Electrical (Qld) Pty Ltd SEQ 4144 Brisbane Inner City 641.TP2530.01 - CP2 - ICT Fredon Electrica SEQ 4119 Logan - Beaudeseri Gordon Clements Nominees Pty Ltd T/A 641.TP1330.01 - CP2 - Carpentry SEQ 4556 Sunshine Coast Heinrich 642.TP0530.01 - MHB - Formwork SEQ 4207 SEQM 642.TP0410.01 - MHB - Concrete Supply REG Old Holcim REQ 4701 Manly Concrete 643.1.TP0420.01 - FMC - Concrete Placing SEO 4173 Brishane - Fast Matchett 642.TP0830.01 - MHB - Blockwork SEQ 4559 Sunshine Coast Matchit Blocklaying 644.2.TP0830.01 & 644.1.TP0830.01 - Blockwork C SEQ 4559 Sunshine Coast 644.2.TP0530.01 - CP2 - Install Formwork SEQ 4173 Brisbane - East Oneform 643.1.TP0410.01 - FMC - Reo Supply Onesteel SEO C 4108 Brisbane - South 642.TP0610.01 - MHB - Reo Supply SEQ C 4108 SEOM s.47(3)(b) OTIS Elevator Company Pty Ltd 642.TP.2030.01 - MHB - Vertical Transportation SEG 4101 Brisbane Inner City OTIS Elevator Company Pty Ltd 643.1.TP2030.01 - FMC - Vertical Transportation **SEQ** 1 4101 Brisbane Inner City QTIS Elevator Company Pty Ltd 643.2.TP2030.01 - MHU - Vertical Transportation SEC L 4101 Brisbane Inner City OTIS Elevator Company Pty Ltd SEC 4101 Brisbane Inner City 644.1.TP2030.01 - CP1 - Vertical Transportation 640.TP3131.01 - CP2 - Landscaping SEQ 4553 Sunshine Coast L PR0057.03 - CP2 - General Clean SEQ Pickwick Group Ptv Ltd L 4101 SEOld Polyseal Waterproofing QLD Pty Ltd 644.2.TP0832.01 - CP2 - Waterproofing SEQ C 4207 Gold Coast Premier Signs 640.TP1532.01 - CP2 - Signage SEQ 4108 Brisbane - South Pro Concrete Puntoina 644.2.TP0422.01 - CP2 -Concrete Pumping SEQ 4220 Gold Coast 642.TP0422.01 - MHB - Concrete Pumping 4220 Pro Concrete Pumping SEQ L SEOId QLD Drink and Snack Machines 640.PR0022.08 - PRW - Vending Machines - OP2 SEQ C 4559 Sunshine Coast Regson Fabrications 641.TP1230.01 - CP2 - Façade SEQ C 4556 Sunshine Coast 640.TP1230.0/ CP2 - General Metalwork Regson Fabrications SEQ C 4556 Sunshine Coast 641.TP.0230.01 RIE - Bulk Earthworks and Fill Shadforth Civil Engineering SEO 4556 Sunshine Coast Sharprock Civil 641.TP.0230.02 - RIE - Preloac SEQ 4076 lpswich Siemens 641.TP2430.01 - SP2 - Security 3153 VIC 644.2.TP0631.01 - CP2 Post Tensioning Structural Systems (Northern) Pty Ltd SEQ C 4207 Gold Coast Sunshine Coast Air Conditioning Service 644.1.TP1830.01 - SP2 - Mechanical SEQ 4556 Sunshine Coast 844.2.1P1732.01 - CP2 - Hydraulics 4573 Tacoma Plumbing and Drainage SEQ C Sunshine Coast Unispan Australia Pty Ltd 644.2 TP0060.01 - CP2 - Scaffolding SEQ 4207 Gold Coast Tower Crane to CP2 VT Services SEQ 1 4074 Brisbane - West 641 P0330.02 - CP1 - Piling Wagstaff Plling Qld Pty Ltd SEQ 4060 Brisbane 643.1 TP0330.02 - FMC - Precast Piling Wagstaff Piling Qld Pty Ltd SEQ 4060 Brisbane Inner City Admira! Concreting Pty Ltd 841.2.TP0420.01 - CP1 - Concrete Place and Finish SEQ SECIId L 4034 OTIS Elevator Company Pty Ltd 644.1:TP2038.01 - CP2 - Vertical Transportation SEQ 4000 SECIId 642.TP.0631.01 - MHB - Post Tensioning SEQ 4207 SEOM Structural Systems unitation Post Terretoring SEC C 4934 8E 9H Menrich Genetichory

Note: Substructure wasn't listed on ICN Gateway website as an opportunity for companies to register through ICN.

644.2 TP0586-84+OP1 > Formework





A Division of QMI Solutions

ATTACHMENT D: Local Industry Participation Plan Outcomes Report Progress Report to 30-03-2014

Project:

Sunshine Coast University Hospital

Project Proponent:

Queensland Health

Contractor:

Lend Lease

Project Location:

Sunshine Coast

Total Project Value:

\$1.8 Billion

Total Value of Contracts:

\$166,468,461.00

ntracts: 57

Value of Contracts placed with

\$163,449,150.95

No. of Contracts:

53

Old businesses:

\$103,443,13U.33

() /

Value of work performed by regional Old businesses

\$0.00

No. of Contracts:

0

(included in total Qld figure

above):

Value of work performed with

businesses outside Qld but within Australia/NZ:

\$0,00

No. of Contracts:

2

Value of Work performed by

Overseas Firms:

\$2,115,519.85

No. of Contracts:

2

Tender Evaluation Criteria:

Tender Evaluation Criteria:

These works are subject to the Queensland Government's local Industry Policy. The successful Contractor is required to provide full, fair and reasonable opportunity to local suppliers and specialist subcontractors when tendering the provision of equipment or services supplied under the scope of works. Contractors are encouraged to use the services of Industry Capability Network (Queensland) ("ICN") to ensure that supply tender invitations meet the requirements of the policy.

Value of Capital Investment:

\$1.8 billion

Employment (FTE)

Construction (FTE):

412

Operational (FTE):

(calculated using AEC multipier)

Skills Development

Number of courses:

No People Trained:

List of Courses:

WHS Representative Course, Safe Working at Heights, General Safety Induction

Innovation, research and development

Project Innovation (brief summary):

(Innovation is the process of intraducing new or significantly improved goods or services and/or implementing new or significantly improved processes.)

This project has put in place a number of good practice or procedures which have presented opportunities to introduce innovative services, products or processes.

Project Research and Development expenditure (brief summary)

Research and Development systematic, investigative and experimental activity that involves innovation or high technical risk acquiring new knowledge or creating new or improved products, devices, processes or services.)

Lip Progress Report #18 Scan April 201449 P8.772





Sunshine Coast University Hospital: Local Industry Participation

Progress Report #19 for period to 31 May 2014 Prepared by Industry Capability Network (Queensland) Ltd

This report details the assistance provided during the above period by ICN (Qld) to Lend Lease in the delivery and implementation of the Local Industry Participation Plan (LIPP) for the Sunshine Coast University Hospital in accordance with the Local Industry Policy (LIP).

1. Liaison with the Project on LIP Issues

ICN met with Queensland Health (Sam Betros) in May 2011 to discuss the project, ICN services, and LIP procedures and issues. ICN assisted QH in the development of the LIPP for the project and provided an evaluation report to QH on project bidders' LIP plan submissions in March 2012.

ICN met with Lend Lease construction management manager on 30th April to review the status of contestable items for the project. ICN had completed all processing for advertised contestable work packages by end of January. Lend Lease advised requested that registration for all opportunities be closed in May and that decisions were pending on other FF&E procurement. Once the procurement approach was confirmed any available work opportunities would be listed on the ICN Gateway and advice published on that site.

2. Liaison with Lend Lease on LIP Compliance

Lend Lease met with ICN to establish processes and procedures for management of the project's obligations to the LIP. It was decided that ICN will provide support on number of services covering:

- Implementation of the LIPP (capability searches on contestable packages)
- Presenting at briefing sessions
- Registering companies via ICN Gateway
- Verification of source of manufacture and service provision in subcontracts
- Business matching
- Progress reporting (Monthly) and final LIPP Outcomes reporting (at end of project)

3. Tier Barometer

Tier Barometer is an on-line self-assessment tool developed by ICN and the State Government. It provides participating companies with an assessment of their tier level in terms of supply to major projects. The tool is used by the project to analyse the basic capabilities of potential suppliers during the registration process.

4. Contestable Packages

Contestable items or packages are those that could potentially be sourced locally or overseas but do not include designated items such as concrete supply, earthworks, etc., which it is assumed will always be supplied from sources local to the project. Nor do they include items that have no chance of being manufactured in Australia, eg turbines. LL supplied ICN with the full schedule of subcontract trade packages for the project. ICN subsequently allocated these into contestable and non-contestable packages.

5. Work Packages

Queensland and Australian capability, content and capacity will be considered for all the work packages. The following activities have been undertaken:





- An ICN officer has been assigned full time to the project.
- Detailed Business Matching has been carried out by ICN. 261 work packages have been managed in this way.
- 1490 registrations against work packages on Gateway have been received
- 65 early works have been awarded in March. These are listed at Attachment B.
- 67 work packages have been awarded so far and they are listed at Attachment D.

Potential subcontractors will be given an indication of the size and generic nature of the project, and questioned regarding their capability and capacity to carry out the work, code compliance, and previous work history. Reports will be sent to Lend Lease detailing local companies which have the capability and capacity to carry out the work for each of the above packages. The primary objective of the Local industry Policy is to ensure that competitive local companies are given full, fair and reasonable opportunity to tender for work packages. This objective will be achieved if the companies nominated by ICN, and other local companies that Lend Lease is aware of, are considered in the establishment of the tender list, and, subject to meeting pre-qualification criteria, a reasonable number of local companies are subsequently invited to tender. Lend Lease intends to apply this requirement.

6. Source of Supply



Lend Lease has advised that out of 132 Purchase Orders, 65 were awarded for early works, 67 for Work Packages during construction. Most of the work packages were awarded to companies that registered interest via CN. As fan as practicable, the measurement of industry participation focuses on the actual source of supply rather than the location through which the order is placed. The location in which services are provided, materials manufactured or where value adding takes place is indicative of the actual source of supply. Of the 67 Work Package contracts that have been awarded, 53 were won by South East Queensland (SEQ) companies, one by Regional Queensland, 13 by other States.

As subcontracts are awarded, the source of manufacture or service provision for contestable packages will be validated and verified in discussion with the corresponding subcontractors. The aggregate value to Queensland and Australian industry will be reported for all packages, and for contestable packages alone. The aggregate value to Queensland and Australian industry of packages awarded so far has been estimated across all trade packages (including both contestable and non-contestable packages) and is currently:

Value of contracts awarded (to date):

Value of components made in Old in contracts awarded (to date):

Value of components made in other states & NZ in contracts awarded (to date):

Value of components made overseas in contracts awarded (to date):

\$ 218.176 M
\$ 207.04 M
Value of components made overseas in contracts awarded (to date):

\$ 9.01 M




These figures are shown graphically in the diagram on the left (top) in terms of the percentage by value of all contracts awarded (contestable and non-contestable), with the Queensland content in the project broken down into Local, South East Queensland, Regional Queensland, Other States and New Zealand, and Overseas figures. The total Queensland content is currently 94.90%.

However, the Local Industry Policy is concerned mainly with contestable contracts as "Local" components are assumed to always be available from sources that are geographically close to the project location. The figures for contestable contracts only are







shown in the diagram on the left (bottom), and these figures are included in reports back to the Department of State Development, Infrastructure and Planning (DSDIP). The Queensland content for contestable contracts is currently 52.62%.

A total of 67 contracts (including 29 contestable contracts) have been awarded where the source of manufacture or service provision is predominantly within Queensland. No contract was awarded directly to regional companies, as the project was predominantly based in South East Queensland.

7. Prototype Building

A prototype showcase building was erected in record time. This enabled focus group to provide input in to the final design in a cost effective manner.

8. Local Industry Participation

Lend Lease Project Director has personally provided project work scope and Lend Lease supplier engagement approach information to a number of larger Australian Manufacturers who have asked for more information. These include The GWA Group; The Laminex Group; Spence Doors and Roskcote industries. For the latter company time was dedicated to a site inspection of their manufacturing facilities.

9. Information Sessions

ICN supported Lend Lease in delivering briefing sessions as proposed in their LIP plan covering:

Monday 3rd September 2012 – Civil, Infrastructure, Structure & Landscaping

Monday 17th September 2012 - Services

Monday 24th September 2012 - Roof & Façade

Monday 8th October 2012 - Fit out & Finishes

Monday 15th October 2012 - Furniture Fittings & Equipment (FF&E)

Lend Lease also presented at the General Briefing Sessions along with ICN on 13, 14, 16 and 20th of August 2012.

Lend Lease project managers attended a briefing presentation by the members of the Cleantech Industries group of companies on 24th September 2012.

Lend Lease took part in a Local Business expo on 10th May 2013.

ICN – Evan Flower – presented to the Gympie Major Project Opportunities Forum on the project on 18th June 2013.

10. Efforts to engage with Local Companies include:

Press release by Health Minister, radio interviews by Project Director, Newspaper articles in CM and Sunshine Coast Daily followed up by substantial advertisements in the same newspapers on 19th January. Support articles followed from SSC Council and local councillors.

As a result of the above information sessions and the advertising campaign almost 1000 registrations have been received with close to 100 companies listing after the newspaper advertisements.

To date over 1490 companies have registered interest in work packages.






11. Source of Manufacture

As subcontracts begin to be awarded, the source of manufacture or service provision for contestable packages will be validated and verified in discussion with the corresponding subcontractors.

12. Reporting

A summary of LIP progress is shown in Attachment C.







Attachment A						
Busmess Engagement		LIPP Categorisation	Source of Supply			
Subcontractor	Resson	SEQ - South East JLD REQ - Regional QLD AUS - Rest of Australia IMP -: Impoded	Contestable L-Local	PostCode	Values of Goods or Services supplied	
Amalgamated Pest Control	Redback Pest Control to SCUH Site Office	SEQ	L	4561	s.47(3)(b)	
Arjohuntleigh	Medical Beds and Patient Lifting System	IMP	C	6163		
Arunta Plastics (QLD) Pty Ltd	Cultural Heritage Induction	SEQ		3134		
ATF Services Pty Ltd	Temp Fencing	SEQ	<u> </u>	4558		
ATF Sunshine Coast and Total Site Set Up Beavis & Bartels Ptv Ltd	Supply & Install crowd control barriers Temp Hydrautics (Site Wide)	SEQ SEQ	C	4000		
Bizfurn Express	Supply and Install of office furniture for Pr		C	4013 4561		
Blue Glue Pty Ltd	Blue Glue	AUS	L .	2113		
Builtsmart Modular Mining Pty Ltd	Modular Prototype Suite	AUS	6	2250		
Catty Constructions	Prototype Building Foundations	SEQ	[L(//	4556		
Cally Constructions	Protoype Marketing Rigging and Marketing	SEQ		4556		
Coates Hire Operations Pty Ltd	Portable toilets	SEQ		4131		
Coates Hire Operations Pty Ltd	General Hire Equipment	SEQ		4131		
Combined Security Services	Security Guards	SEQ		4575		
D&J Services	Site Shed Cleaning	\$EQ	L	4011		
DLA Piper Dunckers Pty Ltd	Professional fees	AUS		4000		
Energex Limited	Supply of Site Accommodation Cleaning Pro Energex Detailed Design	SEQ SEQ		4560 4558	•	
Energex Limited	Temporary Electrics supply South	SEQ /	N 7 !	4006		
Energy Crane Services Pty	Transport Items to SCUH site	SEQ		4034		
Evolution Traffic Control	Provide traffic Controller	SEQ		4558		
EVS Group Australia Pty Ltd	Site Security	SEQ7 /	L	4350		
Fencepac	Site Perimeter Security Fence - Stage 1	SEØ / 1	С	4556		
Floor cover QLD - AK	Installation of vinyl and carpet to the Prato	SEQ	С	4008		
Fredon QLD Pty Limited	SCUH - Nambour Site	SEC	С	4119		
G James	Supply and install of windows and external	SEQ	L	4556		
Gordon Clements Nominees Pty Ltd T/A Calty Constru		SEQ	L	4556		
Greenbins	Size 8 Bin	SEC	L	4074		
Harvey Norman	Supply of kitchen fridge and microwave	// SEQ	C	4575		
Ken Wilson & Associates Pty Ltd T/a KWA Blinds	Prototype Curtain & IV Tracks Supply of Bulk Potable and Non-Potable V	SEQ	С	4163 4567		
Kyana Projects Pty Ltd Kyana Pty Ltd	Temporary Hydrautics	SEQ SEQ	C	4567 4567		
Lucid Edge PTY LTD	Video conversions from AVI to MWV+ You		C	4014		
Lucid Edge PTY LTD	Video Conversions from AVI to MWV +	AUS	c	2010	•	
Verlon (t/a Statewide Communications)	Prototype Nurse Cal & PES	AUS	Č	4113	s.47(3)(b)	
Vetro Express	2 Containers sent from GCUH to SCUH	SEQ	L	4106	`	
Vidmed	Supply and install of examination couch	SEQ	С	4570		
Multimedia, Technology	83" Mutti Toush Interactive Whiteboard	SEQ	С	4006		
Neverfail Springwater Limited	Supply of Rotable Water to Site until Feb 1	SEQ	С	4127		
Vilsen QLD Pty Ltd	Temporary Electrical CR2 & Prototype	SEQ	С	4170		
02 Environmental Pty Ltd	Environmental and Sediment Monitoring	SEQ	L	4573		
Orange Hire Pty Ltd Quality Choice Signs	Supply & Hire of Perimeter Fencing Re skin to existing Billboard	SEQ SEQ	C	2760		
Quality Choice Signs	Re skit to existing billboard Signage	SEQ	C	4575 4575	•	
Quality Choice Signs	Hard Hat Stickers	SEQ	C	45/5	1	
Regson Fabrication	Suppy & Install 2 Gate Closures	SEQ	c	4556		
	AGV Advisory Services	AUS	Č	2127		
Scapeshape Pty Ltd	Paintree re-location	SEQ	L	4211	1	
Shadforths Civil Pty Ltd	Crossover road Construction	SEQ	L	4556]	
Shadforths Civil Pty Ltd	Supply & replace Road Base - Site Accon	SEQ	L	4556]	
Shadforths Civil Pty Ltd	P2 Early Works	SEQ	L	4556		
Siemens	Prototype Security	iMP	С	4006		
pence Door	Supply doors and frame	SEQ	<u>L</u>	4556		
Steve Ryan t/as Rix Ryan Photography P/L Suncoast Water Carriers	Photograph Palm removal & monthly image Re-Fill 2 x 10000L Water Tanks + 1 Addition	SEQ	L	4215		
nuncoast water Carners minediate Response First Aid	Re-Filt 2 x 10000L Water Tanks + 1 Addition	SEQ SEQ	L	4551 4556		
he trustee for The SJ & DY Eade Family Trust T/A V			C	4570		
ranspacific Industries Pty Ltd	Site Sewerage Tank Pump Out	SEQ	C	4064	-	
rumpf Med Austrača Pty Ltd	3x3 Combination light set & Trumpf Serv	IMP	C	2067	•	
Inderground Pipe and Cable Location Pty Ltd	Detect inground services prior to digging f	SEQ	C	4553		
hiversal Cranes Sunshine Coast Pty Ltd	Mobile Crane Hire	SEQ	-1	4556	•	
/iridian	Supply and deliver of Mirrors for Prototype	SEQ	C	4173	1	
Vagstaff Piling	Site Probing Works - 55 Probe Locations	SEQ	L	4060	1	
Vagstaff Piling QLD Pty Ltd	Test Piling	SEQ	n L S	4060	1	
Vorkwide Online Printing Market Street	Masterplan Poster	SEQ	L	4000	1	
		SEQ				





Attachment B:		, , , , , , , , , , , , , , , , , , , ,				
Business Engagement		LIPP Categorisation				
Selecontractor	WorldFactorge	REQ - Regional QLD REQ - Regional QLD AUS - Rest of Australia IMP - Imported	C. Corrisatible L Local	PostCots	Values of Goods and Services	Supplier's location
A1 Waterproofing	642.TP0832.01 - MHB - In ground Waterproofing	SEQ	С	4165	s.47(3)(Brisbane - East
A1 Waterproofing & Applications Pty Ltd	643.1.TP0832.01 - FMC - Waterproofing	SEQ	С	4165		Brisbane - East
Able Security Group	641.TP1510.01 - CP2 - Door Hardware Supply	SEQ	С	4575		Sunshine Coast
ALS	641.TP1712.01 - CP2 - Rainwater Tanks	SEQ	C	4575		Sunshine Coast
Ama:gamated Painting	640.TP3030.01 CP2 - Painting	SEQ	L	4214		Gold Coast
ASP Piling Pty Ltd	643.1.TP0330.01 - FMC - Sheet Piling	SEQ	С	4214		Gold Coast
Beavis & Bartels Pty Ltd	MHB - Temporary Hydraulics	SEQ	С	4060	<u> </u>	SEOM
Boral Construction Materials (QLD)	644.2.TP0410.01 - CP2 - Concrete Supply	SEQ	L	4059	<u> </u>	Brisbane Inner City
Bosform Pty Ltd	643.1.TP0530.01 - FMC - Formwork	SEQ	L	4207		Gold Coast
Coastcrete	642.TP.0431.01 - MHB - Precast	SEQ	L	4215		Gold Coast
Custom Shades Pty Ltd	641.TP1633.00 - CP2 - Shade Structure	SEQ	L	4(173//	K)	Brisbane - East
Delco Steel Old Pty Ltd	642.TP0620.01 - MHB - Reo Fix	Other States	С	2090	<i>y /</i>	NSW
Delco Steel Qld Pty Ltd	644.2.TP0620.01 - CP2 - Reinforcement Fix	Other States	C	2000		NSW
Delco Steel Qld Pty Ltd	643.1.TP0620.01 - FMC - Reinforcement Fixing	Other States	C	2006		NSW
Designa Sabar	641.TP2430.01 - CP2 - Car Park management syste	The second secon	<u></u>	5009	 	SA
East Coast Concrete Contractors	644.2.TP3420.91 - CP2 - Concrete Place and Finish		d	2)185	H	NSW
Eastcoast Concrete Contractors	642.TP0420.02 - MHB - Concrete Place	Other States	<u> </u>	2486	H	NSW
Eastcoast Concrete Contractors	642.TP.0420.01 - MHB - Substructure, incl Pile trime 644.2.TP2330.01 - CP2 - Electrical Installation	The second second	000	2485	H	
FIP Electrical (Qld) Pty Ltd Fredon Electrical	644.2.1P2330.01 - CP2 - Electrical Installation	SEQ SEQ	C	4144 7 4119	H	Brisbane Inner City Logan - Beaudeser
Gordon Clements Nominees Pty Ltd T/A		SEQ	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ 	4556	H	Sunshine Coast
Heinrich	642.TP0530.01 - CP2 - Carpenry	SEQ	Y ([])	4207	H	S E Qld
Holcim	642.TP0410.01 - MHB - Concrete Supply	REA		4701	H	REG Old
Manly Concrete	643.1.TP0420.01 - FMC - Concrete Placing	SEQ 7		4173	+	Brisbane - East
Matchett	642.TP0830.01 - MHB - Blockwork	SEQ	/ 	4559	t l	Sunshine Coast
Matchit Blocklaying	644.2.TP0830.01 & 644.1.TP0830.01 - Blockwork C	SEO	//: "	4559	ł	Sunshine Coast
Oneform	644.2.TP0530.01 - CP2 - Install Formwork	SEQ		4173	+	Brisbane - East
Onesteel	643.1.TP0410.01 - FMC - Reo Supply	SEQ	C	4108	t l	Brisbane - South
Onesteel		SEQ	c	4108	+	S E Qld
OTIS Elevator Company Pty Ltd	642.TP0610.01 - MHB - Reo Supply 642.TP.2030.01 - MHB - Vertical Transportation	SEQ	L	4101	H	Brisbane Inner City
OTIS Elevator Company Pty Ltd	643.1.TP2030.01 - MINB - Vertical Transportation	SEC	L	4101	H	Brisbane Inner City
OTIS Elevator Company Pty Ltd	643.2.TP2030.01 - MHU - Vertical Transportation	SEZ	L	4101	+	Brisbane Inner City
OTIS Elevator Company Pty Ltd	644.1.TP2030.01 - CP1 - Vertical Transportation	8EQ	L	4101	H	Brisbane Inner City
Penfolds	640.TP3131.01 - CP2 - Landscaping	SEQ	L	4553	+	Sunshine Coast
Pickwick Group Pty Ltd	PR0057.03 - CP2 - General/Clean	7 SEQ	L	4101	+	S E Qld
Polyseal Waterproofing QLD Pty Ltd	644.2.TP0832.01 - CP2 - Waterproofing	SEQ	C	4207	s.47(3)(b)	Gold Coast
Premier Signs	640.TP1532.01 - CP2 - Vvala prooming			4108	` /` /	Brisbane - South
	644.2.TP0422.01 - CP2 - Concrete Pumping	SEQ SEQ	L L	4220	H	Gold Coast
Pro Concrete Pumping		SEQ	L L	4220	+	S E Qld
Pro Concrete Pumping	642.TP0422.01 - MRB - Concrete Pumping		C C	4556	+	Sunshine Coast
Regson Fabrications Regson Fabrications	640.TP1230.01 - CP2 General Metalwork	SEQ	C		+	
	641.TP.0230.01 - RIE - BUIK Earthworks and Filt	SEQ		4556	+	Sunshine Coast
Shadforth Civil Engineering Sharmock Civil	641.TP.0230.02 - RIE - Preipad	SEQ	L	4556	+	Sunshine Coast
Ciana	641.T/2430.Q1 - CP2 - Security	SEQ	-	4076 3153	+	lpswich VIC
Charles Carteres (Northwest Dt. 1 td		OFF PRINTS	L		H	
Structural Systems (Northern) Pty Ltd Sunshine Coast Air Conditioning Service	644.2.7.0631.01 CP2 - Rost Tensioning	SEQ SEQ	C	4207 4556	H	Gold Coast Sunshine Coast
			L		H	
Tacoma Plumbing and Drainage	644.2.:R1732.01 - CP2 - Mydrautics	SEQ	С	4573	H	Sunshine Coast
Unispan Australia Pty Ltd Wagstaff Piking Qld Pty Ltd	944.2 TP0060.01 - CP2 - Scaffolding	SEQ		4207	H	Gold Coast
<u> </u>	641.7/03 <mark>20.02 - GP1</mark> - Piling	SEQ	L	4060	H	Brisbane
Wagstaff Plang Qld Pty Ltd	\$43.1.TP0330.02 - FMC - Precast Plang	SEQ	L	4080	i	Brisbane Inner City
Admiral Concreting Pty Ltd	641.2TP0420.01 - CP1 - Concrete Place and Finish		L	4034	H	SEQId
OTIS Elevator Company Pty Ltd	644 1.TP2930.01 - CP2 - Vertical Transportation	SEQ	L	4000 4207	H	S E Old
Structural Systems	642.TP.0637.C1 - MHB - Post Tensioning	SEQ	C		H	S E Qid SE Qid
Australian Post Tensioning Heinrich Constuctions	641.2.TP0631.01 - CP1 - Post Tensioning 641.2.TP0530.01- CP1 - Formwork	SEQ	L	4504 4207	H	SE Qld
Heinrich Constitutions	64. The sound - Language Valuation and	SEC	8	4207	r	SE GIG
Cummins South Pacific Pty Ltd	7 TP2330.03 - Generators	Other States	G	3171	ł	VIC
Boslab Ply Ltd	77P2232.01 - Medical Gases	Other States	3	2111	t	NSW
posiao ry cio Johnson Controls	7 TP1810 04 - Chillers	SEQ	C	4030	t	SE Qid
ponnson Concepts Pty Lid	7 TP 1830.05 - Pneumatic tube	Other Sizaes	G	2214	t	NSW
	7 TP1810.02 - Cooking Towers	SEQ.	C	4119	ł	SE Old
ritchard Pacific Pty Ltd	17.121810.02 - Cooking Towers 642.TP.1131.01 - Façade Windows & FHG	SEQ	č	4173	t l	SE Qid
Superior Wells & Ceilings	642 TP 1032.01 - Fagade Framing	SEQ		4211	î	SE Old
Fivo Australia Pty Ltd	7 TP2130,01 - Fire Protection Services	Other States	7	2118		NSW
Vaco Kwikform Limited	642.TP.0080.01 - Scalibiding	SEQ.		4558	t	SE Old
Vational Fire Solutions (QLD)	640.TP2131.01 - CP2 - Wet & Dry Fire	SEQ		4009	Î	SE CM
	640 TP1930.01-CP2 - BM 69	Other Clates		3153	†	MIG





ATTACHMENT C: Local Industry Participation Plan Outcomes Report

Progress Report to 31-05-2014

Project:

Sunshine Coast University Hospital

Project Proponent:

Queensland Health

Contractor:

Lend Lease

Project Location:

Sunshine Coast

Total Project Value:

\$1.8 Billion

Total Value of Contracts:

\$218,176,286.00

No. of Contracts:

67

Value of Contracts placed with

\$207,045,429.75

\$432,750.00

No. of Contracts:

No. of Contracts:

No. of Contracts:

59 |

0

3

Qld businesses:

Value of work performed by

regional Qid businesses (included in total Qld figure

above):

Value of work performed with

businesses outside Qld but within Australia/NZ:

Value of Work performed by

Overseas Firms:

\$9,012,638.65

\$2,118,217.60

No. of Contracts:

5

Tender Evaluation Criteria:

Tender Evaluation Criteria:

These works are subject to the Queensland Government's Local Industry Policy. The successful Contractor is required to provide full, fair and reasonable opportunity to local suppliers and specialist subcontractors when tendering the provision of equipment or services supplied under the scope of works. Contractors are encouraged to use the services of Industry Capability Network (Queensland) ("ICN") to ensure that supply tender invitations meet the requirements of the policy.

Value of Capital Investment:

\$1.8 billion

Employment (FTE)

Construction (FTE):

526

Operational (FTE):

(calculated using AEC multipier)

Skills Development

Number of courses:

No People Trained:

List of Courses:

WHS Representative Course, Safe Working at Heights, General Safety Induction

Innovation, research and development

Project Innovation (brief summary):

(Innovation is the process of introducing new or significantly improved goods or services and/or implementing new or significantly improved processes.)

This project has put in place a number of good practice or procedures which have presented opportunities to introduce innovative services, products or processes.

Project Research and Development expenditure (brief summary)

Research and Development systematic, investigative and experimental activity that involves innovation or high technical risk acquiring new knowledge or creating new or improved products, devices, processes or services.)





Business Engagement: Attachment D

Winning Supplier	Location (postcode)	Description	\$ Value	Source of
A1 Waterproofing	4165	642.TP0832.01 - MHB - In ground Water	s.47(3)(b)	С
A1 Waterproofing & Applications Pty	4165	643.1.TP0832.01 - FMC - Waterproofing		С
Able Security Group	4575	641.TP1510.01 - CP2 - Door Hardware St		С
ALS	4575	641.TP1712.01 - CP2 - Rainwater Tanks		С
Amalgamated Painting	4214	640.TP3030.01 CP2 - Painting		L
ASP Piling Pty Ltd	4214	643.1.TP0330.01 - FMC - Sheet Piling		С
Beavis & Bartels Pty Ltd	4060	MHB - Temporary Hydraulics		C
Boral Construction Materials (QLD)	4059	644.2.TP0410.01 - CP2 - Concrete Supply	$1/\Omega/\Lambda$	- i
Bosform Pty Ltd	4207	643.1.TP0530.01 - FMC - Formwork	(∨/) /	L
Coastcrete	4215	642.TP.0431.01 - MHB - Precast		L
Custom Shades Pty Ltd	4173	641.TP1633.00 - CP2 - Shade Structure		
	2000		(\land)	C
Delco Steel Qld Pty Ltd		642.TP0620.01 - MHB - Reo Fix		
Delco Steel Qld Pty Ltd	2000	644.2.TP0620.01 - CP2 - Reinforgement		<u>C</u>
Delco Steel Qld Pty Ltd	2000	543.1.TP0620.01 - FMC - Reinforcement		С
Designa Sabar	5009	641.TP2430.01 - CP2 - Car Park manager	/	С
East Coast Concrete Contractors	2485	644.2.TP0420.01 - CP2 - Concrete Flage		С
Eastcoast Concrete Contractors	2485	642.TP0420.02 - MHB - Concrete Place		C
Eastcoast Concrete Contractors	2485	642.TP.0420.01 - MHB - Substructure, inc		С
FIP Electrical (Qld) Pty Ltd	4144	644.2.TP2330,01 - CP2 - Electrical Install		С
Fredon Electrical	4119	641.TP2530.01 CP2-IST		С
Gordon Clements Nominees Pty Ltd	4556	641.TP1330.01 - CP2 - Carpentry		L
Heinrich	4207	642.TP0530.01 - MNB - Formwork		L
Holcim	4701	642.TP0410.01 - MI/B Concrete Supply		L
Manly Concrete	4173	643.1.TP0420.01 FMC - Concrete Placir		
Matchett	4559	642.TP0830.01 - MHB - Blockwork		<u>_</u>
Matchit Blocklaying	4559	644.2. P0830.01 & 644.1. TP0830.01 - B		L
Oneform	4173	544.2 P0530.01 CP2 - Install Formwor		
				L
Onesteel	4108	643.1.7P0410.01 - FMC - Reo Supply		<u>c</u>
Onesteel	4108	642 TP0610.01 - MHB - Reo Supply	s.47(3)(b)	С
OTIS Elevator Company Pty Ltd		642.TP.2030.01 - MHB - Vertical Transpo	- (-)(-)	
OTiS Elevator Company Pty Ltd	4101	643.1.TP2030.01 - FMC - Vertical Transp		L
OTIS Elevator Company Pty Ltd	4101	643.2.TP2030.01 - MHU - Vertical Trans		L
OTIS Elevator Company Pty Ltd	4101	644.1.TP2030.01 - CP1 - Vertical Transpo		L
Penfolds	4553	649.TP3131.01 - CP2 - Landscaping		L
Pickwick Group Pty Ltd	4101	PR0057.03 - CP2 - General Clean		L
Polyseal Waterproofing QLD Pty Ltd	4207	644.2.TP0832.01 - CP2 - Waterproofing		С
Premier Signs	4108	640.TP1532.01 - CP2 - Signage		L
Pro Concrete Pumping	4220	644.2.TP0422.01 - CP2 -Concrete Pumpir		L
Pro Concrete Pumping	42/20	642.TP0422.01 - MHB - Concrete Pumpir		L
Regson Fabrications	4556	641.TP1230.01 - CP2 - Façade		C
Regson Fabrications	4556	640.TP1230.01 - CP2 - General Metalwo		C
Shadforth Civil Engineering	4556	641.TP.0230.01 - RIE - Bulik Earthworks		L
Shamrock Civil	4076	641.TP.0230.02 - RIE - Preload		191
				
Siemens Statement Statemen	3153	641.TP2430.01 - CP2 - Security		
Structural Systems (Northern) Pty Ltd	4207	644.2.TP0631.01 - CP2 - Post Tensioning		<u>C</u>
Sunshine Coast Air Conditioning Serv	4556	644.1.TP1830.01 - CP2 - Mechanical		L
Tacoma Plumbing and Drainage	4573	644.2.TP1732.01 - CP2 - Hydraulics		C
Unispan Australia Pty Ltd	4207	644.2.TP0060.01 - CP2 - Scaffolding		L
Wagstaff Piling Qld Pty Ltd	4060	641.TP0330.02 - CP1 - Piling		L
Wagstaff Piling Qld Pty Ltd	4060	643.1.TP0330.02 - FMC - Precast Piling		L
Admiral Concreting Pty Ltd	4034	641.2.TP0420.01 - CP1 - Concrete Place		L.
OTIS Elevator Company Pty Ltd	4000	644.1.TP2030.01 - CP2 - Vertical Transpo		Ĺ
Structura! Systems	4207	642.TP.0631.01 - MHB - Post Tensioning		L
Australian Post Tensioning	4504	641.2.TP0631.01 - CP1 - Post Tensioning		С
Heinrich Constuctions	4207	641.2.TP0530.01- CP1 - Formwork		L
A1 Waterproofing	4165	642.TP.1330.01 - Temporary Waterproo		c
Cummins South Pacific Pty Ltd	3171	7.TP2330.03 - Generators		ort #19 Scuh May
		Document 116		





Hoslab Pty Ltd	2111	7TP2232.01 - Medical Gases	s.47(3)(b)	L
Johnson Controls	4030	7.TP1810.04 - Chillers		С
Lamson Concepts Pty Ltd	2214	7.TP. 1830.05 - Pneumatic tube		C
Pritchard Pacific Pty Ltd	4119	7.TP1810.02 - Cooling Towers		С
Queensland Glass	4173	642.TP.1131.01 - Façade Windows & FH		С
Superior Walls & Ceilings	4211	642.TP.1032.01 - Façade Framing s.47(3)(b		L
Tyco Australia Pty Ltd	2118	7.TP2130.01 - Fire Protection Services		L
Waco Kwikform Limited	4558	642.TP.0060.01 - Scaffolding		L
National Fire Solutions (QLD)	4009	640.TP2131.01 - CP2 - Wet & Dry Fire		L
Siemens	3153	640.TP1930.01 - CP2 - BMCS		Ĺ





Sunshine Coast University Hospital: Local Industry Participation

Progress Report #21 for period to 31 July 2014 Prepared by Industry Capability Network (Queensland) Ltd

This report details the assistance provided during the above period by ICN (Qld) to Lend Lease in the delivery and implementation of the Local Industry Participation Plan (LIPP) for the Sunshine Coast University Hospital in accordance with the Local Industry Policy (LIP).

1. Liaison with the Project on LIP Issues

ICN met with Queensland Health (Sam Betros) in May 2011 to discuss the project, ICN services, and LIP procedures and issues. ICN assisted QH in the development of the LIPP for the project and provided an evaluation report to QH on project bidders' LIP plan submissions in March 2012.

ICN met with Lend Lease construction management manager on 30th April to review the status of contestable items for the project. ICN had completed all processing for advertised contestable work packages by end of January. Lend Lease advised requested that registration for all opportunities be closed in May and that decisions were pending on other FF&E procurement. Once the procurement approach was confirmed any available work opportunities would be listed on the ICN Gateway and advice published on that site

2. Liaison with Lend Lease on LIP Compliance

Lend Lease met with ICN to establish processes and procedures for management of the project's obligations to the LIP. It was decided that ICN will provide support on number of services covering:

- Implementation of the LIPP (capability searches on contestable packages)
- Presenting at briefing sessions
- Registering companies via ICN Gateway
- Verification of source of manufacture and service provision in subcontracts
- Business matching
- Progress reporting (Monthly) and final LIPP Outcomes reporting (at end of project)

3. Tier Barometer

Tier Barometer is an on-line self-assessment tool developed by ICN and the State Government. It provides participating companies with an assessment of their tier level in terms of supply to major projects. The tool is used by the project to analyse the basic capabilities of potential suppliers during the registration process.

4. Contestable Packages

Contestable items or packages are those that could potentially be sourced locally or overseas but do not include designated items such as concrete supply, earthworks, etc., which it is assumed will always be supplied from sources local to the project. Nor do they include items that have no chance of being manufactured in Australia, eg turbines. LL supplied ICN with the full schedule of subcontract trade packages for the project. ICN subsequently allocated these into contestable and non-contestable packages.

5. Work Packages

Queensland and Australian capability, content and capacity will be considered for all the work packages. The following activities have been undertaken:





- An ICN officer has been assigned full time to the project.
- Detailed Business Matching has been carried out by ICN. 261 work packages have been managed in this way.
- 1489 registrations against work packages on Gateway have been received
- 65 early works have been awarded in March. These are listed at Attachment A.
- 70 work packages have been awarded so far and they are listed at Attachment D.

Potential subcontractors will be given an indication of the size and generic nature of the project, and questioned regarding their capability and capacity to carry out the work, code compliance, and previous work history. Reports will be sent to Lend Lease detailing local companies which have the capability and capacity to carry out the work for each of the above packages. The primary objective of the Local Industry Policy is to ensure that competitive local companies are given full, fair and reasonable opportunity to tender for work packages. This objective will be achieved if the companies nominated by ICN, and other local companies that Lend Lease is aware of, are considered in the establishment of the tender list, and, subject to meeting pre-qualification criteria, a reasonable number of local companies are subsequently invited to tender. Lend Lease intends to apply this requirement.


6. Source of Supply



Lend Lease has advised that out of 135 Purchase Orders, 65 were awarded for early works, 70 for Work Packages during construction. Most of the work packages were awarded to companies that registered interest via ICN. As far as practicable, the measurement of industry participation focuses on the actual source of supply rather than the location through which the order is placed. The location in which services are provided, materials manufactured or where value adding takes place is indicative of the actual source of supply. Of the 70 Work Package contracts that have been awarded, 55 were won by South East Queensland (SEQ) companies, one by Regional Queensland, 14 by other States.

As subcontracts are awarded, the source of manufacture or service provision for contestable packages will be validated and verified in discussion with the corresponding subcontractors. The aggregate value to Queensland and Australian industry will be reported for all packages, and for contestable packages alone. The aggregate value to Queensland and Australian industry of packages awarded so far has been estimated across all trade packages (including both contestable and non-contestable packages) and is currently:


Value of contracts awarded (to date): \$ 232.398 M
Value of components made in other states & NZ in contracts awarded (to date): \$ 221.267 M
Value of components made in other states & NZ in contracts awarded (to date): \$ 2.11 M
Value of components made overseas in contracts awarded (to date): \$ 9.01 M



These figures are shown graphically in the diagram on the left (top) in terms of the percentage by value of all contracts awarded (contestable and non-contestable), with the Queensland content in the project broken down into Local, South East Queensland, Regional Queensland, Other States and New Zealand, and Overseas figures. The total Queensland content is currently 95.21%.







However, the Local Industry Policy is concerned mainly with contestable contracts as "Local" components are assumed to always be available from sources that are geographically close to the project location. The figures for contestable contracts only are shown in the diagram on the left (bottom), and these figures are included in reports back to the Department of State Development, Infrastructure and Planning (DSDIP). The Queensland content for contestable contracts is currently 52.62%.

A total of 70 contracts (including 29 contestable contracts) have been awarded where the source of manufacture or service provision is predominantly within Queensland. No contract was awarded directly to regional companies, as the project was predominantly pased in South East Queensland.

7. Prototype Building

A prototype showcase building was erected in record time. This enabled focus group to provide input in to the final design in a cost effective manner.

8. Local Industry Participation

Lend Lease Project Director has personally provided project work scope and Lend Lease supplier engagement approach information to a number of larger Australian Manufacturers who have asked for more information. These include The GWA Group; The Laminex Group; Spence Doors and Pockcote Industries. For the latter company time was dedicated to a site inspection of their manufacturing facilities.

9. Information Sessions

ICN supported Lend Lease in delivering briefing sessions as proposed in their LIP plan covering:

Monday 3rd September 2012 - Civil, Infrastructure, Structure & Landscaping

Monday 17th September 2012 Services

Monday 24th September 2012 - Roof & Façade

Monday 8th October 2012 – Fit out & Finishes

Monday 15th October 2012 - Furniture Fittings & Equipment (FF&E)

Lend Lease also presented at the General Briefing Sessions along with ICN on 13, 14, 16 and 20th of August 2012.

Lend Lease project managers attended a briefing presentation by the members of the Cleantech Industries group of companies on 24th September 2012.

Lend Lease took part in a Local Business expo on 10th May 2013.

ICN - Evan Flower - presented to the Gympie Major Project Opportunities Forum on the project on 18th June 2013.

10. Efforts to engage with Local Companies include:

Press release by Health Minister, radio interviews by Project Director, Newspaper articles in CM and Sunshine Coast Daily followed up by substantial advertisements in the same newspapers on 19th January. Support articles followed from SSC Council and local councillors.






As a result of the above information sessions and the advertising campaign almost 1000 registrations have been received with close to 100 companies listing after the newspaper advertisements.

To date over 1489 companies have registered interest in work packages.

11. Source of Manufacture

As subcontracts begin to be awarded, the source of manufacture or service provision for contestable packages will be validated and verified in discussion with the corresponding subcontractors.







Attachment A						
			[, , , , , , , , , , , , , , , , , , ,		
Business Engagement		LIPP Categorisation	Source of Supply			
Subcontractor	Receon	REQ - Regional QLD AUS - Rest of Australia IMP - imported	L - Local	PostCode	Values of Goods or Services supplied	
Amalgamated Pest Control	Redback Pest Control to SCUH Site Office	SEQ	L	4561	s.47(3)(b)	
Arjohuntleigh	Medical Beds and Patient Lifting System	IMP	С	6163		
Arunta Plastics (QLD) Pty Ltd	Cultural Heritage Induction	SEQ		3134		
ATF Services Pty Ltd	Temp Fencing	SEQ	L	4558		
ATF Sunshine Coast and Total Site Set Up	Supply & Install crowd control barriers	SEQ	С	4000		
Beavis & Bartels Pty Ltd	Temp Hydraulics (Site Wide) Supply and Install of office furniture for Pr	SEQ	C	4013		
Bizfum Express Blue Glue Pty Ltd	Blue Glue	SEQ AUS	С	4561 2113		
Builtsmart Modular Mining Pty Ltd	Modular Prototype Suite	AUS	<i>k</i>	2250		
Catly Constructions	Prototype Building Foundations	SEQ	- (LO)	4556		
Calty Constructions	Protoype Marketing Rigging and Marketing			4556		
Coates Hire Operations Pty Ltd	Portable toilets	SEQ		4131		
Coates Hire Operations Pty Ltd	General Hire Equipment	SEQ		4131		
Combined Security Services	Security Guards	SEQ		4575		
D&J Services	Site Shed Cleaning	SEQ	(_ /[) / _	4011		
DLA Piper	Professional fees	AUS	\rangle \rangl	4000		
Dunckers Pty Ltd	Supply of Site Accommodation Cleaning Pro		\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	4560		
Energex Limited	Energex Detailed Design Temporary Electrics supply South	SEQ SEQ	<u> </u>	4558 400e		
Energex Limited Energy Crane Services Pty	Temporary Electrics supply South Transport Items to SCUH site	SEQ (1) / :	4006		
Evolution Traffic Control	Provide traffic Controller	SEQ	 	4558		
VS Group Australia Pty Ltd	Site Security	SEQ /		4350		
·	Site Perimeter Security Fence - Stage 1	(650/	c	4556		
	Installation of vinyl and carpet to the Proto		С	4008		
redon QLD Pty Limited	SCUH - Nambour Site	SEQ	С	4119		
3 James	Supply and install of windows and external	SEQ	L	4556		
Bordon Clements Nominees Pty Ltd T/A Catty Constru		SEQ	L	4556		
	Size 8 Bin	SEQ	L	4074		
· ·	Supply of kitchen fridge and microvave	SEQ SEQ	C	4575		
	Prototype Curtain & IV Tracks Supply of Bulk Potable and Non-Potable V	SEQ SEQ	С	4163 4567		
Kyana Projects Pty Ltd Kyana Pty Ltd	Temporary Hydraulics	SEQ	С	4567		
	Video conversions from AVI to MAV+ Yea		c	4014		
	Video Conversions from AVI to MANV +	AUS	c	2010	s.47(3)(b)	
	Prototype Nurse Call & PES	AUS	Č	4113	3.47 (3)(b)	
Vetro Express	2 Containers sent from GCUH to CCUH	SEQ	L	4106		
	Supply and install of examination couch	SEQ	C	4570		
**	83" Multi Touch Interactive Whiteboard	SEQ	С	4006		
	Supply of Potable Water to Site until Feb	SEQ	С	4127		
vilsen QLD Pty Ltd	Temporary Electrical SP2 & Prototype	SEQ	C	4170		
	Ervironmental and Sediment Monitoring	SEQ	L .	4573		
	Supply & Hire of Perimeter Fencing Re skin to existing Billboard	SEQ SEQ	C	2760		
•	Signage	SEQ	C	4575 4575		
	Hard Hat Stickers	· SEQ	c	4575		
	Suppy & Install 2 Gate Closures	SEQ	c	4556		
	AGV Advisory Services	AUS	Č	2127		
	Palmtreg re-location	SEQ	L	4211		
	Crossover road Construction	SEQ	L	4556		
	Supply & replace Road Base - Site Accom		L	4556		
	2P2 Early Works	SEQ	L	4556		
	Prototype Security	IMP	C	4006		
	Supply doors and frame	SEQ	L :	4556		
	Photograph Palm removal & monthly image Re-Fill 2 x 10000L Water Tanks + 1 Addition		L L	4215 4551		
	Car Park First Aid Shed & First Aid	SEQ SEQ	i i	4551 4556		
he trustee for The SJ & DY Eade Family Trust T/A V		SEQ	C	4570		
	Site Sewerage Tank Pump Out	SEQ	C	4064		
	3x3 Combination light set & Trumpf Serv	IMP	č	2067		
	Detect inground services prior to digging f	SEQ	С	4553		
	Mobile Crane Hire	SEQ	L	4556		
	Supply and deliver of Mirrors for Prototype	SEQ	С	4173		
	Site Probing Works - 55 Probe Locations	SEQ	L	4060		
		SEQ	<u>.</u>	4060		
	Test Piling Masterpian Poster	SEQ	L	4000 4000		





Attachment B						
Business Engagement		LIPP Categoriest	Source of Supp	lv		
Special scior	WorkPackage .	SEG - South East OFD		PostCode	Values of Goods	Suppliers
	overn account	RBQ - Regional QLD AUS - Rest of Australia	L-Locel	·		location
A1 Waterproofing	642.TP0832.01 - MHB - In ground Waterproofing	SEQ	С	4165	s.47(3)(1	Brighana East
	643.1.TP0832.01 - FMC - Waterproofing	SEQ	c	4165		Brisbane - East
Able Security Group	641.TP1510.01 - CP2 - Door Hardware Supply	SEQ	Č	4575		Sunshine Coast
	641.TP1712.01 - CP2 - Rainwater Tanks					
ALS		SEQ	Ç	4575		Sunshine Coast
Amalgamated Painting	640.TP3030.01 CP2 - Painting	SEQ	L	4214		Gold Coast
ASP Piling Pty Ltd	643.1.TP0330.01 - FMC - Sheet Piling	SEQ	С	4214		Gold Coast
Beavis & Bartels Pty Ltd	MHB - Temporary Hydraulics	SEQ	С	4060		SEQId
Boral Construction Materials (QLD)	644.2.TP0410.01 - CP2 - Concrete Supply	SEQ	L	4059		Brisbane Inner C
Bosform Pty Ltd	643.1.TP0530.01 - FMC - Formwork	SEQ	L	9207	,	Gold Coast
Coastcrete	642.TP.0431.01 - MHB - Precast	SEQ	L	4245		Gold Coast
Custom Shades Pty Ltd	641.TP1633.00 - CP2 - Shade Structure	SEQ	L	i 4(173//	K)	Brisbane - East
Delco Steel Qld Pty Ltd	642.TP0620.01 - MHB - Reo Fix	Other Sizes	С	2000	/ /	NSW
Delco Steel Qld Pty Ltd	644.2.TP0620.01 - CP2 - Reinforcement Fix	Other States	C	2000	\mathcal{V}	NSW
Delco Steel Qld Pty Ltd	643.1.TP0620.01 - FMC - Reinforcement Fixing	Omer Stame	C/	2900		NSW
Designa Sabar	641.TP2430.01 - CP2 - Car Park management systi	Cuner Stutes	9 ()	5009		SA
East Coast Concrete Contractors	644.2.TP0420.01 - CP2 - Concrete Place and Finish	Other States	c	2A85		NSW
astcoast Concrete Contractors	642.TP0420.02 - MHB - Concrete Place	Other Status	~~~	2485		NSW
astcoast Concrete Contractors	642.TP.0420.01 - MHB - Substructure, incl Pile trim	The same of the sa	C	2485		NSW
P Electrical (Qld) Ptv Ltd	644.2.TP2330.01 - CP2 - Electrical Installation	SEQ	C _C	4144		Brisbane Inner C
redon Electrical	641.TP2530.01 - CP2 - ICT	SEQ	5/3/	4119		Logan - Beaudes
Gordon Clements Nominees Pty Ltd T/A		SEQ	\checkmark / \checkmark \rightarrow \vdash	4556		Sunshine Coast
	642.TP0530.01 - CP2 - Carpentry	SEQ	\leftarrow		H	Sunsnine Coast
				4207		
Holcim	642.TP0410.01 - MHB - Concrete Supply	RFQ	/ <u>/</u>	4701		REG QId
Manly Concrete	643.1.TP0420.01 - FMC - Concrete Placing	sEQ\/	<u> </u>	4173		Brisbane - East
Matchett	642.TP0830.01 - MHB - Blockwork	SEQ	<i>J</i>	4559		Sunshine Coast
Matchit Blocklaying	644.2.TP0830.01 & 644.1.TP0830.01 - Blockwork C	3€Q	L	4559		Sunshine Coast
Oneform	644.2.TP0530.01 - CP2 - Install Formwork	SEQ	L	4173		Brisbane - East
Dnesteel	643.1.TP0410.01 - FMC - Reo Supply	SEQ	С	4108		Brisbane - South
Onesteel	642.TP0610.01 - MHB - Reo Supply	SEQ	С	4108		S E Qld
OTIS Elevator Company Pty Ltd	642.TP.2030.01 - MHB - Vertical Transportation	SEQ.	L	4101		Brisbane Inner C
OTIS Elevator Company Pty Ltd	643.1.TP2030.01 - FMC - Vertical Transportation	SED	L	4101	·	Brisbane Inner C
OTIS Elevator Company Pty Ltd		\sim	_		•	-
	643.2.TP2030.01 - MHU - Vertical Transportation	s∕EQ	L	4101		Brisbane Inner C
OTIS Elevator Company Pty Ltd	644.1.TP2030.01 - CP1 - Vertical Transportation	SEQ	L	4101		Brisbane Inner C
Penfolds	640.TP3131.01 - CP2 - Langiscaping	SEQ	L	4553		Sunshine Coast
Pickwick Group Pty Ltd	PR0057.03 - CP2 - General Stean	SEQ	L	4101		SEQId
Polyseal Waterproofing QLD Pty Ltd	644.2.TP0832.01 - CP2 - Waterpreofing	SEQ	С	4207	s.47(3)(b)	Gold Coast
Premier Signs	1640.TP1532.01 - CP2 - Signage	SEQ	L	4108	` / ` /	Brisbane - South
Pro Concrete Pumping	644.2.TP0422.01 / SP2 -Concrete Pumping	SEQ	L	4220		Gold Coast
Pro Concrete Pumping	642.TP0422.01 - MHB - Concrete Pumping	SEQ	Ĺ	4220		S E Qld
Regson Fabrications	641.TP1230.01 - EP2 Façade	SEQ	c	4556		Sunshine Coast
Regson Fabrications	540.TP1230.01 - CP2 - General Metalwork		C			Sunshine Coast
		SEQ	- C	4556	ļ	
Shadforth Civil Engineering	641.TP.0230.01 RIE - Bullk Earthworks and FIII	SEQ	L	4556		Sunshine Coast
Shamrock Civil	641.TF.0230-02 - RIE - Preload	SEQ	L	4076		lpswich
Slemens	641.1R2430.01 - SP2 - Security	Other States	L	3153		VIC
Structural Systems (Northern) Pty Ltd	644-2 TP0631.01 - CP2- Post Tensioning	SEQ	С	4207		Gold Coast
Sunshine Coast Air Conditioning Service	· · · · · · · · · · · · · · · · · · ·	SEQ	L	4556		Sunshine Coast
acoma Plumbing and Drainage	#44.2.TP1732.01 - CP2 - Hydraulics	SEQ	c	4573		Sunshine Coast
	644.Z.TP0060.01 - CP2 - Scaffolding	SEQ	Ĺ	4207		Gold Coast
	844.TP8330.02 - 6P1 - PIling					
*	-	SEQ.	<u> </u>	4060		Brisbane
Vagstaff Piling Qld Pty Ltd	643.1.TP0330.02 - FMC - Precast Piling	SEQ	L	4060		Brisbane Inner C
dmiral Concreting Pty Ltd	641.2 TP0420.01 - CP1 - Concrete Place and Finish		L	4034		S E Cld
OTIS Elevator Company Pty Ltd	644.1.?P2030.01 - CP2 - Vertical Transportation	SEQ	L	4000	H	SEQId
Structural Systems	642.TP.0631.01 - MHB - Post Tensioning	SEQ	L	4207		SEQId
ustralian Post Tensioning	641.2.TP0631.01 - CP1 - Post Tensioning	SEQ	С	4504		SE Qid
leinrich Constuctions	641.2.TP0530.01- CP1 - Formwork	SEQ	L	4207		SE QId
1 Waterproofing	642.TP.1330.01 - Temporary Waterproofing	SEQ	С	4165		SE QId
ummins South Pacific Pty Ltd	7.TP2330.03 - Generators	Other States	C	3171		ViC
oslab Pty Ltd	7TP2232.01 - Medical Gases	Other States	L	2111		NSW
phasen Controls	7.TP1810.04 - Chillers	SEQ	С	4030	1	SE Qld
	7.TP.1830.05 - Pneumatic tube	Other States	C	2214		NSW
	7.TP1810.02 - Cooling Towers	SEQ	C	4119		SE Qld
Nucensland Glass	642.TP.1131.01 - Façade Windows & FHG	SEQ	C	4173		SE QId
		SEQ		41/3		
	642.TP.1032.01 - Façade Framing		<u>L</u>		1	SE QId
	7.TP2130.01 - Fire Protection Services	Other States	<u>L</u>	2118		NSW
/aco Kwikform Limited	642.TP.0060.01 - Scaffolding	SEQ	L	4558	H	SE QId
lational Fire Solutions (QLD)	640.TP2131.01 - CP2 - Wet & Dry Fire	SEQ	Ĺ	4009		SE QId
emens	640.TP1930.01 - CP2 - BMCS	Other States	L	3153		VIC
pex Modular Wiring	6.TP2330.061 - MFiB - Modular Electric Wiring	Other States	L	3108	N	Vic
Ini-Span	2.TP0060.01 - CP1 - Scaffolding	SEQ	L	4207		SE QId
		1311 526				





ATTACHMENT C: Local Industry Participation Plan Outcomes Report

Progress Report to 31-07-2014

Project:

Sunshine Coast University Hospital

Project Proponent:

Queensland Health

Contractor:

Lend Lease

Project Location:

Sunshine Coast

Total Project Value:

\$1.8 Billion

Total Value of Contracts:

\$232,398,489,71

of Contracts:

69

Value of Contracts placed

with Old businesses:

\$221.267.633.46

No. of Contracts:

62

Value of work performed by

\$432,750.00

No. of Contracts:

o

regional Qld businesses (included in total Qld figure

above):

Value of work performed with businesses outside Qld

but within Australia/NZ:

\$2.118.217.60

No. of Contracts:

3

5

Value of Work performed by

Overseas Firms:

No. of Contracts:

Tender Evaluation Criteria:

Tender Evaluation Criteria:

These works are subject to the Queensland Government's Local Industry Policy. The successful Contractor is required to provide full, fair and reasonable opportunity to local suppliers and specialist subcontractors when tendering the provision of equipment or services supplied under the scope of works. Contractors are encouraged to use the services of Industry Capability Network (Queensland) ("ICN") to ensure that supply tender invitations meet the requirements of the policy.

Value of Capital Investment:

\$1.8 billion

Employment (FTE)

Construction (FTE):

526

Operational (FTE):

(calculated using AEC multipier)

Skills Development

Number of courses:

No People Trained:

List of Courses:

WHS Representative Course, Safe Working at Heights, General Safety Induction

Innovation, research and development

Project Innovation (brief summary):

(Innovation is the process of introducing new or significantly improved goods or services and/or implementing new or significantly improved processes.)

This project has put in place a number of good practice or procedures which have presented opportunities to introduce innovative services, products or processes.

Project Research and Development expenditure (brief summary)

Research and Development systematic, investigative and experimental activity that involves innovation or high technical risk acquiring new knowledge or creating new or improved products, devices, processes or services.)





Business Engagement: Attachment D

Winning Supplier	(postcode)	Description	\$ Value	Source of Supply	
A1 Waterproofing	4165	542.TP0832.01 - MHB - In ground Wate	g 47(2)(h)	C	
A1 Waterproofing & Applications		643.1.TP0832.01 - FMC - Waterproofin		c	
Able Security Group	4575	641.TP1510.01 - CP2 - Door Hardware		c	
ALS	4575	641.TP1712.01 - CP2 - Rainwater Tank		c	
Amalgamated Painting	4214	640.TP3030.01 CP2 - Painting		Ľ	
ASP Piling Pty Ltd	4214	643.1.TP0330.01 - FMC - Sheet Piling		c	
Beavis & Bartels Pty Ltd	4060	MHB - Temporary Hydraulics		c	
Boral Construction Materials (QLI	4059	644.2.TP0410.01 - CP2 - Concrete Supr			
Bosform Pty Ltd	4207	643.1.TP0530.01 - FMC - Formwork	((7/4	
Coastcrete	4215	642.TP.0431.01 - MHB - Precast	()	(/) /	
Custom Shades Pty Ltd	4173	641.TP1633.00 - CP2 - Shade Structure	\bigcirc	L	
Delco Steel Qld Pty Ltd	2000	642.TP0620.01 - MHB - Reo Fix		С	
Delco Steel Qld Pty Ltd	2000	644.2.TP0620.01 - CP2 - Reinforcemen	$ (\mathcal{O}_{\Delta})$	С	
Delco Steel Qld Pty Ltd	2000	643.1.TP0620.01 - FMC - Reinforcemer		/ c	
Designa Sabar	5009	641.TP2430.01 - CP2 - Car Park manage	$\frown \cup$	С	
East Coast Concrete Contractors	2485	644.2.TP0420.01 - CP2 - Concrete Place	0	С	
Eastcoast Concrete Contractors	2485	642.TP0420.02 - MHB - Concrete Place	>///~	С	
Eastcoast Concrete Contractors	2485	642.TP.0420.01 - MHB - Substructure.	(\cup)	С	
FiP Electrical (Qld) Pty Ltd	4144	644.2.TP2330.01 - CP2 - Electrical Insta		С	
Fredon Electrical	4119	641.TP2530.01 - CP2 - ICT		С	
Gordon Clements Nominees Pty L	4556	641.TP1330.01 - CP2 - Carpentry))	L	
Heinrich	4207	642.TP0530.01 - MHB - Formwork		L	
Holcim	4701	642.TP0410.01 - MHB - Concrete Suppl		L	
Manly Concrete	4173	643.1.TP0420.01 - FMC - Concrete Plac		L	
Matchett	4559	642.TP0830.01 - MH/B -/Block/work		L	
Matchit Blocklaying	4559	644.2.TP0830.01 & 644.1.T7 0830 01 - B		Ļ	
Oneform	4173	644.2.TP0530.81 - CP2 - Install Formwo		L	
Onesteel	4108	643.1.TP 0426.01 - FMC - Reo Supply		С	
Onesteel	4108	642.TP0610.01/- NHB - Reg Supply		С	
OTIS Elevator Company Pty Ltd	4101	642. P. 2030 01 MHB Vertical Transp		L	
OTIS Elevator Company Pty Ltd	4101	643.1.TP2030.01 - FMC - Vertical Trans	s.47(3)(b)	L	
OTIS Elevator Company Pty Ltd	4101	643.2.TP2030.01 - MHU - Vertical Trans		L	
OTIS Elevator Company Pty Ltd	4101	644.1.TP2030.01 - CP1 - Vertical Transi		L	
Penfolds	4558	640. 193131.01 - CP2 - Landscaping		L	
Pickwick Group Pty Ltd	\longrightarrow	PROC57.03 - CP2 - General Clean		L	
Polyseal Waterproofing QLD Pty L		644.2.TP0832.01 - CP2 - Waterproofing		С	
Premier Signs	4198	640.TP1532.01 - CP2 - Signage		L	
Pro Concrete Pumping	4220	644.2 TP0422.01 - CP2 - Concrete Pump			
Pro Concrete Pumping		642 7P0422.01 - MHB - Concrete Pump		L	
Regson Fabrications	4556	541.TP1230.01 - CP2 - Façade		c c	
Regson Fabrications		640.TP1230.01 - CP2 - General Metalw		c	
Shadforth Civil Engineering	4556	641.TP.0230.01 - RIE - Bulik Earthwork		L	
Shamrock Civil	4076	641.TP.0230.02 - RIE - Preioad		L	
Siemens	3153	1			
	\sim	641.TP2430.01 - CP2 - Security		L	
Structural Systems (Northern) Pty		644.2.TP0631.01 - CP2 - Post Tensionir		C .	
Sunshine Coast Air Conditioning S		644.1.TP1830.01 - CP2 - Mechanical		L	
Facoma Plumbing and Drainage	4573	644.2.TP1732.01 - CP2 - Hydraulics		C	
Unispan Australia Pty Ltd	4207	644.2.TP0060.01 - CP2 - Scaffolding		L .	
Wagstaff Piling Qld Pty Ltd	4060	641.TP0330.02 - CP1 - Piling		L	
Wagstaff Piling Qld Pty Ltd		643.1,TP0330.02 - FMC - Precast Piling		L	
Admirai Concreting Pty Ltd		641.2.TP0420.01 - CP1 - Concrete Place		L	
OTIS Elevator Company Pty Ltd		644.1.TP2030.01 - CP2 - Vertical Transi		<u> </u>	
Structural Systems	$\overline{}$	642.TP.0631.01 - MHB - Post Tensionin		L	
Australian Post Tensioning	4504	641.2.TP0631.01 - CP1 - Post Tensionir		С	
Heinrich Constuctions	4207	641.2.TP0530.01- CP1 - Formwork		<u>1</u>	
A1 Waterproofing	4165	642.TP.1330.01 - Temporary Waterpro		С	
Cummins South Pacific Pty Ltd		7.TP2330.03 - Generators		С	
Hoslab Pty Ltd	2111	7TP2232.01 - Medical Gases		L	






Johnson Controls	4030	7.TP1810.04 - Chillers	s.47(3)(b)	С
Lamson Concepts Pty Ltd	2214	7.TP.1830.05 - Pneumatic tube		С
Pritchard Pacific Pty Ltd	4119	7.TP1810.02 - Cooling Towers		С
Queensland Glass	4173	642.TP.1131.01 - Facade Windows & FHG		С
Superior Walls & Cellings	4211	642.TP.1032.01 - Façade Framing		L
Tyco Australia Pty Ltd	2118	7.TP2130.01 - Fire Protection Services		L
Waco Kwikform Limited	4558	642.TP.0060.01 - Scaffolding	s.47(3)(b)	L
National Fire Solutions (QLD)	4009	640.TP2131.01 - CP2 - Wet & Dry Fire		L
Siemens	3153	640.TP1930.01 - CP2 - BMCS		L
Apex Modular Wiring	3108	6.TP2330.061 - MHB - Modular Electric Wiring		L
Uni-Span	4207	2.TP0060.C1 - CP1 - Scaffolding		L
RE Spence & Co P/L	4556	6.TP1311.01-MHB-Timber Door Supply		L



Pages 127 through 141 redacted for the following reasons:

Irrelevant - section 73





This section should be read in conjunction with the following documents:

Local Industry Participation Plan – Aconex reference

rrelevant s 73 irrelevant s 73

irrelevant s 73

irrelevant s 73

4.1. CONSTRUCTION PROGRAMME

Lend Lease will utilise the following programming controls when engaging and managing subcontractors to ensure they have capability and responsibility to meet the program:

- Medium Range Schedule provided by Lend Lease Lend Lease to all subcontractors and suppliers.
- Overall Delivery Schedule provided by Lend Lease to the subcontractor, as updated or amended by Lend Lease.
- Program Information the information provided by the subcontractor and approved by Lend Lease.
- Short Range Schedule provided by Lend Lease, as updated of amended by Lend Lease.
- Subcontractor's Program the program provided by the Subcontractor and approved by Lend Lease, as revised or updated by the Subcontractor or Lend Lease and approved by Lend Lease.

Table 4: Schedule of Programming Controls

Program	Author	Frequency of Issue	Subcontract Document	Comments
Overall Delivery	Lend Lease	As required	Yes	Activities or items of work required for completion of the Works or all interfaces with the work of other subcontractors.
Medium Range	Lend Lease	Every 6 to 8 weeks	Yes	will detail particular activities shown on the Overall Delivery Schedule
Subcontractor's Program	SC	10 days of being notified of award	Yes	Refer below
Short Range	Lend Lease	weekly	Yes	Lend Lease will confer with the Subcontractor prior to issuing a Short Range Schedule. A Short Range Schedule must cover the two week period following the date of the Short Range Schedule and will detail particular activities shown on the Subcontractor's Program and the Program Information.

4.2. SUBCONTRACTORS PROGRAMME

Within 10 days of being notified of the award of the Subcontract, the Subcontractor must submit to Lend Lease for approval either a programme or the information required by Lend Lease which must:

- be consistent with the dates shown on the Overall Delivery Schedule and Medium Range Schedule for commencement and completion of:
- the Works;
- the Stages of the Works (if any);



- the activities and items required for completion of the Works, making due allowance for delays since the issue of the Overall Delivery Schedule;
- show all on and off-Site activities necessary to permit weekly comparisons between the Works as programmed and the actual progress of the Works;
- show the dates or periods for;
- supply of drawings and information from Lend Lease;
- approvals from Authorities and Lend Lease;
- provision of samples, opening up for inspection work covered up and testing of materials or executed work:
- provision and approval of shop drawings and as-constructed drawings allowing for the times required for Lend Lease's review and approval;
- provision of all maintenance and operations manuals including drafts thereof;
- supply of essential materials;
- sequences and labour requirements for commissioning;
- provision and approval of safety procedures;
- provision of quality procedures;
- all other activities which have a significant bearing on the time required for Substantial Completion;
- allow for the activities of other subcontractors on the Site which may affect the Works;
- include labour forecasts for each programmed activity and expected labour productivity rates;
- indicate the critical path of the Works; and
- show further information that Lend Lease may require.

4.3. QUALITY

The subcontractors engaged by Lend Lease will comply with the Project requirements including providing a quality plan.

The subcontractor must provide a copy of the proposed Quality Management System for the Works, including a copy of the independent certification.

The subcontractor must comply with the Quality Management System developed in accordance with the requirements stated in the Subcontract in order to assure Lend Lease that the Works will be in accordance with the requirements of the subcontract. The Quality Management System must contain established processes for managing the completion of the Works that are documented, regularly reviewed, audited and monitored and provide for self improvement supported and endorsed by senior management of the subcontractor.

The subcontractor's Quality Management System and any supporting documentation may be audited by Lend Lease at any time during the course, and after completion, of the Works.

For the avoidance of doubt, the subcontractor must ensure that its Quality Management System is applied to all parts of the Works, including those parts which are provided by designers, subcontractors and suppliers to the subcontractor.

The subcontractors Quality Management System must require that all testing and measuring equipment be regularly checked for accuracy. Records of calibration certificates are to be kept on the Site.



The subcontractor must ensure that planned and documented quality audits are carried out on all aspects of the Quality Management System adopted by the Subcontractor's designers, suppliers and subcontractors.

The Subcontractor will develop, in accordance with the specifications, drawings and subcontract, a specific inspection and test Plan (ITP) for the works to be performed. The ITP must identify all the appropriate hold point and inspections required by all relevant parties including the State, Lend Lease, consultants and authorities.

As part of their requirements to achieve Technical Completion and Commercial Acceptance, the subcontractor will submit their Operations and Maintenance Manuals, As-Built Documentation, certificates, warranties and the like in relation to their Works. This information must be submitted for Lend Lease review, as well as that of the State, as part of the Completion Process.

The subcontractor must not cover up or put out of view work:

- requiring an approval by an Authority; or
- affecting:
 - fire rating;
 - sound attenuation:
 - waterproofing;
 - structural soundness; or
 - any other matters required by Lend Lease or the subcontract, and

without the prior written approval of Lend Lease.

4.4. DESIGN COMPLIANCE

Lend Lease will engage subcontractors to provide either:

- a) labour and materials in accordance with the design;
- b) labour and materials including shop drawings for off-site manufacture; and
- c) labour and materials including shop drawings for off-site manufactures design certification for Lend Lease and Authority approval.
- 1) Design by the Subcontractor.

The Subcontractor must design and specify the Works including developing and finalising any design included in the Subcontract ('design obligations'). The subcontractor must ensure that the design of the Works, when complete, complete in all respects with:

- a) the Client Brief and the Design Brief; and
- b) the Specifications and Drawings.

The subcontractor must carry out the design obligations and submit design information at the times indicated in the Design Program.

2) Lend Lease's requirements, information and co-ordination



- The subcontractor will be required to warrant that any design provided by Lend Lease is suitable, appropriate and adequate for the purpose stated in those documents or, if no purpose is stated, the intended purpose of the Works;
- The subcontractor must take all steps necessary from time to time to clarify and confirm Lend Lease's Design Requirements; and
- c) The subcontractor must co-ordinate the performance of the design obligations and related matters with the performance and designs of other parties engaged by Lend Lease.

3) Professional services

- a) The Subcontractor acknowledges that Lend Lease is in reliance upon the skill, experience and ability of the subcontractor to carry out the design obligations and co-ordinate the Works.
- b) The Subcontractor must carry out the Design Obligations with the degree of professional skill, care and diligence expected of a specialised subcontractor experienced in providing the same or similar services; and
- c) The Subcontractor must effect and maintain in a form acceptable to Lend Lease and appropriate to the subcontractor's activities, professional indemnity insurance in respect of liability arising from a breach of a professional duty or from a negligent act, error or omission by the subcontractor or its personnel in accordance with the Schedule of insurances:

4) Design

- a) The subcontractor warrants that the design obligations if required will:
 - i) be undertaken only by or under the direction and direct control of:
 - (1) a properly qualified architect, engineer or surveyor as appropriate; or
 - (2) a person with not less than 5 years relevant practical experience; and
- so as to comply with the requirements of the subcontract and all relevant legislation, ordinances, regulations and by-laws and the requirements of any authority or governmental body which has jurisdiction affecting the Works or the Site.
- c) When requested by Lend Lease, the subcontractor must provide to Lend Lease all calculations, certificates and other information relating to design carried out by the subcontractor.
- d) Lease may engage a suitably qualified consultant to review the suitability of the design. If the design is found to be faulty or unsuitable, without prejudice to Lend Lease's other rights.
- e) The subcontractor must not commence fabrication or construction of a part of the Works until all relevant 'for construction' documents, including any amendments required by Lend Lease, have been submitted to Lend Lease.
- 5) Supply of Material and Labour in Accordance with Design
 - All design completed by Lend Lease consultants or subcontractors will identify the relevant legislative and manufacturers standards. Proof of accreditation from suppliers necessary to maintain warranties will be submitted by subcontractors prior to selection; and



 Samples of specified products requiring consultant approval will be as specified and included in the Project Inspection and Test Plan.

4.5. PERSONNEL SELECTION AND CONTROL

The Subcontractors will be required to warrant that the Project specific management nominated in the Subcontract to Lend Lease have authority to act on behalf of the Subcontractor in all matters relating to the Works except those matters for which another representative of the Subcontractor is nominated under the Subcontract.

- the Subcontractor must ensure that at all times during the execution of the Works the Subcontractor's supervisor is present on the Site:
- any instructions given to the Subcontractor's supervisor by Lend Lease will be deemed to be given to the Subcontractor; and
- the Subcontractor must not change the supervisor without Lend Lease's written consent.

4.6. WORKPLACE HEALTH AND SAFETY MANAGEMENT

Lend Lease requires that WHS awareness and WHS Impacts and Hazards Risk Assessment are the responsibility of all parties engaged in the delivery of a Project.

Successful WHS Management relies largely on the control of subcontractors and the subcontractor's control of it's personnel and sub-subcontractors. It also recognises that subcontractor management is the clear responsibility of the Site Project Team and, in particular, the Project Manager and Foreman responsible for each trade package.

WHS Management of Subcontractors can be broken up into the following stages:

- tender stage;
- subcontract preparation stage; and
- construction stage.

4.7. PROCUREMENT

4.7.1. SUBCONTRACT PREPARATION

Prior to commendement on-Site all subcontractors will have a reviewed WHS plan in place. The Subcontractor WHS Plan must be reviewed by the appropriate Site Engineer/Foreman in consultation with the subcontractor responsible for the works. The review of the Subcontractor's WHS Plan will be verified using the Works to Proceed Checklist' that is to be completed in full and attached to the front sheet of subcontractor's WHS Plan. The Lend Lease General Foreman and Construction Manager will undertake a final review and sign of the 'Works to Proceed Checklist' prior to the subcontractor commencing on-Site.

Specific requirements to be addressed in the Subcontractor's WHS Plan include, but are not limited to:

- the sequence of WHS Management activities to be carried out;
- the way in which the identified risks will be reduced to an acceptable level (Class 3 outcome);
- the management system used to monitor compliance with the agreed safe system of work;
- the way in which the progress of the work will be reviewed for the purposes of WHS protection that any
 necessary modifications and improvements to the system of work can be identified and introduced;



- inspection and Test Plans which relate to the work and the Safe Work Method Statements (SWMS)
 and the plant and equipment to be used; and
- the specific management sections relating to:
 - handling, storage and use of dangerous goods/hazardous substances;
 - manual handling;
 - Plant and Equipment; and
 - Environment Management.

All Subcontractor Safe Work Method Statements (SWMS) will be reviewed by the appropriate Foreman in consultation with the subcontractor responsible for the works. The review of the Subcontractor's SWMS will be verified using the Lend Lease 'SWMS Checklist'.

Specific requirements to be met in the Subcontractors' SWMS include, but are not limited to:

- a task-related identification and assessment of the risk activities in relation to the Site and any person likely to be affected by them;
- sequence and description of the work, including WHS measures to be undertaken to control the hazards. This should include a description of the Plant and Equipment used and relevant Codes of Practice and/or Australian Standards;
- qualifications, skills and training of persons undertaking and supervising the work; and
- management sign off of the SWMS.

The Lend Lease General Foreman or their delegate will then also undertake a final review of the subcontractor's SWMS to check all issues have been considered and sign off the 'SWMS Checklist'. The final review will also ensure the required permits and tags are distributed, implemented and fully understood by the subcontractor responsible. The SWMS will then be added to the SWMS Register. When materials are supplied to the Project the Project Team member responsible for the procurement will ensure all WHS information has been included and is distributed to the persons identified as needing to understand the requirements.

4.7.2. CONSTRUCTION

After a Subcontractor has commenced on-Site the Construction Manager/General Foreman/Foreman/Engineer responsible for the works administers the following disciplines:

- any new works or changes to existing methods are to be addressed by a new risk assessment and SWMS. A documented review of the subcontractor's current SWMS, Risk Assessments and WHS Plans are to be carried out no longer than at monthly intervals by the subcontractor's person responsible for WHS. All new revisions of SWMS will be reviewed by PMC using the SWMS Checklist;
- prior to work being undertaken on-Site, all aspects of the day's activities are to be discussed in a 'Pre-Start Briefing' openly amongst the people directly involved with the work. This will include production, WHS as well as an update on any Site changes and logistics;
- submissions of Subcontractor WHS Monthly Report (with Progress Claims) including those of their subcontractors;
- documented subcontractor inspections of plant, equipment and works to the SWMS on a daily basis;
- monitoring any new plant and equipment coming onto Site and any documentation required to ensure it is used safely; and
- non-conformances (e.g. actual or potential incidents) are issued to the subcontractor using the Defect and Incident module on Aconex, facilitating a documented and auditable trail of all actions undertaken.



The first subcontractor audit is to take place within six weeks prior to a subcontractor starting on-Site and every six months after. These audits are conducted against criteria covering Environment, Health and Safety, and Quality.





Pages 149 through 174 redacted for the following reasons:

Irrelevant - section 73

