Exemplar Health c/- Capella Capital AMP Centre, Level 31, 50 Bridge Street Sydney NSW 2000 Australia Ph+61 2 82243888

MAIL TYPE MAIL NUMBER REFERENCE NUMBER EXH-NOTICE-000040 EXH-NOTICE-000040 Notice Notification of the Occurrence of an Event - Insurance Policy From Bianca Jones - Exemplar Health SCUH Project Director - Queensland Health - Capital Delivery Program □ To (2) Roseanne Jennings - Queensland Health - Capital Delivery Program Сс Mr Pat Coleman - Exemplar Health Sent Monday, 19 October 2015 5:32:44 PM EST (GMT +10:00) N/A Status File Attachments (1) File Name 🎇 SCUH - EH Letter to the State Clause 49.pdf **Attributes** Attribute 1 Administration Attribute 2 Project Wide Message Roseanne Please find attached a Notice from the Project to Representative, thank you. Regards, Bianca Jones | Development Co-ordinator Sunshine Coast University Hospital Site Office Gate 7 South Street, Birtinya QLD 4575 Australia This This Part Out of Scope of Application lica Out of Scope of A



19 October 2015

Ms Roseanne Jennings Executive Project Director Sunshine Coast University Hospital Project K1 Building, Ground Floor, 16 Innovation Parkway Birtinya QLD 4575 Sent via Aconex: Notice

Dear Roseanne

SUBJECT: SUNSHINE COAST UNIVERSITY HOSPITAL PROJECT: NOTIFICATION OF OCCURRENCE OF AN EVENT – INSURANCE POLICY

In accordance with Clause 49.7(c), Project Co hereby notifies the State of the occurrence of an event which would or might entitle Project Co to make a slaim under the Insurance Policy.

Details of the event are as follows:

Date: 16 October 2015

Description: A storage tank carrying approximately 2.7 mega litres of water ruptured adjacent to Kawana Way. As a result, water and debris spilled across the Kawana Way and associated damage to the Works.

Project Co is taking all necessary steps to ensure that its rights, and the rights of any other persons to whom the benefit of the insurance Policy may extend in respect of this claim, are fully preserved.

Should you have any queries or questions in relation to this matter please do not hesitate to contact me on during some of A

Yours sincerely

Pat Coleman Exemplar Health Project Co Representative



MAIL TYPE
General Communication

MAIL NUMBER QHP-GCOM-005927 REFERENCE NUMBER QHP-GCOM-005927

SCPUH TES - Tank failure

From Mr Don Glynn - Queensland Health - Capital Delivery Program То Ms Elizabeth Coe - Umow Lai & Associates Thins Part Out of Scope of Application App □ Cc (9) Roseanne Jennings - Queensland Health - Capital Delivery Program Mr Andrew Leggate - Queensland Health - Capital Delivery Program Mr Cyriac Mukkada - Queensland Health - Capital Delivery Program Chris Anderson - Umow Lai & Associates Mr Andrew Jenkinson - Umow Lai & Associates Mr Brian McDonnell - Umow Lai & Associates Mr Martin O'Connor - Wood & Grieve Engineers TITHis Part Out of Scope of Application? Monday, 19 October 2015 11:24:37 AM EST (SMT +10:00) Sent Submit comments by 23/10/2015 Status Responded File Attachments (1) File Name 📊 From CP1.JPG **Attributes** Attribute 1 Mechanical Facility Management Centre Attribute 2 Message Elizabeth,

No doubt you would have heard by now that one of the TES tanks failed completely at 4pm on Friday after having been filled that day. The second tank suffered structural damage and is likely to be removed as well. The FMC suffered some external and internal damage and CP1 has some minor external damage as does the surrounding area. The full extent of the damage will not be determined for some time but we will keep our Advisors informed whenever we receive updates.

I have attached a picture for your information only and so that you can appreciate the extent of damage. It must not be distributed or used in any way other than for the intended purpose of this correspondence.

What we need to do now is start assessing the immediate and or long term impacts to program, commissioning strategies (ie temporary cooling to ICT rooms), design options (ie less TES, different tank design etc) and recurrent costs (ie no TES on Day 1). Can I ask that your team start to think about these things as we will be presented with options by EH to assess and we want to be ready with our own assessment and views on what options should be considered both immediately, in the interim and of course long term.

Regards,

Don


Don Glynn


Engineering and Technical Director **Sunshine Coast University Hospital Project**

Health Infrastructure Branch | System Support Services | Queensland Health


Ground Floor - K1 | 16 Innovation Parkway | BIRTINYA QLD 4575 This Pantout of Scope of Application

t Out of Scope of Ap





It will be interesting to see how much access of score get to the exclusion zones. We were kept out of the FMC albeit LL reported minimal damage to internal spaces.



Talk soon, RJ

Sent from my BlackBerry 10 smartphone on the Telstra NextG network.

This Part Out of Scope of Applicat
This Part Out of Scope of Application

To: Roseanne Jennings; Tom Kirkland

This Part Out of Scope of Application


This Part Out of Scope of Application


Hi Roseanne and Tom,

Attached is a preliminary advice regarding the tank rupture incident and the notice received from EH earlier today.

I will give you a call tomorrow to discuss.

Regards,






This Part Out of Scope of Application

This Part Out of Scope of Application



Pages 9 through 14 redacted for the following reasons:

This Part Out of Scope of Application



DOH-DL 15/16-031



MAIL TYPE MAIL NUMBER REFERENCE NUMBER
General Communication ULA-GCOM-000701 ULA-GCOM-000701

RE: Failed Chilled Water Tank Comments

From Mr Brian McDonnell - Umow Lai & Associates

To Roseanne Jennings - Queensland Health - Capital Delivery Program

Cc (4) Mr Don Glynn - Queensland Health - Capital Delivery Program

Chris Anderson - Umow Lai & Associates

Ms Elizabeth Coe - Umow Lai & Associates

Mr Andrew Jenkinson - Umow Lai & Associates

Sent Wednesday, 21 October 2015 9:30:47 AM EST (GMT +10:00)

Status N/A

Attributes

Attribute 1 HVAC Equipment

Attribute 2 Facility Management Centre

Message

Roseanne,

Please find below some initial, bullet point, comments on the chilled water tank jailure.

Effect on Hospital Operation

This Part Out of Scope of Application

This Part Out of Scope of Application

Information required from Exemplar;

This Part Out of Scope of Application

This Part Out of Scope of Application

This Part Out of Scope of Application
This Part Out of Scope of Application

Preliminary identification of issues:

This Part Out of Scope of Application

This Part Out of Scope of Application

Any queries please let me know.

Regards,

Brian McDonnell | Associate Director

Umow Lai

This Part Out of Scope of Applicat
This Part Out of Scope of Application

Part Out of Scope of Applic



	Action/Notes	By Whom When
	DG provided the following update on the recent site incident:	
	 At around 4pm on Friday 16 October, one of the Thermal Energy Storage (TES) tanks located beside the FMC collapsed sending 2.4 million litres of water and debris across Kawana Way. 	
	 All debris has since been removed and stored on site so an independent assessment can be undertaken to determine what caused the incident. One section of the tank is wrapped around the corner of the FMC and will remain there to assist investigators with their report. It may take up to 2 months before an interim report is provided outlining what may have occurred. 	
•	 Kawana Way will be closed again this weekend so the second TES tank can be removed due to the damage incurred. Nearby reclaimed water tanks have also been drained uptil the analysis on the cause of the incident is completed. 	
	This Part Out of Scope of Application This Part Out of Scope of Application	
•	to rectify will be undertaken shortly.	
	 Some damage has occurred to the FMC (Energex meter room, kitchen ceiling) and Lendlease will commence repairs to make good prior to the end of December. Commissioning of the FMC may be delayed but alternative options such as alternative temporary cooling solutions for ICT rooms will be implemented to continue facility commissioning overall. 	
•	 Damage to Carpark 1 includes part of a reinforced concrete wall being sheared off; damage to the UPS room; and adjacent pathways. 	
j	The overall critical path for the project is being assessed, and until a final assessment report is received, it is too early to report on the likely impact(s) to the project.	
	Ell have formally provided "Notification of Occurrence of an Event" as per the Project Deed, and the State will respond accordingly. Remedial works will be on hold until such time that the report is received outlining the cause of the tank failure.	
	Lendlease are working with the family who were impacted by this incident.	
	Full site works recommenced today.	



Don Glynn

From:

Graham, Nicky Ohiof Scope of A @lendlease.com>

Sent:

Thursday, October 22, 2015 12:54 PM

To:

Don Glynn

Subject:

FW: SCPUH Incident - Updated Media Statement (Red)

Hi Don

Media statements below:

3.30pm 19 October

Safety is always our number one priority.

The incident area has been deemed safe by Workplace Health and Safety and handed backto Lendlease. Our current focus is working towards re-opening the site.

Once that has occurred, the incident will undergo thorough investigation of the root cause, underlying factors and corrective actions.

10.05am 17 October

The site is closed today and clean-up continues.

The current plan is for a specialist long-reach excavator to disassemble pipework and scaffold adjacent to the tank. Safety remains our number one priority.

10.26pm 16 October

Tank engineers have inspected the second tank. It is empty and has been deemed safe.

We have been in contact with the driver of the vehicle to ascertain how we can assist.

Workplace Health and Safety are now onsite. The site will be closed tomorrow for further investigation. Clean-up of the area continues.

5.38pm 16 October

We are aware of an incident where a water tank has ruptured.

Safety is our number one priority. We are currently working closely with emergency services.

Nicky Graham

Stakeholder Engagement Manager, Sunshine Coast Public University Hospital Project, Building


Site Office: Gate 7 Barny Moy Road, Birtinya QLD 4575 Australia

This Part Out of Scope of Application

Out of Scope of A@lendlease.com | www.landlease.com









MAIL TYPE MAIL NUMBER REFERENCE NUMBER QHP-CA-000279 EXH-NOTICE-000040 Client Advice STATE RESPONSE: Notification of the Occurrence of an Event - Insurance Policy From SCUH Project Director - Queensland Health - Capital Delivery Program □ To (2) Mr Pat Coleman - Exemplar Health Bianca Jones - Exemplar Health Mr Don Glynn - Queensland Health - Capital Delivery Program □ Cc (2) Roseanne Jennings - Queensland Health - Capital Delivery Program Thursday, 22 October 2015 3:41:25 PM EST (GMT +10:00) Sent N/A Status File Attachments (1) File Name SH000721 Letter to EH re TES Tank Rupture.pdf **Attributes** Attribute 1 Administration Attribute 2 Project Wide Message Dear Pat and Bianca Please find attached the State's response to Exemplar Health's Notice. Regards Roseanne SCPUH Project Director Sunshine Coast Public University/Hospital Project Capital Infrastructure Delivery Unit | Department of Health

From: B Jones

Sent: 19/10/2015 5:32:44 PM EST (GMT +10:00) To: SCUH Project Director, Roseanne Jennings

Cc: Pat Coleman

Mail Number: EXH-NOTICE-000040

Subject: Notification of the Occurrence of an Event - Insurance Policy

16 Innovation Parkway | RIRTINYA QLD 4575 P: TOUT OF SCOPE OF AND E: Scuh@health.qld.gov.au

Roseanne

Please find attached a Notice from the Project Co Representative, thank you.

Regards,

Bianca Jones | Development Co-ordinator

Sunshine Coast University Hospital Site Office





Department of Health

Enquiries to: Don Glynn

Telephone: Email: Out of Scope of A

ld.gov.au

File Ref: SH000721

Pat Coleman Chief Executive Exemplar Health (SCUH) Partnership (Exemplar Health) Level 31, 50 Bridge Street SYDNEY NSW 2000

Issued via: Part Out of Scope of Applica

Dear Pat

Sunshine Coast Public University Hospital (SCPUH) Project TES Tank Rupture & Clause 49.7(c) Notice

We acknowledge receipt of your letter dated 19 October 2015 provided in accordance with clause 49.7(c) of the Project Deed that notified the State of the occurrence of an event which will or might entitle Exemplar Health (EH) to make a claim under the Insurance Policy.

EH has a separate obligation, under clause 50.1(a) of the Project Deed, to provide the State with a notice which identifies the damage or destruction to the Works and the location of such damage or destruction (Clause 50.1(a) notice). This notice must be provided at least 5 Business Days of EH becoming aware of any damage to or destruction of any part of the Works.

We note that the State has not yet received a Clause 50.1(a) notice from EH.

Clause 50.2(a) of the Project Deed requires the State, within 5 Business Days of receiving the Clause 50.1(a) notice, to notify EH whether it requires EH to rebuild or repair the Works on the basis of the same specifications as, or different specifications from, the original Works.

The State considers that this notification period does not provide it with adequate time to decide on which specifications EH should use to rebuild or repair the Works. Therefore, the State formally requests that EH agree, in writing, to suspend the notification period under clause 50.2(a) until a date to be agreed between the parties.

We look forward to receiving the Clause 50.1(a) notice as soon as possible and an acknowledgment that EH agrees to suspend the requisite notification period under clause 50.2(a).

This letter does not prejudice any of the State's other rights under the Project Deed.

Yours sincerely

Roseanne Jennings

Executive Project Director

22/10/2015

Sunshine Coast Public University Hospital Project Ground Floor, K1 Building

Phone Fax

Thirhis Part Out of Scope of Application PP1

DO [16][hnovation Parkway 5/1] 6-03 f. I Document 21

Exemplar Health c/- Capella Capital AMP Centre, Level 31, 50 Bridge Street Sydney NSW 2000 Australia Ph +61 2 82243888

MAIL TYPE Notice	MAIL NUMBER EXH-NOTICE-000041	REFERENCE NUMBER EXH-NOTICE-000041		
Notice of De	elay in Progress - Tank Incident Clause 28.4			
From	Bianca Jones - Exemplar Health			
То	SCUH Project Director - Queensland Health - Capital Delivery Program			
□ Cc (3)	Mr Don Glynn - Queensland Health - Capital Delivery Program			
	Kate Gregson - Queensland Health - Capital Delivery Program	(O/A)		
	Roseanne Jennings - Queensland Health - Capital Delivery Pro-	gram		
Sent	Friday, 23 October 2015 10:06:06 PM EST (GMT +10:00)			
Status	N/A			
File Attachments (1) File Name				
SCUH - EH Letter to the State Clause 28.4 Tank Incident Notice of Delay in Progress of Combined Works.pdf				
Attributes Attribute 1	Administration			
Attribute 2 Project Wide				
Message				
Roseanne				
Please see attac	ched a Notice from the Project So Representative. Thank you.			
Regards,				
Bianca Jone	es Development Co-ordinator			
Gate 7 South	ast University Hospital Site Office of Street, Birtinya QLD 4575 Australia Out or Scope of Application plica			



23 October 2015

Ms Roseanne Jennings Executive Project Director Sunshine Coast University Hospital Project K1 Building, Ground Floor, 16 Innovation Parkway Birtinya QLD 4575 Sent via Aconex: Notice

Dear Roseanne

SUBJECT: SUNSHINE COAST UNIVERSITY HOSPITAL PROJECT: NOTIFICATION OF DELAY IN THE PROGRESS OF THE COMBINED WORKS

In accordance with Clause 28.4 of the Project Deed, Project Co notifies the State that a delay in the progress of the Combined Works has or will occur which will dleay or is likely to delay the achievement of Completion.

Nature and Cause of Potential Delay

On 16 October 2015, the thermal energy water storage tank located on the corner of the Facilities Management Centre, Kawana Way and Fenner Street (known as TES 1) ruptured, releasing approximately 2.7 million litres of water (Tank Incident). As a result of the Tank Incident, access to the Site was temporarily restricted.

This Part Out of Scope of Application

This Part Out of Scope of Application

Should you have any queries or questions in relation to this matter please do not hesitate to contact me on our of scope of A

Yours sincerely

Pat Coleman

Exemplar Health c/- Capella Capital AMP Centre, Level 31, 50 Bridge Street Sydney NSW 2000 Australia Ph+61 2 82243888

MAIL TYPE MAIL NUMBER REFERENCE NUMBER EXH-NOTICE-000042 Notice EXH-NOTICE-000042 Notice of Damage - Tank Incident Clauses 50.1(a) and 62.1(f)(4) From Bianca Jones - Exemplar Health То SCUH Project Director - Queensland Health - Capital Delivery Program □ Cc (7) Mr Terence Carroll - Exemplar Health Mr Pat Coleman - Exemplar Health Ms Sandra Hughes - Exemplar Health Mr Phil Morrissey - Exemplar Health Mr Don Glynn - Queensland Health - Capital Delivery Program Kate Gregson - Queensland Health - Capital Delivery Program Roseanne Jennings - Queensland Health - Capital Delivery Program Friday, 23 October 2015 10:15:11 PM EST (GMT +10:00) Sent Status N/A File Attachments (1) File Name SCUH - EH Letter to the State Clause 50.1 and 62.1(f)(4).pdf **Attributes** Attribute 1 Administration Attribute 2 Main Hospital Building Message Roseanne Please see Notice attached from the Project Co Representative. Regards, **Bianca Jones | Development Co-ordinator** Sunshine Coast University Hospital Site Office Gate 7 South Street, Birtinya QLD 4575 Australia This That Part Out of Scope of Application lica Out of Scope of A



23 October 2015

Ms Roseanne Jennings Executive Project Director Sunshine Coast University Hospital Project K1 Building, Ground Floor, 16 Innovation Parkway Birtinya QLD 4575 Sent via Aconex: Notice

Dear Roseanne

SUBJECT: SUNSHINE COAST UNIVERSITY HOSPITAL PROJECT: NOTIFICATION OF DAMAGE TO PART OF THE WORKS

In accordance with Clause 50.1(a) and 62.1(f)(4) of the Project Deed, Project Co hereby notifies the State that damage has occurred to parts of the Works

Identification and Location of Damage

On 16 October 2015, the thermal energy water storage tank located on the corner of the Facilities Management Centre, Kawana Way and Fenner Street (known as TES 1) ruptured, releasing approximately 2.7 million litres of water (**Tank Incident**).

As a result of the Tank incident, damage was caused to parts of the Works. The full extent of the damage is currently being assessed by Lendlease, however, it can be broadly identified in the following locations.

1. Thermal Energy Storage (TES) Tank 1 & 2 and associated pipework

Extensive damage to both tanks.

2. Kawana Way in the vicinity of TES Tank 2

Damage to landscaping, footpaths, traffic signals, street lighting, road signage and asphalt.

Car Park 1

Damage to blockwork wall to UPS Room and to concrete wall.



4. Fenner Street

Damage to landscaping, footpaths and asphalt pavement.

5. Facilities Management Centre (FMC) Building

Damage to Energex metering room and equipment, northern façade to the Dailging at Ground Level and Level 1, ground level dishwashing room and suspended services.

At this stage, Lendlease is working to understand the extent of the damage. We will provide the State with further information regarding our recommended plan for the rectification of the above damage as soon as practicable.

We acknowledge receipt of your letter dated 2 October 2015 ref: SH000721 and, in particular, the State's request to extend the period of time that the State has to respond to this notice under clause 50.2(a) of the Project Deed. Project Co is currently seeking the Contractor's consent in this regard in accordance with the relevant back to back terms of the Construction Contract and will respond shortly.

Should you have any queries or questions in relation to this matter please do not hesitate to contact me on Out of Scope of A

Yours sincerely

Pat Coleman Exemplar Health

Project Co Representative

Exemplar Health c/- Capella Capital AMP Centre, Level 31, 50 Bridge Street Sydney NSW 2000 Australia Ph +61 2 82243888

MAIL TYPE MAIL NUMBER REFERENCE NUMBER EXH-NOTICE-000043 Notice EXH-NOTICE-000043 Notice of Notifiable Incident WHS - Tank Incident Clause 2.10(I) From Bianca Jones - Exemplar Health То SCUH Project Director - Queensland Health - Capital Delivery Program □ Cc (6) Mr Pat Coleman - Exemplar Health Ms Sandra Hughes - Exemplar Health Mr Phil Morrissey - Exemplar Health Mr Don Glynn - Queensland Health - Capital Delivery Program Kate Gregson - Queensland Health - Capital Delivery Program Roseanne Jennings - Queensland Health - Capital Delivery Program Friday, 23 October 2015 10:30:14 PM EST (GMT +10:00) Sent Status N/A File Attachments (1) File Name rdent.pdf SCUH - EH Letter to the State Clause 2.10(I) Notice of Notiflable **Attributes** Attribute 1 Administration Attribute 2 Project Wide Message Roseanne Please find attached a Notice from the Project Co Representative.

Regards,

Bianca Jones | Development Co-ordinator

Sunshine Coast University Hospital Site Office Gate 7 South Street, Birtinya QLD 4575 Australia

ThisThis Part Out of Scope of Application plic au

Dut of Scope of A



23 October 2015

Ms Roseanne Jennings Executive Project Director Sunshine Coast University Hospital Project K1 Building, Ground Floor, 16 Innovation Parkway Birtinya QLD 4575 Sent via Aconex: Notice

Dear Roseanne

SUBJECT: SUNSHINE COAST UNIVERSITY HOSPITAL PROJECT: NOTIFICATION AND REPORT - INCIDENT UNDER WORKPLACE HEALTH AND SAFETY

In accordance with Clause 2.10(I) of the Project Deed, Project Co hereby notifies the State that an incident has occurred curring the carrying out of the Combined Works that is notifiable under WHS Legislation. The following is a report giving details of the incident, results of investigations into cause and steps to rectify damage and prevent repocurence:

Details of Incident

On 16 October 2015 at approximately 4pm, the thermal energy water storage tank located on the corner of the Facilities Management Centre, Kawana Way and Fenner Street (known as TES 1) ruptured, releasing approximately 2.7 million litres of water (**Tank Incident**).

Incident Notification in respect of the Tank Incident was submitted to the Office of Fair and Safe Work Queensland, and confirmed as received on 19 October 2015.

As advised in our Notice of 23 October 2015 under clauses 50.1 and 62.1(f)(4) of the Project Deed, as a result of the Tank Incident, damage was caused to parts of the Works.

Results of Investigations into Cause

The cause of the Fank Incident is not yet known. Lendlease is working to understand the cause of the Tank Incident and we will provide the State with further information as soon as practicable.

Steps to Rectify Damage and Prevent Recurrence

As advised in our Notice of 23 October 2015 under clauses 50.1 and 62.1(f)(4) of the Project Deed, Lendlease is working to understand the extent of the damage caused by the Tank Incident and will provide the State with their recommended plan for the rectification of the damage as soon as practicable.



Immediate steps taken by Lendlease in relation to the Tank Incident have focussed upon ensuring the safety of people and property.

These steps have included:

- 1. Assessment of the second thermal energy storage tank (known as TES 2) by an engineer employed by the Subcontractor responsible for supply of the tank.
- 2. Daily inspections of TES 2
- 3. Establishment of an exclusion zone around the vicinity of TES 2.
- 4. Wind monitoring.
- 5. Placement of emergency traffic control on 'stand-by' in the event the decision is made to evacuate Kawana Way due to high winds.

Should you ha contact me on Out of Scope of A

Yours sincerely

Pat Coleman Exemplar Health Project Co Representative



MAIL TYPE MAIL NUMBER REFERENCE NUMBER
General Communication ULA-GCOM-000704 QHP-GCOM-005927

Re: SCPUH TES - Tank failure

From Ms Elizabeth Coe - Umow Lai & Associates

To Mr Don Glynn - Queensland Health - Capital Delivery Program

Cc (9) Thit file Part Out of Scope of Application App

Roseanne Jennings - Queensland Health - Capital Delivery Program

Mr Andrew Leggate - Queensland Health - Capital Delivery Program

Mr Cyriac Mukkada - Queensland Health - Capital Delivery Program

Chris Anderson - Umow Lai & Associates

Mr Andrew Jenkinson - Umow Lai & Associates

Mr Brian McDonnell - Umow Lai & Associates

Mr Martin O'Connor - Wood & Grieve Engineers

Th This Part Out of Scope of Application App

Sent Friday, 23 October 2015 8:07:27 AM EST (GMT +10:00)

Status N/A

Attributes

Attribute 1 Environmental Sustainability Design (FSD), Mechanical

Attribute 2 Facility Management Centre, Site/Services Infrastructure

Message

Don, Roseanne

Further to our advice (from Brian McDomnelly copied below, This Part Out of his Part Out of Scope of Application

This Part Out of Scope of Application

This Part Out of Scope of Application

Regards, Elizabeth Coe

From: B McDonnell

Sent: 21/10/2015 10:30:47 AM EST (GMT +11:00)

To: Roseanne Jennings

Cc: Don Glynn, Chris Anderson, Elizabeth Coe, Andrew Jenkinson

Mail Number: ULA-GCOM-000701

Subject: RE: Failed Chilled Water Tank Comments

Roseanne,

Please find below some initial, bullet point, comments on the chilled water tank failure.

Effect on Hospital Operation

```
2.
    3.
    4
Information required from Exemplar:
    2.

    Full report on how the incident occurred and the QA process the tanks went through prior, during and after install;

                                       of Application
                                     This Part Out of Scope of Application
    5.
Preliminary identification of issues:
       This Part Out of Scope of Application
    2.
    3.
                                                      This Part Out of Scope of Applica
    4.
    5. How confidence in any new tank strategy can be assured after the failure of original tank(s).
Any queries please let me know.
Regards,
Brian McDonnell | Associate Director
This Part Out of
Part Out of Scope of Applica
Part Out of Scope of Applic
From: D Glynn
Sent: 19/10/2015 12:24:37 PM EST
                                (GMT +11:00)
To: Elizabeth Coe
Cc: Grant Buglar, Roseanne Jennings
                                 Andrew Leggate, Cyriac Mukkada, Chris Anderson, Andrew Jenkinson, Brian McDonnell, Martin O'Connor, Michael Prior
Mail Number: QHP-GCOM-005927
Subject: SCPUH TES - Tank failure
```

Elizabeth,

No doubt you would have heard by now that one of the TES tanks failed completely at 4pm on Friday after having been filled that day. The second tank suffered structural damage and is likely to be removed as well. The FMC suffered some external and internal damage and CP1 has some minor external damage as does the surrounding area. The full extent of the damage will not be determined for some time but we will keep our Advisors informed whenever we receive updates.

I have attached a picture for your information only and so that you can appreciate the extent of damage. It must not be distributed or used in any way other than for the intended purpose of this correspondence.

What we need to do now is start assessing the immediate and or long term impacts to program, commissioning strategies (ie temporary cooling to ICT rooms), design options (ie less TES, different tank design etc) and recurrent costs (ie no TES on Day 1). Can I ask that your team start to think about these things as we will be presented with options by EH to assess and we want to be ready with our own assessment and views on what

This Part Out of his Par Out of Scope of Application

Regards,

Don

Don Glynn


Engineering and Technical Director

Sunshine Coast University Hospital Project

Health Infrastructure Branch | System Support Services | Queensland Health

Ground Floor - K1 | 16 Innovation Parkway | BIRTINYA QLD 4575

This Pantout of Scope of Application Cation





MAIL TYPE MAIL NUMBER REFERENCE NUMBER
General Communication QHP-GCOM-006045 QHP-GCOM-005927

Re: SCPUH TES - Tank failure

From Mr Don Glynn - Queensland Health - Capital Delivery Program

To Ms Elizabeth Coe - Umow Lai & Associates

Third is Part Out of Scope of Application App

Roseanne Jennings - Queensland Health - Capital Delivery Program

Mr Andrew Leggate - Queensland Health - Capital Delivery Program

Mr Cyriac Mukkada - Queensland Health - Capital Delivery Program

Chris Anderson - Umow Lai & Associates

Mr Andrew Jenkinson - Umow Lai & Associates

Mr Brian McDonnell - Umow Lai & Associates

This Part Out of Scope of Appli

This Part Out of Scope of Application

Sent Friday, 23 October 2015 9:59:52 AM EST (GMT +10:00)

Status N/A

Attributes

Attribute 1 Environmental Sustainability Design (FSD), Mechanical

Attribute 2 Facility Management Centre, Site/Services Infrastructure

Message

Elizabeth and Brian,

mments to date This Part Out of This Part Out of Scope of Application

This hart but of Scope of Applicatio

٠

This Part Out of Scope of Application



Extract from Schedule 14 - Payment Schedule:



```
This Part Out of Scope of Application

This Part Out of Scope of Application
```

Don Glynn

Engineering and Technical Director

Sunshine Coast University Hospital Project

Health Infrastructure Branch | System Support Services | Queensland Health

Ground Floor - K1 | 16 Innovation Parkway | BIRTINYA QLD 4575

This Part bur of Scope of Application

Out of Scope of Ap

From: E Coe Sent: 23/10/2015 8:07:27 AM EST (GMT +10:00) To: Don Glynn Cc: Grant Buglar, Roseanne Jennings, Andrew Leggate, Cyriac Mukkada, Chris Anderson, Andrew Jenkinson, Bran McDonnell, Martin O'Connor, Michael Prior Mail Number: ULA-GCOM-000704 Subject: Re: SCPUH TES - Tank failure Don, Roseanne Further to our advice (from Brian McDonnell) copied below, This his Part Out of Scope of Application This Part This Part Out of Scope of Application This Part Out of Scope of Application Scope of Application This Part Out of Regards, Elizabeth Coe From: B McDonnell **Sent:** 21/10/2015 10:30:47 AM EST (GMT +11;80) To: Roseanne Jennings Cc: Don Glynn, Chris Anderson, Elizabeth Coe, Andrew Jenkinson Mail Number: ULA-GCOM-000701 Subject: RE: Failed Chilled Water Tank Comments Roseanne, Please find below some initial, bullet point, comments on the chilled water tank failure. Effect on Hospital Operation 1. This Part Out of Scope of Application 2

This Part Out of Scope of Application

Information required from Exemplar:

3.

4

```
1. This Part Out of Scope of Application


2. This Part Out of Scope of Application

3. Full report on how the incident occurred and the QA process the tanks went through prior, during and after install;

4. This Part Out of Scope of Application

5. This Part Out of Scope of Application
```

Preliminary identification of issues:



Any queries please let me know.

Regards,

Brian McDonnell | Associate Director

Umow Lai

This Part Out of Part Out of Scope of Applic

Part Out of Scope of Applic@umowlai.com.au

W: umowlai.com.au

From: D Glynn

Sent: 19/10/2015 12:24:37 PM EST (GMT +11:00)

To: Elizabeth Coe

Cc: Grant Buglar, Roseanne Jennings, Andrew Leggate, Cyriac Mukkada, Chris Anderson, Andrew Jenkinson, Brian McDonnell, Martin O'Connor, Michael Prior

Mail Number: QHP-GCOM-005927 Subject: SCPUH TES - Tank failure

Elizabeth,

No doubt you would have heard by now that one of the TES tanks failed completely at 4pm on Friday after having been filled that day. The second tank suffered structural damage and is likely to be removed as well. The FMC suffered some external and internal damage and CP1 has some minor external damage as does the surrounding area. The full extent of the damage will not be determined for some time but we will keep our Advisors informed whenever we receive updates.

I have attached a picture for your information only and so that you can appreciate the extent of damage. It must not be distributed or used in any way other than for the intended our pose of this correspondence.

What we need to do now is start assessing the immediate and or long term impacts to program, commissioning strategies (ie temporary cooling to ICT rooms), design options (ie less TES, different tank design etc) and recurrent costs (ie no TES on Day 1). Can I ask that your team start to think about these things as we will be presented with options by EH to assess and we want to be ready with our own assessment and views on what options should be considered both immediately, in the interim and of course long term.

Regards,

Don

Don Glynn


Engineering and Technical Director

Sunshine Coast University Hospital Project

Health Infrastructure Branch | System Support Services | Queensland Health

Ground Floor - K1 | 16 Innovation Parkway | BIRTINYA QLD 4575

t Out of Scope of Ap



NOTES



MAIL TYPE MAIL NUMBER REFERENCE NUMBER
General Communication QHP-GCOM-006099 QHP-GCOM-005927

Re: SCPUH TES - Tank failure

From Mr Don Glynn - Queensland Health - Capital Delivery Program

To Mr Brian McDonnell - Umow Lai & Associates

This Part Out of Scope of Application App

Linda Brandon - Queensland Health - Capital Delivery Program

Mr Peter Callaghan - Queensland Health - Capital Delivery Program

Roseanne Jennings - Queensland Health - Capital Delivery Program

Mr Andrew Leggate - Queensland Health - Capital Delivery Program

Mr Cyriac Mukkada - Queensland Health - Capital Delivery Program

Chris Anderson - Umow Lai & Associates

Ms Elizabeth Coe - Umow Lai & Associates

Mr Andrew Jenkinson - Umow Lai & Associates

This Part Out of Scope of App

This Part Out of Scope of Application

Sent Tuesday, 27 October 2015 12:29:05 PM EST (GMT/+10:00)

Status N/A

Attributes

Attribute 1 Environmental Sustainability Design (ESD), Mechanical

Attribute 2 Facility Management Sentre, Site Services Infrastructure

Message

Brian,

This Part Out of Sope of Application

This Part Out of Scope of Application

Don Glynn

Engineering and Technical Director

Sunshine Coast University Hospital Project

Health Infrastructure Branch | System Support Services | Queensland Health

Ground Floor - K1 | 16 Innovation Parkway | BIRTINYA QLD 4575

This Pranstpart Out of Scoper of Application icatio

Out of Scope of Ap@health.qld.gov.au

From: D Glynn


Sent: 23/10/2015 9:59:52 AM EST (GMT +10:00)

To: Elizabeth Coe

Cc: Grant Buglar, Roseanne Jennings, Andrew Leggate, Cyriac Mukkada, Chris Anderson, Andrew Jenkinson, Brian McDonnell, Martin O'Connor, Michael Prior

Mail Number: QHP-GCOM-006045 Subject: Re: SCPUH TES - Tank failure

Elizabeth and Brian,





From: E Coe

Sent: 23/10/2015 8:07:27 AM EST (GMT +10:00)

To: Don Glynn

Cc: Grant Buglar, Roseanne Jennings, Andrew Leggate, Cyriac Mukkada, Chris Anderson, Andrew Jenkinson, Brian McDonnell, Martin O'Connor, Michael Prior

Mail Number: ULA-GCOM-000704 Subject: Re: SCPUH TES - Tank failure

Don, Roseanne

This Pan Out of Scope of Application This Parthis Part Out of Scope of Application This Part Out of Scope of Application This Part Out of Scope of Application Regards, Elizabeth Coe From: B McDonnell Sent: 21/10/2015 10:30:47 AM EST (GMT +11:00) To: Roseanne Jennings Cc: Don Glynn, Chris Anderson, Elizabeth Coe, Andrew Jenkinson Mail Number: ULA-GCOM-000701 Subject: RE: Failed Chilled Water Tank Comments Roseanne, Please find below some initial, bullet point, comments on the chilled water tank failurge Effect on Hospital Operation This Part Out of Scope of Application 2. This Part Out of Scope of Application 3. 4. Information required from Exemplar: 1 This Part Out of Scope of App This Part Out of Scope of Application 2 3. Full report on how the incident occurred and the QA process the tanks went through prior, during and after install; 4. This Part Out of Sc This Rart Out of Scope of Application Preliminary identification of issues Application 2 3. This Part Out of Scope of Application 4.

Any queries please let me know.

Regards,

Brian McDonnell | Associate Director

Umow Lai

Part Out Brescope of Applic



1

From: D Glynn

Sent: 19/10/2015 12:24:37 PM EST (GMT +11:00)

To: Elizabeth Coe

Cc: Grant Buglar, Roseanne Jennings, Andrew Leggate, Cyriac Mukkada, Chris Anderson, Andrew Jenkinson, Brian McDonnell, Martin O'Connor, Michael Prior

Mail Number: QHP-GCOM-005927 Subject: SCPUH TES - Tank failure

Elizabeth,

No doubt you would have heard by now that one of the TES tanks failed completely at 4pm on Friday after having been filled that day. The second tank suffered structural damage and is likely to be removed as well. The FMC suffered some external and internal damage and CP1 has some minor external damage as does the surrounding area. The full extent of the damage will not be determined for some time but we will keep our Advisors informed whenever we receive updates.

I have attached a picture for your information only and so that you can appreciate the extent of damage. It must not be distributed or used in any way other than for the intended purpose of this correspondence.

What we need to do now is start assessing the immediate and or long term impacts to program, commissioning strategies (ie temporary cooling to ICT rooms), design options (ie less TES, different tank design etc) and recurrent costs (ie no TES on Day 1). Oan I ask that your team start to think about these things as we will be presented with options by EH to assess and we want to be ready with our own assessment and views on what options should be considered both immediately, in the interim and of course long term.

4575

Regards,

Don

Don Glynn

Engineering and Technical Director

Sunshine Coast University Hospital Projet

Health Infrastructure Branch | System Support Services | Queensland Health

Ground Floor - K1 | 16 Innovation Parkway | BIRTINYA QLD

This Part Out of Scope of Application

t Out of Scope of Ap



MAIL TYPE MAIL NUMBER REFERENCE NUMBER
General Communication ULA-GCOM-000706 QHP-GCOM-005927

Fwd: SCPUH TES - Tank failure

From Ms Elizabeth Coe - Umow Lai & Associates

To (2) Mr Brian McDonnell - Umow Lai & Associates (1 more...)

Sent Tuesday, 27 October 2015 1:20:21 PM EST (GMT +10:00)

Status N/A

Attributes

Attribute 1 Environmental Sustainability Design (ESD), Mechanical

Attribute 2 Facility Management Centre, Site Services Infrastructure

Message

Brian & Nick

This Part Out of Scope of Application

This Part Out of Scope of Application

Cheers, E

From: D Glynn

Sent: 27/10/2015 1:29:05 PM EST (GMT + 14:00)

To: Brian McDonnell

Cc: Grant Buglar, Linda Brandon, Peter Callaghan, Roseanne Jennings, Andrew Leggate, Cyriac Mukkada, Chris Anderson, Elizabeth Coe, Andrew Jenkinson,

Martin O'Connor, Michael Prior

Mail Number: QHP-GCOM-006099

Subject: Re: SCPUH TES - Taylor failure

Brian,

This Part Out of Scope of Application

This Part Out of Scope of Application

Don Glynn

Engineering and Technical Director

Sunshine Coast University Hospital Project

Health Infrastructure Branch | System Support Services | Queensland Health

way | BIRTINYA QLD 4575

This Part Out of Scope of Application

Out of Scope of Ar

From: D Glynn


Sent: 23/10/2015 9:59:52 AM EST (GMT +10:00)

To: Elizabeth Coe

Cc: Grant Buglar, Roseanne Jennings, Andrew Leggate, Cyriac Mukkada, Chris Anderson, Andrew Jenkinson, Brian McDonnell, Martin O'Connor, Michael Prior

Mail Number: QHP-GCOM-006045 Subject: Re: SCPUH TES - Tank failure

Elizabeth and Brian,



Extract from Schedule 14 - Payment Schedule:

This Part Out of Scope of Application

This Part Out of Scope of Application



From: E Coe

Sent: 23/10/2015 8:07:27 AM EST (GMT +10:00)

To: Don Glynn

Cc: Grant Buglar, Roseanne Jennings, Andrew Leggate, Cyriac Mukkada, Chris Anderson, Andrew Jenkinson, Brian McDonnell, Martin O'Connor, Michael Prior

Mail Number: ULA-GCOM-000704 Subject: Re: SCPUH TES - Tank failure

Don, Roseanne

```
Further to our advice (from Brian McDonnell) copied below, This Part Out
                                                                         This Part Out of Scope of Application
This Part This Part Out of Scope of Application
This Part Out of Scope of Application
                                               This Part Out of Scope of Application
Regards,
Elizabeth Coe
From: B McDonnell
Sent: 21/10/2015 10:30:47 AM EST (GMT +11:00)
To: Roseanne Jennings
Cc: Don Glynn, Chris Anderson, Elizabeth Coe, Andrew Jenkinson
Mail Number: ULA-GCOM-000701
Subject: RE: Failed Chilled Water Tank Comments
Roseanne,
Please find below some initial, bullet point, comments on the chilled water tank failure
Effect on Hospital Operation
    1. This Part Out of Scope of Application
    2.
                                                   This Part Out of Scope of Application
    3.
Information required from Exemplar:
    1 This Part Out of Scope of
                                          Application
                                                   This Part Out of Scope of Application
    2
    3. Full report on how the ingreent occurred and the QA process the tanks went through prior, during and after install;
                                   This Part Out of Scope of Application
Preliminary identification of issues
                                          Application
    2.
    3.
                                                   This Part Out of Scope of Application
    4.
    5. How confidence in any new tank strategy can be assured after the failure of original tank(s).
```

Any queries please let me know.

Regards,

Brian McDonnell | Associate Director

Umow Lai

This Part Out of Part Out of Scope of Applic

From: D Glynn

Sent: 19/10/2015 12:24:37 PM EST (GMT +11:00)

To: Elizabeth Coe

Cc: Grant Buglar, Roseanne Jennings, Andrew Leggate, Cyriac Mukkada, Chris Anderson, Andrew Jenkinson, Brian McDonnell, Martin O'Connor, Michael Prior

Mail Number: QHP-GCOM-005927 Subject: SCPUH TES - Tank failure

Elizabeth,

No doubt you would have heard by now that one of the TES tanks failed completely at 4pm on Friday after having been filled that day. The second tank suffered structural damage and is likely to be removed as well. The FMC suffered some external and interpal damage and CP1 has some minor external damage as does the surrounding area. The full extent of the damage will not be determined for some time but we will keep our Advisors informed whenever we receive updates.

I have attached a picture for your information only and so that you can appreciate the extent of damage. It must not be distributed or used in any way other than for the intended purpose of this correspondence.

What we need to do now is start assessing the immediate and or long term impacts to program, commissioning strategies (ie temporary cooling to ICT rooms), design options (ie less TES, different tank design etc) and recurrent costs (ie no TES on Day 1). Can I ask that your team start to think about these things as we will be presented with options by EH to assess and we want to be ready with our own assessment and views on what options should be considered both immediately, in the interim and of course long term.

Regards,

Don

Don Glynn

Engineering and Technical Director

Sunshine Coast University Hospital Project

Health Infrastructure Branch | System Support Services | Queensland Health

Ground Floor - K1 | 16 Innovation Parkway | BIRTINYA QLD 4575

This Part Out of Scope of Application catio

t Ölütİ öf Scope oPAd

Sunshine Coast University Hospital PPP Kawana Way Birtinya Queensland 4575 Australia Exemplar Health c/- Capella Capital AMP Centre, Level 31, 50 Bridge Street Sydney NSW 2000 Australia Ph +61 2 82243888

MAIL TYPE Notice	MAIL NUMBER EXH-NOTICE-000046	REFERENCE NUMBER EXH-NOTICE-000046	
Tank Incider	nt - Extension of State Response Clause 50.2(a)	
From	Bianca Jones - Exemplar Health		
То	SCUH Project Director - Queensland Health - Capital Delivery Program		
□ Cc (4)	Mr Pat Coleman - Exemplar Health		
	Ms Sandra Hughes - Exemplar Health	(O/A)	
	Kate Gregson - Queensland Health - Capital Delivery Pro-	gram	
	Roseanne Jennings - Queensland Health - Capital Deliver	ry Program	
Sent	Thursday, 29 October 2015 2:53:23 AM EST (GMT +10:0	00)	
Status	N/A	$(0, \overline{)}$	
Attributes Attribute 1	Administration	on	
Attribute 2	Project Wide		
Message			
Roseanne, pleas	se see attached letter from the Project Co Representative. That	nk you.	
Regards,			
Bianca Jone	es Development Co-ordinator		
Sunshine Co	ast University Hospital Site Office		
	Australia		
Thoiscope of /	au		

Sunshine Coast University Hospital PPP Kawana Way Birtinya Queensland 4575 Australia



MAIL TYPE MAIL NUMBER REFERENCE NUMBER
General Communication ULA-GCOM-000714 QHP-GCOM-005927

Re: SCPUH TES - Tank failure

From Mr Brian McDonnell - Umow Lai & Associates

To Mr Don Glynn - Queensland Health - Capital Delivery Program

Thins Part Out of Scope of Application App (10 more...)

Sent Wednesday, 4 November 2015 12:39:01 PM EST (GMT +10:00)

Status N/A

Attributes

Attribute 1 Environmental Sustainability Design (ESD), Mechanical

Attribute 2 Facility Management Centre, Site Services Infrastructure

Message

Don,

As per discussions I just wanted to confirm that UL will be in attendance on site at 10,30 am from orrow for the mini workshop on the tank failure

outcomes.

We will undertake the site walk post workshop.

Regards,

Brian McDonnell | Associate Director

Umow Lai

This Part Out of Part Out of Scope of Applic

Part Out of Scope of Applic@umowlai.com.au

From: D Glynn

Sent: 27/10/2015 12:29:05 PM EST (GMT +10:00)

To: Brian McDonnell

Cc: Grant Buglar, Linda Brandon, Peter Callaghan, Roseanne Jennings, Andrew Leggate, Cyriac Mukkada, Chris Anderson, Elizabeth Coe, Andrew Jenkinson,

Martin O'Connor, Michael Prior

Mail Number: QHP-GCOM-006099

Subject: Re: SCPUH TES - Tank failure

Brian,

This Part Out of Scope of Application

This Part Out of Scope of Application

establish a viable options list.

Don Glynn

Engineering and Technical Director

Sunshine Coast University Hospital Project

Health Infrastructure Branch | System Support Services | Queensland Health

Ground Floor - K1 | 16 Innovation Parkway | BIRTINYA QLD 4575

This Part Out of Scope of Application ication

Out of Scope of Ad

From: D Glynn

Sent: 23/10/2015 9:59:52 AM EST (GMT +10:00)

To: Elizabeth Coe

Cc: Grant Buglar, Roseanne Jennings, Andrew Leggate, Cyriac Mukkada, Chris Anderson, Andrew Jenkinson, Brian McDonnell, Martin O'Connor, Michael Prior

Mail Number: QHP-GCOM-006045 Subject: Re: SCPUH TES - Tank failure

Elizabeth and Brian,


omments to date. This Part Out of This Part Out of Pris Part Of Application

This Part Out of Scope of Application



Extract from Schedule 14 - Payment Schedule:

This Part Out of Scope of Application
This Part Out of Scope of Application



Don Glynn

Engineering and Technical Director

Sunshine Coast University Hospital Project

Health Infrastructure Branch | System Support Services | Queensland Health

way | BIRTINYA QLD 4575

This Part Out of Scope of Application

t Out of Scope of Ap

From: E Coe

Sent: 23/10/2015 8:07:27 AM EST (GMT +10:00)

To: Don Glynn

Cc: Grant Buglar, Roseanne Jennings, Andrew Leggate, Cyriac Mukkada, Chris Anderson, Andrew Jenkinson, Brian McDonnell, Martin O'Connor, Michael Prior

Mail Number: ULA-GCOM-000704 Subject: Re: SCPUH TES - Tank failure

Don, Roseanne

Further to our advice (from Brian McDonnell) copied below, This Part Out This Parpout of Scope of Application

This Parthis Part Out of Scope of Applicationation

This Part Out of Scope of Application

This Part Out of Scope of Application

Regards, Elizabeth Coe

From: B McDonnell

Sent: 21/10/2015 10:30:47 AM EST (GMT +11:00)

To: Roseanne Jennings

Cc: Don Glynn, Chris Anderson, Elizabeth Coe, Andrew Jenkinson


Mail Number: ULA-GCOM-000701

Subject: RE: Failed Chilled Water Tank Comments

Roseanne,

Please find below some initial, bullet point, comments on the chilled water ank failure.

Effect on Hospital Operation



Information required from Exemplar:

```
1. This Part Out of Scope of Application

2. This Part Out of Scope of Application
```

3. Full report on how the incident occurred and the QA process the tanks went through prior, during and after install;

```
This Part Out of Sope of Application
This Part Out of Scope of Application
```

Preliminary identification of issues:

```
1. This Part Out of Scope of Application
2.
3. This Part Out of Scope of Application
4.
```

Any queries please let me know.

Regards,

Brian McDonnell | Associate Director

Umow Lai

This Part Out of Spart Out of Spart Out of Scope of Application of Scope of Scope of Application of Scope
From: D Glynn

Sent: 19/10/2015 12:24:37 PM EST (GMT +11:00)

To: Elizabeth Coe

Cc: Grant Buglar, Roseanne Jennings, Andrew Leggate, Cyriac Mukkada, Chris Anderson, Andrew Jenkinson, Brian McDonnell, Martin O'Connor, Michael Prior

Mail Number: QHP-GCOM-005927 Subject: SCPUH TES - Tank failure

Elizabeth,

No doubt you would have heard by now that one of the TES tanks failed completely at 4pm on Friday after Haying been filled that day. The second tank suffered structural damage and is likely to be removed as well. The FMC suffered some external and internal damage and CP1 has some minor external damage as does the surrounding area. The full extent of the damage will not be determined for some time but we will keep our Advisors informed whenever we receive updates.

I have attached a picture for your information only and so that you can appreciate the extent of damage. It must not be distributed or used in any way other than for the intended purpose of this correspondence.

What we need to do now is start assessing the immediate and or long term impacts to program, commissioning strategies (ie temporary cooling to ICT rooms), design options (ie less TES, different tank design etc) and recurrent sosts (ie no TES on Day 1). Can I ask that your team start to think about these things as we will be presented with options by EH to assess and we want to be ready with our own assessment and views on what options should be considered both immediately, in the interim and of course long term.

Regards,

Don

Don Glynn

Engineering and Technical Director

Sunshine Coast University Hospital Projec

Health Infrastructure Branch System Support Services | Queensland Health

_way | BIRTINYA QLD 4575


This Part out of Scope of Application ication

Out of Scope of Air




Pages 54 through 55 redacted for the following reasons:

This Part Out of Scope of Application



DOH-DL 15/16-031





Tank Incident

As advised in our relevant Notices to the State, on 16 October 2015 at approximately 4pm, the thermal energy water storage tank located on the corner of the Facilities Management Centre, Kawana Way and Fenner Street (known as TES 1) ruptured, releasing approximately 2.7 million litres of water (Tank Incident). Incident Notification in respect of the Tank Incident was submitted to the Office of Fair and Safe Work Queensland, and confirmed as received on 19 October 2015.

The cause of the Tank Incident is not yet known. Lend Lease is working to understand the cause of the Tank Incident and we will provide the State with further information as soon as practicable.

As a result of the Tank Incident, damage was caused to parts of the Works identified in the following locations:

- 1. Thermal Energy Storage (TES) Tank 1 & 2 and associated pipework Extensive damage to both tanks.
- 2. Kawana Way in the vicinity of TES Tank 2 Damage to landscaping, footpaths, traffic signals, street lighting, road signage and asphalt.
- Car Park 1 Damage to blockwork wall to UPS Room and to concrete wall.
- 4. Fenner Street Damage to landscaping, footpaths and asphalt pavement.



5. Facilities Management Centre (FMC) Building - Damage to Energex metering room and equipment, northern façade to the building at Ground Level and Level 1, ground level dishwashing room and suspended services.

At this stage, Lend Lease is working to understand the extent of the damage. We will provide the State with further information regarding our recommended plan for the rectification of the above damage as soon as practicable.

The TES 2 tank which was damaged in the incident has now been dismantled.



SUNSHINE COAST UNIVERSITY HOSPITAL





Prepared By:


MPN CONSULTING PTY LTD

39 Sherwood Road Toowong Queensland 4066 • Australia



TABLE OF CONTENTS

1	INTRODUCTION	2
2	DESCRIPTION OF STRUCTURE	з
3	FIELD OBSERVATIONS	5



DOH-DL 15/16-03 ATI Document 59



1 INTRODUCTION

- 1.1 This report presents the results on an investigation into the facts and primary evidence of the collapse of Thermal Energy Water Storage Tank No. 1 at Sunshine Coast University Hospital.
- 1.2 The purpose of the report is to obtain the facts and primary evidence associated with the collapsed tank.
- 1.3 The scope of the report is to record observations at the location of the incident to establish the facts and primary evidence associated with the collapse.
- 1.4 It is understood that the Thermal Energy Water Storage Tank No. 1 ruptured at approximately 4pm on 16 October 2015.
- 1.5 Water and debris spilled and was scattered across Rawana Way, Fenner Street and into the adjacent Facilities Management Centre and P1 Carpark.
- 1.6 The adjacent Thermal Tank No. 2 was extensively damaged.
- 1.7 The principal contractor for the site is Lend Lease.
- 1.8 The tank installation was conducted by ALS Group.
- 1.9 This report is based on a reasonably detailed visual inspection of the location of the collapse of Thermal Energy Waste Storage Tank No. 1.
- 1.10 MPN shall have no liability for any claim whatsoever relating to the rupturing of the thermal energy water tank and MPN services.
- 1.11 MPN does not accept any liability or responsibility for any discrepancy, loss, damage or claim arising from the misuse of the "Sunshine Coast University Hospital Thermal Water Tank No. 1 Collapse" supplied.

Job Number: 6954 !:\6000-6999\6900 - 6999\6954\report\03-11-15 thermal water tank collapse.docx



2 DESCRIPTION OF STRUCTURE

- 2.1 The tank is 13 metres in diameter and 23 metres high and contains approximate effective capacity of 2800kl of water.
- 2.2 The tank is constructed from 19 rows of metal plate strakes. Each strake measures 3.0m x 1.2m. There are 14 strakes in each row to form the circumference of the tank. The strakes are galvanised and coated with a protective acrylic film.
- 2.3 The thickness of the strakes decreases with height as follows:


<u>Strake</u>	<u>Thickness</u>
1,2	16mm
3-5	12mm
6,7	10mm
8,9	8mm
10,11	6mm
12,13	5mm
14,15	4mm
16-19	3mm /

- 2.4 The strakes overlap at joints and are connected by M12 8.8/s bolts.
- 2.5 Typically vertical joints for the first 9 strakes comprise approximately 18 sets of 3 bolts. Strakes 10-19 vertical joints comprise approximately 18 sets of 2 bolts.
- Typically, horizontal joints are connected by a single row of bolts at approximately 115mm centres at each horizontal joint for the full height of the tank.
- 2.7 All bolts are 12mm in diameter and galvanised. The bolts have been tensioned to an undetermined load.
- The tank is fixed to the concrete base by M16 stainless steel mechanical anchors connected to a 75mm x 75mm x 5mm rolled angle which is bolted to first strake.
- 2.9 At the location of vertical joints in the first strake a double stiffener has been detailed which is fixed to the concrete base with an M16 chemical anchor.

Job Number: 6954 l:\6000-6999\6900 - 6999\6954\report\03-11-15 thermal water tank collapse.docx Page 3



- 2.10 The tank base is a 1500mm thick circular concrete base which is supported on driven piles.
- 2.11 The tank has an internal layer of rigid polyurethane insulation and a liner.
- 2.12 A 65 x 5 equal angle (wind angle) is attached to the external horizontal joint for the top 6 strakes.
- 2.13 The tank roof is constructed from a rafter aligned along the tank diameter and cold formed purlins at right angles to the rafter. The roof is supported from the tank wall.



Job Number: 6954 l:\6000-6999\6900 - 6999\6954\report\03-11-15 thermal water tank collapse.docx



3 FIELD OBSERVATIONS

- 3.1 MPN Consulting Pty Ltd Thins Part out of scope of Application Application inspected the location of the incident on Saturday 17 October 2015 and Sunday 18 October 2015. Thins Part out of Scope of Application Applicatio
- 3.2 The general pattern of debris of the collapsed Tank No 1 is shown in Figures 1 and 2.

3.3 **Generally**


- Strake 1 remained connected to the base except on the northern side
- Strakes 2-5 are located against the FM Building and extend into the base of Tank No. 2. The southern end wraps around the building towards the SW.
- Strakes 6 and 7 generally align with strakes 2/5
- Strakes 8 to 13 are generally intact and aligned NE/SW across the tank base. This segment extended fully across Fenner Street.
- Strakes 14-19 were crumpled and located to the west of the tank base.
- A 4 panel segment of 12mm plate (from either strakes 3,4 or 5) was observed on the western side of Kawana Way Figure 3. It is understood the panels were bent during relocation.
- 3.4 A significant dimple was observed in strakes 1-5 of Tank No. 2. Refer Figure 4.
- 3.5 Damage to masonry walls and concrete balustrade was observed at SW corner of carpark P1 directly to the north of Tank No. 1. Refer Figures 5 and 6.
- Damage to fascia panels at the NW corner of the FM Building was observed up to LevelRefer Figure 7.
- 3.7 Traffic signal and light poles at Kawana Way/Fenner Street intersection appear relatively undamaged.
- 3.8 Typically, ruptured vertical joints displayed bolts which have failed in shear. Refer Figure 8.

 $\label{loop-first-solution} \begin{tabular}{ll} Job Number: 6954 \\ l:\000-6999\6900-6999\6954\end{tabular} eport\03-11-15\ thermal\ water\ tank\ collapse.\ docx \end{tabular}$

Page 5



- 3.9 The Northernmost vertical joint of Strakes 1-3 display some deformation of the bolt holes. Refer Figure 9.
- 3.10 Typically ruptured horizontal joints display bolts with stripped threads. Refer Figure 10.
- 3.11 Mechanical anchor fixings to the northern third of the base circumference were observed to have been bent in double curvature and come failure at fixing locations was observed in concrete. Refer Figure 11 and Figure 12.
- 3.12 Curved scratch marks were observed on surface of concrete base extending out from the tank circumference which appear to follow the displacement of Strake No.1 during the rupture. Refer Figure 12 and Figure 13. These scratch marks have been recorded on survey of the tank base following clearance of debris.
- 3.13 The survey of reduced levels on the tank base appear to indicate that the base level is within tolerance.




Job Number: 6954 l:\6000-6999\6900 - 6999\6954\report\03-11-15 thermal water tank collapse.docx

SCUH
TES Tank Incident Recovery

Exemplar Health Update 18 November 2015

lendlease DOH-DL 15/16-031



CONTENTS

- Executive Summary
- Incident Facts and Observations
- Investigation
- Replacement & Other Rectification
- Program Impact / Mitigation
- Insurance
- O EH / State
- O Team / R&R's





EXECUTIVE SUMMARY

Investigation:

- Facts and evidence report issued by MPN consulting; separately issued to EH
- Report into cause targeted for late Nov (MPN Consulting)

Workplace Health and Safety Queensland (WHSQ):

- Facts and evidence report has been provided
- Prohibition Notice remains in place for the 'other' tanks pending outcome of investigation

Replacement Options:

This Part Out of Scope of Application

This Part Out of Scope of Application



EXECUTIVE SUMMARY

Program:

- Critical Path impact is dependent upon outcome of above assessments and approvals by EH and State re replacement recommendation
- Also dependent upon no rectification to other tanks required
- Chilled water availability being significantly mitigated by deployment of a temporary chiller.

Insurance:

This Part Out of Scope of Application

This Part Out of Scope of Application



INVESTIGATION

OTHER TANKS:


- There are 6 other tanks (4 x 500kL and 2 x 750kL)
- The 4 x 500kL tanks (fire and potable water) are a priority to fill to avoid delay
- Independent 3rd party Part Out of Scope of Applic engaged to:
 - Desktop model the structural adequacy of the other tanks
 - Carry out site inspection to verify installation of tanks
 - Incorporate the findings of the MPN report into the TES tank failure
- This Part Out of Scope of Appil report to be used to satisfy Lendlease and WHSQ that the other tanks are safe to fill
- Costs This Part Out of Scope of Application
 This Part Out of Scope of Application
 This Part Out of Scope of Application



REPLACEMENT

CONTRACT REQUIREMENTS:

Notice issued to EH under Clause 50







Pages 86 through 90 redacted for the following reasons:

This Part Out of Scope of Application



EH/STATE

NOTICES:


All required Notice have been issued under the Construction Contract

This Part Out of Scope of Application

This Part Out of Scope of Application

RELATIONSHIP & COMMUNICATIONS

- LL to communicate plan to EH and State as soon as possible.
- EH & State have been advised we will update them in the last week of November on probable cause







Pages 92 through 93 redacted for the following reasons:

This Part Out of Scope of Application





DOH-DL 15/16-03 ATI Document 94

This Part Out of Scope of Application

This Part Out of Scope of Application

25 November 2015

Mr Pat Coleman
Chief Executive, Exemplar Health
Sunshine Coast University Hospital Site Office
Gate 7 South Street
Birtinya QLD 4575

Dear Pat

SUNSHINE COAST UNIVERSITY HOSPITAL TES TANK INCIDENT

Further to the TES Tank Incident that occurred on 16 October 2015, of Scope understand from ongoing discussions with various project parties, and more recently the November PCG, investigations are now well advanced and reporting on the root cause and likely outcomes are pending release next month, as advised at the PCG.

Given that a reasonable amount of time has now elapsed for initial investigations and reporting to be undertaken, and further to Exemplan Health letters/correspondence issued to Queensland Health dated 23 October 2015 (and provided for reference) of Scope request that a formal update supported by relevant documents be provided on the following, ey focus on programming impacts:


- Status of the root gause of the incident (or in the event this is unknown, approximate date when a likely outcome and reporting will provide clarify this);
- Status of whether the root cause is likely to impact/affect other water storage tanks as currently built within the facility, and if so reconstruction/remedy requirements to be undertaken, program impacts on undertaking the works, and future impacts on previous programmed commissioning and completion activities;
- Status of reconstruction/make good activities to adjacent work areas affected by the TES Tank incident, This Payt Out of Scope This Part Out of Scope This Part Out of Application

This Part Phis Part Out of Scope of Application on

This Part Out of Scope of Application



Page 96 redacted for the following reason:
----This Part Out of Scope of Application



Sunshine Coast University Hospital PPP This Part Out Kawana Way Birtinya Queensland 4575 Australia art Out of Scope of App MBER MAIL TYPE **ENCE NUMBER General Communication** of Scope GCOM-000307 of Scope IRA-000216 Re: TES Tank Incident - Request for Update Thins Part Out of Scope of Application Pp] From То Mr Pat Coleman - Exemplar Health This Part Out of Scope of Applia ⊕ Cc (6) Friday, 27 November 2015 12:54:58 PM EST (GMT +10:00) Sent N/A Status **Attributes** Attribute 1 Management Attribute 2 Tank Incident Message Pat of Scope This Part Out of Scope of Application This Part Out of Scope of Application We note however correspondence below remains open for EH reply. Regards This Part Out of Scope of Application This Part Out of Scope of Application PLEASE CONSIDER THE ENVIRONMENT BEFORE RINTING THIS EMP From: of Scope Sent: 5 3:30:10 PM EST (GMT 11:00) To: Cc: uf of Scope of Bianca Jones, SCUH Project Director, Don Glynn, Roseanne Jennings Scop RA-000216 Subject: TES cident - Request for Update Pat Find attached for your reference and action a request relating to the TES tank incident.

Regards

This Part Out of Scope of Application
This Part Out of Scope of Application

This Part Out of Scope of Application

This Part Out of Scope of Application

PLEASE CONSIDER THE ENVIRONMENT BEFORE PRINTING THIS EMAIL.



Sunshine Coast University Hospital PPP Kawana Way Birtinya Queensland 4575 Australia Exemplar Health c/- Capella Capital AMP Centre, Level 31, 50 Bridge Street Sydney NSW 2000 Australia Ph+61 2 82243888

MAIL TYPE MAIL NUMBER REFERENCE NUMBER General Communication EXH-GCOM-005913 r\$c66 IRA-000216 Re: TES Tank Incident - Request for Update From Mr Pat Coleman - Exemplar Health This Part Out of Scope of Applic □ To (2) This Part Out of Scope of Application Cc (6) Mr Mark Plummer - Lend Lease Building Mr Paul Quatermass - Lend Lease Building SCUH Project Director - Queensland Health - Capital Delivery Program Mr Don Glynn - Queensland Health - Capital Delivery Program Roseanne Jennings - Queensland Health - Capital Delivery Program Scott Lisle - Sunshine Coast Hospital and Health Service Friday, 27 November 2015 1:34:25 PM EST (GMT +10:00) Sent Status N/A **Attributes** Attribute 1 Management Attribute 2 Tank Incident Message of Scope Thank you for your letter Part Out of Scope of Applicacting as the Independent Reviewer. Please be advised that Project Co does not consider the majority of matters raised within you letter as being with the purview of the Independent Reviewer. Issues relating to causal effect of tank faikures and replacement strategies is a matter for the Parties to the Project Deed. This is not a matter for the which the IR should be requisiting a formal update and none will be given. Updates are already planned and have been foreshadowed to the State Project Director. This Part Out cation This Part Out of Scope of Application

Regards,

Pat Coleman

Project Co Representative

From: of Scope Sent:

3:30:10 PM EST (GMT +11:00)

To:

Cc: Tor Scope of Bianca Jones, SCUH Project Director, Don Glynn, Roseanne Jennings Ma W-IRA-000216

Subject: TES Tank Incident - Request for Update

Pat

Find attached for your reference and action a request relating to the TES tank incident.

Regards This Part Out of Scope of Application This Part Out of Scope of Application PLEASE CONSIDER THE ENVIRONMENT BEFORE PRINTING THIS EMAIL.

H-DL 15/16-03 1 Document 100

NOTES